

information to prevent runway overruns based on insufficient aerodynamic and wheel braking if the lift dump spoilers do not

operate after landing touchdown. This could result in reduced or loss of control of the airplane.

(d) *What must I do to address this problem?* To address this problem, you must accomplish the following actions:

Actions	Compliance
(1) Incorporate information into the FAA-approved Airplane Flight Manual (AFM) that would add requirements for "Landing Performance for Operation of the Airplane with Lift Dump Inoperative." Accomplish this action by inserting Raytheon Temporary Change to the FAA Approved Airplane Flight Manual P/N 390-590001-0003BTC5A1, revised March 24, 2003.	Within the next 5 hours time-in-service (TIS) after April 7, 2003 (the effective date of this AD).
(2) The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may incorporate into the AFM the information specified in paragraphs (d)(1) of this AD. Make an entry into the aircraft records showing compliance with this portion of the AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).	Within the next 5 hours TIS after April 7, 2003 (the effective date of this AD).

(e) *Are special flight permits authorized for this AD?* Special flight permits are not authorized for this AD. On July 10, 2002, FAA published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs FAA's AD system. Part of this amendment to 14 CFR part 39 authorized special flight permits for all ADs, unless specified otherwise. Because the owner/operator holding an appropriate pilot's license may accomplish the action of this AD and the compliance time is 5 hours TIS after the AD effective date, FAA has determined that special flight permits are not necessary for this AD.

(f) *Can I comply with this AD in any other way?* To use an alternative method of compliance or adjust the compliance time, follow the procedures in 14 CFR 39.19. Send these requests to the Manager, Wichita Aircraft Certification Office (ACO). For information on any already approved alternative methods of compliance, contact Derek Morgan, Flight Test Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4172; facsimile: (316) 946-4407.

(g) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Raytheon Temporary Change to the FAA Approved Airplane Flight Manual P/N 390-590001-0003BTC5A1, revised March 24, 2003. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from Raytheon Aircraft Company, 9709 E. Central, Wichita, Kansas 67201-0085; telephone: (800) 429-5372 or (316) 676-3140. You may view this information at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(h) *When does this amendment become effective?* This amendment becomes effective on April 7, 2003.

Issued in Kansas City, Missouri, on March 27, 2003.

Dorenda D. Baker,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-8066 Filed 4-2-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-268-AD; Amendment 39-13103; AD 2003-07-07]

RIN 2120-AA64

Airworthiness Directives; Raytheon Model BAe.125 Series 800A, 800A (C-29A), 800A (U-125), and 800B Airplanes; Model BH.125 Series 400A Airplanes; Model DH.125 Series Airplanes; Model Hawker 800, 800 (U-125A), and 800XP Airplanes; and Model HS.125 Series F3B, F3B/RA, F400B, F403B, 1B, 1B-522, 1B/R-522, 1B/S-522, 3B, 3B/R, 3B/RA, 3B/RB, 3B/RC, 400B, 400B/1, 401B, 403A(C), and 403B Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Raytheon airplanes, that requires inspection of the main landing gear (MLG) wheels to determine the part numbers of the tie-bolt nuts, and replacement of nuts that have the incorrect part number with nuts that have the correct part number. The actions specified by this AD are intended to prevent separation of an MLG wheel due to loose or missing tie-bolts or tie-bolt nuts, with consequent damage to airplane structure or systems, decompression, loss of full braking ability, or injury to personnel on the ground. This action is intended to address the identified unsafe condition.

DATES: Effective May 8, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 8, 2003.

ADDRESSES: The service information referenced in this AD may be obtained from Raytheon Aircraft Company, Department 62, PO Box 85, Wichita, Kansas 67201-0085. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; at the FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: David Ostrodka, Aerospace Engineer, Airframe Branch, ACE-118W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone (316) 946-4129; fax (316) 946-4407.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Raytheon airplanes was published in the **Federal Register** on January 3, 2003 (68 FR 322). That action proposed to require inspection of the main landing gear (MLG) wheels to determine the part numbers of the tie-bolt nuts, and replacement of nuts that have the incorrect part number with nuts that have the correct part number.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 166 airplanes of the affected design in the worldwide fleet. The FAA estimates that 84 airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane to accomplish the required inspection, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$5,040, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions. Manufacturer warranty remedies may be

available for labor costs associated with this proposed AD. As a result, the costs attributable to the proposed AD may be less than stated above.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules

Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2003-07-07 Raytheon Aircraft Company:
Amendment 39-13103. Docket 2002-NM-268-AD.

Applicability: The following airplanes, certificated in any category:

TABLE—AIRPLANE MODELS, SERIAL NUMBERS, AND EQUIPMENT

Model—	Serial No.—	Equipped with—
BAe.125 series 800A	All	none.
BAe.125 series 800A (C-29A)	All	none.
BAe.125 series 800A (U-125)	All	none.
BAe.125 series 800B	All	none.
BH.125 series 400A	All	none.
DH.125 series airplanes	All	none.
Hawker 800	All	none.
Hawker 800 (U-125A)	Up to and including serial numbers 258493.	none.
Hawker 800XP	Up to and including serial numbers 258581.	Dunlop wheels part numbers AH51909, AH52075, AH52286, AH52206, AHA1287, AHA1606, or AHA1814.
HS.125 series F3B	All	none.
HS.125 series F3B/RA	All	none.
HS.125 series F400B	All	none.
HS.125 series F403B	All	none.
HS.125 series 1B	All	none.
HS.125 series 1B-522	All	none.
HS.125 series 1B/R-522	All	none.
HS.125 series 1B/S-522	All	none.
HS.125 series 3B	All	none.
HS.125 series 3B/R	All	none.
HS.125 series 3B/RA	All	none.
HS.125 series 3B/RB	All	none.
HS.125 series 3B/RC	All	none.
HS.125 series 400B	All	none.
HS.125 series 400B/1	All	none.
HS.125 series 401B	All	none.
HS.125 series 403A(C)	All	none.
HS.125 series 403B	All	none.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been

modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or

repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an

alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent separation of a main landing gear (MLG) wheel due to loose or missing tie-bolts or tie-bolt nuts, with consequent damage to airplane structure or systems, decompression, loss of full braking ability, or injury to personnel on the ground, accomplish the following:

Inspection

(a) Within 10 landings or 12 days after the effective date of this AD, whichever comes first, inspect the MLG wheels to determine the part numbers (P/Ns) of the tie-bolt nuts; per Raytheon Service Bulletin SB 32-3522, dated September 2002, excluding Service Bulletin/Kit Drawing Report Fax.

Replacement

(b) If any tie-bolt nut having P/N NAS1804 is found installed during the inspection required by paragraph (a) of this AD, before further flight, replace the tie-bolt nut with a new nut having P/N FN22A524, (or with a new tie-bolt nut having a Dunlop P/N H5227C-5CW, SN407C-054, or LH13318-5, which are P/Ns authorized by Raytheon); per Raytheon Service Bulletin SB 32-3522, dated September 2002, excluding Service Bulletin/Kit Drawing Report Fax.

Parts Installation

(c) As of the effective date of this AD, no person shall install any MLG wheel having a tie-bolt nut with P/N NAS1804, on any airplane.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Wichita Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(f) Unless otherwise provided by this AD, the actions shall be done per Raytheon Service Bulletin SB 32-3522, dated September 2002, excluding Service Bulletin/Kit Drawing Report Fax. This incorporation by reference was approved by the Director of

the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Raytheon Aircraft Company, Department 62, PO Box 85, Wichita, Kansas 67201-0085. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; at the FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(g) This amendment becomes effective on May 8, 2003.

Issued in Renton, Washington, on March 28, 2003.

Michael J. Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 03-8064 Filed 4-2-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2003-14657; Airspace Docket No. 03-ACE-26]

Modification of Class E Airspace; St. Louis, MO

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; request for comments.

SUMMARY: An examination of controlled airspace for St. Louis, MO has revealed discrepancies in the Spirit of St. Louis Airport airport reference point used in the legal description for the St. Louis, MO Class E airspace. This action corrects the discrepancies by modifying the St. Louis, MO Class E airspace area. It also incorporates the revised Spirit of St. Louis Airport airport reference point in the St. Louis, MO Class E airspace legal description.

DATES: This direct final rule is effective on 0901 UTC, July 10, 2003. Comments for inclusion in the Rules Docket must be received on or before May 15, 2003.

ADDRESSES: Send comments on this proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket number FAA-2003-14657/ Airspace Docket No. 03-ACE-26, at the beginning of your comments. You may also submit comments on the Internet at <http://dms.dot.gov>. You may review the public docket containing the proposal,

any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

FOR FURTHER INFORMATION CONTACT:

Brenda Mumper, Air Traffic Division, Airspace Branch, ACE-520A, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust, Kansas City, MO 64106; telephone: (816) 329-2524.

SUPPLEMENTARY INFORMATION: This amendment to 14 CFR 71 modifies the Class E airspace area extending upward from 700 feet above the surface of the earth at St. Louis, MO. It also brings the legal descriptions of this airspace area into compliance with FAA Order 7400.2E, Procedures for Handling Airspace Matters. The area will be depicted on appropriate aeronautical charts. Class E airspace areas extending upward from 700 feet or more above the surface of the earth are published in paragraph 6005 of FAA Order 7400.9K, dated August 30, 2002, and effective September 16, 2002, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

The Direct Final Rule Procedure

The FAA anticipates that this regulation will not result in adverse or negative comment and, therefore, is issuing it as a direct final rule. Previous actions of this nature have not been controversial and have not resulted in adverse comments or objections. Unless a written adverse or negative comment, or a written notice of intent to submit an adverse or negative comment is received within the comment period, the regulation will become effective on the date specified above. After the close of the comment period, the FAA will publish a document in **Federal Register** indicating that no adverse or negative comments were received and confirming the date on which the final rule will become effective. If the FAA does receive, within the comment period, an adverse or negative comment, or written notice of intent to submit such a comment, a document withdrawing the direct final rule will be published in the **Federal Register**, and a notice of proposed rulemaking may be published with a new comment period.

Comments Invited

Interested parties are invited to participate in this rulemaking by