## Selecting the SureServo<sup>™</sup> Servo System

### In This Appendix ...

Selecting the SureServo™ Servo System	B–2 B–2 B–3 B–3
Leadscrew - Example Calculations       Step 1 - Define the Actuator and Motion Requirements         Step 2 - Determine the Positioning Resolution of the Load       Step 3 - Determine the Motion Profile         Step 4 - Determine the Required Motor Torque       Step 5 - Select and Confirm the Servo Motor and Driver System	B–8 B–8 B–9 B–9
Belt Drive - Example Calculations	.B–11 .B–11 .B–12 .B–12
Index Table - Example Calculations	.B–14 .B–14 .B–15 .B–15
Engineering Unit Conversion Tables, Formulas, & Definitions	8–17

PPENDIX


### Selecting the SureServo<sup>™</sup> Servo System

The selection of your *Sure*Servo<sup>™</sup> servo system follows a defined process. Let's go through the process and define some useful relationships and equations. We will use this information to work some typical examples along the way.

### The Selection Procedure

The motor provides for the required motion of the load through the actuator (mechanics that are between the motor shaft and the load or workpiece). Key information to accomplish the required motion is:

- total number of pulses from the PLC
- positioning resolution of the load
- indexing speed (or PLC pulse frequency) to achieve the move time
- required motor torque (including the 25% safety factor)
- load to motor inertia ratio



In the final analysis, we need to achieve the required motion with acceptable positioning accuracy.

### How many pulses from the PLC to make the move?

The total number of pulses to make the entire move is expressed with the equation:

Equation (1):  $P_{total} = total pulses = (D_{total} \div (d_{load} \div i)) \times \theta_{count}$ 

Dtotal = total move distance

dload = lead or distance the load moves per revolution of the actuator's drive shaft (P = pitch = 1/dload)

 $\theta_{count}$  = servo resolution (counts/rev<sub>motor</sub>) (default = 10,000)

i = gear reduction ratio (rev<sub>motor</sub>/rev<sub>gearshaft</sub>)

**Example 1:** The motor is directly attached to a disk and we need to move the disk 5.5 revolutions. How many pulses does the PLC need to send to the driver?

 $\begin{aligned} \mathbf{P_{total}} &= (5.5 \ \text{rev}_{disk} \div (1 \ \text{rev}_{disk}/\text{rev}_{driveshaft} \div 1 \ \text{rev}_{motor}/\text{rev}_{driveshaft})) \\ & 5.5 \div (1.0 \div 10) \ \text{x} \ 10,000 \ \text{=} 550,000 \\ & \text{x} \ 10,000 \ \text{counts/rev}_{motor} \\ &= 55,000 \ \text{pulses} \end{aligned}$ 

**Example 2:** The motor is directly attached to a ballscrew where one turn of the ballscrew results in 20 mm of linear motion and we need to move 45 mm. How many pulses do we need to send the driver?

P<sub>total</sub> = (45 mm ÷ (20 mm/rev<sub>screw</sub> ÷ 1 rev<sub>motor</sub>/rev<sub>screw</sub>)) x 10,000 counts/rev<sub>motor</sub> =22,500 pulses

45 mm	1 rev <sub>screw</sub>	1 rev <sub>motor</sub>	10,000 pulses
move	20 mm	1 rev <sub>screw</sub>	1 rev <sub>motor</sub>

**Example 3:** Let's add a 2:1 belt reduction between the motor and ballscrew in example 2. Now how many pulses do we need to make the 45 mm move?

P<sub>total</sub> = (45 mm ÷ (20mm/rev<sub>screw</sub> ÷ 2 rev<sub>motor</sub>/rev<sub>screw</sub>)) x 10,000 counts/rev<sub>motor</sub> = 45,000 pulses

### What is the positioning resolution of the load?

We want to know how far the load will move for one command pulse. The equation to determine the positioning resolution is:


Equation (2):  $L_{\theta}$  = load positioning resolution = ( $d_{load} \div i$ )  $\div \theta_{count}$ 

Example 4: What is the positioning resolution for the system in example 3?

- $L_{\theta} = (d_{load} \div i) \div \theta_{count}$ 
  - = (20 mm/rev<sub>screw</sub> ÷ 2 rev<sub>motor</sub>/rev<sub>screw</sub>) ÷ 10,000 counts/rev<sub>motor</sub>
  - = 0.001mm/count
  - $\approx$  0.00004"/count

### What is the indexing speed to accomplish the move time?

The most basic type of motion profile is a "start-stop" profile where there is no acceleration or deceleration period. This type of motion profile is only used for low speed applications because the load is "jerked" from one speed to another and the servo system may experience a position deviation error if excessive speed changes are attempted. The equation to find indexing speed for "startstop" motion is:



Equation ③:  $f_{SS}$  = indexing speed for start-stop profiles =  $P_{total} \div t_{total}$ 

ttotal = move time


**Example 5:** What is the indexing speed to make a "start-stop" move with 10,000 pulses in 800 ms?

 $f_{SS}$  = indexing speed =  $P_{total} \div t_{total}$  = 10,000 pulses  $\div$  0.8 seconds = 12,500 Hz.

For higher speed operation, the "trapezoidal" motion profile includes controlled acceleration & deceleration and, in Trapezoidal Profile

some cases, an initial non-zero starting speed. With the acceleration and deceleration periods equally set, the indexing speed can be found using the equation:

Equation (4):  $f_{TRAP} = (P_{total} - (f_{start} x t_{ramp})) \div (t_{total} - t_{ramp})$ for trapezoidal motion profiles



f<sub>start</sub> = starting speed

 $t_{ramp}$  = acceleration or deceleration time

**Example 6:** What is the required indexing speed to make a "trapezoidal" move in 1.8s, accel/decel time of 200 ms each, 100,000 total pulses, and a starting speed of 40 Hz?


 $f_{TRAP} = (100,000 \text{ pulses} - (40 \text{ pulses/sec x } 0.2 \text{ sec})) \div (1.8 \text{ sec} - 0.2 \text{ sec}) \approx 62,375 \text{ Hz}.$ 

### Calculating the Required Torque

The required torque is the sum of acceleration (or deceleration) torque and the running torque. The equation for required motor torque is:

### Equation (5): $T_{motor} = T_{accel} (or decel) + T_{run}$

- $T_{accel}$  = motor torque required to accelerate the total system inertia (including motor inertia).
- T<sub>decel</sub> = motor torque required to decelerate; not always the same as acceleration.
- T<sub>run</sub> = constant motor torque requirement to run the mechanism due to friction, external load forces, etc.




**Continuous Duty Zone** means the system can provide the torque under the curve 100% of the time.

**Intermittent Duty Zone** means the system can provide the torque under the curve LESS THAN 100% of the time.

The amount of time the system can operate in this region depends on the amount of torque. In general, the higher the torque, the shorter period of time is allowed. See overload curves information in Chapter 1. If a system requires more than rated torque occasionally, but only for a short time, the system can do it. Running in this zone continuously will result in an overload fault.

In **Table 1** we show how to calculate torque required to accelerate or decelerate an inertia from one speed to another and the calculation of running torque for common mechanical actuators.




### Appendix B: Selecting the SureServo<sup>™</sup> Servo System

Table 1 (cont'd)				
	Typical Lea	adscrew Data		
Material:	e = efficiency	Material:	μ = coef. of friction	
ball nut	0.90	steel on steel	0.580	
acme with plastic nut	0.65	steel on steel (lubricated)	0.150	
acme with metal nut	0.40	teflon on steel	0.040	
		ball bushing	0.003	
Belt D	rive (or Rack	& Pinion) Equations		
Jgear (	Fgravity 0 Jpinion	Jmotor W1 Fext Fgravity W2	<sup>nion</sup> i = gear ratio	
Description:	Equations:			
Motor rpm	n <sub>motor</sub> = (v <sub>load</sub>	x 2 π r) x i		
Torque required to accelerate and decelerate the load	T <sub>accel</sub> J <sub>total</sub>	x ( $\Delta$ speed ÷ $\Delta$ time) x 0.1		
Inertia of the load	$J_{total} = J_{motor} + J_{gear} + ((J_{pinion} + J_W) \div i^2)$			
Inertia of the load	$J_W = (W \div (g \ x \ e)) \ x \ r^2$ ; $J_W = ((W_1 + W_2) \div (g \ x \ e)) \ x \ r^2$			
Radius of pulleys	r = radius of pinion or pulleys (inch)			
Running torque	$T_{run} = (F_{total} \times r) \div i$			
Force total	$F_{total} = F_{ext} + F_{ext}$	friction + Fgravity		
Force of gravity and Force of friction	F <sub>gravity</sub> = Wsine	θ; F <sub>friction</sub> = μWcosθ		
Bel	t (or Gear) F	Reducer Equations		
J <sub>motor</sub>	torpulley	J <sub>motor</sub> J <sub>loadpulley</sub>	pad	
Description:	Equations:			
Motor rpm	n <sub>motor</sub> = n <sub>load</sub>	xi		
Torque required to accelerate and decelerate the load	'accel stotal	x (Δspeed÷Δtime) x 0.1		
Inertia of the load		+ Jmotorpulley + ((Jloadpulley + JLoa	d) ÷ i <sup>2</sup> )	
Motor torque	$T_{motor} \times i = T_{Lo}$	bad		

Table 1 (cont	d)			
Inertia of Hollow Cylinder Equations				
	(	$D_{o} = 2r_{o}$		
Description:	Equations:			
Inertia (known weight)	$J = (W \times (r_0^2 +$	- r <sub>i</sub> <sup>2</sup> )) ÷ (2g)		
Inertia (known density)	$J = (\pi x L x \rho)$	$x (r_0^4 - r_i^4)) \div (2g)$		
Volume	volume = $\pi/4$	$x (D_0^2 - D_i^2) x L$		
	Inertia of S	Solid Cylinder Equations		
	(	D = 2r		
Description:	Equations:			
Inertia (known weight)	$J = (W \times r^2) \div$	(2g)		
Inertia (known density)	$J = (\pi x L x \rho)$	$J = (\pi \times L \times \rho \times r^4) \div (2g)$		
Volume	volume = $\pi x r^2 x L$			
Ir	nertia of Re	ctangular Block Equations		
	_† h ↓			
Description:	Equations:			
Inertia (known weight)	J = (W ÷ 12g)			
Volume	volume = I x h	1 X W		
	Syı	mbol Definitions		
J = inertia lb-in-s <sup>2</sup> (Kg-m-s <sup>2</sup> )		$\rho$ = density		
L = Length, inches (m)		$\rho = 0.098 \text{ lb/in}^3$ (aluminum)		
h = height, inches (m)		$\rho = 0.28$ lb/in <sup>3</sup> (steel)		
w = width, inches (m)		$\rho = 0.04 \text{ lb/in}^3$ (plastic)		
W = weight, Ibs. (Kg)		$\rho = 0.31 \text{ lb/in}^3 \text{ (brass)}$		
D = diameter, inches (m)		$\rho = 0.322 \text{ lb/in}^3 \text{ (copper)}$		
r = radius, inches (m)				
g = gravity = 386 in/sec <sup>2</sup> (9.8 m/s <sup>2</sup> ) $\pi \approx 3.14$				

### Leadscrew - Example Calculations

### Step 1 - Define the Actuator and Motion Requirements



Weight of table and workpiece = 150 lb Angle of inclination = 0° Friction coefficient of sliding surfaces = 0.05 External load force = 0 Ball screw shaft diameter = 0.8 inch Ball screw length = 96 inch Ball screw material = steel Ball screw lead = 8.0 inch/rev (P  $\approx$  0.125 rev/in) Desired Resolution = 0.0005 inches/count Gear reducer = 2:1 Stroke = 78 inches Move time = 12 seconds

#### Definitions

 $d_{load}$  = lead or distance the load moves per revolution of the actuator's drive shaft (P = pitch = 1/d\_{load})

D<sub>total</sub> = total move distance

 $\theta_{count}$  = servo resolution (counts/rev<sub>motor</sub>)

i = gear reduction ratio (rev<sub>motor</sub>/rev<sub>gearshaft</sub>)

T<sub>accel</sub> = motor torque required to accelerate and decelerate the total system inertia (including motor inertia)

 $T_{run}$  = constant motor torque requirement to run the mechanism due to friction, external load forces, etc.

t<sub>total</sub> = move time

### Step 2 - Determine the Positioning Resolution of the Load

The resolution of the load can be determined using **Equation** (2). If the servo motor is connected directly to the ballscrew, then the best resolution possible would be:

 $L_{\theta} = (\mathbf{d}_{load} \div \mathbf{i}) \div \theta_{count}$  $= (8 \div 1) \div 10,000$ = 0.0008

This does not meet the system requirements; however, if we add a 2:1 transmission with no lost motion (backlash, etc.) to the output of the motor, the resolution gets better by a factor of 2, so the minimum requirements would be met.

$$L_{\theta} = (8 \div 2) \div 10,000$$
  
= 0.0004

### Step 3 - Determine the Motion Profile

From Equation ①, the total pulses to make the required move is:

 $P_{\text{total}} = (D_{\text{total}} \div (d_{\text{load}} \div i)) \times \theta_{\text{count}}$ = (78 ÷ (8 ÷ 2)) x 10,000 = 195,000 pulses

From **Equation** (4), the indexing frequency for a trapezoidal move is:

 $\begin{aligned} \mathbf{f}_{\mathsf{TRAP}} &= (\mathbf{P}_{\mathsf{total}} - (\mathbf{f}_{\mathsf{start}} \times \mathbf{t}_{\mathsf{ramp}})) \div (\mathbf{t}_{\mathsf{total}} - \mathbf{t}_{\mathsf{ramp}}) \\ &= (195,000 - (100 \times 0.6)) \div (12 - 0.6) \approx 17.1 \text{ KHz} \\ &\text{where accel time is 5\% of total move time and starting speed is 100 Hz.} \\ &= 17.1 \text{ KHz x (60 sec/1 min)} \div 10,000 \text{ counts/rev} \\ &\approx 103 \text{ rpm} \end{aligned}$ 

#### Step 4 - Determine the Required Motor Torque

Using the equations in Table 1:

 $J_{total} = J_{motor} + J_{gear} + ((J_{coupling} + J_{screw} + J_W) \div i^2)$ 

For this example, let's assume the gearbox and coupling inertia are zero.

 $J_{W} = (W \div (g \times e)) \times (1 \div 2\pi P)^{2}$ 

 $= (150 \div (386 \times 0.9)) \times (1 \div 2 \times 3.14 \times 0.125)^{2}$ 

 $\approx 0.700 \text{ lb-in-sec}^2$ 

 $\mathbf{J}_{\mathbf{screw}} \approx (\pi \ \mathbf{X} \ \mathbf{L} \ \mathbf{X} \ \rho \ \mathbf{X} \ \mathbf{r}^{4}) \ \div \ (2g)$ 

 $\approx (3.14 \times 96 \times 0.28 \times 0.0256) \div (2 \times 386)$ 

 $\approx 0.0028 \text{ lb-in-sec}^2$ 

The inertia of the load and screw reflected to the motor is:

 $J_{(screw + load)}$  to motor =  $((J_{screw} + J_W) \div i^2)$ 

 $\approx$  ((0.0028 + 0.700) ÷ 2<sup>2</sup>) = 0.176 lb-in-sec<sup>2</sup>

The torque required to accelerate the inertia is:

 $T_{accel} \approx J_{total} \times (\Delta speed \div \Delta time) \times 0.1$ 

= 0.176 x (103  $\div$  0.6) x 0.1  $\approx$  1.08 lb-in

Next, we need to determine running torque. If the machine already exists then it is sometimes possible to actually measure running torque by turning the actuator driveshaft with a torque wrench.

$$\begin{split} \textbf{T}_{run} &= ((\textbf{F}_{total} \div (2 \ \pi \ \text{P})) + \textbf{T}_{preload}) \div \textbf{i} \\ \textbf{F}_{total} &= \textbf{F}_{ext} + \textbf{F}_{friction} + \textbf{F}_{gravity} \\ &= 0 + \mu Wcos\theta + 0 = 0.05 \ x \ 150 = 7.5 \ \text{lb} \\ \textbf{T}_{run} &= (7.5 \div (2 \ x \ 3.14 \ x \ 0.125)) \div 2 \end{split}$$

 $\approx$  4.77 lb-in

where we have assumed preload torque to be zero.

From Equation (5), the required motor torque is:

 $T_{motor} = T_{accel} + T_{run} = 1.08 + 4.77 \approx 5.85 \text{ lb-in} \approx 0.66 \text{ N} \cdot \text{m}$ 


However, this is the required motor torque before we have picked a motor and included the motor inertia.

### Step 5 - Select and Confirm the Servo Motor and Driver System

It looks like a reasonable choice for a motor would be the SVL-207. This motor has an inertia of:

 $J_{motor} = 0.00096 \text{ lb-in-sec}^2$ 

The actual motor torque would be modified:



It looks like the 750W system will work. However, we still need to check the load to motor inertia ratio:


Ratio =  $J_{(screw + load) to motor} \div J_{motor}$ = 0.176 ÷ 0.00096 = 183.3

It is best to keep the load to motor inertia ratio below 10, so 183 is well outside this guideline. Although the servo has enough power to control the system, the large mismatch ratio may prevent proper tuning and faster acceleration settings in the future. Since the motor speed required to move the system is well within the motor specs, we can change the gear ratio to use a 750W motor or select a much larger motor such as the SVM-220. Because the reflected inertia is decreased by the square of the ratio, we will change the gear ratio to 10:1. By doing this, the mismatch ratio is now 7.3 (before we consider any added inertia due to the reducer).

Reflected J = 
$$J_{screw}+J_{load}$$
 = .176, so  
 $2^2$   
New Reflected J =  $J_{screw}+J_{load}$  = .00704  
 $10^2$   
New J Ratios = .00704 = 7.33  
.00096

### **Belt Drive - Example Calculations**

Step 1 - Define the Actuator and Motion Requirements



Weight of table and workpiece = 90 lb External force = 0 lb Friction coefficient of sliding surfaces = 0.05 Angle of table = 0° Belt and pulley efficiency = 0.8 Pulley diameter = 2.0 inch Pulley thickness = 0.75 inch Pulley material = aluminum Desired Resolution = 0.0005 inch/step Gear Reducer = 10:1 Stroke = 50 inch Move time = 4.0 seconds Accel and decel time = 1.0 seconds

#### Definitions

d<sub>load</sub> = lead or distance the load moves per revolution of the actuator's drive shaft (P = pitch = 1/d<sub>load</sub>)

D<sub>total</sub> = total move distance

 $\theta_{count}$  = servo resolution (counts/rev<sub>motor</sub>)

i = gear reduction ratio (rev<sub>motor</sub>/rev<sub>gearshaft</sub>)

T<sub>accel</sub> = motor torque required to accelerate and decelerate the total system inertia (including motor inertia)

 $T_{run}$  = constant motor torque requirement to run the mechanism due to friction, external load forces, etc.

t<sub>total</sub> = move time

### Step 2 - Determine the Positioning Resolution of the Load

The resolution of the load can be determined using **Equation** (2). If the servo motor is connected directly to the pulley, then the best resolution possible would be:

 $\mathsf{L}\boldsymbol{\theta} = (\mathsf{d}_{\mathsf{load}} \div \mathsf{i}) \div \boldsymbol{\theta}_{\mathsf{count}}$ 

 $= ((\pi \times 2.0) \div 1) \div 10,000 \\= = 0.00063$ 

where  $\mathbf{d}_{load} = \pi \mathbf{x}$  Pulley Diameter.

This does not meet the system requirements. However, if we add a 10:1 transmission to the output of the motor, the resolution improves by a factor of 10, meeting the minimum system requirements.

$$Lu = ((p x 2.0) \div 10) \div 10,000 = 0.000063$$

### Step 3 - Determine the Motion Profile

From Equation (1), the total pulses to make the required move is:

 $\begin{aligned} \mathbf{P}_{\text{total}} &= (\mathbf{D}_{\text{total}} \div (\mathbf{d}_{\text{load}} \div \mathbf{i})) \times \mathbf{\theta}_{\text{count}} \\ &= 50 \div ((3.14 \times 2.0) \div 10 \times 10,000) \\ &\approx 795,775 \text{ pulses} \end{aligned}$ 

From **Equation** (4), the running frequency for a trapezoidal move is:

$$\begin{split} \mathbf{f}_{\mathsf{TRAP}} &= (\mathbf{P}_{\mathsf{total}} - (\mathbf{f}_{\mathsf{start}} \times \mathbf{t}_{\mathsf{ramp}})) \div (\mathbf{t}_{\mathsf{total}} - \mathbf{t}_{\mathsf{ramp}}) \\ &= 795,775 \div (4 - 1) \\ &\approx 265,258 \text{ Hz or } 265.3 \text{ KHz} \\ &\text{where accel time is } 25\% \text{ of total move time and starting speed is zero.} \\ &= 265.3 \text{ KHz x } (60 \text{ sec/1 min}) \div 10,000 \text{ counts/rev} \\ &\approx 1,592 \text{ rpm motor speed} \end{split}$$

### Step 4 - Determine the Required Motor Torque

Using the equations in Table 1:

 $J_{total} = J_{motor} + J_{gear} + ((J_{pulleys} + J_W) \div i^2)$ 

For this example, let's assume the gearbox inertia is zero.

 $J_{W} = (W \div (g \times e)) \times r^{2}$ 

= (90  $\div$  (386 x 0.8)) x 1

 $\approx$  0.291 lb-in-sec<sup>2</sup>

Pulley inertia (remember, there are two pulleys) can be calculated as:

$$\begin{split} \textbf{J}_{\textbf{pulleys}} &\approx ((\pi \ x \ L \ x \ \rho \ x \ r^4) \div (2g)) \ x \ 2 \\ &\approx ((3.14 \ x \ 0.75 \ x \ 0.098 \ x \ 1) \div (2 \ x \ 386)) \ x \ 2 \\ &\approx 0.0006 \ \text{lb-in-sec}^2 \end{split}$$

The inertia of the load and pulleys reflected to the motor is:

 $\begin{aligned} \label{eq:J_pulleys + load} J_{\text{(pulleys + load) to motor}} &= ((J_{\text{pulleys}} + J_{\text{W}}) \div i^2) \\ &\approx ((0.291 + 0.0006) \div 100) \approx 0.0029 \text{ lb-in-sec}^2 \end{aligned}$ 

The torque required to accelerate the inertia is:

$$\begin{split} \mathbf{T}_{acc} &\approx \mathbf{J}_{total} \ x \ (\Delta speed \div \Delta time) \ x \ 0.1 \\ &= 0.0029 \ x \ (1592 \div 1) \ x \ 0.1 \\ &= 0.46 \ \text{lb-in} \\ \mathbf{T}_{run} &= (\mathbf{F}_{total} \ x \ \mathbf{r}) \div \mathbf{i} \\ \mathbf{F}_{total} &= \mathbf{F}_{ext} + \mathbf{F}_{friction} + \mathbf{F}_{gravity} \\ &= 0 + \mu W cos\theta + 0 = 0.05 \ x \ 100 = 5.0 \ \text{lb} \end{split}$$

$$T_{run} = (5.0 \text{ x } 1) \div 10$$
  
  $\approx 0.50 \text{ lb-in}$ 

From **Equation** (5), the required motor torque is:

 $T_{motor} = T_{accel} + T_{run} = 0.46 + 0.50 \approx 0.96 \text{ lb-in} \approx 0.11 \text{ N} \cdot \text{m}$ 

However, this is the required motor torque before we have picked a motor and included the motor inertia.


### Step 5 - Select and Confirm the Servo Motor and Driver System

It looks like a reasonable choice for a motor would be the SVL-2040. This motor has an inertia of:

 $J_{motor} = 0.0003 \text{ lb-in-sec}^2$ 

The actual motor torque would be modified:

```
\begin{split} \mathbf{T_{accel}} &= \mathbf{J_{total}} \ x \ (\Delta speed \div \Delta time) \ x \ 0.1 \\ &= (0.0029 + \mathbf{0.0003}) \ x \ (1592 \div 1) \ x \ 0.1 \approx 0.51 \ \text{lb-in} \\ &\text{so that:} \\ \mathbf{T_{motor}} &= \mathbf{T_{accel}} + \mathbf{T_{run}} \\ &= 0.51 + 0.5 \approx 1.01 \ \text{lb-in} \approx 0.12 \ \text{N} \cdot \text{m} \end{split}
```



It looks like the 400W system will work. However, we still need to check the load to motor inertia ratio:


Ratio =  $J_{(pulleys + load)}$  to motor  $\div J_{motor}$ = 0.0029  $\div$  0.0003 = 9.6

It is best to keep the load to motor inertia ratio at or below 10, so 9.6 is within an acceptable range.

-13

### Index Table - Example Calculations

### Step 1 - Define the Actuator and Motion Requirements



Diameter of index table = 12 inch Thickness of index table = 3.25 inch Table material = steel Number of workpieces = 8 Desired Resolution = 0.006° Gear Reducer = 6:1 Index angle = 45° Index time = 0.5 seconds

Definitions
$d_{load}$ = lead or distance the load moves per revolution of the actuator's drive shaft (P = pitch = $1/d_{load}$ )
D <sub>total</sub> = total move distance
$\theta_{count}$ = servo resolution (counts/rev <sub>motor</sub> )
i = gear reduction ratio (rev <sub>motor</sub> /rev <sub>gearshaft</sub> )
T <sub>accel</sub> = motor torque required to accelerate and decelerate the total system inertia (including motor inertia)
T <sub>run</sub> = constant motor torque requirement to run the mechanism due to friction, external load forces, etc.
t <sub>total</sub> = move time

### Step 2 - Determine the Positioning Resolution of the Load

The resolution of the load can be determined using **Equation** ④ If the servo motor is connected directly to the table, then the best resolution possible would be:

$$\begin{split} \textbf{L}_{\pmb{\theta}} &= (\textbf{d}_{\textbf{load}} \div \textbf{i}) \div \textbf{\theta}_{\textbf{count}} \\ &= (360^{\circ} \div 1) \div 10,000 \\ &= 0.036^{\circ} \end{split}$$

This does not meet the system requirements. However, if we add a 6:1 transmission to the output of the motor, the resolution gets better by a factor of 6, meeting the minimum system requirements.

 $= (360^{\circ} \div 6) \div 10,000$  $= 0.006^{\circ}$ 

### Step 3 - Determine the Motion Profile

From **Equation** (1), the total pulses to make the required move is:

 $P_{\text{total}} = (D_{\text{total}} \div (d_{\text{load}} \div i)) \times \theta_{\text{count}}$  $= (45^{\circ} \div (360^{\circ} \div 6) \times 10,000)$ = 7,500 pulses

From **Equation** (4), the running frequency for a trapezoidal move is:

 $\begin{aligned} \mathbf{f}_{\mathsf{TRAP}} &= (\mathbf{P}_{\mathsf{total}} - (\mathbf{f}_{\mathsf{start}} \times \mathbf{t}_{\mathsf{ramp}})) \div (\mathbf{t}_{\mathsf{total}} - \mathbf{t}_{\mathsf{ramp}}) \\ &= 7,500 \div (0.5 - 0.13) \approx 20.27 \text{ kHz} \\ &\text{where accel time is 25\% of total move time and starting speed is zero.} \\ &= 20.27 \text{ kHz x (60 sec/1 min)} \div 10,000 \text{ counts/rev} \\ &\approx 121 \text{ rpm} \end{aligned}$ 

#### Step 4 - Determine the Required Motor Torque

Using the equations in Table 1:

 $J_{total} = J_{motor} + J_{gear} + (J_{table} \div i^2)$ 

For this example, let's assume the gearbox inertia is zero.

 $J_{table} \approx (\pi \times L \times \rho \times r^4) \div (2g)$ 

 $\approx$  (3.14 x 3.25 x 0.28 x 1296) ÷ (2 x 386)

 $\approx$  4.80 lb-in-sec<sup>2</sup>

The inertia of the indexing table reflected to the motor is:

 $J_{table to motor} = J_{table} \div i^2$ 

 $\approx$  0.133 lb-in-sec<sup>2</sup>

The torque required to accelerate the inertia is:

$$\begin{split} \mathbf{T}_{\mathbf{accel}} &\approx \mathbf{J}_{\mathbf{total}} \; \mathbf{x} \; (\Delta \text{speed} \div \Delta \text{time}) \; \mathbf{x} \; 0.1 \\ &= 0.133 \; \mathbf{x} \; (121 \div 0.13) \; \mathbf{x} \; 0.1 \\ &\approx 12.38 \; \text{lb-in} \end{split}$$

From Equation (5), the required motor torque is:

 $T_{motor} = T_{accel} + T_{run}$ =12.38 + 0 = 12.38 lb-in  $\approx$  1.40 N·m


However, this is the required motor torque before we have picked a motor and included the motor inertia.

### Step 5 - Select and Confirm the Servo Motor and Driver System

It looks like a reasonable choice for a motor would be the SVM-220. This motor has an inertia of:

J<sub>motor</sub> = 0.014 lb-in-sec<sup>2</sup>

The actual motor torque would be modified:



It looks like the 2 kW medium inertia system will work. However, we still need to check the load to motor inertia ratio:

 $\begin{aligned} \textbf{Ratio} &= \textbf{J}_{\textbf{table to motor}} \div \textbf{J}_{\textbf{motor}} \\ &= 0.133 \div 0.014 = 9.5 \end{aligned}$ 

It is best to keep the load to motor inertia ratio at or below 10, so 9.5 is within an acceptable range.

# Engineering Unit Conversion Tables, Formulas, & Definitions

			Conver	sion of Len	gth		
To convert A to B, B multiply A by the							
entry in the table. $\mu$ m mm m mil in					ft		
	μm	1	1.000E-03	1.000E-06	3.937E-02	3.937E-05	3.281E-06
	mm	1.000E+03	1	1.000E-03	3.937E+01	3.937E-02	3.281E-03
Α	m	1.000E+06	1.000E+03	1	3.937E+04	3.937E+01	3.281E+00
	mil	2.540E+01	2.540E-02	2.540E-05	1	1.000E-03	8.330E-05
	in	2.540E+04	2.540E+01	2.540E-02	1.000E+03	1	8.330E-02
	ft	3.048E+05	3.048E+02	3.048E-01	1.200E+04	1.200E+01	1

			Conver	sion of Tor	que		
To convert A to B,				I	В		
	Itiply A by the ry in the table.	Nm	kpm(kg-m)	kg-cm	oz-in	lb-in	lb-ft
	Nm	1	1.020E-01	1.020E+01	1.416E+02	8.850E+00	7.380E-01
	kpm(kg-m)	9.810E+00	1	1.000E+02	1.390E+03	8.680E+01	7.230E+00
A	kg-cm	9.810E-02	1.000E-02	1	1.390E+01	8.680E-01	7.230E-02
	oz-in	7.060E-03	7.200E-04	7.200E-02	1	6.250E-02	5.200E-03
	lb-in	1.130E-01	1.150E-02	1.150E+00	1.600E+01	1	8.330E-02
	lb-ft	1.356E+00	1.380E-01	1.383E+01	1.920E+02	1.200E+01	1

			Conversic	on of Mon	nent of In	ertia		
To convert A to B, multiply A by the entry in the table.					В			
		kg-m <sup>2</sup>	kg-cm-s <sup>2</sup>	oz-in-s <sup>2</sup>	lb-in-s <sup>2</sup>	oz-in <sup>2</sup>	lb-in <sup>2</sup>	lb-ft <sup>2</sup>
	kg-m <sup>2</sup>	1	1.020E+01	1.416E+02	8.850E+00	5.470E+04	3.420E+03	2.373E+01
	kg-cm-s <sup>2</sup>	9.800E-02	1	1.388E+01	8.680E-01	5.360E+03	3.350+02	2.320E+00
	oz-in-s <sup>2</sup>	7.060E-03	7.190E-02	1	6.250E-02	3.861E+02	2.413E+01	1.676E-01
Α	lb-in-s <sup>2</sup>	1.130E-01	1.152E+00	1.600E+01	1	6.180E+03	3.861E+02	2.681E+00
	oz-in <sup>2</sup>	1.830E-05	1.870E-04	2.590E-03	1.620E-04	1	6.250E-02	4.340E-04
	lb-in <sup>2</sup>	2.930E-04	2.985E-03	4.140E-02	2.590E-03	1.600E+01	1	6.940E-03
	lb-ft <sup>2</sup>	4.210E-02	4.290E-01	5.968E+00	3.730E-01	2.304E+03	1.440E+02	1

### Engineering Unit Conversion Tables, Formulas, & Definitions (continued)

	General Formulae & Definitions
Description:	Equations:
Gravity	gravity = 9.8 m/s <sup>2</sup> = 386 in/s <sup>2</sup>
Torque	$T = J \alpha, \alpha = rad/s^2$
Power (Watts)	$P(W) = T(N \cdot m) \cdot \omega(rad/s)$
Power (Horsepower)	$P(hp) = T(lb \cdot in) \cdot v(rpm) / 63,024$
Horsepower	1 hp = 746 W
Revolutions	1 rev = 1,296,000 arc·sec = 21,600 arc·min = 360 degrees

Eq	Equations for Straight-Line Velocity & Constant Acceleration			
Description:	Equations:			
Final velocity	$v_f = v_i + at$ final velocity = initial velocity + (acceleration · time)			
Final position	$x_f = x_i + \frac{1}{2}(v_i + v_f)t$ final position = initial position + [1/2 · (initial velocity + final velocity) · time]			
Final position	$x_f = x_i + v_i t + \frac{1}{2}at^2$ final position = initial position + (initial velocity · time) + (1/2 · acceleration · time squared)			
Final velocity squared	$ \begin{array}{l} v_{f}^{2} = v_{i}^{2} + 2a(x_{f} - x_{i}) \\ \text{final velocity squared} = \text{initial velocity squared} + [2 \cdot \text{acceleration} \cdot (\text{final position} - \text{initial} \\ \text{position})] \end{array} $			