

4.2.2 Error Message and Troubleshooting



Messages appear on the Smart Panel program window or on the control panel to indicate machine status or errors. Refer to the tables below to correct the problem.

Error Code	Error Message	Troubleshooting Page
A1-1110	Actuator Motor Failure #A1-1110: Turn off then on.	4-40 Page
A1-1210	Actuator Motor Failure #A1-1210: Turn off then on.	4-42 Page
A1-1310	Actuator Motor Failure #A1-1310: Turn off then on.	4-44 Page
A1-3110	Actuator Motor Failure #A1-3110: Turn off then on.	4-46 Page
A2-1910	Actuator Fan Failure: #A2-1910. Turn off then on.	4-48 Page
A2-1920	Actuator Fan Failure: #A2-1920. Turn off then on	4-49 Page
A2-2410	Actuator Fan Failure: #A2-2410.	4-50 Page
A3-2110	Actuator Sensor Failure: #A3-2110.	4-51 Page
A3-5110	Actuator Sensor Failure: #A3-5110.	4-51 Page
C1-1110	C1-1110 Prepare new toner cartridge.	4-52 Page
C1-1120	C1-1120 Replace with new toner cartridge	4-52 Page
C1-1140	C1-1140 Replace with new toner cartridge	4-52 Page
C1-1311	Toner Failure: #C1-1311: Install toner again	4-53 Page
C1-1330	Toner Failure: #C1-1330: Install toner again	4-54 Page
C1-1411	Toner cartridge is not installed. Install it	
C1-1412	Did not supply enough toner. Reinstall it	4-53 Page
C1-1413	Shake toner cartridge and then install.	4-53 Page
C1-1512	Toner cartridge is not compatible. Check guide	4-54 Page
C3-1110	Prepare new imaging unit	4-55 Page
C3-1120	Replace with new imaging unit	4-55 Page
C3-1140	Replace with new imaging unit	
C3-1312	Imaging Unit Failure #C3-1312: Install IMG. unit.	4-53 Page
C3-1315	Imaging Unit Failure #C3-1315: Install IMG. unit.	4-53 Page
C3-1320	Imaging Unit Failure #C3-1320: Install IMG. unit.	4-55 page
C3-1330	Imaging Unit Failure #C3-1330: Install IMG. unit.	
C3-1411	Imaging unit is not installed. Install the unit.	
C3-1412	Did not supply enough toner. Reinstall Toner	
C3-1512	Imaging unit is not compatible. Check guide	4-56 Page
C3-1514	Imaging unit is not compatible. Check guide	
C5-1510	Imaging Unit Failure #C3-1330: Turn off then on.	4-56 Page
C6-1110	Replace with new fuser unit	4-57 Page
C6-1120	Replace with new fuser unit	
C7-1110	Waste toner container is almost full. Replace with new one	4-57 Page
C7-1120	Waste toner container is almost full. Replace with new one	
C7-1310	Install waste toner container.	4-57 Page



Error Code	Error Message	Troubleshooting Page
H1-1210 H1-1310 H1-1410 H1-1510	Paper Jam in Tray2 Paper Jam in Tray3 Paper Jam in Tray4 Paper Jam in Tray5	4-58 Page
H1-1222 H1-1322 H1-1422 H1-1522	Tray 2 cassette is pulled out. Insert it properly. Tray 3 cassette is pulled out. Insert it properly. Tray 4 cassette is pulled out. Insert it properly. Tray 5 cassette is pulled out. Insert it properly.	4-59 Page
H1-1230 (Tray2) H1-1233 (Tray2) H1-1330 (Tray3) H1-1333 (Tray3) H1-1430 (Tray4) H1-1433 (Tray4) H1-1530 (Tray5) H1-1533 (Tray5) H1-2230 (Tray2-HCF) H1-2233 (Tray2-HCF) H1-2330 (Tray3-HCF) H1-2333 (Tray3-HCF) H1-2430 (Tray4-HCF) H1-2433 (Tray4-HCF)	Input System Failure #H1-1230:Check Tray 2 connection. Input System Failure #H1-1233:Check Tray 2 connection. Input System Failure #H1-1330:Check Tray 3 connection. Input System Failure #H1-1333:Check Tray 3 connection. Input System Failure #H1-1430:Check Tray 4 connection. Input System Failure #H1-1433:Check Tray 4 connection. Input System Failure #H1-1530:Check Tray 5 connection. Input System Failure #H1-1533:Check Tray 5 connection. Input System Failure #H1-2230:Check HCF 2 connection. Input System Failure #H1-2233:Check HCF 2 connection. Input System Failure #H1-2330:Check HCF 3 connection. Input System Failure #H1-2333:Check HCF 3 connection. Input System Failure #H1-2430:Check HCF 4 connection. Input System Failure #H1-2433:Check HCF 4 connection.	4-60 page
H1-1252 H1-1352 H1-1452 H1-1552	Paper Empty in Tray 2 Paper Empty in Tray 3 Paper Empty in Tray 4 Paper Empty in Tray 5	4-61 Page
H1-1253 H1-1353 H1-1453 H1-1553	Error: #H1-1253 Error: #H1-1353 Error: #H1-1453 Error: #H1-1553	4-62 Page
H1-2210 H1-2310 H1-2410	Paper Jam in HCF2 Paper Jam in HCF3 Paper Jam in HCF4	4-63 Page
H1-2222 H1-2322 H1-2422	HCF 2 cassette Out HCF 3 cassette Out HCF 4 cassette Out	4-64 Page
H1-2252 H1-2352 H1-2452	Paper Empty in HCF 2 Paper Empty in HCF 3 Paper Empty in HCF 4	4-65 Page
H1-2253 H1-2353 H1-2453	Error: #H1-2253 Error: #H1-2353 Error: #H1-2453	4-66 Page
H2-1100	Paper jam inside of finisher. Remove paper	4-67 Page

Error Code	Error Message	Troubleshooting Page
H2-1101	Paper jam in front of finisher. Remove paper	4-68 Page
H2-1102	Paper jam inside of finisher. Remove paper	4-69 Page
H2-1200	Paper jam inside of finisher. Remove paper	4-70 Page
H2-1300	Paper jam at exit of finisher. Remove paper	4-71 Page
H2-1302	Paper jam at exit of finisher. Remove paper	4-72 Page
H2-1710 H2-1711	Finisher Failure: #H2-1710. Check finisher Finisher Failure: #H2-1711. Check finisher	4-73 Page
H2-1720 H2-1721	Finisher Failure: #H2-1720. Check finisher Finisher Failure: #H2-1721. Check finisher	4-74 Page
H2-1730 H2-1731	Finisher Failure: #H2-1730. Check finisher Finisher Failure: #H2-1731. Check finisher	4-75 Page
H2-1A70 H2-1750 H2-1751 H2-1753	Finisher Failure: #H2-1A70. Check finisher Finisher Failure: #H2-1750. Check finisher Finisher Failure: #H2-1751. Check finisher Finisher Failure: #H2-1753. Check finisher	4-76 Page
H2-1752	Finisher Failure: #H2-1752. Check finisher	4-77 Page
H2-1760 H2-1A80	Finisher Failure: #H2-1760. Check finisher Finisher Failure: #H2-1A80. Check finisher	4-78 Page
H2-1800	Finisher Failure: #H2-1800. Check finisher	4-79 Page
H2-1A20	Finisher door is open. Close it	4-80 Page
H2-1A32	Too much paper in finisher stacker. Remove printed paper	4-82 Page
H2-1A50	Finisher Failure: #H2-1A50. Check finisher	4-83 Page
H2-1A62	Staple cartridge is low. Replace it	4-84 page
H2-1A63	Staple cartridge is empty. Replace it	4-85 Page
H2-4100	Paper jam in front of mailbox. Remove paper	4-86 page
H2-4101	Paper jam inside of mailbox. Remove paper	4-87 page
H2-4102	Paper jam inside of mailbox. Remove paper	4-88 Page
H2-4200	Paper jam in front of bin 1. Remove paper	4-89 Page
H2-4201	Paper jam at mailbox bin 1. Remove paper	4-90 Page
H2-4202	Paper jam at mailbox bin 1. Remove paper	4-91 Page
H2-4300	Paper jam in front of bin 2. Remove paper	4-92 Page
H2-4301	Paper jam at mailbox bin 2. Remove paper	4-93 Page
H2-4302	Paper jam at mailbox bin 2. Remove paper	4-94 Page
H2-4400	Paper jam in front of bin 3. Remove paper	4-95 Page
H2-4401	Paper jam at mailbox bin 3. Remove paper	4-96 Page
H2-4402	Paper jam at mailbox bin 3. Remove paper	4-97 Page
H2-4500	Paper jam in front of bin 4. Remove paper	4-98 Page
H2-4501	Paper jam at mailbox bin 4. Remove paper	4-99 Page
H2-4502	Paper jam at mailbox bin 4. Remove paper	4-100 Page

Error Code	Error Message	Troubleshooting Page
H2-4700 H2-4701	Mailbox Failure: #H2-4700. Check mailbox Mailbox Failure: #H2-4701. Check mailbox	4-101 Page
H2-4710 H2-4711	Mailbox Failure: #H2-4710. Check mailbox Mailbox Failure: #H2-4711. Check mailbox	4-102 page
H2-4A20	Mailbox door is open. Close it	4-103 Page
H2-4A32	Too much paper in mailbox bin 1. Remove printed paper	4-104 Page
H2-4A35	Too much paper in mailbox bin 2. Remove printed paper	4-105 Page
H2-4A38	Too much paper in mailbox bin 3. Remove printed paper	4-106 Page
H2-4A3C	Too much paper in mailbox bin 4. Remove printed paper	4-107 Page
M1-1110	Paper Jam in Tray 1	4-108 Page
M1-1610	Paper Jam in MP tray	4-108 Page
M1-3122	Tray1 cassette is pulled out. Insert it properly	4-109 Page
M1-4111	Input System Failure: #M1-4111.	4-109 Page
M1-5112	Paper Empty in tray1	4-110 Page
M1-5612	Paper Empty in MP	4-110 Page
M2-1110	Paper Jam in tray1	4-111 Page
M2-2110	Jam top of duplex	4-111 Page
M2-2310	Jam bottom of duplex	4-112 Page
M2-3120	Install duplex unit.	4-112 Page
M3-1110	Jam in exit area	4-113 Page
M3-2130	Output bin full. Remove printed paper	4-113 Page
S2-4110	Door is open. Close it	4-114 Page
S2-4610	Rear Door is open. Close it	4-115 Page
S6-3123	This IP address conflicts with that of other system	4-116 Page
S6-3128	802.1x Network Error Contact the Admin.	4-116 Page
U1-2115	Fuser Unit Failure: #U1-2115. Turn off then on	4-117 Page
U1-2117	Fuser Unit Failure: #U1-2117. Turn off then on	4-120 Page
U1-2320	Fuser Unit Failure: #U1-2320. Turn off then on	4-122 Page
U1-2330	Fuser Unit Failure: #U1-2330. Turn off then on	4-125 Page
U1-2340	Fuser Unit Failure: #U1-2340. Turn off then on	4-129 Page
U2-1111	LSU Unit Failure: #U2-1111. Turn off then on	4-132 Page
U2-1113	LSU Unit Failure: #U2-1113. Turn off then on	4-133 Page


<ul style="list-style-type: none"> • Code A1-1110 	<ul style="list-style-type: none"> • Error message Actuator Motor Failure #A1-1110: Turn off then on.
<ul style="list-style-type: none"> • Symptom / Cause After working the main BLDC motor, the Ready signal has not occurred within 1 sec. <ul style="list-style-type: none"> 1. Harness is defective. Connector is not connected properly. 2. OPC coupler in the imaging unit has overloaded. 3. Main BLDC motor is defective. 4. Engine board is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method : <ul style="list-style-type: none"> ※ First, turn the machine off then on. If the error persists, refer to the following. 1. Check if the connector is connected properly. Reconnect it.  <p>The image shows the internal components of a machine, specifically the main BLDC motor area. A red box highlights a connector on a green PCB, with a label 'Main BLDC connector' pointing to it.</p> <ul style="list-style-type: none"> 2. OPC coupler has overloaded. After removing the imaging unit, rotate the OPC coupler. If there is any damage, the OPC coupler can't rotate well. Replace the imaging unit.  <p>The image shows a close-up of a hand rotating a black OPC coupler. A red circle highlights the coupler, and a label 'OPC coupler Spec : 4kgf.cm' points to it.</p>	

3. The main BLDC motor is defective.
 - Unplug the connector from the motor.
 - Replace the main BLDC motor with new one.
4. If the problem persists, replace the engine board.

<ul style="list-style-type: none"> • Code A1-1210 	<ul style="list-style-type: none"> • Error message Actuator Motor Failure #A1-1210: Turn off then on.
<ul style="list-style-type: none"> • Symptom / Cause After working the Fuser BLDC motor, the Ready signal has not occurred within 1 sec. <ol style="list-style-type: none"> 1. Harness is defective. Connector is not connected properly. 2. Heat roller in the fuser unit has overloaded. 3. Main BLDC motor is defective. 4. Engine board is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method <p>※ First, turn the machine off then on. If the error persists, refer to the following.</p> <ol style="list-style-type: none"> 1. Check if the connector is connected properly. Reconnect it.  <ol style="list-style-type: none"> 2. Heat roller in the fuser unit has overloaded. <ul style="list-style-type: none"> - Remove the fuser unit after removing rear cover and duplex unit. - Rotate the heat roller gear. If there is any damage, the heat roller gear can't rotate well. (Spec : 5kgf.cm) Replace the fuser unit. 	


3. Engine Board is defective.



- Unplug all connectors on the Engine Board.
- Remove 4 screws.
- Replace the Engine Board with new one.



4. Fuser BLDC Motor is defective.


- Remove the Main Drive unit. (Screw 5 EA, Lever Coupler)
- Remove the Engine Board & Engine Board bracket.
- Remove the Main Board & Main Board bracket.
- Remove the Rear Cover and duplex unit.
- Remove the fuser unit.
- Replace the fuser drive unit with new one.



<ul style="list-style-type: none"> • Code A1-1310 	<ul style="list-style-type: none"> • Error message Actuator Motor Failure #A1-1310: Turn off then on.
<ul style="list-style-type: none"> • Symptom / Cause After working the Pick-up BLDC motor, the Ready signal has not occurred within 1 sec. <ol style="list-style-type: none"> 1. Harness is defective. Connector is not connected properly. 2. Pick up/ Regi. clutch is defective. 3. Main BLDC motor is defective. 4. Engine board is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method <p>※First, turn the machine off then on. If the error persists, refer to the following.</p> <ol style="list-style-type: none"> 1. Check if the connector is connected properly. Reconnect it.  <ol style="list-style-type: none"> 2. Pick up/ Regi clutch is defective. <ul style="list-style-type: none"> - Remove the Regi. clutch then warm up the machine. If the corresponding error has disappeared, Regi. clutch is defective. Replace the Regi. clutch. - Remove the pick up clutch then warm up the machine. If the corresponding error has disappeared, pick up clutch is defective. Replace the pick up clutch. 	



3. Pick up BLDC motor is defective.

- Unplug all connectors on the Engine Board.
- Remove the Engine board with the bracket.
- Replace the BLDC motor with new one.





4. Engine Board is defective.

- Unplug all connectors.
- Replace the Engine board with new one after removing 4 screws.


<ul style="list-style-type: none"> • Code A1-3110 	<ul style="list-style-type: none"> • Error message Actuator Motor Failure #A1-3110
<ul style="list-style-type: none"> • Symptom / Cause <p>After working the Deve BLDC motor, the Ready signal has not occurred within 1 sec.</p> <ol style="list-style-type: none"> 1. Harness is defective. Connector is not connected properly. 2. Mag. Roller is overloaded. 3. Deve BLDC motor is defective. 4. Engine board is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method <p>※ First, turn the machine off then on. If the error persists, refer to the following.</p> <ol style="list-style-type: none"> 1. Check if the connector is connected properly. Reconnect it. <div data-bbox="188 815 798 1384">  <p style="text-align: center;">Check the connector</p> </div> <ol style="list-style-type: none"> 2. Mag roller in the imaging unit is overloaded. <ul style="list-style-type: none"> - Rotate the Mag roller. If there is any damage, the Mag roller can't be rotated well. (Spec : 4kgf.cm) Replace the imaging unit. <div data-bbox="188 1603 783 2020">  <p style="text-align: center;">Mag roller (Spec : 4kgf.cm)</p> </div>	

3. Deve BLDC motor is defective.
 - Replace the BLDC motor with new one.
4. Engine Board is defective.
 - Unplug all connectors.
 - Replace the Engine board with new one after removing 4 screws.



<ul style="list-style-type: none">• Code A2-1910	<ul style="list-style-type: none">• Error message Actuator Fan Failure: #A2-1910. Turn off then on.
<ul style="list-style-type: none">• Symptom / Cause The Main(SMPS) Fan does not work normally. <ol style="list-style-type: none">1. Fan Harness connection is bad.2. Harness is defective or GND is short.3. Fan is defective.	
<ul style="list-style-type: none">• Troubleshooting method <ol style="list-style-type: none">1. Check if the Fan Relay connector is connected properly.2. Connect the Harness Housing correctly.3. Check if the Fan harness is normal. If it is defective, replace it.4. Enter the Tech mode and execute the Main Fan test (EDC code : 100-0260 (SMPS FAN)). To enter the Tech mode, press the button in this order. (Menu - # - 1 - 9 -3 -4 - OK) 	

<ul style="list-style-type: none"> • Code A2-1920 	<ul style="list-style-type: none"> • Error message Actuator Fan Failure: #A2-1920. Turn off then on
<ul style="list-style-type: none"> • Symptom / Cause The Rear Fan does not work normally. <ol style="list-style-type: none"> 1. Fan Harness connection is bad. 2. Harness is defective or GND is short. 3. Fan is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if the Fan Relay connector is connected properly. 2. Connect the Harness Housing correctly. 3. Check if the Fan harness is normal. If it is defective, replace it. 4. Enter the Tech mode and execute the Main Fan test (EDC code : 109-0042 (Rear FAN). To enter the Tech mode, press the button in this order. (Menu - # - 1 - 9 -3 -4 - OK) <div data-bbox="189 1093 1233 1473"> </div>	

<ul style="list-style-type: none">• Code A2-2410	<ul style="list-style-type: none">• Error message Actuator Fan Failure: #A2-2410.
<ul style="list-style-type: none">• Symptom / Cause The LSU Fan does not work.	
<ul style="list-style-type: none">• Troubleshooting method <ol style="list-style-type: none">1. Check if there is any obstacle in LSU Fan.2. Check if the harness is connected properly.3. Check if the joint connector is connected properly.4. Check if the harness is defective.5. Enter the tech mode and execute the LSU fan test.6. If the fan is defective, replace it.	
	

<ul style="list-style-type: none"> ● Code A3-2110 	<ul style="list-style-type: none"> ● Error message Actuator Sensor Failure: #A3-2110.
<ul style="list-style-type: none"> ● Symptom / Cause ID control algorithm to control the density finds the ID Sensor value input in an abnormal state. <ol style="list-style-type: none"> 1. The image density of the imaging unit is abnormal. 2. ID sensor (CTD sensor) is defective. 	
<ul style="list-style-type: none"> ● Troubleshooting method <ol style="list-style-type: none"> 1. In case of density defect. Print the sample page. If the density is too low or dark, replace the imaging unit. 2. In case of ID sensor defect. Print the sample page. If the density is normal, replace the ID sensor or the sensor cleaning part. 	

<ul style="list-style-type: none"> ● Code A3-5110 	<ul style="list-style-type: none"> ● Error message Actuator Sensor Failure: #A3-5110.
<ul style="list-style-type: none"> ● Symptom / Cause The signal level of the Toner Empty sensor is 0V. 	
<ul style="list-style-type: none"> ● Troubleshooting method <ol style="list-style-type: none"> 1. Remove the Left cover. Check if the sensor connector of the WTB Pipe unit is connected properly. 2. If the harness is defective, replace it. 	

<ul style="list-style-type: none"> • Code C1-1110 	<ul style="list-style-type: none"> • Error message C1-1110 Prepare new toner cartridge.
<ul style="list-style-type: none"> • Symptom / Cause The remaining toner in cartridge is less than 10% of its life. (10% is default, this value can be adjusted.) 	
<ul style="list-style-type: none"> • Troubleshooting method Check the life remaining of the toner cartridge. If its life is at the end, turn the machine off and replace the toner cartridge with new one. 	

<ul style="list-style-type: none"> • Code C1-1120 	<ul style="list-style-type: none"> • Error message C1-1120 Replace with new toner cartridge
<ul style="list-style-type: none"> • Symptom / Cause The remaining toner in cartridge is less than 0% of its life. 	
<ul style="list-style-type: none"> • Troubleshooting method Check the life remaining of the toner cartridge. If its life is at the end, turn the machine off and replace the toner cartridge with new one. 	

<ul style="list-style-type: none"> • Code C1-1140 	<ul style="list-style-type: none"> • Error message C1-1140 Replace with new toner cartridge
<ul style="list-style-type: none"> • Symptom / Cause The toner cartridge is at the end of its life. 	
<ul style="list-style-type: none"> • Troubleshooting method Replace the toner cartridge with new one. 	

<ul style="list-style-type: none"> • Code C1-1311 C1-1412 C1-1413 C3-1312 C3-1315 	<ul style="list-style-type: none"> • Error message Toner Failure: #C1-1311: Install toner again Did not supply enough toner. Reinstall it Shake toner cartridge and then install. Imaging Unit Failure #C3-1312: Install IMG. unit. Imaging Unit Failure #C3-1315: Install IMG. unit.
<ul style="list-style-type: none"> • Symptom / Cause <p>The imaging unit does not get enough toner from the toner cartridge.</p> <ol style="list-style-type: none"> 1. The toner cartridge shutter does not work normally. 2. The imaging unit shutter does not work normally. 3. The toner cartridge seal is not removed. 4. The toner cartridge is not installed properly. 5. The toner is consumed quickly due to a defective image (Background etc.) 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Turn the machine off then on. 2. Remove the toner cartridge. Thoroughly roll the cartridge five or six times to distribute the toner evenly inside the cartridge. And reinstall the toner cartridge. 3. Try to print out the sample page more than 20 pages. 4. Check the toner cartridge. <ul style="list-style-type: none"> - Check if the toner supply shutter between the toner cartridge and the imaging unit works normally. - Remove the seal. Check if the auger rotates normally. - Reinstall the toner cartridge. 5. Replace the toner cartridge. Print out the sample page. 6. Check if the toner supply motor works normally. 	

<ul style="list-style-type: none"> • Code <p>C1-1330 C1-1411</p>	<ul style="list-style-type: none"> • Error message <p>Toner Failure: #C1-1330: Install toner again Toner cartridge is not installed. Install it</p>
<ul style="list-style-type: none"> • Symptom / Cause <p>1. The toner cartridge is not installed. 2. The toner cartridge is not installed properly.</p>	
<ul style="list-style-type: none"> • Troubleshooting method <p>1. Install the genuine samsung toner cartridge. 2. If the toner cartridge is already installed, check the following.</p> <ul style="list-style-type: none"> a. Reinstall the toner cartridge and imaging unit. b. Check If the CRUM contact is normal. c. After reinstallation, turn the machine off then on. 	


<ul style="list-style-type: none"> • Code <p>C1-1512</p>	<ul style="list-style-type: none"> • Error message <p>Toner cartridge is not compatible. Check guide</p>
<ul style="list-style-type: none"> • Symptom / Cause <p>Toner cartridge is not compatible.</p>	
<ul style="list-style-type: none"> • Troubleshooting method <p>1. Check information of the toner cartridge. 2. If the toner cartridge is not a genuine samsung toner cartridge, replace with new one.</p>	

<ul style="list-style-type: none"> • Code C3-1110 C3-1120 C3-1140 	<ul style="list-style-type: none"> • Error message Prepare new imaging unit Replace with new imaging unit Replace with new imaging unit
<ul style="list-style-type: none"> • Symptom / Cause The remaining life of the imaging unit is less than 10% of its life. The remaining life of the imaging unit is less than 0% of its life. 	
<ul style="list-style-type: none"> • Troubleshooting method Prepare the new imaging unit. 	

<ul style="list-style-type: none"> • Code C3-1320 C3-1330 C3-1411 C3-1412 	<ul style="list-style-type: none"> • Error message Imaging Unit Failure #C3-1320: Install IMG. unit. Imaging Unit Failure #C3-1330: Install IMG. unit. Imaging unit is not installed. Install the unit. Did not supply enough toner. Reinstall Toner
<ul style="list-style-type: none"> • Symptom / Cause 1. The imaging unit is not installed. 2. The imaging unit is not installed properly. 	
<ul style="list-style-type: none"> • Troubleshooting method 1. Install the samsung genuine imaging unit. 2. If the imaging unit is already installed, check the following. <ul style="list-style-type: none"> a. Reinstall the toner cartridge and imaging unit. b. Check If the CRUM contact is normal. c. After reinstallation, turn the machine off then on. 	

<ul style="list-style-type: none"> • Code <p>C3-1512 C3-1514</p>	<ul style="list-style-type: none"> • Error message <p>Imaging unit is not compatible. Check guide Imaging unit is not compatible. Check guide</p>
<ul style="list-style-type: none"> • Symptom / Cause <p>The imaging unit is not compatible.</p>	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check information of the imaging unit. 2. If the imaging unit is not a Samsung genuine imaging unit, replace with new one. 	


<ul style="list-style-type: none"> • Code <p>C5-1510</p>	<ul style="list-style-type: none"> • Error message
<ul style="list-style-type: none"> • Symptom / Cause <p>The imaging unit does not get the normal high voltage.</p> <ol style="list-style-type: none"> 1. The imaging unit is not installed properly. 2. The contact between the machine and the imaging unit is bad. 3. The imaging unit is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Remove the imaging unit. Check if the contact terminal is contaminated. Reinstall the imaging unit. And turn the machine off then on. Print 10 sample pages for test. 2. If the problem persists, replace the imaging unit. 3. If the problem persists after removing the imaging unit, replace the HVPS board or the engine board. 	

<ul style="list-style-type: none"> ● Code C6-1110 C6-1120 	<ul style="list-style-type: none"> ● Error message Replace with new fuser unit Replace with new fuser unit
<ul style="list-style-type: none"> ● Symptom / Cause The fuser unit is at the end of its life. 	
<ul style="list-style-type: none"> ● Troubleshooting method 1. Remove the Rear cover and Duplex unit. Replace the fuser unit after removing 4 screws. 	
	
<ul style="list-style-type: none"> 2. Tighten 4 screws. Assemble the Rear Cover and Duplex Unit. 	

<ul style="list-style-type: none"> ● Code C7-1110 C7-1120 	<ul style="list-style-type: none"> ● Error message Waste toner container is almost full. Replace with new one Waste toner container is almost full. Replace with new one
<ul style="list-style-type: none"> ● Symptom / Cause The waste toner container is full. 	
<ul style="list-style-type: none"> ● Troubleshooting method Replace the waste toner container with new one. 	

<ul style="list-style-type: none"> ● Code C7-1310 	<ul style="list-style-type: none"> ● Error message Install waste toner container.
<ul style="list-style-type: none"> ● Symptom / Cause The waste toner container is full. 	
<ul style="list-style-type: none"> ● Troubleshooting method Install the waste toner container. If the waste toner container is already installed, remove and reinstall it. 	

<p>• Code</p> <p>H1-1210 H1-1310 H1-1410 H1-1510</p>	<p>• Error message</p> <p>Paper Jam in Tray2 Paper Jam in Tray3 Paper Jam in Tray4 Paper Jam in Tray5</p>
<p>• Symptom / Cause</p> <p>A jammed paper has occurred in the option cassette. (SCF unit)</p>	
<p>• Troubleshooting method</p> <ol style="list-style-type: none"> Remove the jammed paper. If the problem persists, check the followings. Check if the paper is loaded in the SCF tray properly. <div data-bbox="204 801 564 1137"> </div> Check if the roller is defective or worn out. <div data-bbox="181 1211 663 1480"> </div> Check if the Empty/ Pickup/ Regi-Act sensor is working properly. <div data-bbox="189 1588 560 2024"> </div> Check if the main board/ motor/ clutch connector are connected properly. <div data-bbox="836 692 1407 958"> </div> Check if the AS-SPRING_ES is deformed or assembled properly. <div data-bbox="858 1099 1369 1447"> </div> Check if the Press D-cut of the Gear-Lifting is broken. <div data-bbox="842 1559 1410 1760"> </div> If the problem persists after checking No. 1~7, replace the SCF main board. If the problem persists, replace the Drop connector harness. 	


<ul style="list-style-type: none">• Code H1-1222 H1-1322 H1-1422 H1-1522	<ul style="list-style-type: none">• Error message Tray2 cassette is pulled out. Insert it properly. Tray3 cassette is pulled out. Insert it properly. Tray4 cassette is pulled out. Insert it properly. Tray5 cassette is pulled out. Insert it properly.
<ul style="list-style-type: none">• Symptom / Cause A optional cassette (SCF) is pulled out.	
<ul style="list-style-type: none">• Troubleshooting method <ol style="list-style-type: none">1. Check if the optional cassette is inserted properly. Remove the cassette then re-install it.2. Check if the Signal-Switch is deformed or broken. If it is defective, replace it. <div data-bbox="188 846 900 1146">The image consists of two photographs. The left photograph shows the interior of a cassette tray with a signal switch mechanism. The right photograph is a close-up of the signal switch mechanism, which is a black plastic component with four white, dome-shaped protrusions. A blue arrow points from the right image to the corresponding part in the left image.</div>	



<ul style="list-style-type: none"> • Code H1-1230 (Tray2) H1-1233 (Tray2) H1-1330 (Tray3) H1-1333 (Tray3) H1-1430 (Tray4) H1-1433 (Tray4) H1-1530 (Tray5) H1-1533 (Tray5) H1-2230 (Tray2-HCF) H1-2233 (Tray2-HCF) H1-2330 (Tray3-HCF) H1-2333 (Tray3-HCF) H1-2430 (Tray4-HCF) H1-2433 (Tray4-HCF) 	<ul style="list-style-type: none"> • Error message Input System Failure #H1-1230:Check Tray 2 connection. Input System Failure #H1-1233:Check Tray 2 connection. Input System Failure #H1-1330:Check Tray 3 connection. Input System Failure #H1-1333:Check Tray 3 connection. Input System Failure #H1-1430:Check Tray 4 connection. Input System Failure #H1-1433:Check Tray 4 connection. Input System Failure #H1-1530:Check Tray 5 connection. Input System Failure #H1-1533:Check Tray 5 connection. Input System Failure #H1-2230:Check HCF 2 connection. Input System Failure #H1-2233:Check HCF 2 connection. Input System Failure #H1-2330:Check HCF 3 connection. Input System Failure #H1-2333:Check HCF 3 connection. Input System Failure #H1-2430:Check HCF 4 connection. Input System Failure #H1-2433:Check HCF 4 connection.
<ul style="list-style-type: none"> • Symptom / Cause The communication error between the machine and option cassette has occurred. 	
<ul style="list-style-type: none"> • Troubleshooting method 1. Turn the machine off then on. 2. Remove and reinstall the corresponding optional tray. 3. Check if the option tray harness is connected properly. Reconnect or replace the harness. 4. Replace the option tray board. 5. Replace the option tray Assy. 	

<ul style="list-style-type: none"> • Code H1-1252 H1-1352 H1-1452 H1-1552 	<ul style="list-style-type: none"> • Error message Paper Empty in Tray2 Paper Empty in Tray3 Paper Empty in Tray4 Paper Empty in Tray5
<ul style="list-style-type: none"> • Symptom / Cause Paper in the optional cassette is empty. 	
<ul style="list-style-type: none"> • Troubleshooting method 1. Check if the paper in optional cassette is loaded. Load the paper. 2. Check if the empty actuator and empty sensor are assembled properly. <div data-bbox="193 819 839 1245" data-label="Image"> </div> <ul style="list-style-type: none"> 3. If the empty actuator is defective, replace it. 4. If the problem persists after replacing the empty actuator, replace the empty sensor. 	

<ul style="list-style-type: none"> • Code <p>H1-1253 H1-1353 H1-1453 H1-1553</p>	<ul style="list-style-type: none"> • Error message <p>Error : #H1-1253 Error : #H1-1353 Error : #H1-1453 Error : #H1-1553</p>
<ul style="list-style-type: none"> • Symptom / Cause <p>The paper in the optional cassette is not picked up.</p>	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if the Gear-Idle Lift is broken. <div data-bbox="172 645 885 907"> </div> 2. Check if the Signal-Switch is operated properly. If it is defective, replace it. <div data-bbox="180 981 911 1294"> </div> 3. Check if the Lift-Motor connector is connected properly. <div data-bbox="188 1361 603 1675"> </div> 4. Check if the Press D-Cut of the Gear-Lifting is deformed or broken. <div data-bbox="188 1742 837 1982"> </div> 5. If the problem persists, replace the Lift-Motor. 	

<ul style="list-style-type: none"> • Code <p>H1-2210 H1-2310 H1-2410</p>	<ul style="list-style-type: none"> • Error message <p>Paper Jam in HCF2 Paper Jam in HCF3 Paper Jam in HCF4</p>
<ul style="list-style-type: none"> • Symptom / Cause <p>A jammed paper has occurred in the option cassette. (HCF unit)</p>	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Remove the jammed paper. If the problem persists, check the followings. 2. Check if the paper is loaded in the HCF tray properly. 3. Check if the roller is defective or worn out. <div data-bbox="204 884 643 1234"> <p>Forward Roller</p> <p>Pickup Roller</p> </div> <ol style="list-style-type: none"> 4. Check if the Empty/ Pick up/ Regi-Act sensor is working properly. <div data-bbox="209 1370 683 1724"> <p>Empty Sensor</p> <p>Pickup Sensor</p> <p>Regi-Act. Sensor</p> </div> <ol style="list-style-type: none"> 5. Check if the main board/ motor/ clutch connector are connected properly. <div data-bbox="847 692 1417 1048"> </div> <ol style="list-style-type: none"> 6. PICK-UP-SPRING is deformed or assembled properly. <div data-bbox="847 1189 1417 1473"> <p>PICK-UP-SPRING</p> </div> <ol style="list-style-type: none"> 7. If the problem persists after checking No. 1~6, replace the HCF main board. 8. If the problem persists, replace the Drop connector harness. 	



<ul style="list-style-type: none">• Code H1-2222 H1-2322 H1-2422	<ul style="list-style-type: none">• Error message HCF 2 cassette Out HCF 3 cassette Out HCF 4 cassette Out
<ul style="list-style-type: none">• Symptom / Cause A optional cassette (HCF) is pulled out.	
<ul style="list-style-type: none">• Troubleshooting method <ol style="list-style-type: none">1. Check if the Cover-Front Door is closed propely. Open and Close it.2. Check if the connector of the PBA-SUB Cover Open is connected properly. If it is defective, replace it.  <ol style="list-style-type: none">3. If the connection is OK, replace the PBA-SUB Cover Open.	

<ul style="list-style-type: none"> • Code H1-2252 H1-2352 H1-2452 	<ul style="list-style-type: none"> • Error message Paper Empty in HCF 2 Paper Empty in HCF 3 Paper Empty in HCF 4
<ul style="list-style-type: none"> • Symptom / Cause Paper in the optional cassette (HCF) is empty. 	
<ul style="list-style-type: none"> • Troubleshooting method 1. Check if the paper in HCF Unit is loaded. Load the paper. 2. Check if the empty actuator and empty sensor are assembled properly. <div style="display: flex; justify-content: space-around; align-items: center;">   </div> <ul style="list-style-type: none"> 3. If the empty actuator is defective, replace it. 4. If the problem persists after replacing the empty actuator, replace the empty sensor. 	





<ul style="list-style-type: none"> • Code 	<ul style="list-style-type: none"> • Error message
H1-2253 H1-2353 H1-2453	Error : #H1-2253 Error : #H1-2353 Error : #H1-2453
<ul style="list-style-type: none"> • Symptom / Cause The paper in the optional cassette is not picked up.	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if the Gear-Coupling and Gear-Lift are broken. <div data-bbox="177 595 975 880"> <p>The diagram shows a main view of the printer's internal mechanism on the left. Two callout boxes on the right show close-ups of the Gear-Coupling and Gear-Lift. The Gear-Coupling is a white gear with a central hole, and the Gear-Lift is a similar gear with a different profile. Red dots in the callouts point to the center of each gear.</p> </div> 2. Check if the SPRING-ES and SPRING-CS are assembled properly. <div data-bbox="181 929 943 1182"> <p>The diagram shows a main view of the printer's internal mechanism on the left. Two callout boxes on the right show close-ups of the SPRING-ES and SPRING-CS. The SPRING-ES is a small black spring, and the SPRING-CS is a larger black spring. Red dots in the callouts point to the center of each spring.</p> </div> 3. Check if the Lift-Motor connector is connected properly. <div data-bbox="185 1240 541 1597"> <p>The diagram shows the internal mechanism with a red box highlighting the Lift-Motor connector. A callout box labeled 'PBA-SUB Cover Open' points to the connector. A red dot in the callout points to the connector.</p> </div> 4. Check if the Press D-Cut of the Gear-Lifting is deformed or broken. <div data-bbox="185 1653 517 1935"> <p>The diagram shows a close-up of the Gear-Lifting mechanism. A red box highlights the Press D-Cut, which is a small notch in the gear. A red dot in the callout points to the notch.</p> </div> 5. If the problem persists, replace the Lift-Motor. 	

<p>• Code H2-1100</p>	<p>• Error message Paper jam inside of finisher. Remove paper</p>
<p>• Symptom / Cause Finisher Entrance sensor actuator does not return after a paper covers it</p> <p>IOT Exit Roller grabs the paper. Or Finisher Feeding Motors Stopped. Or Finisher Entrance Sensor damaged or harness damaged. Or Finisher Main Board damaged</p>	
<p>• Troubleshooting method</p> <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. <ul style="list-style-type: none"> - If the IOT roller is grabbing the paper, it's IOT fault 2. Check the Main Board Harness Connection. <div data-bbox="172 896 743 1272" data-label="Image"> </div> 3. Check Finisher Entrance operation & harness connection. <div data-bbox="172 1406 748 1783" data-label="Image"> </div> 4. Check Finisher Feeding Entrance Motor Harness Connection and operation. <div data-bbox="839 779 1422 1155" data-label="Image"> </div> 5. Check Finisher Feeding Exit Motor Harness Connection and operation. <div data-bbox="839 1279 1422 1655" data-label="Image"> </div> 6. If the same problem happens after checking 1~5, Replace the Finisher main board. 7. If the same problem happens after checking 5, replace the Finisher harnesses. 	


<ul style="list-style-type: none"> • Code H2-1101 	<ul style="list-style-type: none"> • Error message Paper jam in front of finisher. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Paper doesn't reach Finisher's Entrance Sensor. Paper jam in IOT. Or Finisher Diverter operation not well. Or IOT Deflector Damaged. Or Finisher Entrance Sensor not working (Finisher Entrance Sensor Damaged, Harness connection not well, Main Board damaged) 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. 2. Check IOT Deflector part's operation. 3. Check the Main Board Harness Connection. 4. Check Finisher's Entrance operation & harness connection 5. Referring to H2-1800, Check the Finisher Diverter operation. 6. If the same problem happens after checking 1~5, Replace the Finisher main board. 7. If the same problem happens after checking 6, replace the Finisher harnesses. 	



<ul style="list-style-type: none"> • Code H2-1102 	<ul style="list-style-type: none"> • Error message Paper jam inside of finisher. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Initialization started with Jammed paper covering Finisher Entrance Sensor. Paper exists covering Finisher Entrance Sensor. Or Finisher Entrance Sensor Damaged or harness connection not well. Or Finisher Main Board damaged 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if there is a jammed paper inside Finisher. 2. Check the Main Board Harness Connection. 3. Check Finisher Entrance operation & harness connection. 4. If the same problem happens after checking 1~3, Replace the Finisher main board. 5. If the same problem happens after checking 4, replace the Finisher harnesses. <div data-bbox="172 824 745 1200" data-label="Image"> </div> <div data-bbox="172 1339 745 1715" data-label="Image"> </div>	






<ul style="list-style-type: none"> • Code H2-1200 	<ul style="list-style-type: none"> • Error message Paper jam inside of finisher. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Finisher Exit Sensor doesn't turn on after a paper entered Finisher. IOT Exit Roller grabs the paper. Or Finisher Feeding Motors Stopped. Or Finisher Exit Sensor damaged or harness damaged. Or Finisher Main Board damaged 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. <ul style="list-style-type: none"> - If the IOT roller is grabbing the paper, it's IOT fault. 2. Check the Main Board Harness Connection.  3. Check Finisher Exit Sensor operation & harness connection.  4. Check Finisher Feeding Entrance Motor Harness Connection and operation.  5. Check Finisher Feeding Exit Motor Harness Connection and operation.  6. If the same problem happens after checking 1~5, Replace the Finisher main board. 7. If the same problem happens after checking 6, replace the Finisher harnesses. 	

<p>● Code H2-1300</p>	<p>● Error message Paper jam inside of finisher. Remove paper</p>
<p>● Symptom / Cause Finisher Exit Sensor doesn't turn off after the sensor turned on</p> <p>IOT Exit Roller grabs the paper. Or Finisher Feeding Motors Stopped. Or Finisher Exit Sensor damaged or harness damaged. Or Finisher Main Board damaged</p>	
<p>● Troubleshooting method</p> <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. - If the IOT roller is grabbing the paper, it's IOT fault. 2. Check the Main Board Harness Connection. 3. Check Finisher Exit Sensor operation & harness connection. 4. Check Finisher Feeding Entrance Motor Harness Connection and operation. 5. Check Finisher Feeding Exit Motor Harness Connection and operation. 6. If the same problem happens after checking 1~5, Replace the Finisher main board. 7. If the same problem happens after checking 6, replace the Finisher harnesses. 	







<ul style="list-style-type: none"> • Code H2-1302 	<ul style="list-style-type: none"> • Error message Paper jam inside of finisher. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Initialization started with Jammed paper covering Finisher Exit Sensor. Paper exists covering Finisher Exit Sensor. Or Finisher Exit Sensor Damaged or harness connection not well. Or Finisher Main Board damaged 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if there is a jammed paper on the feeding path of Finisher. <div data-bbox="172 797 748 1173" data-label="Image"> </div> 2. Check the Main Board Harness Connection. <div data-bbox="172 1279 748 1655" data-label="Image"> </div> 3. Check Finisher Exit sensors' operation & harness connection. <div data-bbox="839 797 1415 1173" data-label="Image"> </div> 4. If the same problem happens after checking 1~3, Replace the Finisher main board. 5. If the same problem happens after checking 4, replace the Finisher harnesses. 	







<ul style="list-style-type: none"> • Code <p>H2-1710 H2-1711</p>	<ul style="list-style-type: none"> • Error message <p>Finisher Failure: #H2-1710. Check finisher Finisher Failure: #H2-1711. Check finisher</p>
<ul style="list-style-type: none"> • Symptom / Cause <p>Front Jogger is not working well.</p> <p>Front Jogger Home Sensor, Front Jogger Motor Harness Connection not well or damaged, Main Board damaged.</p>	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check the Main Board Harness Connection. <div data-bbox="172 734 746 1106" data-label="Image"> </div> 2. Check the Finisher Front Jogger Home Sensor's Harness Connection. <div data-bbox="172 1245 746 1617" data-label="Image"> </div> 3. Check the Finisher Front Jogger Motor's Harness Connection and operation. <div data-bbox="842 775 1417 1146" data-label="Image"> </div> 4. Check if Front jogger part is contaminated. <div data-bbox="842 1245 1417 1617" data-label="Image"> </div> 5. If the same problem happens after checking 1~4, Replace the Finisher main board. 6. If the same problem happens after checking 5, Replace the Finisher harnesses. 	

<ul style="list-style-type: none"> • Code H2-1720 H2-1721 	<ul style="list-style-type: none"> • Error message Finisher Failure: #H2-1720. Check finisher Finisher Failure: #H2-1721. Check finisher
<ul style="list-style-type: none"> • Symptom / Cause Rear Jogger is not working well. Rear Jogger Home Sensor, Rear Jogger Motor Harness Connection not well or damaged, Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check the Main Board Harness Connection.  2. Check the Finisher Rear Jogger Home Sensor's Harness Connection.  3. Check the Finisher Rear Jogger Motor's Harness Connection and operation.  4. Check if Rear jogger part is contaminated.   5. If the same problem happens after checking 1~4, Replace the Finisher main board. 6. If the same problem happens after checking 5, Replace the Finisher harnesses. 	

<ul style="list-style-type: none"> • Code <p>H2-1730 H2-1731</p>	<ul style="list-style-type: none"> • Error message <p>Finisher Failure: #H2-1730. Check finisher Finisher Failure: #H2-1731. Check finisher</p>
<ul style="list-style-type: none"> • Symptom / Cause <p>Support Finger (Extension Tray) is not working well.</p> <p>Support Finger Home Sensor, Support Finger Motor Harness Connection not well or damaged, Main Board damaged</p>	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check the Main Board Harness Connection. <div data-bbox="172 752 746 1126" data-label="Image"> </div> <ol style="list-style-type: none"> 2. Check the Finisher Support Finger Home Sensor's Harness Connection. <div data-bbox="172 1258 746 1632" data-label="Image"> </div> <ol style="list-style-type: none"> 3. Check the Finisher Support Finger Motor's Harness Connection and operation. <div data-bbox="839 788 1422 1167" data-label="Image"> </div> <ol style="list-style-type: none"> 4. If the same problem happens after checking 1~3, Replace the Finisher main board. 5. If the same problem happens after checking 4, Replace the Finisher harnesses. 	

<p>• Code</p> <p>H2-1A70 H2-1750 H2-1751 H2-1753</p>	<p>• Error message</p> <p>Finisher Failure: #H2-1A70. Check finisher Finisher Failure: #H2-1750. Check finisher Finisher Failure: #H2-1751. Check finisher Finisher Failure: #H2-1753. Check finisher</p>
<p>• Symptom / Cause</p> <p>Stapler is not working well.</p> <p>Stapler Harness Connection not well. Or Cartridge set sensors damaged, Or Main Board damaged.</p>	
<p>• Troubleshooting method</p> <p>NOTE - Make sure that the staple strips on top of the stack are complete and flat. Remove any partial strips and any strips that are bent.</p> <p>1. Check the Main Board Harness Connection.</p>  <p>2. Check the Stapler harness connection.</p>  <p>3. Check if staples are stuck in Stapler Head area and damage of Stapler itself.</p>   <p>4. If the same problem happens after checking 1~3, Replace the Finisher main board.</p> <p>5. If the same problem happens after checking 4, Replace the Finisher Stapler.</p> <p>6. If the same problem happens after checking 5, Replace the Finisher harnesses.</p>	

<ul style="list-style-type: none"> • Code H2-1752 	<ul style="list-style-type: none"> • Error message Finisher Failure: #H2-1752. Check finisher
<ul style="list-style-type: none"> • Symptom / Cause Finisher compiles all the papers and moves them to stapling position and do nothing. the message “Stapler Safety Fault” pops up. Safety Switch Harness connection not well. Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check the Main Board Harness Connection. <div data-bbox="172 757 746 1099" data-label="Image"> </div> 2. Check the Safety Switch Harness Connection. <div data-bbox="172 1200 746 1543" data-label="Image"> </div> 3. Check the Safety Unit's operation. Check the switch is clicked when the Safety Link moves. <div data-bbox="172 1677 746 2020" data-label="Image"> </div> 4. Check the Safety Unit's operation using Rear Jogger. The same “switch ON/OFF” operation should be followed. <div data-bbox="842 831 1417 1196" data-label="Image"> </div> 5. Check the Safety Unit's operation. When Rear Jogger stands at the position having the Shield and Rear Jogger met, the Safety Switch should be ON. <div data-bbox="842 1406 1417 1771" data-label="Image"> </div> 6. If the same problem happens after checking 1~5, Replace the Finisher main board. 7. If the same problem happens after checking 6, Replace the Finisher harnesses. 	

<p>• Code H2-1760 H2-1A80</p>	<p>• Error message Finisher Failure: #H2-1760. Check finisher Finisher Failure: #H2-1A80. Check finisher</p>
<p>• Symptom / Cause Stacker Unit is not working.</p> <p>Stacker Level sensor, Stack Full sensor, Stacker Motor Harness Connection not well or damaged, Main Board damaged.</p>	
<p>• Troubleshooting method</p> <ol style="list-style-type: none"> 1. Check the Main Board Harness Connection. <div data-bbox="172 678 746 1037">  <p>A photograph of a green printed circuit board (PCB) with various electronic components. A red circle highlights a specific area where multiple black cables are connected to the board.</p> </div> 2. Check the Stacker Level Sensor's Harness Connection and Actuator's operation & its Spring behind the wall. <div data-bbox="172 1205 746 1563">  <p>A photograph showing the internal components of a stacker unit. Two red circles highlight specific points where harnesses are connected to sensors or actuators.</p> </div> <div data-bbox="172 1574 746 1966">  <p>A photograph showing a mechanical actuator and its associated spring mechanism. Two red circles highlight the connection points and the spring itself.</p> </div> 3. Check the Stacker Motor Harness Connection and operation. <div data-bbox="842 712 1417 1025">  <p>A photograph of a motor assembly with a gear. A red circle highlights the electrical harness connection to the motor.</p> </div> <div data-bbox="842 1037 1417 1350">  <p>A close-up photograph of the motor harness connection. A red circle highlights the specific connection point.</p> </div> 4. Check the Stack Full Sensor Connection and operation. <div data-bbox="842 1485 1417 1809">  <p>A photograph showing the stack full sensor mechanism. A red circle highlights the sensor's connection point.</p> </div> 5. If the same problem happens after checking 1~3, Replace the Finisher main board. 6. If the same problem happens after checking 4, replace the Finisher harnesses. 	


<p>• Code H2-1800</p>	<p>• Error message Finisher Failure: #H2-1800. Check finisher</p>
<p>• Symptom / Cause Diverter is not working.</p> <p>Diverter Motor, Sensor Harness Connection not well or damaged. Main Board Damaged. IOT's Deflector damaged.</p>	
<p>• Troubleshooting method</p> <ol style="list-style-type: none"> 1. Check the Main Board Harness Connection. <div data-bbox="172 757 746 1102" data-label="Image"> </div> 2. Check the IOT's Deflector operation. <div data-bbox="172 1196 746 1545" data-label="Image"> </div> 3. Check Diverter sensor harness connection. <div data-bbox="172 1639 746 2011" data-label="Image"> </div> 4. Diverter Motor Harness Connection and operation. <div data-bbox="839 797 1420 1173" data-label="Image"> </div> 5. Check if Diverter Unit is not contaminated. <div data-bbox="839 1272 1420 1644" data-label="Image"> </div> 6. If the same problem happens after checking 1~5, Replace the Finisher main board. 7. If the same problem happens after checking 6, replace the Finisher harnesses. 	

<p>• Code H2-1A20</p>	<p>• Error message Finisher door is open. Close it</p>
<p>• Symptom / Cause Finisher Motors doesn't work.</p> <p>Jam Cover Opened, Jam Cover not assembled well or Jam Cover Flag damaged, Stapler Door Opened, Stapler Door Micro Switch not assembled well or Stapler Door Flag damaged, Harness Damaged. Main Board Damaged, door flag damaged.</p>	
<p>• Troubleshooting method</p> <ol style="list-style-type: none"> 1. Check the Jam Cover and Stapler Door Closed firmly. <div data-bbox="172 824 746 1126" data-label="Image"> </div> 2. Check if Mounting Part not damaged <ul style="list-style-type: none"> - Male part in Finisher - Female part in IOT <div data-bbox="172 1285 759 1469" data-label="Image"> </div> 3. Check the Main Board Harness Connection. <div data-bbox="172 1570 748 1912" data-label="Image"> </div> 4. Check the Stapler Door Switch Harness Connection. <div data-bbox="841 824 1422 1205" data-label="Image"> </div> 5. Check the Stapler Door flag damaged. <div data-bbox="844 1301 1417 1673" data-label="Image"> </div> 	

6. Check the Jam Cover Sensor Harness connection.



7. Check the Jam Cover flag damaged










8. If the same problem happens after checking 1~7, Replace the Finisher main board.

9. If the same problem happens after checking 8, replace the Finisher harnesses.


<ul style="list-style-type: none"> • Code H2-1A32 	<ul style="list-style-type: none"> • Error message Too much paper in finisher stacker. Remove printed paper
<ul style="list-style-type: none"> • Symptom / Cause Finisher Full message pops when papers on the Stacker Tray are stacked fully or the full sensor detecting mechanism is out of order Finisher Full detecting sensor damaged, harness connection not well or damaged, Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method 1. Check the Stacker Tray's Full Sensor Connection and check if Flag is damaged - The sensor must not be covered besides the full detecting flag. <div data-bbox="162 792 724 1160" data-label="Image"> </div> <div data-bbox="753 792 1315 1160" data-label="Image"> </div> 2. Check Finisher Main Board Harness Connection. <div data-bbox="162 1263 737 1626" data-label="Image"> </div> 3. If the same problem happens after checking 1~2, Replace the Finisher main board. 4. If the same problem happens after checking 3, Replace the Finisher harnesses. 	

<ul style="list-style-type: none"> • Code H2-1A50 	<ul style="list-style-type: none"> • Error message Finisher Failure: #H2-1A50. Check finisher
<ul style="list-style-type: none"> • Symptom / Cause Finisher doesn't work because of Communication error between finisher and IOT. Interface Cable Connection not well or Interface Cable(Harness) damaged, Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if Mounting Part not damaged <ul style="list-style-type: none"> - Male part in Finisher - Female part in IOT <div data-bbox="162 792 531 1028" data-label="Image"> </div> <div data-bbox="564 792 917 1028" data-label="Image"> </div> 2. Check the Main Board Harness Connection. <div data-bbox="162 1128 737 1498" data-label="Image"> </div> 3. If the same problem happens after checking 1~2, Replace the Finisher main board.. 4. If the same problem happens after checking 3, Replace the Finisher harnesses 	

<ul style="list-style-type: none"> • Code H2-1A62 	<ul style="list-style-type: none"> • Error message Staple cartridge is low. Replace it
<ul style="list-style-type: none"> • Symptom / Cause No more stapling job will not be performed if the near empty Stapler Cartridge will not be replaced soon. The staples in Staple Cartridge are going to a shortage. Or Stapler harness connection now well. Or Stapler set sensors damaged, Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if staples in cartridge are in some level. <ul style="list-style-type: none"> - With such level like the below picture during jobs, The sensor detects it as "Low". Only twenty more stapling jobs can be performed normally.  <p>NOTE - Make sure that the staple strips on top of the stack are complete and flat. Remove any partial strips and any strips that are bent.</p> 2. If the Cartridge is not low after checking with your naked eyes, Check the Stapler Harness connection  3. Check the Cartridge Set sensor's operation. 4. Check the Main Board Harness connection.  5. If the same problem happens after checking 1~4, replace the Finisher main board. 6. If the same problem happens after checking 5, replace the Finisher Stapler. 7. If the same problem happens after checking 6, replace the Finisher harnesses. 	

<p>● Code H2-1A63</p>	<p>● Error message Staple cartridge is empty. Replace it</p>
<p>● Symptom / Cause Finisher doesn't staple.</p> <p>Staple Cartridge is not inserted Or Staples are in short supply. Or Stapler Harness connection not well. Or Cartridge set sensor damaged, Or Main Board damaged.</p>	
<p>● Troubleshooting method</p> <div style="display: flex; justify-content: space-between;"> <div style="width: 48%;"> <p>1. Check if Cartridge exists.</p>  <p>2. Check if Cartridge is inserted firmly.</p> <p>3. Check if staples in cartridge are in some level. - With such level like the below picture or lower during POPO(Power off power on), The sensor detects it "empty".</p>  <p>NOTE - Make sure that the staple strips on top of the stack are complete and flat. Remove any partial strips and any strips that are bent.</p> </div> <div style="width: 48%;"> <p>4. Check the Stapler harness connection.</p>  <p>5. Check the Cartridge Set sensors' operation.</p> <p>6. Check the Main Board Harness Connection.</p>  <p>7. If the same problem happens after checking 1~6, replace the Finisher main board.</p> <p>8. If the same problem happens after checking 7, replace the Finisher Stapler.</p> <p>9. If the same problem happens after checking 8, replace the Finisher harnesses.</p> </div> </div>	

<ul style="list-style-type: none"> • Code H2-4100 	<ul style="list-style-type: none"> • Error message Paper jam in front of mailbox. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Paper doesn't reach Mailbox's Entrance Sensor. Paper jam in IOT. Or Mailbox Lower Diverter operation not well. Or IOT Deflector Damaged. Or Mailbox Entrance Sensor not working (Mailbox Entrance Sensor Damaged, Harness connection not well, MainBoard damaged) 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. 2. Check IOT Deflector part's operation. 3. Check Mailbox Main Board Harness connection. 4. Check Mailbox Entrance operation & harness connection. 5. Refer to the Lower Diverter fault. 6. If the same problem happens after checking 1~5, Replace the mailbox main board. 7. If the same problem happens after checking 6, Replace the mailbox harnesses. 	








<ul style="list-style-type: none"> • Code H2-4101 	<ul style="list-style-type: none"> • Error message Paper jam inside of mailbox. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Mailbox Entrance sensor actuator does not return after a paper covers it. IOT Exit Roller grabs the paper. Or Mailbox Feeding Motor Stops. Or Mailbox Entrance Sensor damaged or harness damaged. Or Mailbox Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. <ul style="list-style-type: none"> - If the IOT roller is grabbing the paper, it's IOT fault. 2. Check Mailbox Main Board Harness connection. <div data-bbox="264 909 657 1491" data-label="Image"> </div> 3. Check Mailbox Entrance operation & harness connection. <div data-bbox="177 1621 745 1989" data-label="Image"> </div> 4. Check Mailbox Feeding Motor Harness connection and operation. <div data-bbox="845 792 1414 1164" data-label="Image"> </div> 5. If the same problem happens after checking 1~4, replace the mailbox main board. 6. If the same problem happens after checking 5, replace the mailbox harnesses. 	

<ul style="list-style-type: none"> • Code H2-4102 	<ul style="list-style-type: none"> • Error message Paper jam inside of mailbox. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Initialization started with Jammed paper covering Mailbox Entrance Sensor. Paper exists covering Mailbox Entrance Sensor. Or Mailbox Entrance Sensor Damaged or harness connection not well. Or Mailbox Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if there is a jammed paper inside Mailbox. 2. Check Mailbox Main Board Harness connection. 3. Check Mailbox Entrance operation & harness connection. 4. If the same problem happens after checking 1~3, replace the mailbox main board. 5. If the same problem happens after checking 4, replace the mailbox harnesses. <div data-bbox="264 831 657 1411" data-label="Image"> </div> <div data-bbox="177 1541 745 1906" data-label="Image"> </div>	






<ul style="list-style-type: none"> • Code H2-4200 	<ul style="list-style-type: none"> • Error message Paper jam in front of bin 1. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Mailbox Bin 1 Exit Sensor doesn't turn on after a paper entered Mailbox. IOT Exit Roller grabs the paper. Or Mailbox Feeding Motor Stops. Or Mailbox Entrance Exit Sensor damaged or Mailbox Gate doesn't work or harness damaged. Or Mailbox Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. - If the IOT roller is grabbing the paper, it's IOT fault. 2. Check Mailbox Main Board Harness connection. <div data-bbox="312 902 609 1344" data-label="Image"> </div> 3. Check Mailbox Exit-related Sensors operation & harness connection. <div data-bbox="277 1476 644 1742" data-label="Image"> </div> <div data-bbox="277 1756 644 1989" data-label="Image"> </div> 4. Check Mailbox Feeding Motor Harness Connection and operation. <div data-bbox="847 779 1414 1149" data-label="Image"> </div> 5. Referring to Upper Diverter Fault, check the Upper Diverter's operation. 6. Referring to Lower Diverter Fault, check the Lower Diverter's operation 7. If the same problem happens after checking 1~6, replace the mailbox main board. 8. If the same problem happens after checking 7, replace the mailbox harnesses. 	

<ul style="list-style-type: none"> • Code H2-4201 	<ul style="list-style-type: none"> • Error message Paper jam at mailbox bin 1. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Mailbox Bin 1 Exit Sensor doesn't turn off after the sensor turned on. IOT Exit Roller grabs the paper. Or Mailbox Feeding Motor Stops. Or Mailbox Entrance Exit Sensor damaged or Mailbox Gate doesn't work or harness damaged. Or Mailbox Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. - If the IOT roller is grabbing the paper, it's IOT fault. 2. Check Mailbox Main Board Harness connection. <div data-bbox="312 902 609 1344" data-label="Image"> </div> 3. Check Mailbox Exit-related Sensors operation & harness connection. <div data-bbox="277 1476 644 1742" data-label="Image"> </div> <div data-bbox="277 1756 644 1989" data-label="Image"> </div> 4. Check Mailbox Feeding Motor Harness Connection and operation. <div data-bbox="844 779 1414 1149" data-label="Image"> </div> 5. Referring to Upper Diverter Fault, check the Upper Diverter's operation. 6. Referring to Lower Diverter Fault, check the Lower Diverter's operation 7. If the same problem happens after checking 1~6, replace the mailbox main board. 8. If the same problem happens after checking 7, replace the mailbox harnesses. 	




<ul style="list-style-type: none"> • Code H2-4202 	<ul style="list-style-type: none"> • Error message Paper jam at mailbox bin 1. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Initialization started with Jammed paper covering Mailbox Bin1 Exit Sensor. Paper exists covering Mailbox Exit Sensor. Or Mailbox Exit Sensor Damaged or harness connection not well. Or Mailbox Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if there is a jammed paper on the feeding path of Mailbox. <div style="display: flex; justify-content: space-around; margin-top: 10px;"> <div style="text-align: center;">   </div> <div style="text-align: center;">   </div> </div> 2. Check Mailbox Main Board Harness connection. <div style="text-align: center; margin-top: 10px;">  </div> 3. Check Mailbox Bin1 Exit-related sensors' operation & harness connection. 4. If the same problem happens after checking 1~3, replace the mailbox main board. 5. If the same problem happens after checking 4, replace the mailbox harnesses. 	

<ul style="list-style-type: none"> • Code H2-4300 	<ul style="list-style-type: none"> • Error message Paper jam in front of bin 2. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Mailbox Bin 2 Exit Sensor doesn't turn on after a paper entered Mailbox. IOT Exit Roller grabs the paper. Or Mailbox Feeding Motor Stops. Or Mailbox Entrance Exit Sensor damaged or Mailbox Gate doesn't work or harness damaged. Or Mailbox Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. <ul style="list-style-type: none"> - If the IOT roller is grabbing the paper, it's IOT fault. 2. Check Mailbox Main Board Harness connection. <div data-bbox="312 898 609 1339" data-label="Image"> </div> 3. Check Mailbox Exit-related Sensors operation & harness connection. <div data-bbox="277 1473 644 1738" data-label="Image"> </div> <div data-bbox="277 1751 644 1986" data-label="Image"> </div> 4. Check Mailbox Feeding Motor Harness Connection and operation. <div data-bbox="845 775 1414 1146" data-label="Image"> </div> 5. Referring to Upper Diverter Fault, check the Upper Diverter's operation. 6. Referring to Lower Diverter Fault, check the Lower Diverter's operation 7. If the same problem happens after checking 1~6, replace the mailbox main board. 8. If the same problem happens after checking 7, replace the mailbox harnesses. 	

<ul style="list-style-type: none"> • Code H2-4301 	<ul style="list-style-type: none"> • Error message Paper jam in front of bin 2. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Mailbox Bin 2 Exit Sensor doesn't turn off after the sensor turned on. IOT Exit Roller grabs the paper. Or Mailbox Feeding Motor Stops. Or Mailbox Entrance Exit Sensor damaged or Mailbox Gate doesn't work or harness damaged. Or Mailbox Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. - If the IOT roller is grabbing the paper, it's IOT fault. 2. Check Mailbox Main Board Harness connection. <div data-bbox="311 898 611 1341" data-label="Image"> </div> 3. Check Mailbox Exit-related Sensors operation & harness connection. <div data-bbox="277 1473 644 1740" data-label="Image"> </div> <div data-bbox="277 1751 644 1986" data-label="Image"> </div> 4. Check Mailbox Feeding Motor Harness Connection and operation. <div data-bbox="845 775 1415 1146" data-label="Image"> </div> 5. Referring to Upper Diverter Fault, check the Upper Diverter's operation. 6. Referring to 12-945, 12-955 Check the Lower Diverter's operation 7. If the same problem happens after checking 1~6, replace the mailbox main board. 8. If the same problem happens after checking 7, replace the mailbox harnesses. 	

<ul style="list-style-type: none"> • Code H2-4302 	<ul style="list-style-type: none"> • Error message Paper jam at mailbox bin 2. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Initialization started with Jammed paper covering Mailbox Bin2 Exit Sensor. Paper exists covering Mailbox Exit Sensor. Or Mailbox Exit Sensor Damaged or harness connection not well. Or Mailbox Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <p>1. Check if there is a jammed paper on the feeding path of Mailbox.</p>   </div> <div style="width: 45%;"> <p>3. Check Mailbox Bin2 Exit-related sensors' operation & harness connection.</p>   </div> </div> <p>2. Check Mailbox Main Board Harness connection.</p>  <div style="display: flex; justify-content: space-between; margin-top: 20px;"> <div style="width: 45%;"> <p>4. If the same problem happens after checking 1~3, replace the mailbox main board.</p> </div> <div style="width: 45%;"> <p>5. If the same problem happens after checking 4, replace the mailbox harnesses.</p> </div> </div>	

<p>• Code H2-4400</p>	<p>• Error message Paper jam in front of bin 3. Remove paper</p>
<p>• Symptom / Cause Mailbox Bin 3 Exit Sensor doesn't turn on after a paper entered Mailbox. IOT Exit Roller grabs the paper. Or Mailbox Feeding Motor Stops. Or Mailbox Entrance Exit Sensor damaged or Mailbox Gate doesn't work or harness damaged. Or Mailbox Main Board damaged.</p>	
<p>• Troubleshooting method</p> <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. - If the IOT roller is grabbing the paper, it's IOT fault. 2. Check Mailbox Main Board Harness connection. 3. Check Mailbox Exit-related Sensors operation & harness connection. 4. Check Mailbox Feeding Motor Harness Connection and operation. 5. Referring to Upper Diverter Fault, check the Upper Diverter's operation. 6. Referring to Lower Diverter Fault, check the Lower Diverter's operation 7. If the same problem happens after checking 1~6, replace the mailbox main board. 8. If the same problem happens after checking 7, replace the mailbox harnesses. 	













<ul style="list-style-type: none"> • Code H2-4401 	<ul style="list-style-type: none"> • Error message Paper jam at mailbox bin 3. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Mailbox Bin 3 Exit Sensor doesn't turn off after the sensor turned on. IOT Exit Roller grabs the paper. Or Mailbox Feeding Motor Stops. Or Mailbox Entrance Exit Sensor damaged or Mailbox Gate doesn't work or harness damaged. Or Mailbox Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. <ul style="list-style-type: none"> - If the IOT roller is grabbing the paper, it's IOT fault. 2. Check Mailbox Main Board Harness connection. <div data-bbox="312 902 609 1344" data-label="Image"> </div> 3. Check Mailbox Exit-related Sensors operation & harness connection. <div data-bbox="277 1476 644 1742" data-label="Image"> </div> <div data-bbox="277 1756 644 1989" data-label="Image"> </div> 4. Check Mailbox Feeding Motor Harness Connection and operation. <div data-bbox="845 779 1414 1151" data-label="Image"> </div> 5. Referring to Upper Diverter Fault, check the Upper Diverter's operation. 6. Referring to Lower Diverter Fault, check the Lower Diverter's operation 7. If the same problem happens after checking 1~6, replace the mailbox main board. 8. If the same problem happens after checking 7, replace the mailbox harnesses. 	






<ul style="list-style-type: none"> • Code H2-4402 	<ul style="list-style-type: none"> • Error message Paper jam at mailbox bin 3. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Initialization started with Jammed paper covering Mailbox Bin3 Exit Sensor. Paper exists covering Mailbox Exit Sensor. Or Mailbox Exit Sensor Damaged or harness connection not well. Or Mailbox Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if there is a jammed paper on the feeding path of Mailbox. <div data-bbox="231 792 691 1097" data-label="Image"> </div> <div data-bbox="231 1120 691 1422" data-label="Image"> </div> 2. Check Mailbox Main Board Harness connection. <div data-bbox="301 1514 620 1984" data-label="Image"> </div> 3. Check Mailbox Bin3 Exit-related sensors' operation & harness connection. <div data-bbox="946 792 1313 1059" data-label="Image"> </div> <div data-bbox="946 1072 1313 1305" data-label="Image"> </div> 4. If the same problem happens after checking 1~3, replace the mailbox main board. 5. If the same problem happens after checking 4, replace the mailbox harnesses. 	

<ul style="list-style-type: none"> • Code H2-4500 	<ul style="list-style-type: none"> • Error message Paper jam in front of bin 4. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Mailbox Bin 4 Exit Sensor doesn't turn on after a paper entered Mailbox. IOT Exit Roller grabs the paper. Or Mailbox Feeding Motor Stops. Or Mailbox Entrance Exit Sensor damaged or Mailbox Gate doesn't work or harness damaged. Or Mailbox Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. <ul style="list-style-type: none"> - If the IOT roller is grabbing the paper, it is IOT fault. 2. Check Mailbox Main Board Harness connection. <div data-bbox="312 902 609 1344" data-label="Image"> </div> 3. Check Mailbox Exit-related Sensors operation & harness connection. <div data-bbox="277 1476 644 1742" data-label="Image"> </div> <div data-bbox="277 1756 644 1989" data-label="Image"> </div> 4. Check Mailbox Feeding Motor Harness Connection and operation. <div data-bbox="844 779 1414 1149" data-label="Image"> </div> 5. Referring to Upper Diverter Fault, check the Upper Diverter's operation. 6. Referring to Lower Diverter Fault, check the Lower Diverter's operation 7. If the same problem happens after checking 1~6, replace the mailbox main board. 8. If the same problem happens after checking 7, replace the mailbox harnesses. 	

<ul style="list-style-type: none"> • Code H2-4501 	<ul style="list-style-type: none"> • Error message Paper jam at mailbox bin 4. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Mailbox Bin 4 Exit Sensor doesn't turn off after the sensor turned on. IOT Exit Roller grabs the paper. Or Mailbox Feeding Motor Stops. Or Mailbox Entrance Exit Sensor damaged or Mailbox Gate doesn't work or harness damaged. Or Mailbox Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check Jam Occurrence in IOT. - If the IOT roller is grabbing the paper, it's IOT fault. 2. Check Mailbox Main Board Harness connection. <div data-bbox="312 902 609 1346" data-label="Image"> </div> 3. Check Mailbox Exit-related Sensors operation & harness connection. <div data-bbox="277 1476 644 1744" data-label="Image"> </div> <div data-bbox="277 1756 644 1989" data-label="Image"> </div> 4. Check Mailbox Feeding Motor Harness Connection and operation. <div data-bbox="839 779 1407 1149" data-label="Image"> </div> 5. Referring to Upper Diverter Fault, check the Upper Diverter's operation. 6. Referring to Lower Diverter Fault, check the Lower Diverter's operation 7. If the same problem happens after checking 1~6, replace the mailbox main board. 8. If the same problem happens after checking 7, replace the mailbox harnesses. 	




<ul style="list-style-type: none"> • Code H2-4502 	<ul style="list-style-type: none"> • Error message Paper jam at mailbox bin 4. Remove paper
<ul style="list-style-type: none"> • Symptom / Cause Initialization started with Jammed paper covering Mailbox Bin4 Exit Sensor. Paper exists covering Mailbox Exit Sensor. Or Mailbox Exit Sensor Damaged or harness connection not well. Or Mailbox Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <p>1. Check if there is a jammed paper on the feeding path of Mailbox.</p>   </div> <div style="width: 45%;"> <p>3. Check Mailbox Bin4 Exit-related sensors' operation & harness connection.</p>   </div> </div> <p>2. Check Mailbox Main Board Harness connection.</p>  <div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <p>4. If the same problem happens after checking 1~3, replace the mailbox main board.</p> </div> <div style="width: 45%;"> <p>5. If the same problem happens after checking 4, replace the mailbox harnesses.</p> </div> </div>	




<p>• Code H2-4700 H2-4701</p>	<p>• Error message Mailbox Failure: #H2-4700. Check mailbox. Mailbox Failure: #H2-4701. Check mailbox.</p>
<p>• Symptom / Cause Two Upper Gates seen when opening Rear Door is not operating well. Upper Diverter Motor or Upper Diverter Sensor not assembled well or damaged. Harness Damaged. Main Board damaged.</p>	
<p>• Troubleshooting method</p> <ol style="list-style-type: none"> 1. Check Upper Diverter Motor Harness connection.  2. Check Upper Diverter Sensor Harness connection.  3. Check Mailbox Main Board Harness connection.  4. Check Upper Diverter operation.  5. Check Mailbox Gate operation.  6. If the same problem happens after checking 1~5, replace the mailbox main board. 7. If the same problem happens after checking 6, replace the mailbox harnesses. 	




<p>• Code H2-4710 H2-4711</p>	<p>• Error message Mailbox Failure: #H2-4710. Check mailbox. Mailbox Failure: #H2-4711. Check mailbox.</p>
<p>• Symptom / Cause The Lowest Gate seen when opening Rear Door is not operating well. Lower Diverter Motor or Lower Diverter Sensor not assembled well or damaged. Harness Damaged. Main Board damaged.</p>	
<p>• Troubleshooting method</p> <ol style="list-style-type: none"> 1. Check Lower Diverter Motor Harness connection.  2. Check Lower Diverter Sensor Harness connection.  3. Check Mailbox Main Board Harness connection.  4. Check Lower Diverter operation.  5. Check Mailbox Gate operation.  6. If the same problem happens after checking 1~5, replace the mailbox main board. 7. If the same problem happens after checking 6, replace the mailbox harnesses. 	

<ul style="list-style-type: none"> • Code H2-4A20 	<ul style="list-style-type: none"> • Error message Mailbox door is open. Close it
<ul style="list-style-type: none"> • Symptom / Cause Mailbox Motors doesn't work. Rear Door Opened, Micro Switch not assembled well or damaged, Harness Damaged. Main Board Damaged, door flag damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check the Rear Door Closed firmly. <div data-bbox="188 763 735 1122" data-label="Image"> </div> 2. Check Mailbox Main Board Harness connection. <div data-bbox="301 1216 620 1686" data-label="Image"> </div> 3. Check the Rear Door Switch Harness connection. <div data-bbox="855 763 1406 1122" data-label="Image"> </div> 4. Check the Mailbox cover flag damaged. <div data-bbox="863 1216 1398 1615" data-label="Image"> </div> 5. If the same problem happens after checking 1~4, replace the mailbox main board. 6. If the same problem happens after checking 5, replace the mailbox harnesses. 	

<ul style="list-style-type: none"> • Code H2-4A32 	<ul style="list-style-type: none"> • Error message Too much paper in mailbox bin 1. Remove printed paper
<ul style="list-style-type: none"> • Symptom / Cause Mailbox bin 1 Full message pops when papers on that bin are stacked fully or the full sensor detecting mechanism is out of order. Mailbox Full detecting sensor damaged, harness connection not well or damaged, Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method : <ol style="list-style-type: none"> 1. Check the Bin's Full Sensor Connection and Actuator's operation. <div data-bbox="201 748 718 1086" data-label="Image"> </div> <div data-bbox="742 768 1366 1086" data-label="Image"> </div> 2. Check Main Board Harness connection. <div data-bbox="201 1180 520 1650" data-label="Image"> </div> 3. If the same problem happens after checking 1~2, replace the mailbox main board. 4. If the same problem happens after checking 3, replace the mailbox harnesses. 	

<ul style="list-style-type: none"> • Code H2-4A35 	<ul style="list-style-type: none"> • Error message Too much paper in mailbox bin 2. Remove printed paper
<ul style="list-style-type: none"> • Symptom / Cause Mailbox bin 2 Full message pops when papers on that bin are stacked fully or the full sensor detecting mechanism is out of order. Mailbox Full detecting sensor damaged, harness connection not well or damaged, Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method : <ol style="list-style-type: none"> 1. Check the Bin's Full Sensor Connection and Actuator's operation. <div style="display: flex; justify-content: space-around; margin-top: 10px;">   </div> 2. Check Main Board Harness connection. <div style="margin-top: 10px;">  </div> 3. If the same problem happens after checking 1~2, replace the mailbox main board. 4. If the same problem happens after checking 3, replace the mailbox harnesses. 	

<ul style="list-style-type: none"> • Code H2-4A38 	<ul style="list-style-type: none"> • Error message Too much paper in mailbox bin 3. Remove printed paper
<ul style="list-style-type: none"> • Symptom / Cause Mailbox bin 3 Full message pops when papers on that bin are stacked fully or the full sensor detecting mechanism is out of order. Mailbox Full detecting sensor damaged, harness connection not well or damaged, Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method : <ol style="list-style-type: none"> 1. Check the Bin's Full Sensor Connection and Actuator's operation. <div style="display: flex; justify-content: space-around;">   </div> 2. Check Main Board Harness connection.  3. If the same problem happens after checking 1~2, replace the mailbox main board. 4. If the same problem happens after checking 3, replace the mailbox harnesses. 	

<ul style="list-style-type: none"> • Code H2-4A3C 	<ul style="list-style-type: none"> • Error message Too much paper in mailbox bin 4. Remove printed paper
<ul style="list-style-type: none"> • Symptom / Cause Mailbox bin 4 Full message pops when papers on that bin are stacked fully or the full sensor detecting mechanism is out of order. Mailbox Full detecting sensor damaged, harness connection not well or damaged, Main Board damaged. 	
<ul style="list-style-type: none"> • Troubleshooting method : <ol style="list-style-type: none"> 1. Check the Bin's Full Sensor Connection and Actuator's operation.. <div style="display: flex; justify-content: space-around; margin-top: 10px;">   </div> 2. Check Main Board Harness connection. <div style="margin-top: 10px;">  </div> 3. If the same problem happens after checking 1~2, replace the mailbox main board. 4. If the same problem happens after checking 3, replace the mailbox harnesses. 	

<ul style="list-style-type: none"> • Code M1-1110 	<ul style="list-style-type: none"> • Error message Paper Jam in Tray 1
<ul style="list-style-type: none"> • Symptom / Cause The jammed paper has occurred in the tray1. <ol style="list-style-type: none"> 1. Pick up/ Forward/ Retard roller is contaminated or worn out. 2. There is some obstacles in the paper path. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Clear the jammed paper. If the problem persists, check the following. 2. Check if the pick up/ forward/ retard roller is contaminated or worn out. Clean or replace it if necessary. 3. Check if there is any obstacles or contamination in the paper path. 	

<ul style="list-style-type: none"> • Code M1-1610 	<ul style="list-style-type: none"> • Error message Paper Jam in MP tray
<ul style="list-style-type: none"> • Symptom / Cause The jammed paper has occurred in the MP tray. <ol style="list-style-type: none"> 1. MP Pick up/ Forward/ Retard roller is contaminated or worn out. 2. There is some obstacles in the paper path. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Clear the jammed paper. If the problem persists, check the following. 2. Check if the MP pick up/ forward/ retard roller is contaminated or worn out. Clean or replace it if necessary. 3. Check if there is any obstacles or contamination in the paper path. 	

<ul style="list-style-type: none"> ● Code M1-3122 	<ul style="list-style-type: none"> ● Error message Tray1 cassette is pulled out. Insert it properly
<ul style="list-style-type: none"> ● Symptom / Cause Tray1 is not installed properly. <ol style="list-style-type: none"> 1. Tray1 is not installed. 2. Paper Size Sensor is defective. 3. Harness connection error. 	
<ul style="list-style-type: none"> ● Troubleshooting method <ol style="list-style-type: none"> 1. Install the tray1. 2. Check if the paper size sensor is working properly. 3. Check if the harness is connected to the connector properly. 	

<ul style="list-style-type: none"> ● Code M1-4111 	<ul style="list-style-type: none"> ● Error message Input System Failure: #M1-4111. Call for service
<ul style="list-style-type: none"> ● Symptom / Cause The paper has jammed in the path or can't be fed. <ol style="list-style-type: none"> 1. Pick up error 2. Multi-feed error 3. Skewed or Wrinkled page 	
<ul style="list-style-type: none"> ● Troubleshooting method <ol style="list-style-type: none"> 1. Check if the pick up/ forward/ retard roller is contaminated or worn out. Replace the defective roller. 2. Check if each sensor is working properly. 3. Check if there is any jammed paper in the path. Remove it. 4. When loading the paper, adjust the paper guide. 	

<ul style="list-style-type: none"> • Code M1-5112 	<ul style="list-style-type: none"> • Error message Paper Empty in tray1
<ul style="list-style-type: none"> • Symptom / Cause Paper is empty in Tray1. The status LED is red. <ol style="list-style-type: none"> 1. There is no paper in the tray1. 2. Actuator-Paper Empty is defective. 3. Photo Sensor is defective or connection is bad. 4. Engine Board is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Load the paper in the tray1. 2. If the Actuator-Paper Empty is defective, replace it. 3. If the Photo Sensor is defective, replace it. Check if the connector is connected properly. 4. If the problem persists, replace the engine board. 	

<ul style="list-style-type: none"> • Code M1-5612 	<ul style="list-style-type: none"> • Error message Paper Empty in MP
<ul style="list-style-type: none"> • Symptom / Cause Paper is empty in Tray1. The status LED is red. <ol style="list-style-type: none"> 1. There is no paper in the MP tray. 2. Actuator-Paper Empty is defective. 3. Photo Sensor is defective or connection is bad. 4. Engine Board is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Load the paper in the MP tray. 2. If the Actuator-Paper Empty is defective, replace it. 3. If the Photo Sensor is defective, replace it. Check if the connector is connected properly. 4. If the problem persists, replace the engine board. 	

<ul style="list-style-type: none"> • Code M2-1110 	<ul style="list-style-type: none"> • Error message Paper Jam in tray1
<ul style="list-style-type: none"> • Symptom / Cause <p>The paper has jammed at the feed sensor.</p> <ol style="list-style-type: none"> 1. Feed sensor detection error. 2. The Regi. Roller is contaminated or worn out. 3. There is any obstacles in the path. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check the level value of the feed sensor. Check the harness connection. 2. Check if the Regi. Roller is contaminated or worn out. 3. If there is any obstacles or contamination in the path, clean or remove it. 	



<ul style="list-style-type: none"> • Code M2-2110 	<ul style="list-style-type: none"> • Error message Jam top of duplex
<ul style="list-style-type: none"> • Symptom / Cause <p>The paper did not enter the duplex path and has jammed.</p> <ol style="list-style-type: none"> 1. The duplex unit is not installed. 2. There is any obstacles in the paper path. 3. The duplex motor is defective. 4. Paper size lever position error. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if the duplex unit is installed properly. 2. If there is any obstacles or contamination in the path, clean or remove it. 3. Check if the duplex motor is operated properly. If the duplex motor is defective, replace it. 4. If the paper size lever is placed on wrong position, adjust it. 	


<ul style="list-style-type: none"> • Code M2-2310 	<ul style="list-style-type: none"> • Error message Jam bottom of duplex
<ul style="list-style-type: none"> • Symptom / Cause The paper has jammed in the duplex path. <ol style="list-style-type: none"> 1. There is any obstacles in the paper path. 2. The duplex motor is defective. 3. The duplex sensor is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. If there is any obstacles or contamination in the path, clean or remove it. 2. Check if the duplex motor is operated properly. If the duplex motor is defective, replace it. 3. Check if the duplex sensor is operated properly. If the duplex sensor is defective, replace it. 	

<ul style="list-style-type: none"> • Code M2-3120 	<ul style="list-style-type: none"> • Error message Install duplex unit.
<ul style="list-style-type: none"> • Symptom / Cause The duplex unit is not installed properly. <ol style="list-style-type: none"> 1. The photo sensor for duplex unit is defective. 2. Harness connection error. 3. Duplex unit installation error. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if the photo sensor for duplex unit is operated properly. 2. Check if the harness is connected to the connector properly. Reconnect it. 3. Reinstall the duplex unit. 	

<ul style="list-style-type: none"> • Code M3-1110 	<ul style="list-style-type: none"> • Error message Jam in exit area
<ul style="list-style-type: none"> • Symptom / Cause The paper has jammed in the exit path. 1. There is any obstacles in the paper path. 2. The exit motor is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method 1. If there is any obstacles or contamination in the path, clean or remove it. 2. Check if the exit motor is operated properly. If the exit motor is defective, replace it. 	



<ul style="list-style-type: none"> • Code M3-2130 	<ul style="list-style-type: none"> • Error message Output bin full. Remove printed paper
<ul style="list-style-type: none"> • Symptom / Cause The paper is full on the output bin. - The outbin full sensor is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method 1. Remove the paper on the output bin. 2. Check if the sensor connector is connected properly. 	

<ul style="list-style-type: none"> • Code S2-4110 	<ul style="list-style-type: none"> • Error message Door is open. Close it
<ul style="list-style-type: none"> • Symptom / Cause The top cover is closed but error message is not disappeared. <ol style="list-style-type: none"> 1. Harness connection error. 2. Micro Switch defect. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if the harness (Picture(1)-①) is normal. 2. Check if the harness is the connected to the Relay connector (Picture(1)-②) properly. 3. Check if the connector CN9 (Picture(1)-③) on the engine board is connected properly. 4. Open the cover of the OPE panel. Check if the UI message is changed when pushing the micro switch (Picture(2)-④). 5. If the micro switch is defective, replace it. 	
<p style="text-align: center;">Picture(1)</p> 	<p style="text-align: center;">Picture(2)</p> 

<ul style="list-style-type: none"> • Code S2-4610 	<ul style="list-style-type: none"> • Error message Rear Door is open. Close it
<ul style="list-style-type: none"> • Symptom / Cause The rear cover is closed but error message is not disappeared. <ol style="list-style-type: none"> 1. The rear cover is closed perfectly. 2. Relay connector pin is defective. 3. Harness connection error. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if the rear cover is closed perfectly. 2. Check the Relay connector Pin ①. If it is defective, replace it. 3. Check the Relay connector②. If it is defective, replace it. 4. Remove the left cover. Check the harness③ between the Joint board and Relay connector. 5. Check if the harness ④ is connected to the connector properly. 	
	


<ul style="list-style-type: none"> • Code S6-3123 	<ul style="list-style-type: none"> • Error message This IP address conflicts with that of other system
<ul style="list-style-type: none"> • Symptom / Cause IP address conflicts with that of other system. 	
<ul style="list-style-type: none"> • Troubleshooting method Change the machine's IP address. 	

<ul style="list-style-type: none"> • Code S6-3128 	<ul style="list-style-type: none"> • Error message 802.1x Network Error Contact the Admin.
<ul style="list-style-type: none"> • Symptom / Cause Can not get the authentication from server after setting up to 802.1x on SWS. Can not access to network. 	
<ul style="list-style-type: none"> • Troubleshooting method Check if the Authentication method is selected properly. Check if the User Name/Password is entered properly. 	



<ul style="list-style-type: none">• Code U1-2115	<ul style="list-style-type: none">• Error message Fuser Unit Failure: #U1-2115. Turn off then on
<ul style="list-style-type: none">• Symptom / Cause The photo sensor is defective or some part is not assembled properly.	
<ul style="list-style-type: none">• Troubleshooting method <ol style="list-style-type: none">1. Remove the Rear Cover and Duplex Unit. Remove the fuser unit after removing 4 screws. 2. Remove the GUIDE-EXIT LOWER. To remove it, first, push and release the green lever to the direction of arrow. Then, lift and pull it. 	

3. To remove the COVER-DUPELX,

a. Remove 1 screw. Lift up the COVER-DUPLEX PATH to the direction of arrow slightly.



b. Release the both hooks with the tweezers or (-) driver.



4. Remove the COVER-LEFT after removing 2 screws.


Remove the COVER-RIGHT after removing 2 screws.



5. Check if the photo sensor connector from the COVER-RIGHT is connected properly.



6. Check if the left/right CAM and the ENCORDER are assembled properly.





7. If there is no problem for above steps, reassemble the fuser unit and turn the machine on.

8. If the error persists, download the firmware again.


9. If the problem persists, replace the fuser unit with new one.

10. If the problem persists, replace the engine board.



<ul style="list-style-type: none">• Code U1-2117	<ul style="list-style-type: none">• Error message Fuser Unit Failure: #U1-2117. Turn off then on
<ul style="list-style-type: none">• Symptom / Cause The photo sensor is defective or some part is not assembled properly.	
<ul style="list-style-type: none">• Troubleshooting method <ol style="list-style-type: none">1. Remove the Rear Cover and Duplex Unit. Remove the fuser unit after removing 4 screws. 2. Remove the GUIDE-EXIT LOWER. To remove it, first, push and release the green lever to the direction of arrow. Then, lift and pull it. 	

3. To remove the COVER-DUPELX,


a. Remove 1 screw. Lift up the COVER-DUPLEX PATH to the direction of arrow slightly.



b. Release the both hooks with the tweezers or (-) driver.



4. Check if the fuser is assembled and fuser connector is connected properly.




5. If there is no problem for above steps, reassemble the fuser unit and turn the machine on.


6. If the error persists, execute the Memory Clear. (Note: Perform a backup first if necessary.)

7. If the problem persists, replace the fuser unit with new one.

8. If the problem persists, replace the engine board.


<ul style="list-style-type: none"> • Code U1-2320 	<ul style="list-style-type: none"> • Error message Fuser Unit Failure: #U1-2320. Turn off then on
<ul style="list-style-type: none"> • Symptom / Cause The fuser unit is not installed or AC is not supplied to the Heat Lamp. Thermistor is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if the fuser unit is installed properly. Turn the machine off then on. 2. Remove the fuser unit. Remove the COVER-UPPER. And measure the thermostat continuity. Check if the thermostat is opened.  <ol style="list-style-type: none"> 3. Measure the LAMP-HALOGEN resistance value from the center and both sides. Check if it has the continuity.  <div style="display: flex; justify-content: space-around; margin-top: 5px;"> Center Lamp Side Lamp </div> 	

4. Check if 2 thermistor connectors are connected properly.




5. Remove the thermistor. Check if the thermistor has curled as shown below. If there is any contamination on the film, clean it.

Caution - Be careful not to be scratched or curled the film.



6. Check if the thermistor connector on the engine board is connected properly.



7. Check if the FDB connector is connected properly.




8. Check if the voltage in user environment is in this range (80V ~ 140V, 160V ~ 260V).


9. Replace the FDB. If the problem persists, replace the engine board.

<ul style="list-style-type: none"> • Code <p>U1-2330</p>	<ul style="list-style-type: none"> • Error message <p>Fuser Unit Failure: #U1-2330. Turn off then on</p>
<ul style="list-style-type: none"> • Symptom / Cause <p>Low Heat error has occurred. The fuser unit can not reach the target temperature within normal time.</p>	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if the fuser unit is installed properly. Turn the machine off then on. 2. Remove the fuser unit after removing 4 screws. <div data-bbox="164 750 716 1146" data-label="Image"> </div> 3. Check if the fuser unit is overheated. <ol style="list-style-type: none"> a. Remove the GUIDE-EXIT LOWER. <p>To remove it, first, push and release the green lever to the direction of arrow. Then, lift and pull it.</p> <div data-bbox="164 1355 721 1749" data-label="Image"> </div> 	

- b. Rotate the gear to direction of arrow and check the surface of the Hear roller and Pressure roller. If there is any overheated traces, replace the fuser unit.




- c. Remove the COVER-UPPER. Check if the thermistor harness is connected properly and the thermistor is defective.



4. Remove the thermistor. Check if the thermistor has curled as shown below. If there is any contamination on the film, clean it.


Caution - Be careful not to be scratched or curled the film.




5. Check if the center/side lamp is assembled properly.

a. To remove the COVER-DUPELX,


Remove 1 screw. Lift up the COVER-DUPLEX PATH to the direction of arrow slightly.



b. Release the both hooks with the tweezers or (-) driver.




c. Check if the lamp harness and harness are connected properly. (white-white , color-color)



* Reassemble the fuser unit. Turn the machine off then on. If the problem persists, go to the next step.



6. Check if the thermistor connector on the engine board is connected properly.




7. Check if the FDB connector is connected properly.




8. If there is no problem, upgrade the latest firmware.

<ul style="list-style-type: none"> • Code U1-2340 	<ul style="list-style-type: none"> • Error message Fuser Unit Failure: #U1-2340. Turn off then on
<ul style="list-style-type: none"> • Symptom / Cause The overheat error has occurred. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if the fuser unit is installed properly. Turn the machine off then on. 2. Remove the fuser unit after removing 4 screws.  3. Check if the fuser unit is overheated. <ol style="list-style-type: none"> a. Remove the GUIDE-EXIT LOWER. To remove it, first, push and release the green lever to the direction of arrow. Then, lift and pull it.  	

- b. Rotate the gear to direction of arrow and check the surface of the Hear roller and Pressure roller. If there is any overheated traces, replace the fuser unit.




- c. Remove the COVER-UPPER. Check if the thermistor harness is connected properly and the thermistor is defective.




4. Remove the thermistor. Check if the thermistor has curled as shown below. If there is any contamination on the film, clean it.

Caution - Be careful not to be scratched or curled the film.




6. Measure the thermostat resistance. Check if the thermostat is opened.

Although the thermostat is opened, check the following steps. And then replace the fuser unit.




7. Remove the FDB cover. Check if the FDB Triac is short.

Check the resistance among 3 legs of both transistors. If it is short, replace the FDB.



8. If there is no problem for above steps, replace the FDB, engine board step by step. If the fuser unit is defective, replace it.

<ul style="list-style-type: none"> • Code <p>U2-1111</p>	<ul style="list-style-type: none"> • Error message <p>LSU Unit Failure: #U2-1111. Turn off then on</p>
<ul style="list-style-type: none"> • Symptom / Cause <p>LSU motor does not work normally.</p> <ol style="list-style-type: none"> 1. Harness connection error. 2. LSU is defective. 3. Main board is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method <p>Check the followings.</p> <ol style="list-style-type: none"> 1. Execute the LSU motor test in EDC mode. Check LSU motor operation sound. 2. If there is no sound, remove the right cover. Check if the C9 or C10 connector is connected properly (Picture-①). 3. If it is OK, remove the top cover. Check if the LSU connector is connected properly. (Picture-②). 4. Check if the LSU harness is defective. (Picture-③) 5. Reconnect the LSU harness and then execute the LSU motor test again. 6. Replace the LSU. 7. If the problem persists, replace the main board. 	
	

<ul style="list-style-type: none"> • Code <p>U2-1113</p>	<ul style="list-style-type: none"> • Error message <p>LSU Unit Failure: #U2-1113. Turn off then on</p>
<ul style="list-style-type: none"> • Symptom / Cause <p>LSU LD(Laser Beam Detect) signal is abnormal.</p> <ol style="list-style-type: none"> 1. Harness connection error. 2. LSU is defective. 3. Main board is defective. 4. Engine board is defective. 	
<ul style="list-style-type: none"> • Troubleshooting method <ol style="list-style-type: none"> 1. Check if the C9 or C10 connector on the main board is connected properly. 2. Check if the LSU harness is defective. 3. Check if the LSU connector is connected properly. Reconnect it. 4. Turn the machine off then on. 5. If the problem persists, replace the LSU. 6. If the problem persists after replacing the LSU, remove the main board. 7. If the problem persists after replacing the main board, remove the engine board. 8. If you have the DVM, measure the voltage level for LD optical power control before step 5. If it is normal, the value is between 0.6V~2.0V. If the value is less than 0.5V, check the FFC cable between engine and main board. Replace the FFC cable. 	
