

Ultrasonic Welding Trouble Shooting Guide

PROBLEM	PROBABLE CAUSES	SOLUTIONS
Overweld	<p>Too much energy into the part.</p> <p>Weld time too long.</p> <p>Too much collapse.</p> <p>Absolute distance too high.</p>	<p>Reduce pressure, trigger force and/or down speed</p> <p>Reduce weld time/energy/ collapse.</p> <p>Change to lower ratio booster to reduce amplitude.</p> <p>Digitally reduce the amplitude %.</p> <p>Use Amplitude Profiling.</p> <p>Reduce down speed.</p> <p>Change to lower gain horn if lowest booster is already in use.</p> <p>Recalibrate absolute distance and adjust.</p>
Underweld	<p>Insufficient energy into the part.</p> <p>Insufficient weld time.</p> <p>Insufficient amplitude.</p> <p>Energy loss into fixture.</p> <p>Presence of mold release.</p> <p>Absolute distance too low.</p> <p>Moisture absorption by hygroscopic material.</p>	<p>Increase pressure, trigger, and/or down speed.</p> <p>Increase weld time/energy/ collapse.</p> <p>Use higher ratio booster to increase amplitude, if horn allows.</p> <p>Change to higher gain horn if highest booster is already in use.</p> <p>If fixture is urethane, change fixture to rigid material such as aluminum, stainless steel.</p> <p>Evaluate part fit in fixture.</p> <p>Eliminate use or clean parts after molding.</p> <p>Increase absolute distance.</p> <p>Dry parts as required.</p>
Non-uniform weld around the joint	<p>Warped part(s).</p> <p>Non-uniform horn face amplitude.</p> <p>Lack of parallelism between horn, fixture and part.</p> <p>Insufficient support in the fixture.</p>	<p>Check part dimensions and flatness</p> <p>Check molding conditions.</p> <p>Use higher trigger pressure.</p> <p>Have horn tested (and modified if needed) to establish uniformity.</p> <p>Shim fixture where necessary, or level adjustable plate.</p> <p>Check part dimensions/flatness.</p> <p>Check part fit with horn using carbon paper.</p> <p>Improve support in critical areas.</p> <p>Change to a rigid fixture.</p> <p>If large sections of urethane are deflecting, add rigid backup</p>

PROBLEM	PROBABLE CAUSES	SOLUTIONS
<p>Non-uniform weld around the joint (continued)</p>	<p>Inconsistent energy director height.</p> <p>Wall flexure.</p> <p>Knock-out pin location in joint area.</p> <p>Improper alignment.</p> <p>Non-uniform horn contact.</p> <p>Part tolerance.</p> <p>Mold release.</p> <p>Accumulation of fillers in one area.</p> <p>Moisture in joint area.</p>	<p>Correct mold to ensure uniform energy director height. Check molding conditions.</p> <p>Add internal ribs to part. Increase wall thickness. Modify fixture to prevent outward flexure.</p> <p>Move knock-out pin location from joint area. Make sure knock-out pin marks are flush with surface.</p> <p>Check for part shifting during welding. Check alignment features in mating parts. Check for parallelism of horn, part, and/or fixture.</p> <p>Check fit of part to horn. Check part fit with horn using carbon paper. Check for sinks. Check for proper support in fixture.</p> <p>Tighten part tolerances. Check molding conditions.</p> <p>Clean mating surfaces. If mold release is required, use a paintable/printable grade.</p> <p>Check molding conditions. Reduce the amount of filler. Use only short fiber fillers</p> <p>Dry parts as required.</p>
<p>Inconsistent weld results part-to-part</p>	<p>Mold release.</p> <p>Part tolerances.</p> <p>Cavity-to-cavity variations.</p> <p>Regrind/degraded plastic.</p>	<p>Clean mating surfaces. If mold release is required, use a paintable/printable grade.</p> <p>Tighten part tolerances. Check part dimensions. Check molding conditions.</p> <p>Run statistical study to see if a pattern develops with certain cavity combinations. Check part tolerances/dimensions. Check for cavity wear. Check molding conditions. Centralize gate location.</p> <p>Check with molder for percentage of regrind Check molding conditions. Reduce percentage of regrind (maintain below 10%). Improve quality of regrind.</p>

PROBLEM	PROBABLE CAUSES	SOLUTIONS
<p>Inconsistent weld results part-to-part <i>(continued)</i></p>	<p>Drop in air line pressure.</p> <p>Filler content too high.</p> <p>Non-uniform distribution of filler.</p> <p>Incorrect joint design.</p> <p>Poor part fit.</p> <p>Incompatible materials or resin grades or lots.</p> <p>Moisture in molded part. (Usually nylon parts.)</p>	<p>Raise compressor output pressure.</p> <p>Add surge tank with a check valve.</p> <p>Check air supply line capacity vs. number of welders supplied.</p> <p>Reduce percentage of filler.</p> <p>Check molding conditions.</p> <p>Change type of filler, i.e., short- to long-glass fibers.</p> <p>Check molding conditions.</p> <p>Check mold design.</p> <p>Redesign joint, check with Branson applications engineering.</p> <p>Improve part dimensions.</p> <p>Improve part tolerances.</p> <p>Check molding conditions and improve.</p> <p>Check Branson Technical Information Sheet PW-1.</p> <p>Check with resin supplier specifications.</p> <p>Check with Branson Applications Lab.</p> <p>Receive parts dry-as-molded, bagged and sealed.</p> <p>Dry parts, then weld.</p>
<p>Marking</p>	<p>Lack of parallelism.</p> <p>Shear interference too great.</p> <p>Energy director too large.</p> <p>No joint design (butt surfaces).</p> <p>Improper fit of part to fixture.</p> <p>Weld cycle is too long.</p>	<p>Readjust for parallelism between horn, part, and fixture.</p> <p>Check horn/part fit.</p> <p>Check part/fixture fit.</p> <p>Level fixture where necessary.</p> <p>Reduce interference.</p> <p>Reduce energy director size.</p> <p>Check for proper support.</p> <p>Redesign fixture.</p> <p>Check for cavity-to-cavity variations.</p> <p>Check part dimensions.</p> <p>Check for cavity-to-cavity variations.</p> <p>Obtain a new horn.</p> <p>Reduce weld time by adjusting amplitude and/or pressure.</p> <p>Adjust Dynamic Triggering pressure.</p>

PROBLEM	PROBABLE CAUSES	SOLUTIONS
Marking <i>(continued)</i>	<p>Horn heats up.</p> <p>Localized high spots in part.</p> <p>Raised lettering.</p> <p>Aluminum oxide (from horn).</p> <p>Overwelding: control mode (time, energy, collapse or absolute distance, peak power, force) too high.</p>	<p>Check for loose tip.</p> <p>Reduce weld time. Cool horn with ambient or refrigerated air.</p> <p>Check coupling between horn and booster.</p> <p>Visually check for cracked horn.</p> <p>If horn is titanium, change to chrome-plated aluminum.</p> <p>Check part dimensions.</p> <p>Check fit of horn to part in fixture.</p> <p>Use polyethylene film between horn and part.</p> <p>Relieve horn.</p> <p>Use recessed lettering where possible.</p> <p>Chrome-plate or clear anodized horn and/or fixture.</p> <p>Use polyethylene film between horn and part.</p> <p>Readjust control parameters.</p>
Flash (see also non- uniform welding)	<p>Weld time too long.</p> <p>Non-uniform joint dimensions.</p> <p>Energy director too large.</p> <p>Shear interference too great.</p> <p>No joint design (butt surfaces).</p>	<p>Reduce weld time.</p> <p>Redimension joint.</p> <p>Check molding conditions.</p> <p>Reduce size of energy director.</p> <p>Reduce weld time.</p> <p>Reduce pressure.</p> <p>Use textured surface.</p> <p>Reduce amount of interference.</p> <p>Redesign joint to direct flash as required by application.</p>
Misalignment of welded assembly	<p>Lack of proper alignment feature between mating parts.</p> <p>Improper support in fixture.</p> <p>Wall flexure.</p>	<p>Add alignment feature to the mating part halves (i.e., pins and sockets).</p> <p>Redesign fixture for proper support.</p> <p>Shim fixture where necessary.</p> <p>If large sections of urethane are deflecting, add rigid backup.</p> <p>Add ribs or gussets to part.</p> <p>Increase wall thickness.</p> <p>If large sections of urethane are deflecting, add rigid backup.</p>

PROBLEM	PROBABLE CAUSES	SOLUTIONS
Misalignment of welded assembly <i>(continued)</i>	Joint design improper dimension. Part tolerance/poor molding. Overwelding.	Redimension parts. Tighten part tolerances. Check molding conditions. Reduce weld time/energy/pressure.
Internal components damaged during welding	Too much energy into the part. Long weld time. Components improperly mounted, i.e., mounted too close to joint area, etc. Location of components.	Reduce amplitude by changing to a lower gain booster, or utilize Amplitude Profiling. Reduce pressure and/or down speed. Reduce weld time/energy. Adjust Dynamic Trigger pressure. Investigate the use of alternate frequencies. Reduce weld time by adjusting amplitude and/or pressure. Adjust Dynamic Triggering pressure. Make sure internals are properly mounted. Isolate internal components from housing. Move components away from areas of high energy concentration. Use nodally-mounted device to dampen energy locally. Components should be in fixture part.
Melting/fracture of part sections outside of joint.	Too much energy into the part. Sharp internal corners. Excessive amplitude. Internal stress. Knit/flow lines. Improper molding conditions. Gate located near joint.	Reduce weld time. Decrease amplitude. Decrease pressure. Adjust Dynamic Triggering pressure. Radius all sharp corners. Reduce amplitude by changing to a lower gain booster, or step amplitude. Reduce horn amplitude if lowest booster is already in use. Monitor/improve molding conditions. Check part design. Check molding process parameters. Check molding conditions. Move gate area away from joint.

Ultrasonic Welding Trouble Shooting Guide

PROBLEM	PROBABLE CAUSES	SOLUTIONS
Diaphragmming	<p>Excessive amplitude.</p> <p>Long weld time.</p> <p>Gate location.</p> <p>Horn type and/or placement.</p> <p>Thin wall section.</p>	<p>Reduce amplitude.</p> <p>Utilize Amplitude Profiling.</p> <p>Reduce weld time by increasing amplitude and/or pressure.</p> <p>Check gate placement.</p> <p>Check molding conditions.</p> <p>Change shape of gate.</p> <p>Add stiffening ribs to the part.</p> <p>Increase thickness of material on the underside of the gate area.</p> <p>Eliminate horn contact over diaphragm area.</p> <p>Check for horn/part fit.</p> <p>Use a horn with a nodal plunger.</p> <p>Add vent hole in horn.</p> <p>Increase wall thickness or add ribs.</p>
Internal parts welding	<p>Internal parts same material as housing.</p>	<p>Change material of internal part to incompatible material. Lubricate internals.</p> <p>Reposition internal parts to prevent contact during weld cycle.</p>

BRANSON

Branson Ultrasonics Corporation
 41 Eagle Road, Danbury, CT 06813-1961
 (203) 796-0400 • Fax: (203) 796-9838
www.bransonultrasonics.com
 e-mail: info@bransonultrasonics.com