G500H Flight Display System Instructions for Continued Airworthiness Bell 407

Reg. No	S/N	_
	STC SR02295LA	

Dwg. Number: 190-01150-21 Rev. 2

Garmin International, Inc. 1200 E. 151st Street Olathe, Kansas 66062 USA

Record of Revision

Rev.	Date	Description of Change		
1	04/05/10	Initial Release		
2	12/8/10	Added VSI Placard		

1.	INTRODU	JCTION	. 3
	1.1	Purpose	. 3
	1.2	Scope	. 3
	1.3	Document Control	. 3
	1.4	Permission to Use Certain Documents	. 3
	1.5	Definitions	. 3
2.	INSTRUC	CTIONS FOR CONTINUED AIRWORTHINESS	. 4
	2.1	Introduction	. 4
	2.2	Description of Alteration	. 5
	2.3	Control, Operating Information	. 8
	2.4	Servicing Information	. 8
	2.5	Periodic Maintenance Instructions	. 8
	2.6	Troubleshooting Information	. 9
	2.7	Removal and Installation Information	. 13
	2.8	Diagrams	. 18
	2.9	Special Inspection Requirements	
	2.10	Application of Protective Treatments	. 18
	2.11	Data Relative to Structural Fasteners	. 18
	2.12	Special Tools	. 18
	2.13	Additional Instructions	. 19
	2.14	Overhaul Period	. 19
	2.15	ICA Revision and Distribution	. 19
	2.16	Assistance	. 19
	2.17	Implementation and Record Keeping	. 19
2	AIDWOD	THINESS I IMITATIONS	10

1. INTRODUCTION

1.1 Purpose

This document is designed for use by the installing agency of the Garmin G500H PFD/MFD System as Instructions for Continued Airworthiness in response to Title 14 CFR Part 27.1529, Part 27 Appendix A.. This ICA includes information required by the operator to adequately maintain the Garmin G500H system installed under STC SR02295LA.

1.2 Scope

This document identifies the Instruction for Continued Airworthiness for the modification of the rotorcraft for installation of the Garmin G500H PFD/MFD System installed under STC SR02295LA.

1.3 Document Control

This document shall be released, archived, and controlled in accordance with the Garmin document control system. When this document is revised, refer to Section 2.15 for information on how to gain FAA acceptance or approval and how to notify customers of changes.

1.4 Permission to Use Certain Documents

Permission is granted to any corporation or person applying for approval of a Garmin G500H system to use and reference appropriate STC documents to accomplish the Instructions for Continued Airworthiness and show compliance with STC engineering data. This permission does not construe suitability of the documents. It is the responsibility of the applicant to determine the suitability of the documents for the ICA.

1.5 Definitions

The following terminology is used within this document:

- 1) ACO: Aircraft Certification Office
- 2) ADC: Air Data Computer
- 3) AEG: Aircraft Evaluation Group
- 4) AHRS: Attitude Heading Reference System
- 5) CFR: Code of Federal Regulations
- 6) **FAA:** Federal Aviation Administration
- 7) ICA: Instructions for Continued Airworthiness
- 8) MFD: Multi-Function Display
- 9) PFD: Primary Flight Display
- 10) **PMI:** Principle Maintenance Inspector
- 11) STC: Supplemental Type Certificate

2. INSTRUCTIONS FOR CONTINUED AIRWORTHINESS

2.1 Introduction

Content, Scope, Purpose and Arrangement: This document identifies the Instructions for

Continued Airworthiness for the modification of the rotorcraft by installation of the Garmin G500H

PFD/MFD System.

Applicability: Applies to Bell models 407 rotorcraft altered by

installation of the Garmin G500H PFD/MFD

System.

Definition of Abbreviations: See Section 1.5

Precautions: None

Units of measurement: None

Referenced publications: Garmin 190-01150-06 Rev. 3 "G500H Rotorcraft

STC Installation Manual" or later FAA Approved

Revisions

Garmin 190-01150-44 Rev. 3 "GENERAL ARRANGEMENT, G500H SYSTEM, BELL 407 ROTORCRAFT" or later FAA Approved Revisions

Additional Maintenance Data: Garmin 190-01150-45 Rev. 3 "INSTALLATION,

G500H SYSTEM, BELL 407 ROTORCRAFT" or

later FAA Approved Revisions

Garmin 005-W0222-00 Rev. 3 "G500H MAIN WIRE HARNESS ASSEMBLY" or later FAA

Approved Revisions

Garmin 005-W0222-01 Rev. 1 "G500H NAV

1 HARNESS ASSEMBLY" or later FAA

Approved Revisions

Garmin 005-W0222-02 Rev. 1 "G500H GPS

2 HARNESS ASSEMBLY" or later FAA

Approved Revisions

Garmin 005-W0222-03 Rev. 1 "G500H NAV

2 HARNESS ASSEMBLY" or later FAA

Approved Revisions

Garmin 005-W0222-04 Rev. 1 "G500H WX

DATALINK HARNESS ASSEMBLY" or later

FAA Approved Revisions

Garmin 005-W0222-05 Rev. 1 "G500H

IRIDIUM DATALINK HARNESS ASSEMBLY"

G500H Flight Display System

190-01150-21 Rev. 2

Instructions for Continued Airworthiness Bell 407

or later FAA Approved Revisions

Garmin 005-W0222-06 Rev. 1 "G500H VIDEO HARNESS ASSEMBLY" or later FAA Approved Revisions

Garmin 005-W0222-07 Rev. 2 "G500H SERIAL ALTITUDE HARNESS ASSEMBLY" or later FAA Approved Revisions

Garmin 005-W0222-08 Rev. 1 "G500H TRAFFIC HARNESS ASSEMBLY" or later FAA Approved Revisions

Retention:

This document, or the information contained within, will be included in the rotorcraft's permanent records.

2.2 Description of Alteration

This STC upgrades existing avionics for the Bell 407 rotorcraft as summarized below.


The Garmin G500H Flight Display System consists of an instrument panel mounted GDU 620 display and remote mounted LRUs which provide data to the display. The GDU 620 provides controls for the G500H system and a PFD and MFD in the pilot's primary field of view. The remote mounted LRUs include one GRS 77H AHRS, one GMU 44 Magnetometer, one GDC 74H ADC, and one GTP 59 OAT probe.

Rotorcraft modified under this G500H STC are restricted to VFR only, including rotorcraft that may not have previously been restricted to VFR. To clarify this operation limitation, a placard with the text, "APPROVED FOR DAY/NIGHT VFR" is required to be in the pilot's view.


A placard with the text, "MAX RATE OF CLIMB 2000 FPM" shall be installed adjacent to the primary flight display.

All installed G500H equipment is connected to a power bus that receives power as soon as the battery master switch is turned on.

Separate circuit breakers have been installed in the overhead circuit breaker panel for each for the GDU 620 (PFD), GRS 77H + GMU 44 (AHRS), and GDC 74H (ADC) as circled below:



The installed G500H equipment can be accessed as described below:



- GDU 620: FS38.0, WL 46.0 Access or remove by removing the six screws in the bezel of the GDU 620.
- 2. GDC 74H: FS27.7, WL 40.1 Access or remove by lowering instrument console at its hinge point and removing the top instrument console cowling.
- 3. GRS 77H: FS57.0, WL22.0 (Secondary location) Access or remove by removing the cushion from the co-pilots seat and the panel on top of the seat pedestal.
- 4. GRS 77H: FS174.5, WL59.4 (Primary location) Access or remove by opening the baggage compartment and removing the access panel located on the ceiling of the baggage compartment.
- 5. GMU 44: FS243.0, WL70.1 (Secondary location) Access or remove by removing the bolts from the access panel on the pilots side of the aircraft at the juncture of the tail boom and fuselage.
- 6. GMU 44: FS316.5, WL74.3 (Primary location) Access or remove by removing the bolts from the access panel on either side of the aircraft at the juncture of the horizontal stabilizer and tail boom.

2.2.1 Weight and Balance Information

Weight and Balance Bell 407			Moment arm (IN)		Location		
Item	Part Number		Weight (LB)	Longitudinal	Lateral	Primary	Secondary
1	011-01264-50	GDU 620 (Unit Only)	6.38	38.0	6.0	6.0	
		GDU 620 (Installed with rack and connector)	7.04	38.0	6.0		
2	011-00882-11	GDC 74H (Unit Only)	1.70	27.7	4.0		
		GDC 74H (Installed with connector)	1.92	27.7	4.0		
3	011-00868-20	GRS 77H (Unit Only)	2.80				
		GRS 77H (Installed with rack and connector)	3.46				
4	011-00870-10	GMU 44 (Unit Only)	0.35	316.5	0.0		
		GMU 44 (Installed with rack and connector)	0.50	316.5	0.0		
		GMU 44 (Unit Only)	0.35	243.0			
		GMU 44 (Installed with rack and connector)	0.50	243.0			

- [1] A rotorcraft weight and balance is required after installation of the G500H system. Refer to STC installation manual P/N 190-01150-06 for additional information, including overall size and center of gravity location of all LRUs.
- [2] The longitudinal arm is measured in terms of the fuselage station (FS) number.
- [3] The lateral arm is measured in terms of the butt line (BL). The centerline of the helicopter is BL0.00. The moment arms to the left side (looking forward) are negative (-) and the moment arms to the right side are positive (+).

2.3 Control, Operating Information

See the G500H Pilot's Guide or the G500H STC Installation Manual, listed under the reference documentation in paragraph 2.1 of this document, for system operation and self-test information.

2.4 Servicing Information

None. In the event of system failure, troubleshoot the G500H system in accordance with Section 2.6.

2.5 Periodic Maintenance Instructions

Maintenance of the components installed by this STC is on condition, except as noted in the following table.

Item	Interval	Description/Procedure		
GRS 77H AHRS	5 years	The GRS 77 utilizes an Earth magnetic field model which is updated once every five years as part of the Aviation Database maintained by the owner/operator. If the magnetic model is not current, the unit will issue an alert upon startup indicating the model has expired. The model can be updated by inserting an aviation database card with an updated IGRF model and powering on the system. A prompt will direct the user to press ENT to update the model.		
GDC 74H ADC	On condition	Per Part 43 Appendix E, paragraph (b)(2), the GDC 74H must be checked using a test procedure equivalent to Part 43 Appendix E, paragraph (b)(1) with the following exception: The tests of sub-paragraphs (iv) (Friction) and (vi) (Barometric Scale Error) are not applicable because the digital outputs of the GDC 74H are not susceptible to these types of errors.		
GDU 620, GRS 77H, GDC 74H, GMU 44, GTP 59	12 Calendar Months	Conduct a visual inspection (look for signs of wear, deterioration, or damage to wires, backshells, or connectors) on units and their wire harnesses to ensure installation integrity: 1. Gain access to LRU (see General Arrangement Drawing for LRU locations) 2. Inspect each unit for security of attachment. 3. Inspect all knobs and buttons for legibility. 4. Inspect condition of wiring, routing and attachment/clamping. 5. Inspect integrity of shield terminations. 6. Inspect for signs of corrosion on equipment and their rack installations.		

Item	Interval	Description/Procedure	
GDU 620, GRS 77H, GDC 74H, GMU 44, GTP 59	Every 2000 flight hours or ten (10) years, whichever is first	Perform an electrical bonding test for each listed LRU: 1. Gain access to the LRU (see General Arrangement Drawing for LRU location) 2. Disconnect all harness connectors from the LRU 3. Measure the resistance between the LRU and a nearby exposed portion of aircraft metallic structure a. For the GDU 620, verify the resistance is less than or equal to 40 milliohms b. For the remaining LRUs, verify the resistance is less than or equal to 20 milliohms 4. Reconnect all disconnected harness connectors and ensure they are secure	

2.6 Troubleshooting Information

If error indications are displayed on the GDU 620 display unit, consult the Troubleshooting section contained below:

2.6.1 G500H Troubleshooting

Table 2-1. GDU 620 Troubleshooting Guide

Problem	Cause	Solution
Unit does not power up – blank screen.	Improper wiring; circuit breaker open.	Ensure power is properly wired to the GDU 620 and the circuit breaker is closed.
	Unit intensity turned down.	Ensure that unit is not in manual intensity control mode with the intensity turned down.
All expected configuration pages are not displayed.	An Installer Unlock Card is not inserted into the GDU 620.	Insert the Installer Unlock Card P/N 010-00769-60 into the bottom slot of the GDU 620 and cycle power.
The GDC OAT probe type shows up as UNKNOWN	The RS-232 connection to the GDC 74H is not working.	Ensure that the GDC 74H RS-232 connection to the GDU is properly wired, and ensure that the GDC 74H circuit breaker is closed.
When loading software, the LRU software is not being displayed on the	The software loader card is installed in the bottom slot of the GDU 620.	Insert the loader card in the top slot and cycle power to the GDU.
SOFTWARE UPLOAD page.	The software loader card contains no information.	Repeat the process for making the software loader card.
Configuration errors are displayed on power-up, before the GDU enters normal mode.	The configuration module has not been updated.	Update the configuration module.

Problem	Cause	Solution
Vertical GPS deviation is not displayed on the GDU 620.	For 400W/500W Series units, the ARINC 429 vertical deviation labels are not being transmitted.	Enable Labels on the 400W/500W Series unit ARINC 429 configuration page.
Unable to control the GPS course when in OBS mode.	The GPS navigator is not correctly configures as LNAV1/2 or SYS1/2.	Configure the ARINC 429 inputs/outputs for LNAV1 (SYS1) or LNAV2 (SYS2) based upon whether the navigator is GPS1 or GPS2.
Data is not being received from an ARINC 429 device.	ARINC 429 bus hi and low are swapped.	Verify wiring.
(valid data is being received on the 429 input port as shown on the GDU 620 PORT MONITORING page)	Wrong device is connected to port on GDU 620.	Use correct ports (refer to interconnect details).
Data is not being received from an ARINC 429 device. (no data is being received on	On the transmitting LRU, the ARINC 429 transmitter speed is not set correctly.	Set the ARINC 429 transmitter speed to correct speed.
the 429 input port as shown on the GDU 620 PORT MONITORING page)	Wiring is not correct.	Check for continuity/shorts and correct as required.
Attitude and heading on GDU 620 red 'X' / GRS 77H resets during air data ground testing.	Attitude and heading errors/resets are possible if the air data tests are conducted indoors without a good GPS signal. With marginal or no GPS signals present, sudden changes in airspeed caused by using a pressure tester may result in attitude and heading errors and possibly cause the GRS 77H to reset. This occurs because the artificial changes in airspeed cause disagreement with the other sensor measurements internal to the GRS 77H. This sensor disagreement will not occur in the normal conditions of flight.	This is expected behavior and no troubleshooting is required if this occurs. To reduce the chances of inducing attitude and heading errors/resets while conducting the air data tests, ensure that the G500H is receiving good GPS signals.
Heading red 'X' during air data ground testing	Invalidation of heading is possible if the air data tests are conducted indoors, due to typical magnetic anomalies, even with a good GPS signal.	This is expected behavior and no troubleshooting is required if this occurs.

2.6.2 G500H Alerts

The G500H will display a number of alerts on the GDU 620 MFD. These are listed in the following table.

Table 2-2. GDU 620 Alert Troubleshooting Guide

Alert Text	Cause	Solution
AHRS1 GPS – AHRS 1 using backup GPS source.	AHRS is using the backup GPS information	Verify GPS1 power and check the wiring
AHRS1 GPS - AHRS is not receiving any GPS information	AHRS is not receiving any GPS information.	Verify GPS power and check the wiring
AHRS1 GPS – AHRS 1 operating in exclusively in no-	AHRS is not receiving any GPS information.	Ensure that at least one GPS has acquired a valid position.
GPS mode.		If GDU 620 does not have a valid position, verify wiring between GDU and GPS receiver, and configuration of GDU 620 and GPS receiver.
		If GDU has a valid GPS position, verify wiring between GDU and GRS. Also verify time mark wiring.
AHRS1 GPS – AHRS 1 not receiving backup GPS information.	AHRS is not receiving GPS information from GPS2.	Verify GPS2 power and check the wiring
AHRS1 SRVC	AHRS magnetic field model should be updated. Appears on ground only.	Update GRS 77H IGRF model (current model is with aviation database).
AHRS1 TAS	AHRS is not receiving true airspeed	GDC not powered up. Close ADC C/B.
	from ADC.	GDC not receiving input from GTP 59 OAT probe. Verify wiring is correct.
		ARINC 429 connection from GDC 74H to GRS 77H is not working. Verify wiring is correct.
CAL LOST	Registry reports that it has lost calibration data.	Contact Garmin Technical Support.
CNFG MODULE	The configuration module is	Verify wiring to configuration module
	inoperative.	Replace configuration module
DATA LOST	Pilot stored data was lost. Recheck data and settings.	
FAN 1 FAIL	Fan 1 has reported 0 RPM when it was powered with a PWM duty cycle higher than or equal to 10%	Inspect the GDU fan for an obstruction. Contact Garmin Technical Support.

Alert Text	Cause	Solution
FAN 2 FAIL	Fan 2 has reported 0 RPM when it was powered with a PWM duty cycle higher than or equal to 10%	Inspect the GDU fan for an obstruction. Contact Garmin Technical Support.
GDL69 CONFIG	The GDL 69 configuration information stored in the GDL 69 and the GDU 620 configuration module do not match.	With the GDU 620 in configuration mode, go to the GDL 69 page in the GDL page group. Verify that the SET and ACTIVE configuration settings are the same. If not, use the SET>ACTV soft key to copy the configuration settings from the GDU 620 into the GDL 69.
	The GDL 69 configuration was updated using another LRU (e.g. the GMX 200 or 400W/500W).	Update the GDL 69 configuration using the GDU 620.
GDU CONFIG	This error appears whenever the GDU is replaced with a GDU that was configured for a different installation.	Cycle power to the GDU. This error automatically clears on the second power up with a different configuration module.
	Error in the configuration of the GDU 620.	
GDU (1/2) COOLING	Specific GDU has poor cooling, and power usage is being reduced.	Ensure fans on indicated GDU are functioning
		Ensure fans on indicated GDU are not obstructed
GDU (1/2) DB ERR	Error in specific database, where GDU (1/2) DB denotes specific database.	Verify the correct card is installed, reload the DB on the card.
GDU (1/2) VOLTAGE	GDU supply voltage is below 12 VDC.	Increase the voltage above 12VDC.
GEO LIMITS	Location is too far north/south for GRS 77H magnetic compass.	
GPS(1/2) FAIL	No GPS1 or GPS2 data is available.	Ensure GPS (1/2) is turned on
		Verify RS-232 wiring from the GPS to the GDU 620.
GPS(1/2) PPS Failure	This alert will be set if the PPS	Ensure GPS (1/2) is turned on
	signal has not been received in more than 5 sec. If the unit is configured for dual GPSs then the side will be specified in the error.	Verify 1PPS wiring from the GPS to the GDU 620.

Alert Text	Cause	Solution
GPS2 FPL USED	The GPS1 has failed and GPS2 is configured and operating.	
HDG FAULT	AHRS magnetometer fault has occurred.	GRS 77H not receiving information from GMU 44. Verify wiring to GMU 44.
HDG LOST	Heading from the GRS77/ GMU 44 is not valid.	Caused by a local magnetic anomaly. No action required.
<lru> SERVICE</lru>	Specific LRU should be serviced, where <lru> denotes specific LRU.</lru>	Return indicated LRU to Garmin for service.
MANIFEST	GDU has received product data for an LRU that should have a manifest entry, but is not in the manifest.	Ensure the manifest is properly configured.
	The LRU software P/N and version number in the manifest does not	Update the LRU software to match the manifest
	match the values being reported by that LRU.	Update the manifest to match the LRU software
NAV1 FAIL	No navigation receiver 1 data.	
NAV2 FAIL	No navigation receiver 2 data.	
SIMULATOR	The simulator mode is active.	Ensure P6202-36 is not grounded.
SVT DISABLED - Out of available terrain region.	Location is beyond region covered by terrain database.	
SVT DISABLED - Terrain DB resolution too low.	A 30 arc-second terrain database is being used.	Update the Supplemental Data card with the 9 arc-second terrain database.
SW MISMATCH	GDU software version strings do not match.	Verify the correct SW is loaded
TRAFFIC FAIL	The traffic information system has failed.	The GDU 620 is not receiving traffic information from the traffic sensor. Verify wiring between GDU 620 and traffic sensor.
		The GDU 620 is receiving information from the traffic sensor, but the information is indicating that the traffic sensor has failed. Troubleshoot traffic system.
TRK LOST	GPS1 TRK lost. HSI defaulted to GPS2 TRK.	
TRK TRAFFIC	Heading Lost. Traffic is now based on track.	See HDG errors.

2.7 Removal and Installation Information

If any G500H LRUs are removed and reinstalled or a new unit is installed, verify that the LRU unit powerup self-test sequence is successfully completed and no failure messages are annunciated on the GDU 620 display. If any work has been done on the rotorcraft that could affect the system wiring or any interconnected equipment, verify the G500H system unit power-up self-test sequence is successfully completed and no failure messages are annunciated on the GDU 620 display.

Whenever removing or installing units, remove power from the LRU by removing aircraft power or opening the LRU circuit breaker.

2.7.1 GDU™ 620 Unit

2.7.1.1 Removal

- 1. Remove the six mounting screws from the bezel of the GDU 620.
- 2. Pull the GDU 620 far enough out from the instrument panel to access the three rear connectors.
- 3. Disconnect the rear connectors.
- 4. Remove the GDU 620.

2.7.1.2 Installation

- 1. Visually inspect the connectors to ensure that there are no bent or damaged pins. Repair any damage.
- 2. Connect the rear connectors, ensuring that each slidelock is secured on both sides.
- 3. Set the GDU 620 into place.
- 4. Install the six mounting screws into the bezel of the GDU 620.

NOTE



The installation configuration settings are stored in the configuration module and will be retained when the GDU 620 is replaced with a new unit. User settings, such as map orientation preferences, are stored internally and will be lost when the GDU 620 is replaced with a new unit.

Original GDU 620 is Reinstalled

If the original GDU 620 is reinstalled, then no software loading is required. This does not include units that were returned for repair as their software and configuration files are deleted during the repair process. No configuration is required.

New, Repaired or Exchange GDU 620 is Installed

If a new, repaired, or exchange GDU 620 unit is installed, then software must be loaded. No configuration is required.

NOTE



Upon first power-up after installing a new GDU 620, it is normal to see a series of "LOADING..." messages appear on the screen. These messages indicate that the GDU 620 is updating its configuration settings from the configuration module.

Refer to Section 5 of the G500H STC Installation Manual for the GDU 620 Software Loading procedure (5.4.1), followed by the Manifest Configuration (5.5.5) and the Configuration Module Update (5.5.12).

GDU 620 Configuration Module is Replaced

If the GDU 620 Configuration Module is replaced, the GDU 620 will update the configuration module from its internally-stored settings when the UPDT CFG soft key is pressed. If the GDU 620 is replaced at the same time as the Configuration Module, then the System Setup will need to be performed per Section 5.5 of the G500H STC Installation Manual.

2.7.1.3 Return to Service

After removing and reinstalling the GDU 620 per the instructions above, a simple return-to-service check should be performed.

- 1. Power up the GDU 620 and all interfaced systems in normal mode.
- 2. Verify that there are no red-Xs and that no alerts are present. If red Xs or alerts are present, troubleshoot using Section 2.6 of this ICA.

2.7.2 GRS 77H Unit

2.7.2.1 Removal

- 1. Disconnect the GRS 77H connector.
- 2. Loosen the four Phillips thumbscrews with a screwdriver.
- 3. Gently lift the GRS 77H from the mounting plate (if the supports for the mounting plate are removed, the GRS 77H must be recalibrated)

2.7.2.2 Installation

- 1. Place the GRS 77H on the mounting plate, ensuring the orientation is correct.
- 2. Fasten the unit to the plate using the Phillips thumbscrews. Recommended torque is 22-25 inch pounds.
- 3. Visually inspect the connectors to ensure there are no bent or damaged pins. Repair any damage.
- 4. Connect the connector to the GRS 77H, ensuring that each slidelock is secured on both sides.

Original GRS 77H is Reinstalled

If the original GRS 77H is reinstalled, then no software loading is required. This does not include units that were returned for repair as their software and configuration files are deleted during the repair testing process. Reference Table 2-3 to determine whether recalibration is required.

New, Repaired, or Exchange GRS 77H is Installed

If a new, repaired, or exchange GRS 77H unit is installed then software must be loaded per Section 5.4.2 of the G500H STC Installation Manual. Reference Table 2-3 to determine whether recalibration is required.

GRS 77H Configuration Module is Replaced

If the GRS 77H Configuration Module is replaced, the GRS 77H must be re-calibrated. Reference Table 2-3.

2.7.2.3 Return to Service

After removing and reinstalling the GRS 77H, the following return-to-service checks should be performed.

- 1. Power up the G500H system with the GDU 620 in normal mode.
- 2. Verify that the GDU displays valid heading and attitude within approximately one minute. Note that heading can remain invalid if the magnetometer is near a large metal structure such as a hangar wall or if the magnetometer is close to a large ground power cart.
- 3. Verify that no unexpected alerts are present. If alerts are present, troubleshoot using Section 2.6 of this ICA.

Table 2-3. GRS 77H Calibration Criteria

	С	Calibrations Required			
Condition	GRS 77H Pitch/Roll Offset See Section 5 of the G500H STC Installation Manual	GRS/GMU Magnetic Calibration See Section 5 of the G500H STC Installation Manual	Engine Run-up Vibration Test See Section 5 of the G500H STC Installation Manual		
GRS 77H AHRS was removed and/or replaced. The mounting tray was NOT removed and the mounting tray bolts were NOT loosened.	None Required.				
GRS 77H AHRS was removed and/or replaced. The mounting tray WAS removed and/or mounting tray bolts WERE loosened.	х	х	х		
GRS 77H AHRS Configuration Module was replaced.	Х	Х	Х		

2.7.3 GMU 44 Unit

2.7.3.1 Removal

- 1. Gain access to the GMU 44 magnetometer.
- 2. Unscrew the three screws that hold the GMU 44 to its mounting rack.
- 3. Carefully lift the GMU 44 from the rack.
- 4. Disconnect the wiring harness.

2.7.3.2 Installation

- 1. Visually inspect the connectors to ensure there are no bent or damaged pins. Repair any damage.
- 2. Connect the wiring harness to the GMU 44.
- 3. Lower the GMU 44 into the rack and secure the plate with the three Phillips screws.

Original GMU 44 is Reinstalled

If the original GMU 44 was reinstalled, then software loading is not required. This does not include units that were returned for repair as their software and configuration files are deleted during the repair testing process. Recalibration is required only if the mount for the magnetometer was changed. If the magnetometer mount was changed, refer to Section 5.6.2 of the G500H STC Installation Manual for the GRS 77H/GMU 44 Magnetic Calibration.

New, Repaired or Exchange GMU 44 is Installed

If a new, repaired, or exchange GMU 44 unit is installed, then software must be loaded and the GRS 77H/GMU 44 Magnetic Calibration must be performed. Refer to Section 5 of the G500H STC Installation Manual for instructions on software loading (5.4.3) and Magnetic Calibration (5.6.2).

Return to Service

After removing and reinstalling the GMU 44, the following return-to-service checks should be performed.

- 1. Power up the G500H system with the GDU 620 in normal mode.
- 2. Verify that the GDU displays valid heading within approximately one minute. Note that heading can remain invalid if the magnetometer is near a large metal structure such as a hangar wall or if the magnetometer is close to a large ground power cart.
- 3. Verify that no unexpected alerts are present. If alerts are present, troubleshoot using Section 2.6 of this ICA.

2.7.4 GDC 74H Unit

2.7.4.1 Removal

- 1. Disconnect the pitot/static plumbing from the rear of the unit. Disconnect the single connector.
- 2. Remove the two (2) screws on the mounting plate near the pitot/static ports. Loosen the other two (2) screws.
- 3. Carefully remove the unit from its mounting location.

2.7.4.2 Installation

- 1. Place the unit in the mounting tray.
- 2. Position the unit and fasten using the four (4) screws.
- 3. Connect the pitot/static plumbing.
- 4. Inspect the connector and pins for damage. Repair any damage.
- 5. Connect the connector to the unit, ensuring that each jackscrew is secured.

Original GDC 74H is Reinstalled

If the original GDC 74H is re-installed, then no software loading is required. This does not include units that were returned for repair as their software and configuration files are deleted during the repair testing process.

New, Repaired or Exchange GDC 74H is Installed

If a new, repaired, or exchange GDC 74H unit is installed, then software must be loaded to the unit. Refer to Section 5.4.4 of the G500H STC Installation Manual for more information.

GDC 74H Configuration Module is Replaced

If the GDC 74H Configuration Module is replaced, the GDC 74H must be configured. Refer to Section 5.5.8 of the G500H STC Installation Manual

2.7.4.3 Return to Service

After removing and reinstalling the GDC 74H, the following return-to-service checks must be performed.

- 1. Power up the G500H system with the GDU 620 in normal mode.
- 2. Verify that the GDU displays valid air data within approximately one minute.
- 3. Verify that no unexpected alerts are present. If alerts are present, troubleshoot using Section 2.6 of this ICA.
- 4. Perform a leak check of the pitot-static system and observe the airspeed, altitude, and vertical speed for proper operation.

2.8 Diagrams

Rotorcraft specific LRU locations and wire routing diagrams are contained in the Garmin Reference Publications listed in Section 2.1 of this document. Point to point wiring diagrams are in Appendix D of the G500H STC Installation Manual. Refer to the G500H Post-Installation Checkout Log retained in the rotorcraft permanent records for a list of the interfaced equipment and port configurations.

2.9 Special Inspection Requirements

2.9.1 Post-Lightning Strike Inspection

In the event of a suspected or actual lightning strike to the aircraft, the GTP 59 OAT Probe and its associated installation shall be inspected.

The probe and the surrounding installation shall be inspected to ensure that there is no structural damage around the areas where lightning may have attached. If there is visible sign of damage to the probe then it must be replaced.

Verify that OAT is displayed on the GDU 620 PFD normally.

2.10 Application of Protective Treatments

None, N/A.

2.11 Data Relative to Structural Fasteners

Refer to the following table for data on the location, type, and torque values for structural fasteners.

Location (see General Arrangement Drawing)	FASTENER TYPE AND TORQUE			
	6-32 Screw	8-32 Screw	10-32 Screw	NUT, 5/16", HEX, SKIRT
	12-15 inch-pounds	12-15 inch-pounds	22-25 inch-pounds	100±20 inch-pounds
Instrument Panel, Instruments	Х	Х		
GDU 620	Х			
GRS 77H	Х		Х	
GDC 74H		Х	Х	
GMU 44	Х	Х		
GTP 59				Х

2.12 Special Tools

For electrical bonding testing, a milliohm meter is required.

G500H Flight Display System

2.13 Additional Instructions

None

2.14 Overhaul Period

The system does not require overhaul at a specific time period. Power on self-test and continuous BIT will monitor the health of the G500H system. If any LRU indicates an internal failure, the unit may be removed and replaced. See the troubleshooting section contained in the G500H STC Installation Manual, listed under reference documentation in paragraph 2.1 of this document.

2.15 ICA Revision and Distribution

To revise this ICA, a letter must be submitted to the ACO along with the revised ICA. The ACO will obtain AEG acceptance, and approve any revision to the Airworthiness Limitations in Section 3. After FAA acceptance/approval, Garmin will release the revised ICA for customer use, and provide any required notification of the revision.

The latest revision of this document will be available through any Garmin dealer or from Garmin customer assistance. A Garmin Service Bulletin, describing ICA revision, will be sent to dealers if revision is determined to be significant.

2.16 Assistance

FAA Flight Standards Inspectors or the certificate holder's PMI have the required resources to respond to questions regarding this ICA. In addition, the customer may refer questions regarding this equipment and its installation to the manufacturer, Garmin. Garmin customer assistance may be contacted during normal business hours via telephone 913-397-8200 or email from the Garmin web site at www.garmin.com.

2.17 Implementation and Record Keeping

Modification of an rotorcraft by this Supplemental Type Certificate obligates the rotorcraft operator to include the maintenance information provided by this document in the operator's rotorcraft maintenance manual and/or the operator's rotorcraft scheduled maintenance program.

3. AIRWORTHINESS LIMITATIONS

There are no additional Airworthiness Limitations as defined in 14 CFR § 27, Appendix A. A27.4 that result from this modification. The Airworthiness Limitations section is FAA approved and specifies maintenance required under §§43.16 and 91.403 of the Federal Aviation Regulations unless an alternative program has been FAA approved.