

Introduction

This errata sheet describes all the functional and electrical problems of the SPC560P34x, SPC560P40x devices, identified with the JTAG_ID = 0x2AE2_2041.

All the topics covered in this document refer to RM0046 rev 5, SPC560P34L1, SPC560P34L3, SPC560P40L1, SPC560P40L3 datasheet rev 9, and SPC560P40H1 datasheet rev 2 (see [A.1: Reference document](#)).

Device identification for cut 1.2:

- JTAG_ID = 0x2AE2_2041
- MIDR1 register:
 - MAJOR_MASK[3:0]: 4'b0000
 - MINOR_MASK[3:0]: 4'b0010
- Package device marking mask identifier: AC
- Die mask ID: FP40X1

This errata sheet applies to SPC560P34x, SPC560P40x devices in accordance with [Table 1](#).

Table 1. Device summary

Part number	Package
SPC560P34L1	LQFP64
SPC560P34L3	LQFP100
SPC560P40L1	LQFP64
SPC560P40L3	LQFP100
SPC560P40H1	Bare die

Contents

1	Functional problems	6
1.1	ERR000575: DSPI: Changing CTARs between frames in continuous PCS mode causes error	6
1.2	ERR001082: DSPI: set up enough ASC time when MTFE=1 and CPHA=1	6
1.3	ERR001103: DSPI: PCS Continuous Selection Format limitation	6
1.4	ERR002360: FlexCAN: Global Masks misalignment	7
1.5	ERR002656: FlexCAN: Abort request blocks the CODE field	8
1.6	ERR002685: FlexCAN: Module Disable Mode functionality not described correctly	8
1.7	ERR002883: FMPLL: FMPLL_CR[UNLOCK_ONCE] wrongly set	9
1.8	ERR002894: ADC: Minimum sampling time for ADC at 32 MHz	9
1.9	ERR002897: ADC: Inaccuracy due to Digital Offset Cancellation Handling mechanism	9
1.10	ERR002958: MC_RGM: Clearing a flag at RGM_DES or RGM_FES register may be prevented by a reset	11
1.11	ERR002963: CMU XOSC Monitoring cannot be guaranteed when RCDIV>0 and FOSC is less than $1.5 \cdot F_{rc} / 2^{\wedge}rcdiv$	12
1.12	ERR002971: ADC ABORT bit (single conversion)	12
1.13	ERR002972: ADC: Last conversion in chain not aborted	12
1.14	ERR002973: ADC ABORT CHAIN bit	13
1.15	ERR002981: FMPLL: Do not poll flag FMPLL_CR[PLL_FAIL]	13
1.16	ERR002997: ADC: Injected conversion not executed during scan mode	13
1.17	ERR002999: MC_CGM and MC_PCU: A data storage exception is not generated on an access to MC_CGM or MC_PCU when the respective peripheral is disabled at MC_ME	13
1.18	ERR003010: ADC: conversion chain failing after ABORT chain	14
1.19	ERR003021: LINFlex: Unexpected LIN timeout in slave mode	14
1.20	ERR003022: SWT: Watchdog is disabled during BAM execution	14
1.21	ERR003028: LINFlex: BDRL/BDRM cannot be accessed as byte or half-word	14
1.22	ERR003060: MC_RGM: SAFE mode exit may be possible even though condition causing the SAFE mode request has not been cleared	15
1.23	ERR003069: ADC: ADC_DMAE[DCLR] set to 1 clears the DMA request incorrectly	15

1.24	ERR003110: Debugging functionality could be lost when unsecuring a secured device.	15
1.25	ERR003158: MC_ME: Default data flash configuration for HALT0 mode is illegal	16
1.26	ERR003164: FCU: Timeout feature doesn't work correctly.	16
1.27	ERR003220: MC_CGM: system clock may stop in case target clock source dies during clock switching	16
1.28	ERR003248: ADC: Abort request during last sampling cycle corrupts the data register of next channel conversion	17
1.29	ERR003256: eTimer: Configuring an eTimer counter channel in GATED-COUNT mode or in SIGNED-COUNT mode may cause a possible incorrect counting of 1 tick.	17
1.30	ERR003257: FlexPWM: Configuring the count value to set PWMA/PWMB first low and then high in the same cycle the output signals are low.	18
1.31	ERR003262: Register Protection on full CMU_CSR	19
1.32	ERR003263: Serial Boot and Censorship: flash read access	19
1.33	ERR003264: MCM: MRSR does not report Power On Reset event	19
1.34	ERR003269: MC_ME: Peripheral clocks may get incorrectly disabled or enabled after entering debug mode	19
1.35	ERR003310: FlexPWM: PWM signals are improperly synced when using Master Sync	20
1.36	ERR003335: FlexPWM: Incorrect PWM operation when mixing DMA and non-DMA controlled channels	20
1.37	ERR003407: FlexCAN: CAN Transmitter Stall in case of no Remote Frame in response to Tx packet with RTR=1	20
1.38	ERR003442: CMU monitor: FXOSC/FIRC and FMPLL/FIRC relation	21
1.39	ERR003452: FLASH: Programming just after reading a location of Data Flash with double ECC error can trigger a functional reset.	22
1.40	ERR003511: FlexPWM: Incorrect PWM operation when IPOL is set.	22
1.41	ERR003547: FLASH: Running ECC logic check just after reading a location of data Flash with double ECC error can trigger a functional reset.	22
1.42	ERR003579: Nexus pins may drive an unknown value immediately after power up but before the 1st clock edge	23
1.43	ERR003583: MC_RGM: A non-monotonic ramp on the VDD_HV_REG supply can cause the RGM module to clear all flags in the DES register.	23
1.44	ERR003584: MC_ME: Possibility of Machine Check on Low-Power Mode Exit	24

1.45 ERR003610: FlexCAN: Wrong data transmission exiting from STOP mode in case EXTAL frequency is greater than IRC 26

1.46 ERR005113: ADC: triggering an ABORT or ABORTCHAIN before the conversion starts 26

1.47 ERR005203: ADC: "Abort command" aborts the ongoing injected channel as well as the upcoming normal channel. 27

1.48 ERR005569: ADC: The channel sequence order will be corrupted when a new normal conversion chain is started prior to completion of a pending normal conversion chain. 27

1.49 ERR006583: eTimer: Incorrect updating of the Hold Register 28

1.50 ERR006588: FLASH: 64-bit programming on Data Flash is not supported 28

1.51 ERR006802: eTimer: Extra input capture events can set unwanted DMA requests 29

1.52 ERR007804: LINFlex: Consecutive headers received by LIN Slave triggers error interrupt 29

1.53 ERR007877: FlexPWM: do not enable the fault filter 30

1.54 ERR010865: FCU: Possible fake software faults, SRF[3] and SRF[4], can be captured during flash read access 30

1.55 ERR010876: LINFlex: LINS bits in LIN Status Register(LINSR) are not usable in UART mode. 31

Appendix A Further information 32

A.1 Reference document. 32

A.2 Acronyms 32

Revision history 34



List of tables

Table 1.	Device summary	1
Table 2.	MCR register	10
Table 3.	MSR register	11
Table 4.	OFFSET WORD (OFFWR) register Addr: Base + 0x00C0	11
Table 5.	Interrupt Status Register (ISR)	11
Table 6.	Acronyms	32
Table 7.	Document revision history	34

1 Functional problems

1.1 ERR000575: DSPI: Changing CTARs between frames in continuous PCS mode causes error

Description:

Erroneous data could be transmitted if multiple Clock and Transfer Attribute Registers (CTAR) are used while using the Continuous Peripheral Chip Select mode (DSPIx_PUSHR[CONT=1]). The conditions that can generate an error are:

1. If DSPIx_CTARn[CPHA]=1 and DSPIx_MCR[CONT_SCKE = 0] and DSPIx_CTARn[CPOL, CPHA, PCSSCK or PBR] change between frames.
2. If DSPIx_CTARn[CPHA]=0 or DSPIx_MCR[CONT_SCKE = 1] and any bit field of DSPIx_CTARn changes between frames except DSPIx_CTARn[PBR].

Workaround:

When generating DSPI bit frames in continuous PCS mode, adhere to the aforementioned conditions when changing DSPIx_CTARn bit fields between frames.

1.2 ERR001082: DSPI: set up enough ASC time when MTFE=1 and CPHA=1

Description:

When the DSPI is being used in the Modified Transfer Format mode (DSPI_MCR[MTFE]=1) with the clock phase set for Data changing on the leading edge of the clock and captured on the following edge in the DSPI Clock and Transfer Attributes Register (DSPI_CTARn[CPHA]=1), if the After SCK delay scaler (ASC) time is set to less than 1/2 SCK clock period the DSPI may not complete the transaction - the TCF flag will not be set, serial data will not received, and last transmitted bit can be truncated.

Workaround:

If the Modified Transfer Format mode is required DSPI_MCR[MTFE]=1 with the clock phase set for serial data changing on the leading edge of the clock and captured on the following edge in the SCK clock (Transfer Attributes Register (DSPI_CTARn[CPHA]=1) make sure that the ASC time is set to be longer than half SCK clock period.

1.3 ERR001103: DSPI: PCS Continuous Selection Format limitation

Description:

When the DSPI module has more than one entry in the TX FIFO and only one entry is written and that entry has the CONT bit set, and continuous SCK clock selected the PCS levels may change between transfer complete and write of the next data to the DSPI_PUSHR register.

For example:

If the CONT bit is set with the first PUSHR write, the PCS de-asserts after the transfer because the configuration data for the next frame has already been fetched from the next

(empty) FIFO entry. This behavior continues till the buffer is filled once and all CONT bits are one.

Workaround:

To insure PCS stability during data transmission in Continuous Selection Format and Continuous SCK clock enabled make sure that the data with reset CONT bit is written to DSPI_PUSHR register before previous data sub-frame (with CONT bit set) transfer is over.

1.4 ERR002360: FlexCAN: Global Masks misalignment

Description:

Convention: MSB=0.

During CAN messages reception by FlexCAN, the RXGMASK (Rx Global Mask) is used as acceptance mask for most of the Rx Message Buffers (MB). When the FIFO Enable bit in the FlexCAN Module Configuration Register (CANx_MCR[FEN], bit 2) is set, the RXGMASK also applies to most of the elements of the ID filter table. However there is a misalignment between the position of the ID field in the Rx MB and in RXIDA, RXIDB and RXIDC fields of the ID Tables. In fact RXIDA filter in the ID Tables is shifted one bit to the left from Rx MBs ID position as shown below:

- Rx MB ID = bits 3-31 of ID word corresponding to message ID bits 0-28
- RXIDA = bits 2-30 of ID Table corresponding to message ID bits 0-28

Note that the mask bits one-to-one correspondence occurs with the filters bits, not with the incoming message ID bits.

This leads the RXGMASK to affect Rx MB and Rx FIFO filtering in different ways.

For example, if the user intends to mask out the bit 24 of the ID filter of Message Buffers then the RXGMASK will be configured as 0xffff_ffef. As result, bit 24 of the ID field of the incoming message will be ignored during filtering process for Message Buffers. This very same configuration of RXGMASK would lead bit 24 of RXIDA to be "don't care" and thus bit 25 of the ID field of the incoming message would be ignored during filtering process for Rx FIFO.

Similarly, both RXIDB and RXIDC filters have multiple misalignments with regards to position of ID field in Rx MBs, which can lead to erroneous masking during filtering process for either Rx FIFO or MBs.

RX14MASK (Rx 14 Mask) and RX15MASK (Rx 15 Mask) have the same structure as the RXGMASK. This includes the misalignment problem between the position of the ID field in the Rx MBs and in RXIDA, RXIDB and RXIDC fields of the ID Tables.

Workaround:

Therefore it is recommended that one of the following actions be taken to avoid problems:

- Do not enable the RxFIFO. If CANx_MCR[FEN]=0 then the Rx FIFO is disabled and thus the masks RXGMASK, RX14MASK and RX15MASK do not affect it.
- Enable Rx Individual Mask Registers. If the Backwards Compatibility Configuration bit in the FlexCAN Module Configuration Register (CANx_MCR[BCC], bit 15) is set then the Rx Individual Mask Registers (RXIMR0-63) are enabled and thus the masks RXGMASK, RX14MASK and RX15MASK are not used.
- Do not use masks RXGMASK, RX14MASK and RX15MASK (i.e. let them in reset value which is 0xffff_ffff) when CANx_MCR[FEN]=1 and CANx_MCR[BCC]=0. In this

case, filtering processes for both Rx MBs and Rx FIFO are not affected by those masks.

- Do not configure any MB as Rx (i.e. let all MBs as either Tx or inactive) when CANx_MCR[FEN]=1 and CANx_MCR[BCC]=0. In this case, the masks RXGMASK, RX14MASK and RX15MASK can be used to affect ID Tables without affecting filtering process for Rx MBs.

1.5 ERR002656: FlexCAN: Abort request blocks the CODE field

Description:

An Abort request to a transmit Message Buffer (TxMB) can block any write operation into its CODE field. Therefore, the TxMB cannot be aborted or deactivated until it completes a valid transmission (by winning the CAN bus arbitration and transmitting the contents of the TxMB).

Workaround:

Instead of aborting the transmission, use deactivation instead.

Note that there is a chance that the deactivated TxMB can be transmitted without setting IFLAG and updating the CODE field if it is deactivated.

1.6 ERR002685: FlexCAN: Module Disable Mode functionality not described correctly

Description:

Module Disable Mode functionality is described as the FlexCAN block is directly responsible for shutting down the clocks for both CAN Protocol Interface (CPI) and Message Buffer Management (MBM) sub-modules. In fact, FlexCAN requests this action to an external logic.

Workaround:

In FlexCAN documentation chapter:

Section "Modes of Operation", bullet "Module Disable Mode": Where is written:

"This low power mode is entered when the MDIS bit in the MCR Register is asserted. When disabled, the module shuts down the clocks to the CAN Protocol Interface and Message Buffer Management sub-modules."

The correct description is:

"This low power mode is entered when the MDIS bit in the MCR Register is asserted by the CPU. When disabled, the module requests to disable the clocks to the CAN Protocol Interface and Message Buffer Management sub-modules."

Section "Modes of Operation Details", Sub-section "Module Disable Mode": Where is written:

"This low power mode is entered when the MDIS bit in the MCR Register is asserted. If the module is disabled during Freeze Mode, it shuts down the clocks to the CPI and MBM sub-modules, sets the LPM_ACK bit and negates the FRZ_ACK bit."

The correct description is:

"This low power mode is entered when the MDIS bit in the MCR Register is asserted. If the module is disabled during Freeze Mode, it requests to disable the clocks to the CAN Protocol Interface (CPI) and Message Buffer Management (MBM) sub-modules, sets the LPM_ACK bit and negates the FRZ_ACK bit."

1.7 **ERR002883: FMPLL: FMPLL_CR[UNLOCK_ONCE] wrongly set**

Description:

If the FMPLL is locked and a functional reset occurs, FMPLL_CR[UNLOCK_ONCE] is automatically set even when the FMPLL has not lost lock.

Workaround:

Do not use the FMPLL_CR[UNLOCK_ONCE] when a functional reset occurs.

1.8 **ERR002894: ADC: Minimum sampling time for ADC at 32 MHz**

Description:

When ADC is running at 32 MHz the minimum sampling time of 135 ns specified is not met.

Workaround:

At 32 MHz the minimum sampling time must be at least 180 ns.

1.9 **ERR002897: ADC: Inaccuracy due to Digital Offset Cancellation Handling mechanism**

Description:

The intrinsic ADC precision is better when used without the Digital Offset Cancellation Mechanism. For this reason, reference to the Digital Offset Cancellation (DOC) was removed from the reference manual. However, there is a possible side effect that may result in a small but potentially significant offset up to +/- 8 least significant bits. To remove this possible offset, the following cancellation steps should be followed.

Workaround:

The following three step approach should be used to eliminate any potential offset add-on.

1. Run the offset cancellation routine. Steps:
 - a) Check that the ADC is in Power Down Mode in the ADC Status register MSR[ADCSTATUS] == 001
 - b) Configure ADC Conversion Time in the ADC Conversion time register - The value of this register depends on the ADC clock.
 - c) Enable Offset Cancellation by setting the offset cancellation enable bit in the ADC Module Control Register MCR[OFFCANC]=1
 - d) Power up ADC by clearing the MCR[PWDN] bit and wait for MSR[ADCSTATUS] == 000 (IDLE state)
 - e) Wait until ADC Offset Cancellation completes MSR[OFFCANC] == 0 or until the ISR[EOFFSET] is set. If the offset error cancellation occurs, the ISR[EOFFSET] flag is set and the OFFCANC bit of MCR and MSR registers remain at 1. The MCR[OFFCANC] bit can be cleared by software to abort the DOC sequence, while the MSR[OFFCANC] flag cannot be cleared until the next reset.
 - f) When ISR [EOFFSET] do these: Abort DOC procedure: Clear MCR[OFFCANC], Wait for MSR[ADCSTATUS] == 000 (IDLE state) and clear the ISR[OFFCANC] flag.
2. Overwrite the digital cancellation result to 0 in the Offset Word Register (OFFWR Register). Steps:
 - a) Enable Offset Register setting/write OFFWR[OFFSET_LOAD] bit
 - b) Write OFFWR[OFFSET_WORD] field with 0 with setting OFFWR[OFFSET_LOAD] bit
3. Load the new value of OFFSET_WORD instead of the one calculated from DOC mechanism into internal offset register which is buffered and disable possibility to overwrite the OFFSET_WORD. There is necessary to create one dummy conversion by sampling at least one channel.
 - a) Enable sampling one channel in the NCMR[0].R.
 - b) Start conversion by setting MCR[NSTART] or MCR[JSTART] bit.
 - c) Check if the conversation is finished in the main status register MSR[NSTART].
 - d) Disable the load of offset register OFFWR[OFFSETLOAD].

Register description

Registers and fields related to Digital Offset Cancellation procedure have been removed from documentation. In the following they are described in order to allow applying the software workaround described.

Table 2. MCR register

Bit	Bit Name	Description
28	OFFCANC	0: No offset cancellation phase 1: Offset cancellation phase before conversion

This bit is reset to zero when the Offset Cancellation ends.

Table 3. MSR register

Bit	Bit Name	Description
28	OFFCANC	0: Offset cancellation phase completed 1: Offset cancellation phase is ongoing

Table 4. OFFSET WORD (OFFWR) register Addr: Base + 0x00C0

Bit	Bit Name	Description
0:14	Reserved	Write of any value has no effect, read value is always zero.
15	OFFSET_LOAD	0: Disable offset loading, 1: Enable offset loading, that bit should be written before writing OFFSET_WORD field.
16:23	Reserved	Write of any value has no effect, read value is always zero.
24:31	OFFSET_WORD	The offset word coefficient generated at the end of the Digital Offset Cancellation phase is latched into this register. The offset word can also be written by software. In this case, it is loaded into analog ADC and used as offset cancellation word instead of the one calculated using offset cancellation process.

Table 5. Interrupt Status Register (ISR)

Bit	Bit Name	Description
25	OFFCANCOVR	Offset Cancellation Phase Over When the ADC generate the offset_ok_i to high indication then the offset cancellation phase programmed by the user is over and the offset coefficient is written into the offset register.
26	EOFFSET	This interrupt is generated during the offset cancellation phase in case the offset_measure_ok_i pulse is not received.

Note: Both bits are cleared by writing one to their position.

1.10 ERR002958: MC_RGM: Clearing a flag at RGM_DES or RGM_FES register may be prevented by a reset

Description:

Clearing a flag at RGM_DES and RGM_FES registers requires two clock cycles because of a synchronization mechanism. As a consequence if a reset occurs while clearing is ongoing the reset may interrupt the clearing mechanism leaving the flag set.

Note that this failed clearing has no impact on further flag clearing requests.

Workaround:

No workaround for all reset sources except SW reset.

Note that in case the application requests a SW reset immediately after clearing a flag in RGM_xES the same issue may occur. To avoid this effect the application must ensure that flag clearing has completed by reading the RGM_xES register before the SW reset is requested.

1.11 **ERR002963: CMU XOSC Monitoring cannot be guaranteed when RCDIV>0 and FOSC is less than $1.5 \cdot Frc / 2^{RCDIV}$**

Description:

A False OLRI (Oscillator frequency less than RC frequency) event may be generated when FOSC is less than $1.5 \cdot (FRC / 2^{RCDIV})$ and RCDIV>0, and not $FRC / 2^{RCDIV}$ as described in the Reference Manual).

Correct crystal clock monitoring is guaranteed when FOSC is strictly above $1.5 \cdot (FRC / 2^{RCDIV})$.

Workaround:

There are 2 workarounds available :

1. Keep RCDIV = 0
2. When RCDIV > 0, ensure FOSC is greater than $FRC / 2^{(RCDIV - 1)}$ to avoid false OLRI (CMU external oscillator failure) event.

1.12 **ERR002971: ADC ABORT bit (single conversion)**

Description:

If the User starts one single ADC conversion and, after, starts a chain of conversions, when the User tries to abort one of the chained conversions, the abort command aborts the chain instead of a single conversion of the chain.

Workaround:

- A minimum of two conversions must be programmed
- A dummy conversion must be started before or after a single conversion

1.13 **ERR002972:ADC: Last conversion in chain not aborted**

Description:

If the user aborts the last ADC conversion of a chain the conversion appears to be aborted but the relevant data register is updated with the conversion data.

Workaround:

None.

1.14 ERR002973: ADC ABORT CHAIN bit

Description:

If user aborts a chain of ADC conversions, the current conversion appears as aborted but the relative data register is however updated.

Workaround:

None.

1.15 ERR002981: FMPLL: Do not poll flag FMPLL_CR[PLL_FAIL]

Description:

For the case when the FMPLL is indicating loss of lock the flag FMPLL_CR[PLL_FAIL] is unpredictable.

Workaround:

To avoid reading an incorrect value of FMPLL_CR[PLL_FAIL] only read this flag inside the FMPLL Interrupt Service Routine (ISR). The ISR indicates the flag has been set correctly and at this point the flag can be cleared. Do not poll flag FMPLL_CR[PLL_FAIL] at any other point in the application software.

1.16 ERR002997: ADC: Injected conversion not executed during scan mode

Description:

When ADC is converting a chain in scan mode -configured using NSTART bit in non-CTU mode operation; and a injected conversion arrives -triggered by software with JSTART bit or by hardware from eTimer_1 channel 5 (internal connection); the ADC gets stuck in the sampling phase (the triggered conversion is not executed and the chain is not restarted).

Workaround:

None.

1.17 ERR002999: MC_CGM and MC_PCU: A data storage exception is not generated on an access to MC_CGM or MC_PCU when the respective peripheral is disabled at MC_ME

Description:

If a peripheral with registers mapped to MC_CGM or MC_PCU address spaces is disabled via the MC_ME any read or write accesses to this peripheral will be ignored without producing a data storage exception.

Workaround:

For any mode other than a low-power mode do not disable any peripheral that is mapped to MC_CGM or MC_PCU.

1.18 **ERR003010: ADC: conversion chain failing after ABORT chain**

Description:

During a chain conversion while the ADC is in scan mode when ADC_MCR[ABORTCHAIN] is asserted the current chain will be aborted as expected. However, in the next scan the first conversion of the chain is performed twice and the last conversion of the chain is not performed.

Workaround:

When aborting a chain conversion enable ADC_MCR[ABORTCHAIN] and disable ADC_MCR[START].

ADC_MCR[START] can be enabled when the abort is complete.

1.19 **ERR003021: LINFlex: Unexpected LIN timeout in slave mode**

Description:

If the LINFlex is configured in LIN slave mode, an unexpected LIN timeout event (LINESR[OCF]) may occur during LIN Break reception.

Workaround:

It is recommended to disable this functionality during LINFlex initialization by clearing LINTCSR[IOT] and LINIER[OCIE] bits, and ignore timeout events.

1.20 **ERR003022: SWT: Watchdog is disabled during BAM execution**

Description:

The watchdog is disabled at the start of BAM execution. In the case of an unexpected issue during BAM execution the CPU may be stalled and it is necessary to generate an external reset to recover.

Workaround:

No workaround.

1.21 **ERR003028: LINFlex: BDRL/BDRM cannot be accessed as byte or half-word**

Description:

LINFlex data buffers (BDRL/BDRM) cannot be accessed as byte or halfword. Accessing BDRL/BDRM in byte/half word mode will lead to incorrect data writing/reading.

Workaround:

Access BDRL/BDRM registers as word only.

1.22 **ERR003060: MC_RGM: SAFE mode exit may be possible even though condition causing the SAFE mode request has not been cleared**

Description:

A SAFE mode exit should not be possible as long as any condition that caused a SAFE mode entry is still active. However, if the corresponding status flag in the RGM_FES register has been cleared, the SAFE mode exit may incorrectly occur even though the actual condition is still active.

Workaround:

Software must clear the SAFE mode request condition at the source before clearing the corresponding RGM_FES flag. This will ensure that the condition is no longer active when the RGM_FES flag is cleared and thus the SAFE mode exit can occur under the correct conditions.

1.23 **ERR003069: ADC: ADC_DMAE[DCLR] set to 1 clears the DMA request incorrectly**

Description:

When ADC_DMAE[DCLR] is set the DMA request should be cleared only after the data registers are read. However for this case the DMA request is automatically cleared and will not be recognised by the eDMA.

Workaround:

None.

1.24 **ERR003110: Debugging functionality could be lost when unsecuring a secured device.**

Description:

Providing the backdoor password via JTAG or via serial boot would unsecure the device, but on some devices may leave the Nexus interface and potentially the CPUs in an undetermined state.

Normal operation without a debugger is unaffected, debugging unsecured devices is also unaffected.

Workaround:

A second connection attempt may be successful. Boot in serial mode (using the Flash password), then execute code which unsecures the device (the JTAG interface needs to be inactive while the unsecure happens).

Implement a separate backdoor in application software. Once the software detects the custom backdoor sequence it can unlock the device via Flash write.

Leave device unsecured for debugging.

1.25 **ERR003158: MC_ME: Default data flash configuration for HALT0 mode is illegal**

Description:

The data flash supports only the 'normal mode' and the 'power down' which are coded as "11" and "01", respectively, in the ME_<mode>_MC registers. In the case of the ME_HALT0_MC register, the default value of the DFLAON field is "10", which is not supported and may lead to an unknown data flash state if not changed before entering the HALT0 mode.

Workaround:

Software must write the DFLAON field of the ME_HALT0_MC register with a legal value of either "11" or "01" prior to requesting a mode change to the HALT0 mode.

1.26 **ERR003164: FCU: Timeout feature doesn't work correctly.**

Description:

A fault occurs, timeout for this fault is enabled and the fault is not recovered automatically before the timeout. In this case device will go to ALARM state and waits for timeout, after timeout has elapsed it enters to FAULT state. However, if another fault occurs with timeout enabled the FCU will go directly to FAULT state without waiting for timeout to be elapsed. If it is desired that FCU will go again to ALARM state for the second fault, a Watchdog reset needs to be asserted after first fault is detected.

Workaround:

None.

1.27 **ERR003220: MC_CGM: system clock may stop in case target clock source dies during clock switching**

Description:

The clock switching is a two step process. The availability of the target clock is first verified. Then the system clock is switched to the new target clock source within two target clock cycles.

For the case when the FXOSC stops during the required two cycles, the switching process may not complete, causing the system clock to stop and prevent further clock switching. This may happen if one of the following cases occurs while the system clock source is switching to FXOSC:

- FXOSC oscillator failure
- SAFE mode request occurs, as this mode will immediately switch OFF the FXOSC (refer to ME_SAFE_MC register configuration).

Workaround:

The device is able to recover through any destructive reset event, so typically either the SWT (internal watchdog) will generate a reset and the device will restart properly after reset.

To reduce the probability that this issue occurs in the application, it is recommended to disable SAFE mode transitions when the device is executing a mode transition with the FXOSC as the system clock source in the target mode.

1.28 **ERR003248: ADC: Abort request during last sampling cycle corrupts the data register of next channel conversion**

Description:

If the abort pulse is valid in the last cycle of the SAMPLE phase, the current channel is correctly aborted but the data register (CDR[0...15]) of the next channel conversion shows an invalid value.

Workaround:

None.

1.29 **ERR003256: eTimer: Configuring an eTimer counter channel in GATED-COUNT mode or in SIGNED-COUNT mode may cause a possible incorrect counting of 1 tick.**

Description:

This bug affects eTimer in the following counting modes:

- GATED-COUNT mode, the CNTMODE field is '011' (count rising edges of primary source while secondary input is high);
- SIGNED-COUNT mode, the CNTMODE field is '101' (count primary source rising edges, secondary source specifies direction (up/down)).

Delays in the edge detection circuitry lead to a bug where the rising edge on the primary source is compared to the secondary source value one clock later in time. This means that if there is a rising edge on the primary source followed immediately by the secondary source going high, the eTimer logic could see this as a rising primary edge while the secondary is high even though the secondary input was low at the time of the rising primary edge.

Note: The counter will also increment if the primary source is already high when the secondary source goes high.

The inputs are sampled by MOTC_CLK and a transition detector finds the rising edge. It is not an asynchronous counter. Also, transitions are limited to one rising or falling edge per clock period. The primary and secondary inputs come into the Timer and are sampled. The primary input is checked for a rising edge which takes another clock period. This extra cycle of delay on only the primary input is the problem.

If the primary source transitions high while the secondary is low, then no counting should occur. If the secondary source transitions high in the clock cycle after the primary source transition, then the extra delay to find the rising edge will confuse the counter and it will think that the primary rising edge occurred while the secondary was high and will increment the counter.

If the transitions of the primary and secondary sources are more than one clock period apart, then there will be no incorrect counting.

Possibly, the user will accept that if the edges occur this close together, then its okay to consider it as a countable occurrence, this is application dependant and the responsibility of the user.

Workaround:

The source selected as the secondary input to the eTimer channel needs to have an additional clock cycle of delay added to it. This can be achieved by using the input filters.

For the primary source set `FILT_PER==1` and `FILT_CNT==0`.

For the secondary source set `FILT_PER==1` and `FILT_CNT==1`.

This will introduce a 5 clock cycle latency on the primary source and a 6 cycle latency on the secondary source which will properly align the two signals for Gated and Signed count modes.

Note: Ensure that the primary source is low before the secondary source goes high to avoid a false count.

Note: This work-around is only valid when the sources are external an pass through the input filter, internal signals have no work-around.

1.30 **ERR003257: FlexPWM: Configuring the count value to set PWMA/PWMB first low and then high in the same cycle the output signals are low.**

Description:

The VAL2 and VAL4 registers define the turn-on edge and the VAL3 and VAL5 registers define the turn off edge of the PWMA/PWMB signals respectively. VAL3 cannot be less than VAL2 and VAL5 cannot be less than VAL4. Doing so will cause the PWM signal to turn off at the correct time (VAL3 or VAL5), but it will not turn on at the time defined by VAL2 or VAL4. This can be an issue during the generation of phase delayed pulses where the PWM signal goes high late in PWM cycle N and remains high across the cycle boundary before going low early in cycle N+1 and goes high again in PWM cycle N+1. This errata will allow that to happen.

VAL3 register must be "greater than or equal to" VAL2 register and VAL5 must be "greater than or equal to" VAL4.

Workaround:

None.

1.31 **ERR003262: Register Protection on full CMU_CSR**

Description:

The register protection on CMU_CSR of CMU0 works only on the full 32 bit, while it should protect only the bits 24-31.

As a consequence, when register protection is active on CMU_CSR the frequency meter cannot be used anymore.

Workaround:

In order to perform a frequency meter operation, the register protection of the relevant CMU must be disabled first; this workaround would work only when soft lock is active.

1.32 **ERR003263: Serial Boot and Censorship: flash read access**

Description:

In a secured device, starting with a serial boot, it is possible to read the content of the four flash locations where the RCHW is stored.

For example if the RCHW is stored at address 0x00000000, the reads at address 0x00000000, 0x00000004, 0x00000008 and 0x0000000C will return a correct value. Any other flash address is not readable.

Workaround:

No workaround.

1.33 **ERR003264: MCM: MRSR does not report Power On Reset event**

Description:

The flag POR of MRSR register stays low after Power On Reset event on the device.

Workaround:

Do not use MRSR[POR] to determine Power on reset cause. Use RGM_DES instead.

1.34 **ERR003269: MC_ME: Peripheral clocks may get incorrectly disabled or enabled after entering debug mode**

Description:

If ME_RUN_PCx, ME_LP_PCx, ME_PCTLx registers are changed to enable or disable a peripheral, and the device enters debug mode before a subsequent mode transition, the peripheral clock gets enabled or disabled according to the new configuration programmed. Also ME_Psx registers will report incorrect status as the peripheral clock status is not expected to change on debug mode entry.

Workaround:

After modifying any of the ME_RUN_PCx, ME_LP_PCx, ME_PCTLx registers, request a mode change and wait for the mode change to be completed before entering debug mode in

order to have consistent behaviour on peripheral clock control process and clock status reporting in the ME_PSx registers.

1.35 **ERR003310: FlexPWM: PWM signals are improperly synced when using Master Sync**

Description:

If Master Sync signal, originated as the Local Sync from sub-module 0, is selected as the counter initialization signal for sub-modules 1-2-3 (slaves), with a prescaler PRSC < 0x2 on PWM clock, the slave sub-module PWM outputs are delayed approx 2 IP clock against sub-module 0.

For PRSC > 0x1 the delay on slave sub-modules disappears.

Workaround:

If Master Sync signal is requested, use a prescaler value PRSC >=0x2 to synchronize PWM outputs of Sub-module 0 to slave sub-modules PWM outputs, or don't use the sub-module 0 channel A and B.

1.36 **ERR003335: FlexPWM: Incorrect PWM operation when mixing DMA and non-DMA controlled channels**

Description:

When some submodules use DMA to load their VALx registers and other submodules use non-DMA means that means direct writes from the CPU, the LDOK bits for the non-DMA submodules can be incorrectly cleared at the completion of the DMA controlled load cycle. This leads to the non-DMA channels not being properly updated.

Submodules that use DMA to read the input capture registers do not cause a problem for non-DMA submodules.

Workaround:

Set the DMA enable bit to 1 also for non-DMA submodules, according to this the DMA will not incorrectly clear the LDOK bit for non-DMA submodules but they will be set to 1 at the end of each DMA cycle. When the CPU has to update the VALx registers of non-DMA submodules, first clear LDOK bit for non-DMA submodules.

1.37 **ERR003407: FlexCAN: CAN Transmitter Stall in case of no Remote Frame in response to Tx packet with RTR=1**

Description:

FlexCAN does not transmit an expected message when the same node detects an incoming Remote Request message asking for any remote answer.

The issue happens when two specific conditions occur:

1. The Message Buffer (MB) configured for remote answer (with code "a") is the last MB. The last MB is specified by Maximum MB field in the Module Configuration Register (MCR[MAXMB]).
2. The incoming Remote Request message does not match its ID against the last MB ID.

While an incoming Remote Request message is being received, the FlexCAN also scans the transmit (Tx) MBs to select the one with the higher priority for the next bus arbitration. It is expected that by the Intermission field it ends up with a selected candidate (winner). The coincidence of conditions (1) and (2) above creates an internal corner case that cancels the Tx winner and therefore no message will be selected for transmission in the next frame. This gives the appearance that the FlexCAN transmitter is stalled or "stops transmitting".

The problem can be detectable only if the message traffic ceases and the CAN bus enters into Idle state after the described sequence of events.

There is NO ISSUE if any of the conditions below holds:

- a) The incoming message matches the remote answer MB with code "a".
- b) The MB configured as remote answer with code "a" is not the last one.
- c) Any MB (despite of being Tx or Rx) is reconfigured (by writing its CS field) just after the Intermission field.
- d) A new incoming message sent by any external node starts just after the Intermission field.

Workaround:

Do not configure the last MB as a Remote Answer (with code "a").

1.38 ERR003442: CMU monitor: FXOSC/FIRC and FMPLL/FIRC relation

Description:

Functional CMU monitoring can only be guaranteed when the following conditions are met:

- FXOSC frequency must be greater than $(FIRC / 2^{RCDIV}) + 0.5\text{MHz}$ in order to guarantee correct FXOSC monitoring
- FMPLL frequency must be greater than $(FIRC / 4) + 0.5\text{MHz}$ in order to guarantee correct FMPLL monitoring

Workaround:

Refer to description.

1.39 **ERR003452: FLASH: Programming just after reading a location of Data Flash with double ECC error can trigger a functional reset.**

Description:

If a double-bit ECC error is encountered when reading the data flash, a functional reset will occur if the next data flash access is a program (irrespective of the length of time between the data read causing the ECC error and the program attempt).

If another location in the data flash is read (which does not generate an ECC error) before attempting to program the data flash, the reset does not occur. This only impacts programming operations - an erase after a double-bit ECC error will not generate a reset.

Workaround:

If a double-bit ECC error is encountered in the data flash, the application software must read another byte in the data flash without an ECC error prior to performing a program operation on the data flash. There is a read only data flash test flash block at address 0x00C0_2000 and the recommendation is to read data from this location to provide the "non ECC" data read. This procedure could be automated by adding the test block read to the exception handler for a data flash ECC event.

1.40 **ERR003511: FlexPWM: Incorrect PWM operation when IPOL is set.**

Description:

When IPOL bit is set in complementary mode, the source of the PWMi waveform is supposed to be switched from the VAL2 and VAL3 registers to the VAL4 and VAL5 registers. This switch is not happening.

Workaround:

Instead of setting IPOL bit, the application can swap the VAL2/3 values with the VAL4/5 values.

1.41 **ERR003547: FLASH: Running ECC logic check just after reading a location of data Flash with double ECC error can trigger a functional reset.**

Description:

If a double-bit ECC error is encountered when reading the data flash, a functional reset occurs if an ECC Logic Check is then carried out on the data flash at any point before the next reset.

Workaround:

Ensure that there have been no ECC double bit errors encountered in the data flash before carrying out an ECC Logic check.

1.42 **ERR003579: Nexus pins may drive an unknown value immediately after power up but before the 1st clock edge**

Description:

The Nexus Output pins (Message Data outputs 0:3 [MDO] and Message Start/End outputs 0:1 [MSEO]) may drive an unknown value (high or low) immediately after power up but before the 1st clock edge propagates through the device (instead of being weakly pulled low). This may cause high currents if the pins are tied directly to a supply/ground or any low resistance driver (when used as a general purpose input [GPI] in the application).

Workaround:

1. Do not tie the Nexus output pins directly to ground or a power supply.
2. If these pins are used as GPI, limit the current to the ability of the regulator supply to guarantee correct start up of the power supply. Each pin may draw up to few hundred mA current.

If not used, the pins may be left unconnected.

1.43 **ERR003583: MC_RGM: A non-monotonic ramp on the VDD_HV_REG supply can cause the RGM module to clear all flags in the DES register.**

Description:

At system power-up a non-monotonic voltage ramp-up or a very slow voltage ramp-up (also known as 'soft start-up') can cause incorrect flag setting in the RGM_DES register. During monotonic power-up, F_POR flag is set when the high voltage regulator supply (VDD_HV_REG) goes above LVD27_VREG low voltage detector threshold and the 1.2V supply (VDD_LV_REGCOR) goes above LVD12_PD0 low voltage detector threshold. Expected behavior POR =1, LVD27 =0, LVD12=0.

During a non-monotonic power-up the VDD_HV_REG may show a non-linearity in the ramp up. When the VDD_HV_REG supply dips below LVD27_VREG threshold, LVD27_VREG low voltage detector is re-fired. If VDD_LV_REGCOR is already above LVD12_PD0 low voltage detector threshold, F_POR flag is reset and F_LVD27_VREG is set. Expected behavior POR=0, LVD27 =1, LVD12=0.

This errata reports behavior when the non-linearity on VDD_HV_REG coincides with the ramp-up of VDD_LV_REGCOR completion and LVD27_VREG is re-fired just after the LVD12_PD0 is released. In this case, neither F_POR flag nor F_LVD27_VREG flag will be set. In this case, application code cannot use the flags to tell if a power-on reset has occurred.

This errata only affects the flag circuit and not a the device initialization. Device initializes correctly under all conditions.

Workaround:

Hardware Workaround

Ensure that non-linearity on VDD_HV_REG is < 100mV. This is the hysteresis limit of the device. Board regulator should be chosen accordingly.

Software Workaround

The software workaround need only be applied when neither the F_POR, LVD27 or LVD12 flags are set and involves checking SRAM contents and monitoring for ECC errors during this process. In all cases, an ECC error is assumed to signify a power-on reset (POR).

Two suggestions are made for software workarounds. In both cases, if POR is detected all RAM should be initialized otherwise no power-on condition is detected and it is possible to initialize only needed parts of RAM while preserving required information.

Software workaround #1:

An area of RAM can be reserved by the compiler into which a KEY, such as 0x3EC1_9678, is written. This area can be checked at boot and if the KEY is incorrect or an ECC error occurs, POR can be assumed and the KEY should be set. Use of a KEY increases detection rate to 31 bits(= $<10e-9$) or 23bits (= $<5.10e-6$) instead of 7-bit linked to ECC (= $<10e-2$)

Software workaround #2:

When runtime data should be retained and RAM only re-initialized in the case of POR, the CRC module should be used to calculate and store a CRC signature when writing data that can be checked at boot time. If CRC signature is incorrect, POR can be assumed.

1.44 ERR003584: MC_ME: Possibility of Machine Check on Low-Power Mode Exit

Description:

When executing from the flash and entering a Low-Power Mode (LPM) where the flash is in low-power or power-down mode, 2-4 clock cycles exist at the beginning of the RUNx to LPM transition during which a wakeup or interrupt will generate a machine check due to the flash not being available on RUNx mode re-entry. This will cause either a checkstop reset or machine check interrupt.

Workaround:

This issue can be handled in one of the following ways. Workaround #1 configures the application to handle the machine check interrupt in RAM dealing with the problem if it occurs. Workaround #2 configures the MCU to avoid the machine check interrupt.

Workaround #1

The application can be configured to handle the machine check interrupt in RAM; when this occurs, the Mode Entry module can be used to bring up the flash normally and resume execution. Before stop mode entry, ensure the following:

1. Enable the Machine Check interrupt at the core MSR[ME] – this prevents a machine check reset occurring
2. Copy IVOR vector table to RAM
3. Point IVPR to vector table in RAM
4. Implement Machine Check interrupt handler in RAM to power-cycle flash to synchronise status of flash between Mode Entry and flash module

The interrupt handler should perform the following steps:

1. Test Machine Check at LPM exit due to wakeup/interrupt event
2. ME_RUNx_MC[CFLAON] = 0b01 (power-down)
3. Re-enter mode RUNx (x = 0,1,2,3) to power down flash
4. Wait for transition to RUNx mode to complete (ME_GS[S_MTRANS] = 1)
5. ME_RUNx_MC[CFLAON] = 0b11 (normal)
6. Re-enter mode RUNx (x = previous x) to power up flash
7. Wait for transition to RUNx mode to complete (ME_GS[S_MTRANS] = 1)
8. On completion, code execution will return to flash (via se_rfc)

Workaround #2

The application can be configured to avoid the machine check interrupt; low-power mode can be entered from a RAM function and Mode Entry configured to have flash off on return to the current RUNx mode. Flash can then be re-enabled by Mode Entry within the RAM function before returning to execution from flash.

1. Prior to LPM mode entry request branch to code execution in RAM while flash is still in normal mode
2. Set ME_RUNx_MC[CFLAON] = 0b01 (power-down) or 0b10 (low-power) for STOP0/HALT0
3. Set ME_STOP0/HALT0_MC[CFLAON] = ME_RUNx_MC[CFLAON]
4. Enter STOP0/HALT0 mode
5. At wakeup or interrupt from STOP0/HALT0, MCU enters RUNx mode executing from RAM with flash in low-power or power-down as per the ME_RUNx_MC configuration from step 2.
6. After the STOP0/HALT0 request, set ME_RUNx_MC[CFLAON] = 0b11 (normal)
7. Enter RUNx mode
8. Wait for transition to RUNx mode to complete (ME_GS[S_MTRANS] = 0)
9. Return to code execution in flash

1.45 **ERR003610: FlexCAN: Wrong data transmission exiting from STOP mode in case EXTAL frequency is greater than IRC**

Description:

The FlexCAN module has got a programmable clock source that can be either the system clock (SYS_CLK) or oscillator clock (XOSC_CLK) selected by CLK_SRC bit in the FlexCAN_CTRL register.

In case FlexCAN module has selected the oscillator clock as clock source and XOSC_CLK is bigger than IRC frequency @16 MHz and the system clock is PLL_CLK if the device enters STOP mode and the FlexCAN module is in transmission then when device exits from STOP mode the FlexCAN module can transmit wrong data.

This behavior happens because during STOP mode exit, SYS_CLK will be IRC @16MHz till PLL gets locked and if a frame transmission happens during this time itself then there will be a CAN Spec violation.

The FlexCAN module clock source should not be faster than SYS_CLK.

Workaround:

Just before entering/requesting the STOP mode, set the "FRZ" and "HALT" bit of CAN_MCR register to '1' to request for freeze mode.

During the STOP mode exit, check for the mode transition completion. As mode transition will be over, only when all clock sources are on and the PLL is selected as system clock, unfreeze the CAN by resetting the "FRZ" or "HALT" bit.

1.46 **ERR005113: ADC: triggering an ABORT or ABORTCHAIN before the conversion starts**

Description:

When ABORTCHAIN is programmed (ADC_MCR[ABORTCHAIN] = 1) and an injected chain conversion is programmed afterwards, the injected chain is aborted, but neither ADC_ISR[JECH] is set, nor ADC_MCR [ABORTCHAIN] is reset.

When ABORT is programmed (ADC_MCR[ABORT] = 1) and normal/injected chain conversion comes afterwards, the ABORT bit is reset and chain conversion runs without a channel abort.

If ABORT or ABORTCHAIN feature is programmed after the start of the chain conversion, it works properly.

Workaround:

Do not program ADC_MCR[ABORT]/ ADC_MCR[ABORTCHAIN] before starting the execution of the chain conversion.

1.47 **ERR005203: ADC: "Abort command" aborts the ongoing injected channel as well as the upcoming normal channel.**

Description:

If an Injected chain (jch1,jch2,jch3) is injected over a Normal chain (nch1,nch2,nch3,nch4) the Abort switch does not behave as expected.

Expected behavior:

Correct Case (without SW Abort on jch3): Nch1-> Nch2(aborted)->Jch1 -> Jch2 -> Jch3 ->Nch2(restored) -> Nch3->Nch4

Correct Case (with SW Abort on jch3): Nch1-> Nch2(aborted)->Jch1 -> Jch2 -> Jch3(aborted) ->Nch2(restored) -> Nch3->Nch4

Observed unexpected behavior:

Fault1 (without SW abort on jch3): Nch1-> Nch2(aborted) -> Jch1 -> Jch2 -> Jch3 -> Nch3 -> Nch4 (Nch2 not restored)

Fault2 (with SW abort on jch3): Nch1-> Nch2 (aborted)->Jch1 -> Jch2 -> Jch3(aborted) -> Nch4 (Nch2 not restored &Nch3 conversion skipped)

Workaround:

It is possible to detect the unexpected behavior by using the ADC_CDATAB[x] register. The ADC_CDATAB[x][VALID] fields will not be set for a not restored or skipped channel, which indicates this issue has occurred. The ADC_CDATAB[x][VALID] fields need to be checked before the next Normal chain execution (provided ADC_MCR[OWREN] bit is set in scan mode). The ADC_CDATAB[x][VALID] fields should be read by every ECH interrupt at the end of every chain execution.

1.48 **ERR005569: ADC: The channel sequence order will be corrupted when a new normal conversion chain is started prior to completion of a pending normal conversion chain.**

Description:

If One shot mode is configured in the Main Configuration Register (MCR[MODE] = 0) the chained channels are automatically enabled in the Normal Conversion Mask Register 0 (NCMR0). If the programmer initiates a new chain normal conversion, by setting MCR[NSTART] = 0x1, before the previous chain conversion finishes, the new chained normal conversion will not follow the requested sequence of converted channels.

For example, if a chained normal conversion sequence includes three channels in following sequence: channel0, channel1 and channel2, the conversion sequence is started by MCR[NSTART] = 0x1. The software re-starts the next conversion sequence when MCR[NSTART] is set to 0x1 just before the current conversion sequence finishes.

The conversion sequence should be: channel0, channel1, channel2, channel0, channel1, channel2.

However, the conversion sequence observed will be: channel0, channel1, channel2, channel1, channel1, channel2. Channel0 is replaced by channel1 in the second chain conversion and channel1 is converted twice.

Workaround:

Ensure a new conversion sequence is not started when a current conversion is ongoing. This can be ensured by issuing the new conversion setting MCR[NSTART] only when MSR[NSTART] = 0.

Note: MSR[NSTART] indicates the present status of conversion. MSR[NSTART] = 1 means that a conversion is ongoing and MSR[NSTART] = 0 means that the previous conversion is finished

1.49 ERR006583: eTimer: Incorrect updating of the Hold Register**Description:**

The eTimer's Hold Registers (ETIMER_CHn_HOLD) are incorrectly updated when a Compare and Capture Control Register (ETIMER_CHn_CCCTRL) is read.

Workaround:

The eTimer's Hold Registers are supposed to be updated with the Counter Registers (ETIMER_CHn_CNTR) value whenever a Counter Register is read. Recognize that the Hold Registers values will also be updated if a Compare and Capture Control Register is read.

1.50 ERR006588: FLASH: 64-bit programming on Data Flash is not supported**Description:**

Data flash access for programming is limited to word-mode (32-bit). Double-word-mode (64-bit) is not implemented.

Workaround:

Do not use Double-word-mode.

1.51 ERR006802: eTimer: Extra input capture events can set unwanted DMA requests

Description:

When using the DMA to read the eTimer channel capture registers (ETIMER_CHn_CAPTn) and the DMA has completed its programmed number of transfers an extra input capture event will set the eTimers input capture flag bit in the status register (ETIMER_CHn_STS[ICFn]) and also set the internal DMA request signal. While the input capture flag status bits (ICFn) can be cleared by writing a 1 to their bit positions the DMA request can only be cleared by the DMA done signal. This means that when a new DMA transfer is programmed the eTimer will request a DMA read with possibly unwanted data. This behavior occurs once the DMA requests are disabled on the side of eDMA (DMA_ERQ[ERQn] = 0), but are still enabled in eTimer (ETIMER_CHn_INTDMA[ICFnDE] = 1), and the active edge is detected

Workaround:

In cases where extra eTimer input capture events might occur the following procedure can be used to prevent unwanted DMA read requests:

1. Upon completion of the DMA transfer, disable the DMA requests by clearing the ETIMER_CHn_INTDMA[ICFnDE] bits.
2. If ETIMER_CHn_STS[ICFn] bits are clear then there are no extra input capture events and the eTimer is ready for further operation.
3. If the ICFn bits are set then read the ETIMER_CHn_CAPTn registers until the ETIMER_CHn_CTRL3[CnFCNT] fields are both 0 indicating the capture FIFO's are empty.

Then write a 1 to the ICFn bits to clear them. Next, create a dummy DMA read transfer to read the CAPTn registers. The DMA done signal will clear any pending DMA request.

1.52 ERR007804: LINFlex: Consecutive headers received by LIN Slave triggers error interrupt

Description:

As per the Local Interconnect Network (LIN) specification, the processing of one frame should be aborted by the detection of a new header sequence.

But in LINFlex IP, if the LIN Slave receives a new header instead of data response corresponding to a previous header received, it triggers a framing error during the new header's reception. Also the LIN Slave remains waiting for the data response corresponding to the first header received.

Workaround:

The following workaround should be applied:

1. Set the LTOM bit in the LIN Time-Out Control Status Register (LINTCSR[LTOM]) to '0'.
2. Set Idle on Timeout in the LINTCSR[IOT] register to '1'.
3. Configure master to wait until the occurrence of the Output Compare flag in LIN Error Status Register (LINESR[OCF]) before sending the next header. This flag causes the LIN Slave to go to an IDLE state before the next header arrives, which will be accepted without any framing error.

1.53 ERR007877: FlexPWM: do not enable the fault filter

Description:

Operation of the fault pin filter of the Flexible Pulse Width Modulation (FLEX_PWM) may be inconsistent if the Fault Filter is enabled, by setting the Filter Period greater than zero in the Fault Filter register (FFILT[FILT_PER] > 0). The fault filter flag may be set even though the pulse is shorter than the filter time.

Workaround:

Do not enable the PWM fault pin filters. Disable the fault pin filters by setting the Fault Filter Period to 0 in the Fault Filter Register (FFILT[FILT_PER] = 0).

1.54 ERR010865: FCU: Possible fake software faults, SRF[3] and SRF[4], can be captured during flash read access

Description:

After flash read access, despite no Double ECC Error is actually present, a fake fault may be captured by FCU module and reported as one of the following SW faults:

- SRF[4]: Code Flash ECC Multi bit error
- SRF[3]: Data Flash ECC Multi bit error

The Flash correctly does not signal the ECC event error and the ECC Event Error flag (EER) in Module Configuration Register (MCR) of Flash is set to '0x0' to indicate that all previous reads (from the last reset, or clearing of EER) were correct.

The Data storage interrupt (IVOR 2) is not invoked.

Based on SYS_CLK frequency, the issue on SRF[4] does not happen in case of number of wait states for Code Flash is programmed by PFCR0[BK0_RWSC] bit field bigger or equal than:

- 3WS @ 50 < freq <= 64 MHz
- 2WS @ 25 < freq <= 50 MHz
- 1WS @ freq <= 25 MHz

The issue on SRF[3] does not happen in case of number of wait states for Data Flash is programmed by PFCR1[BK1_RWSC] bit field bigger or equal than 8 (RWSC >= 8).

Workaround:

To ensure the actual fault condition, the software should confirm the setting SRF[3] and SRF[4] flags in Fault Flag Register (FCU_FFR) by reading the value of ECC Event Error flag (EER) in the MCR register of Flash.

1.55 **ERR010876: LINFlex: LINS bits in LIN Status Register(LINSR) are not usable in UART mode.**

Description:

When the LINFlex module is used in the Universal Asynchronous Receiver/Transmitter (UART) mode, the LIN state bits (LINS[3:0]) in LIN Status Register (LINSR) always indicate the value zero. Therefore, these bits cannot be used to monitor the UART state.

Workaround:

LINS bits should be used only in LIN mode

Appendix A Further information

A.1 Reference document

1. *SPC560P34/SPC560P40 32-bit MCU family built on the embedded Power Architecture® (RM0046, DocID16912)*
2. *32-bit Power Architecture® based MCU with 576 KB Flash memory and 40 KB SRAM for automotive chassis and safety applications (SPC560P44L3, SPC560P44L5, SPC560P50L3, SPC560P50L5 datasheet, DocID14723)*
3. *32-bit Power Architecture® based MCU with 320 KB Flash memory and 20 KB RAM for automotive chassis and safety applications (SPC560P40H1 datasheet, DocID024401)*

A.2 Acronyms

Table 6. Acronyms

Acronym	Name
ABS	Alternate boot selector
ADC	Analog-to-digital converter
AIE	Array integrity enable
BAM	Boot assist module
BDRL	Buffer Data Register Least Significant
BDRM	Buffer Data Register Most Significant
CHI	Controller host interface
CMU	Clock monitor unit
DMA	Direct memory access
ECC	Error correction code
ECR	ECC configuration register
EDC	ECC data correction
FAB	Force alternate boot
FCU	Fault collection unit
FIFO	First in first out
Flash_MCR	Flash module configuration register
HBL	High address space block locking register
ISR	Interrupt service routine
LPM_ACK	Low power mode acknowledge
LVD	Low voltage detector
MB	Message buffer
MBCCSR	Message buffer configuration, control, status register
MCKO	Nexus clock

Table 6. Acronyms (continued)

Acronym	Name
MCR	Module configuration register
MCU	Microcontroller unit
MDO	Nexus message data output
ME	Match enabled
NVM	Non-volatile memory
PCR	Pad configuration register
PFAPR	Platform Flash access protection register
PFCR	Platform Flash configuration register
POR	Power on reset
RWE	Read-while-write event error
RXGMASK	RX global mask
RXIMR	RX individual mask register
SLL	Secondary low/mid address space block lock register

Revision history

Table 7. Document revision history

Date	Revision	Changes
12-Jun-2013	1	Initial release
17-Sep-2013	2	Updated Disclaimer.
16-May-2017	3	Added following functional problems: – ERR005569 – ERR006583 – ERR006802 – ERR007804 – ERR007877 – ERR010865 – ERR010876 Removed Appendix A “Defects across silicon version”.
25-May-2017	4	Removed following functional problem: – ERR006082

IMPORTANT NOTICE – PLEASE READ CAREFULLY

STMicroelectronics NV and its subsidiaries ("ST") reserve the right to make changes, corrections, enhancements, modifications, and improvements to ST products and/or to this document at any time without notice. Purchasers should obtain the latest relevant information on ST products before placing orders. ST products are sold pursuant to ST's terms and conditions of sale in place at the time of order acknowledgement.

Purchasers are solely responsible for the choice, selection, and use of ST products and ST assumes no liability for application assistance or the design of Purchasers' products.

No license, express or implied, to any intellectual property right is granted by ST herein.

Resale of ST products with provisions different from the information set forth herein shall void any warranty granted by ST for such product.

ST and the ST logo are trademarks of ST. All other product or service names are the property of their respective owners.

Information in this document supersedes and replaces information previously supplied in any prior versions of this document.

© 2017 STMicroelectronics – All rights reserved