Bulletin No.: 03-00-91-001G

GM CONTROL OF THE CON

Date: Jan-2015

Service Bulletin

INFORMATION

Subject: Vibration Analysis Worksheet

Models: 2015 and Prior GM Passenger Cars and Trucks

This Bulletin has been revised to add the 2015 Model Year and to edit the ring gear backlash measurements in the Vibration Analysis Worksheet. Please discard Corporate Bulletin Number 03-00-91-001F.

When diagnosing vibration concerns, use the following worksheet in conjunction with the appropriate Vibration Analysis-Road testing procedure in the Vibration Correction sub-section in SI. FILL OUT ONLY THE APPLICABLE PORTION OF THE WORKSHEET THAT APPLIES TO THE VIBRATION / NOISE.

Refer to the appropriate section of SI for specifications and repair procedures that are related to the vibration concern.

Vibration Analysis Worksheet

To:
Dealer:
Fax Number:
VIN
Procedure Performed By:
Date:
Model:
Year: Gear Ratio:
Odometer:
VIN
TAC Case #, if applicable:
Conditions During Road Test Procedures
As condition occurs: Engine RPM
Vehicle Speed
Vibration/Noise detected during the following road test procedures:
Engine RPMVehicle Speed
Slow Acceleration Test: Yes No
Neutral Coast-Down Test: Yes No
Downshift Test: YesNo
Neutral Run-Up Test: Yes No
Brake Torque Test: Yes No
Steering Input Test: Yes No
Standing Start Acceleration (Launch Shudder) Test: Yes No
Vibration/Noise Eliminated with TCC Commanded On: YesNo
Vibration/Noise Eliminated with TCC Commanded Off: YesNo
Vibration/Noise Duplicated on Hoist: YesNo
When using the EVA, always take a snapshot. This will help determine which vibration shows up the most.
Important: Vibrate software can also be used to assist in vibration diagnosis. Refer to Vibrate Software Description and Operation in SI.
EVA Readings
Refer to Electronic Vibration Analyzer (EVA) Description and Operation in SI for more detailed information.
Important: As a reminder, place the EVA sensor where the vibration is felt by the customer or on the test drive i.e.: if the vibration complaint is from the seat then place the sensor on the seat track, if the vibration complaint is from the steering wheel then attach the sensor to the steering column. Ensure the word "UP" on the sensor is physically facing up. The typical areas are the seat track, the steering
column or the instrument panel. Locating the EVA sensor on additional area (i.e. the right fender, left fender, right quarter panel, left quarter panel, rear seat track, etc.) may also assist in determining the component causing the vibration/noise. The key is to look for the same Hz
reading with the greatest amplitude G readings.
FILL OUT ONLY THE APPLICABLE PORTION OF THE WORKSHEET THAT APPLIES TO THE VIBRATION/NOISE:
Sensor at Steering Column:
1st Line MPH/KPH: HZ: Gs:
2nd Line MPH/KPH: HZ: Gs:
Sensor at Drivers Seat Rail:

Sensor at D	rivers Se	at Rail:									
1st Line MP	H/KPH:_		HZ:	Gs:_							
2nd Line MF	PH/KPH:		_ HZ:	Gs:_							
Sensor at P	assenge	Seat Rail:									
1st Line MP	H/KPH:_		HZ:	Gs:_							
2nd Line MF	PH/KPH:		_ HZ:	Gs:_							
Driveshaft F	Runout:										
Is runout wit	thin spec	ification? Ye	es	No							
Initial: Frt:		_ Center:_		Rear:	Stub S	Shaft:					
Current: Frt	:	Center	·	_ Rear:	Stu	b Shaft:					
Pinion Flan	ge Runou	it Reading:_									
Has a syste	m baland	e been atte	mpted: Yes		No	(If no,	perform a Sy	/stem Balar	nce)		
Were the dr	ums rem	oved to sys	tem balance	e? Yes	No						
Initial: HZ		_ Gs									
Current: HZ		Gs									
Hose clamp	s added:	Yes	No								
Prop shaft in	ndexed?	Yes	No								
If a System	Balance	has been a	ttempted bu	t the vibrat	ion is still pres	ent or syst	em balance	was not able	e to be achieve	d, check the r	ing gear
		th of the rin	g gear. Note	e that exces	ssive ring gea	r runout ma	ay result in a	first order ti	re speed or firs	t order prop s	haft
speed conce			,								
				_	ıld not vary mo						
					57						
									20		
									30		
						37	38	39	40		
Does the ve		-	_		s attached?						
Pinion damp	_										
Pinion flang					-						
Exhaust dar											
			_		Rear Ang						
				ngle:	Rear A	ngle:					
Were shims	added to	the followi	ng?								
					0						
Pinion nose	(rear spr	ings): Yes_		No							
Center Supp	port Mou	nt: Yes	No		_						
Tire Size an	d Brand:										
Record whe	el baland	e information	on below if a	available re	cord weight in	formation	prior to balan	ce and afte	r balance.		
\A(I) 1(T)											
Wheel/Tire		arla 4.	0.1	\\/a:							
Right rear: I											
Left rear: In											
Right front:											
Left front: In	_										
Wheel/Tire											
Refer to the	latest ve	rsion of Co	rporate Bulle	etin Numbe	er 00-03-10-00	6 for tire ra	adial force va	riation infori	mation.		

Refer to the latest version of Corporate Bulletin Number	00-03-10-006 for tire radial force variation information.
Right rear: Inner lateral: Center radial:	
Left rear: Inner lateral: Center radial:	
Right front: Inner lateral: Center radial:	
Left front: Inner lateral: Center radial:	
Mounting surface runouts (max. 0.005 in (0.127 mm))	
Flange, right rear: Hub, right front:	_
Flange, left rear: Hub, left front:	
Wheel stud runouts (max. 0.008 in (0.203 mm))	
Flange, right rear: Hub, right front:	_
Flange, left rear: Hub, left front:	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

