

ArubaOS 8.9.0.0 Release Notes



a Hewlett Packard
Enterprise company

Copyright Information

© Copyright 2021 Hewlett Packard Enterprise Development LP.

Open Source Code

This product includes code licensed under the GNU General Public License, the GNU Lesser General Public License, and/or certain other open source licenses. A complete machine-readable copy of the source code corresponding to such code is available upon request. This offer is valid to anyone in receipt of this information and shall expire three years following the date of the final distribution of this product version by Hewlett Packard Enterprise Company. To obtain such source code, send a check or money order in the amount of US \$10.00 to:

Hewlett Packard Enterprise Company
6280 America Center Drive
San Jose, CA 95002
USA

Contents	3
Revision History	5
Release Overview	6
Related Documents	6
Supported Browsers	6
Guidelines Before Upgrading 7000 Series Controllers to ArubaOS 8.9.0.0	7
Terminology Change	7
Contacting Support	7
New Features and Enhancements in ArubaOS 8.9.0.0	9
Configuring Default Gateway on 7280 Controllers	9
Dashboard Monitoring	9
Displaying the Name for Assa Abloy Door Locks	9
Enhancement to Serial Data Transport Profiles	9
Exporting IDS Logs from WebUI	9
New IoT Generic Filtering options	9
Configuring Wireless Containment Deauth	9
Upgrade to Vendor QOSMOS Code	10
Mesh Support on Wi-Fi 6E Access Points	10
Support for Azure Southbound Action for BLE Devices	10
Support for UTB	10
Increase in Maximum Supported BLE and Zigbee TX Power Values	10
Support for 512 Clients on Wi-Fi 6E Access Points	10
Support for Air Slice on Wi-Fi 6E Access Points	10
Support for New Channel Representation on Wi-Fi 6E Access Points	10
Support for New AP Platform	11
Support for Hotspot on Wi-Fi 6E Access Points	11
Support for Multiple BSSID on Wi-Fi 6E Access Points	11
Configuring 6 GHz Radio Band on AP-635 Access Points	11
Support for Wi-Fi 6E ARM	12
Support for Wi-Fi 6E AirMatch	12
Support for Wi-Fi 6E Air Management	12
Support for Wi-Fi 6E Air Management Activity Detection	12
Support for Wi-Fi 6E Air Management Information Element Parsing	12
Scanning Enhancements for Wi-Fi 6E Access Points	12
Support for 6 GHz Radio	12
Support Regulatory Domain Profile for 6 GHz Radio	12
Support for Client Match for 6 GHz Radio	12
Support for EN302502 and EN301893 in UN13 Bands	13
Support for GCM Ciphers on AP-555 Access Point	13
Support for Dropbear SSH	13
Client Match Support for 802.11v	13
Enhancements to Multicast Group Limit	13
Enabling TLS Method for an External Logging Server	13
Encrypt Private Key in the Flash	13
Enhancements to number of PVST+ instances	13
Increase in Number of Tunneled Networks in VIA	13

Upgrade Notification for a Cluster Upgrade	13
Supported Platforms in ArubaOS 8.9.0.0	14
Mobility Conductor Platforms	14
Mobility Controller Platforms	14
AP Platforms	14
Regulatory Updates in ArubaOS 8.9.0.0	16
Resolved Issues in ArubaOS 8.9.0.0	17
Known Issues in ArubaOS 8.9.0.0	30
Limitation	30
Known Issues	30
Upgrade Procedure	35
Important Points to Remember	35
Memory Requirements	36
Low Free Flash Memory	36
Backing up Critical Data	40
Upgrading ArubaOS	42
Verifying the ArubaOS Upgrade	43
Downgrading ArubaOS	45
Before Calling Technical Support	47

The following table lists the revision numbers and the corresponding changes that were made in this release:

Table 1: *Revision History*

Revision	Change Description
Revision 01	Initial release.

This ArubaOS release notes includes the following topics:

- New Features and Enhancements
- Supported Platforms
- Regulatory Updates
- Resolved Issues
- Known Issues and Limitations
- Upgrade Procedure

Related Documents

The following guides are part of the complete documentation for the Aruba user-centric network:

- *ArubaOS Getting Started Guide*
- *ArubaOS User Guide*
- *ArubaOS CLI Reference Guide*
- *ArubaOS API Guide*
- *Aruba Mobility Conductor Licensing Guide*
- *Aruba Virtual Appliance Installation Guide*
- *Aruba AP Software Quick Start Guide*

Supported Browsers

The following browsers are officially supported for use with the ArubaOS WebUI:

- Microsoft Internet Explorer 11 on Windows 7 and Windows 8
- Microsoft Edge (Microsoft Edge 38.14393.0.0 and Microsoft EdgeHTML 14.14393) on Windows 10
- Mozilla Firefox 48 or later on Windows 7, Windows 8, Windows 10, and macOS
- Apple Safari 9.0 or later on macOS
- Google Chrome 67 on Windows 7, Windows 8, Windows 10, and macOS

Guidelines Before Upgrading 7000 Series Controllers to ArubaOS 8.9.0.0

Customers with deployments containing the following 7000 Series controllers should read the [Low Free Flash Memory](#) requirements prior to attempting an upgrade of the 7000 Series controllers to ArubaOS 8.9.0.0:

- 7005
- 7008
- 7010

If you are unable to free up sufficient flash memory, contact Technical Support. Do not reboot the controller.

Terminology Change

As part of advancing HPE's commitment to racial justice, we are taking a much-needed step in overhauling HPE engineering terminology to reflect our belief system of diversity and inclusion. Some legacy products and publications may continue to include terminology that seemingly evokes bias against specific groups of people. Such content is not representative of our HPE culture and moving forward, Aruba will replace racially insensitive terms and instead use the following new language:

Usage	Old Language	New Language
Campus Access Points + Controllers	Master-Slave	Conductor-Member
Instant Access Points	Master-Slave	Conductor-Member
Switch Stack	Master-Slave	Conductor-Member
Wireless LAN Controller	Mobility Master	Mobility Conductor
Firewall Configuration	Blacklist, Whitelist	Denylist, Allowlist
Types of Hackers	Black Hat, White Hat	Unethical, Ethical

Contacting Support

Table 2: *Contact Information*

Main Site	arubanetworks.com
Support Site	https://asp.arubanetworks.com/
Airheads Social Forums and Knowledge Base	community.arubanetworks.com
North American Telephone	1-800-943-4526 (Toll Free) 1-408-754-1200
International Telephone	arubanetworks.com/support-services/contact-support/

Software Licensing Site	lms.arubanetworks.com
End-of-life Information	arubanetworks.com/support-services/end-of-life/
Security Incident Response Team	Site: arubanetworks.com/support-services/security-bulletins/ Email: aruba-sirt@hpe.com

This chapter describes the features and enhancements introduced in this release.

Configuring Default Gateway on 7280 Controllers

ArubaOS supports configuring the default gateway for dedicated OOB management Ethernet port on 7280 controllers by using the **ip default-gateway mgmt <next-hop>** command.

Dashboard Monitoring

A search option is introduced in the **Campus AP Allowlist** and **Remote AP Allowlist** tables of the **Configuration > Access Points > Allowlist** page in the WebUI.

Displaying the Name for Assa Abloy Door Locks

The Assa Abloy door locks will now be displayed using a name in the output of the `show ap debug zigbee client-table` command. This enhancement is helpful in identifying and debugging issues related to a specific Assa Abloy door lock connected to the system.

Enhancement to Serial Data Transport Profiles

A new CLI parameter **usbSerialDeviceTypeFilter <filter>** is added to the IoT transport profile configuration to allow users to filter serial data based on the USB dongle type.

Exporting IDS Logs from WebUI

Starting from ArubaOS 8.9.0.0, a user has the option of exporting IDS logs as a CSV file from the WebUI.

New IoT Generic Filtering options

The following generic filtering parameters are introduced in the IoT Transport Profile configuration:

- **usbSerialDeviceTypeFilter <filter>**
- **companyIdentifierFilter <filter>**
- **serviceUUIDFilter <filter>**
- **macOuiFilter <filter>**
- **localNameFilter <filter>**

Configuring Wireless Containment Deauth

A new parameter **Wireless Containment Deauth** is introduced to enable users to set a unique reason code in the deauth frame. This unique reason code identifies if the deauths are originating from the WIPs solution.

Upgrade to Vendor QOSMOS Code

The vendor QOSMOS code is upgraded to ProtoBundle-1.530.1-25 for ArubaOS 8.9.0.0 release.

Mesh Support on Wi-Fi 6E Access Points

ArubaOS provides support for mesh deployment and WPA3-SAE-AES opmode on Wi-Fi 6E access points.

Support for Azure Southbound Action for BLE Devices

The Asynchronous Cloud to Device (C2D) messages are added to support Azure southbound action on BLE devices.

Support for UTB

A new parameter **utb_filter_block** is introduced to control the band on which the Ultra Tri-Band (UTB) limitation is applied in the regulatory-domain-profile. The UTB filter supports channel band on both 5 GHz and 6 GHz in ArubaOS 8.9.0.0 release.

Increase in Maximum Supported BLE and Zigbee TX Power Values

The maximum configurable transmission (Tx) power rate in an IoT radio profile is increased to 20 dBm.

Support for 512 Clients on Wi-Fi 6E Access Points

ArubaOS supports 512 clients for each radio band on Wi-Fi 6E access points.

Support for Air Slice on Wi-Fi 6E Access Points

ArubaOS supports Air Slice on Wi-Fi 6E access points for 5 GHz radio band only.

Support for New Channel Representation on Wi-Fi 6E Access Points

ArubaOS represents the channels on 6 GHz band as four separate fields for Wi-Fi 6E access points. The four separate fields are as follows:

- **Pri-Channel**
- **Sec-Channel**
- **Band**
- **Bandwidth**

ArubaOS also modifies the following AMON messages to include the four separate fields for each 6 GHz radio channel:

- RADIO_STATS
- RADIO_INFO
- AMON_TAG

- UCM_SESSION_UPDATE
- SPEC_DEV_DETAILS
- AG_SVC_SESSION_UPDATE

Support for New AP Platform

The Aruba 630 Series access points (AP-635) are high performance, tri-radio, indoor access points that can be deployed in either controller-based (ArubaOS) or controller-less (Aruba Instant) network environments. These APs deliver high performance concurrent 2.4 GHz, 5 GHz, and 6 GHz 802.11ax Wi-Fi (Wi-Fi 6E) functionality with MIMO radios (2x2 in 2.4 GHz, 5 GHz, and 6 GHz), while also supporting 802.11a, 802.11b, 802.11g, 802.11n, and 802.11ac wireless services. Containment does not work on the 6 GHz radio when WPA3 with Management Frame Protection (MFP) is enabled.

Additional features include:

- IEEE 802.11a, IEEE 802.11b, IEEE 802.11g, IEEE 802.11n, IEEE 802.11ac, and IEEE 802.11ax operation as a wireless access point.
- IEEE 802.11a, IEEE 802.11b, IEEE 802.11g, IEEE 802.11n, IEEE 802.11ac, and IEEE 802.11ax spectrum monitor.
- Two Ethernet ports, ENET0 and ENET1, capable of data rates up to 2.5 Gbps.
- Compatible with IEEE 802.3bt, IEEE 802.3at, and IEEE 802.3af PoE standards on both Ethernet ports.
- Thermal management.
- Support for OFDMA.

For complete technical details and installation instructions, see Aruba 630 Series Access Points Installation Guide.

Support for Hotspot on Wi-Fi 6E Access Points

ArubaOS supports Hotspot 2.0 on the 2.4 GHz and 5 GHz radio bands of Wi-Fi 6E access points.

Support for Multiple BSSID on Wi-Fi 6E Access Points

ArubaOS supports Multiple BSSID feature on Wi-Fi 6E access points. Multiple BSSID feature supports multiple virtual APs of a radio and advertises information for multiple BSSIDs by using a single beacon or probe response frame instead of multiple beacon or probe response frames, each corresponding to a single BSSID.

Configuring 6 GHz Radio Band on AP-635 Access Points

Following are the guidelines to ensure a successful deployment of AP-635 access points by configuring the 6 GHz radio band:

- The virtual APs for 6 GHz radio band are disabled by default and must be enabled manually in the WLAN SSID settings of the virtual APs. To configure the WLAN SSID settings in the WebUI, navigate to **Configuration > System > Profiles** and select **Wireless LAN > Virtual AP** under **All Profiles** list, and enable the **Allow 6GHz Band** parameter. You can also enable the **allowed-band-6ghz** parameter in the **wlan virtual-ap <profile>** command.
- To allow the 6 GHz clients to connect to the 6 GHz WLAN SSID, Aruba recommends the following steps:

- a. Navigate to **Configuration > System > Profiles** and select **Wireless LAN > Virtual AP** under **All Profiles** list, and select **none** from the **Allowed band** drop-down list and enable the **Allow 6GHz Band** check box. You can also set the **allowed-band** parameter to **none** and enable the **allowed-band-6ghz** parameter in the **wlan virtual-ap <profile>** command.
- b. Create an alternate WLAN SSID virtual AP on 2.4 GHz and 5 GHz radio bands. Navigate to **Configuration > System > Profiles** and select **Wireless LAN > Virtual AP** under **All Profiles** list, and select **all** from the **Allowed Band** drop-down list, and disable the **Allow 6GHz Band** check box. You can also set the **allowed-band** parameter to **all** and **allowed-band-6ghz** parameter to **none** in the **wlan virtual-ap <profile>** command. This allows 6 GHz clients to locate 6 GHz APs through Reduced Neighbor Report (RNR) in 2.4 GHz and 5 GHz beacons.

For more information, refer to the *ArubaOS 8.9.0.0 User Guide*.

Support for Wi-Fi 6E ARM

ArubaOS supports ARM on Wi-Fi 6E access points.

Support for Wi-Fi 6E AirMatch

ArubaOS supports AirMatch on Wi-Fi 6E access points.

Support for Wi-Fi 6E Air Management

ArubaOS supports Air Management on Wi-Fi 6E access points.

Support for Wi-Fi 6E Air Management Activity Detection

ArubaOS supports Wi-Fi 6E Air Management activity detection on 6 GHz channels.

Support for Wi-Fi 6E Air Management Information Element Parsing

ArubaOS supports Wi-Fi 6E Air Management information element parsing on 6 GHz channels.

Scanning Enhancements for Wi-Fi 6E Access Points

Air Monitoring is enhanced to support scanning in the new Wi-Fi 6E AP-635 access points.

Support for 6 GHz Radio

ArubaOS supports configuration of the 6 GHz radio in the applicable access points. The 6 GHz radio can be configured in the RF management profile.

Support Regulatory Domain Profile for 6 GHz Radio

ArubaOS supports configuration of the regulatory domain profile for the 6 GHz radio.

Support for Client Match for 6 GHz Radio

ArubaOS supports configuration of the client match for the 6 GHz radio.

Support for EN302502 and EN301893 in UNI3 Bands

The AP-374 outdoor access point supports EN302502 and EN301893 for DFS in UNI3 bands. Support for EN302502 allows the usage of higher power in the UNI3 band in ETSI and support for EN301893 allows radar detection.

Support for GCM Ciphers on AP-555 Access Point

AP-555 access point supports GCM ciphers.

Support for Dropbear SSH

ArubaOS supports Dropbear SSH version 2019.78.

Client Match Support for 802.11v

The Client Match process sends only the fields that are relevant to it in the protobuf format and the AP station management process populates the rest of the message.

Enhancements to Multicast Group Limit

Starting from ArubaOS 8.9.0.0, the multicast group limit per managed device is increased from 8 to 32.

Enabling TLS Method for an External Logging Server

Starting from ArubaOS 8.9.0.0, a new sub-parameter is introduced to enable TLS method defined in RFC-5425. It can be used to secure log messages sent to an external logging server.

Encrypt Private Key in the Flash

Starting from ArubaOS, private key and passphrase are encrypted using TPM keys.

Enhancements to number of PVST+ instances

ArubaOS supports 128 PVST+ instances.

Increase in Number of Tunneled Networks in VIA

Starting from ArubaOS 8.9.0.0, VIA split tunnel network limit is increased to 256.

Upgrade Notification for a Cluster Upgrade

Starting from ArubaOS 8.9.0.0, the **Maintenance > Software Management** page in the **Managed Network** node hierarchy displays **RAPs are present, upgrade may take longer time** message when a cluster with Remote APs are upgraded.

This chapter describes the platforms supported in this release.

Mobility Conductor Platforms

The following table displays the Mobility Conductor platforms that are supported in this release:

Table 3: *Supported Mobility Conductor Platforms*

Mobility Conductor Family	Mobility Conductor Model
Hardware Mobility Conductor	MM-HW-1K, MM-HW-5K, MM-HW-10K
Virtual Mobility Conductor	MM-VA-50, MM-VA-500, MM-VA-1K, MM-VA-5K, MM-VA-10K

Mobility Controller Platforms

The following table displays the Mobility Controller platforms that are supported in this release:

Table 4: *Supported Mobility Controller Platforms*

Mobility Controller Family	Mobility Controller Model
7000 Series Hardware Mobility Controllers	7005, 7008, 7010, 7024, 7030
7200 Series Hardware Mobility Controllers	7205, 7210, 7220, 7240, 7240XM, 7280
9000 Series Hardware Mobility Controllers	9004, 9012
MC-VA-xxx Virtual Mobility Controllers	MC-VA-10, MC-VA-50, MC-VA-250, MC-VA-1K

AP Platforms

The following table displays the AP platforms that are supported in this release:

Table 5: *Supported AP Platforms*

AP Family	AP Model
200 Series	AP-204, AP-205
203H Series	AP-203H
203R Series	AP-203R, AP-203RP
205H Series	AP-205H

Table 5: Supported AP Platforms

AP Family	AP Model
207 Series	AP-207
210 Series	AP-214, AP-215
220 Series	AP-224, AP-225
228 Series	AP-228
270 Series	AP-274, AP-275, AP-277
300 Series	AP-304, AP-305
303 Series	AP-303, AP-303P
303H Series	AP-303H, AP-303HR
310 Series	AP-314, AP-315
318 Series	AP-318
320 Series	AP-324, AP-325
330 Series	AP-334, AP-335
340 Series	AP-344, AP-345
360 Series	AP-365, AP-367
370 Series	AP-374, AP-375, AP-377
370EX Series	AP-375EX, AP-377EX, AP-375ATEX
AP-387	AP-387
500 Series	AP-504, AP-505
500H Series	AP-505H
510 Series	AP-514, AP-515, AP-518
530 Series	AP-534, AP-535
550 Series	AP-555
560 Series	AP-565, AP-567
570 Series	AP-574, AP-575, AP-577
635 Series	AP-635

This chapter contains the Downloadable Regulatory Table (DRT) file version introduced in this release. Periodic regulatory changes may require modifications to the list of channels supported by an AP. For a complete list of channels supported by an AP using a specific country domain, access the controller Command Line Interface (CLI) and execute the **show ap allowed-channels country-code <country-code> ap-type <ap-model>** command.

For a complete list of countries and the regulatory domains in which the APs are certified for operation, refer to the Downloadable Regulatory Table or the DRT Release Notes at <https://asp.arubanetworks.com/>.

The following DRT file version is part of this release:

- DRT-1.0_80922

This chapter describes the resolved issues in this release.

Table 6: *Resolved Issues in ArubaOS 8.9.0.0*

New Bug ID	Old Bug ID	Description	Reported Version
AOS-200515 AOS-219987	—	The DDS process crashed on managed devices running ArubaOS 8.3.0.10 or later versions. The fix ensures that the managed devices work as expected.	ArubaOS 8.3.0.10
AOS-209352	—	Some managed devices terminating VIA connection displayed the error message, httpd[30106]: Reached session limit: 64 . The fix ensures that the managed devices work as expected. This issue was observed in managed devices running ArubaOS 8.6.0.5 or later versions.	ArubaOS 8.6.0.5
AOS-211545 AOS-217654	—	Some APs crashed and rebooted unexpectedly. The log files listed the reason for the event as, Reboot caused by kernel panic: Fatal exception in interrupt . The fix ensures that the APs work as expected. This issue was observed in APs running ArubaOS 8.5.0.10 or later versions.	ArubaOS 8.5.0.10
AOS-212386	—	The Configuration > Licensing tab of the WebUI did not display any data. The fix ensures that the WebUI displays the licensing details. This issue occurred when high availability was configured. This issue was observed in Mobility Conductors running ArubaOS 8.3.0.0 or later versions.	ArubaOS 8.3.0.0
AOS-212755	—	Some users connecting to AP-505 access points running ArubaOS 8.7.0.0 were unable to pass traffic intermittently. The fix ensures that clients are able to pass traffic.	ArubaOS 8.7.0.0
AOS-213337	—	A few AP-325 access points running ArubaOS 8.5.0.10 or later versions crashed unexpectedly. The log files list the reason for the event as Reboot caused by kernel panic: Fatal exception in interrupt . The fix ensures that the APs work as expected.	ArubaOS 8.5.0.10
AOS-214391 AOS-217130 AOS-217832	—	The STM process crashed on 7240XMcontrollers. The fix ensures that the controllers work as expected. This issue was observed in 7240XMcontrollers running ArubaOS 8.4.0.0 or later versions.	ArubaOS 8.4.0.0

Table 6: Resolved Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-214416	—	Some stand-alone controllers running ArubaOS 8.6.0.6 or later versions displayed the error message, An internal system error has occurred at file main.c function rx_handler line 1517 error sxd_r_read_str_safe szFunctionName failed . The fix ensures that the stand-alone controllers work as expected.	ArubaOS 8.6.0.6
AOS-214510 AOS-219139	—	A few clients were disconnected from the network. The log files listed the reason for the event as Wlan driver excessive tx fail quick kickout . The fix ensures seamless connectivity. This issue was observed in managed devices running ArubaOS 8.6.0.5 or later versions.	ArubaOS 8.6.0.5
AOS-214846	—	The status of the APs was incorrectly displayed as down. The fix ensures that the Mobility Conductors display the correct status of APs. This issue was observed in Mobility Conductors running ArubaOS 8.5.0.9 or later versions.	ArubaOS 8.5.0.9
AOS-215669	—	Some managed devices running ArubaOS 8.6.0.7 or later versions crashed and rebooted unexpectedly. The log file listed the reason for the event as Datapath timeout (Heartbeat Initiated) (Intent:cause:register 53:86:50:4) . The fix ensures that the managed devices work as expected.	ArubaOS 8.6.0.7
AOS-216536 AOS-220630	—	Some managed devices running ArubaOS 8.5.0.11 or later versions are unable to come up on the Mobility Conductor. This issue occurs when the managed devices get the branch IP address as the controller IP address in a VPNC deployment.	ArubaOS 8.5.0.11
AOS-216777	—	The Mobility Conductor was unable to recover. This issue was observed when the flash memory was 100% used in the Mobility Conductor. Once the flash space is increased as per SKU requirements, the Mobility Conductor recovers. This issue is observed in ArubaOS 8.9.0.0 version.	ArubaOS 8.9.0.0
AOS-215852	—	Mobility Conductors running ArubaOS 8.6.0.6 or later versions log the error message, ofa: 07765 ofproto INFO Aruba-SDN: 1 flow_mods 28 s ago (1 modifications) . This issue occurs when openflow is enabled and when 35 seconds is configured as UCC session idle timeout.	ArubaOS 8.6.0.6
AOS-216145	—	Mobility Conductors running ArubaOS 8.5.0.8 or later versions sent continuous DNS requests to the managed devices. This issue occurred when a folder that was not available on the /mm node was trying to get synchronized on the managed devices. The fix ensures that the Mobility Conductors do not send continuous DNS requests to the Managed Devices.	ArubaOS 8.5.0.8

Table 6: Resolved Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-216536 AOS-220630	—	Some managed devices running ArubaOS 8.5.0.11 or later versions were unable to come up on the Mobility Conductor. This issue occurred when the managed devices received the branch IP address as the controller IP address in a VPNC deployment. The fix ensures that the managed devices are able to come up on the Mobility Conductor.	ArubaOS 8.5.0.11
AOS-217104 AOS-219159	—	The ESI redirect failed and traffic was forwarded to the default gateway. The fix ensures that the managed devices work as expected. This issue was observed in managed devices running ArubaOS 8.6.0.6 or later versions.	ArubaOS 8.6.0.6
AOS-151022 AOS-188417	185176	The output of the show datapath uplink command displayed incorrect session count. The fix ensures that the show datapath uplink command displays correct session count. This issue was observed in managed devices running ArubaOS 8.1.0.0 or later versions.	ArubaOS 8.1.0.0
AOS-193231 AOS-200101 AOS-207456	—	The Dashboard > Infrastructure > Access Devices page of the WebUI displayed an error message, Error retrieving information . The fix ensures that the WebUI displays the list of access devices. This issue was observed in Mobility Conductors running ArubaOS 8.5.0.3 or later versions.	ArubaOS 8.5.0.3
AOS-209093 AOS-210452	—	Some managed devices running ArubaOS 8.7.0.0 or later versions generated multiple AMON receiver errors. The fix ensures that the managed devices work as expected.	ArubaOS 8.7.0.0
AOS-210198	—	The Dashboard > Security > Detected Radio page of the WebUI displayed incorrect number of Clients . The fix ensures that the WebUI displays correct number of Clients . This issue was observed in Mobility Conductors running ArubaOS 8.6.0.5 or later versions.	ArubaOS 8.6.0.5
AOS-213011 AOS-219946	—	Packet loss was observed for a few clients during a cluster failover. This issue was observed in managed devices running ArubaOS 8.0.0.0 or later versions. The fix ensures that the managed devices work as expected.	ArubaOS 8.5.0.10
AOS-214977 AOS-220420	—	Memory leak was observed in arci-cli-helper process. This issue occurred while running an API script. The fix ensures that the APs work as expected. This issue was observed in APs running ArubaOS 8.5.0.8 or later versions.	ArubaOS 8.5.0.8

Table 6: Resolved Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-215303	—	Users were unable to view file names in the Diagnostic > Technical Support > Copy Files page of the WebUI. This issue occurred when Flash file system was selected as the source file. The fix ensures that users are able to view the file names in the Diagnostic > Technical Support > Copy Files page of the WebUI. This issue was observed in managed devices running ArubaOS 8.5.0.11 or later versions.	ArubaOS 8.5.0.11
AOS-215498	—	Some AP-535 access points running ArubaOS 8.5.0.11 or later versions detected false radar. The fix ensures that the APs work as expected.	ArubaOS 8.5.0.11
AOS-215712	—	Mobility Conductors running ArubaOS 8.7.0.0 or later versions forwarded all syslog messages with severity level marked as debug. This issue occurred when CEF format was enabled on the Mobility Conductor. The fix ensures that the Mobility Conductors work as expected.	ArubaOS 8.7.0.0
AOS-216512	—	The DHCP client / station related AMON message sent the mask, server IP address, and client IP address in a reverse order to the AirWave server. The fix ensures that the Mobility Conductors work as expected. This issue was observed in Mobility Conductors running ArubaOS 8.6.0.6 or later versions.	ArubaOS 8.6.0.6
AOS-216622	—	A few APs running ArubaOS 8.7.0.0 or later versions incorrectly displayed the restricted flag, p = Restriction mode in POE-AF/AT in the AP database even if the Ethernet port was disabled. The fix ensures that the APs work as expected.	ArubaOS 8.7.0.0
AOS-216764	—	Users were not redirected to the captive portal page. The fix ensures that the captive portal works as expected. This issue was observed in managed devices running ArubaOS 8.7.1.0 or later versions in a cluster setup.	ArubaOS 8.7.1.0
AOS-216766	—	Some APs generated sapd coredump. The fix ensures that the APs work as expected. This issue was observed in APs running ArubaOS 8.5.0.11 or later versions.	ArubaOS 8.5.0.11
AOS-216874 AOS-219841	—	Some users were unable to access the network and a network outage was also observed. This issue occurred when the VRRP IP was removed from the datapath bridge table. The fix ensures that the managed devices work as expected. This issue was observed in managed devices running ArubaOS 8.5.0.11 or later versions.	ArubaOS 8.5.0.11

Table 6: Resolved Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-216972	—	Some managed devices running ArubaOS 8.6.0.7 or later versions forwarded data frames that are larger than the configured IPsec tunnel MTU value. The fix ensures that the managed devices do not forward data frames that are larger than the configured IPsec tunnel MTU value.	ArubaOS 8.6.0.7
AOS-217106	—	The no valid parameter of the ap regulatory-domain-profile command did not work while creating a new regulatory profile. The fix ensures that the no valid parameter of the ap regulatory-domain-profile command works as expected. This issue was observed in controllers running ArubaOS 8.0.0.0 or later versions.	ArubaOS 8.6.0.7
AOS-217807	—	Some Remote APs took a long time to come up on a managed device. This issue occurred due to a delay in allowlist-db synchronization between the Mobility Conductor and managed devices and when external authentication was enabled for Remote APs. The fix ensures that the Remote APs do not take a long time to come up on a managed device. This issue was observed in managed devices running ArubaOS 8.6.0.5 or later versions in a cluster setup.	ArubaOS 8.6.0.5
AOS-218012	—	The Maintenance tab of the WebUI displayed a list of clusters that were not configured for that particular node. The fix ensures that the WebUI does not display clusters that are not configured for a particular node. This issue was observed in Mobility Conductors running ArubaOS 8.5.0.9 or later versions.	ArubaOS 8.5.0.9
AOS-218231 AOS-216177	—	Wireless users were unable to find a few wired clients. The fix ensures that the wireless users are able to find the wired clients. This issue was observed in controllers running ArubaOS 8.7.1.1 or later versions.	ArubaOS 8.7.1.1
AOS-218622	—	Some APs running ArubaOS 8.6.0.6 or later versions crashed unexpectedly. The log files listed the reason for the event as PC:aruba_wlc_ratesel_getcurrate+0x24/0xd0 [wl_v6] Warm-reset . The fix ensures that the APs work as expected.	ArubaOS 8.7.1.1
AOS-218795	—	Downloadable user roles were not downloaded and hence, user roles were not assigned to the tunnel-node users. The fix ensures that the user roles are assigned to the tunnel-node users. This issue was observed in managed devices running ArubaOS 8.7.1.2 or later versions.	ArubaOS 8.7.1.2
AOS-218822	—	High flash memory utilization was observed in Mobility Conductors running ArubaOS 8.5.0.10 or later versions. The fix ensures that the Mobility Conductors work as expected.	ArubaOS 8.5.0.10

Table 6: Resolved Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-219098 AOS-219914	—	Some devices were unable to connect to the network. The fix ensures seamless connectivity. This issue was observed in APs running ArubaOS 8.7.1.1 or later versions.	ArubaOS 8.7.1.1
AOS-219098 AOS-219914	—	Some devices were unable to connect to the network. The fix ensures seamless connectivity. This issue was observed in APs running ArubaOS 8.7.1.1 or later versions.	ArubaOS 8.7.1.1
AOS-219178	—	Clients connected to the anchor controller were unable to receive IP addresses. The fix ensures that the clients are able to receive IP addresses. This issue was observed in managed devices running ArubaOS 8.3.0.7 or later versions.	ArubaOS 8.3.0.7
AOS-219214	—	The valid user ACL was reordered in stand-alone controllers running ArubaOS 8.6.0.8 or later versions. The fix ensures that the ACL is not reordered.	ArubaOS 8.6.0.8
AOS-219328	—	SNMP configurations failed and the error message, Error: User (itam_net) should be created before adding to the trap host was displayed. This issue occurred when the SNMP server v3 trap host which had the engine-id same as the engine-id of the controller was removed and added again. The fix ensures that the SNMP configurations do not fail. This issue was observed in managed devices running ArubaOS 8.5.0.11 or later versions.	ArubaOS 8.5.0.11
AOS-219365	—	Some APs running ArubaOS 8.7.0.0 or later versions rebooted sporadically. This issue occurred when the smart antenna feature was enabled. The fix ensures that the APs work as expected.	ArubaOS 8.7.1.1
AOS-219376	—	Some users were unable to add VIA server details if the domain name exceeded 32 characters. The fix ensures that the users are able to add VIA server details. This issue was observed in Mobility Conductors running ArubaOS 8.7.1.2 or later versions.	ArubaOS 8.7.1.2
AOS-219384	—	Some APs running ArubaOS 8.7.1.1 or later versions crashed unexpectedly. The log files listed the reason for the event as PC is at wlc_nar_dotxstatus+0x450 . The fix ensures that the APs work as expected.	ArubaOS 8.7.1.1
AOS-219390	—	The datapath process crashed on stand-alone controllers running ArubaOS 8.7.1.1 or later versions. The log files listed the reason for the event as Reboot Cause: Datapath timeout (SOS Assert) (Intent:cause:register 54:86:50:2) . This issue occurred when the op mode of the SSID profile was changed from WPA3-AES-CCM-128 to WPA3-CNSA. The fix ensures that the stand-alone controllers work as expected.	ArubaOS 8.7.1.1

Table 6: Resolved Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-219627 AOS-218851	—	Clients were unable to connect to 2.4 GHz SSID of some APs. This issue occurred when the MAC address of the Radio 1 was incorrect. The fix ensures seamless connectivity. This issue was observed in APs running ArubaOS 8.7.1.1 or later versions.	ArubaOS 8.7.1.1
AOS-219725	—	Some APs running ArubaOS 8.7.1.1 or later versions crashed unexpectedly. The log files listed the reason for the event as PC is at wlc_nar_detach+0x8c . The fix ensures that the APs work as expected.	ArubaOS 8.7.1.1
AOS-219936	—	The stand-alone controller displayed the error message, Module Profile Manager is busy. Please try later while configuring netdestination. The fix ensures that the stand-alone controllers work as expected. This issue was observed in stand-alone controllers running ArubaOS 8.7.1.1 or later versions.	ArubaOS 8.7.1.1
AOS-219978 AOS-220568	—	A few iPhone 12 Pro users experienced poor upstream network performance. This issue occurred when APs operated in tunnel mode. The fix ensures optimal network performance. This issue was observed in APs running ArubaOS 8.6.0.9 or later versions in tunnel mode.	ArubaOS 8.7.1.2
AOS-220053	—	Some Remote APs went down on managed devices running ArubaOS 8.6.0.5 or later versions. This issue occurred after a failover. The fix ensures that the Remote APs work as expected.	ArubaOS 8.6.0.5
AOS-220108	—	The OFA process crashed on Mobility Conductor Virtual Appliances running ArubaOS 8.6.0.6 or later versions. This issue occurred when the show openflow debug ports command was executed. The fix ensures that the Mobility Conductor Virtual Appliances work as expected.	ArubaOS 8.6.0.6
AOS-220552	—	The Configuration > Services > Clusters page of the WebUI did not display the status of live upgrade. This issue occurred when the cluster profile name had blank spaces. The fix ensures that the WebUI displays the status of live upgrade. This issue was observed in Mobility Conductors running ArubaOS 8.6.0.9 or later versions.	ArubaOS 8.6.0.9
AOS-221005	—	Some stand-alone controllers running ArubaOS 8.7.1.2 or later versions were stuck in reboot loop. The log files listed the reason for the event as Nanny rebooted machine - fpapps process died (Intent:cause:register 34:86:50:2) . The fix ensures that the stand-alone controllers work as expected.	ArubaOS 8.7.1.2

Table 6: Resolved Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-221429	—	Downloadable user role was not applied correctly to the first user connecting in the split tunnel mode. The fix ensures that the downloadable user role are applied correctly. This issue was observed in stand-alone controllers running ArubaOS 8.6.0.9 or later versions.	ArubaOS 8.6.0.9
AOS-221666 AOS-222708	—	Some Remote APs running ArubaOS 8.6.0.9 or later versions crashed and rebooted unexpectedly. The log file listed the reason for the event as, Kernel panic - not syncing . The fix ensures that the Remote APs work as expected.	ArubaOS 8.6.0.9
AOS-224186	—	The show tech-support command did not display any information about the kernel crash and an error message, No kernel crash information available was displayed. The fix ensures that the show tech support command displays crash related information. This issue was observed in stand-alone controllers running ArubaOS 8.6.0.9 or later versions.	ArubaOS 8.6.0.9
AOS-223839	—	The output of the show ap active command did not display any value for Outer IP . The fix ensures that the command displays the Outer IP value. This issue was observed in Mobility Conductors running ArubaOS 8.6.0.9 or later versions.	ArubaOS 8.6.0.9
AOS-223797	—	The show ap remote auth-trace-buf command did not display any output. The fix ensures that the command displays the output. This issue was observed in stand-alone controllers running ArubaOS 8.6.0.9 or later versions.	ArubaOS 8.6.0.9
AOS-222931	—	Some APs did not form active tunnels with the AAC. The fix ensures that the APs form tunnels with the AAC. This issue was observed in managed devices running ArubaOS 8.7.1.4 or later versions.	ArubaOS 8.7.1.4
AOS-222904	—	A few USB clients connected to an Instant AP became inactive when the Instant AP was rebooted. The fix ensures that the APs work as expected. This issue was observed in APs running ArubaOS 8.6.0.6 or later versions.	ArubaOS 8.6.0.6
AOS-222771	—	Some managed devices running ArubaOS 8.5.0.12 or later versions did not send SNMPv3 information to the AirWave server. The fix ensures that the managed devices send SNMPv3 information to the AirWave server.	ArubaOS 8.5.0.12

Table 6: Resolved Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-222754	—	The SNMP walk to managed devices failed when the SNMP requests had the IPv6 address of the controller. This issue occurred when the primary managed device had VRRP IPv6 address configured. The fix ensures that the SNMP walk to managed devices do not fail. This issue was observed in managed devices running ArubaOS 8.4.0.1 or later versions.	ArubaOS 8.4.0.1
AOS-222540 AOS-224221	—	Some APs dropped EAPOL packets from the bridge mode wired port. The fix ensures that the APs do not drop the EAPOL packets. This issue was observed in APs running ArubaOS 8.6.0.9 or later versions.	ArubaOS 8.6.0.9
AOS-221938	—	Some users were unable to download the VIA profile and were redirected to an incorrect link. This issue occurred when users accessed VIA from a public network. The fix ensures that the users are able to download the VIA profile. This issue was observed in Mobility Conductors running ArubaOS 8.5.0.0 or later versions.	ArubaOS 8.5.0.0
AOS-221726 AOS-223220	—	Some managed devices running ArubaOS 8.7.1.1 or later versions were unable to form L2 clusters with its peers. The fix ensures that the managed devices are able to form L2 clusters.	ArubaOS 8.7.1.1
AOS-221478 AOS-221569 AOS-221572	—	The auth process crashed on managed devices running ArubaOS 8.5.0.9 or later versions. This issue occurred when the show auth-tracebuf mac command was executed. The fix ensures that the managed devices work as expected.	ArubaOS 8.5.0.9
AOS-221352	—	Some mesh links reported incorrect RSSI values. The fix ensures that the mesh links report correct RSSI values. This issue was observed in APs running ArubaOS 8.7.0.0 or later versions.	ArubaOS 8.7.0.0
AOS-221225	—	Some AP-387 access points running ArubaOS 8.7.1.1 or later versions rebooted unexpectedly. The log files listed the reason for the event as Reboot caused by kernel panic: Fatal exception . The fix ensures that the APs work as expected.	ArubaOS 8.7.1.1
AOS-221222	—	Some APs came up with the IDe flag and the show ap database command displayed the e flag even when EST was not configured. This issue occurred when an external allowlist authentication was configured on the managed devices and also when CPsec enabled APs were brought up on the managed devices. The fix ensures that the APs work as expected. This issue was observed in managed devices running ArubaOS 8.8.0.0.	ArubaOS 8.8.0.0

Table 6: Resolved Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-221144	—	ARP packets were not forwarded to the uplink switch when bcmc-optimization was enabled on the controllers. This issue was observed in Mobility Conductors and managed devices running ArubaOS 8.5.0.9 or later versions. The fix ensures that the Mobility Conductors and managed devices work as expected.	ArubaOS 8.5.0.9
AOS-221018 AOS-220919	—	Some users were unable to connect to SSIDs. This issue occurred in 802.11r and MultiZone enabled configurations. The fix ensures seamless connectivity. This issue was observed in APs running ArubaOS 8.5.0.11 or later versions.	ArubaOS 8.5.0.11
AOS-220903	—	The s flag indicating LACP striping was not displayed in the output of the show ap database long command even when LLDP was enabled on two uplinks. The fix ensures that the show ap database long command displays the s flag when LLDP is enabled. This issue is observed in APs running ArubaOS 8.6.0.8 or later versions.	ArubaOS 8.6.0.8
AOS-220704	—	Some APs were incorrectly displayed under different clusters. The fix ensures that the APs are not displayed under different clusters. This issue was observed in managed devices running ArubaOS 8.5.0.11 or later versions.	ArubaOS 8.5.0.11
AOS-224336	—	The IoT transport profile authentication failed. This issue occurred when a remote server was used. The fix ensures successful authentication. This issue was observed in Mobility Conductors running ArubaOS 8.8.0.1 or later versions.	ArubaOS 8.8.0.1
AOS-223656	—	Some Remote APs are unable to come up on managed devices after a reboot. The fix ensures that the Remote APs are able to come up on the managed devices. This issue was observed in managed devices running ArubaOS 8.7.1.4 or later versions.	ArubaOS 8.7.1.4
AOS-221093 AOS-222773	—	Mobility Conductors running ArubaOS 8.0.1.0 or later versions took a long time to process templates that were sent to the managed devices. The fix ensures that the Mobility Conductors work as expected.	ArubaOS 8.0.1.0
AOS-222776	—	Some managed devices running ArubaOS 8.0.1.0 or later versions established IPsec tunnels with stale WAN IP addresses. The fix ensures that the managed devices work as expected.	ArubaOS 8.0.1.0
AOS-220515	—	Some managed devices running ArubaOS 8.5.0.12, or later versions displayed the error message, fpapps filling up the default gateway configuration . The fix ensures that the managed devices work as expected.	ArubaOS 8.5.0.12

Table 6: Resolved Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-220398	—	A few clients in bridge mode were unable to connect to wpa2-psk SSIDs. The fix ensures that the clients in bridge mode are able to connect to wpa2-psk SSIDs. This issue was observed in stand-alone controllers running ArubaOS 8.6.0.8 or later versions.	ArubaOS 8.6.0.8
AOS-220251	—	Some users experienced connectivity issues. This issue occurs when APs did not respond to the authentication frames in MultiZone networks that had non-cluster zones and dot11r enabled Virtual APs. The fix ensures that the APs work as expected. This issue was observed in stand-alone controllers running ArubaOS 8.5.0.4 or later versions.	ArubaOS 8.5.0.4
AOS-220179	—	A few clients were unable to complete the SAE handshake. This issue occurred when the password of an SSID profile was modified to a length greater than the existing password. The fix ensures that the SAE handshake is not interrupted. This issue was observed in APs running ArubaOS 8.8.0.0.	ArubaOS 8.8.0.0
AOS-218328 AOS-220026 AOS-223535	—	VRRP flapping was observed on managed devices running ArubaOS 8.6.0.4 or later versions and hence, clients faced connectivity issues. The fix ensures that the managed devices work as expected.	ArubaOS 8.6.0.4
AOS-219803	—	XML query done on a non-existing user resulted in an invalid response. The fix ensures that the controller responds as expected. This issue was observed in Controllers running ArubaOS 8.7.1.2 or later versions.	ArubaOS 8.7.1.2
AOS-219769	—	The rap-gre-mtu parameter of the ap system-profile command did not work as expected. The fix ensures that the rap-gre-mtu parameter works as expected. This issue was observed in Mobility Conductors running ArubaOS 8.8.0.0 or later versions.	ArubaOS 8.8.0.0
AOS-219385	—	Some APs took a long time to come up on the backup data center after primary data center failover. The fix ensures that the APs work as expected. This issue was observed in APs running ArubaOS 8.5.0.10 or later versions.	ArubaOS 8.5.0.10
AOS-219112	—	UBT clients hopped between VLANs. The fix ensures that the managed devices work as expected. This issue was observed in managed devices running ArubaOS 8.7.1.1 or later versions.	ArubaOS 8.7.1.1
AOS-218661	—	The AP process crashed on managed devices running ArubaOS 8.7.1.1 or later versions. The fix ensures that the managed devices work as expected.	ArubaOS 8.7.1.1

Table 6: Resolved Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-218646	—	Some users connected to AP-515 access points running ArubaOS 8.6.0.7 or later versions experienced degraded audio quality. The fix ensures that the clients do not experience degraded audio quality.	ArubaOS 8.6.0.7
AOS-218642	—	Some users were unable to access the internet. This issue occurred when client entries were not removed by the managed devices even when CoA disconnect was triggered for the clients. The fix ensures that the clients are able to access the internet as expected. This issue was observed in managed devices running ArubaOS 8.5.0.11 or later versions.	ArubaOS 8.5.0.11
AOS-218488 AOS-219694	—	The management VLAN address of the Mobility Conductor was pointed to the Remote AP tunnel. The fix ensures that the management VLAN address is not available in the Remote AP tunnel. This issue was observed in Mobility Conductors running ArubaOS 8.3.0.0 or later versions.	ArubaOS 8.3.0.0
AOS-219806	—	Some APs running ArubaOS 8.8.0.0 or later versions did not have the support for H2E advertisement. The fix ensures that the APs support H2E advertisement in beacon and probe responses.	ArubaOS 8.8.0.0
AOS-218322	—	Some managed devices running ArubaOS 8.5.0.5 or later versions did not send SSID related information during data collection. The fix ensures that the managed devices send SSID related information during data collection.	ArubaOS 8.5.0.5
AOS-214428 AOS-218277	—	The auth process crashed on managed devices running ArubaOS 8.5.0.11 or later versions. Hence, the Remote APs rebooted and VIA users faced connectivity issues. The fix ensures that the managed devices work as expected.	ArubaOS 8.5.0.11
AOS-216152 AOS-218208 AOS-222478	—	Some clients were unable to connect to APs. The log file listed the reason for the event as, AP is resource constrained . The fix ensures seamless connectivity. This issue was observed in APs running ArubaOS 8.5.0.8 or later versions.	ArubaOS 8.5.0.8
AOS-218162	—	The wired Ethernet port did not form GRE tunnel with the managed device. The fix ensures that the wired Ethernet port forms GRE tunnel with the managed device. This issue was observed in managed devices running ArubaOS 8.7.1.1 or later versions.	ArubaOS 8.7.1.1
AOS-218117 AOS-219179 AOS-224575	—	The show ntp servers and show ntp status commands displayed the error message, Address family for hostname not supported . However, the WebUI displayed the NTP servers. The fix ensures that the commands do not display the error message. This issue was observed in managed devices running ArubaOS 8.6.0.7 or later versions.	ArubaOS 8.6.0.7

Table 6: Resolved Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-217890	—	A managed device running ArubaOS 8.5.0.10 or later versions crashed and rebooted unexpectedly. The log file listed the reason for the event as Reboot Cause: Datapath timeout (SOS Assert) (Intent:cause:register 54:86:50:2) . The fix ensures that the managed devices work as expected.	ArubaOS 8.5.0.10
AOS-217741	—	Mobility Conductors experienced timeout and did not send SNMP response to the AirWave server. The fix ensures that the Mobility Conductors work as expected. This issue was observed in Mobility Conductors running ArubaOS 8.5.0.11 or later versions.	ArubaOS 8.5.0.11
AOS-217678 AOS-218131	—	Some APs running ArubaOS 8.6.0.7 or later versions did not honor the user alias route src-nat ACL and tunnelled the traffic to managed devices. The issue occurred when a netdestination alias is configured in the ACL. The fix ensures that the APs work as expected.	ArubaOS 8.6.0.7
AOS-217539 AOS-219010 AOS-219952 AOS-220918 AOS-221298	—	The auth process crashed in managed devices running ArubaOS 8.7.0.0 or later versions. The fix ensures that the managed devices work as expected.	ArubaOS 8.7.0.0

This chapter describes the known issues and limitations observed in this release.

Limitation

Following is the limitation observed in this release.

6 GHz Channel Information in Regulatory Domain Profile

ArubaOS does not display the 6 GHz channel information in the existing regulatory domain profile of Wi-Fi 6E APs by default.

To include 6 GHz channel information, ensure that you change the country code to a different country code, apply the change, and then revert it to the original country code. Another option is to create a new regulatory domain profile that includes the 6 GHz channel information by default, or copy the existing regulatory domain profile into a new regulatory domain profile to save the configuration.

The following example configures a regulatory domain profile and specifies a valid 6 GHz band.

```
host) [mynode] (config) #ap regulatory-domain-profile reg-635
host) [mynode] (Regulatory Domain profile "reg-635") #country-code US
host) [mynode] (Regulatory Domain profile "reg-635") #valid-6ghz-channel 165
```

Known Issues

Following are the known issues observed in this release.

Table 7: *Known Issues in ArubaOS 8.9.0.0*

New Bug ID	Old Bug ID	Description	Reported Version
AOS-218844	—	Mobility Conductor picks only 43% of the APs for cluster CRU. This issue is observed in Mobility Conductor running ArubaOS 8.8.0.0.	ArubaOS 8.8.0.0
AOS-219249	—	The VLAN configuration as part of conductorip or conductoripv6 command is not pushed from the Mobility Conductor to a managed device after the zero touch provisioning process. This issue is observed on a managed device running ArubaOS 8.8.0.0.	ArubaOS 8.8.0.0
AOS-222200	—	Mobility Conductors running ArubaOS 8.7.0.0 or later versions are unable to classify webrtc traffic. This issue is observed during conference calls.	ArubaOS 8.9.0.0

Table 7: Known Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-223354	—	Some stand-alone controllers running in ArubaOS 8.9.0.0 display the error message, Error upgrading image: Basic image verification failed on Ancillary Image during the upgrade. Workaround: Issue the show storage command to ensure that the controller has enough flash storage.	ArubaOS 8.9.0.0
AOS-223199	—	OpenFlow connection flaps between Mobility Conductor and managed devices. This issue occurs when the IPsec tunnel MTU is set to a value lesser than 1500. This issue is observed in Mobility Conductors running ArubaOS 8.9.0.0.	ArubaOS 8.9.0.0
AOS-223012	—	Datapath categorization does not work as expected for Skype4B calls. This issue occurs in Remote APs operating in split-tunnel mode. This issue is observed in Mobility Conductors running ArubaOS 8.9.0.0.	ArubaOS 8.9.0.0
AOS-223807	—	The inet_frag_secret_rebuild: hashfn (ffffffffc17679b8/ip6_hashfn) kernel debug messages are observed on 7280 controllers running ArubaOS 8.8.0.2. This issue occurs during upgrade of the 7280 controllers.	ArubaOS 8.8.0.2
AOS-224042	—	A few APs experience packet drop when clients roam between the APs. This issue is observed in APs running ArubaOS 8.9.0.0.	ArubaOS 8.9.0.0
AOS-224867	—	An rsync failure occurs on a managed device. This issue occurs during boot when the DHCP process wrongly derives the switch IP as IP address of the Mobility Conductor. The IP address of the Mobility Conductor is subsequently configured as a FQDN in configuration. This issue is observed in a managed device running ArubaOS 8.9.0.0.	ArubaOS 8.9.0.0
AOS-222699 AOS-223281 AOS-223640	—	A few Intel AX210 clients face connectivity issue while connecting to AP-635 access points operating in 6 GHz band. This issue occurs when an existing non-Tx VAP is changed to Tx VAP. This issue is observed in AP-635 access points running ArubaOS 8.9.0.0.	ArubaOS 8.9.0.0
AOS-222662	—	Both WebUI and CLI display incorrect logging severity. The output of the show logging server command displays All as logging severity and the Syslog Servers table in the Configuration > System > Logging page displays the severity as Warning . This issue occurs only when logging severity is not configured. This issue is observed in Mobility Conductors running ArubaOS 8.9.0.0.	ArubaOS 8.9.0.0

Table 7: Known Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-222661	—	The Syslog Servers table in the Configuration > System > Logging page of the WebUI does not display the port number. This issue occurs when port numbers are not configured. This issue is observed in Mobility Conductors running ArubaOS 8.9.0.0.	ArubaOS 8.9.0.0
AOS-222660	—	The show logging server command does not display the status of BSD as enabled even if the TLS option is enabled. This issue is observed in Mobility Conductors running ArubaOS 8.9.0.0.	ArubaOS 8.9.0.0
AOS-221676	—	When Intel AX210 client is connected to TX VAP in 6GHz radio of 635 Series, it shows 70% or more ping drops and keeps getting disconnected with reason "Wlan driver wireless client out of range (seq num 0)". This is an existing Intel driver side issue and known to occur in version 22.70.x.x or lower if used with AX210 chipsets.	ArubaOS 8.9.0.0
AOS-220557	—	Some Intel AX clients face connectivity issues. This issue is observed in ArubaOS version 8.7.1.3 or later versions in 635 Series, AP-555, AP-535.	ArubaOS 8.9.0.0
AOS-220125	—	The Datapath process crashes on Mobility Conductors running ArubaOS 8.9.0.0. This issue occurs when the packet size is larger than the configured IPsec tunnel MTU value.	ArubaOS 8.9.0.0
AOS-219048	—	When Service AP is configured with PSK SSID, AP brings up the controller and configures Provision AP as WIFI-Uplink profile. The Service AP becomes unstable in the controller. The AP's uplink is disconnected, resulting in loss of connection with the controller. This issue is observed in AP-335.	ArubaOS 8.9.0.0
AOS-218578		In a dual stack setup, when there is a scheduled upgrade in MM, the upgrade fails consistently. This issue is observed in controllersMM-MD and Controller Build is ArubaOS70xx_8.8.0.0_79405.	ArubaOS 8.9.0.0
AOS-218219		A Microsoft Teams call with an external client does not get classified and prioritized.. This MS-Teams call is not classified and prioritized by UCC. This issue is observed in ArubaOS 8.8.0.0 or later versions.	ArubaOS 8.9.0.0
AOS-215989		Some APs running ArubaOS 8.8.0.0 or later versions experience low throughput. This issue occurs when the number of VAPs is increased. This issue occurs when HE MU-OFDMA parameters are enabled. This affects only HE MU-OFDMA capable client devices.	ArubaOS 8.9.0.0
AOS-213507		Some managed devices running ArubaOS 8.5.0.10 or later versions crash unexpectedly. The log files list the reason for the event as, Reboot Cause: Soft Watchdog reset	ArubaOS 8.9.0.0

Table 7: Known Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-213428	—	The Upgrademgr process does not provide FQDN support for image servers. This issue is observed in Mobility Conductors running ArubaOS 8.8.0.0 or later versions.	ArubaOS 8.8.0.0
AOS-213345	—	The output of the show ap image-preload status <summary/all/list> command does not display the list of APs. This issue is observed in managed devices in a cluster setup running ArubaOS 8.8.0.0 or later versions.	ArubaOS 8.8.0.0
AOS-212858	—	The Maintenance > Software Management > Upload AOS image for controller page of the WebUI does not allow users to delete multiple images simultaneously. This issue is observed in Mobility Conductors running ArubaOS 8.8.0.0 or later versions.	ArubaOS 8.8.0.0
AOS-212847	—	The Maintenance > Software Management > Upload AOS image for controller page of the WebUI does not allow users to upload multiple images simultaneously. This issue is observed in Mobility Conductors running ArubaOS 8.8.0.0 or later versions.	ArubaOS 8.8.0.0
AOS-212288	—	The status of the managed devices are displayed as UKN after an L2 fail over. This issue is observed in Mobility Conductors and managed devices running ArubaOS 8.8.0.0 or later versions.	ArubaOS 8.8.0.0
AOS-211655	—	Some clients are unable to roam between APs when co-ex is enabled. This issue is observed in AP-514 access points running ArubaOS 8.8.0.0 or later versions.	ArubaOS 8.8.0.0
AOS-213157	—	A Mobility Conductor fails to perform version check of managed devices during the image upgrade process. This issue is observed in Mobility Conductors in a cluster setup running ArubaOS 8.8.0.0 or later versions.	ArubaOS 8.8.0.0
AOS-212941	—	The newly configured VLANs are not displayed when the show vlan command is executed. This issue occurs after a flash backup restore. This issue is observed in managed devices running ArubaOS 8.8.0.0 or later versions.	ArubaOS 8.8.0.0
AOS-211634	—	The Controller field is not updated in the Dashboard> Services page of the WebUI. This issue occurs when a cluster-failover happens during an ongoing Microsoft Teams call. This issue is observed in managed device running ArubaOS 8.8.0.0 or later versions.	ArubaOS 8.8.0.0
AOS-211453	—	Microsoft Teams conference call is not supported. This issue is observed in managed devices running ArubaOS 8.8.0.0 or later versions.	ArubaOS 8.8.0.0

Table 7: Known Issues in ArubaOS 8.9.0.0

New Bug ID	Old Bug ID	Description	Reported Version
AOS-210383	—	The Cluster Members pop-up window in the Dashboard > Infrastructure > Clusters page of the WebUI does not display any value for Hostname , Role , and Reachable fields. This issue occurs when the user configures IPv6 cluster in the WebUI. This issue is observed in Mobility Conductors running ArubaOS 8.8.0.0 or later versions in a Mobility Conductor-Managed Device topology.	ArubaOS 8.8.0.0
AOS-208640 AOS-215865 AOS-219181	—	A few high efficiency clients experience poor performance with AP-505 access points running ArubaOS 8.7.1.0 or later versions. This issue occurs when HE MU-OFDMA parameters are enabled.	ArubaOS 8.7.1.0
AOS-202352 AOS-202531	—	After a live upgrade is initiated, users are unable to stop the upgrade as the Cancel button in the Maintenance > Software Management > Controllers and Clusters page of the WebUI does not work. This issue is observed managed devices running ArubaOS 8.7.0.0 or later versions.	ArubaOS 8.7.0.0
AOS-222554 AOS-222612	—	WPA3-AES-CCM-128 authentication fails for a few clients. This issue occurs in APs operating in 6 GHz channels. This issue is observed in APs running ArubaOS 8.9.0.0.	ArubaOS 8.9.0.0
AOS-211070	—	Cluster live upgrade fails and the WebUI displays an error message, Controller <IP address > is down . This issue occurs when an IPv6 enabled managed device establishes an IPv4 connection with the Mobility Conductor. This issue is observed in Mobility Conductors running ArubaOS 8.8.0.0 or later versions.	ArubaOS 8.8.0.0
AOS-223903	—	A Mobility Conductor does not accept applying a valid XML file that is generated in Python for IPv6 relay-option and IPv4 option 82. The Mobility Conductor displays the Filename <sample.xml> has invalid keywords error. This issue is observed in a Mobility Conductor running ArubaOS 8.9.0.0.	ArubaOS 8.9.0.0
AOS-221963	—	When a policy has both WebCC and AppRF rules, the Mobility Controller classifies all traffic as ssl, https or http2. This issue is observed in Mobility Controllers running ArubaOS 8.9.0.0.	ArubaOS 8.9.0.0
AOS-225201	—	The scheduled upgrade information of cluster and managed device is not displayed in the WebUI and CLI. This issue is observed in Mobility Conductor running ArubaOS 8.9.0.0.	ArubaOS 8.9.0.0

This chapter details software upgrade procedures. It is recommended that you schedule a maintenance window for the upgrade.



Read all the information in this chapter before upgrading your Mobility Conductor, managed device, or stand-alone controller.

Important Points to Remember

To upgrade your managed device or Mobility Conductor:

- Schedule the upgrade during a maintenance window and notify your community of the planned upgrade. This prevents users from being surprised by a brief wireless network outage during the upgrade.
- Avoid making any changes to your network, such as configuration changes, hardware upgrades, or changes to the rest of the network during the upgrade. This simplifies troubleshooting.
- Know your network and verify the state of the network by answering the following questions:
 - How many APs are assigned to each managed device? Verify this information by navigating to the **Dashboard > Access Points** page in the WebUI, or by executing the **show ap active** or **show ap database** commands.
 - How are those APs discovering the managed device (DNS, DHCP Option, Broadcast)?
 - What version of ArubaOS runs on your managed device?
 - Are all managed devices running the same version of ArubaOS?
 - What services are used on your managed device (employee wireless, guest access, Remote AP, wireless voice)?
- Resolve any existing issues (consistent or intermittent) before you upgrade.
- If possible, use FTP to load ArubaOS images to the managed device. FTP is faster than TFTP and offers more resilience over slow links. If you must use TFTP, ensure the TFTP server can send over 30 MB of data.
- Always upgrade the non-boot partition first. If you encounter any issue during the upgrade, you can restore the flash, and switch back to the boot partition. Upgrading the non-boot partition gives you a smoother downgrade path, if required.
- Before you upgrade to this version of ArubaOS, assess your software license requirements and load any new or expanded licenses that you might require. For a detailed description of these new license modules, refer the *Aruba Mobility Conductor Licensing Guide*.
- Multiversion is supported in a topology where the managed devices are running the same version as the Mobility Conductor, or two versions lower. For example multiversion is supported if a Mobility Conductor is running ArubaOS 8.5.0.0 and the managed devices are running ArubaOS 8.5.0.0, ArubaOS 8.4.0.0, or ArubaOS 8.3.0.0.

Memory Requirements

All Aruba managed devices store critical configuration data on an onboard compact flash memory module. Ensure that there is always free flash space on the managed device. Loading multiple large files such as JPEG images for RF Plan can consume flash space quickly. Following are best practices for memory management:

- Do not proceed with an upgrade unless 100 MB of free memory is available. Execute the **show memory** command to identify the available free memory. To recover memory, reboot the managed device. After the managed device comes up, upgrade immediately.
- Do not proceed with an upgrade unless the minimum flash space in [Table 8](#) is available. Execute the **show storage** command to identify the available flash space. If the output of the **show storage** command indicates that there is insufficient flash memory, free some used memory. Copy any log files, crash data, or flash backups from your the managed device to a desired location. Delete the following files from the managed device to free some memory:
 - **Crash data:** Execute the **tar crash** command to compress crash files to a file named **crash.tar**. Use the procedures described in [Backing up Critical Data on page 40](#) to copy the **crash.tar** file to an external server. Execute the **tar clean crash** command to delete the file from the managed device.
 - **Flash backups:** Use the procedures described in [Backing up Critical Data on page 40](#) to back up the flash directory to a file named **flash.tar.gz**. Execute the **tar clean flash** command to delete the file from the managed device.
 - **Log files:** Execute the **tar logs** command to compress log files to a file named **logs.tar**. Use the procedures described in [Backing up Critical Data on page 40](#) to copy the **logs.tar** file to an external server. Execute the **tar clean logs** command to delete the file from the managed device.



In certain situations, a reboot or a shutdown could cause the managed device to lose the information stored in its flash memory. To avoid such issues, it is recommended that you execute the **halt** command before power cycling.

Deleting a File

You can delete a file using the WebUI or CLI.

In the WebUI

From the Mobility Conductor, navigate to **Diagnostic > Technical Support > Delete Files** and remove any aging log files or redundant backups.

In the CLI

```
(host) #delete filename <filename>
```

Low Free Flash Memory

Sometimes, after extended use, the flash memory might get used up for logs and other files. The ArubaOS image has increased in size and this may cause issues while upgrading to newer ArubaOS images without cleaning up the flash memory.

Prerequisites

Before you proceed with the freeing up the flash memory:

- Ensure to always backup the configuration and flash memory. Issue the **backup configuration** and **backup flash** commands to backup the configuration and flash.

- Copy the **flashbackup.tar.gz** and **configbackup.tar.gz** files out of the controller. Then delete the **flashbackup.tar.gz** and **configbackup.tar.gz** files from the flash memory of the controller.
- Use only one partition for the upgrade activity and keep the other partition unchanged.

If you use the WebUI to perform an upgrade, a banner on the **Maintenance** page provides the following reminder to have sufficient free flash memory before initiating an upgrade.

For a healthy and stable system it requires free space of 360 MB for AOS v8.3 and 8.5, 570 MB for AOS 8.6 and 8.7 and 450 MB for AOS 8.8 and higher version in the /flash directory. Please make sure minimum required memory is available in /flash before upgrading to newer version.

Freeing up Flash Memory

The following steps describe how to free up the flash memory before upgrading to ArubaOS 8.9.0.0:

1. Check if the available memory in **/flash** is greater than the limits listed in [Table 8](#) for all supported controller models:

Table 8: *Flash Memory Requirements*

Upgrading from	Upgrading to	Minimum Required Free Flash Memory Before Initiating an Upgrade
8.3.x	8.9.x	360 MB
8.5.x	8.9.x	360 MB
8.6.x	8.9.x	570 MB
8.7.x	8.9.x	570 MB
8.8.x	8.9.x	450 MB
8.9.x	8.9.x	450 MB

To check the available free flash memory, issue the **show storage** command. Following is the sample output from a controller with low free flash memory:

```
(host) [mynode] #show storage
Filesystem      Size  Available      Use    %      Mounted on
/dev/usb/flash3 1.4G  1014.2M    386.7M  72%    /flash
```

2. If the available free flash memory is less than the limits listed in [Table 8](#), issue the following commands to free up more memory.
 - **tar crash**
 - **tar clean crash**
 - **tar clean logs**
 - **tar clean traces**
3. Issue the **show storage** command again to check if the available space in **/flash** is more than the minimum space required for ArubaOS upgrade as listed in [Table 8](#)
4. If sufficient flash memory is available, proceed with the standard ArubaOS upgrade. See [Upgrading ArubaOS](#).

5. If a reboot was performed, you may see some of the following errors. Follow the directions below:
 - Upgrade using standard procedure. You may see some of the following errors:
 - Error upgrading image: Ancillary unpack failed with tar error (tar: Short header).**
Please clean up the /flash and try upgrade again.
 - Error upgrading image: Ancillary unpack failed with tar error (tar: Invalid tar magic).**
Please clean up the /flash and try upgrade again.
 - Error upgrading image: Need atleast XXX MB space in /flash for image upgrade, please clean up the /flash and try upgrade again.**
 - Failed updating: [upgradelImageNew.c] extractAncTar (dev: /dev/usb/flash1 imgLoc: /flash/config/ArubaOS_70xx_8.8.0.0-mm-dev_78066**

- If any of the above errors occur, issue the **show image version** command to check for the default boot partition. The partition which was upgraded should become the default partition. Following is the sample output of the **show image version** command:

```
(host) [mynode] #show image version
-----
Partition           : 0:0 (/dev/usb/flash1) **Default boot**
Software Version    : ArubaOS 8.9.0.0 (Digitally Signed SHA1/SHA256 - Production
Build)
Build number        : 81046
Label               : 81046
Built on            : Thu Aug 5 22:54:49 PDT 2021
-----
Partition           : 0:1 (/dev/usb/flash2)
Software Version    : ArubaOS 8.7.0.0-2.3.1.0 (Digitally Signed SHA1/SHA256 -
Developer/Internal Build)
Build number        : 0000
Label               : arpitg@sdwan-2.3_arpitg-3-ENG.0000
Built on            : Tue Aug 10 15:02:15 IST 2021
```

- If the default boot partition is not the same as the one where you performed the upgrade, change the default boot partition. Issue the **boot system partition <part_number>** command to change the default boot partition. Enter **0** or **1** for **part_number** representing partition 0:0 or partition 0:1, respectively.
- Reload the controller. If any of the errors listed in step 4 were observed, the following errors might occur while booting ArubaOS 8.9.0.0.

```
Sample error:
[03:17:17]:Installing ancillary FS [ OK ]
Performing integrity check on ancillary partition 1 [ FAIL : Validating new
ancillary partition 1...Image Integrity check failed for file
/flash/img1/mswitch/sap/arm32.ari. Digest Mismatch]
Extracting Webui files..tar: Short read
chown: /mswitch/webui/*: No such file or directory
chmod: /mswitch/webui/wms/wms.cgi: No such file or directory
```

- After the controller reboots, the login prompt displays the following banner:


```
*****
* WARNING: An additional image upgrade is required to complete the *
* installation of the AP and WebUI files. Please upgrade the boot *
* partition again and reload the controller. *
*****
```

- Repeat steps 1 through 5. If sufficient free flash memory is available, proceed with the standard ArubaOS upgrade procedure. See [Upgrading ArubaOS](#).
- If sufficient free flash memory is not available, issue the **dir** and **dir flash** commands to identify large files occupying the flash memory.



Exercise caution while deleting files. Contact Technical Support if you are not sure which large files in the **/flash** directory could be safely deleted to free up the required space.

- Issue the **delete filename <filename>** command to delete large files to free more flash memory.
- Check if sufficient flash memory is free as listed in [Table 8](#).
- Proceed with the standard ArubaOS upgrade procedure in the same partition. See [Upgrading ArubaOS](#).

ArubaOS 8.8.0.0 and 8.8.0.1

The following steps describe how to free up the flash memory before upgrading to ArubaOS 8.8.0.0 or 8.8.0.1:

1. Follow the steps 1 through 4 listed in [Freeing up Flash Memory](#) before upgrading to ArubaOS 8.8.0.0 or 8.8.0.1.
2. If sufficient flash memory is still not available, issue the **dir** to identify large files occupying the flash memory.



Exercise caution while deleting files. Contact Technical Support if you are not sure which large files in the **/flash** directory could be safely deleted to free up the required space.

3. Issue the **delete filename <filename>** command to delete large files to free more memory.
4. Check if sufficient flash memory is free as listed in [Table 8](#).
5. **If sufficient flash memory is not available, do not proceed with the upgrade. Contact Technical Support.**

Backing up Critical Data

It is important to frequently back up all critical configuration data and files on the flash memory to an external server or mass storage device. You should include the following files in these frequent backups:

- Configuration data
- WMS database
- Local user database
- Licensing database
- Custom captive portal pages
- x.509 certificates
- Log files
- Flash backup

Backing up and Restoring Flash Memory

You can backup and restore the flash memory using the WebUI or CLI.

In the WebUI

The following steps describe how to back up and restore the flash memory:

1. In the Mobility Conductor node hierarchy, navigate to the **Maintenance > Configuration Management > Backup** page.
2. Click **Create Backup** to backup the contents of the flash memory to the **flashbackup.tar.gz** file.
3. Click **Copy Backup** to copy the file to an external server.

You can copy the backup file from the external server to the flash memory using the file utility in the **Diagnostics > Technical Support > Copy Files** page.

4. To restore the backup file to the flash memory, navigate to the **Maintenance > Configuration Management > Restore** page and click **Restore**.

In the CLI

The following steps describe how to back up and restore the flash memory:

1. Execute the following command in the **enable** mode:

```
(host) #write memory
```

2. Execute the following command to back up the contents of the flash memory to the **flashbackup.tar.gz** file.

```
(host) #backup flash
Please wait while we take the flash backup.....
File flashbackup.tar.gz created successfully on flash.
Please copy it out of the controller and delete it when done.
```

3. Execute either of the following command to transfer the flash backup file to an external server or storage device.

```
(host) #copy flash: flashbackup.tar.gz ftp: <ftphost> <ftpusername> <ftpuserpassword>
<remote directory>
```

```
(host) #copy flash: flashbackup.tar.gz usb: partition <partition-number>
```

You can transfer the flash backup file from the external server or storage device to the flash memory by executing either of the following command:

```
(host) #copy tftp: <tftphost> <filename> flash: flashbackup.tar.gz
```

```
(host) #copy usb: partition <partition-number> <filename> flash: flashbackup.tar.gz
```

4. Execute the following command to untar and extract the **flashbackup.tar.gz** file to the flash memory.

```
(host) #restore flash
```

Please wait while we restore the flash backup.....

Flash restored successfully.

Please reload (reboot) the controller for the new files to take effect.

Upgrading ArubaOS

Upgrade ArubaOS using the WebUI or CLI.



Ensure that there is enough free memory and flash space on your Mobility Conductor or managed device. For details, see [Memory Requirements on page 36](#).



When you navigate to the **Configuration** tab in the WebUI, the managed device might display the **Error getting information: command is not supported on this platform** message. This message is displayed occurs when you upgrade using the WebUI and navigate to the **Configuration** tab after the managed device reboots. This message disappears after clearing the Web browser cache.

In the WebUI

The following steps describe how to upgrade ArubaOS from a TFTP server, FTP server, or local file.

1. Download the ArubaOS image from the customer support site.
2. Upload the ArubaOS image to a PC or workstation on your network.
3. Validate the SHA hash for the ArubaOS image:
 - a. Download the **Aruba.sha256** file from the download directory.
 - b. Load the ArubaOS image to a Linux system and execute the **sha256sum <filename>** command. Alternatively, use a suitable tool for your operating system that can generate a **SHA256** hash of a file.
 - c. Verify that the output produced by this command matches the hash value found on the customer support site.



The ArubaOS image file is digitally signed and is verified using RSA2048 certificates preloaded at the factory. The Mobility Conductor or managed device will not load a corrupted ArubaOS image.

4. Log in to the ArubaOS WebUI from the Mobility Conductor.
5. Navigate to the **Maintenance > Software Management > Upgrade** page.
 - a. Select the **Local File** option from the **Upgrade using** drop-down list.
 - b. Click **Browse** from the **Image file name** to navigate to the saved image file on your PC or workstation.
6. Select the downloaded image file.
7. Choose the partition from the **Partition to Upgrade** option.
8. Enable the **Reboot Controller After Upgrade** toggle switch to automatically reboot after upgrading. If you do not want to reboot immediately, disable this option.



The upgrade does not take effect until reboot. If you chose to reboot after upgrade, the Mobility Conductor or managed device reboots automatically.

9. Select **Save Current Configuration**.
10. Click **Upgrade**.
11. Click **OK**, when the **Changes were written to flash successfully** message is displayed.

In the CLI

The following steps describe how to upgrade ArubaOS from a TFTP server, FTP server, or local file.

1. Download the ArubaOS image from the customer support site.

2. Open an SSH session to your Mobility Conductor.
3. Execute the **ping** command to verify the network connection between the Mobility Conductor and the SCP server, FTP server, or TFTP server.

```
(host)# ping <ftphost>
```

or

```
(host)# ping <tftphost>
```

or

```
(host)# ping <scphost>
```

4. Execute the **show image version** command to check if the ArubaOS image is loaded on the flash partition. The partition number appears in the **Partition** row; **0:0** is partition 0, and **0:1** is partition 1. The active boot partition is marked as **Default boot**.

```
(host) #show image version
```

5. Execute the **copy** command to load the new image to the non-boot partition.

```
(host)# copy ftp: <ftphost> <ftpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy tftp: <tftphost> <image filename> system: partition <0|1>
```

or

```
(host)# copy scp: <scphost> <scpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy usb: partition <partition-number> <image filename> system: partition <0|1>
```

6. Execute the **show image version** command to verify that the new image is loaded.

```
(host)# show image version
```

7. Reboot the Mobility Conductor.

```
(host)#reload
```

8. Execute the **show version** command to verify that the upgrade is complete.

```
(host)#show version
```

Verifying the ArubaOS Upgrade

Verify the ArubaOS upgrade in the WebUI or CLI.

In the WebUI

The following steps describe how to verify that the Mobility Conductor is functioning as expected:

1. Log in to the WebUI and navigate to the **Dashboard > WLANs** page to verify the ArubaOS image version.
2. Verify if all the managed devices are up after the reboot.
3. Navigate to the **Dashboard > Access Points** page to determine if your APs are up and ready to accept clients.
4. Verify that the number of APs and clients are as expected.
5. Test a different type of client in different locations, for each access method used.
6. Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 40](#) for information on creating a backup.

In the CLI

The following steps describe how to verify that the Mobility Conductor is functioning as expected:

1. Log in to the CLI to verify that all your managed devices are up after the reboot.
2. Execute the **show version** command to verify the ArubaOS image version.
3. Execute the **show ap active** command to determine if your APs are up and ready to accept clients.
4. Execute the **show ap database** command to verify that the number of APs and clients are as expected.
5. Test a different type of client in different locations, for each access method used.
6. Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 40](#) for information on creating a backup.

Downgrading ArubaOS

A Mobility Conductor or managed device has two partitions, 0 and 1. If the upgrade fails on one of the partitions, you can reboot the Mobility Conductor or managed device from the other partition.

Pre-requisites

Before you reboot the Mobility Conductor or managed device with the pre-upgrade ArubaOS version, perform the following steps:

1. Back up your Mobility Conductor or managed device. For details, see [Backing up Critical Data on page 40](#).
2. Verify that the control plane security is disabled.
3. Set the Mobility Conductor or managed device to boot with the previously saved configuration file.
4. Set the Mobility Conductor or managed device to boot from the partition that contains the pre-upgrade ArubaOS version.

When you specify a boot partition or copy an image file to a system partition, Mobility Conductor or managed device checks if the ArubaOS version is compatible with the configuration file. An error message is displayed if the boot parameters are incompatible with the ArubaOS version and configuration files.

5. After switching the boot partition, perform the following steps:
 - Restore the pre-upgrade flash backup from the file stored on the Mobility Conductor or managed device. Do not restore the ArubaOS flash backup file.
 - Do not import the WMS database.
 - If the RF plan is unchanged, do not import it. If the RF plan was changed before switching the boot partition, the changed RF plan does not appear in the downgraded ArubaOS version.
 - If any new certificates were added in the upgraded ArubaOS version, reinstall these certificates in the downgraded ArubaOS version.

Downgrade ArubaOS version using the WebUI or CLI.

In the WebUI

The following steps describe how to downgrade the ArubaOS version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, copy the file to the Mobility Conductor or managed device by navigating to the **Diagnostics > Technical Support > Copy Files** page.
 - a. From **Select source file** drop-down list, select FTP or TFTP server, and enter the IP address of the FTP or TFTP server and the name of the pre-upgrade configuration file.
 - b. From **Select destination file** drop-down list, select **Flash file system**, and enter a file name (other than default.cfg).
 - c. Click **Copy**.
2. Determine the partition on which your pre-upgrade ArubaOS version is stored by navigating to the **Maintenance > Software Management > Upgrade** page. If a pre-upgrade ArubaOS version is not stored on your system partition, load it into the backup system partition by performing the following steps:



You cannot load a new image into the active system partition.

- a. Enter the FTP or TFTP server address and image file name.
 - b. Select the backup system partition.
 - c. Enable **Reboot Controller after upgrade**.
 - d. Click **Upgrade**.
3. Navigate to the **Maintenance > Software Management > Reboot** page, select **Save configuration before reboot**, and click **Reboot**.
- The Mobility Conductor or managed device reboots after the countdown period.
4. When the boot process is complete, verify that the Mobility Conductor or managed device is using the correct ArubaOS version by navigating to the **Maintenance > Software Management > About** page.

In the CLI

The following steps describe how to downgrade the ArubaOS version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, use the following command to copy it to the Mobility Conductor or managed device:

```
(host) # copy ftp: <ftphost> <ftpusername> <image filename> system: partition 1
```

or

```
(host) # copy tftp: <tftphost> <image filename> system: partition 1
```

2. Set the Mobility Conductor or managed device to boot with your pre-upgrade configuration file.

```
(host) # boot config-file <backup configuration filename>
```

3. Execute the **show image version** command to view the partition on which your pre-upgrade ArubaOS version is stored.

```
(host) #show image version
```



You cannot load a new image into the active system partition.

4. Set the backup system partition as the new boot partition.

```
(host) # boot system partition 1
```

5. Reboot the Mobility Conductor or managed device.

```
(host) # reload
```

6. When the boot process is complete, verify that the Mobility Conductor or managed device is using the correct ArubaOS version.

```
(host) # show image version
```

Before Calling Technical Support

Provide the following information when you call the Technical Support:

- The status of installation (new or existing) and recent changes to network, device, or AP configuration. If there was a configuration change, list the exact configuration steps and commands used.
- A detailed network topology including all the devices in the network with IP addresses and interface numbers.
- The make and model number of the wireless device and NIC, driver date, version, and configuration of the NIC, and the OS version including any service packs or patches.
- The logs and output of the **show tech-support** command.
- The syslog file at the time of the problem.
- The date and time when the problem first occurred. If the problem is reproducible, list the exact steps taken to re-create the problem.
- Any wired or wireless sniffer traces taken during the time of the problem.
- The device site access information.