

Use Soldering iron with earth.
Solder in cloth-gloves.
Apply insulation coating at the area shaded
in the diagram

Soldering Material:

Solder CCS

Flux L-35



