

Errata Sheet

This Errata Sheet contains corrections or changes made after the publication of this manual.

Product Family: DL305 Date: April 2018

Manual Number D3-DCU-M

Revision and Date 1st Edition, Rev. A; June, 1998

Change to Page 15. Address Switch

The second sentence in the Address Switch section is incorrect. There is no BCD (Binary Coded Decimal) involved with the addressing.

Instead of "The decimal address is set in BCD (Binary Coded Decimal) format with valid addresses from 1 to 90 decimal." the sentence should be:

"The decimal address is set from 1 to 90 decimal."

Change to Page 19. Troubleshooting

For the "DIAG off" entry in the troubleshooting table, the cause listed is "DCU is defective". Two other possible causes are a defective CPU module or base.