

## Sacrificial Anode Anode Sacrificielle Anodo Protector Fungible

Little Giant Pump Company  
P. O. Box 12010  
Oklahoma City, OK 73157-2010  
405.947.2511 • Fax: 405.947.8720

# SA-1

### GB INSTALLATION

The sacrificial anode kit you have purchased has been designed to help protect your Little Giant pump from galvanic corrosion. It is for use on the 1-EA, 1-MA, #1, #2, #3, #4 and #5 model pumps. The life of the anode will vary depending on each application.

1. Attach the anode to the pump as illustrated. The lockwasher should be located between the screw head and the anode ring terminal.
2. Once the anode is attached, cover the mounting screw and anode terminal with the epoxy which is provided. Following the mixing instructions on the epoxy packets.
3. Once the epoxy has dried ( approximately 5 minutes) the pump is ready for use.

### F INSTALLATION

L'ensemble d'anodes sacrificielles que vous avez acheté a été conçu pour protéger votre pompe Little Giant de la corrosion galvanique. L'anode s'utilise avec les pompes 1-EA, 1-MA, #1, #2, #3, #4 et #5. Sa durée de vie dépendra de chaque application.

1. Fixer l'anode à la pompe, tel qu'illustré. La rondelle de blocage doit se trouver entre la tête de la vis et la borne de l'anode.
2. Une fois l'anode en place, couvrir la vis de montage et la borne de l'anode avec l'époxyde fourni. Suivre le mode d'emploi sur les contenants d'époxyde.
3. Une fois l'époxyde sec (environ 5 minutes plus tard), la pompe est prête à l'utilisation.

### E INSTALACION


El juego de ánodo protector fungible que ha comprado ha sido diseñado para ayudarle a proteger su bomba Little Giant de la corrosión galvánica. Debe usarse con las bombas modelos 1-EA, 1-MA, #1, #2, #3, #4, y #5. La vida del ánodo variará dependiendo de cada aplicación.

1. Sujete el ánodo a la bomba tal y como se muestra. La arandela de seguridad debiera estar situada entre la cabeza del tornillo y el terminal del anillo del ánodo.
2. Una vez que el ánodo está sujeto, cubra el tornillo de montaje y el terminal del ánodo con la resina epoxi que se suministra. Siga las instrucciones de mezclado de los paquetes de resina epoxi.
3. Una vez que la resina epoxi se ha secado (aproximadamente 5 minutos) la bomba está lista para ser usada.


CONTENTS • CONTENU • CONTENIDO	
Item	Description • Nomenclature • Descripción
1	Anode • Anodo
2	Epoxy • Époxyde • Epoxi
3	Machine Screw • Vis Mécanique • Tornillo para Metales, #8-32 x 3/8" (P/N 901419)
4	Self-tapping Screw • Vis Auto-taraudeuse • Tornillo, Autorroscante, #10-16 x 1/2" (P/N 902514)
5	Self-tapping Screw • Vis Auto-taraudeuse • Tornillo, Autorroscante #8-18 x 3/8" (P/N 902404)
6	Lock Washer • Rondelle, verrouillage • Arandela de seguridad, #10 (P/N 921023)
7	Epoxy Mixing Stick • Bâton Pour Mélange De L'époxyde • Espatula Para El Mezclado De La Resina Epoxi

Shown Actual Size  
Montré Réel Évaluer  
Mostrado real clasificar

Machine Screw  
Vis mécanique  
Tornillo para metales  
#8-32 x 3/8" (P/N 901419)



Self-tapping Screw  
Vis Auto-taraudeuse  
Tornillo, Autorroscante  
#10-16 x 1/2" (P/N 902514)



Self-tapping Screw  
Vis Auto-taraudeuse  
Tornillo, Autorroscante  
#8-18 x 3/8" (P/N 902404)

