

DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/1/04	8337	10.70.229.4	Pricing						part found in lis, no price given 26 628 134122541 drum,gas dryer,stainless steel	pricing source is 417	1
3/1/04	8337	10.70.229.4	Pricing						part found in lis,no price given 22 998 20-01-137 br chrome	pricing source is 994	1
3/1/04	8337	10.70.229.4	Pricing						part found in lis, no price given 22 998 20-09-102 br chrome overlay (gcv36g)	PRT PRICING FROM SOURCE 994	1
3/1/04	8337	10.70.229.4	Pricing						part found in lis, no price given 22 998 20-01-181 left bracket (gcv36)	PRT PRICING FROM SOURCE 994	1
3/1/04	8337	10.70.229.4	Pricing						part found in lis,no price given 22 998 20-09-006-14 flash tube	part comes back invalid from mfg referred it stac research under mdl GCV36 flash tube has been verified n/a	1
3/1/04	8337	10.70.229.4	Pricing						part found in lis, no price given 22 998 20-09-128 switch cover(4)	per mfg prt is invalid- stac research ref # DLL00366	1
3/1/04	8071	10.70.229.4	DPA						PART# 71500590749 SHOULD BE 71 143 590749	need mdl# this was found on	6
3/1/04	8337	10.70.229.4	Pricing						refrigerator roper model#rt14bkxkq02 part 46 106 2215207 evaporator assy listed in lis but not showing a price. please update system. thanks.	prt subs to 2166055	1
3/1/04	8087	10.70.229.6	Search						Model # 137.248030 Not on LIS. Drillpress Thanks	requested from mfg	5
3/1/04	9276	10.70.229.4	Image	247	646000	113179345	P9100316	2	Key #31 Hose end soft part#09/113/73241 price 9.49 and Key #32 Hose 1-1/2 Dia x 10Ft are missing from schematic and partslist. Please add both parts. Thank you	corrected version will be available with in 10 working days.	8

3/1/04	8337	10.70.229.4	Search							please look at the model number kerc607hww6....the control board in lis is showing up as one board....it is really two boards the tech is working with....the control board with relay is down on the bottom right side...in lis its one single board on top of the range rrg	additional part looking for found on page 3 key 30, relay	8
3/1/04	8048	10.70.229.6	Image	582	1090000	6253485500	10034168	3		what are 65 and 66?	corrected version will be available with in 10 working days.	8
3/1/04	8337	10.70.229.6	Search							SM..NEED PTS LIS FOR THE MOD#72.163653300 THANKS CUBE.. 1150	requested from mfg	5
3/1/04	8337	10.70.229.4	Parts	1770	1610360	A61-20	P9090132			MODEL #A61-20--THE BLOWER WHEEL COMES UP PART #B13680-47--WHICH PRICES AND COMES UP BLADE--CHECKED STACSEARCH AND THE PART WAS RESEARCHED THEY FORGOT TO TYPE AN A AT THE END OF THE PART #--SO THE PART # IS B13680-47A--BLOWER WHEEL. THANKS.	corrected	3
3/1/04	8337	10.70.229.4	Parts	582	152000	41797862791	10052323			mdl# 417.97862791 missing key #21 drum. original pt# was 131427807 changes to 134138400 per stac research in 1998. please provide an updated parts list for this model.Thanks LaToya	part is correctly subbing	8
3/1/04	8337	10.70.229.3	DPA							is there a fiche index card for chambers or is it on storsearch. we have fiche but no way to find model.	contact your document control	6

3/1/04	7103	10.70.229.3	DPA						On model: 116C85PBPk0V02 belt p/n should be 4368510 not 8192011	lis crtt to manual, resubmit with further info for research.	8
3/1/04	8131	10.70.229.3	DPA						part number 09-009-24888 is incorrectly priced in the system at 139.99, price is listed in the plan to sell at 199.99. thanks judy 8131	per source pricing correct at 139.99	2
3/1/04	9276	10.70.229.3	DPA						INCORRECT PRICING. PLEASE UPDATE LIS.	need more specific information	6
3/1/04	7999	10.70.229.3	Image	582	153200	11022894101	P0110061	5	you are missing Key # 19 part # 8529935 motor main drive mdl 110.22894101	corrected	3
3/1/04	7999	10.70.229.3	Pricing						for part 20 860 85323a, use source 107 instead of 860	need more specific information	3
3/1/04	8173	10.70.229.3	Image	247	755200	875188990	10038552	1	Image for 875.188990 is not correct for the model selected. The difference is in the trigger area. This model does not have index 54, 55, 57. Instead the trigger mechanism is held in by a roll pin inserted in index 1.	lis correct to manual	8
3/1/04	8337	10.70.229.3	Parts	1245	1503500	19G402-1170-E1	10055784		ENGINE MODEL #19G402-1170-E1 PART #FOR THE CARBEURATOR IN LIS IS GIVING A 690011--BUT IT IS SUPPOSED TO BE 690111-- WHICH WAS FOUND ON BRIGGS WEBSITE.	corrected	3
3/1/04	8337	10.70.229.3	Image	582	151200	11072036100	P0101091	2	lis sys has no page 4 which includes top and connectors need to have inserted into parts lis found parts list in libary lcation s84-03-609 which has it in book mech tech bill cube 2136	correction will be available with in 10 working days	3

DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/5/04	8087	10.70.229.6	Parts	517	642000	S3655	P0020296		vac model # 72133079030.when you select # for bag,it gives you the # for the filter.thanks brenda/8087	lis is correct to manual	8
3/5/04	8224	10.70.229.6	Image	582	642000	11627412790	10048951	3	Part 676418 shows in lis as whole assembly, part in bin has only one part, contact disc, no matching contacts or grease, as previously sent, thanks laretta 82224	need service order # for mfg bin check	8
3/5/04	8170	10.70.229.6	Image	432	124002	JGBP26GEJ9	E2103908	3	Model # JGBP26GEJ9, KEY # 718 PART # SHOWING IS WB2X116 THIS IS AN INVALID # CALLED GE THE CORRECT PART # IS WB2X10016 THANKS,	corrected	8
3/5/04	8231	10.70.229.6	Search						model 758.144115 no parts info. Jack Padovano	requested from mfg	5

									SUZANNE, I AM USING THIS PAGE AS AN EXAMPLE: THE SERVICE FLASH LISTED ON THIS PAGE; S/F22-714 WAS REVISED JUNE 19, 2002. IT IS NOW S/F22-714R, BUT YOU ARE STILL LISTING THE OUT OF DATE SERVICE FLASH, AND THE CORRECT CURRENT FLASH IS NOT IN THE SYSTEM. WHICH BEGS THE QUESTION. WHAT KIND OF QUALITY CONTROL IS IN PLACE TO MAKE SURE YOU HAVE THE LATEST UP TO DATE INFORMATION, AND NOT OUTDATED INCORRECT INFORMATION SUCH AS ABOVE. WHICH IF THE TECH WAS TO FOLLOW HE WOULD NOT CORRECT THE PROBLEM HE WAS SENT TO FIX. J.R. EXT #14687 CUBE #2129		
3/5/04	8337	10.70.229.6	Documen	582	130000	66515872000				corrected for this flash will still appear to have two because of mfg names	3
3/5/04	8248	10.70.229.6	Image	116	645000	3593	P0403002	1	part numbers do not come up.	lis is correct to manual	3
3/5/04	8337	10.70.229.6	Image	3048	151200	MDG7657BWQ	M0312300	11	THERE IS NOT A SERIES # DESCRIPTION FOR THIS WIRING DIAGRAM THE ONE ON PG.10 IS FOR SERIES 20. I BELIEVE THIS PG IS FOR A SERIES #23, BUT NOT SURE. DEFINITELY NEED THIS CORRECTED SO WE KNOW WHICH DIAGRAM TO USE	series are indicated in parts selection area	8

3/5/04	8337	10.70.229.6	Image	3048	151200	MDE8057AYW	X2906348	10	this is unreadable COULD WE GET A CLEARER COPY Thanks, J.R. CHAVERS CUBE #2129 EXT.#14687	will attempt to locate/will need to use zoom option until then	3
3/5/04	8337	10.70.229.6	Search						this model# shows to be a power screw driver in image with the wrong parts the library file m583779 lists it to be a drill also the 315.111250 also is a drill file#m583912 PLS CORRECT,,,,THANKS ALEXIS	model is valid for both units.	3
3/5/04	8224	10.70.229.6	Parts	247	1500600	917377540	P0311091		LIS says engine Number is Briggs 123k02-0314-E1 ACTUAL NUMBER IS 143.986500 Please Address Unit 8224 Darren( For Dennis/Skelly)	YOU MUST GET THE CORRECT ENGINE MODEL DIRECTLY OFF THE LAWNMOWER.	8
3/5/04	8375	10.70.229.6	Image	582	165000	10653652300	P0303217	12	for model 106.53652300 page 12 key number 10 is wrong part number. shows part number 46 106 2255457 and sub over to 2188622 that is wrong it should be sub to 4389177. please correct system. Info was confirmed by whirlpool rep on 3/4/04 from so# 94577473. Thanks, Deb Dubbs ps8375u	corrected	8
3/5/04	8337	10.70.229.4	Pricing						part found in lis, no price given 22 335 32059501b erc,sigma gas	prt subs to 77001201	1
3/5/04	8337	10.70.229.4	Pricing						part found in lis, no price given 42 106 1185613 compressor	USE DIVISION 46	1
3/5/04	8337	10.70.229.4	Pricing						part found in lis, no price given 26 417 q631141 ring deflector	FORMAT PRT TOO q000631141	1
3/5/04	8337	10.70.229.4	Pricing						part found in lis, no price given 26 417 q174604 basket-spin	FORMAT PRT TOO q000174604	1

3/5/04	8337	10.70.229.4	Pricing						part found in lis, no price given 26 417 q631052 hub-spinner	part# subs to 131026001	1
3/5/04	8337	10.70.229.4	Pricing						part found in lis, no price given 26 417 q615642 seal set	FORMAT PRT TOO Q000	1
3/5/04	8337	10.70.229.4	Pricing						part found in lis, no price given 26 417 q102262 tub-outer	FORMAT PRT TOO Q000	1
3/5/04	8071	10.70.229.4	Image	247	1500600	917377540	P0311091	1	this modle is for a 97 ft drive the pitcher is a 03 push	BOTH ARE CORRECT.. THIS IS A RE-USED MODEL#.	8
3/5/04	8337	10.70.229.4	Pricing						part found in lis, no price given 22 998 14-33-627 s/s door panel and glass w/tape	PRICING FROM SOURCE 994	1
3/5/04	8337	10.70.229.4	Pricing						part found in lis, no price given 22 998 14-33-529-02 switch light with terminal	PRICING FROM SOURCE 994	1
3/5/04	8337	10.70.229.4	Image	996	333200	KP-51WS510	L0312204	83	model # kp51ws510 cant read some of the part numbers in the exploded view page 83 name liz cube1098	locating additional parts information for lis update	3
3/5/04	8231	10.70.229.6	Search						model 14120 is a Kemore portable humidifier and it is not in the system . Jack Padovano	model # given incomplete	5
3/5/04	8337	10.70.229.6	Image	3048	151200	MDE8757AYQ	M0312610	3	model # mde8757ayq iamge and part list does not match	have requested mfg to send corrected rpl	8
3/5/04	8375	10.70.229.6	Image	247	1505200	580768310	P0103214	2	there are three parts number 23. One on pg.1& pg.2 are the same(94804gs) when you price them. Part 23a is not the same part as the 23 on pg2 .cust. is looking for the connections male/female,not what is in 23a(part #187879gs). but what is just 23 on pg. 2. ps#8375 941-379- 1013 m.blum	key #23 is only nozzle, key #23a is the kit for the nozzle not including the nozzle	8

3/5/04	8337	10.70.229.6	DPA						MODEL #106.54606300--THE PART #S FOR BOTH REF. AND FZ. DOORS STAINLESS VCM ARE NOT PRICING BECAUSE THERE NEEDS TO BE AND L ON THE BEGINING OF THE PART #S--COMING UP W/ PART #L2255526LJ AND #L2255891LJ	submitting to buyer 08 for change	1
3/5/04	8037	10.70.229.6	Parts	1262	333100	27R410T	50022995		Could the part number for TL035 be added to the parts list? Thanks, 8037	part# 230760 will be added as an NI	8
3/5/04	8337	10.70.229.6	Image	582	166000	10679902990	P8110220	5	compresser and items not in imaging thanks lt-12999 m/p	submitted for changes	3
3/5/04	8337	10.70.229.4	Pricing						part found in lis, no price given 26 110 8538262 motor assembly 60hz	prt subs to 279827	1
3/5/04	8337	10.70.229.4	Pricing						part found in lis, no price given 22 665 8528854 console assemblyincludes active overlay	prt subs to 8528857	1
3/5/04	8337	10.70.229.4	Pricing						part found in lis, no price given 57 528 lsd10243 mirror	PRT IS PRICING	1
3/5/04	8200	10.70.229.4	Search						model # jsp69bvbb range. the black handle is part # wb15x5218 and black knob is part # wb3x5850. neither of these are showing in lis parts list.	submitted for changes	8



3/5/04	8337	10.70.229.4	Parts	582	124002	79075762001	P0020039	MODEL #790.75762001. PART # FOR THE BAKE IGNITOR COMES UP 5303935068--TECH SAYS IT IS TOO LONG. CHECKED STACSEARCH AND THE RESEARCHED IT ON 9/2003 AND THEY CAME UP W/ PART #5303935066--TECH SAYS THAT'S ON HIS TRUCK AND IS JUST LIKE THE ORIGINAL. SO I BELIEVE IT MAY NEED TO BE CHANGED IN LIS. THANKS.	corrected	8
3/5/04	8337	10.70.229.4	Pricing					part found in lis, no price given 42 596 c6476901 gas valve	PRT SUBS TO C6476904 AND IS NLA	1
3/5/04	8337	10.70.229.4	Parts	432	130000	GSD3000W01	E2102256	MODEL #GSD3000W01 IS MISSING KEY # FOR THE CONTROL ASSEMBLY PART IS LISTED IN LIS WHICH IS WD21X10150	corrected	8
3/5/04	7999	10.70.229.4	Image	247	740000	31517390	40788	1 M#31517390- IMAGE IS TERRIBLE.	corrected	3
3/5/04	8337	10.70.229.6	DPA					MODEL #FRS22WNCD3-- PART # FOR THE DOOR BIN ON THE REF. DOOR GIVES PART #218592325--THIS PART WAS ORDERED TWICE BY A TECHNICIAN-- CHECKED STACSEARCH AND THE PART WAS RESEARCHED IN 10/2003 AND THEY CAME UP W/ PART #218592322. THANKS.	corrected	8

3/5/04	8206	10.70.229.6	Image	1100	333300	MW24FM1	50020940	1	For TV/VCR/DVD combo, the crt is pricing at 1100.99. Can this be verified? This is twice the price of the complete tv.ThanksFrank at Unit 8206	pricing notes have been verified by buyer.. Pricing is correct	4
3/5/04	8231	10.70.229.4	DPA						on part #20-116-8175265--the cord reel in the box is a racheting type--the part needed uses a brake--this uissue has been addressed at least 3 times by me--please correct it thank you	need model# & serial # for further research	6
3/5/04	8337	10.70.229.4	Pricing						for model#831.294031 there are no part#'s in the parts list in the owners manual, manual just has parts list but does not have part#'s, please update, jf25019	documents available	5
3/5/04	8337	10.70.229.4	Pricing						for models FAV6800AWW and FAV6800AWQ there is an owners manual but no parts list, please update, jf25019	documents available	5
3/5/04	9271	10.70.229.4	DPA						for model# 116.30712001 the part# for the motor cover is 4370856.this is blue-green in color.the part is blue.the correct part# is 4370406	refer to stac research ref # SCR00558	8
3/5/04	8071	10.70.229.4	Parts	247	1503120	358797550	P0401204		the part # that comes up for the flywheel is 71 358 530039209. this is for the flywheel that uses a seperate flywheel key and is wrong. the correct part # is 71 358 530071402. thanks	corrected	8

3/5/04	8337	10.70.229.4	Pricing						3399643 is number on back of temp switch . number 34 not 33 in lis wrong. number 33 in lis is signal switch has 3405151 on it. 3405152 is wrinkle guard switch number 34. number 27 is temp switch in lis.thay johnson cube 2138	need model# & serial # for further research	6
3/5/04	8224	10.70.229.4	Image	517	644100	F5872-900	P0112084	1	hose part numbers are wrong!!!!	need specific details for further research	6
3/5/04	8337	10.70.229.4	Image					2	can we have an image for the sewing machines	need model# & serial # for further research	6
3/5/04	8337	10.70.229.4	Image	582	642000	11622513201	P0304103	1	ON MDL#116.22513201, PAGE 1 KEY#13 MOTOR FILTER P#8174919 & KEY#34 NOISE SUPPRESSOR P#8175181, BOTH PRICE AS A SUPPRESSOR AND THAT IS WHAT CUSTOMER RECEIVES. PER FRANK HOWARD AT MATSUSHITA, THE CORRECT P# FOR THE MOTOR FILTER IS P#8175084 20/116. PLEASE CORRECT IN SYSTEM.	corrected	8
3/5/04	7510	10.70.229.3	DPA						G.E. SAYS THIS PART IS NLA 3/5/04	need more specific information	6
3/5/04	8337	10.70.229.3	Image	1100	333100	36A43	L0306305	23	OUR MODEL # IS 36A43...THE FRONT PAGE IN LIS HAS THE CORRECT MODEL LISTED BUT ON PAGE 23 WE NEED SOME CABINET PARTS AND OUR MODEL IS NOT LISTED...PLEASE VERIFY THAT THIS IS THE CORRECT FILE.....NICOLE JONES EXT 14600	refer to stac research ref # DLL00359	8

3/5/04	8354	10.70.229.3	Pricing						you should be able to look up parts by serial number	option not available	9
3/5/04	8211	10.70.229.3	DPA						part number 20 116 8192767 per Frank Howard at matsushita today 03-04-04 said that this is an invalid part number. it is not a pwr part. he says our lis is referencing an incorrect number for the lower plate for model number 116.33729300 upright kenmore vacuum cleaner for so 01075999 for unit 8211 tulsa ok. says to use this part number instead: 20 116 kc27abzhzv07. Cynthia	pwt was valid at previous source now corrected on this mdl	8
3/5/04	7042	10.70.229.3	DPA						Would like to be able to click on the motor model number off the lawn/garden model and have it go directly into that image rather than having to back out and reenter the motor model number.	option not available	9
3/5/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 22 575 funtkb230mre0	part sub to 46-119717-3..order pwr.	1
3/5/04	8224	10.70.229.4	DPA						per stac the part #20158dpx50474 is no longer available, since 2003. please put nla in pricing results so we don't have to wait almost a month to find out the part is nla.	need mdl# for STAC research to confirm	2
3/5/04	8337	10.70.229.3	Image	582	151200	11060982990	P9060085	1	even heat board 3976609 or r is substituting with 8546223 according to balenda at whirlpool .thay johnson. 2138	corrected	8
3/5/04	8337	10.70.229.3	DPA						part # is listed in lis but no price given 26 464 22004191	pwt subs to 22004333	1

3/5/04	8337	10.70.229.3	DPA						part # is listed in lis but no price given 22 364 wb61t10113	part# valid please order pwr	1
3/5/04	8037	10.70.229.3	Image	996	311200	RCD-W500C	L0312060	1	wrong model the one pictured is a cdpcx355 under the rcdw500 model.	on page 2 is model# rcd-w500c	3
3/5/04	8935	10.70.229.3	Pricing						ON MODEL 79099013102 TRY TO SELECT MAIN TOP IT'S SUPOSE TO BE GREY SO THE STUFF THAT I GET IS WHITE CAN YOU HELP ME TO FIND THE CORRECT ONE THANKS A LOT RLAUREANO UNIT 8935	part correct to model	8
3/5/04	8337	10.70.229.3	Models						ksss48QDW05 PT# FOR SS DR HANDLE IS COMING UP 2003679 BUT SHOULD BE 2003675... PT# FOR ICE GUIDE IS COMING UP IN WHITE 1124730 BUT SHOULD BE BLACK 1119035 THE WHITE AND BLACK CROSSOVER TO SAME NUMBER....	part# correct for ss dr handle & ice guide is valid sub.. Black is no longer available	8
3/5/04	8211	10.70.229.3	DPA						vacuum model 72133078000 serial number 310TA16421 every time we order the bag 20 721 5230Fi37498 key number 4-17 we receive a filter with the same part number.thanksTulsa E&MQuestions call David 918-660-6765dbower@sears.com	per model# given.. You are ordering wrong part#.	8
3/5/04	8337	10.70.229.3	Search						RF BURNER INFINITE SW. IS FOR LF INFINITE SW. AND LF FOR RF INFINITE SW. PER. MODEL 790.95682300	per mfg.. Part# are correct to part..	8

3/5/04	7999	10.70.229.3	Image	3204	151200	DLE2532W	L0309516	33	CANNOT SEEM TO LOCATE A PART NUMBER FOR THE LEGS ON THESE UNITS ANYWHERE, THE LEGS ARE SHOWN ON THE ILLUSTRATION, BUR THERE IS NO KEY NUMBER OR PART NUMBER ASSIGNED TO THE LEGS THANX KELLI	SUBMITTED TO STAC RESEARCH.. REF: # DLL00358	8
3/5/04	8087	10.70.229.3	Customer						briggs engine # 129612-0111-e1 needs to be added to lis.thanks,brenda/8087	must have model# & serial# for further research	5
3/5/04	8337	10.70.229.3	Search						MISSING DATA ON PAGE 4 OF 6 PARTS NUMBERS ARE NOT IN ORDER WITH OWNERS MANUAL . OWNERS MANUAL HAS MAGNATRON KEY NR 5000 AND LIS HAS KEY NR 500A EACH KEY NR IS DIFFERENT ON THIS PAGE THAN OWNERS MANUAL SHOWS VERY CONFUSING FOR TECH AND MECH PARTS	missing model# & serial#.	8
3/5/04	8337	10.70.229.3	Pricing						part found in lis, no price given 22 628 5304429449 control panel assy,bisue,less pcb	prt is valid order PWR	1
3/5/04	8337	10.70.229.3	Pricing						part found in lis, no price given 46 106 2223137 tube,water	prt subs to 4387492	1
3/5/04	8337	10.70.229.3	Image	809	311400	S-CR205	L0090015	1	This model (S-CR205) has part of the service manual that has been replaced with a different model. You can see the model number change in the upper left hand corner of the pages....Thanx...Nicole Jones ext 14600 cube 1091	Image will be replaced within 10 working days	3

3/5/04	8337	10.70.229.3	Pricing					part found in lis, no price given 22 335 31967101 bake element 2800w	PART SUBS TO 77001101	1
3/5/04	8337	10.70.229.3	Pricing					part found in lis, no price given 46 596 12568601 b/b gal tilt assembly (qty 2)	PART SUBS TO 67003711	1
3/5/04	8211	10.70.229.3	DPA					need to start pricing so we can begin to order these lower plates: part number 20 116 8192767, example service order 01075999. tech has put into stac research but I think it is just a pwr part. will check w/manufacture as well. 8211's 3-3-04/cpr/	model# & serial# needed for further research	1
3/5/04	8337	10.70.229.3	Pricing					ON MDLS.#116.33728300 & 116.33729300, THE SECONDARY FILTER ON PG.2 KEY#16 SHOWS TO BE P#8192772, PER FRANK HOWARD AT MATSUSHITA, THE CORRECT P# IS # KC37KBZKZ000 20/116. FOR THE PRIMARY FILTER ON PG.3 KEY# 7, LIS SHOWS IT TO BE P#8192756.PER FRANK,#8192756 HAS BEEN OBSOLETE SINCE 8/11/03.IT IS NOT THE CORRECT PRIMARY FILTER FOR THIS MDL.TO BEGIN WITH. THE CORRECT PRIMARY FILTER P# IS #KC95KBZHZU01 20/116, WHICH IS STILL PENDING PRICE AT MATSUSHITA. PLEASE CORRECT P#'S IN LIS...THKS,JO	CORRECTED	8

DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/8/04	8337	10.70.229.6	Image	593	125300	KEBS107DWH7	P9090018	5	please correct this model on the blower motor tech recieved motor 6610168 this motor came witch out instructions and is incorrect for this model we talked to our tech billie and he verifiedthis this blower has the motor on the wrong side will not mount . we do not know why this motor is being sent when the original part from blower motor 4455334 is advailable this was taken off old motor and still runs please correct image thankslt-12999 m/p	PER MFG * THIS IS A VALID SUB * PRT#6610168 IS CORRECT TO MODEL.	8
3/8/04	8337	10.70.229.6	Search						CORRECTION TO PART( N.L.A.) FOR MANUAL RESET (SEE MODEL KEBS277S----)UPPER OR LOWER RESET (PAGE 5 FIGURE 7) THERE IS A KIT AVAILABLE TO REPLACE THESE PARTS SEE PART NO. 4175395 PER W P TECH LINE(RICH)03/05/04 JAMES EDWARDS (CUBE 2166)	THERE IS A INFORMATION SHEET IN LIBRARY THAT COVERS THIS PART#. DATED 04/1989	8
3/8/04	8337	10.70.229.6	Image	1269	123245	56-4677-10-01	Y6002068	2	sm.. the pt# for the toucpad crosses over to 5303207683 and is nla as of 5/23/02, checked with research....cube1150	corrected	2
3/8/04	8337	10.70.229.6	Image	582	153200	11082372810	14506	1	sm.. the pt# 385081for the almond top key no. 15 is nla and varified by stac as of 5/04/2000---checked the research system..	pricing nla in system	2



3/8/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 46 596 d7813044	model# & serial# needed for further research	6
3/8/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 71 536 1501032	PRT IS VALID ORDER PWR	1
3/8/04	8337	10.70.229.6	DPA						TECH ORDER THE PART # 8519332 for model# 110.82824101 and he keeps getting the wrong part.	need mdl# , serial# , & service order for further research	6
3/8/04	8374	10.70.229.6	Image	1245	1503500	286707-0441-01	63493	3	286707-0441-01 b&s engine comes with a 3-1/2 " shaft starter and shows the repair kit as being 490421 which subs to 696540 which is for the long shaft and will not work on the short shaft starter - looking up a service flash for the short shaft 'c' ring install tool it states the rebuild kit for the 'c' ring style is 71 500 497606. this item should be entered into the system as it is used on 71 500 499521 starter that we are currently selling dave deverunit 8374, brookpark, oh	can not locate prt#s referring to will need key#	8
3/8/04	7464	10.70.229.4	DPA						per whirlpool part # 26-110-829966 shows as a drum in the lis system no pricing but whirlpool verified the correct part# is 26-110-8299966. please check this out and make the correction in the lis system. thank, barbara ps7464s	corrected	1

3/8/04	7464	10.70.229.4	Pricing					part# 22-664-8184319 per whirlpool is a stainless steel frame. this is correct in lis, but there is a second listing in lis key 10 c. shows part# 22-664-8184744 as stainless but it is really biscuit .this needs to be corrected as the tech has ordered the wrong part due to this error. thanks. barbara ps7464s	which model# was used? Need model# & serial#.	3
3/8/04	7464	10.70.229.4	DPA					why is the complete door stainless steel pt# 22-664-8183737 \$153.49, the stainless steel panel \$264.49 part# 22-664-8184319 and the biscuit door panel 22-664-8184744 only #26.99??????please investigate.thanks,barbara ps7464s	per mfg pricing is correct	8
3/8/04	8337	10.70.229.4	Pricing					part found in lis, no price given 22 335 r0913143 timer	PART IS VALID ORDER PWR	1
3/8/04	8337	10.70.229.6	Pricing					part found in lis, no price given 22 628 5303305324 paint,touch-up,white	prt sub to 5303321319	1
3/8/04	8337	10.70.229.6	Pricing					part found in lis, no price given 57 528 bz310376 deck cd	prt subs to 169J00018A	1
3/8/04	8337	10.70.229.6	Pricing					part is found in lis, no price given 46 106 2255891lj freezer door (stainless-vcn)	prt subs to L2255891lj	1
3/8/04	8337	10.70.229.6	Pricing					part found in lis, no price given 26 464 40107001 valve,mixing-e2	PART IS VALID ORDER PWR	1

3/8/04	8270	10.70.229.6	Search						In the case of humidifier M# 303.9303 the media pad is listed as NLA (42/303 35-5437-01). Yet the 42/042 93191 media pad is a perfect fit on this unit's media wheel. Unless an associate is aware of this by experience, they will turn away valuable customers. Anonymous Unit 8270	per mfg model is obsolete and will not authorize additional prt subs	8
3/8/04	8337	10.70.229.6	Pricing						part found in lis, no price given 57 528 873504805 crt	pricing from source 060	1
3/8/04	8337	10.70.229.6	Pricing						part found in lis, no price given 46 106 2255934w freezer door	prt subs to L2255934W	1
3/8/04	8010	10.70.229.6	Pricing						part #42-363 wc1x285 is no longer available through GE	need mdl# for STAC Research to confirm	1
3/8/04	8337	10.70.229.6	Parts	996	333100	KV-32FS12	50018391		MODEL NUMBER KV32FS12...IN DOCUMENTS PART LIST MULI BUTTON TOP DOES NOT MATCH DOCUMENTS SERVICE MANUAL...PART NUMBERS ARE NOT THE SAME FOR THIS MODEL...NEED TO CHANGE PART NUMBER..CUB 1094 JAMES TUCKER	submitted to stac research with ref. DLL00353	8
3/8/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 46 106 2198160	part# is 2188656, crisper pan	1
3/8/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 71 917 188240	part# valid please order pwr	1
3/8/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 09 351 20401.00	prt is pricing	1
3/8/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 46 253 8001044	prt is 08001044	1
3/8/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 46 253 8001045	prt is 08001045	1

3/8/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 46 596 b8385404	PART SUBS TO B8385403	1
3/8/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 22 998 20-01-137	pricing from source 994	1
3/8/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 22 998 20-09-102	pricing from source 994	1
3/8/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 22 998 20-01-181	pricing from source 994	1
3/8/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 57 528 418195301	CORRECTED	1
3/8/04	8337	10.70.229.4	Parts	582	123245	72189950590	10038371		MODEL #721.89950590. PART # FOR THE A/C POWER CORD COMES UP PART #6411WZA001B. IT IS ACTUALLY SUPPOSED TO BE 6411W2A001B--NOT PRICING IN TECHS COMPUTER. THANKS. FOUND PART # IN STACSEARCH.	corrected	8
3/8/04	8337	10.70.229.4	Image	1816	124100	DE500JDD1	Y2701109	6	DE500JDD1--MODEL FOR A DRYER. LIS SAYS IT IS A RANGE--BUT PICTURE SHOWS IT AS A DRYER. WHEN YOU PRICE PARTS THEY ARE COMING OUT OF DIV. 22 A RANGE SOURCE. THANKS.	corrected	8
3/8/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 57 528 491p086030	prt pricing	1
3/8/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 57 528 761a196020	prt pricing	1
3/8/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 22 575 cdorfb323mrk0	prt pricing	1
3/8/04	8337	10.70.229.4	Pricing						part found in lis,no price given 42 580 6631ar3843u connector assy	part subs to 4995a20194e	1

3/8/04	8337	10.70.229.4	Pricing					part found in lis, no price given 42 580 6631a30003a connector assy	prt subs to 4995a20194e	1
3/8/04	8337	10.70.229.4	Pricing					part found in lis, no price given 42 568 cwd00157d air filter	pricing out of division 57 source 528	1
3/8/04	8337	10.70.229.4	Pricing					part found in lis, no price given 57 528 a1605989a frame block assy, screen	prt pricing	1
3/8/04	8037	10.70.229.3	Pricing					Belt shield for model# 917378030 is part #182002. This is the same part as #48283. Please show sub #s for each.GRC at 8037	part# correct to model. No changes made	8
3/8/04	8211	10.70.229.3	DPA					Model 580325600 Serial 1008820758 generator the brush assy would not price in LIS part number 71 580 91825GS Key number 6 page 4 However, when you change the DIV. number to 9 the part will price 09 580 91825GS Please update LIS to eliminate confusion ThanksTULSA GRC	corrected	3
3/8/04	8048	10.70.229.4	DPA					part # 22 464 01200011 as per maytag this part went nla in 1994 please update LIS . part inquiry from model # mw317z- 5p...thx unit 8048	model # given, could not be located. Please verify model# & part info.	2
3/8/04	8980	10.70.229.4	DPA					part number for paper bag is #5231fi2453d not part #5230fi3749b which is filter cust upset need up date thanks joyce at #8980 parts division is 20 source 721 please help	model# & serial# needed for further research	2

DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/9/04	8337	10.70.229.6	DPA						part # is correct in LIS, but no price available 22 665 3193354 given by tech pwr	PART IS VALID ORDER PWR	1
3/9/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 22 628 5304430276	PART# VALID PLEASE ORDER PWR	1
3/9/04	8071	10.70.229.6	Customer						ON NEW CANISTER MODEL 11623813300 FINDING SWIVEL CONTACTS BURNT ON MOST OF EVERY ONE	NEED ALL SO#'S FOR MFG RESEARCH	6
3/9/04	8087	10.70.229.6	Documents	247	1500600	917387321			NEED BLOWN UP IMAGE FILE FOR THISMODEL PLEASE	SUBMITTED TO STAC RESEARCH FOR AVAILABLE LITERATURE. REF: DLL00360	5
3/9/04	8077	10.70.229.4	Pricing						SAMSUNG ---- MODEL SCL810.....IC601 PART# AD09-00158A PAGE 3-4 OF PARTS LIST NOT ON LIS. PLEASE MAKE AVAIL FOR ORDERING. THANKS	PART# VALID PLEASE ORDER PWR	8
3/9/04	8075	10.70.229.4	Image	582	1500125	415151010	50022878	1	ON MODEL# 415151010 VALVE HOSE REGULATOR PT# 4524120 SUBS TO 4530152/BUT THESE ARE 2 ENTIRELY DIFFERENT PARTS/SUB PT# 4530152 IS A CONSOLE FOR A CHAR-BROIL SIDE BURNER.	CORRECTED TO PRT 4530047	8
3/9/04	8337	10.70.229.4	Pricing						part found in lis, no price given 22 363 wd34x10924 panel asm outer ss	PART IS VALID ORDER PWR	1
3/9/04	9279	10.70.229.4	DPA						71 991 50-1170 does not sub to a champion plug. i believe it should be a pm-3	price out of 71/136 will sub over to 98/661 prt# pm-3	1
3/9/04	8337	10.70.229.4	Pricing						part found in lis, no price given 22 575 fami-a108wrmz high rack assy	PRT IS PRICING	1
3/9/04	8337	10.70.229.4	Pricing				0309		part found in lis,no price given 26 464 22004191 valve,water	PRT SUBS TO 22004333	1

3/9/04	8337	10.70.229.6	Image	432	125200	JGRP17WEP1WW	WE2103713	1	model-jgrp17wep1ww key# 304 page 1 tubing when pricing key 304 it prices up pt# wb1x1117 for the nut per katrina at mfg should also order pt# std317372 div 98 source 980 for the 3/8 tubing thanks jmr 1179	CORRECTED	8
3/9/04	8337	10.70.229.6	Image	214	912130	DGAA056BDTA	P0210104	1	Susann reference # scr00536 Model dgaa056bdta page 1 key 1 air pressure switch part number 024-27666-000 is correct please run out of div 64/342 Thank you, Shelia ext 14270 3/8/04	CORRECTED	3
3/9/04	8337	10.70.229.6	Image	934	SRS064	867815054	51057	2	Susann Model 867.815054 page 2 key 10a heat exchanger part number in lis is 64/867 522530 . per mfg the correct part number should be 64/867 522531 for model except 815002 and nrgf36edb03. And part number 64/867 522530 for model 815002 and nrgf36edb03 Shelia ext 14270 3/8/	CORRECTED	3
3/9/04	8337	10.70.229.4	Pricing						part found in lis, no price given 46 596 12683802w gasket, fz dr (wht)	PRT SUBS TO 67003550	1
3/9/04	8224	10.70.229.3	Image	247	1503820	358795501	P0308061	2	we can not get a price or availibility for# 52 the crankcase and crankshaft together..thanks Thom Stanley 8224	PRT 530071730 VALID ORDER PWR	1

DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/10/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 46 363 wr57x98	PRT IS WR57X0098	1
3/10/04	8084	10.70.229.6	DPA						sharp microwave mod# r-430ek temp fuse 22/575/502110 the value is too low. oem is 20A at 150 deg. the sub is rated at 15A at 145 deg. gary unit 8084	REFERRED TO STAC RESEARCH REFERENCE SCR00556	8
3/10/04	9276	10.70.229.4	DPA						this control bar part #169780 is the wrong bar//correct bar is #146771	NEED MDL#	6
3/10/04	8337	10.70.229.4	Image	582	166000	25360822001	P0090206	1	ON KENMORE REFRIGERATOR MODEL NO. 253.60822001, PAGE 1, KEY 1, FREEZER DOOR GASKET, PER FRIGIDAIRE THE PART NUMBER SHOULD BE 215608916. THANKS, LYNN	CORRECTED	3
3/10/04	8337	10.70.229.6	DPA						part # is correct in LIS, but no price available 22 575 phok-a043wrfo given by tech pwr	PRICING FROM 57/528	1
3/10/04	8231	10.70.229.6	DPA						model # 5649149910 serial # 021114992 not on lis i waste to much time calling stac please add to lis thank you jim peters at 8231	WILL BE AVAILABLE WITHIN 10 WORKING DAYS	5
3/10/04	8337	10.70.229.6	Image	582	165000	10653552202	P0308109	1	Susann, model # 106.53552202 page 1 key 29 the water filter is part number 2203980. Per Pam at Whirlpool part number 2203980 should sub to 9902 not 9908 Shelia ext 14270 3/9/04	MFG STATES AS OF 3/2 PRT IS CORRECTLY SUBBING TO 9908 THE 9902 IS ALSO SUBBING TO THE 9908	8



3/10/04	8337	10.70.229.6	Image	582	124100	1039747000	36429	3	Susann model 103.9747000 page 3 key 225 the bake element original part number is 277543 and that sub to 400055 but Per Bob Vondale at Hoffman we will make that part 277543 NLA, the 400055 is a surface element not bake Shelia ext 14270***3/9/04	REPLACED PRT ON LIS WITH NPA UNTIL FURTHER NOTICE PER STAC RESEARCH MANAGER	3
3/10/04	8211	10.70.229.6	Document	582	123245	72162362200			to whom it may concern please put a parts list and image into lis for model 72162362200 thanks lisa at 8211	REQUESTED FROM MFG	5
3/10/04	8337	10.70.229.6	DPA						FOR MODEL KEMC378KSSO1 OVEN PARTS PAGE KEY#2F STATES TRIM STAINLESS STEEL SCREW BUT WHEN WE WENT TO THE FICHE CARD IT PRICED AS THE TRIM. ALSO THE RIGHT HAND STAINLESS STEEL ONE MISSING.... PT FOR LH IS 4452084 RH IS 4452083. PLZ CORRECT IMAGE PARTS LIST.	CORRECTED	8
3/10/04	8337	10.70.229.6	Image	582	161000	59662824200	M0310555	2	Susann model 596.62824200 page 2 key 9 part number 12683802w should sub to 67003550. also notified Hoffman of correction shelia ext 14270 3/9/04	CORRECTED	3
3/10/04	8393	10.70.229.6	Search						PN 42/580/6871A10013K SHOULD BE 42/580/687120061J PER FIDELTONE...NPSC	NEED MDL#	6

3/10/04	8211	10.70.229.6	Image	582	642000	11623813300	L0308156	4	Power mate model 11653813300 serial 003702644 will not show an image in LIS. Thanks, Tulsa E&M Shop David Bowersock 918-660-6765 dbower@sears.com	located on page 5 of model# 116.23813300	5
3/10/04	8337	10.70.229.6	Image	593	124002	KGRT607HWH9	W0208042	1	16 AND 16C ARE SMALL CAPS ONE SHOULD BLACK AND ONE GRAY THE SAME FOR 16A AND 16D TECH 12575 IN STAC EXT 14831 MOD.KGRT607 HWH9 PAGE	LIS CORRECT TO MANUAL FROM MFG	8
3/10/04	8337	10.70.229.6	Image	582	121050	91133214100	P0110155	2	A TECH IN THE FIELD CALLED TO TELL US THAT ITEM #323 ON PG 2 IS WRONG AND THE RIGHT P/N IS WB18T10245.THUGHT I WOULD PASS THIS ON. MOD. IS 911.33214100 AND SERIAL IS 2V SERIES. PHIL MORRILL,CUBE 2163,PHONE-	CORRECTED	8
3/10/04	8244	10.70.229.6	Comments						can we have fone numbers of vendor's for lock and key please	NEED MORE SPECIFIC DETAILS	6
3/10/04	8337	10.70.229.4	Pricing						part found in lis, no price given 71 500 699747 sump-engine	PRT IS PRICING	1
3/10/04	8337	10.70.229.4	Pricing						part found in lis, no price given 26 417 5995392205 repair parts list	part# valid pls order pwr	1
3/10/04	8337	10.70.229.4	Pricing						part found in lis, no price given 26 596 40070002 assembly- mild stool	PART SUBS TO 12002013	1

3/10/04	8337	10.70.229.4	Image	582	124111	79095683301	R0308086	1	Replacement infinite switch pt#316238200 will not wire up for left front large 9in burner. Part numbers are reversed in LIS for right front and left front infinite switches. Parts list shows left front Infinite switch for 9in element uses PT#316238200 and right front infinite switch for dual 9in / 6in element uses PT 316049800. This is wrong Also PT#316236200 says a dual switch. This is wrong also. This is actually a single infinite switch. Correction: Correct part numbers are as follow: left front infinite switch for 9in element use PT#316049800 for right front infinite switch for dual 9in / 6in element, use PT316238200. This is for mdl's 790.95683300, 3301, 3302	CORRECTED	8
3/10/04	8337	10.70.229.4	Image	1268	123245	ACM1580AS-PACM1580AS0	M0312599	4	Susann model acm1580as-pacm1580as0 page 4 key 1 latch board part number r0130679 should subto part number 22/464/ r0130612. Submitted to hoffman 3/9/04 also shelia ext 14270 3/9/04	CORRECTED	3
3/10/04	8337	10.70.229.4	Image	1268	123245	ACM1580AS-PACM1580AS0	M0312599	4	Susann model br2256w-p1196703ww page 7 key 22 original part number is 10654206 fan motor is NLA. Lis is listed it with a sub of r0151007 Per mfg that is incorrect. Part is NLA Shelia ext 14270 3/9/04	SUBMIT TO BUYER	3

3/10/04	8337	10.70.229.3	Pricing					part found in lis, no price given 22 364 wb21k10014 valve burner 270 11000 b	part# valid pls order pwr	1
3/10/04	8337	10.70.229.3	Pricing					part found in lis, no price given 46 963 3-11-058-0 compressor (125ws1k)	part# subs to 4201400	1
3/10/04	8200	10.70.229.3	Search					div 22 source 364 part # wb13t10005 is not pricing	part# valid pls order pwr	1
3/10/04	8087	10.70.229.3	Search					580 51300100 Not on LIS Thanks	REQUESTED FROM MFG	5
3/10/04	8087	10.70.229.3	Search					briggs engine # 130202-1650- 01 is not in lis.thanks,brenda/8087	MDL ILS AVAILABLE IN BRIGGS SERIES FORMAT ENTER ON 1ST 4 DIGITS	5
3/10/04	6990	10.70.229.3	DPA					model agc585ww/p1143127n several parts on the oven door page are coming up Part Number Not Found.chad cowden 517-787-9188	PRT# 0041966 SUBS TO 31975801...PRT#0088647 SUBS TO 07729700...PART# 0088788 SUBS TO 02068200...PRT#077007400 IS NLA.. PRT# 07721100 IS NLA..	1
3/10/04	8087	10.70.229.3	Models					briggs engine # 129612-0111- e1 needs to be added to lis.thanks,brenda/8087	REQUESTED FROM MFG	5
3/10/04	8077	10.70.229.3	DPA					the substitute part for the bp508 battery is showing hhr- v20a/1b. this may be correct if you are using an older battery number BUT canon is using the part number bp508 for its NEW batteries used with the ZR65 and OPTURA 10 mini-dv camcorders. they do not, repeat, do not use the panasonic battery it is completely wrong; wrong voltage, wrong size, etc..	NEITHER MODEL GIVEN HAVE BP508 LISTED AS REPLACEMENT BATTERY- ZR65 HAS 6760A002 AND OPTURA HAS BP-514- WILL NEED TO GO TO MODEL NUMBER AND IMAGE PAGE YOUR FINDING THIS THEN SUBMIT FEEDBACK	8

3/10/04	8087	10.70.229.3	DPA					MODEL#917377130 IS GIVEN PART#71 917 189713X428 WHICH IS A_Y_P INSTEAD OF 71 917 183724 WHICH WE HAVE IN STOCK. STORE #8087	RPL DOES NOT CONFIRM USAGE OF 183724	9
3/10/04	8707	10.70.229.3	Pricing					FOR MODEL #407777-0174-E1 - DATA ENTRY ERROR - From the Parts List Diagram Pg #2 key #967 - Filter-Per Cleaner - p/n - 71/500 - 272638 but when priced out it's not a filter. The correct p/n for filter is - 71/500 - 273638 Please make correction to model. Thanks...PS8707P	CORRECTED	8

DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/11/04	8337	10.70.229.4	Pricing						part found in lis, no price given 22 998 35-00-536 control kit dreefs	PRICING FROM SOURCE 994	1
3/11/04	8337	10.70.229.4	Pricing						part found in lis, no price given 22 628 5303210732 rack	part is nla as of 04/26/1999	1
3/11/04	8120	10.70.229.6	Parts	1428	130000	PLDS999CC0	R0303013		need owner's manual parts # for model plds999cc0 thanks/alaina/8120	consumer/customer may call 1- 800-444-4944 for owner manuals..	5
3/11/04	7999	10.70.229.6	DPA						part number for bags should be el200b	model# & serial# needed for further research	6
3/11/04	8337	10.70.229.6	Image	1811	130000	HDA300Y-70BA	E2136620	1	MOD :HDA300Y-70BA, SER: MR705826Y PART KEY#711-- DOOR & HINGE ASM OUTER SHOWN IN LIS AND FICHE CARD #275 E11 AS WD1X0304....THE SYSTEM CONVERTS THIS PART NO. TO A SCREW #WD3M62.... THE PART# SHOULD BE CONVERTING TO DOOR ASM OUTER #WD31X10012....PER MANUFACTURER ...PLZ MAKE CORRECTION TO THE LIS DATA ....JOYCELYN 28405.... CCN RR	corrections will appear in LIS through buyers is now a multi part order	8
3/11/04	9276	10.70.229.6	Image	582	640000	1162832080	41579	2	Hose Ass;y part # 20/116/4147156 which subs to 20/116/8175176 and Hose-Vac part #20/116/4147895 which subs to part # 20/116/4153852 are incorrect for Model # 1162832080. Our Serial number is D74506418. Please research again.	submitted to stac research for part/model verification.. Ref: DLL0352	8
3/11/04	8072	10.70.229.6	DPA				3/11		Per Proform this is not the correct part number, it should be 128093.	model# & serial# needed for further research	6

3/11/04	8231	10.70.229.4	DPA						model #25379106990 serial #jk91910470 part # 42 253 309626501 side curtain is the wrong design and will not fit this A/C pls research thank you jim peters 8231 but if u use part # 42 253 5304423372 plus 42 253 5303311128 rt & lt frame it comes with the correct curtain	according to LIS & Library files part#'s are correct.	8
3/11/04	7464	10.70.229.4	DPA						pt# 22-464-74007473 ignitor listed in lis as non-illustrated for model# 629.jgc9430adb jenn air is incorrect. per maytag that part # is for an amana model. the correct part # for the jenn air model jgc9430adb is 22-464-74009336 please correct the lis system. thanks barbara ps7464s. l	corrected	8
3/11/04	8162	10.70.229.4	Parts	3028	334000	56453491751	41338		Please include part # 57/528 46-9073-3 (belt kit) for this VCR! It will save us many hours of sitting on the phone with STAC in the future!!!!!!	CORRECTED	8
3/11/04	8337	10.70.229.4	Image	3048	153200	MAH6500AWW	M0401152	1	EVERYTHING I HAVE IN THE WAY OF DIAGRAMS SHOWS THIS SHOULD HAVE A TIMER ON IT AND NOT BE THE LED VERSION CONTROL. CAN YOU FIND OUT WHY THE PARTS LIST IS INCORRECT.J.R. CHAVERS CUBE #2129 EXT#14687	PARTS LIST IS CORRECT.. ALL INFORMATION IS LED.	8

3/11/04	8337	10.70.229.4	Image	432	130000	GSD1000G01	E2102255	2	model# gsd1000g01 part# wd18x205 part: inlet sump key 505 page 2 of 3 . Original Part# crosses over to wd1x1392 sump clamp.. I called & spoke w/ Katrina at ge.. orginal part# does indeed cross over.. but there should be 3 parts it crosses too.. 1) wd18x213 inlet sump 2) wd12x418 sump cap & 3) wd1x1392 sump clamp.. this should be good for all models that have the orginal part# wd18x205... Thank you Donna Oradesky research.	corrected	3
3/11/04	8337	10.70.229.4	Image	582	153200	11024852300	L0401340	1	This is so light that you cannot see it unless you blow it up so much you cannot use it effectively.J.R. CHAVERS CUBE #2129 EXT #14867	attempted to reload wtng MFG for better copy	5
3/11/04	8337	10.70.229.4	DPA						MODEL#110.86870100 DRYER PER MFG ANSWER 3/10 OWNERS MANUAL PART# LIT3388864 SHOULD SUB OVER TO LIT3388872.. THANKS DONNA ORADESKY	corrected	3
3/11/04	8337	10.70.229.3	DPA						part # is listed in lis but no price given 71 917 188240	part# valid please order pwr	1
3/11/04	8337	10.70.229.3	DPA						part # is listed in lis but no price given 09 137 14860701	prt# subs to 14960701	1
3/11/04	8337	10.70.229.3	Pricing						part found in lis, no price given 57 528 a-17649-15 crt,blue	PRICING FROM SOURCE 060	1
3/11/04	8211	10.70.229.3	Search						Need model number 72133189030 put into the system please. Thank you 8211 CJ	requested from mfg	5



3/11/04	8254	10.70.229.3	DPA						PART 154245104 COMES IN UNIT SAYING THAT IT IS REPLACING PART 5303943066 RACK 154245104 SHOWS COST AT \$2.16 PLEASE ADVISE AND CORRECT	corrected	6
3/11/04	8337	10.70.229.3	Image	582	124200	9113672991	63782	1	the part # wb27k5202r for the clock is the wrong part # per research done on 2/5/04 clock is supposed to be a wb27k5187r....thanks jg19555	corrected	3
3/11/04	8337	10.70.229.3	DPA						MODEL NUMBER DV650U A SHARP DVD PLAYER...WE DO NOT HAVE A PART LIST IN LIS...CAN GET PART LIST FROM NET...NET TAKES TO LONG TO DOWNLOAD FOR US TO USE....PLEASE ADD PARTS LIST TO LIS.. JAMES CUB 1094	requested from mfg	5
3/11/04	9276	10.70.229.3	Pricing						THIS PART #71 917 701037 IS FRONT WHEEL KNOB AND REAR WHEEL # TOO. REAR WHEEL # SHOULD BE 71 917 161961.	model# & serial# needed for further research	6
3/11/04	8087	10.70.229.3	Image	247	1500600	917377540	P0311091	1	This is suppose to be a self propelled mower--front wheel drive--Mower in diagram is a push mower--917377540	MODEL# IS BOTH A SELF PROPELLED & A PUSH MOWER.. SELECT OPTION CAREFULLY	8

DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/12/04	8337	10.70.229.4	Pricing						part found in lis,no price given 22 664 98005822 cord,power wiring harness parts	PRT SUBS TO 6610236	1
3/12/04	8211	10.70.229.4	Search						to whom it may concern please put parts list and image for model 72162222300 thanks lisa 8211	requested from mfg.	5
3/12/04	9276	10.70.229.6	DPA						Ayp told me that part # 71/917/184486 is a wheel. Can you please put that under discription instead of part.	model# & serial# for further research..	6
3/12/04	8337	10.70.229.6	Image	582	165000	59650692001	P0010607	2	MODEL #596.50692001, KEY # 11B , PAGE "FREEZER DOOR" .....P NO. SHOULD BE TAGGED AS #P50692000W0...NOT #P50694000C0...PLZ CORRECT INFO. ...JOYCELYN #28405	CORRECTED	8
3/12/04	8337	10.70.229.6	Image	593	162000	KSSC42QMS00	W0306035	15	MOD: KSSC42QMS00....PAGE" ICEMAKER PARTS" NOT SHOWING IMAGE OF VALVE, SOLENOID KEY #10 .....PLZ CORRECT IMAGE ...JOYCELYN #28405	mfg sending in next download	8
3/12/04	8337	10.70.229.6	Pricing						part found in lis, no price given 26 464 25001002 control board/lcd ntl	PRICING FROM SOURCE 596	1
3/12/04	8211	10.70.229.6	DPA						On model number 11656512690 part number 20 116 8191504 is wrong and should be 20 116 8175168. Please correct this. Thnak you 8211CJ	submitted to stac research.. Ref: dll 00355	8

3/12/04	9269	10.70.229.4	Image	247	1503400	536796526	43008	1	LAWN EDGER MODEL 536796526 COVER QUILL PULLEY PART # 71 536 53405 COMES UP NLA I CALLED GARDN THEY TOLD ME IT NEEDS A COLOR CODE ADDED TO THE END OF THE PART NO. LIKE E701 71 536 53405E701 SANDY PARTS PRO UNIT9269	PER MFG*THIS PART# 53405, COVER, QUILL PULLEY IS NLA	9
3/12/04	8037	10.70.229.4	DPA						model# 358.797310 cylinder indicates 71 358 530069865 this part has subbed to part #530012381.....8037	PER MFG* THIS IS A VALID SUB..	8
3/12/04	8337	10.70.229.6	Image	582	130000	36314232100	G0112372	3	for model# 363.14232100, on page 3 the motor-pump page, key#493 (part#WD21x10060) only includes one spirng key#553 in the package, pls fix if possible, thank you very much, jf25019	submitted to stac research.. Ref. dll 00354	8
3/12/04	7004	10.70.229.3	DPA						part number 71 917 145425 not found in system	part# valid. Please order pwr	1
3/12/04	8087	10.70.229.3	Parts	247	1500600	917377540	P0311091		mower #917377540 has a wrong engine, instead having tecumseh #143.986500 it has briggs & stratton engine #123k02-0314-e1,in the lis. store#8087	THERE ARE 2 DIFFERENT UNITS WITH SAME MODEL#.. LOOK CAREFULLY..	8
3/12/04	8037	10.70.229.3	Models						no parts info on briggs model # 120802 0120 d1-8037	need mfg code &/or serial# for further research.	6
3/12/04	8087	10.70.229.3	Customer						need model number 121312- 0145-e1 install in lis.thanks,sue	this is a prt#. Not a model#. Found on Model 121a12-0277- e1	5

3/12/04	8084	10.70.229.3	DPA						PART 20/721/6411FI2422V ,POWER CORD, IS NOT A GOOD PART #. PER FIDEL,PART # IS 6411FI2422U. PLEASE CORRECT IN LIS. THANK YOU.	model# & serial# for further research..	6
3/12/04	8337	10.70.229.3	DPA						please correct this cooktop number 316114802 is almond not white it is giving 2 numbers for white cooktopthanks lt- 12999 m/p	need exact model# used for lis feedback correction	6

DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/16/04	8087	10.70.229.4	DPA						for model number 116.22513200 the upper wand should be 20-116-4370623 and lower wand should be 20-116-4370619.thanks,.sue 8087	submitted to stac research, ref: # DLL00357	8
3/16/04	8337	10.70.229.4	DPA						cycle switch coming in as the rinse selector switch and the fabric softner switch is coming in as the cycle switch..fabrc softner switch crosses to temp switch...correct nums: cycle switch is supposed to be 3363917 and the rinse switch is 3354284	model# & serial# needed for further research	6
3/16/04	8337	10.70.229.4	Image	582	151200	11062622100	P0103377	1	On Kenmore electric dryer model no. 110.62622100, page 1, key 3, timer, per Pam at Whirlpool, part number should be 3977678. This is not a 230v. timer. Thanks, Lynn.	corrected	3
3/16/04	7999	10.70.229.4	Search						hi guys:just letting you know that model # 11621600100c doesn't come up on lis thanks.	this is a Canadian model. Will attempt to locate for US Lis	5
3/16/04	7625	10.70.229.4	Search						model 536249810 rear mount 30 inch rear engine bagger is not available in lis	model# not located * please verify & resubmit	6
3/16/04	8231	10.70.229.4	DPA						receive 227213506w1a245b for model 72162253200 on 03/15/04 wrong part received, check stock to see if all parts are wrong for this model. Keypad should be parallelogram w/ right side of keypad going up and down about 1/4".	PART# CORRECT TO MODEL..PLEASE REORDER	8

3/16/04	9276	10.70.229.4	DPA						part#71 917 189713x428 is not right it is 71 917 183724	model# & serial# needed for further research	6
3/16/04	9269	10.70.229.4	Pricing						MODEL 58053701300 DEHUM. FILTER AIR LIS TELLS YOU TO USE 42 580 5230A20026C IT SHOULD BE 42 580 5230A20026A uNIT 9269 SANDY PARTS PRO	PART# IS 5230A20026C * PER MFG	8
3/16/04	8393	10.70.229.6	Pricing						Technician has received 2 of these where the limiter was closed when cold and open when hot. Should actually be open when cold and closed when hot. Tech ordered part 3rd time and wants to ensure that limiter which is spot welded to element is wired correctly. Tech seems to think that these parts may have been manufactured incorrectly and that vendor has defective parts in stock. Can we let the vendor know about this so that the situation can be corrected please?	model# ,serial# & part needed for further research	6
3/16/04	8337	10.70.229.6	Image	1198	130000	DU018DWJX0	W0110039	5	lib file shwng pump/motor assy is key num 8, not shwng in parts list.. par num in lib file is 8193586	CORRECTED	8
3/16/04	8337	10.70.229.6	DPA						part # for white console is wrong in image # 8528854 is wrong. part # 8528857 is correct that # is on stac	corrected	6
3/16/04	8337	10.70.229.6	Pricing						part found in lis, no price given 46 106 2176217 crispier cover	corrected to part# 2176216	1
3/16/04	8337	10.70.229.6	Pricing					3/16	part found in lis, no price given 71 917 188844 tine assembly	PRICING	1

3/16/04	8337	10.70.229.6	DPA					part found in lis, no price given 71 917 532181127 handle	PRT VALID ON 8/29/03 ORDER PWR	1
3/16/04	8337	10.70.229.6	Pricing					part found in lis, no price given 22 364 wb21x00 thermostat, u.o.	INCOMPLETE PRT#	1
3/16/04	8337	10.70.229.6	Pricing					part found in lis, no price given 46 596 12683806b gasket, fz door (blk)	PART SUBS TO 67003559	1
3/16/04	8337	10.70.229.6	DPA					MODEL #152.217060 JOINER/PLANER. PART #OR90365 IS SUPPOSED TO BE A CAPACITOR AND COMES UP OWNERS MANUAL. CHECKED STACSEARCH AND THE CAPACITOR IS PART #OR90397. THANKS.	corrected	8
3/16/04	8087	10.70.229.6	Models					BRIGGS ENGINE # 123K02- 0236-01 IS NOT IN LIS. THANKS, BRENDA/8087	Briggs engine are in series format enter only the first four digits	5
3/16/04	8337	10.70.229.4	DPA					part # is listed in lis but no price given 22 575 rthm- a024wre0	PRICING IN 57/528	1
3/16/04	8337	10.70.229.4	DPA					part # is listed in lis but no price given 46 106 2207184t	PRT IS L2207184T	1
3/16/04	8337	10.70.229.4	DPA					part # is listed in lis but no price given 71 917 812000035	part# valid Please order pwr	1
3/16/04	8337	10.70.229.4	DPA					part # is listed in lis but no price given 71 917 532008393 and 532109230	part#'s valid Please order pwr	1
3/16/04	8211	10.70.229.6	Pricing					On model number 088520 the motor for the newer models (20 475 2-990303-000) is not found in the system. Can you please find this information and get it into the system. Thank you CJ 8211	part# valid Please order pwr	8
3/16/04	8077	10.70.229.6	DPA					model #11627200990c not in the computer...thanks	this is a Canadian model. Will attempt to locate for US Lis	5

3/16/04	8024	10.70.229.6	Pricing						no murray products are listed in the lis and its difficult to find the parts for murray mowers when the model number does not appear in the lis.	Model# & serial# needed for further research	6
3/16/04	8337	10.70.229.4	DPA						part # is correct in LIS, but no price available 46 106 2255934t given by tech pwr	prrt subs to L2255934t	1
3/16/04	8337	10.70.229.4	DPA						part # is correct in LIS, but no price 06 831 126395 given by tech pwr	PRT STATES NLA IN PRICING	1
3/16/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 26 464 25001002	PRICING FROM SOURCE 596	1
3/16/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 46 106 2255891t	PRT IS L2255891T	1
3/16/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 57 528 251c222040	PRICING FROM SOURCE 060	1
3/16/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 57 528 251c222060	pricing from source 060	1
3/16/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 57 528 932217323682	PRICING FROM SOURCE 060	1
3/16/04	8037	10.70.229.3	Search						Could Service Lit for model 20MS233S99 be added to LIS?Thanks, 8037	model# could not be located.. Please verify & resubmit	6
3/16/04	8337	10.70.229.3	Docume	505	333200	43FWX20B			FOR MODEL 43FWX20B CAN NOT READ PARTS LIST....WE DO HAVE A LIB FILE S-86-01-393...PLEASE REDO PARTS LIST	CORRECTED	3
3/16/04	8224	10.70.229.3	Pricing						for this model 38512014590, the needle plate is given as 20385756604004, is incorrect. the correct needle plate for this model is 20385744004001. please correct history. thanks 8224	OUR RECORDS INDICATE THAT CORRECT PART# IS 20/385/742003004	8



3/16/04	8337	10.70.229.3	Image	582	166000	79573263300	50021876	5	MODEL #795.73263300--THE PARTS LIST IS MISSING FOR SEVERAL PARTS SHOWED ON THE IMAGING. TECH NEEDED ICEMAKER AND THAT PART # IS 5989JA0002E--FOUND IN STACSEARCH. TRYED TO CHECK OUT THE LIBRARY FILE BUT THEY SAID THEY DIDN'T HAVE IT. THANKS.	CORRECTED	8
3/16/04	8337	10.70.229.3	Parts	593	165000	KSRS27FGAL01	P9030259		MODEL #KSRS27FGAL00--PART # FOR THE ICE DOOR COMES UP PART #21711713--WHICH WON'T PRICE. CHECKED MODEL W/A 01 ON THE END PART # IS SUPPOSED TO BE 2171713. THANKS.	CORRECTED	8
3/16/04	7464	10.70.229.3	DPA						per tech information for model# pss25mgmbb part#46-363-wr55x10074 control cust is the wrong part for this model. it does not come with the ribbon attaching to unit. the correct part# is 46-363-wr55x10208. please correct this error in lis. thanks.ps7464s barbara	CORRECTED	8
3/16/04	8231	10.70.229.3	Search						model number 116-27115006c is not in our computer.	this is a Canadian model. Will attempt to locate for US Lis	5
3/16/04	7599	10.70.229.3	Image	247	1509200	917270820	10059468	3	tractor model#917270820. is there a replacement complete transaxle?	PART# 150071 71/917	8
3/16/04	8337	10.70.229.3	DPA						mod # 110.94832201....pt # 829966 complete drum asm.....should be pt # 829996,,thanks m.p. sharon	CORRECTED	8

DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/17/04	9269	10.70.229.6	DPA						From Jeff M. at 9269 chassis number 917-372342. when ordering a blade LIS lists pn 7191769334 as replacement. It then substitutes pn 71917850973. This blade is too wide to fit the application. The correct substitution pn is 71204114-886.	REFERRED TO stac Research SCR00539 for verification	8
3/17/04	8337	10.70.229.6	DPA						part # is correct in LIS, but no price available given by tech pwr	need prt# and mdl#	6
3/17/04	8337	10.70.229.6	DPA						part # is correct in LIS, but no price available 46 795 6781jb1185b given by tech pwr	REFERRED TO stac Research SCR00540 for verification	1
3/17/04	8337	10.70.229.6	DPA						part # is listed in lis but no price listed 26 464 25001030	PRICING FROM SOURCE 596	1
3/17/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 46 106 8206659	PRT IS VALID ORDER PWR	1
3/17/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 46 106 2188739	PRT SUBS TO 2188755	1
3/17/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 22 628 318110500	BAKE ELEME HAS BEEN NLA SINCE 01/18/01	1
3/17/04	8163	10.70.229.6	DPA						Could this pricing be incorrect for a plastic turntable support? The microwave is on sale for \$49. Thank you Joyce Kennedy 7183	need prt# and mdl#	6
3/17/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 57 528 313918728041	PRT IS VALID ORDER PWR	1
3/17/04	8015	10.70.229.4	Image	247	1500600	917378072	P0112093	1	Mod: 917.378072 Page 1 Key 55 Blade 22". Picture shows key 55 to be a washer and blade to be key 56. Perhaps this needs your attention. Thanks, Greenville, SC.	CORRECTED	3

3/17/04	8337	10.70.229.4	Image	247	744600	137218250	P0050245	2	Susann,Model 137.218250 page 2 key 80a part number is listed as 14911402 but it should be 14911402a2 Shelia ext 14270 3/16/04	CORRECTED	3
3/17/04	8337	10.70.229.4	Image	247	744600	137218250	P0050245	2	Susann Model 137.218250 page 2 key 80 the part number is listed as unav when pricing part's 0.00 but the part number should be 14911402 for key 80	CORRECTED	3
3/17/04	8211	10.70.229.4	Models						briggs model 130202-0685-02 will not come up on LIS please make necessary adjustments thanx unit 8211	MDL IS AVAILABLE UNDER SERIES FORMAT ENTER ONLY FIRST 4 DIGITS	5
3/17/04	8337	10.70.229.4	Image	1269	124002	TGF657BFD2	P9120330	2	model number tgf657bfd2 spark module on page 2 of 6 key # 8 when pricing the spark module description is an ignitor i called rick at frigidaire to verify that part number 5303912606 *it is a spark module with wrong description thank you jessica cube 1179	referred to buyers for description correction	2
3/17/04	8337	10.70.229.6	Pricing						part found in lis, no price given 46 253 8006995 support	PLACE 0 IN FRONT of the 8	1
3/17/04	8337	10.70.229.6	Pricing						part found in lis, no price given 46 253 8009827 hydrator	PLACE 0 IN FRONT of the 8	1
3/17/04	8337	10.70.229.6	Pricing						part found in lis, no price given 46 253 8009855 trayh,meat tender	PLACE 0 IN FRONT of the 8	1
3/17/04	8940	10.70.229.6	Search						UNDER ENGINE MODEL 143031101 THE IGNITION KEY IS LISTED AS A 71-500-35062, SHOULD BE A 71-143-35062	CORRECTED	3

3/17/04	8211	10.70.229.3	Image	582	645000	11632913200	P0309144	3	Model 11632913200 Page 3 key number 1 is a motor assembly. Their are two parts listed with that assembly that need to be offored as seperate parts. This would reduce IW & MA parts cost as well as incese collect business. Thanks, Tulsa 8211 918-660-6765	WHICH TWO PARTS	6
3/17/04	8337	10.70.229.4	Pricing						Charkie Rodriguez cube #1089,when model #fu11fk2aw3 parts break down comes up,Drian Cup is choosen part #216854002 will not run.	MDL GIVEN NOT FOUND	6
3/17/04	8077	10.70.229.3	Image	582	645000	72133078000	50022842	1	model #721.330780360 not in the computer..thanks	MDL INVALID	5
3/17/04	8337	10.70.229.3	Pricing						part found in lis,no price given 09 137 1ad31602 knob	pricing pending at source	1
3/17/04	8337	10.70.229.3	DPA						part found in lis, no price given 71 500 31q777-0036 engine	PRT SHOULD BE 31Q777- 0036E1	1
3/17/04	8337	10.70.229.3	Pricing						part found in lis, no price given 22 575 pc0vpb054mrp0 waveguide cover	prt subs to 46-214605-3	1
3/17/04	8337	10.70.229.3	DPA						part found in lis, no price given 26 464 25001002	PRICING FROM SOURCE 596	1

DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/18/04	8707	10.70.229.6	Pricing						FOR MODEL #31H777-0202-E1 - BRIGGS ENGINE - PART NUMBER UPDATE - From the Parts List Diagram - Pg #2 key #789 - Wiring Harness - p/n - 71/500 - 695050 - this is not the correct harness for this model. From the Briggs website the correct p/n for the harness is - 71/500 - 698329. Please verify and make correction to model. Thanks....PS8707P	Corrected	8
3/18/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 71 536 578926	prt invalid should be 578927 if LH rod asm	1
3/18/04	8707	10.70.229.6	Models						REQUEST FOR MODEL TO BE ADDED TO LIS DATABASE - CRAFTSMAN MOWER MODEL #917.374641.....Thanks....PS8707P	model is approx. 1986 no indication that a 41 was ever produced just 0 and 2	5

3/18/04	8707	10.70.229.6	Image	247	734000	351233831	P0402093	2	P FOR MODEL #351.233831 - ARTWORK AND PARTS LIST NOT RIGHT. For Pg #2 and Pg #3 - The artwork does not match the parts list on the right hand side. Example - Pg #2 Key #22 - motor chain and Pg #3 Key #22 - handwheel. For Pg #2 the artwork is a handwheel and Pg #3 is the motor chain. It is reversed.Thanks....PS8707	reloading	3
3/18/04	8337	10.70.229.6	Pricing						part found in lis, no price given 26 464 22004191 valve,water (series 10)	prt subs to 22004333	1
3/18/04	8337	10.70.229.6	DPA						hi, on mdl 831.294050 key 99 pt#203358 is a base endcap, you changed it to say rail endcap. Also on same mdl# and also 831.294051 key 106 pt# 203357 is a wheel housing, please update	LIS correct as is	2
3/18/04	8337	10.70.229.6	DPA						part found in lis, no price given 71 500 31q777- 0036 engine	prt is 31Q777-0036E1	1
3/18/04	8337	10.70.229.6	Pricing						part found in lis, no price given 22 665 8528854 console assembly	PRT SUBS TO 8528857	1
3/18/04	8337	10.70.229.6	Pricing						part found in lis, no price given 22 364 wb30t10093 element haliant bridge	part is valid and pricing is pending	1
3/18/04	8337	10.70.229.6	Pricing						part found in lis, no price given 46 106 2255114 p.c. board,receivefr	PRT SUBS TO 4389102	1

3/18/04	8337	10.70.229.6	Pricing					part found in lis, no price given 57 528 a80jyv50x loc-56:picture tube	USE SOURCE 060 PRT IS NLA	1
								mod # 790.93851302...ser # vf40834462...message from tech # 16337-ed...please change the pt # 316105500..warmer drawer glide (2) key # 77 on page 2 of 6 so that when that part is ordered they will know they are not recv 2 rails, only one ...when they order that pt they will only recv 1 rail and he must reorder another part of the same number and wait on another part before he can repair customers range ....I told the tech i would pass the message along thanks sharon # 1127 mech parts	THE (2) IS AN INDICATOR THAT 2 OF THESE PRT#'S ARE REQUIRED NOT THAT 2 ARE INCLUDED.	9
3/18/04	8337	10.70.229.6	DPA							
3/18/04	8171	10.70.229.4	Pricing					this number indicates a burner not a regulator. #4594652. Also, when you click on burner, nothing comes up. thanks, mary at 8171 913-541-8632	NEED MDL#	6
3/18/04	8337	10.70.229.4	DPA					model: 110.49182990 washer(26) part#3968298 microcptr should be crossing over to prt# 3970630 cntrl-elec. this is per mfg answer on 3/16. response to a bin check.. Thanks Donna Oradesky, Research	Corrected	3

3/18/04	8087	10.70.229.4	Image	3199	1500600	ROYAL 53S INTEK	L0401308	1	ROYAL 53S INTEK WE NEED PARTS BREAKDOWN.THANKS, 8087 SUE	REQUESTED	5
3/18/04	9279	10.70.229.3	DPA						917377540 has the wrong part number for the rear wheels	PRT IS THE SAME NUMBER AS THE FRONT	9
3/18/04	9279	10.70.229.3	Image	247	1500600	917378550	L0401210	1	917378550 has no parts list diagram	WILL BE AVAILABLE WITHIN 10 WORKING DAYS	5



DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/22/04	8393	10.70.229.4	Search						Div 22 Src 665 pn 675806 are being shipped from whirlpool and the pdc's missing the spring.	will need SO and model number to further research	4
3/22/04	8707	10.70.229.4	Models						FOR MODEL NUMBER'S - L212PNC & L212SNC - DATA ENTRY ERROR - LIS showing wrong model numbers. From both models on Page #1 there shows two model numbers - one number is typed and the other number is hand written. The handwritten model number is the correct model Per the LawnBoy website. The correct model numbers are - L21ZPNC & L21ZSNC. The fourth digit is a "Z" not a number "2". Please make corrections to model.Thanks.....PS8707P	L212 is valid model made for MW- L21Z sister model	9
3/22/04	8337	10.70.229.3	Search						model number 113.248350 is a 1997 model..and this model number does not come up in lis...looking for parts please input model number	Requested from MFG	5
3/22/04	8337	10.70.229.3	Search						the model number 911.49489992..it does not show a breakdown of the control assy	requested from mfg to add micro parts	3
3/22/04	8337	10.70.229.3	Search						model number 665.4433450 it does list part number or key number for magnetron...thanks	CORRECTED	3

3/22/04	8337	10.70.229.4	Image	582	153200	11044936202	K0312031	3	MODEL #110.44936202 IS MISSING KEY #1 ON PAGE 3--CONTROL PANEL. WON'T LET YOU SELECT. THANKS.	ATTEMPTING TO CORRECT IMPORT	4
3/22/04	8337	10.70.229.4	Image	996	333600	KF-42WE610	L0311069	##	please fix page 138 cant see some parts model kf42we610 liz cube1098	will need to use zoom option	9
3/22/04	8211	10.70.229.6	Pricing						on engine model EHF00935 the electric starter will not price out thanx unit 8211	CORRECTED	1
3/22/04	8337	10.70.229.6	Image	1404	333100	CK-3502R	98080092	34	PLEASE LOOK AT PARTS LIST SOME PAGES ARE TOO DARK IN THE SERVICE MANUAL PLSEASE REDO PAGE 34...MODEL CK3502R JAMES TUCKER CUB 1094	When MFG shade's these areas scanners can not filter them out	3
3/22/04	8337	10.70.229.6	Image	582	166000	10679907990	P8110220	5	MODEL #106.79907990 IS MISSING PAGE FOR THE COMPRESSOR PARTS IN LIS. YOU CAN TYPE IN COMPRESSOR ON PARTS TAB AND IT WILL COME UP IN PART LIST ON THE REFRIGERATOR DOOR PAGE.	will be available within 10 working days	3
3/22/04	7711	10.70.229.6	Search						this syatem needs to be avabile to every computer which could reduce handle time	Acknowledged	10
3/22/04	8337	10.70.229.6	Parts	582	123370	72163684300	50022005		MODEL #721.63684300--SKIPS KEY #5056 LAMP HOLDER--ON PAGE 6	Referred to STAC Research reference SCR00549	8
3/22/04	8337	10.70.229.6	Image	582	153200	11044921301	K0312031	1	MODEL 110.44921301 IS MISSING KEY #19--SCREEN DOOR. WON'T LET YOU SELECT THAT PART #. THANKS.	ATTEMPTING TO CORRECT IMPORT	4

3/22/04	8337	10.70.229.3	Pricing						part found in lis, no price given 26 464 25001046 valve,water inlet	pricing source is 596 for this part	1
3/22/04	8295	10.70.229.3	Pricing						the second seperator on this mod that we have had warped so bad doors could not adjust enough to fix prob.so#95385121Model # . . 25353322300 Serial # . . LA30926263	Referred to STAC Research reference SCR00550	8
3/22/04	8295	10.70.229.3	Image	582	165000	59650392001	L0206146	1	mod #795 73266300 ser#302mr00736 glass shelf has no part #in lis order part 46/795/3550jl2001c plastic shelf that holds glass comes.need to be able to get glass for plastic shelf.	prt number given not found on org prt list or sub-	8
3/22/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 46 183 rf-1900-24	part# valid. Please order pwr	1
3/22/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 22 628 5304434315	part# valid. Please order pwr	1
3/22/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 22 628 5304429457	part# valid. Please order pwr	1
3/22/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 22 628 5304408938	part# valid.. Please order pwr	1
3/22/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 22 628 5304408963	part# valid. Please order pwr	1

3/22/04	8166	10.70.229.6	Search						model number 119.7498893.incorrect parts listed for bothe the left and right side hinges. the correct numbers are reversed. the system says to order part #3205894 for the left side andto order part #3205895 for the right side.....this information is wrong..... the correct part # for the left is 3205895 and the right is 3205894 this information is per frigidaire thanks, sheila lee unit 8166	Corrected	3
3/22/04	8337	10.70.229.6	Pricing						part found in lis, no price given 22 628 722t070p02 thermostat	part# nla verified 08/28/2000	1
3/22/04	8337	10.70.229.6	Pricing						part found in lis, no price given 22 335 32059501b erc,sigma gas	prt subs to 77001201	1
3/22/04	8337	10.70.229.6	Pricing						part found in lis, no price given 71 141 p0726a bowl panel lt	model# needed for further research.	1
3/22/04	8337	10.70.229.6	Image	247	702250	580323300	P0309003	1	MODEL 580.323300, SER: NONE...MAIN UNIT PAGE KEY #19 -- RECTIFIER, BRUSH AND BRIDGE ASM, SHOWN IN LIS AS #71/580 91825GS....NOT PRICING ....PLZ CORRECT THE DIVISION FOR RUNNING IN SYSTEM TO #09/580 91825GS...THIS WILL PRICE UNDER DIVISION 09....THANKS JOYCELYN 28405	Corrected	3
3/22/04	8231	10.70.229.3	Pricing						no reference for model 72163352300 manufactured in 2003	Requested from MFG	5

3/22/04	8337	10.70.229.3	Image	247	1500600	917372852	10036358	2	Model# 917.372852 page 2 key # 53 prt# 144747 and key # 52 should be prt#144748. Prt numbers are incorrect in image. Eric	corrected	8
3/22/04	8337	10.70.229.4	DPA						model#790.79013102 gas range part#316237900-901-902 are all natrual gas orifices.. pricing up as lp .. called Rick at frigidaire.. confirmed .. these are all natural gas orifices.. thank you donna - research	Referred to buyer 08 for correction on 901 and 902	8
3/22/04	8163	10.70.229.4	Parts	582	903000	43783231	10051858		Activated filter 83237 subs to DP83120. The original filter is 3 1/8" wide and the substitute is 7" wide.	STAC Research has confirmed with source the sub prt is correct for mdl given	8
3/22/04	7599	10.70.229.6	Pricing						according to the schematics the filter element is 71-501 12-743-12-S, this is misleading all the customer got was the kit, air cleaner seal. Luckily the customer wasn't in a hurry to get the parts, but it did take extra time out of his schedule.	need additional information	6
3/22/04	7464	10.70.229.4	DPA						THE NPS SYSTEM SHOWS THERMOSTAT 46-106-876264 AS NO LONGER AVAILABLE, THE LIS SYSTEM DOES NOT REFLECT THIS INFORMATION.	LIS does not update NPS	9
3/22/04	8337	10.70.229.6	DPA						model 917.256510...key punch error on mulch kit ,part should be 141112 not 14112	corrected	3

3/22/04	8224	10.70.229.6	Image	582	1210000	3851960180	41491	5	for this model 3851960180, the item #1 on this page, needle plate unit shows the box around the needle plate and the bobbin cover plate. the part # given 20385826602002, comes without the bobbin cover plate. please correct. thanks 8224	will need so# for research to do bin check	8
3/22/04	9276	10.70.229.6	Customer						in the past week we received 2 toro mowers model #20018 and 20017. For both models we needed blade and handle knob. could you please put images and partslist for both models into lis. And also enter parts and pricing in lis.	Requested from MFG	5
3/22/04	8337	10.70.229.6	Pricing						hi, part description correction, mdi# args7650ww/p1130765n amana range, 22/335 31746202w prices as a 6" element, however this is verified by mfg as a storage drawer wrapper. thanks jeff 1186 ext 14718	confirming with mfg	8
3/22/04	8248	10.70.229.3	Image	247	1505200	580768020	P9030149	2	ther is no number 17 on page 2.	CORRECTED	3
3/22/04	8206	10.70.229.3	Image	1268	153000	LW3503W2/PLW3503W2	I2204167	21	Arrgh!! About two months ago (1/19/04), we requested new images for Amana washer LW3503W2/PLW3503W2, as all images were of a refrigerator door. They still haven't updated! ThanksFrank at Unit 8206	CORRECTED/mfg REPLACED WITH MODEL A OR B	3

3/22/04	7510	10.70.229.3	DPA					part 22 628 5303300160 rh end cap is different from part 22 628 5303300161 lh end cap when you put in part numbers comes up 22 628 5303307197 for both parts	kit	9
3/22/04	8337	10.70.229.3	Pricing					part found in lis, no price given 71 917 132823 spacer, spring stop idler	part subs to 532132823	1
3/22/04	8337	10.70.229.3	Pricing					part found in lis, no price given 46 106 1185613 compressor	PRT IS PRICING	1
3/22/04	8337	10.70.229.3	Pricing					part found in lis, no price given 22 628 318005105 thermostat	part# valid. Pricing is pending	1
3/22/04	8337	10.70.229.3	DPA					part # is listed in lis but no price given 26 464 25001030	PRICING FROM SOURCE 596	1
3/22/04	8337	10.70.229.3	Pricing					part found in lis, no price given 42 106 1184613 compressor	PRICING IN DIV 46	1
3/22/04	8337	10.70.229.3	Pricing					part found in lis, no price given 46 106 2216062s stainless freezer door	PRT SUBS TO L2223091S	1
3/22/04	8337	10.70.229.3	Pricing					part found in lis, no price given 57 528 kr00276 screen assy	PRT # VALID PLEASE ORDER PWR	1
3/22/04	8337	10.70.229.3	DPA					part # is listed in lis but no price given 46 106 4390734	PRT SUBS TO 4387774	1
3/22/04	8337	10.70.229.3	DPA					part # is listed in lis but no price given 71 500 31q777-0036	PRT IS 31Q777-0036E1	1
3/22/04	8337	10.70.229.3	Pricing					part found in lis, no price given 22 665 4392899 paint, touch-up (1/2oz) (biscuit)	PRT PRICING 26/110/4392899	1
3/22/04	8337	10.70.229.3	DPA					part # is listed in lis but no price given 26 110 8538262	PRT SUBS TO 279827	1
3/22/04	9276	10.70.229.3	DPA					WE NEED PRICING ON THIS PART.	need additional information	6

3/22/04	8337	10.70.229.3	Image	1198	124200	SF318PEWN0	O2024123	3	model#sf318pewn0 burner valve switch not shown in image tech assist*** missing off all our images but pt# is 4157180 tech got pt# from using an n1 at the end of mdl# cause it is a color option thanks jmr 1179	PRT# GIVEN IS AN IGNITOR SWITCH PRT GIVEN BY MODEL GIVEN IS NOT THE SAME WILL NEED DETAILS ON WHY PRT 4157210 IS INCORRECT FOR MODEL	6
3/22/04	8337	10.70.229.3	Pricing						part found in lis, no price given 46 363 wr57x119 water valve asm	PRT IS WR57X0119	1
3/22/04	8337	10.70.229.3	Pricing						part found in lis, no price given 42 153 31919 2 pole thermostat	referred to stac research under mdl 153.326860 ref# DLL00367	1



DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/24/04	8337	10.70.229.6	Image	582	904032	25370094000	P0060390	4	MODEL #253.70094000-- PART #FOR THE CONDENSER IS NOT CORRECT IN LIS IMAGING-- CORRECT PART #IS SUPPOSED TO BE 5304403945--FOUND IN STACSEARCH.	Corrected	8
3/24/04	8337	10.70.229.6	DPA						MODEL #TBX23ZHB PART # FOR THE COMPRESSOR IN LIS COMES UP WR17X2088-- THE MODEL WAS UNDER SERVICE FLASH SF46-288-- THE CORRECT PART # IS SUPPOSED TO BE WR87X10082. THANKS.	prt correctly subs	8
3/24/04	8337	10.70.229.6	DPA						MODEL #HMG219627A-- COMES UP IN LIS AS 21962- A. PART #FOR THE REFRIGERATOR INNER LINER ON IMAGE PAGE COMES UP AS A SCREW. WHEN YOU GO TO THE PARTS LIST PAGE YOU CAN PICK THE MODEL AND GET THE CORRECT PART # THAT WAY--BUT NOT ON THE IMAGE PAGE. THANKS.	prt# not available	8
3/24/04	8337	10.70.229.6	Image	247	718000	139664753	34215	3	MOD:139.664753.....PAGE RADIO CONTROLS , KEY #7 IS TRYING TO RUN OUT OF DIV 64 ...DIV SHOULD BE DIV #09....PLZ CORRECT .....JOYCELYN 28405	corrected	3

3/24/04	9276	10.70.229.6	DPA					9173776661 I was looking up a rear door for this application. The part number I recieved is 71-917-183058. This is incorrect This number giver me a side mulcher door, not a rear door as I need Thankyou (GT)	LIS is corrected to manual	8
3/24/04	8337	10.70.229.6	Pricing					part found in lis no price given 57 528 tcrt190gs041 crs a80qcf340x and 57 528 tcrt190gs042 crt a80qcf340x03	prts pricing from source 060	1
3/24/04	8337	10.70.229.6	Pricing					part found in lis, no price given 71 536 015x84 nut,flange	remove the "0"	1
3/24/04	8337	10.70.229.6	Pricing					part found in lis, no price given 71 536 009x75 bolt,shoulder	remove the "0"s	1
3/24/04	8337	10.70.229.6	Pricing					part found in lis, no price given 57 528 0em000670 front cabinet	THIS IS A NON-SERVICEABLE PART	1
3/24/04	8337	10.70.229.6	Search					Wrong part running in system-water valve Model number of unit - 106.54609300 ser number- sp3542075 incorrect part number - 2255457 water valve Water valve for this unit - correct part number 4389177	corrected	2
3/24/04	8337	10.70.229.4	DPA					part # is listed in lis but no price given 46 183 rf-0668-08	SUBMITTED TO STAC RESEARCH UNDER MODEL# 183.13401300. REF# DLL00347	1
3/24/04	8211	10.70.229.4	DPA					to whom it may concern please put into lis parts list and image of model 72163359300 thanks lisa 8211	requested from MFG	5

3/24/04	8337	10.70.229.4	Image	582	152000	41794814301	L0202075	1	THIS OWNERS MANUAL IS MISSING THE FIRST 8 PAGES=. WHY? WHY? BERTRAMITE?	requested for new import	5
3/24/04	8337	10.70.229.4	Image	582	124002	36273271690	P0212182	1	MODEL NO. 362.73271690 PARTS LIST IS INCORRECT FOR THE BAKE BURNER cORRECT PART NO. IS WB16K10035 SEE PAGE 1 FIGURE 26.THANKS JAMES EDWARDS CUBE 2166 COOK TECH)	corrected	3
3/24/04	8206	10.70.229.4	Image	247	731750	820693	10000238	1	For electric motor model 820693, the image showing is that of an electric drill, not the electric motor required.ThanksFrank at Unit 8206	requested from MFG	3
3/24/04	7999	10.70.229.4	Image	1281	645000	4475AT-2	P9060003	3	on page 2 hose amd attachments the description of part #7 and #8 are flipped.	corrected	3
3/24/04	8299	10.70.229.4	Pricing						Air filter for model number 143.986001 is 36046 not 36045. 36045 is the primer bulb.	corrected	8
3/24/04	8337	10.70.229.4	Image	582	152000	41799877990	P9030255	5	On Kenmore Laundry Center model # 417.99877990, page 5, key 28, washer belt, part # should be 131686100. Info from library file.Thanks, Lynn.	corrected	3
3/24/04	8224	10.70.229.6	Image	247	1503820	358798270	10034343	1	Hi this is Bob from 8224. #9, shield kit, is the wrong part for this model.	further information needed for STAC Research	8
3/24/04	8337	10.70.229.4	Search						model number gld8957ab2..for a frigidaire dishwasher does not come up in lis...this model is brand new....please enter model number into lis...age: 1 month old ...thanks...	correct mdl is GLDB8957AB2	5

3/24/04	8337	10.70.229.3	DPA						part # is listed in lis but no price given 22 628 318015037	part# valid. Please order pwr	1
3/24/04	8077	10.70.229.3	DPA						THIS IS 2ND REQUEST TO PUT PART# AD09-00158A DIV 57/528 AVAILABLE ON LIS SYSTEM FOR ORDERING /////3/23/2004	source and lis do not recognize prt emailed unit for mdl#	1
3/24/04	8087	10.70.229.3	Models						murry mower #20615x8a is not in lis. thanks,brenda/8087	DOCUMENT AVAILABLE WITHIN 10 WORKING DAYS	5
3/24/04	8337	10.70.229.3	DPA						part # is listed in lis but no price given 22 628 5304417433	part# valid. Please order pwr	1
3/24/04	8087	10.70.229.3	Models						MURRY MOWER # 22267X92A IS NOT IN LIS.THANKS,BRENDA/8087	REQUESTED FROM MFG	5
3/24/04	8337	10.70.229.3	DPA						part # is listed in lis but no price given 71 143 756340b	part# valid. Please order pwr	1
3/24/04	8337	10.70.229.3	DPA						part # is listed in lis but no price given 46 253 241546902	prt subs to 240521107	1
3/24/04	8337	10.70.229.3	DPA						kenmore refrig. m# 106.54604300 part 46 106 2255510t freezer handle bisq. part listed in lis but not pricing. please update	PRT SUBS TO 2255514T	1
3/24/04	8337	10.70.229.3	Pricing						tiller m#917294270 part 71 917 188240 transmission listed in lis but not pricing. please update.	part# valid. Please order pwr	1
3/24/04	8038	10.70.229.3	Image	934	1142000	TOOLS	L0106160	2	HOW DO YOU PRINT?jtroj00@sears.com Please send me a List of all of the TOOLS for each of the industries. Please include: TV, Laundry, Refer-HVAC, Water Treatment, Dishwashers, Ranges,...I already found the one ISO doc for Calibrated Tools on the ISO database.	referred to lis management for review	9

3/24/04	8038	10.70.229.3	Image	934	1142000	TOOLS	L0208063	1	PLEASE HELP ASAPI need a printed list of each of the "Basic Tools" tool lists for site work, and each of the sub lists (Range Line, Microwaves, Laundry...all lists please. Thanks.John Troja, Tech Mgr, ISO coordinator, cell-619-249-4602, jstroj00@sears.com	referred to lis management for review	9
3/24/04	8087	10.70.229.3	Pricing						MODEL # 31AE160-062..FOR PART NUMBER 71-247-7512B1476 PRIMER IS WRONG. CORRECT NUMBER IS 71-247-751-0354.SUE	model given not found	8
3/24/04	7131	10.70.229.3	Search						why do we have so much trouble signing on on a daily basis? Most days it takes 4-5 hours to get lis 2 signed on, costing us many dollars.	refer issue to unit management and it help desk	9
3/24/04	8337	10.70.229.3	DPA						part # is listed in is but no price given 46 596 12683806w	PRT SUBS TO 67003558	1
3/24/04	8337	10.70.229.3	DPA						part # is listed in lis but no price given 46 106 2255526lj	PRT SUBS TO L2255526lj	1

3/24/04	8197	10.70.229.3	DPA						<p>atten; to whom it may concern, the following part in the lawn dept as follows div 71 source 071 part# 3332 same as 71-143-35066 as single item, the 3332 is a package that contains two for the price of 6.99 and the single part sell for 2.40 each. total for two is 4.80 verses 6.99 the difference of 2.19. before price went up on part 332 it was selling for 3.99 it has gone up 3.00 see if can make some kind of adjustment, not selling, need to be fair to ours sears customers. please let me know if price can correct in main office. or let me know know who we can contact...call us at 432-563-5002 and ask for norma a concerned associate.....this was done on 3-22-04.....please give some kind of feedback!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!</p> <p>thanks</p>	<p>correct sam prt different sourcing/ 071 is for repair and 143 is for consumer purchase/ attempted to call to no response</p>	9
3/24/04	8337	10.70.229.3	DPA						<p>91727630 riding tractor part number 71 917 189088 decal. part listed in lis but not pricing. please update</p>	<p>part# valid. Please order pwr</p>	1
3/24/04	8337	10.70.229.3	DPA						<p>maytag washer m#mav7557eww part 26 464 22004191 water valve listed in lis but not pricing. please update system.</p>	<p>prt subs to 22004333</p>	1
3/24/04	8211	10.70.229.3	Image	1324	1500600	LO45N21CA	P0402101	0324 1	<p>A&amp;E mower 127802-1901-B2 will not come up in LISThanks,Tulsa GRC 8211</p>	<p>REQUESTED ENGINE BREAKDOWN FROM MFG</p>	9

3/24/04	8211	10.70.229.3	Search						KAWASAKI ENGINE #SR621 NOT IN LISA&E CALLTULSA 8211	AVAILABLE IN LIS SINCE 3/19/04	5
3/24/04	8707	10.70.229.6	DPA						FOR MODEL #GCV160ABHH - DATA ENTRY ERROR - From the Parts List Diagram - Pg #6 Key #2 - Plate Assy. - LIS shows p/n as - 71/550 - 7058951 - and that shows as "Part Number Not Found" Per a phone call to Honda the correct p/n is - 75111-VE1-G01 - Please make corrections to model.....Thanks.....PS8707P	CORRECTED TO PRT 75110- ZOL-000	8
3/24/04	8337	10.70.229.3	Pricing						part found in lis, no price given 46 253 240330005 base- compressor	part# valid. Please order pwr	1
3/24/04	8337	10.70.229.3	Pricing						part found in lis, no price given 57 528 ue20461 prt assy (red)	PRT PRICES OUT OF SOURCE 060	1
3/24/04	8337	10.70.229.6	Pricing						model # 233.57800890 * prt# v03509 filter (qty2) per mfg * called fidelitone, there is only 1 filter per pkg... thanks dlo research	CORRECTED	8
3/24/04	8120	10.70.229.6	DPA						20116 kc94pbztzb39 does not price for model 11623612300	part# valid. Please order pwr	1
3/24/04	8337	10.70.229.3	Pricing						part found in lis, no price given 46 363 wr87x10085 comprsr repl kit	prt subs to wr87x10095	1
3/24/04	8337	10.70.229.3	Pricing						part found in lis, no price given 46 106 4396702 water filter	prt subs to 2301705	1
3/24/04	8131	10.70.229.3	Image	582	153200	11082980100	42396	2	11082980100 Timer has a splined shaft, subs to a threaded knob.	prt 387987 subbing to 3362624 has been confirmed by stac research as correct	8

3/24/04	9276	10.70.229.3	Image	247	1503820	358795200	P0306271	1	LIS WEEDWACKER MODEL 358.795200 DEFINES KEY 38 AS PART 71 358 71-85740 HOWEVER PART COMES UP IN LIS AS "PART NUMBER NOT FOUND". ALSO TECHNICIANS FOUND CRAFTSMAN COMMERCIAL GRADE HASLE- FREE TRIMMING SYSTEM PART IN STOCK AS 71 071 71-85740 WHICH LOOKS EVERY BIT LIKE THE LIS PICTORAL BUT THIS PACKAGE CONTAINS A FEW NUTS BUT DOES NOT CONTAIN THE LARGER SHOULDERED MOUNTING NUT. LIS IS CALLING OUT AN INCORRECT NUMBER AND IF IT IS INTENDED THAT THE 071 SOURCE PART IS THE CORRECT ITEM, IT TO SHOULD BE EVALUATED FOR PROPER INCLUDED HARDWARE.	CORRECTED	8
3/24/04	8337	10.70.229.4	Pricing						part found in lis, no price given 22 587 154336301 timer	part subs to 154351501 new part# pwr	1
3/24/04	8337	10.70.229.4	Pricing						part found in lis, no price given 46 106 2209551w white freezer door	PART SUBS TO 4388589	1



3/24/04	8337	10.70.229.4	DPA					MODEL# MGR5745ADA * PRT# 71003054 * DESCRIPTION SAYS: SET OF 4 - TAUPE. PER MFG * THIS IS ONLY ONE CAP PER ORDER* CUSTOMER NEEDS TO ORDER ACCORDINGLY.. THANKS DLO RESEARCH	WILL HAVE LAWSON REFLECT TO PURCHASE 4	3
---------	------	-------------	-----	--	--	--	--	--	---	---

DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/25/04	8087	10.70.229.4	Search						vac mod# 088150 needs to be in lis. thanks brenda/8087	requested from MFG	5
3/25/04	8337	10.70.229.6	Image	1428	124150	FED367DSA	R0309085	2	Cube # 1159 Ray Malkowski Jr. Mech Parts RR CC: Model # FED367DSA Page 2 of 6 Key# 141, Which is 141b from the Image? 3/23/2004	corrected	8
3/25/04	8393	10.70.229.6	Documents	1198	165000	ED25DQXYN01			I need a Black Shelf Cant for Refrigerator Model# ED25DQXYN01. Thanks NPSC	mdl# given is almond will need mdl# for blk	8
3/25/04	7127	10.70.229.6	Parts	247	1503320	247775870	10062218		Catcher Bag for this model part number 71 099 463-3036 per STAC. Please add to parts list for this item.	corrected	8
3/25/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 71 536 578924e701	PRT SUBS TO 578924 AND IS NLA	1
3/25/04	8337	10.70.229.4	DPA						part number not priced in lis part number correct in lis 46 596 12683802w	PRT SUBS TO 67003550	1
3/25/04	8010	10.70.229.4	DPA						71517a-04447 prices in LIS for 12.99- it has a 25.82 RPDC sell	need div/sce	6
3/25/04	8211	10.70.229.4	Parts	1339	744600	2708	10035133		to whom it may concern please put into lis parts list and image of makita table saw model 2703 thanks lisa at 8211	WILL BE AVAILABLE WITHIN 10 WORKING DAYS	5
3/25/04	7252	10.70.229.4	DPA						71/842 3045 IS NLA PER SOURCE, PLS UPDATE AT RPDC	need mdl# for stac research to confirm and submit change	2
3/25/04	8337	10.70.229.6	Image	582	130000	36316569790	L0207018	1	there is no parts list in image for this mod #. david webb ext 3466	requested from MFG	5

3/25/04	8337	10.70.229.3	DPA						RIDING TRACTOR TROYBUILT M#J609 PART 71 247 747-04146 SHIFT ROD LISTED IN LIS BUT NOT PRICING. PLEASE UPDATE.	submitted to stac research Ref# dli00345	1
3/25/04	8337	10.70.229.3	Models						PANASONIC MODEL SAXR25S WHEN SELECTED BRINGS UP SONY STRDE185 MANUAL	document listed is ML book will attempt to locate mdl service documents	3
3/25/04	8337	10.70.229.3	Models						SONY MODEL RCDW500C BRINGS UP MANUAL FOR SONY CDPCS355	document listed is ML book will attempt to locate mdl service documents	3
3/25/04	8337	10.70.229.3	Pricing						part found in lis, no price given 57 528 ph06891 speaker grille 61"	PRT # SUBS TO PH07421	1
3/25/04	8337	10.70.229.3	DPA						PLS CHECHK INTO THE WASH MOTOR SEAL KIT PART # 99002760 CHANGE TO 99002980IT IS PRICING AT 134.98	need div/sce	6
3/25/04	8337	10.70.229.3	Image	3048	153200	MAV8600AWW	M0402210	5	TECH SAYS WHEN ORDERING KEY 9 ON THE TRANS DO NOT GET KEY 26 WITH IT BOB STEELE EXT.14721	referred to STAC RESEARCH FOR BIN CHECK AT MFG SCR00553 (SO# 94596536)	8
3/25/04	8337	10.70.229.3	Pricing						part found in lis,no price given 71 917 18820 transmission assembly	prt# 18820 is invalid.. Prt# 188240 is valid . Please order pwr	1

3/25/04	8337	10.70.229.3	Search						The part number running in the system switches to - part number B1368042 that is the incorrect size for the squirrel cage blower - tech has gotten this part 2 times. - called Goodman and got the peoper part number and the proper - 10 in. x 10 in. Correct part number - B1368047Model number - GMPN1004Serial number- 9509803743Division 42Source 709	INVALID INFORMATION 047 IS PRT GIVEN ON LIS WHICH SUBS TO 042	8
3/25/04	8337	10.70.229.3	Pricing						part found in lis, no price given 09 351 17512.00 front trunnion brkt	part# valid. Please order pwr	1
3/25/04	8337	10.70.229.3	Pricing						part found in lis, no price given 46 106 2188371 timer,defrost	PRT SUBS TO 482493	1
3/25/04	8337	10.70.229.3	Pricing						part found in lis, no price given 71 500 31q777-0036	PRT IS 31Q777-0036E1	1
3/25/04	8037	10.70.229.3	Models						need info and parts on Troy built model # 020209 pressure washer.....8037	requested from MFG	5

DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/26/04	8337	10.70.229.4	Search						Model number: 165.155400 On parts list, it is not listing key number 14 from the image to give us a description. Caller was looking for the motor mounted in the base.	KEY 13 IS LISTED BUT IT'S A DECAL ON PAG 2 AND AN O-RING ON PG 1	8
3/26/04	8337	10.70.229.4	DPA						PLEASE CHECK PART # ON THIS MODEL RST310UWW. GRATE PART # IN SIMAGE IS 314651T AND IT SHOULD BE 314651Y	CORRECTED SOURCE	8
3/26/04	8337	10.70.229.6	DPA						model gew9200lw0 .Machine board 3980062 in our system is being subed with 8557308 according to angela at wp. t.johnson cube 2138	MDL GIVEN USE'S 3978918 WHICH SUBS TO 3980062	8
3/26/04	9277	10.70.229.6	DPA						71/358 53007166 oil vent kit does not price for model 358.350462	PRT IS 530071666 ORDER PWR	1
3/26/04	7194	10.70.229.6	Pricing						After calling STAC, Part Number 11 639 30426 should be changed into 11 369 DP30426,	CORRECTED	6
3/26/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 71 536 001x92	PRT IS 1X92	1
3/26/04	8087	10.70.229.6	Models						VAC MOD# U4617-920 NEEDS TO IN LIS.THANKS,BRENDA/8087	REQUESTED FROM MFG	5
3/26/04	8337	10.70.229.6	DPA						PANASONIC HDTV MODEL PT-47WX49E PART 57 528 TNPA2033 HD-BOARD LISTED IN LIS BUT NOT PRICING PLEASE UPDATE.	PRT# SUB TO TNPA2033S	1

3/26/04	8337	10.70.229.6	DPA						MODEL #253.9239711--PART #FOR THE LIGHT SWITCH COMES UP 5309918896-- WHICH ISN'T A GOOD #. CORRECT PART IS SUPPOSED TO BE 5309918806--IT GIVES THE INCORRECT PART # FOR MODELS W/A 1, 2, AND 3 ON THE END. MODEL # W/A 4-- ON THE END IS CORRECT.	CORRECTED	3
3/26/04	9276	10.70.229.6	Pricing						20 020 5218 that is suggested by lis to use in place of Kc28sbztz000 is actually an old style belt that will not work on this unit	NEED MDL# TO CONFIRM	6
3/26/04	8337	10.70.229.6	Pricing						tiller model #9172994270 part 71 917 188240 transmission listed in lis but not pricing. please reupdate the system.	part# valid. Please order pwr	1
3/26/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 26 464 22004191	PRT SUSB TO 22004333	1
3/26/04	8337	10.70.229.6	Pricing						kenmore m#110.74632300 part 26 110 8538262 motor listed in lis but not pricing. please update the system.	PRT SUBS TO 279827	1
3/26/04	8231	10.70.229.4	DPA						on the cord reel 20-116-8175265--ratchet pawls or in the unit preventing thereford not needing a brake--it is not right for the vacuum it goes into---please correct this sue frankovich 8231 submitted 03-26-04	NEED MDL# FOR STAC RESEARCH	6
3/26/04	8337	10.70.229.4	Pricing						part found in lis, no price given 46 106 2255934lb freexer door	PRT IS L2255934LB	1
3/26/04	8337	10.70.229.4	Pricing				0326		part found in lis, no price given 22 664 487939 nut	PRICING FROM SOURCE AND DIV 46/106	1

3/26/04	8337	10.70.229.4	Pricing					part found in lis, no price given 46 363 wr60x157 motor cond fan	PRT IS WR60X0157	1
3/26/04	8707	10.70.229.6	Pricing					FOR MODEL #890 - RYOBI TRIMMER - PART NUMBER UPDATE - From Part List Diagram pg #1 key #34 - Fuel Tank Assy. - p/n - 71/316 - 753- 04085 - LIS shows as "Part Number Not Found" From an RPR to Fidelitone the correct p/n is - 791-182355...Please make corrections to model....Thanks....PS8707P	PART # VALID ORDER PWR	8
3/26/04	8153	10.70.229.3	Search					At 8153 we have had a couple of craftsman air compressors with the model number 19551. We were inquiring if there is any information about this unit that can be placed on LIS. Thank you JSteele8153	REQUESTED FROM MFG	5
3/26/04	8171	10.70.229.3	DPA					For model number 415.15650 Kenmore Gas Grill the part number for the hose, regulator, valve assembly is incorrect. The part number prices to a burner assembly. Need to find out what exactly is the part number and get this corrected if at all possible.	CORRECTED	8

3/26/04	8295	10.70.229.3	DPA						FOR MODEL 3 3631499580 ON THE CABINET AND DOOR DISPLAY PART 711 DOOR & HINGE ASM OUTER PRICES AS A SCREW WD3M62 PLZ MAKE CORRECTION THANKS SHIRLEY AT UNIT 8295	REFERRED TO STAC RESEARCH REFERENCE SCR00554	8
3/26/04	8037	10.70.229.3	DPA						Sewing machine 385.19010200 Part number 832523007 shows picture of foot and shank combined. Our parts bin has only foot in package without shank. Is problem with our parts or yours? Need foot and shank both together as illustrated for that part number. Page 4 of 11, item number 20 on LIS. Thanks.	NEED SO#S FOR SOURCE BIN CHECK	8
3/26/04	8337	10.70.229.3	Pricing						For model WS65413 the part number is incorrectly stated as 260P117010. It should be corrected to read 290P117010. It is correct in the service manual but incorrect in document type parts list.....STAC Tom Morrow	CORRECTED	3
3/26/04	8337	10.70.229.3	Pricing						part found in lis, no price given 71 917 174333x599 lens, grille	REFERRED TO STAC RESEARCH REFERENCE SCR00555	1
3/26/04	8337	10.70.229.3	Pricing						part found in lis, no price given 42 106 1185523 filter	PRICING FROM DIV 46	1
3/26/04	8337	10.70.229.3	Pricing						part found in lis, no price given 22 628 5304423492 thermostat	PRT IS VALID ORDER PWR	1



3/26/04	8337	10.70.229.3	Pricing						part found in lis, no price given 22 464 74008702 latch assembly	PART IS VALID ORDER PWR	1
3/26/04	8337	10.70.229.3	Pricing						part found in lis, no price given 71 501 pa-cv740s-0016 replacement engine	PRT SUBS TO PA-CV7400018	1
3/26/04	8337	10.70.229.3	Pricing						part found in lis, no price given 71 500 123332-0036 replacement engine	prt subs to 123332-0036e1	1
3/26/04	8337	10.70.229.3	Pricing						part found in lis, no price given 22 628 316233860 panel,backquard,black	part# valid. Please order pwr	1
3/26/04	8337	10.70.229.3	Pricing						part found in lis, no price given 71 917 188975 bar,drive control	part# subs to 188952x428	1
3/26/04	8337	10.70.229.3	Pricing						part found in lis, no price given 42 565 ep200a/pmpm651 pump assembly 115v	NEED MODEL#	1
3/26/04	8337	10.70.229.3	Documents	3048	151200	MDE4057AYW			No manual/no warranty info included in system	REQUESTED FROM MFG	5
3/26/04	8116	10.70.229.3	Image	247	1503500	143986502	L0203124	1	Model no. 917-387282 Engine no. 143-996000 Should be included in the SF71- 423 to replace the carb. It has the white cap on the pilot screw.	MDL GIVEN IS NOT INCLUDED WITH THIS SF	8
3/26/04	8707	10.70.229.3	Models						REQUEST TO ADD MODEL TO LIS DATABASE - INGERSOLL-RAND IMPACT WRENCH MODEL #231H.....Thanks.....PS8707P	REQUESTED FROM MFG	5
3/26/04	7464	10.70.229.3	DPA						change source number for caloric dishwasher is now 587	NEED MDL#	6
3/26/04	7999	10.70.229.3	Pricing						part number for manual not in system takes to long to print off 79 pages	NEED MDL#	6
3/26/04	8084	10.70.229.4	Image	909	1503820	825R	L0403328	1	how come we suddenly don't get a picture breakdown anymore???????	WILL BE AVAILABLE WITHIN 10 WORKING DAYS	5

DATE	UNIT	LOCATION	TAB	BRAND	PRODUCT	MODEL	DOC ID	PG	COMMENT	ACTION	CODE
3/29/04	8337	10.70.229.6	DPA						2nd request!! pump/motor complete original part wd26x79 subs in system to wd21x10032 jump harness with no mention of the motor pt# wd26x10013, mdl# gsd4230x65ww. parts price out of 22/3663, info from linda at ge. thanks div 22	corrected	8
3/29/04	8248	10.70.229.6	Image	1268	166000	TP21A3W-P1181503VWV	I2204568	2	ther is no number 31 for screws	corrected	3
3/29/04	8337	10.70.229.4	Image	582	161000	59672283202	M0306277	1	key num 27 nameplate on ff door missing in parts list...	REFERRED TO STAC RESEARCH SCR00557	8
3/29/04	8337	10.70.229.4	DPA						PART 4681A20027B MOTOR IS WRONG. (MODEL 580.71122100) FOUND OWNERS MANUAL AND IT SHOWS A 4681A20027H. PER TECH 3624 CHUCK FROM UNIT 8344. CHUCK WILL ORDER IT.I ASKED CHUCK TO CALL US BACK WHEN CONFIRMS THAT MOTOR DOES FIT.RAY EXT 3219 CUBE 2149	corrected	8
3/29/04	8337	10.70.229.4	DPA						part is correct in LIS, but no price available 22 364 wb56t10161 given by tech pwr	part # valid please order pwr	1
3/29/04	8337	10.70.229.4	DPA						part # is listed in lis but no price given 46 106 2209551w	PART SUBS TO 4388589	1
3/29/04	8337	10.70.229.4	Image	432	124002	JGBP34GEP3	E2103198	1	please look into model #jgbp34gep3 the part list is the same for a four pages	SCROLL DOWN TO KEY# NEEDED	3

3/29/04	8337	10.70.229.4	DPA						MODEL R-530AW. PART # FOR THE UNIT CONTROL COMES UP CPWBFB005MRUO--THE LETTER --O-- ON THE END NEEDS TO BE NUMBER --0-- ON THE END. OTHERWISE IT DOESN'T PRICE IN OUR SYSTEM. THANKS.	corrected	3
3/29/04	8337	10.70.229.4	Pricing						part found in lis, no price given 22 575 dpwbfb081mru0 control pcb assy	PRT SUBS TO 46-356723-3	1
3/29/04	8337	10.70.229.4	Pricing						part found in lis, no price given 57 528 a68agd01x picture tube	PRT PRICING FORM SOURCE 060	1
3/29/04	8337	10.70.229.4	Pricing						part found in lis, no price given 26 417 131825500 idler arm	part# subs to 131862900	1
3/29/04	8337	10.70.229.4	DPA						MODEL #KHMS155LSS0--GIVE 2 PART #S FOR STAINLESS STEEL DOOR FRAMES. CHECKED OUT LIBRARY FILE AND PART #8184319--IS STAINLESS AND PART #8184744 IS SUPPOSED TO BISCUIT. BOTH NOT STAINLESS PART #S. THANKS.	corrected	3
3/29/04	8027	10.70.229.6	Image	3199	1503220	55RANCHER	P0403728	1	there is a page missing from this 55rancher it would be letters E & F please email me and let me know when this will be fixed thill17@sears.com thank you Tori Hill	WILL BE CORRECTED	3
3/29/04	8337	10.70.229.6	DPA						part # is listed in lis but no price given 22 628 5304429448	part# valid. Please order pwr	1

3/29/04	8337	10.70.229.6	DPA					part # is listed in lis but no price given 22 628 5303305345	PRT SUBS TO 5303321321	1
3/29/04	8337	10.70.229.6	DPA					part # is listed in lis but no price given 71 500 31q777-0036	31Q777-0036E1	1
3/29/04	8707	10.70.229.6	Pricing					FOR MODEL #DW954TY2 - PART NUMBER UPDATE - From the Parts List Diagram Key #48 - Clutch Mech Assy. - p/n - 09/900 - 385306-00. From an RPR to Fidelitone the correct p/n for the Type 2 model is - 09/900 - 391106-13. Please make corrections to model.. Thanks...PS8707P	referred to stac research to confirm ref# DLL00368	8
3/29/04	8337	10.70.229.6	DPA					part # is listed in lis but no price given 22 335 0088874	PRT SUBS TO 07455200	1
3/29/04	8337	10.70.229.6	DPA					part # is listed in lis but no price given 57 528 862281011377	PRT SUBS TO 483531057599	1
3/29/04	8393	10.70.229.6	Pricing					per "katrina " at ge wr57x98 subs to wr57x10051 water valve asm	NEED MDL # TO REEFER TO STAC RESEARCH	6
3/29/04	9650	10.70.229.6	DPA					LIS 2 Team,I need to confirm the price of the motor for a Kitchenaid ventilation system. The entire system costed about \$450.00,but the motor alone costs \$1442.49. Is the assembly supposed to come with a motor?Model number: KPEC992MSS Motor--Fan #: 22 664 8190604 Contact Aaron or Nancy (Unit 9650) @ (815) 484-0088 between 8am and 6pm Mon-Fri Mailing Address: 1888 Daimler Rd Rockford, Il 61112	pricing has been confirmed	2

3/29/04	7999	10.70.229.3	DPA						the part # for the lid #5 on breakdown does not work in the system and if you look on the microfiche it is a totally different part# 22 629 22002871 and this does work, thanx	need mdl#	6
3/29/04	9276	10.70.229.3	DPA						LIS HAS WRONG PART # LISTED FOR TRUSS HEAD ROUND NECK SCREW. CORRECT PART # IS 09-137-2642BDDA25 NOT 09-137-2842BDDA25. PLEASE CORRECT INFO IN LIS. THANK YOU.	need mdl#	6
3/29/04	9277	10.70.229.3	DPA						71 144 km-11029-7010 (filter) and 71 144 km-bpr5es (plug) are in lis but no price listed for kawasaki engines along with other with other parts. thank you bbb	wtng confirmation from source	1
3/29/04	8337	10.70.229.3	Image	582	153200	11020092993	L0040001	3	page 3 of tech sheet says WH/VL is med speed, on page 6 says BU is med speed. which one is right, david webb ext 3466.	wtng answer from STAC Techs	7
3/29/04	7464	10.70.229.3	DPA						PER FRIGIDAIRE MODEL# 790.46373401 THE CORRECT BAKE ELEMENT IS PART# 22-628-318255400 PRICING COMES UP IN LIS . THE INFO FOR THIS MODEL IN LIS IS INCORRECT SHOWING PT# 22-628-318110500 WITH NO PRICING. PLEASE CHECK INTO THIS PROBLEM WITH LIS. PS7464S/BARBARA	referred to stac research ref# DLL00369	8

3/29/04	8171	10.70.229.4	DPA					There is a small glitch in the pricing system. Model # 917.377582 pump for this unit 71 917 153769 prices at \$1,407.39 Need to know what the actual price for this part is.	pricing has been confirmed	2
3/29/04	8270	10.70.229.4	DPA					PLEASE LOOK AT MODEL NUMBER 417.99370830. THE TOP PANEL HAS BEEN SUBSTITUTED, HOWEVER THE GROMMET THAT SHOULD GO WITH THE SUBSTITUTION DOES NOT CHANGE. THE ORIGINAL GROMMET IS 26/417/3204362 AND SHOULD BE SUBSTITUTED TO 26/417/5303208743. PLEASE MAKE THE CHANGES AND EMAIL MWITULS@SEARS.COM WHEN COMPLETED.THANKSMELIS SA WITULSKI	referred to stac research to confirm ref# DLL00370	8