

GEICO
GEICO San Diego
Request a supplement at
partners.geico.com
PO BOX 509060
San Diego, CA 92150

Claim #: 0653123010101013-01
Workfile ID: 1c7242ec

Supplement of Record 1 Summary

Written By: JAMES DARCY, 1/15/2021 2:39:59 PM
Adjuster: A4SD

Insured: Danielle Wilson Owner Policy #: 4580927921 Claim #: 0653123010101013-01
Type of Loss: Collision Date of Loss: 11/11/2020 08:30 AM Days to Repair: 2
Point of Impact: 06 Rear Deductible: 500.00

Owner (Insured): Danielle Wilson
164 Seacountry Ln
Rcho Sta Marg, CA 92688
(949) 633-6857 Evening
(949) 910-2754 Cellular

Inspection Location: Prestige Auto Collision
Prestige Auto Collision
23720 VIA FABRICANTE
MISSION VIEJO, CA 92691
Drive-in
(949) 581-3702 Day

Appraiser Information: (949) 353-4144

Repair Facility: CALIBER COLLISION - RSM
23251 Antonio Pkwy
Rancho Santa Margari, CA 92688
(949) 888-8260 Business
330730794 Federal ID
33-0730794 License Number

VEHICLE

2004 TOYO Sequoia Limited 4D UTV 8-4.7L Gasoline SFI GREY

VIN: 5TDZT38A24S229926 Production Date:
License: 6WGX429 Odometer: 198219 Interior Color:
State: CA Condition: Exterior Color: GREY

TRANSMISSION	TRACTION CONTROL	PASSENGER AIR BAG	REAR CONVENIENCE
AUTOMATIC TRANSMISSION	STABILITY CONTROL	PAINT	DUAL AIR CONDITIONING
OVERDRIVE	ALARM	CLEARCOAT PAINT	DECOR
DRIVER CONVENIENCE	AIR CONDITIONING	FRONT END	LUGGAGE/ROOF RACK
KEYLESS ENTRY	CLIMATE CONTROL	FOG LAMPS	BODY SIDE MOLDINGS
MESSAGE CENTER	REAR DEFOGGER	CALIFORNIA EMISSIONS	RUNNING BOARDS/SIDE STEPS
POWER DRIVER SEAT	RADIO	POWER STEERING	REAR END
POWER WINDOWS	AM RADIO	POWER BRAKES	REAR WINDOW WIPER
POWER LOCKS	FM RADIO	ANTI-LOCK BRAKES (4)	WHEELS
POWER MIRRORS	STEREO	GLASS & MIRRORS	4-WHEEL DISC BRAKES
HEATED MIRRORS	SEARCH/SEEK	DUAL MIRRORS	ALUMINUM/ALLOY WHEELS
CRUISE CONTROL	CD PLAYER	PRIVACY GLASS	TRUCK & TOWING
INTERMITTENT WIPERS	CASSETTE	SEATS	REAR STEP BUMPER
TILT WHEEL	PREMIUM RADIO	LEATHER SEATS	TRAILER HITCH
STEERING WHEEL TOUCH CONTROLS	ROOF	POWER PASSENGER SEAT	TRAILERING PACKAGE
CONSOLE/STORAGE	ELECTRIC GLASS ROOF	HEATED SEATS	
HOME LINK	SAFETY	3RD ROW SEAT	

Supplement of Record 1 Summary

2004 TOYO Sequoia Limited 4D UTV 8-4.7L Gasoline SFI GREY

INSTRUMENT PANEL

DRIVERS SIDE AIR BAG

CAPTAIN CHAIRS (2)

Supplement of Record 1 Summary

2004 TOYO Sequoia Limited 4D UTV 8-4.7L Gasoline SFI GREY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		QUARTER PANEL					
2	* S01 Rpr	LT Quarter panel w/o molding	616120C021	0	0.00	2.0	1.0
3	S01	Add for Clear Coat		0	0.00	0.0	0.4
4	S01 Repl	Vent louver	62940AA012	1	46.83	0.2	0.0
5		REAR BODY & FLOOR					
6	* S01 Rpr	Panel below gate	583020C011	0	0.00	3.5	1.0
7	S01	Overlap Major Adj. Panel		0	0.00	0.0	-0.4
8	* S01	Add for Clear Coat		0	0.00	0.0	0.0
9		<u>REAR BUMPER</u>					
10	S01	O/H bumper assy	NONE	0	0.00	1.8	0.0
11	** Repl	Non OEM Bumper cover w/o flare	P28981	1	248.75	Incl.	3.0
12		Add for Clear Coat		0	0.00	0.0	1.2
13	Repl	LT Reflector	819200C010	1	47.58	Incl.	0.0
14	* R&I	RT Reflector	819100C010	0	0.00	Incl.	0.0
15	S01 Repl	LT Bracket	5219716020	1	2.24	Incl.	0.0
16	S01 Repl	LT Guide	5218745010	1	3.05	Incl.	0.0
17		VEHICLE DIAGNOSTICS					
18	* S01 Repl	Post-repair scan		1	0.00 X m	0.5	0.0
		NOTE: SUBLET COST TO BE UPDATED WHEN INVOICES ARE PROVIDED.					
		SHOP SUBLETTING OUT REMOTE SCANNING AND DTC DIAGNOSIS SERVICE BUT CONNECTING TOOL THEMSELVES.					
19	* S01 Repl	Pre-repair scan		1	0.00 X m	0.5	0.0
		NOTE: SUBLET COST TO BE UPDATED WHEN INVOICES ARE PROVIDED.					
		SHOP SUBLETTING OUT REMOTE SCANNING AND DTC DIAGNOSIS SERVICE BUT CONNECTING TOOL THEMSELVES.					
20		MISCELLANEOUS OPERATIONS					
21	#	AGREEMENT REACHED		1	0.00	0.0	0.0
22	#	FLEX ADDITIVE		1	5.00 T	0.0	0.0
23	# S01	RESTORE CORROSION PROTECTION		1	12.00	0.3	0.0
24	# S01 Rpr	COLOR MATCH		0	0.00	0.0	0.5
25		OTHER CHARGES					
26	#	E.P.C.		1	3.00		
SUBTOTALS					368.45	8.8	6.7

NOTES

Estimate Notes:

The labor rate utilized to complete your estimate is the (agreed rate or prevailing rate) for your area. This was determined by utilizing the closest auto body shop to your residence address which is, CALIBER COLLISION CENTERS 23251 ANTONIO PARKWAY RANCHO SANTA MARGARITA, CA 92688

Prior Damage Notes:

Supplement of Record 1 Summary

2004 TOYO Sequoia Limited 4D UTV 8-4.7L Gasoline SFI GREY

REAR BUMPER-SCRATCHES AND CHIPPED
 FRONT BUMPER-SCRATCHES

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			360.45
Body Labor	8.8 hrs @	\$ 56.45 /hr	496.76
Paint Labor	6.7 hrs @	\$ 54.43 /hr	364.68
Paint Supplies	6.7 hrs @	\$ 40.00 /hr	268.00
Miscellaneous			5.00
Other Charges			3.00
Subtotal			1,497.89
Sales Tax	\$ 633.45 @	7.7500 %	49.09
Total Cost of Repairs			1,546.98
Deductible			500.00
Total Adjustments			500.00
Net Cost of Repairs			1,046.98

Supplement of Record 1 Summary

2004 TOYO Sequoia Limited 4D UTV 8-4.7L Gasoline SFI GREY

SUPPLEMENT SUMMARY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Changed Items							
1	**	Repl Non OEM Bumper cover w/o flare	P28981	1	-248.75	-1.3	-3.0
11	**	S01 Repl Non OEM Bumper cover w/o flare	P28981	1	248.75	Incl.	3.0
3		Repl LT Reflector	819200C010	1	-47.58	-0.1	0.0
13		S01 Repl LT Reflector	819200C010	1	47.58	Incl.	0.0
4	*	R&I RT Reflector	819100C010	0	0.00	<u>-0.1</u>	0.0
14	*	S01 R&I RT Reflector	819100C010	0	0.00	<u>Incl.</u>	0.0
Added Items							
1		QUARTER PANEL					
2	*	S01 Rpr LT Quarter panel w/o molding	616120C021	0	0.00	<u>2.0</u>	<u>1.0</u>
3		S01 Add for Clear Coat		0	0.00	0.0	0.4
4		S01 Repl Vent louver	62940AA012	1	46.83	0.2	0.0
5		REAR BODY & FLOOR					
6	*	S01 Rpr Panel below gate	583020C011	0	0.00	<u>3.5</u>	<u>1.0</u>
7		S01 Overlap Major Adj. Panel		0	0.00	0.0	-0.4
8	*	S01 Add for Clear Coat		0	0.00	0.0	<u>0.0</u>
10		S01 O/H bumper assy	NONE	0	0.00	1.8	0.0
15		S01 Repl LT Bracket	5219716020	1	2.24	Incl.	0.0
16		S01 Repl LT Guide	5218745010	1	3.05	Incl.	0.0
17		VEHICLE DIAGNOSTICS					
18	*	S01 Repl Post-repair scan		1	0.00 X m	<u>0.5</u>	0.0
		NOTE: SUBLET COST TO BE UPDATED WHEN INVOICES ARE PROVIDED.					
		SHOP SUBLETTING OUT REMOTE SCANNING AND DTC DIAGNOSIS SERVICE BUT CONNECTING TOOL THEMSELVES.					
19	*	S01 Repl Pre-repair scan		1	0.00 X m	<u>0.5</u>	0.0
		NOTE: SUBLET COST TO BE UPDATED WHEN INVOICES ARE PROVIDED.					
		SHOP SUBLETTING OUT REMOTE SCANNING AND DTC DIAGNOSIS SERVICE BUT CONNECTING TOOL THEMSELVES.					
23	#	S01 RESTORE CORROSION PROTECTION		1	12.00	0.3	0.0
24	#	S01 Rpr COLOR MATCH		0	0.00	0.0	0.5
SUBTOTALS					64.12	7.3	2.5

NOTES

Estimate Notes:

The labor rate utilized to complete your estimate is the (agreed rate or prevailing rate) for your area. This was determined by utilizing the closest auto body shop to your residence address which is, CALIBER COLLISION CENTERS 23251 ANTONIO PARKWAY RANCHO SANTA MARGARITA, CA 92688

Prior Damage Notes:

REAR BUMPER-SCRATCHES AND CHIPPED

Supplement of Record 1 Summary

2004 TOYO Sequoia Limited 4D UTV 8-4.7L Gasoline SFI GREY

FRONT BUMPER-SCRATCHES

TOTALS SUMMARY

Category	Basis	Rate	Cost \$
Parts			64.12
Body Labor	8.8 hrs @	\$ 56.45 /hr	496.76
Paint Labor	2.5 hrs @	\$ 54.43 /hr	136.08
Additional Supplement Labor			-84.69
Paint Supplies	2.5 hrs @	\$ 40.00 /hr	100.00
Subtotal			712.27
Sales Tax	\$ 164.12 @	7.7500 %	12.72
Total Supplement Amount			724.99
NET COST OF SUPPLEMENT			724.99

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate	821.99	JAMES DARCY
Supplement S01	724.99	JAMES DARCY
Workfile Total:	\$ 1,546.98	
TOTAL ADJUSTMENTS:	\$ 500.00	
NET COST OF REPAIRS:	\$ 1,046.98	

This is not an authorization to repair.

All GEICO customers have the right to have their vehicle repaired in the shop of their choice.

No Supplement will be honored unless authorized by GEICO.

NOTICE: Vehicles constructed of special metals may require the use of specialized welding and bonding equipment. Proper measuring and structural repair systems are required on today's vehicle to accurately accomplish vehicle repairs. Make sure your shop has the proper equipment to repair your vehicle.

ALTERNATE PARTS DISCLAIMER:

IF A QUALITY REPLACEMENT PART (A/M, LKQ, RECOND OR OPT OEM) APPEARS ON THIS ESTIMATE, IT INDICATES THAT THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. GUARANTEES, IF ANY, APPLICABLE TO THESE REPLACEMENT CRASH PARTS ARE PROVIDED BY THE PART MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.

***IN ADDITION TO ANY SUCH GUARANTEES, GEICO PROVIDES THE FOLLOWING:

****OWNER LIMITED GUARANTEE**** WE GUARANTEE THAT ALL QUALITY REPLACEMENT BODY PARTS (PARTS NOT MANUFACTURED BY THE MANUFACTURER) IDENTIFIED ON YOUR ESTIMATE, ARE FREE OF DEFECTS IN MATERIAL AND WORKMANSHIP AND MEET GENERALLY ACCEPTED INDUSTRY STANDARDS. THIS PARTS AND LABOR GUARANTEE WILL BE IN EFFECT FOR AS LONG AS YOU OWN THE VEHICLE DESCRIBED IN THE ESTIMATE.

Supplement of Record 1 Summary

2004 TOYO Sequoia Limited 4D UTV 8-4.7L Gasoline SFI GREY

THIS GUARANTEE COVERS THE COST OF THE PART, LABOR TO INSTALL, AND INCIDENTALS SUCH AS PAINT AND MATERIALS AND IS SPECIFICALLY LIMITED TO THOSE ITEMS. THIS GUARANTEE DOES NOT COVER LOSS OR DAMAGE THAT IS UNRELATED TO DEFECTS IN THE QUALITY REPLACEMENT PARTS. THIS IS NOT TRANSFERABLE. IF ANY QUALITY REPLACEMENT PARTS ARE DEFECTIVE IN EITHER MATERIAL OR WORKMANSHIP, CONTACT YOUR LOCAL GEICO REPRESENTATIVE.

FOR YOUR PROTECTION CALIFORNIA LAW REQUIRES THE FOLLOWING TO APPEAR ON THIS FORM: ANY PERSON WHO KNOWINGLY PRESENTS FALSE OR FRAUDULENT CLAIM FOR THE PAYMENT OF A LOSS IS GUILTY OF A CRIME AND MAY BE SUBJECT TO FINES AND CONFINEMENT IN STATE PRISON.

THE FOLLOWING IS A LIST OF ABBREVIATIONS OR SYMBOLS THAT MAY BE USED TO DESCRIBE WORK TO BE DONE OR PARTS TO BE REPAIRED OR REPLACED:

MOTOR ABBREVIATIONS/SYMBOLS: D=DISCONTINUED PART, A=APPROXIMATE PRICE. LABOR TYPES: B=BODY LABOR, D=DIAGNOSTIC, E=ELECTRICAL, F=FRAME, G=GLASS, M=MECHANICAL, P=PAINT LABOR, S=STRUCTURAL, T=TAXED MISCELLANEOUS, X=NON TAXED MISCELLANEOUS. CCC ONE: ADJ=ADJACENT, ALGN=ALIGN, A/M=AFTERMARKET, BLND=BLEND, CAPA=CERTIFIED AUTOMOTIVE PARTS ASSOCIATION, D&R=DISCONNECT AND RECONNECT, EST=ESTIMATE, EXT. PRICE=UNIT PRICE MULTIPLIED BY THE QUANTITY, INCL=INCLUDED, MISC=MISCELLANEOUS, NAGS=NATIONAL AUTO GLASS SPECIFICATIONS, NON-ADJ=NON ADJACENT, O/H=OVERHAUL, OP=OPERATION, NO=LINE NUMBER, QTY=QUANTITY, RECOND=RECONDITION, REFN=REFINISH, REPL=REPLACE, R&I=REMOVE AND INSTALL, R&R=REMOVE AND REPLACE, RPR=REPAIR, RT=RIGHT, SECT=SECTION, SUBL=SUBLET, LT=LEFT, W/O=WITHOUT, W/_=WITH/_ SYMBOLS: #=MANUAL LINE ENTRY, *=OTHER [IE..MOTORS DATABASE INFORMATION WAS CHANGED], **=DATABASE LINE WITH AFTERMARKET, N=NOTES ATTACHED TO LINE. OPT OEM=ORIGINAL EQUIPMENT MANUFACTURER PARTS EITHER OPTIONALLY SOURCED OR OTHERWISE PROVIDED WITH SOME UNIQUE PRICING OR DISCOUNT.

"CURE TIME" MEANS THE LENGTH OF TIME THAT, PER THE ADHESIVE MANUFACTURER, THE WINDSHIELD ADHESIVE NEEDS TO CURE UNTIL THE WINDSHIELD CAN PROPERLY FUNCTION AS A SAFETY DEVICE PURSUANT TO THE FEDERAL MOTOR VEHICLE SAFETY STANDARDS AND THE VEHICLE MANUFACTURER'S SPECIFICATIONS.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE PARTS, RATHER THAN BY THE ORIGINAL MANUFACTURER OF YOUR VEHICLE.

Supplement of Record 1 Summary

2004 TOYO Sequoia Limited 4D UTV 8-4.7L Gasoline SFI GREY

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide AEM8431, CCC Data Date 01/11/2021, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2021 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Supplement of Record 1 Summary

2004 TOYO Sequoia Limited 4D UTV 8-4.7L Gasoline SFI GREY

WE WARRANT THAT ALL PARTS USED IN THE REPAIR OF THIS VEHICLE ARE EQUAL TO THE ORIGINAL EQUIPMENT MANUFACTURER PARTS IN TERMS OF KIND, QUALITY, SAFETY, FIT AND PERFORMANCE. THIS PARTS AND LABOR WARRANTY WILL BE IN EFFECT FOR AS LONG AS YOU OWN THE VEHICLE DESCRIBED IN THE ESTIMATE. THIS WARRANTY COVERS THE COST ASSOCIATED WITH RETURNING THE PART AND THE COST TO REMOVE AND REPLACE THE NON-ORIGINAL EQUIPMENT MANUFACTURER PART WITH A COMPLIANT NON-ORIGINAL EQUIPMENT PART OR AN ORIGINAL EQUIPMENT MANUFACTURER PART. THIS WARRANTY DOES NOT COVER LOSS OR DAMAGE THAT IS UNRELATED TO DEFECTS IN THE QUALITY REPLACEMENT PARTS. THIS WARRANTY IS NOT TRANSFERABLE. IF ANY QUALITY REPLACEMENT PARTS ARE DEFECTIVE IN EITHER MATERIAL OR WORKMANSHIP, YOU MUST CONTACT YOUR LOCAL GEICO REPRESENTATIVE.

If a customer subsequently chooses a repair shop, GEICO shall prepare a supplement using the prevailing rate in the Geographic Area of the customer's chosen shop.

This is not an authorization to repair. The undersigned repair facility is in agreement to the estimate prepared by GEICO in the amount of \$_____. No supplements will be honored by GEICO without prior approval.

Signed: _____

Print Name: _____

Date: _____

We are required under sect 2695.7(b) of the Unfair Claims Settlement Practices Regulations to provide the following notice: If you believe that your claim has been wrongfully denied or rejected, you also have the right to have the California Department of Insurance review this matter. The Department of Insurance is located at 300 South Spring Street, Los Angeles, CA 90013, telephone number (800) 927-4357.

Supplement of Record 1 Summary

2004 TOYO Sequoia Limited 4D UTV 8-4.7L Gasoline SFI GREY

ALTERNATE PARTS SUPPLIERS

Line	Supplier	Description	Price
11	Pacific Auto Company Orange Alonzo Rivera 1936 W. BUSINESS CENTER DRIVE ORANGE CA 92867 (800) 698-8181	#P28981 Non OEM Bumper cover w/o flare	\$ 248.75

Supplement of Record 1 Summary

2004 TOYO Sequoia Limited 4D UTV 8-4.7L Gasoline SFI GREY

RECALL INFO

2004 TOYO Sequoia Limited 4D UTV 8-4.7L Gasoline SFI GREY

VIN:	5TDZT38A24S229926	Production Date:		Interior Color:	
License:	6WGX429	Odometer:	198219	Exterior Color:	GREY
State:	CA	Condition:			

The National Highway Transportation and Safety Administration (NHTSA) has issued 5 safety-related recall notice(s) that may apply to the selected vehicle.

NHTSA ID: 18V883000 Issued: Dec 12, 18 Number of Vehicles: 00169481

AIR BAGS Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2002-2005 Lexus SC and Toyota Sequoia, 2003-2005 Toyota Corolla and Tundra, and 2003-2007 Pontiac Vibe vehicles. These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation. An inflator explosion may result in sharp metal fragments striking the driver or other occupants resulting in serious injury or death. Toyota will notify the Toyota and Lexus owners. General Motors will notify the Pontiac Vibe owners. Depending on the vehicle model, dealers will replace the front passenger air bag inflator with an alternate inflator, or replace the air bag assembly that includes an alternate inflator, free of charge. The recall is expected to begin January 14, 2019. Owners may contact Toyota customer service at 1-888-270-9371, Lexus customer service at 1-800-255-3987 or Pontiac customer service at 1-800-762-2737. Toyota's numbers for these recalls are J0A (Zone A Toyota), J0B (Zone B Toyota), J0C (Zone C Toyota), JLI (Zone A Lexus), JLJ (Zone B Lexus), and JLK (Zone C Lexus). Note: This recall includes vehicles that have had their air bag previously replaced under an earlier air bag campaign.

NHTSA ID: 15V285000 Issued: May 5, 15 Number of Vehicles: 00176631

AIR BAGS Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain model year 2004 Sequoia vehicles manufactured August 18, 2003, to August 19, 2004, and 2003-2004 Tundra vehicles manufactured March 18, 2003, to August 25, 2004 to address a safety defect in the passenger side frontal air bag inflator which may produce excessive internal pressure causing the inflator to rupture upon deployment of the air bag. This recall addresses both the passenger side frontal air bags that were originally installed in the vehicles, as well as replacement air bags that may have been installed as replacement service parts. A replacement air bag may have been installed, as one example, if a vehicle had been in a crash necessitating the replacement of the passenger side frontal air bag. In the event of a crash necessitating deployment of the front passenger's frontal air bag, the inflator could rupture with metal fragments striking and potentially seriously injuring the passenger seat occupant or other occupants. Toyota will notify owners, and dealers will replace the front passenger air bag. The manufacturer has not yet provided a notification schedule. Owners may contact Toyota customer service at 1-800-331-4331. NOTE: This recall is an expansion of 14V-312.

NHTSA ID: 14V655000 Issued: Oct 10, 14 Number of Vehicles: 00247000

AIR BAGS Toyota Motor Engineering and Manufacturing (Toyota) is recalling certain model year 2002-2005 Lexus SC and Toyota Sequoia and 2003-2005 Toyota Tundra, Corolla, Corolla Matrix and Pontiac Vibe vehicles that were originally sold, or are currently registered, in high absolute humidity areas of southern Florida, along the Gulf Coast, Puerto Rico, Hawaii, the U.S. Virgin Islands, Guam, Saipan and American Samoa. The inflators in the front passenger air bags are susceptible to rupture in the event of a crash necessitating the deployment of the front passenger air bag. In the event of a crash necessitating deployment of the front passenger's frontal air bag, the inflator could rupture with metal fragments striking and potentially seriously injuring the passenger seat occupant or other occupants. Toyota will notify owners of affected Toyota and Lexus vehicles and General Motors will notify owners of affected Pontiac Vibe vehicles. Toyota, Lexus, and GM dealers will replace the passenger side air bag inflator, free of charge. If a replacement inflator is not available, as an interim measure, the dealer will disable the front passenger air bag and advise the customer not to use the front passenger seat until a replacement inflator is installed. Toyota will begin its owner notification and remedy of the affected Toyota and Lexus vehicles on or around October 25, 2014. Details on GM's notification and remedy schedule are pending. Owners may contact Toyota customer service at 1-800-331-4331. Pontiac Vibe owners may contact GM at 1-800-521-7300.

NHTSA ID: 14V312000 Issued: Jun 6, 14 Number of Vehicles: 00844277

Supplement of Record 1 Summary

2004 TOYO Sequoia Limited 4D UTV 8-4.7L Gasoline SFI GREY

AIR BAGS Toyota Motor Engineering and Manufacturing (Toyota) is recalling certain model year 2002-2004 Toyota Sequoia and Lexus SC and 2003-2004 Toyota Corolla, Corolla Matrix, Tundra, and Pontiac Vibe vehicles to address a safety defect in the passenger side frontal air bag inflator which may produce excessive internal pressure causing the inflator to rupture upon deployment of the air bag. This recall addresses both the passenger side frontal air bags that were originally installed in the vehicles, as well as replacement air bags that may have been installed as replacement service parts. A replacement air bag may have been installed, as one example, if a vehicle had been in a crash necessitating the replacement of the passenger side frontal air bag. In the event of a crash necessitating deployment of the front passenger's frontal air bag, the inflator could rupture with metal fragments striking and potentially seriously injuring the passenger seat occupant or other occupants. Toyota will notify owners of affected Toyota and Lexus vehicles and General Motors will notify owners of affected Pontiac Vibe vehicles. Toyota, Lexus, and GM dealers will replace the passenger side air bag inflator, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Toyota customer service at 1-800-331-4331. Pontiac Vibe owners may contact GM at 1-800-521-7300. IMPORTANT NOTE: This recall supersedes recall 13V-133 in which some vehicles were inspected and received a replacement inflator, while others were inspected but did not have their inflator replaced. All owners of vehicles that did not get an inflator replacement, or owners that do not know if they got an inflator replacement, should contact their Toyota or Lexus dealer.

NHTSA ID: 13V133000

Issued: Apr 4, 13

Number of Vehicles: 00844277

AIR BAGS Toyota is recalling certain model year 2002 through 2004 Toyota Corolla, Corolla Matrix, Sequoia, Tundra, Lexus SC, and Pontiac Vibe vehicles to address a safety defect in the passenger side frontal air bag which may produce excessive internal pressure causing the inflator to rupture upon deployment of the air bag. This recall addresses both the passenger side frontal air bags that were originally installed in the vehicles, as well as replacement air bags that may have been installed as replacement service parts. A replacement air bag may have been installed, as one example, if a vehicle had been in a crash necessitating the replacement of the passenger side frontal air bag. In the event of a crash necessitating deployment of the passenger's frontal air bag, the inflator could rupture with metal fragments striking and potentially seriously injuring the passenger seat occupant or other occupants. Toyota will notify owners of affected Toyota and Lexus vehicles and General Motors will notify owners of affected Pontiac Vibe vehicles. Toyota, Lexus, and GM dealers will inspect vehicles, and where a defective air bag inflator is identified, the inflator will be replaced, free of charge. The manufacturer has not yet provided the agency with a notification schedule. Toyota and Lexus owners may contact Toyota at 1-800-331-4331. Pontiac Vibe owners may contact GM at 1-800-521-7300.