

Tektronix®
COMMITTED TO EXCELLENCE



COMBINATION EDITION

Wizards Workshop

* ALL SERVICE QUESTIONS FROM EUROPE, MIDDLE EAST, *
* AND AFRICA SHOULD BE ADDRESSED TO THE EUROPEAN *
* MARKETING CENTER SERVICE GROUP IN THE NETHERLANDS. *

TEKTRONIX INTERNAL USE ONLY

PUBLISHED BY SERVICE ADMIN SUPPORT
56-037 EXT, 8939 MERLO

JUNE 1981

WIZARDS WORKSHOP MASTER INDEX

JANUARY 1977 - DECEMBER 1980

NOTE: THIS INDEX REPLACES MAY 1980 EDITION.

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
ADMINISTRATIVE SUPPORT.	1
GENERAL	2
INFORMATION DISPLAY DIVISION	
MEASUREMENT DISPLAY PRODUCTS	11
TEST AND MEASUREMENT PRODUCTS GENERAL	12
LABORATORY INSTRUMENT DIVISION	
BENCHTOP SEMICONDUCTOR TEST SYSTEMS.	14
SAMPLING PRODUCTS	14
TM500	16
5000 SERIES	19
7000 SERIES	20
COMMUNICATIONS DIVISION	
MEDICAL PRODUCTS	23
SPECTRUM ANALYZERS	27
TELEVISION PRODUCTS	29
1980	37
SERVICE INSTRUMENT DIVISION	
ACCESSORIES	38
DIGITAL SERVICE INSTRUMENTS	40
DATA COMMUNICATION ANALYZERS	40
LOGIC ANALYZERS	41
PORTABLES	43
TELEQUIPMENT	51

TABLE OF CONTENTS (CONTINUED)

<u>SECTION</u>	<u>PAGE</u>
INFORMATION DISPLAY DIVISION	52
DATA COMMUNICATIONS	71
LABORATORY INSTRUMENT DIVISION	
MICROCOMPUTER DEVELOPMENT PRODUCTS	71
SEMICONDUCTOR TEST SYSTEMS	74
SIGNAL PROCESSING SYSTEMS	79
COMMUNICATIONS DIVISION	
1980	81



WIZARDS WORKSHOP INDEX

ADMINISTRATIVE SUPPORT

TITLE	ISSUE	DATE	PAGE
"DOA", DEFINITION	10-11	MAY 30,1980	9
4014, 4014-1, 4015, 4015-1 MAINTENANCE AGREEMENT	10-17	AUG 22,1980	4
ACTIVITY CODE CHANGE	10-18	SEPT 5,1980	4
BLANKET REPAIR PURCHASE ORDERS	10-19	SEPT 19,1980	5
COMPONENT FAILURE REPORTING	10-10	MAY 16,1980	3
IN-HOUSE SERVICE RECORDS (ACTIVITY CODE 01)	10-07	APR 4,1980	4
MAINTENANCE AGREEMENT PRICING	10-07	APR 4,1980	4
MAINTENANCE AGREEMENT ADMINISTRATION	10-21	OCT 17,1980	10
MAINTENANCE AGREEMENT ADMINISTRATION	10-23	NOV 21,1980	4
MORE ON THE NEW SERVICE RECORDS	10-03	FEB 8,1980	12
NEW SERVICE RECORDS	10-01	JAN 11,1980	9
NEW SERVICE RECORDS - U.S. DOMESTIC SERVICE ONLY	10-04	FEB 22,1980	5
NEW SERVICE RECORDS	10-05	MAR 7,1980	8
NEW SERVICE RECORDS	10-06	MAR 21,1980	7
NEW SERVICE RECORDS(CHANGES MADE)	10-11	MAY 30,1980	10
NON-PART RELATED FAILURE CODES	10-10	MAY 16,1980	3
REPORT DISTRIBUTION	10-16	AUG 8,1980	4
REPORT DISTRIBUTION	10-22	OCT 31,1980	4
SERVICE RECORD PROCEDURES (REFERENCE PULL-OUT)	10-07	APR 4,1980	A-1
SERVICE RECORD REPORTING - MODULE EXCHANGE COPY	10-08	APR 18,1980	4
SERVICE RECORD PROCEDURES	10-12	JUNE 13,1980	5
SERVICE RECORD PROCESSING	10-13	JUNE 27,1980	8
SERVICE RECORD/TIME DISTRIBUTION SHEETS	10-20	OCT 3,1980	3
SERVICE RECORD PROCEDURES - FAILURES CODES (REF. PULL-OUT)	10-24	DEC 12,1980	A-1

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
067-0878-00 "RS-232 SELF TEST ADAPTER" - CROSSTALK	10-18	SEPT 5,1980	5
118-0588-00 INCORRECT VALUE	9-22	NOV 16,1979	6
118-0802-00 MIXED STOCK--PURGE	10-25	DEC 19,1980	4
131-0679-02, BNC CONNECTORS	9-13	JUL 13,1979	5
131-0847-00 REDESIGNED	8-23	JUL 21,1978	9
136-0220-00 INFORMATION ONLY (TRANSISTOR'S SOCKETS)	9-17	SEP 7,1979	7
148-0034-XX RELAYS	7-18	AUG 12,1977	9
151-0150-00 TRANSISTOR, MOTOROLA MANUFACTURED DEFECTIVE CODE DATES	7-11	MAY 27,1977	7
151-0188-00, DEFECTIVE	7-24	OCT 7,1977	4
151-0190-00 DEFECTIVE STOCK	10-10	MAY 16,1980	1
151-0220-00 INFORMATION ONLY	9-19	OCT 5,1979	4
151-0225-00 DEFECTIVE DATE CODE -- "TELEDYNE"	7-30	DEC 9,1977	8
151-0239-00 OUT OF SPECS "FAIRCHILD BRAND ONLY"	7-30	DEC 9,1977	8
151-0254-00 LEAD CONFIGURATION CHANGE	7-19	AUG 19,1977	6
151-0373-00 (PNP), 151-0349-00 (NPN) MARKED WRONG--MOTOROLA BRAND ONLY	7-18	AUG 12,1977	6
151-0402-00 LEAD CONFIGURATION	9-17	SEP 7,1979	7
151-1036-00 MIXED STOCK	10-03	FEB 8,1980	3
151-1042-00 DEFECTIVE DATE CODE - "TELEDYNE"	9-06	APR 6,1979	8
152-0141-02 MIXED STOCK	10-18	SEPT 5,1980	5
152-0141-02 MIXED STOCK	9-09	MAY 18,1979	3
152-0153-00 SILICON DIODE, FAIRCHILD MANUFACTURED, DISCONTINUED	7-11	MAY 27,1977	7
152-0153-00/-02 DEFECTIVE DATE CODE	9-08	MAR 4,1979	13
152-0293-00 - DEFECTIVE PLATING	9-12	JUN 29,1979	3
152-0429-00 WRONG PARTS	9-09	MAY 18,1979	4
152-0574-00 MIXED STOCK - "PURGE"	10-18	SEPT 5,1980	6
152-0585-00 POOR RELIABILITY	9-15	AUG 10,1979	9
153-0610-02 - RAW PART CHANGE (INFORMATION ONLY)	9-14	JUL 27,1979	7
155-0006-01 DEFECTIVE DATE CODES	9-22	NOV 16,1979	6
155-0049-01 DEFECTIVE DATE CODE	7-18	AUG 12,1977	6
155-0067-02 DEFECTIVE LOT DATE	9-20	OCT 19,1979	3
155-0067-02 MIXED STOCK	9-14	JUL 27,1979	7
155-0123-00 DEFECTIVE DATE CODE	7-18	AUG 12,1977	6
155-0195-00 - IMPROPERLY MARKED	9-12	JUN 29,1979	3
156-0021-00 -- DEFECTIVE DATE CODE -- "PURGE"	10-18	SEPT 5,1980	6
156-0047-00 MIXED STOCK - SIGNETICS	9-05	MAR 16,1979	7
156-0058-00 MIXED STOCK	9-05	MAR 16,1979	7
156-0067-00 COMPONENT FAILURE	8-15	MAY 12,1978	6
156-0087-00 MIXED STOCK	9-08	MAR 4,1979	13
156-0118-00 - DISQUALIFIED VENDOR	9-12	JUN 29,1979	3
156-0118-01 - DISQUALIFIED VENDOR	9-14	JUL 27,1979	8
156-0141-00 - INCORRECT OUTPUTS	9-14	JUL 27,1979	8

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
156-0177-00/01 DEFECTIVE DATE CODE-MOTOROLA	7-22	SEPT 23,1977	4
156-0182-00 DEFECTIVE DATE CODE "PURGE"	10-18	SEPT 5,1980	6
156-0182-00 DEFECTIVE DATE CODE "MOTOROLA"	8-15	MAY 12,1978	6
156-0182-00 WRONG PART NUMBER, MOTOROLA	7-14	JULY 8,1977	19
156-0218-00/01 DEFECTIVE DATE CODE (FAIRCHILD)	9-05	MAR 16,1979	7
156-0326-00 MIXED STOCK	9-04	MAR 2,1979	7
156-0328-00 DEFECTIVE DATE CODE	9-08	MAR 4,1979	13
156-0349-03 CHANGE OF MARKING (INFORMATION)	9-05	MAR 16,1979	7
156-0385-00/01 MIXED STOCK	9-09	MAY 18,1979	4
156-0410-00 DEFECTIVE DATE CODES	9-20	OCT 19,1979	3
156-0412-00 DEFECTIVE DATE CODE	9-22	NOV 16,1979	6
156-0530-00 MIXED STOCK	10-01	JAN 11,1980	8
156-0733-00 DEFECTIVE DATE CODE	9-21	NOV 2,1979	6
156-0788-00 OUTPUT IS OPEN	9-19	OCT 5,1979	4
156-0801-00 MIXED STOCK	9-06	APR 6,1979	8
156-0874-00 DEFECTIVE DATE CODE "T.I. BRAND"	8-15	MAY 12,1978	6
156-0916-00 INCORRECT PART	9-17	SEP 7,1979	8
156-0945-00 DEFECTIVE PARTS	9-16	AUG 24,1979	5
156-0956-00 & 01 DEFECTIVE DATE CODE - TEXAS INSTRUMENT'S BRAND	9-03	FEB 16,1979	7
156-0972-00 DEFECTIVE DATE CODE "INTEL BRAND"	8-15	MAY 12,1978	7
156-0982-00 - MIXED STOCK "PURGE"	10-18	SEPT 5,1980	6
156-0987-00 DEFECTIVE DATE CODE	9-09	MAY 18,1979	4
156-0998-00 DEFECTIVE DATE CODES - "SIGNETICS"	9-06	APR 6,1979	8
156-1059-00 MIXED STOCK	9-14	JUL 27,1979	8
156-1068-00 DEFECTIVE DATE CODE - MOTOROLA	9-04	MAR 2,1979	7
156-1097-00 MIXED STOCK	9-14	JUL 27,1979	8
156-1243-00 - MARKING ERRORS	9-14	JUL 27,1979	8
156-1254-00 DEFECTIVE DATE CODE	9-15	AUG 10,1979	9
156-1336-01 DEFECTIVE DATA CODE--PURGE	10-25	DEC 19,1980	4
158-0151-00 MIXED STOCK "PURGE"	10-22	OCT 31,1980	3
160-0117-00 INCORRECT MARKINGS AND PARTS	9-09	MAY 18,1979	4
211-0256-00 MIXED STOCK	9-09	MAY 18,1979	5
212-0517-00 DAMAGED THREADS	9-09	MAY 18,1979	5
260-0742-00 MIXED STOCK	9-09	MAY 18,1979	5
281-0093-00 MIXED STOCK	9-05	MAR 16,1979	7
281-0178-00/281-0182-00 MIXED STOCK	9-05	MAR 16,1979	8
281-0593-00 INCORRECT PARTS	9-17	SEP 7,1979	8
283-0299-00 MIXED STOCK	9-05	MAR 16,1979	8
283-XXXX-XX DEFECTIVE DATE CODES - "SPRAGUE"	9-09	MAY 18,1979	5
285-0938-00:DEFECTIVE DATE CODES	10-08	APR 18,1980	2
285-0938-00 DEFECTIVE DATE CODES "PURGE"	10-13	JUNE 27,1980	6
307-0387-00 MIXED STOCK	9-12	JUN 29,1979	3

GENERAL

TITLE	ISSUE	DATE	PAGE
308-0213-00 MARKINGS INCORRECT	10-03	FEB 8,1980	4
311-0601-00 INCORRECT VALUE	9-24	DEC 14,1979	8
311-1162-00 DEFECTIVE DATE CODE	9-05	MAR 16,1979	8
311-1224-00 DEFECTIVE DATE CODE	9-19	OCT 5,1979	4
311-1817-00 DEFECTIVE DATE CODE	9-05	MAR 16,1979	8
311-1915-00 DEFECTIVE DATE CODE	10-09	MAY 2,1980	3
321-0086-00 INCORRECT VALUE AND COLOR CODE	9-05	MAR 16,1979	8
321-0126-03 MIXED STOCK	10-12	JUNE 13,1980	4
321-0236-00 RESISTOR MARKED WRONG	7-16	JULY 29,1977	4
321-0338-00 AND 321-0242-00/08 MIXED STOCK "PURGE"	10-13	JUNE 27,1980	7
321-0983-00 INCORRECT MARKINGS	9-21	NOV 2,1979	6
322-0510-00 TEMPERATURE SENSITIVE	9-22	NOV 16,1979	6
366-1433-00 - INCORRECT ALIGNMENT	9-12	JUN 29,1979	3
382-0299-00 MIXED STOCK	9-05	MAR 16,1979	8
4016/GMA125 CRT PACKAGING	10-15	JULY 25,1980	8
832/833 - RE-EMPHASIS OF VIDEO TAPES	9-23	NOV 30,1979	3
ACTIVITY CODE 18 "PRODUCT FIELD INSTALLED"	8-26	SEPT 1,1978	8
ADM	10-16	AUG 8,1980	4
AEROSOL CLEANERS	7-09	APR 29,1977	5
ANNOUNCEMENT OF CALIBRATION FIXTURES CATALOG	10-08	APR 18,1980	2
ANNOUNCEMENT OF TRAINING PACKAGES (CORRECTION)	8-11	APR 14,1978	3
ANNOUNCEMENT OF TRAINING PACKAGES (CORRECTION TO THIS ARTICLE IN ISSUE 8-11)	8-09	MAR 31,1978	4
ANTI-STATIC BENCH TOP COVER - BLACK CONDUCTIVE FOAM	7-03	FEB 4,1977	4
ANTI-STATIC SHIPPING MATERIAL AVAILABLE	8-03	FEB 3,1978	4
AUDIOTAPES, VIDEOTAPES, AND TRAINING PACKAGES AVAILABLE	8-13	APR 28,1978	6
AVOID JAMMED AND RUINED AUDIO CASSETTES	7-14	JULY 8,1977	4
AVX BRAND CERAMIC GLASS ENCAPSULATED CAPACITORS	8-03	FEB 3,1978	4
BATTERY CARE AND MAINTENANCE	10-14	JULY 11,1980	2
BEAVERTON PRODUCT UPDATE STATUS	10-22	OCT 31,1980	2
BERG CONNECTOR CRIMP TOOLS	10-23	NOV 21,1980	2
CAL COMP FLOPPY DISC VIDEO TAPE AVAILABLE	7-10	MAY 13,1977	5
CAM SWITCH REPAIR MANUAL (REFERENCE PULL-OUT)	10-23	NOV 21,1980	E-1
CARE AND CLEANING OF SOLDERING IRONS AND IRON-CLAD TIPS	9-22	NOV 16,1979	1
CERAMIC THICK FILM ENCAPSULATION MATERIAL CHANGE	7-10	MAY 13,1977	5
CHARGING NICK BATTERIES	7-01	JAN 14,1977	5
CLEANING NOISY POTENTIOMETERS	10-17	AUG 22,1980	2
CLEANING SWITCHES	8-28	SEPT 29,1978	4
COLOR CONCENTRATION REDUCED IN HARMONICS	7-18	AUG 12,1977	4
CRT FAILURE INFORMATION	10-13	JUNE 27,1980	3
CRT NECK PINS	7-05	MAR 4,1977	9
CRT PART NUMBERS IN GENERAL	7-06	MAR 18,1977	4

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
CRT REMOVAL PRECAUTIONS	7-28	NOV 18,1977	3
CRTS, REPORTING DOA	7-28	NOV 18,1977	3
DATA SHEETS & CAL FIXTURES FOR MICROFICHE	10-02	JAN 25,1980	4
DEC EQUIPMENT RACKS	8-22	JUL 7,1978	5
DIGITAL STORAGE CONCEPTS	9-22	NOV 16,1979	2
EMC SERVICE GROUP (REFERENCE PULL-OUT)	9-24	DEC 14,1979	A-1
EUROPEAN MANUFACTURING	10-04	FEB 22,1980	1
EXCHANGE/REPAIR & RETURN	7-01	JAN 14,1977	5
FAILURE CODES - ALPHABETICAL LISTING	10-13	JUNE 27,1980	4
FAILURE MODE OF FIELD REJECTS ANALYZED	7-07	APR 1,1977	8
FAILURE REPORTING	9-17	SEPT 7,1979	9
FAILURE REPORTING	7-10	MAY 13,1977	6
FAILURE REPORTING (PULLOUT REFERENCE)	7-19	AUG 19,1977	16
FAIRCHILD 152-0061-00 "WRONG PART"	7-26	OCT 28,1977	4
FIELD FAILURE REPORTING	8-05	MAR 3,1978	5
FIELD FAILURE REPORTS ON TEKTRONIX INTEGRATED CIRCUITS	8-13	APR 28,1978	8
FIELD PRODUCT UPDATES	10-15	JULY 25,1980	2
FLUKE 5101B TAPES	10-21	OCT 17,1980	3
FLUOROCARBON SPRAY PAINT	7-26	OCT 28,1977	4
GMA125/4016 CRT PACKAGING	10-15	JULY 25,1980	8
GPIB CABLES, NEW PART NUMBERS	8-33	DEC 8,1978	6
GUERNSEY MODIFICATIONS, JANUARY & FEBRUARY 1980	10-09	MAY 2,1980	2
HARMONICA TERMINAL CONNECTOR HOLDERS	7-26	OCT 28,1977	5
HIGH RESISTANCE MEASUREMENT TECHNIQUE	10-21	OCT 17,1980	4
HISTORY STATUS MICROFICHE REPORT BY PRODUCT	7-15	JULY 22,1977	5
IC PULLER	8-27	SEPT 15,1978	4
IC SOCKET RELIABILITY PROBLEM	8-13	APR 28,1978	8
INFORMATION SYSTEMS-TEKNETTING SERVICE RECORDS	8-21	JUN 30,1978	5
INFORMATION SYSTEMS-CODE 18	8-20	JUN 23,1978	5
INFORMATION SYSTEMS-MORE ON SERVICE RECORDS	8-19	JUN 9,1978	5
INFORMATION SYSTEMS-FILLING OUT SERVICE RECORDS	8-18	JUN 2,1978	4
INFORMATION SYSTEMS-WIZARD'S WORKSHOP SPLIT	8-17	MAY 26,1978	3
INFORMATION SYSTEMS-COMPONENT FAILURE ANALYSIS	8-25	AUG 18,1978	3
INFORMATION SYSTEMS-INTERIM MIS	8-24	AUG 4,1978	5
INFORMATION SYSTEMS-MAINTENANCE AGREEMENTS	8-27	SEPT 15,1978	4
INFORMATION SYSTEMS-SQI	8-34	DEC 22,1978	4
INFORMATION SYSTEMS-EXCHANGE PROGRAMS	8-22	JUL 7,1978	5
INFORMATION SYSTEMS-MAINTENANCE AGREEMENT TRANSMITTAL FORMS	8-32	NOV 24,1978	5
INFORMATION SYSTEMS-TDS & SERVICE RECORDS	8-16	MAY 19,1978	5
INFORMATION SYSTEMS CORRECTION	8-20	JUN 23,1978	6
INITIAL MANUAL DISTRIBUTION	8-30	OCT 27,1978	7
INSTALLATION REPORT	10-24	DEC 12,1980	1

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
INSTALLATION AND REPAIR OF NON-CORPORATE DOCUMENTED MODIFICATIONS	8-25	AUG 18,1978	4
INSTRUCTION MANUAL CORRECTION REQUEST FORMS CHANGES	8-34	DEC 22,1978	4
INTERMITTENT I.C. SOCKETS (ALL TYPES)	10-03	FEB 8,1980	3
INTERNATIONAL POWER CORD & PLUG OPTIONS - GCS PRODUCTS	10-13	JUNE 27,1980	5
INTERNATIONAL SYSTEM DOWN ORDERING PROCEDURE	9-12	JUN 29,1979	8
INVENTORY CONTROL TAG	10-13	JUNE 27,1980	6
INVOICING PROCEDURES	8-28	SEPT 29,1978	7
JET TRAINING PACKAGE	8-23	JUL 21,1978	6
LOCATING MOD KIT INSTRUCTIONS IN THE M.R.I.S.	10-21	OCT 17,1980	5
LOGIC ANAL CANNON PLUGS P/N 131-1345-00 - DEFECTIVE "PURGE"	10-18	SEPT 5,1980	5
LONG TERM PRODUCT SUPPORT	9-02	FEB 2,1979	5
MAINTENANCE AGREEMENT LABEL AVAILABLE	7-28	NOV 18,1977	3
MANUAL CORRECTION FORM CHANGES DELIVERY STATION	8-09	MAR 31,1978	5
MANUAL SECTION OF THE MICROFICHE	9-25	DEC 21,1979	2
MICROFICHE CORRECTION FORM	9-10	JUN 1,1979	5
MICROFICHE STORAGE	7-31	DEC 16,1977	5
MICROFICHE USER INFORMATION	9-22	NOV 16,1979	2
MICROFICHE, NEW INDEXES AVAILABLE	9-09	MAY 18,1979	3
MYSTERIOUS DISAPPEARANCE REPORT	7-26	OCT 28,1977	5
NBS TIME AND FREQUENCY BULLETIN	10-03	FEB 8,1980	3
NBS TRACEABLE TRANSITION TIME MEASUREMENTS AT TEK	9-08	MAR 4,1979	5
NEW 156-0067, 156-0158 OP AMPS AVAILABLE	7-27	NOV 11,1977	9
NEW ANTI-STATIC WRIST STRAP AVAILABLE	8-26	SEPT 1,1978	11
NEW PARTS ORDERABLE FROM CSG	10-12	JUNE 13,1980	2
NEW POWER CORDS - SAFETY HAZARD	7-15	JULY 22,1977	7
NEW SERVICE RECORDS	9-24	DEC 14,1979	9
NEW SHIPPING MEMO FORM	7-32	DEC 23,1977	6
NEW SMALL KNOB DESIGNED	7-31	DEC 16,1977	5
NOTE ON MAINTENANCE AGREEMENTS	8-29	OCT 13,1978	4
ON-SITE SERVICE RECORD AND TDS WHEN PARTS AND LABOR ARE WARRANTED	8-30	OCT 27,1978	8
ON-SITE SERVICE RECORDS	9-06	APR 6,1979	6
OPTO COUPLER/ISOLATORS - DEFECTIVE DATE CODES	10-08	APR 18,1980	2
PART NUMBERS FOR 10 WIRE RIBBON CABLES WITH HARMONIC CONNECTORS	8-03	FEB 3,1978	5
PAYROLL CODES ON TIME DISTRIBUTION SHEETS	8-25	AUG 18,1978	4
PELTOLA CONNECTOR SYSTEM PART NUMBERS	10-14	JULY 11,1980	6
PHONE EXTENSION CHANGES FOR BEAVERTON T&M SERVICE SUPPORT	10-12	JUNE 13,1980	3
PINK POLYETHYLENE ANTI-STATIC BAGS	9-08	MAR 4,1979	11
PROCEDURE CONCERNING SERVICE CENTER REQS IN ERROR	9-24	DEC 14,1979	3
PRODUCT HISTORY STATUS LISTING - HEERENVEEN	10-09	MAY 2,1980	3
PRODUCT RESPONSIBILITY LIST FR T&M SERV SUPP (REF PULL-OUT)	10-15	JULY 25,1980	C-1

1 JANUARY 1981

PAGE 6

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
PRODUCT RESPONSIBILITY LIST FOR WALKER RD SERV SUPP (R.P.O.)	10-15	JULY 25,1980	B-1
PRODUCT RESPONSIBILITY LIST FOR IDD SER SUPPORT (REF PULL-OUT)	10-15	JULY 25,1980	A-1
PRODUCT SAFETY	10-15	JULY 25,1980	5
PRODUCTS SENT DIRECTLY TO BEAVERTON BY CUSTOMER FOR REPAIRS	7-04	FEB 18,1977	5
QUALITY ASSURANCE	9-15	AUG 10,1979	8
QUALITY CHECK PROGRAM FOR ASSEMBLIES	10-14	JULY 11,1980	6
QUALITY CHECK PROGRAM FOR ASSEMBLIES	10-17	AUG 22,1980	2
QUERIES FROM INTERNATIONAL	9-17	SEP 7,1979	3
QUESTIONABLE SUPPLY COMPANY	8-18	JUN 2,1978	4
R.F. CABLES	9-22	NOV 16,1979	4
RE-EMPHASIS OF 832/833 VIDEO TAPES	9-23	NOV 30,1979	3
RE-FORMING CAPACITORS EXTENDS SHELF LIFE	9-14	JUL 27,1979	3
RELAYS (TEK MADE, DEFECTIVE CODE DATES)	7-22	SEPT 23,1977	3
REPAIR OF SAFETY DEFECTS	7-11	MAY 27,1977	6
REPORT OF CALIBRATION & CERTIFICATION	9-18	SEP 21,1979	3
RETURNING DEFECTIVE CRT'S TO BEAVERTON	10-05	MAR 7,1980	2
RETURNING CRT'S TO BEAVERTON FOR SALVAGE	7-10	MAY 13,1977	7
RETURNING PARTS AND ACCESSORIES FROM SERVICE CENTERS	7-04	FEB 18,1977	5
REVENUE SPLITTING	8-20	JUN 23,1978	7
REVISED "FIELD MODIFICATIONS SUGGESTION/CORRECTION REPORT"	7-30	DEC 9,1977	6
REVISION TO IDD TROUBLESHOOTING SYMPTOMS HANDBOOK	9-22	NOV 16,1979	3
SAFETY HAZARDS	7-18	AUG 12,1977	5
SALES TRAINING MOVES	10-11	MAY 30,1980	8
SALES/SERVICE AND MOD SUMMARY SECTION OF MICROFICHE	9-25	DEC 21,1979	3
SAW FILTERS	9-13	JUL 13,1979	3
SERVICE CENTER TIME DISTRIBUTION SHEET	9-03	FEB 16,1979	8
SERVICE GROUPS MOVE	10-15	JULY 25,1980	6
SERVICE LABOR RATE CHANGE	9-07	APR 20,1979	8
SERVICE RECORD REPORTING-TIMES	9-08	MAR 4,1979	5
SERVICE RECORD PROCESSING-CLARIFICATION OF BLOCKS	9-15	AUG 10,1979	4
SERVICE RECORD PROCEDURES-TRAVEL INFORMATION	9-15	AUG 10,1979	3
SERVICE RECORD REPORTING-WORKMANSHIP PROBLEMS	8-31	NOV 10,1978	5
SERVICE RECORD PROCESSING-REPORTING INSTRUMENT	9-23	NOV 30,1979	3
SERVICE RECORD PROCEDURES - (COPIES)	9-17	SEPT 7,1979	11
SERVICE TEKNOTES - PURPOSE AND PROCEDURES	10-07	APR 4,1980	3
SERVICE TEKNOTES	9-25	DEC 21,1979	4
SHAFT CAM SWITCH INTERCONCENTRIC DRIVER BREAKAGE	7-17	AUG 5,1977	6
SHIPPING INFORMATION	8-32	NOV 24,1978	6
SIGNATURE/DATA ANALYSIS	9-13	JUL 13,1979	5
SIGNETICS 156-0172-00 "DEFECTIVE DATE CODE"	7-30	DEC 9,1977	8
SOFTWARE AND FIRMWARE ARE VALUABLE PROPERTY	7-28	NOV 18,1977	4

1 JANUARY 1981

PAGE 7

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
SOLDERING WITH EUTECTIC SOLDER	10-06	MAR 21,1980	2
SPANNER WRENCH AVAILABLE	9-02	FEB 2,1979	6
STATIC AWARENESS	8-26	SEPT 1,1978	8
STATIC PRECAUTIONS	9-06	APR 6,1979	7
STATIC SENSITIVE PARTS HANDLING - WRIST STRAP AND SOLDAPULLT	8-21	JUN 30,1978	5
STOLEN INSTRUMENTSS(INTERNATIONAL)	10-01	JAN 11,1980	1
STOLEN INSTRUMENTS (INTERNATIONAL)	10-03	FEB 8,1980	4
STOLEN INSTRUMENTS (INTERNATIONAL)	10-16	AUG 8,1980	3
STOLEN INSTRUMENTS (INTERNATIONAL)	10-19	SEPT 19,1980	4
STOLEN INSTRUMENTS (INTERNATIONAL)	10-21	OCT 17,1980	6
STOLEN INSTRUMENTS (INTERNATIONAL)	10-23	NOV 21,1980	3
STOLEN INSTRUMENTS (INTERNATIONAL)	10-24	DEC 12,1980	4
SURVEY-31 WARRANTY	9-15	AUG 10,1979	6
SWITCH MAINTENANCE	7-02	JAN 21,1977	6
SWITCHES VIDEO CASSETTE	7-05	MAR 4,1977	10
SYSTEM DOWN ORDERING PROCEDURES VERSUS 021- PART NUMBERS	9-13	JUL 13,1979	5
T.I. 151-0423-00 CODE DATE FAILURES	7-16	JULY 29,1977	5
TDS MAIL SCHEDULE	10-06	MAR 21,1980	3
TDS REPORTING/LABOR EXCEPTIONING	9-01	JAN 12,1979	5
TEKTRONIX FIRMWARE SUPPORT POLICY	9-05	MAR 16,1979	6
TEKTRONIX LONG TERM PRODUCT SUPPORT INFORMATION	8-02	JAN 27,1978	3
TEKTRONIX LONG TERM PRODUCT SUPPORT INFORMATION (CORRECTION)	8-03	FEB 3,1978	5
TEKTRONIX PART NUMBER 290-0308-00 VENDOR CHANGE WITHOUT PART NUMBER CHANGE	7-09	APR 29,1977	5
TEKTRONIX PRODUCTS BOUND FOR OVERSEAS CORRECTION	8-06	MAR 10,1978	7
TEKTRONIX PRODUCTS BOUND FOR OVERSEAS USE	8-01	JAN 20,1978	7
TEKTRONIX PRODUCTS BOUND FOR OVERSEAS USE - UPDATE	8-04	FEB 17,1978	6
TELEQUIPMENT	10-09	MAY 2,1980	3
TEN ELECTRO COMMANDMENTS	9-07	APR 20,1979	9
TIME DISTRIBUTION SHEET (TDS) REPORTING	10-17	AUG 22,1980	3
TIME DISTRIBUTION SHEETS	9-25	DEC 21,1979	5
TO-202 TRANSISTOR PIN-OUTS	8-14	MAY 5,1978	4
TOPICS FROM MARKETING TRAINING	9-07	APR 20,1979	10
TRANSPORTING HAZARDOUS MATERIALS	7-30	DEC 9,1977	7
TREATMENT OF LEDS	8-27	SEPT 15,1978	6
TROUBLESHOOTING YOUR OSCILLOSCOPE - ARTICLE 4	10-01	JAN 11,1980	2
TROUBLESHOOTING YOUR OSCILLOSCOPE- ARTICLE 6	10-03	FEB 8,1980	5
TROUBLESHOOTING YOUR OSCILLOSCOPE	10-05	MAR 7,1980	3
TROUBLESHOOTING YOUR OSCILLOSCOPE -ARTICLE 5	10-02	JAN 25,1980	5
TROUBLESHOOTING YOUR OSCILLOSCOPE - ARTICLE 8	10-06	MAR 21,1980	4
TROUBLESHOOTING YOUR OSCILLOSCOPE - REVISION	10-08	APR 18,1980	3
TROUBLESHOOTING YOUR OSCILLOSCOPE (ARTICLE 3)	9-25	DEC 21,1979	7

1 JANUARY 1981

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
TROUBLESHOOTING YOUR OSCILLOSCOPE (ARTICLE 1)	9-23	NOV 30,1979	5
TROUBLESHOOTING YOUR OSCILLOSCOPE (FORWARD)	9-22	NOV 16,1979	5
TROUBLESHOOTING MICROPROCESSOR BASED SYSTEMS VIDEO CASSETTE	7-05	MAR 4,1977	9
TROUBLESHOOTING YOUR OSCILLOSCOPE (ARTICLE 2)	9-24	DEC 14,1979	4
TURN-AROUND-TIME REPORT	9-13	JUL 13,1979	3
U.S. FIELD FAILURE REPORTING TREND	7-05	MAR 4,1977	10
UNAUTHORIZED PRODUCT MODIFICATIONS	10-04	FEB 22,1980	4
UNIT OF MEASURE - BY THE FOOT	7-15	JULY 22,1977	7
UNIVERSAL LOAD UNIT - DESIGN ERROR	10-21	OCT 17,1980	7
UNIVERSAL LOAD UNIT - PRODUCTION ERROR	10-23	NOV 21,1980	3A
UPDATING SCHEDULE FOR MICROFICHE (MRIS)	9-23	NOV 30,1979	9
VACUUM SOLDER EXTRACTION	9-11	JUN 15,1979	4
VIDEO AND AUDIO TAPES AVAILABLE	8-04	FEB 17,1978	6
VIDEO AND AUDIOTAPES AVAILABLE	9-12	JUN 29,1979	2
VIDEO AND AUDIO TAPES AVAILABLE	8-20	JUN 23,1978	8
VIDEO AND AUDIO TAPES AVAILABLE	8-34	DEC 22,1978	5
VIDEO AND TRAINING PACKAGE ANNOUNCEMENTS	8-23	JUL 21,1978	7
VIDEO CASSETTE ON CREDIT	7-06	MAR 18,1977	4
VIDEO CASSETTES ON MEASUREMENTS IN THE SERVICE DOMAIN THE 851 DIGITAL TESTER	7-08	APR 15,1977	3
VIDEO TAPE AND AUDIOTAPES AVAILABLE	9-07	APR 20,1979	12
VIDEO TAPE ANNOUNCEMENTS	8-31	NOV 10,1978	6
VIDEO TAPE ANNOUNCEMENTS	9-18	SEP 21,1979	9
VIDEO TAPE ANNOUNCEMENTS	7-26	OCT 28,1977	6
VIDEO TAPE ANNOUNCEMENTS	7-31	DEC 16,1977	7
VIDEO TAPE AVAILABLE	7-23	SEPT 30,1977	3
VIDEO TAPES AVAILABLE	7-14	JULY 8,1977	5
VIDEO TAPES AVAILABLE	8-29	OCT 13,1978	5
VIDEO TAPES AVAILABLE	7-12	JUNE 10,1977	4
VIDEO TAPES AVAILABLE	7-20	AUG 26,1977	5
VIDEO TAPES AVAILABLE	7-27	NOV 11,1977	9
VIDEO TAPES FOR THE TEST & MEASUREMENT SERVICE TECHNICIAN	9-08	MAR 4,1979	12
VIDEOTAPE ANNOUNCEMENTS	10-02	JAN 25,1980	10
VIDEOTAPE DISTRIBUTION MOVES	10-11	MAY 30,1980	7
VIDEOTAPES AVAILABLE	10-11	MAY 30,1980	5
VIDEOTAPES AVAILABLE	10-20	OCT 3,1980	1
WALKER ROAD PRODUCT UPDATE STATUS	10-19	SEPT 19,1980	4
WARRANTY FAILURE RETURNS	7-12	JUNE 10,1977	5
WARRANTY POLICIES	10-01	JAN 11,1980	6
WARRANTY POLICIES MANUAL UPDATE	10-03	FEB 8,1980	11
WARRANTY POLICY	10-04	FEB 22,1980	4
WARRANTY POLICIES	9-17	SEPT 7,1979	16

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
WATTS TO BTU/HOUR CONVERSION	8-12	APR 21,1978	4
WD40 LUBRICANT	7-08	APR 15,1977	3
WIRE FOR CIRCUIT BOARD MODIFICATION	8-09	MAR 31,1978	6
WIRE PREP GENERAL INFORMATION	10-01	JAN 11,1980	8
WIZARDS WORKSHOP MASTER INDEX	10-23	NOV 21,1980	4
WIZARDS WORKSHOP NOW ON MICROFICHE	8-17	MAY 26,1978	3
ZIP GRIP #10 NOW ORDERABLE	8-34	DEC 22,1978	6

WIZARDS WORKSHOP INDEX
INFORMATION DISPLAY DIVISION

MEASUREMENT DISPLAY PRODUCTS

TITLE	ISSUE	DATE	PAGE
600 SERIES PRODUCTS	10-17	AUG 22,1980	10
602 - H.V. TRANSISTOR Q200	8-11	APR 14,1978	6
602 HIGH VOLTAGE POWER SUPPLY IMPROVEMENT	10-07	APR 4,1980	8
602 MOD 705B PACKAGING	7-18	AUG 12,1977	8
602 NOISY FOCUS POT PROBLEM	10-05	MAR 7,1980	24
602 PHASING ADJUSTMENT	10-23	NOV 21,1980	25
602 POWER SWITCH IMPROVEMENT	8-28	SEPT 29,1978	22
603,603A,604,604A,605,606,606A DEF AMPLIFIER SETTLING	10-04	FEB 22,1980	21
603/604 AND 605 TRANSISTOR RELIABILITY MOD (REPEAT)	8-11	APR 14,1978	7
603/604 DEFLECTION AMPLIFIER	8-07	MAR 17,1978	15
603/604 HIGH VOLTAGE IMPROVEMENT	7-10	MAY 13,1977	23
603/604 HIGH VOLTAGE CIRCUIT MOD	8-16	MAY 19,1978	12
603/604 MONITOR OUTPUT TRANSISTORS	7-19	AUG 19,1977	13
603/604 RELIABILITY MOD - M31277	8-11	APR 14,1978	6
603/604 TRANSISTOR CHANGES	8-11	APR 14,1978	7
605, 607 DOT OR TRACE BLINKING 5-9-77	7-11	MAY 27,1977	20
606 DISPLAY MONITOR	7-10	MAY 13,1977	24
606 MONITOR AVERAGE PLATE VOLTAGE ADJUSTMENT	7-20	AUG 26,1977	9
606A 607A 608 624 634 OP AMP CHANGE	10-20	OCT 3,1980	13
606B,607,607A,620,624, DEFLECTION AMPLIFIER SETTLING TIME PROBLEM	10-04	FEB 22,1980	21
608 CRT REPLACEMENT IN EARLY INSTRUMENTS	10-23	NOV 21,1980	25
608 GROUND CLIP	8-28	SEPT 29,1978	23
608 OPTION 25 CHANGE	8-06	MAR 10,1978	10
608 Z-AXIS EXTENDER BOARD	8-12	APR 21,1978	7
611 U450 LAYOUT MISLEADING	10-23	NOV 21,1980	25
611 Z-AXIS NOISE ELIMINATED	7-21	SEPT 9,1977	11
613 CG,/613-1 CG/613 JA; MODIFICATION 35391 APPLIES	10-23	NOV 21,1980	26
634 ARCING CRT DETECTION	10-23	NOV 21,1980	26
634 MODIFICATION #36364	10-23	NOV 21,1980	26
634 OPTIONS 23 AND 28 MECHANICAL PART NUMBERS	8-32	NOV 24,1978	13
634 RELIABILITY & NOISE MODIFICATION #3777	10-20	OCT 3,1980	14
634 TORX TOOLS AVAILABLE	10-20	OCT 3,1980	20
ALL MONITORS - CORRECT SHIPPING PROCEDURES	10-03	FEB 8,1980	20
DOT GENERATOR CIRCUIT CHANGE	8-17	MAY 26,1978	5

WIZARDS WORKSHOP INDEX

TEST & MEASUREMENT PRODUCTS GENERAL

TITLE	ISSUE	DATE	PAGE
"DIP" INSERTION TOOL	9-02	FEB 2,1979	20
067-0741-99 USING THE CRYSTAL CLOCK	7-04	FEB 18,1977	11
105-XXXX-XX - CAM DRUMS CAUSING LEAKAGE PROBLEMS	8-04	FEB 17,1978	14
1440 - 741 OP. AMP. REPLACEMENT	7-08	APR 15,1977	11
148-0034-00 FAILURES OF RELAYS	7-09	APR 29,1977	13
150-1037-00 LED DISPLAY, 7 SEGMENT PROBLEMS	7-04	FEB 18,1977	11
151-0188-00 MIXED STOCK	8-30	OCT 27,1978	24
151-0192-00 POOR RELIABILITY	8-20	JUN 23,1978	16
151-0251-00 DEFECTIVE DATE CODE "MOTOROLA"	8-05	MAR 3,1978	17
152-0227-00 MIXED PARTS	8-21	JUN 30,1978	15
152-0462-00 - MOTOROLA BRAND	8-04	FEB 17,1978	14
152-0493-00 - DEFECTIVE DATE CODES - "HIGH VOLTAGE DEVICES"	8-07	MAR 17,1978	15
152-0586-00 VENDOR'S PART NUMBER CHANGE	8-21	JUN 30,1978	15
152-0639-00 CRACKING OF DIODES' GLASS BODY -- CAUTION	8-30	OCT 27,1978	24
155-0014-01 WRONG PART INTERNALLY	7-19	AUG 19,1977	4
155-0023-00 DEFECTIVE DATE CODE	8-25	AUG 18,1978	8
155-0024-00 DEFECTIVE DATE CODE	8-25	AUG 18,1978	9
155-0108-00 DEFECTIVE RUNS	8-20	JUN 23,1978	16
156-0030-00 DEFECTIVE DATE CODE	8-24	AUG 4,1978	11
156-0053-00 DEFECTIVE DEVICES - AMD BRAND	8-32	NOV 24,1978	9
156-0058-00 - COMPONENT MIX	8-13	APR 28,1978	15
156-0058-00 - COMPONENT MIX (CORRECTION)	8-14	MAY 5,1978	9
156-0091-00 DEFECTIVE DATE CODES - "SIGNETICS"	8-06	MAR 10,1978	10
156-0120-00/01 DEFECTIVE "ITT BRAND"	8-24	AUG 4,1978	11
156-0141-00 DEFECTIVE DATE CODE	8-30	OCT 27,1978	25
156-0178-00/152-0107-03 MIXED STOCK	8-28	SEPT 29,1978	21
156-0178-00/152-0107-03 MIXED STOCK	8-28	SEPT 29,1978	21
156-0245-00 MIXED STOCK	8-30	OCT 27,1978	25
156-0325-00 MIXED STOCK	8-21	JUN 30,1978	15
156-0349-00 MIXED STOCK	8-24	AUG 4,1978	11
156-0403-00 DEFECTIVE DATE CODE	8-25	AUG 18,1978	9
156-0465-00 MIXED STOCK	8-32	NOV 24,1978	9
156-0480-00 - DISQUALIFIED VENDOR	8-13	APR 28,1978	15
156-0515-02 MIXED PARTS	8-20	JUN 23,1978	16
156-0576-02 MIXED STOCK	8-21	JUN 30,1978	15
156-0599-00 VENDOR PART NUMBER DELETED	8-08	MAR 24,1978	8
156-0666-01 INCORRECT DATA AT ALL ADDRESSES - MOTOROLA	8-32	NOV 24,1978	9
156-0914-00 INCORRECT MARKED DEVICES	8-20	JUN 23,1978	16
156-0916-00 MIXED PARTS	8-20	JUN 23,1978	17
156-0957-00 - DEFECTIVE DATE CODE	8-13	APR 28,1978	15
156-0982-00 DEFECTIVE TEXAS INSTRUMENTS BRAND ONLY	8-20	JUN 23,1978	17
156-1013-00 DEFECTIVE DATE - MOTOROLA BRAND	8-31	NOV 10,1978	18

TEST & MEASUREMENT PRODUCTS GENERAL

TITLE	ISSUE	DATE	PAGE
156-1031-00 DEFECTIVE DATE CODE - FAIRCHILD BRAND	8-30	OCT 27,1978	25
159-0049-00 OPEN FUSES--BUSS BRAND	8-02	JAN 27,1978	9
159-0116-00 FUSE--MIXED PARTS	8-02	JAN 27,1978	9
161-0071-XX - DEFECTIVE POWER CORDS	8-04	FEB 17,1978	15
290-0480-00 EXCESSIVE LEAKAGE	8-04	FEB 17,1978	15
311-1177-00 DEFECTIVE DATE CODE--BECKMAN/HELIPOT	7-30	DEC 9,1977	17
7603/7403/D40/D83 CRT PROBLEM	7-03	FEB 4,1977	4
APPROVED RTV SILICON RUBBER PRODUCTS	9-05	MAR 16,1979	15
AUDIO AND VIDEO TRAINING TAPES	8-28	SEPT 29,1978	20
AUDIO TAPES AVAILABLE	7-18	AUG 12,1977	4
AVX BRAND CERAMIC GLASS ENCAPSULATED CAPACITORS ADDENDUM	8-10	APR 7,1978	7
CORRECTION TO TERMINAL POST SOLDERING PROBLEM (WIZARD 12-10-76)	7-02	JAN 21,1977	9
CRT RELIABILITY	7-11	MAY 27,1977	6
DEFECTIVE LITTLEFUSE BRAND FUSES	8-20	JUN 23,1978	13
ELECTROLYTIC CAP FAILURES ANALYZED	9-05	MAR 16,1979	15
EQUIPMENT RACK	8-04	FEB 17,1978	13
FIXED CAPACITORS - CLARIFICATION OF MARKINGS	8-25	AUG 18,1978	8
METROLOGY - TRACEABILITY	8-28	SEPT 29,1978	20
MOSTEK 156-0410-00 "DEFECTIVE DATE CODE"	7-26	OCT 28,1977	17
MOTOROLA 2N3055 TRANSISTORS/151-0140-00	7-09	APR 29,1977	13
NEW "CAUTION" LABEL FOR TEK-MADE SWITCHES	8-20	JUN 23,1978	14
NEW FORMAT GUIDELINES FOR T&M MANUALS	9-02	FEB 2,1979	20
NEW SCHEMATIC SYMBOLS, "DRAFTING STANDARD" AVAILABLE	8-30	OCT 27,1978	24
OMISSION IN MEASURING CRT PHOTOGRAPHIC WRITING RATE ARTICLE/FEB 19, 1977	7-05	MAR 4,1977	11
POTENTIAL NUVISTOR SHORTAGE	7-10	MAY 13,1977	8
REJECT PARTS PROVIDE VALUABLE FAILURE INFORMATION	8-27	SEPT 15,1978	17
RELAYS (TEK MADE, DEFECTIVE CODE DATES)	8-04	FEB 17,1978	13
SHAFT CAM SWITCH INTERCONCENTRIC DRIVER BREAKAGE (CORRECTION)	7-19	AUG 19,1977	4
SWITCH PIN INFORMATION	7-13	JUNE 24,1977	21
TECHNICAL SUPPORT OF OLDER PRODUCTS	7-13	JUNE 24,1977	22
TM 500 LABEL PART NUMBER	9-07	APR 20,1979	28
TUTORIAL - MEASURING CRT PHOTOGRAPHIC WRITING RATE	7-04	FEB 18,1977	1
155-0006-01 DEFECTIVE DATE CODE	9-01	JAN 12,1979	14
156-0030-00 DEFECTIVE DATE CODE - FAIRCHILD	9-01	JAN 12,1979	14
156-0398-00 INCORRECT MARKINGS	9-02	FEB 2,1979	16
156-0511-00 DEFECTIVE DATE CODES - "SIGNETICS"	9-01	JAN 12,1979	14
290-0804-00 MIXED STOCK	9-03	FEB 16,1979	21
P/N 151-0301-00 - MIXED STOCK	8-26	SEPT 1,1978	26
PDP-11 DL11-E PART NUMBER	9-07	APR 20,1979	24
PDP-11/35 COMPUTER CONFIGURATION GUIDE	8-26	SEPT 1,1978	24
PDP/11 TERMINAL INTERFACE STRAPPING	8-28	SEPT 29,1978	14
SYSTEM INSTALLATION REPORTS - STS, SPS, AND MDL	9-02	FEB 2,1979	16
SYSTEMS PHONE INFORMATION	7-22	SEPT 23,1977	3

WIZARDS WORKSHOP INDEX

LABORATORY INSTRUMENT DIVISION

BENCHTOP SEMICONDUCTOR TEST SYSTEMS

TITLE	ISSUE	DATE	PAGE
576 AMPLIFIER OSCILLATIONS	10-21	OCT 17,1980	11
576 STEP GENERATOR INTERMITTENTLY SKIPS STEPS	10-17	AUG 22,1980	5
576/577 TRANSISTOR ADAPTER SOCKET CHANGES	10-24	DEC 12,1980	5

SAMPLING PRODUCTS

1500 SERIES CHART RECORDER - L8215 SHORTING TO FRAME	9-02	FEB 2,1979	36
1501 CHART PAPER INCOMPATABILITY	8-13	APR 28,1978	21
1501/1503 DISTANCE METER "O" RING PART NUMBER (354-0563-00)	9-09	MAY 18,1979	23
1502 ABERRATIONS	7-28	NOV 18,1977	16
1502 ABERRATIONS	8-03	FEB 3,1978	15
1502 CALIBRATION PROCEDURE REWRITTEN	8-29	OCT 13,1978	11
1502 CASE REMOVAL	7-29	NOV 25,1977	8
1502 CHART RECORDER - EXPLODED VIEW	7-04	FEB 18,1977	13
1502 MAINTENANCE NOTE	7-07	APR 1,1977	16
1502 MANUAL CHANGE INFORMATION (070-1792-00)	7-26	OCT 28,1977	22
1502 NON-LINEARITY ON X0.1 RAMP	8-32	NOV 24,1978	17
1502 SAMPLING BRIDGE INSTALLATION AID	10-08	APR 18,1980	29
1502 STRIPLINE MAINTENANCE NOTE	7-05	MAR 4,1977	22
1502/1503 BATTERY PACK RETURNS	7-01	JAN 14,1977	11
1502/1503 BNC REPLACEMENT	7-15	JULY 22,1977	14
1502/1503 CAMERA FUNCTION	7-32	DEC 23,1977	15
1502/1503 CAMERA FUNCTION DELETED	7-29	NOV 25,1977	9
1502/1503 CHART RECORDER	8-02	JAN 27,1978	13
1502/1503 CHART RECORDER FUSING, M30656	8-16	MAY 19,1978	12
1502/1503 CHART RECORDER FUSING	8-19	JUN 9,1978	23
1502/1503 CHART RECORDER MANUAL	8-09	MAR 31,1978	15

SAMPLING PRODUCTS

TITLE	ISSUE	DATE	PAGE
1502/1503 FRONT PANEL PLUG-IN SEAL REPLACEMENT	7-06	MAR 18,1977	10
1502/1503 INTENSITY PROBLEMS CORRECTION	8-25	AUG 18,1978	9
1502/1503 MANUALS REPRINTED	9-16	AUG 24,1979	6
1502/1503 DISTANCE METER "O" RING PART NUMBER (354-0563-00)	9-09	MAY 18,1979	6
1502/1503 CHART RECORDER - SECURING ROD	9-02	FEB 02,1979	37
1502/1503 - INTENSITY RANGE IMPROVEMENT	9-04	MAR 2,1979	26
1502/1503 -- CHANGE IN TORQUE FOR THE CASE SCREWS	8-30	OCT 27,1978	32
1502/1503 BATTERY PACK SIDE COVERS	8-09	MAR 31,1978	15
1502/1503 CABLE PART NUMBERS	7-03	FEB 4,1977	19
1502/1503 CHART RECORDER MANUAL	8-31	NOV 10,1978	21
1502/1503 HAND TOOLS TORQUE SCREWDRIVER	7-31	DEC 16,1977	19
1502/1503 LINE FUSE CHANGE	7-18	AUG 12,1977	9
1502/1503 POTENTIAL INTENSITY LOSS/DEGRADATION	8-31	NOV 10,1978	21
1502/1503 PROBLEM -- CRACKED CASES	8-29	OCT 13,1978	12
1502/1503 WATERPROOFING	7-31	DEC 16,1977	20
1502/1503 ZERO REFERENCE POT MOD	8-30	OCT 27,1978	32
1503 - FAST RAMP CALIBRATION PROCEDURE CORRECTION	8-29	OCT 13,1978	12
1503 - INTENSITY LIMIT ADJUSTMENT	9-02	FEB 02,1979	37
1503 INTERMITTENT 50 OHM TERM SWITCH	7-07	APR 1,1977	16
1S2 TDR/SAMPLER D435 REPLACEMENT	7-05	MAR 4,1977	21
3S5 CHANNEL 'A' TRIG CONNECTOR	7-05	MAR 4,1977	23
7S14 TRIG KICKOUT PULSE SPECIFICATION	8-15	MAY 12,1978	12
7S14/5S14 TRACE JITTER: MOD 32888	8-10	APR 7,1978	17
ADDENDUM TO 1502 STRIP LINE REPAIR	7-09	APR 29,1977	13
FUSE HOLDER WATERSEAL	8-31	NOV 10,1978	20
S-1 INPUT TERMINATOR, R4 METAL FLANGE PART NUMBER	7-22	SEPT 23,1977	11

WIZARDS WORKSHOP INDEX

TM 500

TITLE	ISSUE	DATE	PAGE
131-0274-00 DEFECTIVE BNC CONNECTORS - KING BRAND	9-03	FEB 16,1979	34
150-1038-00 MIXED STOCK	9-03	FEB 16,1979	34
151-0254-00 CHANGE OF MARKINGS	9-03	FEB 16,1979	34
151-0333-00 DEFECTIVE - SPRAGUE	9-03	FEB 16,1979	35
151-0347-00/01 DEFECTIVE DATE CODES	9-03	FEB 16,1979	35
151-0434-00/01 DEFECTIVE DATE CODE - MOTOROLA	9-03	FEB 16,1979	35
152-0634-00 ARCING OR DEAD	9-03	FEB 16,1979	35
152-0635-00 ARCING THROUGH THE CONNECTOR	9-03	FEB 16,1979	35
156-0305-00 MIXED STOCK	9-03	FEB 16,1979	35
156-0398-00 MIXED STOCK	9-03	FEB 16,1979	36
156-0426-00 DEFECTIVE DATE CODE - AMI BRAND	9-03	FEB 16,1979	36
156-0574-00 MIXED STOCK	9-03	FEB 16,1979	36
156-0785-00 DEFECTIVE DATE CODES - INTERSIL	9-03	FEB 16,1979	36
283-0111-00 MIXED STOCK	9-03	FEB 16,1979	37
290-0582-00 MIXED STOCK	9-03	FEB 16,1979	37
311-0160-00 DEFECTIVE DATE CODE	9-03	FEB 16,1979	37
311-0571-00 MIXED STOCK	9-03	FEB 16,1979	37
40 DC 505/DC 505A NEW FIELD MODIFICATION KIT	8-28	SEPT 29,1978	28
5110/5112 MOD 172F - MISSING MICA WASHER ON Q213	9-21	NOV 2,1979	8
AF 501 CIRCUIT IMPROVEMENT	10-15	JULY 25,1980	9
AF 501 ERRATIC NOISE SPIKES ON OUTPUT	8-06	MAR 10,1978	19
AF 501 MAINTENANCE NOTES	10-19	SEPT 19,1980	6
AM 501 INTERNAL OFFSET NULL ADJUST INOP	8-08	MAR 24,1978	12
AM 502 DIFFICULTY MEETING 1 MHZ BANDPASS	10-08	APR 18,1980	5
AM 502 MAINTENANCE NOTES	10-03	FEB 8,1980	13
AM 502-P/N 151-1029-00 DEFECTIVE DATE CODES	9-22	NOV 16,1979	7
CG 551AP +5 VOLT SUPPLY LOADING	10-20	OCT 3,1980	4
CG 551AP PARTS SUPPORT	10-22	OCT 31,1980	5
CG 551AP SHIPPING	10-19	SEPT 19,1980	7
DC 503 "MANUAL MODE INOP"	8-04	FEB 17,1978	20
DC 503 FIELD MOD INSTRUCTION ERRORS	9-03	FEB 16,1979	30
DC 503 MAINTENANCE NOTES	9-12	JUN 29,1979	A-1
DC 503 NO GATE LIGHT	9-15	AUG 10,1979	10
DC 503 PREVENT DISPLAY ERRORS	9-03	FEB 16,1979	31
DC 504 - "Q195 REPLACEMENT"	9-12	JUN 29,1979	4
DC 504 - 156-0410-00 - DEFECTIVE DATE CODE - "MOSTEK"	8-08	MAR 24,1978	13
DC 504 040-0901-00	9-05	MAR 16,1979	34
DC 504/OPT. 1 "PREVENT CROSSTALK"	7-10	MAY 13,1977	19
DC 505/DC505A MOD KIT CORRECTION	7-07	APR 1,1977	20
DC 505A - U925 VENDOR COMPATIBILITY	7-16	JULY 29,1977	17
DC 505A AND 153 INTERFACE PROBLEMS	7-31	DEC 16,1977	22
DC 505A ERRONEOUS COUNTING AT 10HZ	10-08	APR 18,1980	5

1 JANUARY 1981

PAGE 16

WIZARDS WORKSHOP INDEX

TM 500

TITLE	ISSUE	DATE	PAGE
DC 505A MANUAL ERROR	10-08	APR 18,1980	5
DC 505A MAINTENANCE NOTES	9-12	JUN 29,1979	B-1
DC 505A NEW MANUAL	9-08	MAY 4,1979	14
DC 505A NEW POWER SUPPLY IMPROVEMENT MOD KIT	8-07	MAR 17,1978	20
DC 505A PRECAUTIONS WHEN USING AN EXTENDER CABLE	9-03	FEB 16,1979	31
DC 505A U90 REPLACEMENT	10-22	OCT 31,1980	5
DC 508 MAINTENANCE NOTES (BELOW SN:B02) REFERENCE PULL-OUT	10-01	JAN 11,1980	A-1
DC 508 NEW FIELD MOD KIT: 050-1175-00	9-03	FEB 16,1979	31
DC 508 NEW FIELD MODIFICATION KITS	8-30	OCT 27,1978	36
DC 508 NEW PRESCALER BOARD	9-06	APR 6,1979	50
DC 508 PERFORMANCE CHECK CORRECTION	9-12	JUN 29,1979	5
DC 508 PRESCALER CABLE ASSEMBLIES	10-11	MAY 30,1980	11
DM 501 - 156-0041-00 - DEFECTIVE DATE CODE - "FAIRCHILD"	8-07	MAR 17,1978	20
DM 501 ARCING	9-15	AUG 10,1979	10
DM 501 INCORRECT INPUT CLAMPING PROTECTION	8-05	MAR 3,1978	21
DM 501 MAINTENANCE NOTES - REF PULL-OUT	10-01	JAN 11,1980	B-1
DM 501 MAINTENANCE NOTES - REFERENCE PULL-OUT	10-01	JAN 11,1980	D-1
DM 501 NEW MOD KITS FOR DISPLAY CIRCUIT BOARD REPLACEMENT	8-02	JAN 27,1978	15
DM 501A 500V AC RANGE 1% LOW	10-10	MAY 16,1980	4
DM 501A SPECIAL MAINTENANCE INFORMATION (REFERENCE PULL-OUT)	10-22	OCT 31,1980	A-1
DM 501A UNSTABLE OHMS READINGS	10-18	SEPT 5,1980	7
DM 502 MAINTENANCE NOTES - REFERENCE PULL-OUT	10-01	JAN 11,1980	C-1
DM 502 S/N B029624 & BELOW INTERMITTENT ERROR COUNT... RANGE (CORRECTION)	8-04	FEB 17,1978	21
DM 502 S/N B029624 & BELOW INTERMITTENT ERROR COUNT -200VDC RANGE	8-02	JAN 27,1978	15
DM 502A MAINTENANCE NOTES	9-25	DEC 21,1979	11
DM 502A, 02 - PROTECTION FOR U1301 AND U1321	9-13	JUL 13,1979	6
FG 501 - FRONT PANEL AND SUBPANEL REPLACEMENT	9-14	JUL 27,1979	9
FG 501 BOARD POLARITY PADS WRONG	8-01	JAN 20,1978	19
FG 501 EXCESSIVE DRIFT IN HOLD MODE - "CORRECTION"	8-34	DEC 22,1978	21
FG 501 EXCESSIVE DRIFT IN HOLD MODE	8-31	NOV 10,1978	21
FG 501 MAJOR MANUAL ERRORS	9-01	JAN 12,1979	A-1
FG 501 NEW CUSTOM MODIFICATION	8-32	NOV 24,1978	18
FG 501 OUTPUT AMPLIFIER IMPROVED	8-32	NOV 24,1978	18
FG 501 U-48 VENDOR COMPATIBILITY	7-24	OCT 7,1977	11
FG 503 "DS528 REPLACEMENT"	9-13	JUL 13,1979	6
FG 503 "U121 REPLACEMENT"	9-13	JUL 13,1979	7
FG 503 POWER LAMP REPLACED	9-19	OCT 5,1979	5
FG 503 TIMING PROBLEMS WHEN A CUSTOM TIMING CAPACITOR IS INSTALLED	9-22	NOV 16,1979	8
FG 504 "B04 REWORK PROGRAM" DISCONTINUED	9-07	APR 20,1979	33
FG 504 (B042 AND ABOVE) BLOWING FUSES	10-18	SEPT 5,1980	7

1 JANUARY 1981

PAGE 17

WIZARDS WORKSHOP INDEX

TM 500

TITLE	ISSUE	DATE	PAGE
FG 504 - NEW MANUAL FOR S/N B04 -- AND ABOVE	10-04	FEB 22,1980	6
FG 504 1 AMP FUSE MODIFICATION	10-24	DEC 12,1980	6
FG 504 151-0232-00 - DEFECTIVE DATE CODES - "INTERSIL"	8-04	FEB 17,1978	22
FG 504 COMPONENTS REVERSED	9-08	MAY 4,1979	14
FG 504 FACTORY REWORK	8-04	FEB 17,1978	21
FG 504 IMPROVE 10(5) TIMING ADJUSTMENT RANGE	9-22	NOV 16,1979	9
FG 504 IMPROVE RELIABILITY OF OUTPUT AND POWER SUPPLY CIRCUIT	7-05	MAR 4,1977	28
FG 504 MAINTENANCE NOTES	9-06	APR 6,1979	A-1
FG 504 MISSING RUNS	7-10	MAY 13,1977	19
FG 504 POSSIBLE DAMAGE TO CUSTOMERS EQUIPMENT	7-10	MAY 13,1977	21
FG 504 REAR INTERFACE OUTPUT CHANGES	9-12	JUN 29,1979	6
FG 504 TROUBLE SHOOTING HINTS	7-15	JULY 22,1977	20
FG501A/FG507 SINE DISTORTION ADJUSTMENT	10-25	DEC 19,1980	6
FIELD MOD KIT FOR REAR INTERFACE WIRING	8-07	MAR 17,1978	20
INTERMITTENT RELAYS IN DM501A AND DM502A	10-15	JULY 25,1980	9
NOTICE ABOUT RMC CAPS IN DM 501A'S AND DM 502A'S	10-14	JULY 11,1980	7
PG 501 "Q170 AND Q176 REPLACEMENT	8-27	SEPT 15,1978	28
PG 501 MAINTENANCE NOTES	10-19	SEPT 19,1980	8
PG 502 MAINTENANCE NOTES	10-19	SEPT 19,1980	9
PS 503A MAINTENANCE NOTES	10-04	FEB 22,1980	6
RG 501 MAINTENANCE NOTES	10-19	SEPT 19,1980	12
RTM/TM 506 APPLICATION PRECAUTION (CORRECTION)	10-17	AUG 22,1980	6
RTM/TM 506 APPLICATION PRECAUTIONS	10-10	MAY 16,1980	5
SC 502 MAINTENANCE NOTES (REFERENCE PULL-OUT)	10-05	MAR 7,1980	A-1
SC 503 - P/N 311-2017-00 DEFECTIVE	10-04	FEB 22,1980	7
SC 503 MAINTENANCE NOTES	10-08	APR 18,1980	6
SC 504 INTERMITTENT +5V/ -5V SUPPLIERS	10-10	MAY 16,1980	6
SC 504 MODIFICATIONS	10-22	OCT 31,1980	6
SCPDA 1 SOFTWARE PERFORMANCE REPORT	10-24	DEC 12,1980	7
SG 502 MAINTENANCE NOTES	10-19	SEPT 19,1980	13
SG 503 MAINTENANCE NOTES	10-20	OCT 3,1980	5
SG 503 Q190 LEAD CONFIGURATION	9-08	MAY 4,1979	15
SG 504 HARMONIC DISTORTION & LEVELING IMPROVEMENTS	10-21	OCT 17,1980	12
SG 504 MAINTENANCE NOTES	10-20	OCT 3,1980	9
TM 500 - REAR INTERFACE ACCESS EXTENDER FOR PLUG-INS	10-10	MAY 16,1980	7
TM 500 SOCKET REWORK PROGRAM (CODE 18) DISCONTINUED	10-12	JUNE 13,1980	6
TM 501 & TM 503 TRANSFORMER LEAD COLOR CHANGES	10-21	OCT 17,1980	13
TM 506 CABINET TO RACKMOUNT CONVERSION	10-22	OCT 31,1980	6

WIZARDS WORKSHOP INDEX

5000 SERIES

TITLE	ISSUE	DATE	PAGE
067-0883-99/067-0919-99	10-16	AUG 8,1980	6
1502/1503 MANUALS REPRINTED	9-16	AUG 24,1979	6
5000 FLEXIBLE EXTENDER	10-08	APR 18,1980	7
5000 SERIES MODIFIED INSTRUMENTS 768 X, Y, T	7-06	MAR 18,1977	16
5000 SERIES OSCILLATING NEON BULBS	7-11	MAY 27,1977	18
5100/R, S/N B070029 & UP -30 VOLT POWER SUPPLY OSCILLATIONS	10-25	DEC 19,1980	6
5110/R, 5111/R, 5115/R.H.V. REGULATION	9-25	DEC 21,1979	15
5223 MEMORY CONTENTS L.E.D.'S	10-24	DEC 12,1980	7
5223 POSSIBLE POWER SUPPLY FAILURE B010145 & BELOW	10-20	OCT 3,1980	10
5400 SERIES READOUT	10-08	APR 18,1980	7
5440/5441 READOUT SHORTING TO MOUNTING SCREW	10-18	SEPT 5,1980	8
5440/R 5441/R READOUT MALFUNCTION	10-16	AUG 8,1980	5
5440/R 5441/R TRANSISTOR AVAILABILITY	10-16	AUG 8,1980	5
5440/R AND 5441/R FAN MODIFICATION	7-22	SEPT 23,1977	15
5441 AUTO FOCUS MOD DOCUMENTATION S/N B092860 & UP	10-22	OCT 31,1980	8
5441 ENGINEERING SPECIFICATION CHANGE	7-04	FEB 18,1977	15
5441 HANDLE SUPPORT	10-21	OCT 17,1980	16
5441 MANUAL ERROR	7-06	MAR 18,1977	18
5441 TRACE ROTATION	7-22	SEPT 23,1977	17
5A18N CHOPPED MODE OSCILLATIONS S/N B129148 & UP	10-20	OCT 3,1980	10
5A22N CAM SWITCH	9-25	DEC 21,1979	13
5A22N DIFFERENTIAL AMPLIFIER DC OFFSET	8-06	MAR 10,1978	21
5A48 ABNORMAL DECREASE IN GAIN AND BANDWIDTH	7-26	OCT 28,1977	23
5A48 CHANNEL 2 OSCILLATIONS	9-25	DEC 21,1979	13
5B10N RANDOM LOSS OF SWEEP S/N B099092 & UP	10-22	OCT 31,1980	7
5B12N,5A13N, 5B42,5B44 HELIDIAL SETTINGS	10-13	JUNE 27,1980	9
5B42 TRIGGER DIODES	7-10	MAY 13,1977	23
7B87 INSURE STARTING OF CLOCK OSCILLATOR	10-16	AUG 8,1980	8
SERVICE SUPPORT PRODUCT RESPONSIBILITY CHANGE(5000/7000 SERIES)	10-20	OCT 3,1980	10

7000 SERIES

TITLE	ISSUE	DATE	PAGE
067-0587-02 SIGNAL STANDARDIZER, OSCILLATOR CRYSTAL SHORTING	9-07	APR 20, 1979	35
067-0655-00, SIGNAL PICK-OFF CABLE REPLACEMENT	10-13	JUNE 27, 1980	12
7000 SERIES CRT WRITING SPEED CHANGES	10-19	SEPT 19, 1980	14
7000 SERIES, REPLACEMENT CABLE ASSY FOR "SPOT-O-GOLD" CONNECTORS	10-07	APR 4, 1980	5
7000 SERIES PART NUMBERS FOR WARNING TAGS	9-25	DEC 21, 1979	20
7000 SERIES CRT CLAMP TIGHTENING PROCEDURE	7-11	MAY 27, 1977	20
7000 SERIES MAINFRAME INTERFACE CONNECTOR COVERS	7-06	MAR 18, 1977	20
7000 SERIES OSCILLOSCOPE--MANDATORY MODIFICATION	8-28	SEPT 29, 1978	29
7104 7704A 7834 7844 7854 R7903 7904 DEFECTIVE CAPACITOR	10-13	JUNE 27, 1980	10
7104 BACKGROUND SCINTILLATION	10-02	JAN 25, 1980	11
7104 CRT CIRCUIT, C1796 ADDED, B010157 AND UP	10-01	JAN 11, 1980	10
7104 CRT VOLTAGE SETTINGS	10-18	SEPT 5, 1980	9
7104 INCOMPATIBILITY WITH 7B70, 7B71 AND 7B92	9-08	MAY 4, 1979	15
7104 INTENSITY UNIFORMITY	10-01	JAN 11, 1980	10
7104 INTENSITY CHANGING WITH TIME	9-25	DEC 21, 1979	20
7104 LOGIC CIRCUIT DIODE CHANGE S/N B010100-B010130	9-25	DEC 21, 1979	21
7104 POWER SUPPLY START-UP	10-18	SEPT 5, 1980	9
7104/7704A/7834/7844/7854/R7903 & 7904 DEFECTIVE CAPACITOR	10-10	MAY 16, 1980	9
7104/R836 ADJUSTMENT	10-05	MAR 7, 1980	9
7313/7603/7613/7623A/7633/U973 INTERMITTENTS IN +5 SUPPLY	9-25	DEC 21, 1979	20
7313/R 7613/R 7623/R 7633/R EMI MODIFICATION KIT	10-10	MAY 16, 1980	9
7600 SERIES HORIZONTAL JITTER	7-05	MAR 4, 1977	29
7603 CRT STATIC DISCHARGE	10-07	APR 4, 1980	6
7603 FAN SYSTEM KIT	10-21	OCT 17, 1980	16
7603 H.F. ADJUSTMENT	10-08	APR 18, 1980	8
7603 PRODUCTION MOD, 30310 DEFICIENCY	7-30	DEC 9, 1977	22
7603/7403N CAMERA POWER CABLE	8-10	APR 7, 1978	19
7603/R CABLE CHANGE	10-06	MAR 21, 1980	8
7603/R EMI MODIFICATION KIT	10-10	MAY 16, 1980	9
7603/R7603 HIGH VOLTAGE CAPACITOR (C1241) FAILURES	9-22	NOV 16, 1979	10
7623A/7633 STORAGE INCOMPATIBILITIES IN FAST MODES	10-01	JAN 11, 1980	13
7623A/7633/7834 FLOOD GUN ANODE VOLTAGE SPECIFICATION WAIVER	10-22	OCT 31, 1980	8
7623A/R, 7633/R GATED READOUT	10-17	AUG 22, 1980	8
7623A/R, 7633/R MODIFICATION TO FRONT MESH CIRCUIT REMOVED	10-05	MAR 7, 1980	10
7623A/R, 7633/R REDUCTION OF NOISE ON TRACE	9-25	DEC 21, 1979	22
7633/R, 7623 A/R GATED READOUT	10-17	AUG 22, 1980	8
7633/R7633 SERVICE MANUAL CHANGE	9-25	DEC 21, 1979	23
7704A 7104 7834 7844 7854 R7903/7904 DEFECTIVE CAPACITOR	10-13	JUNE 27, 1980	10
7704A/7104/7834/7844/7854/R7903 & 7904 DEFECTIVE CAPACITOR	10-10	MAY 16, 1980	9
7704A/7B53A INTENSIFIED MODE OPERATION	9-25	DEC 21, 1979	23

WIZARDS WORKSHOP INDEX

7000 SERIES

TITLE	ISSUE	DATE	PAGE
7704A/R7903/7904 HI-VOLTAGE MULTIPLIER RELIABILITY PROBLEMS	7-27	NOV 11,1977	19
7834 -15V SUPPLY RESISTANCE CHECK	9-25	DEC 21,1979	23
7834 7104 7704A 7844 7854 R7903 7904 DEFECTIVE CAPACITOR	10-13	JUNE 27,1980	10
7834 STORAGE	7-07	APR 1,1977	21
7834 TRIGGER OSCILLATIONS (BELOW B010250)	7-10	MAY 13,1977	27
7834/7104/7704A/7844/7854/R7903 & 7904 DEFECTIVE CAPACITOR	10-10	MAY 16,1980	9
7834/7633/7623A FLOOD GUN ANODE VOLTAGE SPECIFICATION WAIVER	10-22	OCT 31,1980	8
7834/7844/R7903/7904 WIRE LOOP INDUCTORS IN HF COMPENSATIONS	9-25	DEC 21,1979	24
7844 7104 7704A 7834 7854 R7903 7904 DEFECTIVE CAPACITOR	10-13	JUNE 27,1980	10
7844 INCORRECT PART NUMBER, MOUNTING SCREW FOR LV REGULATOR CHASSIS	9-23	NOV 30,1979	11
7844/7104/7704A/7834/7854/R7903 & 7904 DEFECTIVE CAPICATOR	10-10	MAY 16,1980	9
7844/7904 WRENCH FOR POWER ON SWITCH DODEC NUT	9-25	DEC 21,1979	24
7844/R, R7903 7904 TRANSFORMER REPLACEMENT	10-13	JUNE 27,1980	11
7854 7104 7704A 7834 7844 R7903 7904 DEFECTIVE CAPACITOR	10-13	JUNE 27,1980	10
7854 CALIBRATOR RISETIME AND FALLTIME	10-09	MAY 2,1980	5
7854 CONTROL RECTIFIER BOARD FAILURE	10-17	AUG 22,1980	8
7854 ROM BOARD JUMPER LOCATION	10-10	MAY 16,1980	10
7854/7104/7704A/7834/7844/R7903 & 7904 DEFECTIVE CAPACITOR	10-10	MAY 16,1980	9
7904 5 VOLT LIGHT SUPPLY	10-06	MAR 21,1980	8
7904 H.F. ABERRATION SPECIFICATION CORRECTION	10-08	APR 18,1980	8
7904 H.F. ABERRATION SPECIFICATIONS	10-06	MAR 21,1980	8
7904 INCORRECT PART NUMBERS FOR LV REGULATOR MOUNTING HARDWARE	9-23	NOV 30,1979	12
7904/7104/7704A/7834/7844/7854/R7903 & DEFECTIVE CAPACITOR	10-10	MAY 16,1980	9
7A13 CALIBRATION PROCEDURE	7-32	DEC 23,1977	20
7A13 CALIBRATION PROCEDURE CORRECTION	8-01	JAN 20,1978	21
7A13 LOOSE CONNECTORS ON READOUT DISPLAY	10-05	MAR 7,1980	9
7A13 LOOSE CONNECTORS ON READOUT DISPLAY	9-23	NOV 30,1979	11
7A13 TRANSISTOR TYPE CHANGED FOR Q330, Q340, Q430 AND Q440	9-07	APR 20,1979	36
7A16A/7A26 INPUT CAPACITANCE INCREASE	9-25	DEC 21,1979	17
7A19 VARIABLE ATTENUATOR REPLACEMENT, HELPFUL HINT	7-09	APR 29,1977	16
7A22 U.S. NAVY INCOMING INSPECTION BANDPASS REJECTS	7-09	APR 29,1977	16
7A24 OSCILLATION IN ADD WITH TRIGGER SOURCE SET TO MODE	9-25	DEC 21,1979	18
7A26 B15XXXX AND B17XXXX INSTRUMENTS WITH B18XXXX MANUAL CHANGE INFORMATION	8-18	JUN 2,1978	13
7A26 H.F. ADJUSTMENT	10-11	MAY 30,1980	12
7AXX AND 7BXX PLUG-IN SIDE ELECTRICAL SHIELDS	10-18	SEPT 5,1980	8
7B10/7B15 7B10/7B15 POSSIBLE SWEEP OSCILLATIONS	10-09	MAY 2,1980	4
7B53A "B" SWEEP INOPERATIVE S/N B210000 & UP	10-10	MAY 16,1980	8
7B53A 7B71 7B921/A 7D11 HELIDIAL SETTINGS	10-14	JULY 11,1980	8

1 JANUARY 1981

WIZARDS WORKSHOP INDEX

7000 SERIES

TITLE	ISSUE	DATE	PAGE
7B53A PROPAGATION DELAY	8-01	JAN 20,1978	22
7B71 7B53A 7B92/A 7D11 HELIDIAL SETTINGS	10-14	JULY 11,1980	8
7B92 TRIGGERING PROBLEMS	7-09	APR 29,1977	17
7B92/A 7BB53A 7B71 7D11 HELIDIAL SETTINGS	10-14	JULY 11,1980	8
7B92A -- 152-0153-00 VENDOR COMPATIBILITY	7-30	DEC 9,1977	21
7B92A TROUBLESHOOTING FIXTURE	8-05	MAR 3,1978	22
7D11 7B53A 7B71 7B92/A HELIDIAL SETTINGS	10-14	JULY 11,1980	8
7D12 A/D CONVERTER, U440, CORRECT PIN OUT ASSIGNMENT	10-17	AUG 22,1980	7
7D15 CALIBRATION PROCEDURE	7-11	MAY 27,1977	23
AUDIO CASSETTE TAPES AVAILABLE	7-03	FEB 4,1977	4
HARMONIC CONNECTORS AVAILABLE	8-04	FEB 17,1978	26
INTENSIFIED ZONE CONTRAST MODIFICATION FOR 7844/7904	7-05	MAR 4,1977	29
MOD #30219 TO 067-0587-01 AND 7A22	7-06	MAR 18,1977	19
R7844 RELIABILITY - MOD M30624	7-04	FEB 18,1977	15
R7903 7904 DEFECTIVE CAPACITOR	10-13	JUNE 27,1980	10
R7903 MANUAL CHANGE, CALIBRATION SECTION	9-25	DEC 21,1979	16
R7903/7104/7704A/7834/7844/7854/ & 7904 DEFECTIVE CAPACITOR	10-10	MAY 16,1980	9
REAR PANEL (PLUG-INS) MODIFIED	8-01	JAN 20,1978	20

WIZARDS WORKSHOP INDEX

MEDICAL PRODUCTS

COMMUNICATIONS DIVISION

TITLE	ISSUE	DATE	PAGE
067-0706-99 TEST UNIT MANUAL CORRECTION	10-22	OCT 31,1980	9
400 400 RECORDER MANUAL ERRORS	10-04	FEB 22,1980	8
400 CHART RECORDER GEAR PROBLEM	10-22	OCT 31,1980	9
400 MEDICAL MONITOR RECORDER COMBINATIONS	7-16	JUL 29,1977	18
400 MEDICAL RECORDER PRIOR TO B010600 REMOTE SAMPLE/MARK WIRING ERROR	7-15	JULY 22,1977	22
400 MEDICAL RECORDER PRIOR TO B010600 REMOTE SAMPLE/ MARK	7-13	JUN 24,1977	26
400 MEDICAL RECORDER, DIGITAL PRINT PROBLEM	7-29	NOV 25,1977	7
400 MEDICAL RECORDER - NEW MANUAL 070-2429-00	8-06	MAR 10,1978	17
400 MEDICAL RECORDER, DIGITAL PRINT PROBLEM	7-29	NOV 25,1977	7
400 MEDICAL RECORDER - NEW MANUAL 070-2429-00	8-06	MAR 10,1978	17
400 MEDICAL RECORDER RUN CONTROL	8-11	APR 14,1978	9
400 MEDICAL RECORDER WRITING QUALITY	7-28	NOV 18,1977	15
400 OPT. 4 RECORDER WIRING ERROR	7-20	AUG 26,1977	10
400 PAPER DRIVE MOTOR P/N	9-16	AUG 24,1979	8
400 RECORDER, U1075 REPLACEMENT	10-05	MAR 7,1980	11
400 RECORDER TENSION GATE	10-16	AUG 8,1980	10
400 RECORDER TRIGGER PROBLEM	10-22	OCT 31,1980	9
400 RECORDER CHART RATE ADJUSTMENT	8-30	OCT 27,1978	27
400 RECORDER DRIVE MOTOR P/N	9-17	SEPT 7,1979	13
400 RECORDER FEMALE CONNECTOR	9-06	APR 6,1979	38
400 RECORDER IMPROVEMENTS	8-03	FEB 3,1978	11
400 RECORDER MODULES WILL CHANGE	7-27	NOV 11,1977	15
400 RECORDER MULTIPLEX CONCERN	8-32	NOV 24,1978	14
400 RECORDER NEW RUN CONTROL CARD	7-27	NOV 11,1977	16
400 RECORDER OVERPRINT	9-04	MAR 2,1979	16
400 RECORDER PRINT ERROR	9-06	APR 6,1979	38
400 RECORDER PRINT HEAD PART NUMBER	8-07	MAR 17,1978	17
400 RECORDER PRINT HEAD PLATEN	8-19	JUN 9,1978	20
400 RECORDER RUN CONTROL CORRECTION	9-02	FEB 2,1979	25
400 RECORDER STYLUS PART NUMBER	9-06	APR 6,1979	38
400 RECORDER STYLUS PART NUMBER	8-19	JUN 9,1978	21
400 RECORDER TRACE NOISE	8-28	SEPT 29,1978	23
400 SERIES MEDICAL MONITORS, UNDERSIZED CRT'S	10-22	OCT 31,1980	10
400 SERIES GALVANOMETER CARE AND HANDLING	7-02	JUN 21,1977	11
400 SERIES INTERIM MANUAL CALIBRATION PROCEDURE CORRECTION	7-02	JAN 21,1977	10
400 SERIES MEDICAL--INSTRUMENT COMBINATIONS	7-27	NOV 11,1977	13
400 SERIES MEDICAL MONITORS	7-24	OCT 7,1977	10
400 SERIES MEDICAL WIRING ERROR OF SOURCE SWITCH	7-02	JAN 21,1977	10
400 SERIES RECORDER MANUAL CORRECTION (PN 070-2145-00)	7-07	APR 1,1977	22
400 SERIES RECORDER PRINTOUT	7-10	MAY 13,1977	30
400 SERIES RECORDER POWER UPDATE	7-05	MAR 4,1977	30

WIZARDS WORKSHOP INDEX

MEDICAL PRODUCTS

TITLE	ISSUE	DATE	PAGE
400 SERIES SERVICE MANUAL	7-06	MAR 18,1977	23
401 DRM POWER SUPPLY SQUEGGING	10-11	MAY 30,1980	13
401 TO MONITOR BATTERY CONTROL	9-04	MAR 2,1979	17
401 TOP COVERS	8-22	JULY 7,1978	12
401/413/414 DIGITAL READOUT DISPLAY DEVICES	9-17	SEPT 7,1979	13
401/413/414 READOUT DEVICES	9-04	MAR 2,1979	17
401/413/OPT.2 SQI	9-09	MAY 18,1979	7
408 POWER CORD	10-12	JUNE 13,1980	7
408/412/414 D-CELL BATTERY PACK CONVERSION	10-04	FEB 22,1980	9
408/412/413/414 MED MON-CRT SOCKET RELIABILITY IMPROVEMENT	10-05	MAR 7,1980	13
408/412/414/S661 REPLACEMENT KIT	10-05	MAR 7,1980	12
408/412/414 CABINET FRAMES	10-11	MAY 30,1980	14
408/412/413/414 BATTERY CHARGE CURRENT CHANGE	9-04	MAR 2,1979	18
408/412/413/414 CHASSIS LEAKAGE CURRENT	9-15	AUG 10,1979	11
408/412/413/414 POWER WIRE TERMINATION STANDOFF	9-07	APR 20,1979	30
408/412/414 ARS GLITCH SUPPRESSION	9-15	AUG 10,1979	11
408/412/414 POWER SUPPLY IMPROVEMENT	9-04	MAR 2,1979	18
408/414 POWER SUPPLY CHANGE	10-23	NOV 21,1980	5
410 BATTERY PACK	9-16	AUG 24,1979	8
410 BATTERY POWER PACK REPLACEMENT	8-02	JAN 27,1978	10
410 CRT REPLACEMENT KIT	10-22	OCT 31,1980	10
410 LEAKAGE CURRENT	9-14	JUL 27,1979	13
410 LEAKAGE TEST UPDATE	9-16	AUG 24,1979	8
410 MEDICAL MONITOR SUPPORT	9-15	AUG 10,1979	12
410 PATIENT CABLES	10-14	JULY 11,1980	9
412/413/414 VERTICAL OUTPUT TRANSISTORS	8-19	JUN 9,1978	21
413 B/B CHANGE (ERRATA)	8-21	JUN 30,1978	18
413 B/B CHANGE	8-19	JUN 9,1978	22
413 CIRCUIT BOARD RETAINER	7-25	OCT 21,1977	10
413 ECG LEAD FAULT IMPROVEMENT	9-04	MAR 2,1979	19
413 ECG NOISE	8-10	APR 7,1978	10
413 EMI IMPROVEMENT	10-19	SEPT 19,1980	15
413 EMI IMPROVEMENT (CORRECTION)	10-22	OCT 31,1980	10
413 GLITCH CAUSED BY 555 TIMES	9-24	DEC 14,1979	10
413 IMPROVEMENTS	8-04	FEB 17,1978	16
413 INSPIRATION SENSITIVITY	9-06	APR 6,1979	39
413 KIT 040-0855-00	8-08	MAR 24,1978	9
413 MAIN BOARD, 670-5068-00, CHANGE	8-06	MAR 10,1978	17
413 MECHANICAL PART CHANGES	9-04	MAR 2,1979	19
413 MEDICAL MONITOR AUDIO TAPES AVAILABLE	7-20	AUG 26,1977	10
413 MEDICAL MONITOR MANUAL ERROR	7-15	JULY 22,1977	22
413 MEDICAL MONITOR WIRING ERROR	7-13	JUN 24,1977	26

WIZARDS WORKSHOP INDEX

MEDICAL PRODUCTS

TITLE	ISSUE	DATE	PAGE
413 MONITOR - POWER SUPPLY MODIFICATION (CODE 18)	10-12	JUNE 13,1980	8
413 POWER SUPPLY KIT	10-14	JULY 11,1980	10
413 PRESSURE CIRCUIT PROTECTION	9-04	MAR 2,1979	20
413 READOUT IMPROVEMENT	9-04	MAR 2,1979	20
413 RESPIRATION	10-04	FEB 22,1980	11
413 RESPIRATION MICROPHONICS	10-09	MAY 2,1980	6
413 RESPIRATION WAVEFORM IMPROVEMENT	9-04	MAR 2,1979	21
413/414 GAUGE FACTOR	9-04	MAR 2,1979	21
413/414 POWER SUPPLY TROUBLESHOOTING	9-10	JUN 1,1979	7
413/414 TEMPERATURE CIRCUIT CALIBRATION RESISTORS	8-18	JUN 2,1978	7
413/414 VERTICAL OFFSET	9-01	AUG 10,1979	12
413A QUESTIONS AND ANSWERS	10-24	DEC 12,1980	8
414 - NOISE ON THE PULSE INPUT	7-07	APR 1,1977	22
414 MAIN CIRCUIT BOARD	10-24	DEC 12,1980	10
414 MEDICAL MONITOR (OPT. 4)	10-11	MAY 30,1980	15
414 MOD TO RATE CONVERTER	9-05	MAR 16,1979	22
414 POWER CORD	10-11	JUNE 13,1980	7
414 RATE OVERRANGE INTERMITTENT - ERRATA	9-04	MAR 2,1979	22
414 RATE OVERRANGE INTERMITTENT	8-32	NOV 24,1978	15
414 RELIABILITY IMPROVEMENT (ERRATA)	8-19	JUN 9,1978	20
414 RELIABILITY IMPROVEMENT	8-17	MAR 26,1978	6
414 VERTICAL OUTPUT IMPROVEMENT	9-05	MAR 16,1979	22
414/408 POWER SUPPLY CHANGE	10-23	NOV 21,1980	5
606 MONITOR, HIGH VOLTAGE SHIELD	7-31	DEC 16,1977	16
AUDIO CASSETTE TAPE AVAILABLE	7-07	APR 1,1977	9
BATTERY PARTS AND MAINTENANCE	8-11	APR 14,1978	8
BIOPHYSICAL MEASUREMENTS CONCEPT BOOK	7-08	APR 15,1977	12
CHART PAPER TENSION GATE - TEK MADE MODULE	8-10	APR 7,1978	10
CORRECTING MED. MONITORS TO RECORDER TEST BOARD SOB OF 12-2-77, ISSUE 13-77	7-31	DEC 16,1977	17
CORRECTION ON 400 RECORDER IMPROVEMENTS ARTICLE	8-05	MAR 3,1978	17
CRT SOCKET KIT P/N 040-0876-01	10-16	AUG 8,1980	10
DIGITAL READOUT MODULE (DRM)	8-06	MAR 10,1978	14
DIGITAL VOLTMETER ANALOG IC SOCKET	8-30	OCT 27,1978	26
ECG SIGNAL GETTING INTO PULSE ON 414	7-07	APR 1,1977	22
GOULD-STATHAM PRESSURE TRANSDUCERS	10-18	SEPT 5,1980	10
IC SOCKET REPLACEMENT PARTS	9-05	MAR 16,1979	17
LITTLEFUSE FUSES 0.2A, 250V, 12 SEC. 3AG, P/N 159-0044-00	8-08	MAR 24,1978	8
MEDICAL CAL MONITOR MOUNTING	7-29	NOV 25,1977	6
MEDICAL MAINTENANCE	7-26	OCT 28,1977	22
MEDICAL MONITOR ACCESSORIES	10-11	MAY 30,1980	13
MEDICAL MONITORS SYSTEM CALIBRATION MANUAL	10-13	JUNE 27,1980	13
MEDICAL MONITOR PRESSURE CALIBRATIONS	8-07	MAR 17,1978	16

1 JANUARY 1981

WIZARDS WORKSHOP INDEX

MEDICAL PRODUCTS

TITLE	ISSUE	DATE	PAGE
MEDICAL MONITOR MOUNTING ADAPTER 014-0054-00	7-29	NOV 25,1977	6
MEDICAL MONITORS LOSING INTENSITY	7-29	NOV 25,1977	5
MEDICAL MONITOR GAUGE FACTOR MODS	8-24	AUG 4,1978	12
MEDICAL MONITOR SOCKET REPLACEMENT	8-20	JUN 23,1978	19
MEDICAL MONITOR STERILIZATION	7-32	DEC 23,1977	10
MEDICAL MONITOR BATTERY SOURCE	7-29	NOV 25,1977	5
MEDICAL MONITOR GAUGE FACTOR MODS	8-24	AUG 4,1978	12
MEDICAL MONITOR MECHANICAL CHANGES	8-06	MAR 10,1978	16
MEDICAL PRODUCTS-REFER OUTSIDE INQUIRIES TO BEAVERTON	8-13	APR 28,1978	17
MEDICAL PRODUCTS - WARRANTY POLICY (DOMESTIC ONLY)	9-25	DEC 21,1979	25
MEDICAL PRODUCTS - REFER OUTSIDE INQUIRIES TO BEAVERTON	8-13	APR 28,1978	17
MEDICAL TEMPERATURE CALIBRATION	8-07	MAR 17,1978	16
MEDICAL TRANSDUCERS - WARRANTY	9-04	MAR 2,1979	16
MONITOR BATTERY CHARGE FIXTURE	9-05	MAR 16,1979	20
MOUNTING ADAPTER FRICTION SCREWS	8-24	AUG 4,1978	12
POWER SUPPLY CAPACITOR CHANGE	9-02	FEB 2,1979	25
PULSE OSCILLATIONS	8-30	OCT 27,1978	26
RESPIRATION HETERODYNING	8-30	OCT 27,1978	27
RESPIRATION WAVEFORM SPIKES	8-30	OCT 27,1978	27
SERVICE COST FORECAST AND DEMO SUPPORT PACKAGE ERROR	8-08	MAR 24,1978	9
SWITCHES NOW FROM NEW VENDOR	8-31	NOV 10,1978	19
TENSION ADJUST NEW TEK-MADE MODULE	8-11	APR 14,1978	8
VIDEO CASSETTES AVAILABLE	7-07	APR 1,1977	9
WIRING ERROR ON NEW TEK MADE RECORDER MODULE	8-07	MAR 17,1978	17

SPECTRUM ANALYZERS

TITLE	ISSUE	DATE	PAGE
1501 1502 1503 BATTERY METER REPLACEMENT KITS	10-11	MAY 30,1980	16
1501/1503 NTENSITY RANGE IMPROVEMENT	10-04	FEB 22,1980	12
1502 1503 VERTICAL AMP/SLOW RAMP CIRCUIT BOARD REPLACEMENT	10-11	MAY 30,1980	17
1502 STATIC SUPPRESSOR	10-24	DEC 12,1980	13
1502/1503 IMPROPER CHARGING OF BATTERY PACKS	10-02	JAN 25,1980	13
1502/1503 OUTPUT AMPLIFIER CIRCUIT BOARD REPLACEMENT	10-04	FEB 22,1980	13
1502/1503 HIGH VOLTAGE POWER CIRCUIT BOARD REPLACEMENT	10-04	FEB 22,1980	12
1502/1503 FUSED BATTERY PACKS	10-23	NOV 21,1980	15
1503 OPTION 1/TEST PULSE LENGTH SELECTOR PUSHBUTTON	10-05	MAR 7,1980	18
1503 REPLACEMENT OF Q1558 OR Q1578	10-11	MAY 30,1980	17
492 - 33KHZ POWER SUPPLY SPURS	10-16	AUG 8,1980	11
492/492P SER VOL #2 - POWER SUPPLY DIAGRAM CORRECTION (REF PULL-OUT)	10-18	SEPT 5,1980	A-1
492/492P SERVICE POINTS	10-23	NOV 21,1980	15
5L4N NEW LATCH ASSY "ADDENDUM TO W2 ARTICLE-MAR 7,1980"	10-07	APR 4,1980	7
5L4N NEW LATCH ASSEMBLY	10-05	MAR 7,1980	14
5L4N REPLACEMENT KIT FOR CENTER FREQUENCY DIAL DRIVE GEAR	10-05	MAR 7,1980	15
5L4N REPLACEMENT KIT FOR K160 RELAY	10-04	FEB 22,1980	13
7L12 & 7L13 FL370 REPLACEMENT	8-20	JUN 23,1978	22
7L12 MOD HB	9-04	MAR 2,1979	26
7L12 THREE-LEGGED REGULATOR ON REF LEVEL READOUT INSERTED WRONG (M32661)	8-13	APR 28,1978	22
7L12, 7L13, L-1, & L-2 RELAY RELIABILITY IMPROVEMENT	7-10	MAY 13,1977	14
7L12/7L13 PART REPLACEMENT KIT FOR FL360	10-04	FEB 22,1980	14
7L12/7L13 ATTENUATORS	10-03	FEB 8,1980	15
7L12/7L13 INTERMITTENT EDGE CARD CONNECTOR	9-15	AUG 10,1979	13
7L12/7L13/7L18 INTERNAL RESOLUTION FILTER SHAPE SPECIFICATIONS	9-09	MAY 18,1979	9
7L13 PROM'S	8-12	APR 21,1978	15
7L13 REGULATOR MOD (32662) INSTALLED WRONG	8-15	MAY 12,1978	12
7L13, REPLACEMENT OF YIG OSCILLATOR	10-01	MAR 7,1980	16
7L18 - DIFFICULTY REMOVING FROM MAINFRAMES	9-05	MAR 16,1979	32
7L18 INTERMODULATION CHECK	8-11	APR 14,1978	9
7L18 MOD FB	9-04	MAR 2,1979	26
7L18 REPLACEMENT PARTS KIT FOR U825	10-04	FEB 22,1980	14
7L18 RETURN FOR REPAIR LABELS	8-18	JUN 2,1978	9
7L18 RF CABLES	10-03	FEB 8,1980	15
7L5 CHANGE TO SWEEP OFFSET CIRCUIT	10-05	MAR 7,1980	15
7L5 CR836 MARKED BACKWARDS ON PRINTED CIRCUIT BOARD	9-05	MAR 16,1979	32
7L5 MODIFICATION TO REPLACE U2235 OR U5070	9-05	MAR 16,1979	31
7L5 MODIFICATION TO REPLACE U830	9-05	MAR 16,1979	31
7L5 NEW STORAGE BOARD, ADDENDUM TO JAN 12, 1979 ARTICLE	10-06	MAR 21,1980	9
7L5 NEW STORAGE BOARD, 040-0872-01, PRICE INCREASE	10-22	OCT 31,1980	11
7L5 OPTION 21, CHANGE TO SWEEP OFFSET CIRCUIT	10-05	MAR 7,1980	17

WIZARDS WORKSHOP INDEX

SPECTRUM ANALYZERS

TITLE	ISSUE	DATE	PAGE
7L5 OPTIONS	8-20	JUN 23,1978	22
7L5 POTENTIAL RELIABILITY PROBLEM	7-06	MAR 18,1977	10
7L5 POTENTIAL RELIABILITY PROBLEM	7-10	MAY 13,1977	12
7L5 PRESET R665 AND R664	8-13	APR 28,1978	21
7L5 SPECIFICATION CHANGE	9-09	MAY 18,1979	8
7L5 SPECTRUM ANALYZER COMPATIBILITY PROBLEM	7-04	FEB 18,1977	12
7L5 STORAGE BOARD	9-01	JAN 12,1979	16
7L5 TRANSVERSE VERTICAL INTERFACE BOARD, P/N 670-3588-00	9-05	MAR 16,1979	32
7L5, R4722 ELECTRICAL PARTS LIST & SCHEMATIC CHANGE	9-09	MAY 18,1979	8
7L5,OPTION 25 TRACKING GENERATOR AVAILABLE AS KIT	10-01	JAN 11,1980	16
AN EXPLANATION OF THE MISSING SEGMENT IN THE 7L5 SPECTRUM ANALYZER DIGITAL STORA	7-15	JULY 22,1977	14
LEVELING OF HEWLETT PACKARD HP 8620C SYSTEM	10-23	NOV 21,1980	6
MEASURING HARMONIC DISTORTION WITH A SPECTRUM ANALYZER - CORRECTION	7-06	MAR 18,1977	24
PA1, REPLACEMENT OF Q3021, Q3022 AND Q4021	10-11	MAY 30,1980	16
RECOMMENDED EQUIPMENT FOR SIGNAL INSERTION ON SPECTRUM ANALYZERS	9-18	SEPT 21,1979	10
SPECTRUM ANALYZER SPOT-O-GOLD (SOG) CONNECTORS	10-22	OCT 31,1980	11
SPECTRUM ANALYZER C95 SOCKET REPAIR	10-22	OCT 31,1980	11
TUTORIAL - MEASURING HARMONIC DISTORTION WITH A SPECTRUM ANALYZER	7-05	MAR 4,1977	1

TITLE	ISSUE	DATE	PAGE
1441 1430 1440 1460 1461 MISSNG FIBER WASHER ON PWR SUPPLY BOARD	10-15	JULY 25,1980	10
140 SERIES - REGULATION OF +10V SUPPLY DURING CRYSTAL OVEN WARM-UP	9-18	SEPT 21,1979	14
140 SERIES - SUBCARRIER OSCILLATOR REPLACEMENT KITS	8-25	AUG 18,1978	10
140/144, SUBCARRIER OSCILLATOR REPLACEMENT	10-01	JAN 11,1980	18
1401 1401A BATTERY CHARGE LEVEL METER REPLACEMENT KIT	10-09	MAY 2,1980	9
1405 PARTS KIT FOR REPLACEMENT OF U500	10-09	MAY 2,1980	9
1405/VAR IN VF IN CR170,172,174,176 CAUSE SAMPL GATE IMBALANCE	10-25	DEC 19,1980	8
1410 - TSG-1 BELOW S/N B010169, RESIDUAL SUBCARRIER ON OUTPUT ELIMIN	7-27	NOV 11,1977	18
1410 - U800 MICA INSULATOR REPLACEMENT	8-16	MAY 19,1978	21
1410 - WIRING CORRECTION TO PROTECT 155-0145-00	8-32	NOV 24,1978	18
1410 -- PREMATURE FAILURE OF U-800	7-10	MAY 13,1977	14
1410 AND 1411 - CORRECT WIRING OF INTERCONNECT BOARD TO SUBCARRIER INPUT BOARD	8-23	JUL 21,1978	26
1410 AND 1411 SCHEMATIC CORRECTION	8-29	OCT 13,1978	14
1410 BLACK BURST - MOD FOR VARIABLE BLANKING	9-06	APR 6,1979	48
1410 BLANK PANEL PART NUMBER INFORMATION	7-04	FEB 18,1977	12
1410 CALIBRATION	7-31	DEC 16,1977	21
1410 LINE SELECTOR CIRCUIT BOARD	7-18	AUG 12,1977	10
1410 MANUAL	7-03	FEB 4,1977	14
1410 MANUAL CHANGE/OPERATOR TRAP	8-10	APR 7,1978	19
1410 MODULAR REPAIR	7-24	OCT 7,1977	11
1410 OSCILLATOR INSTABILITY	7-15	JULY 22,1977	16
1410 SERIES - SPG11, 12, 22 CAPACITOR FIT PROBLEM	10-22	OCT 31,1980	14
1410 SERIES/EXTENDER BOARDS AVAILBLE FOR SPG,TSG,PLUG-INS.	10-16	AUG 8, 1980	12
1410 SERIES - CHASSIS TOP COVER	9-03	FEB 16,1979	28
1410 SHORT TERM FREQUENCY STABILITY	7-16	JULY 29,1977	13
1410 SPG, TSG SERIES DEFECTIVE TRIMMER POT, PART NUMBER 311-1915-00	10-09	MAY 2,1980	9
1410/1411 - U129/U119 IC SOCKETS	9-02	FEB 2,1979	39
1410/1411 NEW PART NUMBER FOR CABINET FRAME	9-07	APR 20,1979	33
1410/1411 POWER SUPPLY CURRENT LIMIT	8-07	MAR 17,1978	19
1410/1411 POWER SUPPLY MODIFICATION KIT	9-06	APR 6,1979	50
1410/1411 SERIES - SPG TIMING ERRORS CAUSED BY TEMPERATURE SENSITIVE 74LS163	8-27	SEPT 15,1978	27
1410/1411 SPRING CLIPS FOR REMOTE PROGRAM PLUG	8-05	MAR 3,1978	21
142 CONVERGENCE - MANUAL CHANGE INFORMATION	8-16	MAY 19,1978	13
142,SUBCARRIER OSCILLATOR REPLACEMENT	10-01	JAN 11,1980	18
1420 POWER SUPPLY NOISE	10-22	OCT 31,1980	15
1420 SYNC STRIPPER MALFUNCTION AT HIGH TEMPERATURES	10-05	MAR 7,1980	21
1420 TRANSISTOR IDENTIFICATION	7-01	JAN 14,1977	12
1420-21-22 T.O. 126 LEAD CONFIGURATION ERROR	7-05	MAR 4,1977	23

TITLE	ISSUE	DATE	PAGE
1420/1421/1422 CRYSTAL SOCKET CHANGE	8-23	JUL 21,1978	27
143 - CIRCUIT BOARD PART NUMBER CHANGES	8-27	SEPT 15,1978	26
143 - RCA "GOLD CHIP" OP-AMP REPLACEMENT	8-27	SEPT 15,1978	26
143 CAPACITOR INSTALLED BACKWARDS	8-09	MAR 31,1978	16
143 INTERMITTENT POWER SUPPLY	9-06	APR 6,1979	45
1430 1440 1441 1460 1461 -MISSNG WASHR ON PWR SUPP BOARD, PART NO CORR	10-19	SEPT 19,1980	17
1430 INTERFACE	8-14	MAY 5,1978	12
1430 WIRING ERROR ON LINE SELECT SWITCH	9-04	MAR 2,1979	27
1430/1440/1441/1460/1461 MSG FIBER WASHER ON POWER SUPPLY BRD	10-15	JULY 25,1980	10
1430/1441 INCREASE SYNC LOCK UP RANGE	9-14	JULY 27,1979	14
1430/1441/1461 DIFFERENTIAL PHASE ADJUSTMENT	8-05	MAR 3,1978	21
1440 1430 1441 1460 1461 MISSNG FIBER WASHER ON PWR SUPPLY BOARD	10-15	JULY 25,1980	10
1440 1441 1430 1460 1461 -MISSNG WASHR ON PWR SUPP BOARD, PART NO CORR	10-19	SEPT 19,1980	17
1440 4H OSCILLATOR ADJUSTMENT RANGE	10-22	OCT 31,1980	16
1440 DECODED BOARD - VIRS RECO.	9-08	MAY 4,1979	18
1440 DECODER BOARD - VIRS RECOGNITION PROBLEM ADDENDUM	9-11	JUN 15,1979	6
1440 I2R, I3B, I3C VARIABLE SYNC WIDTH MODIFICATION	10-03	FEB 8,1980	16
1440 MANUAL CORRECTION	7-25	OCT 21,1977	13
1440 MOD 12R-13B-13C - MANUAL CORRECTION	8-19	JUN 9,1978	24
1440 MOD 13B SHIPPING ERROR	7-29	NOV 25,1977	10
1440 MODS 12R, 13R, 13C	10-22	OCT 31,1980	15
1440 ZERO CARRIER CHECK	7-03	FEB 4,1977	14
1440/741 -OP. -AMP. REPLACEMENT	7-06	MAR 18,1977	12
1440/741 OP - AMP FAILURE (156-0158-00)	7-05	MAR 4,1977	24
1441 - INTERMITTENT GROUND CONNECTIONS	8-25	AUG 18,1978	11
1441 SUBCARRIER LOCK UP OUT OF PHASE ELIMINATED	7-13	JUNE 24,1977	23
1441/1461 - RCA "GOLD CHIP" OP-AMP REPLACEMENT	8-27	SEPT 15,1978	27
145-M, SUBCARRIER OSCILLATOR REPLACEMENT	10-01	JAN 11,1980	18
145/R145 OSCILLATOR QUILTS AFTER TURNED OFF AND ON	7-07	APR 1,1977	17
1450 CABLE CLAMP LOOSENESS PROBLEM	10-23	NOV 21,1980	20
1450 PART NUMBER CHANGE FOR 151-0472-00	10-03	FEB 8,1980	19
1450 SERIES/AVAILABLE IN THE FIELD	10-21	OCT 17,1980	17
1450, PART NUMBER CHANGE FOR 151-0472-00	10-01	JAN 11,1980	27
1450-1 POWER LEVEL ADJUSTMENT	10-25	DEC 19,1980	10
145M - RCA "GOLD CHIP" OP-AMP REPLACEMENT	8-27	SEPT 15,1978	26
146, SUBCARRIER OSCILLATOR REPLACEMENT	10-01	JAN 11,1980	19
1460 1430 1440 1441 1461 MISNG FIBER WASHER ON PWR SUPPLY BRD	10-15	JULY 25,1980	10
1460 1461 1430 1440 1441 -MISSNG WASHR ON PWR SUPP BOARD, PART NO CORR	10-19	SEPT 19,1980	17
1460/BURST GAIN "BOUNCE" WITH SOUND IN SYNC	10-13	JUNE 27,1980	16

WIZARDS WORKSHOP INDEX

TELEVISION PRODUCTS

TITLE	ISSUE	DATE	PAGE
1461 - TEKTRONIX PART NUMBER FOR PROGRAMMED MICROCIRCUIT	6-27	SEPT 15,1978	28
1461 1430 1440 1441 1460 MISSNG FIBER WASHER ON PWR SUPPLY BRD	10-15	JULY 25,1980	10
147/149 PULSE TO BAR RATIO & CHROMA GAIN MEASUREMENT	9-14	JULY 27,1979	14
147/149A RIPPLE SPECIFICATIONS	10-25	DEC 19,1980	7
1470 CRYSTAL DRIFT	7-15	JULY 22,1977	16
1470 CRYSTAL DRIFT/1441 HUM/1410 SUBCARRIER PHASING	7-15	JULY 22,1977	17
1470 CRYSTALS P/N 158-0116-00	7-30	DEC 9,1977	19
1470 H. SYNC PROBLEM	7-04	FEB 18,1977	12
1470 LOSS OF FLATNESS IN MULTIBURST MODE	10-06	MAR 21,1980	11
1470 TROUBLESHOOTING HINT FOR LOSS OF SYNC IN GEN LOCK MODE	10-01	JAN 11,1980	27
1470/1474 CHANGES TO COLOR PHASE CONTROLLER BOARD	10-01	JAN 11,1980	28
1470/1474 FREQUENCY STABILIZATION	9-03	FEB 16,1979	28
1470/1474 POWER SUPPLY REGULATION	9-03	FEB 16,1979	28
1474 BURST GATE COINCIDENT WITH HORIZONTAL SYNC	10-02	JAN 25,1980	18
147A 148 148M 149A UNRELIABLE CAPACITOR, P/N 283-0192-00	10-15	JULY 25,1980	13
147A BREEZEWAY SPECS	10-22	OCT 31,1980	13
147A/148M/149A UNRELIABLE CAPACITOR,P/N 283-0192-00 (CORR)	10-19	SEPT 19,1980	16
147A/149A TEMPORARY CHANGE OF PART NUMBER FOR PWR LAMP ASSY	10-15	JULY 25,1980	14
147A/149A CORRECTION TO EXTERNAL VITS GAIN ADJUST	10-10	MAY 16,1980	12
147A/149A BREEZEWAY SPECS (CORRECTION)	10-24	DEC 12,1980	15
147A/149A MOD G8C, G8E, G9V SHIPPED TO CANADA	7-32	DEC 23,1977	18
147A/149A OSCILLATIONS ON THE SYNC PULSE	9-06	APR 6,1979	45
147A/149A VIDEO LINE 21, DELETE COLOR BARS OUT OF SPEC	9-06	APR 6,1979	46
147A/149A/650HR SERIES, CRYSTAL MAY SHORT CIRCUIT	10-24	DEC 12,1980	16
148 - R294 PART NUMBER CHANGE	8-23	JUL 21,1978	25
148-0034-XX RELAY REPLACEMENT	8-06	MAR 10,1978	18
148-0034-XX RELAYS REPLACEMENT	7-27	NOV 11,1977	18
148/148M,149A/147A UNRELIABLE CAPACITOR P/N 283-0192-00	10-15	JULY 25,1980	13
1480 - CORRECTED PART NUMBER FOR LATCH INDEX	8-18	JUN 2,1978	11
1480 C/R SERIES - IMPROVED 0.1 MICROSECOND SWEEP LINEARITY	9-14	JULY 27,1979	15
1480 CRT SETUP	7-18	AUG 12,1977	10
1480 INTERMITTENT TRIGGERS, B06000 AND UP	8-15	MAY 12,1978	14
1480 OPT. 8 - ERRATIC OPERATION OF 2 FIELD DISPLAY	8-22	JUL 7,1978	19
1480 OPTION 6 - BNC TO WECO ADAPTER	8-18	JUN 2,1978	11
1480 SERIES/DEFECTIVE HIGH VOLTAGE TRANSFORMER	10-12	JUNE 13,1980	9
1480 SERIES/SPACER REQUIRED FOR PUSHBUTTON SWITCHES	10-12	JUNE 13,1980	10
1480 SERIES CORRCION FOR INCOMPLETE D.C. RESTORER	10-08	APR 18,1980	11
1480 SERIES, PART NUMBER FOR RUBBER WASHER UNDER CRT BEZEL	10-09	MAY 2,1980	10
1480 SERIES, D.C. RESTORER, WIZARD CORRECTION	10-23	NOV 21,1980	21
1480 SERIES - CANCEL INSTRUMENT MODIFICATION NOTICE	8-34	DEC 22,1978	21

TELEVISION PRODUCTS

TITLE	ISSUE	DATE	PAGE
1480 SERIES - CRT NECK CLAMP ADJUSTMENT	8-30	OCT 27,1978	34
1480 SERIES - HORIZONTAL TIMING PROCEDURE CHANGE	9-06	APR 6,1979	50
1480 SERIES - MOD KITS FOR REPLACEMENT OF VERTICAL CIRCUIT BOARDS	8-23	JUL 21,1978	27
1480 SERIES - SYNC SEPARATOR MOD, B06 AND UP	9-08	MAY 4,1979	20
1480 SERIES - VERTICAL GAIN DRIFTS WITH TEMPERATURE CHANGE	8-30	OCT 27,1978	35
1480 SERIES FAILURE TO FREE RUN IN TWO FIELD DISPLAY	9-18	SEPT 21,1979	15
1480 SERIES FRONT PANEL MOUNTED POTS	7-06	MAR 18,1977	12
1480 SERIES INSTRUCTION MANUAL FOR SERIAL NUMBER B06 AND UP	9-08	MAY 4,1979	20
1480 SERIES INTERMITTENT TRIGGERING IN CAL MODE	9-13	JULY 13,1979	8
1481/1485 OPTION 08 INTERMITTENT SINGLE FRAME RECOGNITION	10-19	SEPT 19,1980	20
149A,147A,148/148M UNRELIABLE CAPACITOR, P/N 283-0192-00	10-15	JULY 25,1980	13
149A/R149A NOISE SPIKE DURING VERTICAL BLANKING COLOR BARS	9-13	JULY 13,1979	9
1500 SERIES - SEALING BATTERY PACKS	9-03	FEB 16,1979	30
155-0032-01 REPLACED IN TV PRODUCTS	10-03	FEB 8,1980	19
155-0147-00, 155-0147-02,050 REPLACEMENT KITS FR TV PRODUCTS	10-09	MAY 2,1980	11
156-0388-00 DISQUALIFIED VENTOR	9-18	SEPT 21,1979	13
1900 INSTRUCTION MANUAL CORRECTION	10-24	DEC 12,1980	17
1900/CALIBRATION PRECAUTIONS	10-17	AUG 22,1980	9
1900/OPERATING PRECAUTIONS FOR 1900 TEST INSERTION GEN	10-13	JUNE 27,1980	14
1900/SUBCARRIER OUT TO FL/FELD OUT BRST PHSE RELTNSHIP MAY BE RANDOM	10-20	OCT 3,1980	12
1900/SUBCARRIER OUT/FULL FIELD OUT BURST PHASE RELATIONSHIP RANDOM (CORN 1	10-22	OCT 31,1980	17
1980 POWER-UP DIAGNOSTICS	10-23	NOV 21,1980	22
290-0117-00 HIGH FAILURE RATE IN 670A AND 520 SERIES	8-15	MAY 12,1978	14
520 A CALIBRATION PROCEDURE CHANGE	10-08	APR 18,1980	9
520 SERIES DIFF GAIN TRACE NOISE	10-23	NOV 21,1980	16
520/R520 NTSC VECTORSCOPE	10-04	FEB 22,1980	20
520A ACCESS DOOR SLIDE	7-21	SEPT 9,1977	14
520A REPLACEMENT OF C1423	8-01	JAN 20,1978	19
520A SERIES, 1420 SERIES, INSULATORS FOR CRYSTALS	10-01	JAN 11,1980	19
520A SERIES, ELIMINATION OF "NEWTON RINGS" ON CRT SCALE	10-05	MAR 7,1980	20
520A/ PART NUMBER FOR SLIDE DOOR TRACK SPACER	10-14	JULY 11,1980	11
520A/521A/522A CHANGES	8-07	MAR 17,1978	18
520A/521A/522A CHANGES (CORRECTION)	8-13	APR 28,1978	23
520A/528/1480 SERIES - 283-0071-00 AND 283-0162-00	9-19	OCT 5,1979	7
520A/R520A, PART NUMBER CHANGE FOR PUSH BUTTON KNOBS	10-08	APR 18,1980	10
528 - C512 INTERMITTENT CONNECTION	8-28	SEPT 29,1978	27
528 - PART NUMBER CHANGE FOR HORIZONTAL OUTPUT TRANSISTOR	10-15	JULY 25,1980	14
528 - RGB RELAY - K370 MAY CAUSE INTERMITTENT OR TEMPERATURE RELATED MALFUNCTION	9-19	OCT 5,1979	8

TELEVISION PRODUCTS

TITLE	ISSUE	DATE	PAGE
528 - RINGING BETWEEN SYNC PULSE AND BURST	8-18	JUN 2,1978	10
528 INSUFFICIENT FOCUS CONTROL	7-01	JAN 14,1977	12
528 OPTION 2 PARTS LIST	8-30	OCT 27,1978	34
528 POWER SUPPLY - BURNED IN PART FOR C472	9-15	AUG 10,1979	16
528 Q520 RELIABILITY	10-25	DEC 19,1980	8
528 RELIABILITY IMPROVEMENT MOD, M24530	7-05	MAR 4,1977	24
528 RESISTOR RELIABILITY PROBLEM	10-22	OCT 31,1980	12
528 SYNC SWITCH & DC RESTORER SWITCH CHANGED TO CORRECT INTER. MALFCTN.	10-08	APR 18,1980	10
528 TRANSISTOR HEAT SINK CHANGES	9-03	FEB 16,1979	27
528 UNDERRATED POWER SUPPLY CAPACITOR C472	10-01	JAN 11,1980	20
528 VERTICAL, NOISE ON TRACE	10-23	NOV 21,1980	18
529/RM529 UPDATE FOR CRT REPLACEMENT KIT	10-08	APR 18,1980	10
630, EHT SUPPLY PART NUMBER	10-01	JAN 11,1980	20
632 MONITORS C495 CHANGES	7-21	SEPT 9,1977	15
650 EHT AND 741 OP. AMP FAILURES	7-04	FEB 18,1977	13
650 HR SERIES - MANUAL CORRECTION	8-32	NOV 24,1978	17
650 HR, PART NUMBER FOR CRT	10-01	JAN 11,1980	20
650 SERIES IMPROVED CONVERGENCE PROCEDURE	8-16	MAY 19,1978	15
650 SERIES RELIABILITY MOD KIT UPDATE	7-05	MAR 4,1977	25
650 SERIES: WIRE CRIMP PROBLEM	8-14	MAY 5,1978	12
650/650A POWER SUPPLY BOARD SHORTING HAZARD	7-11	MAY 27,1977	16
650/650A/650HR SERIES EHT	10-20	OCT 3,1980	11
650/670 YOKE: GLUE REMOVAL	8-20	JUN 23,1978	23
650/670/650A/670A COLOR TEMPERATURE SETUP LEVELS	7-10	MAY 13,1977	15
650A - APERTURE SWITCH	8-18	JUN 2,1978	11
650A - BLUE ONLY MALFUNCTION	7-12	JUNE 10,1977	17
650A MANUAL	7-06	MAR 18,1977	13
650A SERIES/DEFECTIVE CAPACITORS P/N 290-0521-00	10-20	OCT 3,1980	11
650A SERIES, CRT PART NUMBER CHANGE	10-01	JAN 11,1980	21
650A SERIES - +5 VOLT FUSE BLOWING	9-05	MAR 16,1979	33
650A SERIES - MOD TO ELIMINATE EXCESSIVE ELECTRO MAGNETIC ...CUSHION TRANSFORMER	9-08	MAY 4,1979	16
650A SERIES - SLIGHT HOOK IN VERTICAL CONVERGENCE LINES	9-10	JUN 1,1979	9
650A SERIES - VISIBLE LINE ON CRT	8-19	JUN 9,1978	24
650A SERIES CIRCUIT BOARDS COMPATIBLE WITH 650HR SERIES	9-08	MAY 4,1979	16
650A SLIDE ASSEMBLY	7-22	SEPT 23,1977	11
650A/650HR SERIES, MODIF TO REEVENTP P5POTNBURNGTOFUCRTNPHOSPHOR	10-11	MAY 30,1980	19
650A/650HR SERIES, PARTS KITS AVAIL. TO PREVENT SPOT BURNING OF CRT	10-23	NOV 21,1980	20
650A/651A/652A/653A COLOR TEMPERATURE SETUP	7-31	DEC 16,1977	21
650A/653A SERIES - CONVERGENCE IMPROVEMENT	8-23	JUL 21,1978	26
650A/670A DEFECTIVE EHT'S	10-16	AUG 8, 1980	12

WIZARDS WORKSHOP INDEX

TELEVISION PRODUCTS

TIITLLE	ISSUE	DATE	PAGE
650A/670A COLOR MONITORS, PART NO CHNGE FOR Q5126/Q5915/Q6137	10-11	MAY 30, 1980	24
650A/670A SYNC STRIPPER MALFUNCTION AT HIGH TEMPERATURES	10-01	JAN 11, 1980	21
650A/670A SERIES, NEW PART FOR EHT TO CORRECT CONVERGENCE DRIFT	10-05	MAR 7, 1980	20
650A/670A/670AL COLORIMITRY, MOD PROPOSAL CTV0325	8-12	APR 21, 1978	16
650A/REWORK OF 119-0320-04 EHT SUPPLIES	10-12	JUNE 13, 1980	9
650HR/147A/149A SERIES, CRYSTAL MAY SHORT CIRCUIT	10-24	DEC 12, 1980	16
653A/656A CIRCUIT BOARDS COMPATIBLE WITH 653HR/656HR CIRCUIT BOARDS	9-08	MAY 4, 1979	18
670 CRT REPLACEMENT KIT	10-25	DEC 19, 1980	8
670 FAMILY DEFLECTION YOKE MOUNTING	8-28	SEPT 29, 1978	27
670 H.V. PHASING PROBLEMS	7-01	JAN 14, 1977	13
670 SERIES RELIABILITY IMPROVEMENT	7-05	MAR 4, 1977	26
670/670A-1 CR5021 NOT GROUNDED	7-09	APR 29, 1977	14
670/671/672 DEFLECTION COIL PARTS REPLACEMENT KIT	10-01	JAN 11, 1980	27
670A - MOD 31454 CORRECTS MOMENTARY CHANGE OF PICTURE SIZE	7-29	NOV 25, 1977	11
670A SCAN FAILURE	8-07	MAR 17, 1978	19
670A SERIES, MODIF TO HORIZNTL OUTPUT CIRCUITS REPLCMNT ARTICLE	10-11	MAY 30, 1980	24
670A SERIES, REPLACEMENT OF U5770, U5860, U5945, U5946	10-01	JAN 11, 1980	26
670A SERIES, MODIFICATION TO HORIZONTAL OUTPUT CIRCUITS	10-09	MAY 2, 1980	7
670A SETUP PROCEDURE	8-27	SEPT 15, 1978	27
670A TIP-OUT DOOR	7-05	MAR 4, 1977	26
670A/670A-1/671A, POWER SUPPLY FILTER CAPACITOR MOUNTING BASE	10-01	JAN 11, 1980	26
670A/670A-1 671A/ CR5020 5021 PART NUMBER CHANGE	10-02	JAN 25, 1980	20
670A/670A1/671A BURNING R5230	8-07	MAR 17, 1978	19
670A/670A1/671A BURNING R5230 CORRECTION	8-10	APR 7, 1978	18
670A/671A UNWANTED VERTICAL LINE IN YELLOW COLOR BAR	10-11	MAY 30, 1980	26
670A/671A/670A-1 REPLACEMENT OF CR5020 OR CR5021	10-04	FEB 22, 1980	20
ADAPTER PART NUMBER	7-21	SEPT 9, 1977	14
AMPEX TV PRODUCTS REPAIR	7-17	AUG 5, 1977	13
APPLICATION NOTE 22 CORRECTION	7-25	OCT 21, 1977	12
AVAILABILITY OF CRT SPECS	7-29	NOV 25, 1977	15
C95 SOCKET CORRECTIVE ACTION FOR TV PRODUCTS	9-22	NOV 16, 1979	13
COLOR TEMPERATURE OF 650A/670A SERIES PICTURE MONITORS	7-17	AUG 5, 1977	14
CORRECTION TO 613 HIGH VOLTAGE BOARD ARTICLE	10-02	JAN 25, 1980	21
DISPOSITION OF NCR MICROCARD 833 READERS	7-29	NOV 25, 1977	15
EQUIPMENT REQUIRED FOR A SECAM SYSTEM TV TEST BENCH	9-15	AUG 10, 1979	14
EQUIPMENT REQUIRED FOR A PAL SYSTEM TELEVISION TEST BENCH	9-06	APR 6, 1979	42
FAILING CRYSTALS	7-13	JUNE 24, 1977	23
GMA101A/ GMA102A STORAGE ASSEMBLY MODIFICATIONS 37884, 38046 & 38234	10-02	JAN 25, 1980	21
IC INTERMITTENT FAILURES MAY BE DUE TO DEFECTIVE SOCKETS	9-02	FEB 2, 1979	38

TELEVISION PRODUCTS

TITLE	ISSUE	DATE	PAGE
LEADLESS SOCKET DISCONTINUED	7-30	DEC 9,1977	20
MICROFICHE STATUS UPDATE	7-29	NOV 25,1977	13
MICROFICHE USER REPRESENTATIVES	7-29	NOV 25,1977	16
MODIFIED 1440 AND INTERFACE COMPATIBILITY	7-07	APR 1,1977	16
MOISTURE ABSORPTION IN COMPOSITION RESISTORS	10-25	DEC 19,1980	7
NEW PERFORMANCE ASSURANCE ENGINEER FOR TV PRODUCTS	10-24	DEC 12,1980	14
R147A/147A, R149A/149A, EQUALIZING PULSE WIDTH	10-01	JAN 11,1980	17
R147A/147A, R149A/149A INCOMPLETE DELETION OF LINE 21, FIELD ONE	10-04	FEB 22,1980	15
R147A/R149A DEFECTIVE CRYSTALS P/N 158-0069-00	10-02	JAN 25,1980	14
R520/R521A/R522A - CRT RETAINER CLAMP BREAKAGE	9-03	FEB 16,1979	26
RECOMMENDED TELEVISION TEST EQUIPMENT - ADDENDUM	9-01	JAN 12,1979	18
RECOMMENDED TELEVISION TEST EQUIPMENT	8-33	DEC 8,1978	15
SHIPPING CARTON KITS FOR 1410 SERIES, L1,L3,PA1,1101,7603 NMS	10-17	AUG 22,1980	9
SPG 1,2,3,11,12,13,22 CHANGE TO SYNC TIMING BOARD	10-04	FEB 22,1980	18
SPG 1/SPG 2, ADJUSTING VARIABLE H BLANKING START AND STOP	10-04	FEB 22,1980	18
SPG 11/12 - WIRE REVERSAL ON P170 REMOTE PLUG	8-28	SEPT 29,1978	26
SPG-1/SPG-2 HORIZONTAL DELAY CHANGES WITH TEMPERATURE CHANGE	9-02	FEB 2,1979	38
SPG/TSP, PART NUMBER FOR CABLE SETS & WIRING HARNESS	10-11	MAY 30,1980	18
SPG1, 2,3,11,12,13,22 CHANGE TO SYNC TIMING BOARD	10-01	JAN 11,1980	17
T.V. GENERAL 151-0164-00	7-07	APR 1,1977	17
TDC SERIES/PART NUMBER 441-1376-00	10-18	SEPT 5,1980	10
TELEVISION PRODUCTS, REMOVAL OF SELECTED TRANSISTOR SOCKETS	10-04	FEB 22,1980	19
TELEVISION BLANKING STANDARDS	8-29	OCT 13,1978	12
TELEVISION PRODUCTS	8-14	MAY 5,1978	11
TRAINING SURVEY FOR TV TECHNICIANS- (REF. PULL-OUT)	10-24	DEC 12,1980	B-1
TSG-1 IMPROVE COLOR BAR OUTPUT ACCURACY	8-25	AUG 18,1978	10
TSG-1 MANUAL CHANGE INFORMATION	9-02	FEB 2,1979	A-1
TSG-1 REDUCING SPURIOUS SUBCARRIER ON WHITE BAR	10-02	JAN 25,1980	14
TSG-12 CORRECT LINEARITY GRATICULE	9-13	JULY 13,1979	8
TSG-16 MULTIBURST FREQUENCY CHANGED	9-16	AUG 24,1979	9
TSG-2 WRONG MANUALS	8-22	JUL 7,1978	18
TSG-5/TSG-6/TSG-15/TSG-16 - MISSING SIGNAL DUE TO SPG TIMING ERROR	9-18	SEPT 21,1979	12
TSG-6/TSG-16/TSG26 TEST FIXTURE UPDATE	9-13	JULY 13,1979	8
TSG16/TSG26 AMPLITUDE VARIATION IN TRIANGLE OUTPUT	9-20	OCT 19,1979	6
TSG2 MANUAL CALIBRATION PROCEDURE ERROR, B020470 AND UP	10-06	MAR 21,1980	11
TSG3 LINEARITY LUMINANCE AMPLITUDE	8-28	SEPT 29,1978	26
TSG5/TSG15 - INTERMITTENT SWITCHES ON THE LOGIC BOARD	8-30	OCT 27,1978	33
TSG5/TSG15 COMPATABILITY PROBLEM WITH OTHER TSG'S	8-13	APR 28,1978	24
TSG6/CABLE HARNESS FRM FRONT PANEL FREQ CONTROL MAY BE CUT	10-19	SEPT 19,1980	15

1 JANUARY 1981

WIZARDS WORKSHOP INDEX

TELEVISION PRODUCTS

TITLE	ISSUE	DATE	PAGE
TSP-1 CORRECTING PULSE OVERSHOOT	10-02	JAN 25,1980	16
TSP-1/TSP-11 LOSS OF SYNC & BURST INSERTION ON CHANNEL A IN REMOTE OPERATION	9-18	SEPT 21,1979	14
TV GENS/REPLCMNT OF TEK MADE SYNC & TIMING CHIPADDENDUM	10-13	JUNE 27,1980	14
VIDEO CASSETTE ON 653 COLOUR MONITOR	7-06	MAR 18,1977	4
VIDEO TAPE AVAILABLE	7-05	MAR 4,1977	11

WIZARDS WORKSHOP INDEX

COMMUNICATIONS DIVISION (1980)

TITLE	ISSUE	DATE	PAGE
"SCR" PHENOMENA EXHIBITED BY NVM BOARD (ANS.SERVICE BULLETIN #7)	10-17	AUG 22,1980	38
1980 - 1900 COMPATIBILITY (ANSWER SERVICE BULLETIN #10)	10-23	NOV 21,1980	46
ADDITIONAL RECOMMENDED EQUIP FOR 1980 SERV (ANSWER B#2)	10-13	JUNE 27,1980	40
ANSWER SERVICE BULLETIN #1	10-13	JUNE 27,1980	40
FALSE "FPULSE" ERRORS (ANSWER B#4)	10-13	JUNE 27,1980	41
HEAT RELATED CSKIP-F ERROR (ANSWER SERVICE BULLETIN #6)	10-17	AUG 22,1980	38
IMPROPER SETTING OF AIR JUMPER OF NVM BOARD - ANSWER BULLETIN #8	10-21	OCT 17,1980	39
OPTIONAL PATCH ALLOWS GRAPHING VIDEO LINE 263 (ANS.SERV BULLTN#5)	10-16	AUG 8,1980	28
RETURN TO MEASUREMENT ROUTINES AFTER SYSTEM INTERRUPTION(ANSWER B#3)	10-13	JUNE 27,1980	42

WIZARDS WORKSHOP INDEX

SERVICE INSTRUMENT DIVISION

ACCESSORIES

TITLE	ISSUE	DATE	PAGE
1101 POWER SUPPLY RIPPLE	10-10	MAY 16,1980	14
1101 PROBE POWER SUPPLY RELIABILITY	9-15	AUG 10,1979	18
282 TYPE PROBE ADAPTER	10-06	MAR 21,1980	14
AM 503 AC BANDWIDTH IMPROVED	7-31	DEC 16,1977	19
AM 503 CURRENT PROBES AMPLIFIER RELIABILITY	7-02	JAN 21,1977	12
AM 503 CURRENT/DIV SWITCH	9-07	APR 20,1979	31
AM 503 DEGAUSS OSCILLATOR	9-07	APR 20,1979	32
AM 503 PERFORMANCE CHECK AND ADJUSTMENT PROCEDURE CORRECTION	9-08	MAY 4,1979	22
AM 503 POWER SUPPLY OSCILLATION	9-07	APR 20,1979	32
AM 503 POWER SUPPLY NOISE ELIMINATED	7-06	MAR 18,1977	22
AM 503 PRODUCT RELIABILITY MODIFICATION	7-04	FEB 18,1977	18
AM 503/P6302 ADJUSTMENT PROCEDURE CLARIFICATION	7-01	JAN 14,1977	16
C-12/27/30/31 CAMERAS	8-16	MAY 19,1978	11
C-50 SERIES CAMERA CURRENT SURGE	10-22	OCT 31,1980	18
C-51 CAMERA	10-08	APR 18,1980	14
C-51/C-53/C-59 CAMERA OCCLUDER ASSEMBLIES	10-22	OCT 31,1980	18
C28 CAMERA	10-14	JULY 11,1980	12
C52/C53 APERTURE ADJUST GEARS (ARTICLE REPEATED)	9-20	OCT 19,1979	A-1
C52/C53 APERTURE ADJUST GEARS	9-19	OCT 5,1979	11
C5A CAMERA LIGHT LEAK	7-04	FEB 18,1977	16
EFFECTIVE MODULAR-PROBE CABLES	7-10	MAY 13,1977	31
J-16 REPLACEMENT KIT	10-20	OCT 3,1980	21
J6511 SENSITIVITY	10-13	JUNE 27,1980	20
MODULAR PROBE FAILURE REPORTS	7-24	OCT 7,1977	10
P6010 PROBE R103 REPLACEMENT KITS	10-24	DEC 12,1980	18
P6013/P6013A SUPPORT POLICY	10-09	MAY 2,1980	12
P6042 CABLE REPLACEMENT KIT	10-05	MAR 7,1980	25
P6045 FET REPLACEMENT	10-18	SEPT 5,1980	11
P6045 FET REPLACEMENT	10-21	OCT 17,1980	18
P6046, Q123 PARTS REPLACEMENT KIT	10-22	OCT 31,1980	19
P6058 PROBE TIP REPLACEMENT AND UPDATE KIT	10-11	MAY 30,1980	28
P6065A REPLACED BY P6105	9-04	MAR 2,1979	25
P6108 PROBE	10-08	APR 18,1980	15
P61XX PROBE PARTS	7-10	MAY 13,1977	32
P61XX PROBE PARTS CORRECTION	7-11	MAY 27,1977	26
P6201 Q100 PEPLACEMENT	10-22	OCT 31,1980	19
P6201 WIRING ERROR	10-21	OCT 17,1980	19
P6202 AND P6420	8-20	JUN 23,1978	21
P6302/P6042 HALL DEVICE EPOXY PROBLEM	10-22	OCT 31,1980	19
P6303 REPLACEMENT TRANSFORMERS	10-03	FEB 8,1980	21
P6303/AM503 PERFORMANCE CHECK AND ADJUSTMENT PROCEDURE CORRECTION	9-08	MAY 4,1979	24
P6451 LABEL	10-04	FEB 22,1980	22

WIZARDS WORKSHOP INDEX

ACCESSORIES

TITLE	ISSUE	DATE	PAGE
P6451 WIRING ERROR	10-07	APR 4,1980	9
PROBE CODE DATE MARKINGS - ACTIVE AND PASSIVE PROBES	7-06	MAR 18,1977	23
PROBE CROSS REFERENCE INDEX	10-13	JUNE 27,1980	21
PROBE CROSS REFERENCE INDEX - CORRECTION	10-14	JULY 11,1980	13
PROBE DATE CODES	10-13	JUNE 27,1980	21
PROBES AND ACCESSORIES FAILURE REPORTS	7-01	JAN 14,1977	16
PROBES, MODULAR, BNC REPLACEMENT	9-14	JUL 27,1979	17

DIGITAL SERVICE INSTRUMENTS

TITLE	ISSUE	DATE	PAGE
067-0878-00 "RS-232 SELF TEST ADAPTER" -- CROSSTALK	10-18	SEPT 5,1980	12
832 833 -- SLIDE SWITCH CONTACTS IN BACKWARDS	10-18	SEPT 5,1980	12
832 CLARIFICATION OF OPTION 2 FIELD MOD KIT-P/N 040-0897-00	10-14	JULY 11,1980	14
833 - TIMING SIGNAL JITTER	10-18	SEPT 5,1980	12
851 "50 MEG OHM RANGE" - (DIFFICULTY MEETING SPECS)	10-17	AUG 22,1980	11
851 "CLEAR TEST" - OPERATOR TRAP	10-14	JULY 11,1980	16
851 "FREQ-RATIO CLEAR AND SAVE TEST" - (IMPROVE RELIABILITY)	10-17	AUG 22,1980	11
851 CALIBRATION AID	10-14	JULY 11,1980	15
851 INTERMITTENT DISPLAYS	10-14	JULY 11,1980	16

DATA COMMUNICATION ANALYZERS

832 833 SLIDE SWITCHES	10-21	OCT 17,1980	22
832 INTERMITTENT ERROR CODE 16 AND/OR PARITY ERRORS	10-11	MAY 30,1980	29
832 MAIN POWER SUPPLY BOARD/SWITCH CHANGE	9-19	OCT 5,1979	14
832 OPERATING INFORMATION	9-25	DEC 21,1979	B-1
832 OPTION 2:040 KIT CORRECTION	10-24	DEC 12,1980	18A
832 OPTION 2 INSTALLATION FOR INFOREX, INC.	9-21	NOV 2,1979	9
832 OPTION STATUS	9-15	AUG 10,1979	19
832 POTENTIAL LOW LINE FAILURE OF THE +12 VOLT SUPPLY	9-19	OCT 5,1979	14
834 SELF TEST ADAPTER	10-20	OCT 3,1980	21
834 USER GUIDE MANUAL ERROR	10-21	OCT 17,1980	20
851 CAPACITOR CHANGE FOR INCREASED PART RELIABILITY	9-19	OCT 5,1979	15
851 POWER SUPPLY PERFORMANCE IMPROVEMENT	10-25	DEC 19,1980	12
SIMULATING 832/833 ASYNCHRONOUS ECHO MODE IN THE 834	10-25	DEC 19,1980	11
USING THE 834 DIAGNOSTICS	10-21	OCT 17,1980	20

WIZARDS WORKSHOP INDEX

LOGIC ANALYZERS

TITLE	ISSUE	DATE	PAGE
067-0872-99 NOW AVAILABLE	10-05	MAR 7,1980	27
156-0229-00 PIN 9 HIGH	8-13	APR 28,1978	16
2942 FAN MOD NOW AVAILABLE	9-12	JUN 29,1979	18
308 AUTO UPDATE MODE	10-09	MAY 2,1980	14
308 OVERHEATING CAPACITORS CAUSES DAMAGE	10-13	JUNE 27,1980	22
4641 PRINTER, RIBBON TENSION	9-18	SEP 21,1979	34
4641 PRINTER, POWER BOARD BURNING OR FUSES BLOWING	9-18	SEP 21,1979	33
672 NEW PART NUMBERS	8-20	JUN 23,1978	18
7D01 "IC SOCKET UPDATE PROGRAM"	8-34	DEC 22,1978	14
7D01 "SOCKET UPDATE PROGRAM"	9-15	AUG 10,1979	20
7D01 - 7903/7904 MECHANICAL INCOMPATIBILITY	7-10	MAY 13,1977	24
7D01 CURSOR SWITCH FIELD MOD CORRECTION	7-31	DEC 16,1977	14
7D01 CURSOR SWITCH FIELD MOD	7-30	DEC 9,1977	18
7D01 CURSOR SWITCH INFORMATION	7-12	JUNE 10,1977	20
7D01 CURSOR SWITCH REPLACEMENT	7-32	DEC 23,1977	9
7D01 ENGINEERING INSTRUMENT SPECIFICATION CHANGE NOTICE	7-31	DEC 16,1977	14
7D01 NOISY CURSOR SWITCH FIX	7-24	OCT 7,1977	16
7D01 OUTPUT BOARD MODIFICATIONS	9-16	AUG 24,1979	11
7D01 POWER SUPPLY CIRCUIT BOARD REPLACEMENT S/N B010100-B020274	8-26	SEPT 1,1978	30
7D01 POWER SUPPLY RELIABILITY MODIFICATION	7-11	MAY 27,1977	22
7D01 RESET CAUSED BY STATIC DISCHARGE	8-09	MAR 31,1978	14
7D01 SOCKET UPDATE CODE 18 TERMINATION PLAN	10-19	SEPT 19,1980	23
7D01 SOCKET UPDATE PROGRAM WORK RECOGNIZER BOARD AND CURSOR BOARD	9-19	OCT 5,1979	16
7D01 SPECIFICATION CHANGED	8-20	JUN 23,1978	18
7D01 SPECIFICATION CHANGE CORRECTION	8-23	JUL 21,1978	24
7D01 STATIC DISCHARGE PROBLEMS	9-01	JAN 12,1979	15
7D01 STATIC DISCHARGE PROBLEM	9-06	APR 6,1979	37
7D01 TROUBLESHOOTING CHART	7-26	OCT 28,1977	20
7D01/7D01F SET UP AND HOLD TIMES	8-06	MAR 10,1978	14
7D01F BLANKING OF TIMING DIAGRAM	8-13	APR 28,1978	17
7D01F COMPONENT RELIABILITY	7-27	NOV 11,1977	13
7D02 FAILURE TO POWER UP	10-23	NOV 21,1980	27
7D02 PERSONALITY MODULE LOOPBACK	10-23	NOV 21,1980	30
BATTERY POWER FOR THE 308	10-09	MAY 2,1980	13
DF1 - 156-0291-00 DEFECTIVE DATE CODES "SIGNETICS"	7-22	SEPT 23,1977	18
DF1 - 156-0882-00 DEFECTIVE DATE CODE "GI BRAND"	7-22	SEPT 23,1977	18
DF1 MICROPROCESSOR MOD KIT	7-32	DEC 23,1977	9
DF1 S/N B033535 & UP REPLACEMENT OF C568	8-21	JUN 30,1978	16
DF1 SUPPORT	7-07	APR 1,1977	20
DF1 U263 REPLACEMENT	8-20	JUN 23,1978	17
DF1 USER INPUT	7-27	NOV 11,1977	13
DF1 WITH EXTRA DOTS IN MAP AFTER REPLACEMENT OF 6800-CPU	7-24	OCT 7,1977	12

LOGIC ANALYZERS

TITLE	ISSUE	DATE	PAGE
DF1/DF2 DIAGNOSTIC TEST PACKAGE	8-33	DEC 8,1978	14
DF1/DF2 INTERMITTENT MICROPROCESSOR U264 (SYMPTOM SIMILAR TO DEFECTIVE SOCKET)	9-06	APR 6,1979	36
DF1/DF2 U 422 REPLACEMENT	8-21	JUN 30,1978	16
DF1/DF2 U264 REPLACEMENT	8-21	JUN 30,1978	16
DF1/DF2 USE CHECKED 2101 ROM'S	8-13	APR 28,1978	16
DF1/DF2, INTERMITTENT U412 (SYMPTOM SIMILAR TO DEFECTIVE SOCKET)	9-06	APR 6,1979	36
DF2 ASCII CONVERSION TABLE	8-33	DEC 8,1978	14
DF2 MANUAL ERROR (CORRECTION TO WIZARDS WORKSHOP ISSUE 9-5, MAR 15, 1979)	9-06	APR 6,1979	37
DF2 MANUAL ERROR	9-05	MAR 16,1979	16
DL 2 SPECIFICATION CHANGE	8-21	JUN 30,1978	17
DL 502 SPECIFICATION CHANGE	8-21	JUN 30,1978	17
LA 501 -- COLLECTOR OF Q910 SHORTING	8-06	MAR 10,1978	11
LA 501 CAPACITORS PHYSICALLY TOO LARGE	8-06	MAR 10,1978	11
LA 501 CURE FOR FRONT PANEL...INTERMITTENT (R690,R695, R740 & R745)	7-16	JULY 29,1977	17
LA 501 PART NUMBER ERROR	8-06	MAR 10,1978	12
LA 501, DF1/2, WR 501 DL 502 CAPACITOR FAILURES	8-21	JUN 30,1978	17
LA 501/LA 501W RELIABILITY IMPROVEMENTS	8-06	MAR 10,1978	12
LA 501W WIRING DIAGRAM FOR INTERCONNECT CABLES	8-06	MAR 10,1978	12
LA 501W/OSCILLOSCOPE COMPATABILITY LIST	7-26	OCT 28,1977	18
LA501 NEW MANUAL	10-09	MAY 2,1980	13
LOGIC ANALYZER CANNON PLUGS P/N 131-1345-00--DEFECTIVE --"PURGE".	10-18	SEPT 5,1980	13
LOGIC ANALYZER DEMO AID/TEST AID	8-13	APR 28,1978	16
S-3000 SERIES MICROFICHE NOW AVAILABLE	9-12	JUN 29,1979	15
S-3200 PDP/34-XE STANDARD CONFIGURATION	9-12	JUN 29,1979	16
S-3200-5V POWER SUPPLY REPLACEMENT	9-12	JUN 29,1979	18
S-3455 AUDIO TAPES	9-12	JUN 29,1979	18
VIDEO TAPES AVAILABLE	7-03	FEB 4,1977	6

PORTABLES

TITLE	ISSUE	DATE	PAGE
1105 BATTERY SET REPLACEMENT	10-09	MAY 2,1980	17
200 SERIES "APPARENT" WET SPOTS ON CRT FACEPLATE	8-04	FEB 17,1978	16
200 SERIES BATTERY PACK REPLACEMENT	8-27	SEPT 15,1978	23
200 SERIES OSCILLOSCOPE SWEEP AND TRIGGER GENERATOR IC REPLACEMENT HISTORY	8-22	JUL 7,1978	13
200 SERIES OSCILLOSCOPE TRIGGER/SWEEP GENERATOR REPLACEMENT KITS	8-29	OCT 13,1978	11
200 SERIES TRACE ROTATION COILS, CORRECTION	7-25	OCT 21,1977	11
200 SERIES TRACE ROTATION COILS	7-23	SEPT 30,1977	10
211 212 213 214 221 POWER CORD	10-16	AUG 8,1980	13
212/214 HORIZONTAL MAGNIFICATION POT	10-24	DEC 12,1980	19
212/214 REPLACING Q388 AND SELECTING R388	10-24	DEC 12,1980	20
212/214 SHORTENED SWEEP CAUSED BY U370 OSCILLATING	8-19	JUN 9,1978	22
212/214 SHORTENED SWEEP	9-13	JULY 13,1979	12
212/214 VERTICAL NOISE	9-13	JULY 13,1979	14
212/214 VERTICAL INPUT FET CHANGE	9-23	NOV 30,1979	15
212/221 IMPROVED BATTERY RELIABILITY	7-25	OCT 21,1977	11
213 - 155-0114-00 - DEFECTIVE DATE CODES	8-07	MAR 17,1978	18
213 SHORTENED SWEEP CAUSED BY U335 OSCILLATING	8-19	JUN 9,1978	23
214 - U320 INSERTED INCORRECTLY	10-18	SEPT 5,1980	14
214 FREE RUNS IN SINGLE SWEEP AT HIGH SWEEP SPEEDS	10-24	DEC 12,1980	21
214 POWER SUPPLY LOADING IN STORAGE MODE	10-03	FEB 8,1980	22
214 UNRELIABLE TRIGGER IN SINGLE SWEEP MODE	8-19	JUN 9,1978	23
221 211 212 213 214 POWER CORD	10-16	AUG 8,1980	13
221 CHARGER CIRCUIT IMPROVEMENT	8-17	MAY 26,1978	6
221 TRANSFORMER SHIELD ASSEMBLY CORRECTION	10-14	JULY 11,1980	17
221 VERTICAL DRIVE TRANSISTOR PROTECTION	8-13	APR 28,1978	18
305 HIGH VOLTAGE MODULE WITH CONNECTORS	10-06	MAR 21,1980	17
305 NOISE ON SQUARE WAVE SIGNAL	9-15	AUG 10,1979	25
305 VERTICAL GAIN CHANGES	9-13	JULY 13,1979	16
305DMM RESISTANCE MEASUREMENT ERROR	9-15	AUG 10,1979	24
314 - NO INTENSITY DUE TO Q703, Q704 FAILURE	9-19	OCT 5,1979	17
314 ADJUSTING INTENSITY LIMIT	9-17	SEPT 7,1979	14
314 IMPROVE MAGNIFIED TIMING LINEARITY	8-13	APR 28,1978	19
314 READY LIGHT REMAINS ON	7-04	FEB 18,1977	17
314 RELIABILITY MOD: 31023	7-01	JAN 14,1977	13
314--GEOMETRY ADJ. FULLY CW AND +170V SUPPLY RIPPLE IS MARGINAL	7-17	AUG 5,1977	19
314/335 CRT MOUNTING SCREWS	7-12	JUNE 10,1977	21
323 DIFFICULT TO AMPLIFY 4 MHZ SIGNAL TO SIX DIVISIONS	8-08	MAR 24,1978	10
323 IMPROVE MAGNIFIED TIMING LINEARITY	8-13	APR 28,1978	19
323--IMPROVE HIGH VOLTAGE REGULATION	7-17	AUG 5,1977	19
326 - CIRCUIT IMPROVEMENTS AND Q464 AND Q474 REPLACEMENT	8-12	APR 21,1978	12
326 CRT PART NUMBER CHANGE ADDENDUM	8-33	DEC 8,1978	15

1 JANUARY 1981

PORTABLES

TITLE	ISSUE	DATE	PAGE
326 CRT PART NUMBER CHANGE	8-31	NOV 10,1978	19
326 IMPROVED CH. 2, 1 VOLT, 10 MHZ BANDWIDTH	8-24	AUG 4,1978	17
326 POWER SUPPLY TRANSFORMER FAILURE	9-10	JUN 1,1979	10
335 - VERTICAL OUTPUT AMPLIFIER OSCILLATES	8-08	MAR 24,1978	11
335 DELAY TIME MULTIPLIER POT	9-17	SEPT 7,1979	15
335 DRIFT IMPROVEMENT OF EXTERNAL HORIZONTAL VARIABLE BALANCE	7-01	JAN 14,1977	14
335 FREQUENCY RESPONSE AND STEP RESPONSE SPECIFICATION CHANGES	8-13	APR 28,1978	20
335 IMPROVE HIGH VOLTAGE REGULATION	7-30	DEC 9,1977	18
335 IMPROVE RELIABILITY OF THE X2 HV MULTIPLIER	7-17	AUG 5,1977	20
335 MOD WP "FOLLOW UP"	8-18	JUN 2,1978	9
335 NEW CUSTOM MODIFICATION - "WP"	8-13	APR 28,1978	20
335 PREVENT VARIABLE TIME/DIVISION COUPLER FROM LOOSENING	8-08	MAR 24,1978	10
335 SELECTING R1218 WHEN CHANGING THE CRT	9-23	NOV 30,1979	20
335 UNSTABLE TRIGGERING IN AUTO AT 20HZ	9-18	SEPT 21,1979	19
335, 070-1943-00, MANUAL CORRECTION (CORRECTION)	7-17	AUG 5,1977	6
335, 070-1943-00, MANUAL CORRECTION	7-15	JULY 22,1977	23
335--PLASTIC SLEEVE PART NUMBERED	8-01	JAN 20,1978	16
335--SWEEP LENGTH IS MARGINAL, OPERATING TIME OF LOW LINE INDICATOR IS TOO SHORT	7-17	AUG 5,1977	20
400 SERIES TIMING SWITCH CHANGE (A REFERENCE PULLOUT)	8-31	NOV 10,1978	1
434 BELOW B50, CHANNEL 2 INTERMITTENT POSITIONING	10-05	MAR 7,1980	28
434 CHANNEL 2, 1MV ABERRATION IMPROVEMENT	7-32	DEC 23,1977	10
434 DIODE BREAKAGE PRIOR TO SERIAL NUMBER B500000	7-04	FEB 18,1977	18
434 INCORRECT POWER SUPPLY BURST MODE	9-05	MAR 16,1979	25
434 INTENSITY MODULATION B528370-B528420	8-06	MAR 10,1978	18
434 INTERMITTENT BURST MODE	10-12	JUNE 13,1980	13
434 POTENTIAL POWER SUPPLY SHUT DOWN IF U1910 IS REPLACED	9-05	MAR 16,1979	25
434 POWER SUPPLY SHUTDOWN CORRECTION	8-01	JAN 20,1978	17
434 POWER SUPPLY SHUTDOWN, B0527800 TO B0528170	7-31	DEC 16,1977	17
434 PROBE CODING LIGHTS	9-15	AUG 10,1979	25
434/475 POLYSULFONE	7-01	JAN 14,1977	15
434/485 POWER SUPPLY REGULATOR, 155-0067-02	9-20	OCT 19,197	9
442 AND T900 SERIES, Q458 REPLACEMENT	9-16	AUG 24,1975	12
442 AND T900 SERIES INTERMITTENT CHASSIS MOUNTED TRANSISTORS	8-04	FEB 17,1978	17
442 CALIBRATION SHIELD	8-13	APR 28,1978	21
442 FUSE HOLDER IS REWIRED	10-24	DEC 12,1980	21
442 H.V. OSCILLATOR, Q458 HEAT SINKING	10-05	MAR 7,1980	29
442 HALO - SUPPRESSANT CRT MOD KIT P/N (050-1150-00)	9-15	AUG 10,1979	27
442 HALO SUPPRESSANT CRT	8-24	AUG 4,1978	18
442 MANUAL NOW AVAILABLE	7-22	SEPT 23,1977	4
442 PILOT CHANGE CORRECTION	8-24	AUG 4,1978	18
442 PILOT CHANGES - ADDENDUM	8-12	APR 21,1978	13

PORTABLES

TITLE	ISSUE	DATE	PAGE
442 PILOT CHANGES	8-10	APR 7,1978	11
442 Q4388 CASE SHORTING	8-24	AUG 4,1978	19
442 TRACE FLICKER AT 2MS/DIV	8-24	AUG 4,1978	19
442 TRIGGER SWITCH BINDING	10-06	MAR 21,1980	18
442 TRIGGER CIRCUIT NOISE REDUCTION	8-24	AUG 4,1978	20
442 TROUBLESHOOTING CHART (REF PULL-OUT)	10-12	JUNE 13,1980	A-1
442 Z AXIS TRANSIENT RESPONSE IMPROVED	8-24	AUG 4,1978	20
442/T912/T922/T932/T935/T932A/T935A/442 DOUBLE TRIGGERING	9-15	AUG 10,1979	23
442/T932A/T935A VERTICAL DRIFT	9-21	NOV 2,1979	10
453'S FILAMENT WINDING LEAD DRESS ON HIGH-VOLTAGE TRANSFORMERS	7-07	APR 1,1977	27
453/453A REPLACEMENT VERTICAL PREAMP & ATTENUATOR ASSEMBLIES	8-31	NOV 10,1978	20
453/454 SPECIFICATION CHANGE	7-10	MAY 13,1977	30
454/454A CALIBRATION TEST EQUIPMENT CHANGE (109/113)	7-02	JAN 21,1977	13
454/R REPLACEMENT OF P/N 151-0213-00, 151-0222-00 TRANSISTORS	10-05	MAR 7,1980	30
455 +5V LATCH UP	7-23	SEPT 30,1977	10
455 A2 & B2 MODULE CONNECTOR INTERMITTENT	8-09	MAR 31,1978	14
455 EXTENDER CABLE	7-06	MAR 18,1977	22
455 HIGH VOLTAGE BURSTING	7-05	MAR 4,1977	31
455 SCALE FACTOR LED PART NUMBER CHANGE	9-04	MAR 2,1979	23
455 SWEEP GENERATOR IC PROTECTION BELOW B050000	7-32	DEC 23,1977	11
455 U4160, PART NUMBER CHANGE	7-25	OCT 21,1977	11
455 VERTICAL INPUT CIRCUIT CAPACITOR ADDITION ADDENDUM	8-04	FEB 17,1978	18
455 VERTICAL INPUT CIRCUIT CAPACITOR ADDITION	8-02	JAN 27,1978	11
455, IMPROVED NORMAL TRIGGER AT 50 MHZ	8-24	AUG 4,1978	21
455/465M AND USM 465: TROUBLESHOOTING THE HIGH VOLTAGE	9-02	FEB 2,1979	26
455/465M/USM425 INTERMITTENT VERTICAL IC'S	7-25	OCT 21,1977	12
455/465M/USM425: FOCUS POT VENDOR CHANGE	8-22	JUL 7,1978	16
455/465M/USM425; LEAD CONFIGURATION OF P/N 151-1090-02	9-05	MAR 16,1979	26
455A2B2 EXCESSIVE BANDWIDTH (>70MHZ)	9-18	SEPT 21,1979	20
455A2B2/465 +5 VOLT LATCH UP	9-15	AUG 10,1979	27
455A2B2/465M Q552 PART NUMBER CHANGE	9-15	AUG 10,1979	27
455AB F736 BLOWS	7-02	JAN 21,1977	13
460 AND 470 SERIES BANDWIDTH LIMIT--TRIGGER VIEW SWITCH REPLACEMENT AID	8-06	MAR 10,1978	18
460 AND 470 SERIES PORTABLES ELECTROLYTIC CAP FAILURES ADDENDUM	8-05	MAR 3,1978	19
460 AND 470 SERIES PORTABLES ELECTROLYTIC CAP FAILURES	8-04	FEB 17,1978	18
460/470 SERIES JUMPY VERTICALS	9-03	FEB 16,1979	23
464 466 VERTICAL OSCILLATIONS	10-19	SEPT 19,1980	24
464 BELOW B132140 -- 466 BELOW B134620	7-11	MAY 27,1977	25
464,465,466,475/A 485 PRESS NUTS USED TO MOUNT REAR FEET	10-13	JUNE 27,1980	24
464/465/465B/475/475A ACCESSORY POUCH PARTS BREAKDOWN	9-25	DEC 21,1979	29

PORTABLES

TITLE	ISSUE	DATE	PAGE
464/465/466 BURNED CONTACT ON TIMING BOARD	9-03	FEB 16,1979	23
464/465/466 CONTACT 15 BURNED	7-01	JAN 14,1977	15
464/465/466 DM 44 1/TIME COUNT DRIFT	7-09	APR 29,1977	19
464/465/466 DOUBLE TRIGGERING	7-08	APR 15,1977	14
464/465/466 JUMPY VERTICALS	7-09	APR 29,1977	20
464/465/466 VARIABLE VOLT/DIV POT, P/N 311-1364-00	9-15	AUG 10,1979	28
464/465/466/475 HEAT STAKING PIN FOR INSTALLING BANDWIDTH LIMIT AND TRIGGER	8-27	SEPT 15,1978	23
464/465/466/475/475A HIGH VOLTAGE CAP. CHANGE	9-13	JULY 13,1979	16
464/465/466/475/475A SERIES - FAN MOTOR BOARD CHANGES	9-13	JULY 13,1979	18
464/465/466/475A TIMING SWITCH ADDENDUM	9-16	AUG 24,1979	13
464/466 ABNORMAL VARIABLE VIEW TIME OPERATION	9-04	MAR 2,1979	24
464/466 BRIDGE RECTIFIER BATCH PROBLEM	7-13	JUNE 24,1977	27
464/466 LOW FREQUENCY COMPENSATION	8-14	MAY 5,1978	9
464/466 LOW FREQUENCY COMPENSATION	7-07	APR 1,1977	27
464/466 OPTION 10 MANUAL	9-13	JULY 13,1979	24
464/466 REAR CORD WRAP MOD	9-20	OCT 19,1979	9
464/466 SN B010100 TO B120000 INTENSITY FLICKER ELIMINATED	7-07	APR 1,1977	26
465 +110 VOLT SUPPLY SHUTDOWN	9-08	MAY 4,1979	29
465 - 311-1430-00 - ERRATIC, INTERMITTENT AND/OR DRIFT	8-04	FEB 17,1978	18
465 INTERMITTENT INPUT	7-01	JAN 14,1977	16
465 LOOSE HARDWARE ON BNC CONNECTORS	7-02	JAN 21,1977	14
465 MAJOR FAILURE:...SWEEP GENERATOR & POWER SUPPLY	8-30	OCT 27,1978	28
465 MAJOR FAILURE ADDENDUM	8-34	DEC 22,1978	17
465 MOD UC INCORRECT IC PART NUMBER	10-14	JULY 11,1980	19
465 OPTION 5 MANUAL SUPPLEMENT	8-30	OCT 27,1978	29
465 REPLACE C1220 IN UNITS BELOW B294620	10-07	APR 4,1980	10
465 TRANSISTOR CHANGES IN CHOP AND UNBLANKING CIRCUITS	9-05	MAR 16,1979	28
465 VERTICAL OSCILLATIONS, HF COMPENSATIONS	10-05	MAR 7,1980	30
465 VOLTAGE SUPPLY FAILURES AND INTERMITTENTS	9-03	FEB 16,1979	25
465/465B VERTICAL OSCILLATIONS	10-05	MAR 7,1980	31
465/475 TO 465/475DM44 MOD KITS	9-24	DEC 14,1979	11
465/475/475A HIGH VOLTAGE ARCING	7-30	DEC 9,1977	19
465/475A VERTICAL AND HORIZONTAL OSCILLATIONS	9-14	JULY 27,1979	18
465B ADJUSTING H.F. ABERRATIONS AFTER CHANGING INPUT FET	10-09	MAY 2,1980	15
465B DTM JITTER	10-23	NOV 21,1980	32
465B FAST SWEEP LINEARITY	10-09	MAY 2,1980	16
465B INTERMITTENT RISE TIME IN 5 VOLTS/DIV	10-24	DEC 12,1980	21
465B RISETIME AT 5 VOLTS/DIV IMPROVED	10-19	SEPT 19,1980	27
465B UNSTABLE B TRIGGERING	10-09	MAY 2,1980	16
465B/DM44 FIELD INSTALLATION KIT	9-24	DEC 14,1979	11
465B44, 475A44 PROPER DESIGNATIONS	10-13	JUNE 27,1980	25
465M PARTS LIST	8-08	MAR 24,1978	11

PORTABLES

TITLE	ISSUE	DATE	PAGE
465M/455A2B2 +5 VOLT LATCH UP	9-15	AUG 10,1979	27
465M/455A2B2 Q552 PART NUMBER CHANGE	9-15	AUG 10,1979	27
465M/USM425 IMPROVED EMI SHIELD	8-28	SEPT 29,1978	25
466 HIGH VOLTAGE NOISE IN THE VERTICAL ADDENDUM	8-34	DEC 22,1978	18
466 HIGH VOLTAGE NOISE IN THE VERTICAL	8-32	NOV 24,1978	16
466 SWEEP GENERATOR, CR1004, CR1011 WRONG PART NUMBERS	9-17	SEPT 7,1979	15
468 AUDIO CIRCUIT DESCRIPTION TAPES	10-24	DEC 12,1980	22
468 MANUALS AVAILABLE	10-20	OCT 3,1980	21
468 SWITCHING FROM NORM STORAGE TO SAVE CAUSES A VERT.POS. SHIFT	10-23	NOV 21,1980	33
475 2mv INADEQUATE GAIN ADJUSTMENT	9-22	NOV 16,1979	18
475 475A LOCKOUT ASSEMBLY DELETED FROM TIMING SWITCH	10-10	MAY 16,1980	17
475 AND 475A, VERTICAL OUTPUT IC PROTECTION	8-30	OCT 27,1978	29
475 INTERCHANNEL CROSSTALK IN CHOP MODE	9-09	MAY 18,1979	14
475 SWEEP TIMING ERROR IN MIX MODE ADDENDUM	8-08	MAR 24,1978	12
475 SWEEP TIMING ERROR IN MIX MODE	8-05	MAR 3,1978	20
475/475A BLANKING AMPLIFIER CIRCUIT CHANGE	8-28	SEPT 29,1978	24
475/475A TRANSISTOR TYPE CHANGE	9-03	FEB 16,1979	25
475/475A VERTICAL SWITCHING, TROUBLESHOOTING VOLTAGE READINGS	9-24	DEC 14,1979	12
475/A LIMITED VERTICAL GAIN ADJUSTMENT	9-20	OCT 19,1979	10
475/A LOSS OF INTENSITY OR INTENSITY CONTROL	10-03	FEB 8,1980	22
475/A VERTICAL LEAD CONNECTOR P/N 131-1119-00	9-20	OCT 19,1979	10
475/A VERTICAL OUTPUT IC PROTECTION	8-27	SEPT 15,1978	24
475A DM44 PG MOD INSUFFICIENT RANGE OF TIME ADJUSTMENT (R3287)	9-13	JULY 13,1979	20
475A MOD PG TIME THERMAL INSTABILITY	10-04	FEB 22,1980	23
475A TIME/DIV KNOB ACTUATOR PIN	9-21	NOV 2,1979	10
475A VERTICAL OUTPUT IC REPLACEMENT	8-05	MAR 3,1978	20
485 D.C. RESTORER DIODE REPLACEMENT	9-13	JULY 13,1979	22
485 INPUT PROTECTION DIODE CHANGE	8-28	SEPT 29,1978	24
485 INPUT RELAY DRIFT	9-13	JULY 13,1979	22
485 INTERMITTENT FOCUS, INTENSITY, AND POWER SUPPLY	10-03	FEB 8,1980	23
485 INTERMITTENT INTENSITY FLASH	8-30	OCT 27,1978	29
485 L.E.D'S CR 97,98,99	9-14	JULY 27,1979	21
485 LIGHT SENSITIVE DIODES	8-30	OCT 27,1978	30
485 ONE MEG TRANSIENT RESPONSE MAY EXCEED SPECIFICATIONS	10-01	JAN 11,1980	32
485 POWER INVERTER PROTECTION DURING BURST MODE	7-32	DEC 23,1977	14
485 RELAY CHANGE	9-14	JULY 27,1979	19
485 VERTICAL OSCILLATIONS DUE TO FAST IC'S	8-14	MAY 5,1978	10
7A13 LOOSE CONNECTORS ON READOUT DISPLAY	10-04	FEB 22,1980	25
832 TEST PROM FOR IDD: ORDERING CORRECT PART NUMBER	10-13	JUNE 27,1980	25
832 USER PROM, ENABLED CONSTANTLY	9-04	MAR 2,1979	24
851 +/- PEAK VOLTS THRESHOLD LIGHT-OPERATION CHANGE, OCCURRING PRIOR TO B020550	8-12	APR 21,1978	14

1 JANUARY 1981

PORTABLES

TITLE	ISSUE	DATE	PAGE
851 240 VOLT LINE FUSES	8-18	JUN 2,1978	9
851 A/D CONTROL LOGIC TROUBLESHOOTING AID (CORRECTION)	7-31	DEC 16,1977	18
455A2B2 FUSE, F736, PROTECTED BY ZENER DIODE CHANGE	7-08	APR 15,1977	13
851 AND T900 SERIES, MIXED PARTS	8-20	JUN 23,1978	21
851 AUDIO TAPES	8-03	FEB 3,1978	13
851 CIRCUIT BOARD LEAKAGE	8-34	DEC 22,1978	18
851 CLEANING NOTE	7-31	DEC 16,1977	18
851 CORRECTION TO DIGITAL TESTER MANUAL	8-22	JUL 7,1978	18
851 DIGITAL TESTER MANUAL INSERT	8-03	FEB 3,1978	14
851 DMM AUTO RANGE MALFUNCTION	9-08	MAY 4,1979	29
851 IC'S SOCKETED FOR SELECTABILITY	8-23	JUL 21,1978	24
851 IMPROVED +/- 15 VOLT SUPPLY REGULATION	8-14	MAY 5,1978	10
851 LED DISPLAY ALIGNMENT MOD KIT B010100 TO B022315	8-05	MAR 3,1978	20
851 MANUAL CLARIFICATION	7-30	DEC 9,1977	17
851 MANUAL INFORMATION CORRECTION	7-32	DEC 23,1977	14
851 NEW MANUAL	8-22	JUL 7,1978	18
851 NEW MANUAL - INCLUDES HISTORY AND CORRECTED PERFORMANCE CHECK	9-09	MAY 18,1979	14
851 OPTO-ISOLATOR SPEED-UP BELOW B020730	7-31	DEC 16,1977	18
851 POWER SUPPLY REPLACEMENT BELOW B020550	8-03	FEB 3,1978	14
CHANGE OF PRODUCT SUPPORT RESPONSIBILITY FOR 400 SERIES PORTABLES	7-16	JULY 29,1977	4
CRT BIAS FAILURE 464/466 ADDENDUM	8-04	FEB 17,1978	19
CRT BIAS FAILURE, 464 B132500 TO B132650 AND 466 B135100 TO B132650	8-02	JAN 27,1978	10
CRT BIAS PROBLEM, 464 B132500 TO B132650 AND 466 B135100 TO B132650	8-01	JAN 20,1978	15
DELAY TIME MULTIPLIER, MECHANICAL "ZERO" SETTINGS	9-19	OCT 5,1979	A-1
DM 44 FIELD INSTALLATION KITS	7-03	FEB 4,1977	20
DM 44 INSTALLATION MOD KITS	8-05	MAR 3,1978	18
DM 44 TIME MEASUREMENT ERROR	8-05	MAR 3,1978	18
DM43/44 USING A X10 VOLTAGE PROBE	9-20	OCT 19,1979	8
DM43/44 USING A X10 VOLTAGE PROBE, CORRECTION	9-23	NOV 30,1979	13
DM44 -5 VOLT REFERENCE SUPPLY	10-24	DEC 12,1980	19
DM44 ALTERNATIVE CALIBRATION PROCEDURE FOR SWEEP START/STOP	9-23	NOV 30,1979	14
DM44 CHANGES TO CAL PROCEDURE (REF. PULL-OUT)	10-05	MAR 7,1980	B-1
DM44 EXCESSIVE SETTLING TIME BETWEEN TIME AND 1/TIME	9-04	MAR 2,1979	23
DM44 MOD KITS TO REPLACE RIBBON CABLES	9-22	NOV 16,1979	16
DM44 SWEEP START AND STOP CALIBRATION	10-05	MAR 7,1980	28
DM44 TEMPERATURE PROBE SPECIFICATION CHANGE	10-01	JAN 11,1980	30
DM44/OPTION 5 COMBINATION MOUNTING BRACKET FOR 400 SERIES OSCILLOSCOPES	9-02	FEB 2,1979	26
H.V. OSCILLATOR BLOWS F722 FUSE	7-08	APR 15,1977	12
NEW T921/T922/T922R MANUAL	8-25	AUG 18,1978	9

PORTABLES

TITLE	ISSUE	DATE	PAGE
SC-502 BRIGHT SPOT AT START OF SWEEP	8-01	JAN 20,1978	15
SONY/TEK 314 IMPROVED MAGNIFIED TIMING LINEARITY	8-20	JUN 23,1978	19
SONY/TEK 323 IMPROVED MAGNIFIED TIMING LINEARITY	8-20	JUN 23,1978	20
SONY/TEK 326 IMPROVED MAGNIFIED TIMING LINEARITY	8-20	JUN 23,1978	20
T900 - PLASTIC SWITCH GUIDE FOR LINE ADJUSTMENT	9-21	NOV 2,1979	10
T900 050 KITS AVAILABLE	8-24	AUG 4,1978	13
T900 CRT NECKPIN LEADS	7-12	JUNE 10,1977	21
T900 EPOXY - GLASS SHAFT .123 DIAMETER	9-13	JULY 13,1979	11
T900 H.V. MULTIPLIER PART NUMBERS	7-29	NOV 25,1977	8
T900 INTERMITTENT ATTENUATOR	10-22	OCT 31,1980	20
T900 INTERMITTENT ATTENUATOR UPDATE #2	10-11	MAY 30,1980	30
T900 INTERMITTENT ATTENUATORS	10-10	MAY 16,1980	15
T900 INTERMITTENT ATTENUATORS UPDATE	10-01	JAN 11,1980	31
T900 SERIES AND 442, Q458 REPLACEMENT	9-16	AUG 24,1979	12
T900 SERIES CLEAR IMPLOSION SHIELD FOR USE WITH CAMERAS	8-11	APR 14,1978	11
T900 SERIES OCCASIONAL SWEEP LOCKUP	8-04	FEB 17,1978	25
T900 SERIES POSSIBLE DEFECTIVE CAPCITORS	8-03	FEB 3,1978	13
T900 SERIES POWER TRANSFORMER REPLACEMENT	8-03	FEB 3,1978	19
T900 SERIES POWER SUPPLY CONNECTOR WITH SHORT PINS	8-04	FEB 17,1978	25
T900 SERIES TEMPORARY TRANSISTOR TYPE CHANGE	7-14	JULY 8,1977	21
T900 SERIES, HIGH VOLTAGE OSCILLATOR TRANSISTOR REPLACEMENT	8-11	APR 14,1978	11
T900 SLOW TURN ON TIME OF H.V.	10-23	NOV 21,1980	32
T900 T.V. OVERLAY (035-0174-00)	9-16	AUG 24,1979	12
T900 TIMING AND TRIGGER INTERMITTENTS	8-08	MAR 24,1978	14
T912 (ONLY) - EXCESSIVE GAIN, FREQUENCY RESPONSE CUT IN HALF, FRONT CORNER ROLL	7-03	FEB 4,1977	21
T912 CRT REPLACEMENT, ADDITIONAL INFORMATION	7-27	NOV 11,1977	19
T912 INTENSITY MODULATION	7-07	APR 1,1977	24
T912 RELIABILITY IMPROVEMENTS	10-22	OCT 31,1980	21
T912 STORAGE CIRCUIT, Z942 FAILURE	9-20	OCT 19,1979	8
T912,T921,T922/R,T932A,T935A & 442 MOLDED KNBS WITH SHAFTS CHANGE	10-13	JUNE 27,1980	23
T912,T922/R,T932A,T935A,442 -8 VOLTS SUPPLY LOCKS UP AT +7V	10-17	AUG 22,1980	12
T912/T921/T922 VERTICAL JITTER	9-15	AUG 10,1979	22
T912/T921/T922/T932/T935/T932A/T935A/442 DOUBLE TRIGGERING	9-15	AUG 10,1979	23
T921,T922/R,T932A,T935A,442 EXCL OSCILLATIONS IN 100V PWR SUPPLY	10-13	JUNE 27,1980	24
T921/22/32A/35A/22R LOW VOLTAGE POWER SUPPLY TRANSFORMER	8-27	SEPT 15,1978	25
T921/T922/T922R/T932A/T935A, 442 INTERMITTENT VERTICAL ATTENUATORS	9-25	DEC 21,1979	27
T921/T922/T922R TRACE FLICKER AT 2MS/DIV	8-24	AUG 4,1978	14
T921/T922/T922R HIGH VOLTAGE REGULATION	8-30	OCT 27,1978	30
T921/T922/T922R/T932A/T935A INTENSITY FLASHING	9-18	SEPT 21,1979	17
T921/T922/T932A/T935A HALO-SUPPRESSANT CRT	9-15	AUG 10,1979	22

WIZARDS WORKSHOP INDEX

PORTABLES

TITLE	ISSUE	DATE	PAGE
T922 CRT NECKPIN LEAD PART NUMBER CORRECTION	7-24	OCT 7,1977	12
T922/R,T912,T932A,T935A,442 -8 VOLTS SUPPLY LOCKS UP AT +.7V	10-17	AUG 22,1980	12
T922R, HALO SUPPRESSANT CRT	8-24	AUG 4,1978	15
T932/T935A MECHANICAL PARTS LIST ERRORS	9-13	JULY 13,1979	11
T932A,T912,T922/R,T935A,442 -8 VOLTS SUPPLY LOCKS UP AT +.7V	10-17	AUG 22,1980	12
T932A/T935A -8V REGULATION AT HIGH LINE	8-24	AUG 4,1978	15
T932A/T935A AND 442 VERTICAL DRIFT	8-30	OCT 27,1978	32
T932A/T935A AND 442 CHANNEL II TEMPERATURE DRIFT	8-27	SEPT 15,1978	25
T932A/T935A TRACE FLICKER AT 2 MS/DIV	8-24	AUG 4,1978	16
T932A/T935A VERTICAL GAIN CHANGE WITH TEMPERATURE	8-24	AUG 4,1978	16
T932A/T935A VERTICAL INPUT LEAKAGE CURRENT	8-24	AUG 4,1978	17
T932A/T935A/442 VERTICAL DRIFT	9-21	NOV 2,1979	10
T935A,442,T912,T922/R,T932A -8 VOLTS SUPPLY LOCKS UP AT +.7V	10-17	AUG 22,1980	12
TRACE MODULATION AT 1 M/SEC AND SLOWER	7-13	JUNE 24,1977	27

WIZARDS WORKSHOP INDEX

TELEQUIPMENT

TITLE	ISSUE	DATE	PAGE
"TELEQUIPMENT DISTRIBUTOR SUPPORT"	8-28	SEPT 29,1978	25
CAPACITOR REPLACEMENT	10-22	OCT 31,1980	25
PC BOARDS	10-22	OCT 31,1980	25
PILOT LAMP FAILURE	10-22	OCT 31,1980	25
S61 - BRIGHT DOT ON CRT	7-08	APR 15,1977	15
S61 INABILITY TO FOCUS	7-09	APR 29,1977	20
TECHNICAL SUPPORT ON TELEQUIPMENT	10-23	NOV 21,1980	33
TLD 32 ALL GAINS OFF	7-01	JAN 14,1977	17
TLD 32 BATTERY REPLACEMENT	7-16	JULY 29,1977	20
TLD 67 INTENSITY CONTROL REPLACEMENT--R-305/S-401	8-01	JAN 20,1978	17
TLD 67 VOLTS/DIV SWITCH ASSEMBLY REPLACEMENT	8-23	JUL 21,1978	25
TLD 83 NEW CRT INSTALLATION PROBLEMS	7-13	JUNE 24,1977	29
TLS 61 L.V. CIRCUIT PROTECTION (T.Q. CHANGE #1806)	7-03	FEB 4,1977	20
TLS221/TLS61 OSCILLOSCOPES	10-16	AUG 8,1980	14

WIZARDS WORKSHOP INDEX

INFORMATION DISPLAY DIVISION

021-0072-00 TTY PORT INTERFACES TO DATA GENERAL ECLIPSE S-200, WITH 4077 I/O	7-23	SEPT 30,1977	4
040 HARD COPY KIT FOR 4014/15	7-19	AUG 19,1977	9
040 HARD COPY KIT FOR 4014/15 CORRECTION	7-21	SEPT 9,1977	4
040-0809-00 ORDERS	7-09	APR 29,1977	11
045 KITS, ORDERING INFORMATION	9-19	OCT 5,1979	19
067-0801-00 TEST FIXTURE	8-07	MAR 17,1978	5
067-0807-00 DISPLAY EXERCISER	8-05	MAR 3,1978	6
067-0807-00 FRONT PANEL CHANGE, MOD #34322	9-02	FEB 2,1979	8
067-0843-00 FIRMWARE ERROR	8-33	DEC 8,1978	9
119-0845-00 CALCOMP, FLEXIBLE DISK DRIVE, PRESSURE PAD	10-13	JUNE 27,1980	37
152 HAND MOD REQUIRED TO INCREASE TRIGGER PULSE WIDTH	7-09	APR 29,1977	12
156-0402-00 FAILURE	7-09	APR 29,1977	7
19" CRT GROUND WIRE DRESSING CAN AFFECT STORAGE BOARDS	10-11	MAY 30,1980	31
19" STORAGE CRT REPLACEMENT DATA	8-34	DEC 22,1978	7
22	10-16	AUG 8,1980	15
4002A/4010 HEWLETT PACKARD 2100 COMPUTER INTERFACE	7-01	JAN 14,1977	9
4006 LOGIC BOARDS RETURNED TO FACTORY SERVICE	9-04	MAR 2,1979	9
4006 MODIFICATION ERROR (MOD #M32777)	8-14	MAY 5,1978	5
4006-1 AC, 4010 AN, 4023 AC, 4662 AB: CURRENT LOOP INTERFACE	9-21	NOV 2,1979	12
4006-1 CR GIVES LF PROBLEM -----	7-24	OCT 7,1977	7
4006-1 DIRECT TO DEC PDP-10	7-13	JUNE 24,1977	13
4006-1/4051 HARD COPY NOISE PROBLEMS	7-03	FEB 4,1977	10
4006/4051 HIGH VOLTAGE CAPACITOR INSTALLATION	7-26	OCT 28,1977	7
4010 KEYBOARD ASSEMBLY	7-17	AUG 5,1977	8
4010 OPTION 1 HALF DUPLEX NORMAL MODIFICATION	7-31	DEC 16,1977	8
4010 SERIES PRODUCTS DISCONTINUED	10-24	DEC 12,1980	23
4010 SERIES INSTALLATION OF TTY PORT INTERFACE TO INTERDATA CPU WITH M48-024	8-23	JUL 21,1978	13
4010 SERIES OPTION 16 TTY INTERFACE, RUNNING TELETYPE AT 300BD	9-1	JAN 12,1979	7
4010 SERIES VARIABLE SPEED VECTOR GENERATOR (CM-018-0074-00) IMPROVED	7-21	SEPT 9,1977	8
4010 TERMINAL WITH VARIABLE SPEED VECTOR GENERATOR (CM-018-0074-00)	7-24	OCT 7,1977	7
4010-1 HARD COPY HELPFUL HINT	8-26	SEPT 1,1978	17
4010/4012/4013 HEAVY DUTY POWER SUPPLY MOD KIT	7-07	APR 1,1977	11
4010/4012/4013 RESPONSIBILITY	7-14	JULY 8,1977	7
4012/13, 4014/15 INTERMITTENT BREAKS	8-04	FEB 17,1978	9
4012/13/14/15 KEYBOARD INTERMITTENT BREAK (ADDENDUM-#2)	8-23	JUL 21,1978	17
4012/4013/4051 CRT	9-03	FEB 16,1979	15
4012/4014 KEYBOARD FIX	8-09	MAR 31,1978	7
4012/4015 ADDENDUM TO KEYBOARD FIX	8-14	MAY 5,1978	5
4013 KEYBOARD CABLE CROSS TALK	9-08	MAY 4,1979	32

1 JANUARY 1981

PAGE 52

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
4013, 4014, 4015 AND 4081 HIGH VOLTAGE TRANSFORMER MOD 35981	10-04	FEB 22,1979	36
4013/4015/4023 KEYBOARDS MODIFICATION	10-01	JAN 11,1980	33
4013/4015/4023 COMPUTER TERMINAL KEYBOARD CHANGE	8-26	SEPT 1,1978	12
4014 CALMA OEM TERMINALS SANTA CLARA SERVICE PROCEDURES	7-15	JULY 22,1977	8
4014 ERASE RECOVERY TIME CHANGED	7-28	NOV 18,1977	7
4014-4051/52 HIGH VOLTAGE FOCUS POTS	10-04	FEB 22,1979	38
4014/15 ANALOG MULTIPLEXER USED	7-10	MAY 13,1977	9
4014/15 CRT GROUND WIRE DRESSING AFFECTS STORAGE BOARD	10-09	MAY 2,1980	23
4014/15 CROSSHAIR POT FAILURE REPORTING	8-27	SEPT 15,1978	10
4014/15 DOCUMENTING CRT LIFE	7-30	DEC 9,1977	9
4014/15 GRAPHICS TERMINAL, OPTIONS 22, 23, 40 & 41 TEST FIXTURE	8-18	JUN 2,1978	6
4014/15 HIGH VOLTAGE CALIBRATION FOR MAJOR MOD	7-03	FEB 4,1977	7
4014/15 INTERMITTENT NULLS ON THE DATA LINE	7-27	NOV 11,1977	11
4014/15 LONG RIBBON CABLES FOR TERMINAL	7-03	FEB 4,1977	8
4014/15 POWER SUPPLY LOOSE CAPS	8-04	FEB 17,1978	9
4014/15 POWER SUPPLY +5 VOLT LIMITATIONS	7-22	SEPT 23,1977	6
4014/15 PRINTING DOUBLE CHARACTERS	8-15	MAY 12,1978	9
4014/15 TC-3 INTERMITTENT PROBLEMS WITH	7-05	MAR 4,1977	14
4014/15/16 COMPUTER TERMINALS - SUPPORT OF OPTION 40/41	9-03	FEB 16,1979	10
4014/15/16 TEKTRONIX OPTIONS 40 & 41 FOR BOARD EXCHANGE PROCEDURES	9-01	JAN 12,1979	6
4014/4014-1 4015/4015-1: SDRC ANIMATION BUFFER W/TEK OPTN 40	10-15	JULY 25,1980	15
4014/4015 - 401X OPTION 40-41	9-08	MAY 4,1979	32
4014/4015 - POWER SUPPLY RECTIFIER CHANGE	9-06	APR 6,1979	19
4014/4015 CRT PART NUMBERS	9-06	APR 6,1979	19
4014/4015 LARGE CHARACTER SIZE DISTORTING IN WRITE THRU MODE	9-04	MAR 2,1979	9
4014/4015/4016 OPTIONS 26 & 27:NEW P/N FOR OPT. 40 RAM KITS	9-12	JUN 29,1979	11
4014/4015/4016 GRAPHICS TERMINAL WITH FLAGGED INTERFACE	9-02	FEB 2,1979	8
4014/4015/4016 OPTION 40/41 USE OF CODE 18	9-06	APR 6,1979	19
4014/4016 TC-1 BOARDS	9-20	OCT 19,1979	13
4015/15 D/A PARTS CHANGE	7-28	NOV 18,1977	6
4015/4015-1/4014/4014-1 SDRC ANIMATION BUFFER W/TEK OPT 40	10-15	JULY 25,1980	15
4016 AND GMA-125 HIGH EFFICIENCY POWER SUPPLY	10-02	JAN 25,1980	28
4016-1 FUSEHOLDER MODIFICATION	10-07	APR 4,1980	12
4016-1 RELIABILITY UPGRADE ON LOW VOL. PWR SUP & STRG BRD ASSY	10-10	MAY 16,1980	24
4016-1 SERVICE MANUAL	9-13	JULY 13,1979	27
4016/GMA125: LOW VOLTAGE POWER SUPPLY MOD #37309	10-04	FEB 22,1979	27
4016/GMA125 DISPLAY: LOW VOLTAGE POWER SUPPLY MOD 37309	10-02	JAN 25,1980	24
4016/GMA125: HIGH VOLTAGE AND Z AXIS MODIFICATION 38078	10-05	MAR 7,1980	33

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
401X (OPTION 5) DELETING CODE 18	10-20	OCT 3,1980	29
401X - NEW OPTION 1 AND 4923 COMPATIBILITY IN HALF DUPLEX	9-09	MAY 18,1979	16
401X - OPTION 5 ROM	9-09	MAY 18,1979	17
401X COMPUTER TERMINAL OPTIONS 1 AND 15 COMPATABILITY	8-26	SEPT 1,1978	14
401X DUAL INTERFACING SLOW BAUD RATE	9-18	SEPT 21,1979	22
401X NEW OPTION 1, BACKPANEL ASSEMBLY NOW ORDERABLE	9-14	JULY 27,1979	22
401X OPT 1 EXTERNAL CLOCKING PROBLEM	8-07	MAR 17,1978	9
401X OPT. 4 CHANGES TO INSTALLATION PROCEDURE	9-15	AUG 10,1979	33
401X OPT.1 (021-0074-01) SLOW LINE TURNAROUND	8-19	JUN 9,1978	12
401X OPTION 40, 41 FIRMWARE (REF. PULL-OUT)	10-06	MAR 21,1980	A-1
401X OPTION 4 TTY PORT INTERFACE INSTALLATION	10-10	MAY 16,1980	23
401X OPTION 15 (021-0068-01) INSTALLATION ON DL-11W (M7856)	9-18	SEPT 21,1979	23
401X OPTION 16 INSTALLATION TO DEP PDP11 W/DLV11	8-07	MAR 17,1978	12
401X OPTION 22 AND 23 FIRMWARE BUG	8-01	JAN 20,1978	9
401X OPTION 4 (P/N 021-0072-00), DATA GENERAL TTY INSTALLATION PROCEDURE UPDATE	8-26	SEPT 1,1978	16
401X OPTS 40, 41 & 5: SYSTEMS ERRORS, WHAT ARE THEY?	9-13	JULY 13,1979	26
401X SELECTING HALF DUPLEX MODES	8-05	MAR 3,1978	8
401X SERIES COMPUTER GRAPHIC TERMINALS, OPTION 1 BREAK SIGNAL DURATION	8-19	JUN 9,1978	12
401X TELETYPE PORT INTERFACE MODIFICATION FOR AUTO-TROL	8-27	SEPT 15,1978	9
401X TTY PORT INTERFACE "GLA" STRAP	10-20	OCT 3,1980	29
401X TTY INTERFACES, RELAY CARD ASSEMBLY NOW ORDERABLE ITEM	9-14	JULY 27,1979	23
401X TTY PORT INTERFACE TESTING WITH AN 832/833 OPT.2	10-20	OCT 3,1980	30
401X USING TEST FIXTURE TO TEST OPT. 5	9-11	JUN 15,1979	8
401X: NEW CHECK SUMS FOR OPTIONS 22,23,40,41, AND 5 PROMS	9-06	APR 6,1979	17
4020 SERIES POLLING REFERENCE MANUAL	8-26	SEPT 1,1978	17
4020 SERIES POLLING TROUBLESHOOTING HINTS	8-30	OCT 27,1978	12
4023 - DATA ERRORS FROM ECHOED CHARACTERS IN BUFFER MODE	7-12	JUNE 10,1977	10
4023 CURSOR BOARD MOD #34741	9-10	JUN 1,1979	13
4023 FUSEHOLDER PROBLEM	9-06	APR 6,1979	20
4023 MODS AD, AN AND EV: KEYBOARD CHANGE	9-07	APR 20,1979	15
4023 MONITOR BOARDS RETURNED TO FACTORY SERVICE	9-01	JAN 12,1979	7
4023 MONITOR SERVICING	7-09	APR 29,1977	11
4024 BASIC DISPLAY CONTROLLER MODIFICATION	8-24	AUG 4,1978	8
4024 BAUD RATE STRAPPING	8-09	MAR 31,1978	8
4024 CHARACTER SELECTION STRAPPING	8-09	MAR 31,1978	10
4024/25/27 OPTION 2 AND 11: BAD LOT DATES ON OPTO ISOLATORS	10-08	APR 18,1980	16
4024/25/27 FIRMWARE UPGRADE	10-17	AUG 22,1980	13
4024/25/27 FIRMWARE UPGRADE NOTICE PART NUMBER CORRECTION	10-18	SEPT 5,1980	16

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
4024/25/27 FIRMWARE UPGRADE REVISION (REFERENCE PULL-OUT)	10-21	OCT 17,1980	A-1
4024/4025 - SAFETY RELIABILITY MODIFICATION	8-30	OCT 27,1978	19
4024/4025 FIXIT FIRMWARE	8-27	SEPT 15,1978	11
4024/4025 INSTALLATION CHARGES	8-06	MAR 10,1978	9
4024/4025 MOTOROLA MONITOR REPLACEMENT	8-30	OCT 27,1978	14
4024/4025 MOTOROLA MONITOR FAILURE	8-26	SEPT 1,1978	17
4024/4025 NEW PRELIMINARY SERVICE MANUAL	8-23	JUL 21,1978	21
4024/4025 OPTION 11 POLLING WIRING CONNECTIONS	8-26	SEPT 1,1978	19
4024/4025 OPTION 2 CURRENT LOOP WIRING CONNECTIONS	8-26	SEPT 1,1978	18
4024/4025 POWER FAIL CIRCUIT	8-09	MAR 31,1978	10
4024/4025 SERVICE MANUAL CORRECTION	9-01	JAN 12,1979	8
4024/4025 UPGRADE PROGRAM	9-10	JUN 1,1979	14
4024/4025/4027 FIRMWARE PART NUMBERS	9-07	APR 20,1979	A-1
4024/4025/4027 COMMUNICATIONS BOARD MOD	9-15	AUG 10,1979	34
4024/4025/4027 NEW SERVICE MANUALS ARE NOW AVAILABLE	9-23	NOV 30,1979	21
4024/4025/4027 MEMORY UPGRADES	9-06	APR 6,1979	23
4024/4025/4027 OPTION 2 INSTRUCTION SHEET	9-11	JUN 15,1979	10
4024/4025/4027 DISPLAY MEMORY MOD #M34037	8-32	NOV 24,1978	8
4024/4025/4027: PRESSING A KEY IN THE LOWEST ROW CAUSES	9-21	NOV 2,1979	14
4024/4025/4027: FLUX CONTAMINATION OF THE EDGE CONNECTORS	9-03	FEB 16,1979	15
4025 CHECKSUMS USING OPTION 41	8-31	NOV 10,1978	9
4025 DISPLAY MEMORY VS GRAPHICS AREA	8-34	DEC 22,1978	7
4025 EVERY OTHER HARD COPY IS LOST WHEN MAKING MULTIPLE COPIES	9-07	APR 20,1979	16
4025 EXPERIENCING A RESET CONDITION AFTER CYCLING POWER	9-07	APR 20,1979	16
4025 EXTENDER RIBBON CABLE	8-13	APR 28,1978	10
4025 FIRMWARE UPGRADE MOD #34422	8-28	SEPT 29,1978	11
4025 FIX-IT UPGRADE	8-16	MAY 19,1978	7
4025 GRAPHICS MEMORY BOARD MOD #36315	9-12	JUN 29,1979	12
4025 HARDCOPY FIXES	8-22	JUL 7,1978	8
4025 INCORRECT WIRING OF FAN	8-03	FEB 3,1978	7
4025 MECHANICAL UPGRADE KIT CHANGES PART NUMBER	9-23	NOV 30,1979	21
4025 OPTION 10 FIRMWARE UPGRADE V2.1	10-09	MAY 2,1980	24
4025 OPTION 3 I/F WITH A 4641 LINE PRINTER	8-26	SEPT 1,1978	18
4025 OPTION 40 SPECIFICATIONS	8-07	MAR 17,1978	14
4025 OPTION 41	8-34	DEC 22,1978	8
4025 OPTION 41 AS A TEST AID	8-31	NOV 10,1978	12
4025 POLLING CONTROLLER MOD #34759	8-27	SEPT 15,1978	12
4025 POLLING CONTROLLER MOD #34759 (CORRECTION)	8-28	SEPT 29,1978	11
4025 ROM EXPANSION BOARD ROM PLACEMENT	8-27	SEPT 15,1978	13
4025 VIDEO OUT HAS INCORRECT BLANKING LEVEL	10-07	APR 4,1980	12
4025 WITH AN EXTERNAL CLOCK	8-24	AUG 4,1978	9

WIZARDS WORKSHOP INDEX

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
4025 WITH AN EXTERNAL CLOCK ADDENDUM	8-26	SEPT 1,1978	19
4025/27 FIRMWARE ERROR	10-19	SEPT 19,1980	28
4025/27 OPTION 11 FIRMWARE UPGRADE	10-09	MAY 2,1980	25
4025/4027 - JUMPERS REQUIRED FOR GRAPHICS MEMORY UPGRADE KITS	8-29	OCT 13,1978	7
4025/4027 GPIB COMPATIBILITY	8-28	SEPT 29,1978	10
4025/4027 OPTION 11: 8251A USART IS INCOMPATIBLE	9-03	FEB 16,1979	16
4025/4027 ROM EXPANSION BOARD MOD #35570	9-01	JAN 12,1979	8
4025/4027 ROM EXPANSION BOARD MOD #35570 CORRECTION	9-03	FEB 16,1979	16
4025/4027: ROM CHECKSUM OF ADDRESS 5000-0 MAY BE INCORRECT	9-05	MAR 16,1979	9
4027 - RETURN OF REJECT CRT'S	9-03	FEB 16,1979	17
4027 ADJUSTING THE CRT BRIGHTNESS	9-12	JUN 29,1979	13
4027 AND 4632 OPTION 6	9-14	JULY 27,1979	24
4027 BAD LOT DATES ON HIGH VOLTAGE TRIPLER	10-07	APR 4,1980	13
4027 BATTERY CIRCUIT MOD ON PROC BRD & OPT 11 PROC BRD	10-08	APR 18,1980	16
4027 CHARACTER SET EXPANSION BOARD STRAPPING	9-02	FEB 2,1979	11
4027 CHARACTER SET EXPANSION BOARD STRAPPING CORRECTION	9-03	FEB 16,1979	16
4027 CONVERGENCE & Z AXIS BOARD MOD #M37254	9-13	JULY 13,1979	27
4027 CONVERGENCE & Z AXIS BOARD MOD #36215	9-08	MAY 4,1979	32
4027 DISPLAY ASSEMBLY SUPPORT LEVELS	9-03	FEB 16,1979	17
4027 EXTERNAL CONVERGENCE BOARD 670-5648-00	9-14	JULY 27,1979	24
4027 HIGH VOLTAGE TRIPLER DEFECT MAY CAUSE FOCUS TO CHANGE	10-14	JULY 11,1980	20
4027 JUMPER REQUIRED WHEN ADDING ANY CHARACTER ROM	9-10	JUN 1,1979	14
4027 LINE FILTER MODULE INTERMITTENT POWER ON/OFF	10-14	JULY 11,1980	21
4027 MECHANICAL CLEARANCE MAY CAUSE 5V SUPPLY TO CURRENT LIMIT	10-07	APR 4,1980	13
4027 NEW DEFLECTION YOKE IMPROVES CONVERGENCE	10-03	FEB 8,1980	24
4027 PART NUMBER FOR IC WITH HEAT SINK	9-18	SEPT 21,1979	29
4027 POOR SOLDER CONNECTIONS ON THE PWR SUPPLY & DEFL. BRDS.	10-21	OCT 17,1980	25
4027 POWER SUPPLY MOD #M36443 AND #M36778	9-09	MAY 18,1979	18
4050A07 GRAPH PLOT BUG FIX	7-16	JULY 29,1977	8
4050A08 PLOT 50 GENERAL UTILITY PROGRAMS VOL. 1 PROBLEMS	7-17	AUG 5,1977	11
4051 - UNDERSTANDING THE MAGNETIC TAPE DRIVE	9-03	FEB 16,1979	12
4051 BINARY ALPHA STRINGS	7-16	JULY 29,1977	6
4051 CABLE PART NUMBERS EXPLAINED	8-03	FEB 3,1978	8
4051 CHANGING A TAPE FILE HEADER	7-05	MAR 4,1977	17
4051 CHANGING A TAPE FILE HEADER CORRECTION	7-07	APR 1,1977	13
4051 FIRMWARE LEVELS AND CHECK SUMS	7-06	MAR 18,1977	7
4051 FIRMWARE LEVEL 3	7-01	JAN 14,1977	9
4051 FIRMWARE LEVEL 5 PARTS	7-07	APR 1,1977	13
4051 FIRMWARE LEVEL 5 PARTS CORRECTION	7-08	APR 15,1977	8
4051 FIRMWARE PROBLEM WHEN LISTING OR SAVING FILE	7-17	AUG 5,1977	9

1 JANUARY 1981

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
4051 GRAPHIC SYSTEM SERVICE MANUAL AVAILABLE	7-14	JULY 8,1977	15
4051 HARD COPY PROBLEM	7-13	JUNE 24,1977	14
4051 HIGH VOLTAGE LINES	7-03	FEB 4,1977	12
4051 KEYBOARD GLITCH CAUSING WRONG CHARACTERS	7-28	NOV 18,1977	9
4051 KEYBOARD PART NUMBER	7-21	SEPT 9,1977	8
4051 MAG TAPE LOAD POINT CURRENT ADJUSTMENT	9-09	MAY 18,1979	19
4051 MANUAL REVISIONS	8-09	MAR 31,1978	11
4051 MICROPROCESSOR STATUS AFFECTS MAG TAPE OPERATIONS	8-21	JUN 30,1978	6
4051 MISSING ERROR MESSAGE	7-01	JAN 14,1977	10
4051 OPT 1 PARAMETER CHANGES	7-16	JULY 29,1977	9
4051 OPT. 10 CAUSING SYSTEM ERROR 0 WITH DEVICES ON GPIB	8-04	FEB 17,1978	11
4051 OPTION 1 DATA COMMUNICATIONS INTERFACE SOFTWARE HELPS	7-28	NOV 18,1977	9
4051 OPTION 10 RS-232 PRINTER INTERFACE SOFTWARE BUG	7-28	NOV 18,1977	10
4051 OPTION 10 (PRINTER I/F) AND THE 4907	8-33	DEC 8,1978	9
4051 R07 PROM TO ROM CONVERSION	9-15	AUG 10,1979	35
4051 ROM PACK CHECKSUMS (CORRECTION)	7-07	APR 1,1977	14
4051 ROM PACK CHECKSUMS	7-04	FEB 18,1977	9
4051 ROM TEST PROGRAM BUG	8-03	FEB 3,1978	8
4051 SERVICE ROM PACK	10-18	SEPT 5,1980	16
4051 SERVICE MANUAL CORRECTION	7-21	SEPT 9,1977	8
4051 SYSTEM ERROR 0	7-30	DEC 9,1977	11
4051 TAPE CIRCUITRY TEST CORRECTION	7-14	JULY 8,1977	16
4051 TAPE DRIVE CALIBRATION	8-33	DEC 8,1978	10
4051 TAPE DRIVE EXCHANGE	8-29	OCT 13,1978	8
4051 VECTOR LINEARITY	7-12	JUNE 10,1977	11
4051 WARRANTY EXTENDED TO ONE YEAR	8-27	SEPT 15,1978	14
4051/4610 HARD COPY PROBLEM	7-31	DEC 16,1977	10
4051/52-4014 HIGH VOLTAGE FOCUS POTS	10-04	FEB 22,1979	38
4051/52/54 OPTION 10 WITH 4642	10-04	FEB 22,1979	39
4051/52/54 KEYBOARD LEVEL B	10-08	APR 18,1980	19
4051: HOW TO ACCESS THE GPIB CONTROL LINES	7-14	JULY 8,1977	15
4051: RECOVERING OVERWRITTEN 4051 FILES	7-28	NOV 18,1977	11
4051: RUNNING OUT OF DYNAMIC MEMORY	7-28	NOV 18,1977	11
4051C01 RAM/ROM TEST CORRECTION	8-14	MAY 5,1978	7
4051E01 AND 4051C01 BUFFER BOARD MODIFICATION	8-08	MAR 24,1978	6
4051E01 POWER RELAY MOD	8-04	FEB 17,1978	10
4051R06 EDITOR ROM LOCKUP PROBLEM	7-17	AUG 5,1977	12
4051R06 EDITOR ROMPACK LEVEL 2 CHECKSUMS	7-15	JULY 22,1977	9
4051R06 FIRMWARE LEVEL 2	7-16	JULY 29,1977	8
4052 4054 TAPSEND ENHANCEMENT ROMPACK CHECKSUM	10-16	AUG 8,1980	15
4052 B0 SUPPORT	9-07	APR 20,1979	18

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
4052 INTERMITTENT SYSTEM ERROR #41	10-04	FEB 22,1979	38
4052 POWER SUPPLY	10-03	FEB 8,1980	25
4052 SERVICE UPDATE PROGRAM DELETED	10-09	MAY 2,1980	26
4052 SRVCE UPDATE PRGRM DELET(REPLACES ARTCL PRNTD IN MAY 2 ISSUE	10-11	MAY 30,1980	31
4052 WITH OPT 1 COMMUNICATION PROBLEM	9-22	NOV 16,1979	21
4052/4054 ALU BOARDS 4.9 MHZ CLOCK	10-04	FEB 22,1979	38
4052/4054 VERSION 4.1 FIRMWARE	10-05	MAR 7,1980	34
4052/4054 OPTION 10 PRINTER INTERFACE MODIFICATION #M37416	10-05	MAR 7,1980	34
4052/4054 HARD COPY QUALITY	10-09	MAY 2,1980	26
4052/4054 VERSION 4.2 FIRMWARE	10-13	JUNE 27,1980	27
4052/4054 MISLABELED IC'S ON MAS BOARD	10-22	OCT 31,1980	26
4052/4054 VERSION 4.2 FIRMWARE	10-24	DEC 12,1980	24
4052/4054 FOUR SLOT BACKPACK WITH A 4907 FILE MANAGER ROMPACK	10-24	DEC 12,1980	24
4052/4054 R09 REAL TIME CLOCK ROMPACK FIRMWARE UPGRADE	10-25	DEC 19,1980	13
4052/54 +15 REGULATOR CIRCUIT #M39801	10-09	MAY 2, 1980	31
4052/54 +15V REGULATOR CIRCUIT #M39801 CORRECTION	10-12	JUNE 13,1980	14
4052/54 DIAGNOSTIC ROMPAC (067-0900-00) FIRMWARE UPGRADE	10-07	APR 4,1980	13
4052/54 MAG TAPE ERROR - COM CLOCK MOD #M40828	10-23	NOV 21,1980	34
4052/54 MANUALS NOW AVAILABLE	9-23	NOV 30,1979	22
4052/54 OPTION 10 PRINTER INTERFACE CRC	10-18	SEPT 5,1980	16
4052/54 ROM PACK, ROM PART NUMBERS PRINTED INCORRECTLY	9-23	NOV 30,1979	22
4052/54 SERVICE INFORMATION	10-09	MAY 2, 1980	29
4052/54 VERSION 4.1 FIRMWARE	10-09	MAY 2, 1980	31
4054 +5 VOLT OUTPUT BOARD	10-05	MAR 7,1980	43
4054 4052 TAPESEND ENHANCEMENT ROMPACK CHECKSUM	10-16	AUG 8,1980	15
4054 DISPLAY CONTROLLER MOD #39369	10-05	MAR 7,1980	36
4054 DISPLAY CONTROLLER MODIFICATION #39763	10-06	MAR 21,1980	22
4054 DISPLAY CONTROLLER MODIFICATION #39763 CORRECTION	10-13	JUNE 27,1980	30
4054 F30 SHIPMENTS	10-10	MAY 16,1980	24
4054 GPIB ERROR	10-07	APR 4,1980	14
4054 HARDCOPY ON POWER-UP MOD #40915	10-17	AUG 22,1980	19
4054 I/O BOARD (670-5666-00) WIRING ERROR	10-02	JAN 25,1980	28
4054 OPT 30 - MEMORY TESTING WITH DIAGNOSTIC ROMPAK (067-0900-00)	10-07	APR 4,1980	16
4054 OPT. 30 VECTOR GEN & DISPLAY CONTROLLER INTERACTING PRBLM	10-13	JUNE 27,1980	30
4054 OPTION 30 INSTALLATION	10-03	FEB 8,1980	26
4054 OPTION 30	10-07	APR 4,1980	15
4054 OPTION 30 MOD #M40364	10-17	AUG 22,1980	19
4054 VECTOR GENERATOR MODIFICATION #M38743	10-05	MAR 7,1980	38
4054 VECTOR GEN & DISPLAY CONTROLLER MODS #M41262 & M41404	10-23	NOV 21,1980	36
4054/4052 ALU BOARDS 4.9 MHZ CLOCK	10-04	FEB 22,1979	38

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
4054/618 DEFLECTION AMP BOARD (672-0783-02)MODIF #M39710 & #M38624	10-20	OCT 3,1980	31
405X 4923 4924 4081 TAPE DRIVE MAINTENANCE	10-19	SEPT 19,1980	29
405X SERIES COMPATIBILITY	10-03	FEB 8,1980	24
405X TAPE DRIVE BOARDS	10-04	FEB 22,1979	35
4081 & MEG SYSTEMS ADDED TO THE SYSTEM DOWN SUPPORT CATEGORY	9-24	DEC 14,1979	14
4081 - WE'VE GOT OUR EARS ON!	7-05	MAR 4,1977	18
4081 BACKPLANE PROBLEMS CAUSED BY SHIPPING VIBRATION	7-04	FEB 18,1977	10
4081 CARD CAGE COVER	7-03	FEB 4,1977	14
4081 CARTRIDGE TAPE CONTROL BOARD POWER UP IPL MOD	7-03	FEB 4,1977	13
4081 C0 CARD CAGE UPDATE	8-26	SEPT 1,1978	20
4081 COMMUNICATION/MODEM COMPATIBILITY	8-01	JAN 20,1978	9
4081 COMMUNICATIONS INTERFACE/SET UTILITY PROGRAM	7-05	MAR 4,1977	19
4081 DISPLAY CONTROLLER PROM PART NUMBERS	7-16	JULY 29,1977	12
4081 DISPLAY CONTROLLER PROM PART NUMBERS CORRECTION	7-18	AUG 12,1977	5
4081 DISPLAY CONTROLLER PROM PART NUMBERS CORRECTION	8-05	MAR 3,1978	12
4081 FIELD FAILURE REPORTING	7-26	OCT 28,1977	10
4081 FLOATING POINT AND BACKPLANE SHIELD CODE 18 UPDATE	10-02	JAN 25,1980	31
4081 HEX PANEL (067-0772-00) FAILURE TO CLEAR WHEN ATTEMPTING BITSWITCH PROGRAMS	9-16	AUG 24,1979	18
4081 HEX PANEL (067-0772-00) LOCKUP DURING POWER UP	9-16	AUG 24,1979	19
4081 IPL/MKPHT EPROM'S P/N	9-04	MAR 2,1979	14
4081 KEYBOARD JOY SWITCH PART NUMBER	7-16	JULY 29,1977	12
4081 MEMORY GOES TO SLEEP	7-08	APR 15,1977	7
4081 PRODUCT ENHANCEMENT FLOATING POINT UPGRADE CODE-18	8-20	JUN 23,1978	10
4081 ROMULAN BOARD VOLTAGE DEFICIENCY	9-02	FEB 2,1979	12
4081 TABLET I/F CARD PLACEMENT	8-01	JAN 20,1978	10
4081 TAPE DRIVE COMPATIBILITY/FAILURE TO IPL PROBLEM CORRECTION	8-10	APR 7,1978	6
4081 TAPE DRIVE COMPATIBILITY/FAILURE TO IPL PROBLEMS	8-04	FEB 17,1978	11
4081 WHEEL KITS	7-17	AUG 5,1977	12
4081/4012/RE4012/4013/4014/4015 HIGH VOLTAGE TRANSFORMER MOD 35981	10-04	FEB 22,1979	36
4081/4905 FLOPPY DISC FORMATTING ERRORS	7-11	MAY 27,1977	12
4081/4905 HARD DISC POWER UP/POWER DOWN	7-05	MAR 4,1977	20
4081/4905 MAINTENANCE HANDBOOK AND 4081 SERVICE DISC	8-01	JAN 20,1978	11
4081/4905 MAINTENANCE HANDBOOK (067-0855-99) REVISION			26
4081/4923/4924 TAPE DRIVES	8-21	JUN 30,1978	6
4081/4931 COMPATIBILITY PROBLEMS	7-05	MAR 4,1977	21
4081/619 & MEG121/619 CABLE INTERCONNECT BOARD	10-17	AUG 22,1980	20
4081/619 STORAGE BOARD MODIFICATION #36079	10-04	FEB 22,1979	37
4081/619 STORAGE CIRCUIT BOARD M36079	10-22	OCT 31,1980	27
40XX KEYBOARDS	7-30	DEC 9,1977	11
4601/4601-1	7-03	FEB 4,1977	9

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
4601/4610 PROCESSOR CLEANING	7-21	SEPT 9,1977	9
4601/4610 TROUBLESHOOTING HIGH VOLTAGE REGULATORS	7-04	FEB 18,1977	6
4610 HARD COPY WITH MULTIPLEXER OPTION	7-11	MAY 27,1977	9
4610 PROCESSOR	9-07	APR 20,1979	18
4623/4631/4632 PART NUMBER ERROR, PROCESSOR ASSEMBLY	9-02	FEB 2,1979	12
4623/4631/4633 CRT REPLACEMENT INFORMATION	7-24	OCT 7,1977	4
4631 ADJUSTMENTS TO COPY A 4025	7-30	DEC 9,1977	13
4631 MAINBOARD	8-06	MAR 10,1978	9
4631 MULTIPLEXER - ADJACENT CHANNEL COPYING PROBLEM	7-06	MAR 18,1977	5
4631 OPTION 31 COMPATIBILITY	9-02	FEB 2,1979	13
4631 OPTION 31, 4025 COMPATIBILITY	8-07	MAR 17,1978	6
4631 Y-AXIS DEFLECTION MODIFICATION #40282	10-23	NOV 21,1980	37
4631/32/33A/34 POWER TRANSFORMER JUMPERING	10-10	MAY 16,1980	25
4631/32/33A/34: CLUTCH & CNTRL BOARD MODIF #37349,40065 & 40750	10-13	JUNE 27,1980	30
4631/32/33A/34 FAULTY SPROCKETS	10-22	OCT 31,1980	28
4631/43 LOSS OF SLACK LOOP	10-11	MAY 30,1980	32
4631/4632 MECHANICAL MODIFICATION #35572	10-02	JAN 25,1980	31
4631/4632 - SETSCREWS NOT LISTED IN MANUAL	7-01	JAN 14,1977	8
4631/4632 230-V WIRING INFORMATION	7-08	APR 15,1977	4
4631/4632 CABINET MOD #35647	9-08	MAY 4,1979	33
4631/4632 CONTROL BOARD 670-4	8-26	SEPT 1,1978	21
4631/4632 CONTROL BOARD MOD #36278	9-07	APR 20,1979	21
4631/4632 CUTTER CLUTCH PART NUMBER CHANGE AND NEW ADJUSTMENT PROCEDURE CHANGE	8-21	JUN 30,1978	7
4631/4632 H.V. BOARD RESISTORS CHANGED	7-24	OCT 7,1977	6
4631/4632 HEATER PLATES	9-03	FEB 16,1979	18
4631/4632 HIGH VOLTAGE ARCING AND CAPACITOR BREAKDOWN PROBLEMS	7-06	MAR 18,1977	5
4631/4632 MAINBOARD FUSES	9-07	APR 20,1979	22
4631/4632 NOT RECEIVING CUT COMMAND	7-11	MAY 27,1977	9
4631/4632 PHOTOISOLATOR REPLACED	7-21	SEPT 9,1977	11
4631/4632 PROCESSOR, CHAIN RUBS ON CHAIN GUARD	8-31	NOV 10,1978	13
4631/4632 TEMPERATURE ADJUSTMENT EXTENSION SHAFT	7-28	NOV 18,1977	6
4631/4632/4633A/4634: MOTOR MODIFICATION #38116	10-06	MAR 21,1980	23
4631/4632/4633A/4634 BOWED PAPER CUT	10-22	OCT 31,1980	27
4631/4632/4633 CABINET ALIGNMENT BRACKETS	8-05	MAR 3,1978	6
4631/4632/4633 DC MOTOR BRUSHES	8-16	MAY 19,1978	10
4631/4632/4633 HEATER PLATE WEAR	8-07	MAR 17,1978	6
4631/4632/4633A/4634 INTERRUPTER ROTORS, MOD #S35061	9-02	FEB 2,1979	14
4632 - HORIZONTAL SYNC PROBLEM LINKED TO C1 VIDEO BOARD	7-01	JAN 14,1977	7
4632 OPTION 8 AVAILABLE	10-04	FEB 22,1979	39
4632 OPTION 6: VIDEO INTERFACE MODIFICATION #39499	10-08	APR 18,1980	20
4632 TIMING BOARD	8-12	APR 21,1978	5

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
4632 TIMING BOARD	8-07	MAR 17,1978	7
4632 VIDEO ASSEMBLY STRAPPING OPTIONS	9-08	MAY 4,1979	33
4633 MANUAL AVAILABLE	7-19	AUG 19,1977	7
4633 TEST FIXTURE	8-02	JAN 27,1978	4
4633A 4634 CONVEYOR MODIFICATION #37411	10-20	OCT 3,1980	33
4633A CONTROL BOARD MOD #36142	9-07	APR 20,1979	22
4633A INSTRUCTION MANUAL, 070-2547-01	9-04	MAR 2,1979	10
4633A MOD JE: VIDEO ASSEMBLY CHANGE	10-07	APR 4,1980	21
4633A MOD JE: MAINBOARD DEFLECTION AMPLIFIER CHANGE	10-07	APR 4,1980	20
4633A MOD JE: MAINBOARD MODIFICATION	10-08	APR 18,1980	21
4633A MOD JE MAINBOARD BLANKING CHANGE	10-10	MAY 16,1980	26
4633A MOD JE: T.V. TIMING BOARD CHANGE	10-13	JUNE 27,1980	32
4633A REAR PANEL, FUSE VALUE ERROR	9-03	FEB 16,1979	19
4633A ROTARY BLADE MODIFICATION 36766	10-05	MAR 7,1980	43
4633A SWITCHED PHONE PLUG	10-06	MAR 21,1980	23
4633A VIDEO AND SWEEP BOARD MOD 38204	10-21	OCT 17,1980	25
4633A/4634 DISSASSEMBLY/REASSEMBLY VIDEO TAPES	10-12	JUNE 13,1980	14
4633A/4634 CONVEYOR ASSEMBLY MOD #36198	9-07	APR 20,1979	23
4634 OPTION 52, 100 VOLTS: MODIFICATION #38641	10-05	MAR 7,1980	44
4634 SCAN RATE CALIBRATION	10-13	JUNE 27,1980	33
4634 SCAN RATE CALIBRATION CORRECTION	10-22	OCT 31,1980	29
4634 TIMING BOARD CHANGE, PICN #9	9-03	FEB 16,1979	19
4634 VIDEO BOARD ASSEMBLY, PICN #10	9-03	FEB 16,1979	20
463X FAN HOUSING MODIFICATION #36277	10-02	JAN 25,1980	27
463X HARD COPIER PAPER LENGTH VARIATIONS	9-07	APR 20,1979	19
463X HARD COPIER PROCESSOR BELT MOD #35409	9-07	APR 20,1979	20
463X HARD COPY UNIT PROCESSOR STATIC PROBLEMS	8-33	DEC 8,1978	10
463X HARD COPY BELT INSTALLATION	9-03	FEB 16,1979	18
463X HCU AND 4953/4954 TABLET DATA TRANSMISSION INTERFERENCE	8-20	JUN 23,1978	10
463X HEATER PLATE MODIFICATION #36948	9-14	JULY 27,1979	26
463X HEATER PLATES: INCORRECT LEAD LENGTH	9-18	SEPT 21,1979	29
463X PROCESSOR DISASSEMBLY AND REASSEMBLY	9-10	JUN 1,1979	15
463X STICKY PROCESSOR BELTS	9-18	SEPT 21,1979	30
463X: PAPER GUIDE ASSEMBLY	10-09	MAY 2,1980	22
4641 DRIVE PULLEY	10-01	JAN 11,1980	34
4641 ENCODER ADJUSTMENT PROCEDURE CHANGE	10-06	MAR 21,1980	24
4641 ENCODER ADJUSTMENT, SERVICE MANUAL ERROR	8-28	SEPT 29,1978	13
4641 LOGIC BOARDS	10-04	FEB 22,1979	40
4641 PRINTER, ERRONEOUS CHARACTERS	9-10	JUN 1,1979	21
4641 PRINTER, POWER BOARD BURNING OR FUSES BLOWING	9-12	JUN 29,1979	13
4641 PRINTER, RIBBON TENSION	9-06	APR 6,1979	26
4641 RESISTORS CHANGED TO IMPROVE PRINTER RELIABILITY	7-14	JULY 8,1977	16

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
4641 RIBBON CABLE PART NUMBERED	10-13	JUNE 27,1980	36
4641/4051 SWITCH SETTINGS	7-13	JUNE 24,1977	15
4641/4641-1 PRINTER, NEW PART NUMBER FOR ENCODER	8-31	NOV 10,1978	13
4642 COLUMN SCALE/TEAR BAR	9-20	OCT 19,1979	13
4642 COLUMN SCALE/TEAR BAR CHANGE	9-22	NOV 16,1979	23
4642 ELECTRO MAGNETIC INTERFERENCE RADIATION	8-33	DEC 8,1978	11
4642 PRINTER, CIRCUIT BOARD CONFIGURATIONS (REPLACEMENT OF ARTICLE IN ISSUE 9-6)	9-10	JUN 1,1979	22
4642 PRINTER, CIRCUIT BOARD CONFIGURATIONS	9-06	APR 6,1979	27
4642 SERVICE MANUAL CHANGE	9-18	SEPT 21,1979	30
4642/4642-1 PRINTER, SERVICE MANUAL AVAILABLE	9-06	APR 6,1979	27
4661 STEP DRIVE BOARD'S CABLE KEYED WRONG	10-15	JULY 25,1980	16
4662 "TERMINAL MUT" MODE "GLITCH"	7-13	JUNE 24,1977	19
4662 - PEN PRESSURE TOO HIGH OR LOW	8-27	SEPT 15,1978	15
4662 - WET PEN VENDOR	7-28	NOV 18,1977	14
4662 ALPHA RESET	7-12	JUNE 10,1977	12
4662 CUSTOM MOD PROM'S	7-11	MAY 27,1977	12
4662 DELETE IGNORE MODE FIRMWARE BUG	8-24	AUG 4,1978	10
4662 DEMO PAPER	7-19	AUG 19,1977	9
4662 DIAGNOSTICS TEST FIXTURE	7-22	SEPT 23,1977	8
4662 DIAGNOSTIC TEST FIXTURE (067-0831-00) WRONG PART NUMBERS ON PROMS	8-21	JUN 30,1978	9
4662 DRIVE MOTOR PROBLEM	8-27	SEPT 15,1978	14
4662 DRIVE MOTOR PROBLEM	8-26	SEPT 1,1978	21
4662 FAMILIARIZATION IN NON-COPY MODE	7-13	JUNE 24,1977	17
4662 FRONT PANEL EXTENDER CABLE	8-27	SEPT 15,1978	15
4662 HALF DUPLEX RS-232	7-19	AUG 19,1977	9
4662 HEX SWITCH CLEANING DAMAGE	7-07	APR 1,1977	12
4662 HIGH FAILURE COMPONENTS	8-22	JUL 7,1978	9
4662 INFORMATION ON THE VIDEO TRAINING TAPE	7-10	MAY 13,1977	11
4662 INHIBITING PEN BUG MOVEMENT	8-02	JAN 27,1978	5
4662 INTERACTIVE DIGITAL PLOTTER FIRMWARE LEVELS	8-23	JUL 21,1978	21
4662 INTERACTIVE DIGITAL PLOTTER FIRMWARE LEVELS	8-13	APR 28,1978	11
4662 JOYSTICKS	7-30	DEC 9,1977	14
4662 LEVEL 3P FIRMWARE MOD #M35132	9-04	MAR 2,1979	10
4662 LIMIT SWITCHES, PART NUMBERS	7-19	AUG 19,1977	10
4662 MEASURING THE PLATEN ELECTROSTATIC 880 VDC	10-07	APR 4,1980	17
4662 MOTOR REPLACEMENT	7-30	DEC 9,1977	14
4662 OPTION 20 AVAILABLE	10-11	MAY 30,1980	33
4662 PEN HEIGHT CHANGING	8-14	MAY 5,1978	7
4662 PLATTEN ALIGNMENT: REF ISSUE 9-13, P. 28	8-21	JUN 30,1978	9
4662 PLOTTER BOARD, RAM PLACEMENT	9-22	NOV 16,1979	23
4662 PLOTTER, ORTHOGONALITY VERIFICATION: REF ISSUE 9-22, P. 23	9-13	JULY 13,1979	28

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
4662 PLOTTER, PEN ACTIVATES UPON POWER DOWN	8-34	DEC 22,1978	9
4662 PLOTTER, PLOTTER BOARD (670-4102-07) MOD M31709	9-13	JULY 13,1979	28
4662 PLOTTER, PLOTTER BOARD (670-4102-XX) REPLACEMENT	9-14	JULY 27,1979	26
4662 POWER SUPPLY MODIFICATIONS	7-15	JULY 22,1977	9
4662 POWER SUPPLY RESISTANCE WIRE	7-15	JULY 22,1977	11
4662 POWER SUPPLY SWITCHING TRANSISTORS	8-23	JUL 21,1978	22
4662 POWER SUPPLY TRANSFORMER PROBLEM	7-11	MAY 27,1977	13
4662 PREVENTATIVE MAINTENANCE SCHEDULE AND PROCEDURE	7-10	MAY 13,1977	9
4662 REPLACEMENT CABLE - PARTS ORDER INFORMATION	8-20	JUN 23,1978	11
4662 RS-232-C INTERFACE ARTWORK PROBLEM	7-23	SEPT 30,1977	6
4662 TEST TAPE	7-21	SEPT 9,1977	9
4662 WET INK PENS	7-13	JUNE 24,1977	16
4662 WIRE STRINGING	7-30	DEC 9,1977	14
4662 X AXIS PULLEY	7-31	DEC 16,1977	11
4662/4051 OPT 1 GRAPHICS OPERATION	7-13	JUNE 24,1977	16
4662/HP 9830A GLITCHES	7-13	JUNE 24,1977	18
4662/RS-232 MUTE OVERRIDE	7-19	AUG 19,1977	10
4662/TTY WITH 4010 SERIES	7-24	OCT 7,1977	8
4663 CORRECTIVE ACTION	10-05	MAR 7,1980	44
4663 DEMO SERVICE SUPPORT	9-04	MAR 2,1979	10
4663 DIAGNOSTIC TEST FIXTURE F/W UPDATE	10-01	JAN 11,1980	34
4663 DIAGNOSTIC TEST FIXTURE MANUAL AVAILABLE	10-10	MAY 16,1980	27
4663 DIAGNOSTIC TEST FIXTURE ROM CHECKSUM TEST	9-18	SEPT 21,1979	31
4663 FIELD INSTALLABLE MEDIA ADVANCE PROBLEMS	9-15	AUG 10,1979	35
4663 FIRMWARE IDENTIFICATION: REF ISSUE 9-24, P.15	9-14	JULY 27,1979	27
4663 FIRMWARE LOGISTICS AND FUNCTIONS: REF ISSUE 9-24, P. 15	9-19	OCT 5,1979	20
4663 FLEX STRIP TERMINATION CIRCUIT BOARD KIT	10-12	JUNE 13,1980	14
4663 FRONT PANEL LAMP REPLACEMENT	10-21	OCT 17,1980	27
4663 HANGS UP GPIB WHEN AN RS232 INTERFACE IS SELECTED	9-17	SEPT 7,1979	19
4663 INTERMITTENT FAILURE TIPS	10-06	MAR 21,1980	24
4663 INTERFACE BOARDS MODIFICATION	10-22	OCT 31,1980	31
4663 INTERACTIVE DIGITAL PLOTTER, STOPS PLOTTING... WHEN DRIVEN OVER GPIB	9-17	SEPT 7,1979	20
4663 INTERACTIVE DIGITAL PLOTTER PARAMETER ENTRY, LED ON AT POWER UP	9-17	SEPT 7,1979	20
4663 MEASURING PLATEN ELECTROSTATIC VOLTAGE	10-19	SEPT 19,1980	30
4663 NEW "B" PROCESSOR BOARD	10-07	APR 4,1980	18
4663 OPERATOR'S MANUAL	9-19	OCT 5,1979	19
4663 OPTION 32 VERIFICATION	10-24	DEC 12,1980	25
4663 PAPER ROLL HOLDERS	10-02	JAN 25,1980	32
4663 PAPER CLUTCH ADJUSTMENT NUT ROTATES	10-13	JUNE 27,1980	36
4663 PERFORMANCE VERIFICATION KIT	9-19	OCT 5,1979	19
4663 PLATEN CLEANING PROCEDURE	10-14	JULY 11,1980	21

WIZARDS WORKSHOP INDEX

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
4663 PLOTTER, DO NOT USE ALCOHOL ON PLATTEN: REF ISSUE 10-14, P.21	9-09	MAY 18,1979	20
4663 PLOTTER, RS232 INTERFACE (670-5579-01)	9-10	JUN 1,1979	24
4663 PLOTTER, ROM OVERLAY BOARD (670-6275-00) STRAPPING	9-13	JULY 13,1979	29
4663 PLOTTER, SERVICE MAINTENANCE INFORMATION	9-13	JULY 13,1979	A-1
4663 POWER SUPPLY LOAD FOR TROUBLESHOOTING	9-03	FEB 16,1979	20
4663 ROM OVERLAY BOARD MODIFICATION	10-17	AUG 22,1980	20
4663 ROM OVERLAY BOARD EPROM LOCATIONS	9-24	DEC 14,1979	15
4663 ROM SHORTAGE: FOR U.S. ONLY	10-07	APR 4,1980	18
4663 SERVICE IMPLEMENTATION NOTICE CORRECTION	9-18	SEPT 21,1979	31
4663 SET UP FOR 4662 EMULATION	10-15	JULY 25,1980	16
4663 TWO VOLUME SERVICE MANUAL AVAILABLE	10-20	OCT 3,1980	32
4663 VERIFICATION OF THE RS232 I/F WITH AN 832: REF 10-24; P25	10-17	AUG 22,1980	23
4663 VERSION 2 FIRMWARE	10-08	APR 18,1980	22
4663 VERSION 3&4 FIRMWARE & ASSOC HARDWARE (STARTNG S/N B05 & ABOVE)REF	10-20	OCT 3,1980	A-1
4663 WET INK PEN	9-21	NOV 2,1979	14
4663 X CABLE CORRECTION	10-04	FEB 22,1979	43
4663 X, Y CABLE: REF. ISSUE 10-24; P.43	10-01	JAN 11,1980	34
4663 X, Y CABLE	10-01	JAN 11,1980	35
4663 Y AXIS CABLE PULLEY ALIGNMENT	10-11	MAY 30,1980	33
46XX HARD COPY PAPER	8-24	AUG 4,1978	10
4905 CABINET FANS	7-08	APR 15,1977	8
4905 CALCOMP DISC DRIVE DOOR LATCH	8-31	NOV 10,1978	13
4905 CALCOMP FLOPPY DISC DRIVE -- ALIGNMENT DISC RECALL	7-05	MAR 4,1977	20
4905 HARD DISK SPINDEL DRIVE PWR TRANSISTORS	10-03	FEB 8,1980	29
4905 HARD DISC PART I AND PART II (WANGCO) VIDEO CASSETTES	7-05	MAR 4,1977	17
4905 OPT. 33/34 (WANGCO DISC DRIVE) - BAD POT ON +5 VOLT REGULATOR BOARD	7-08	APR 15,1977	14
4905 OPTION 33 & 34 INTERFACE CABLE	10-06	MAR 21,1980	25
4905 OPTION 33/34 WANGCO PART NUMBERS	8-26	SEPT 1,1978	22
4905 OPTION 33/34 WANGCO PHASING HARNESS	8-26	SEPT 1,1978	22
4905 OPTION 33/34 WANGCO HARD DISC CAPS	8-25	AUG 18,1978	5
4905 OPTION 33/34 HARD DISC DRIVE	8-25	AUG 18,1978	5
4905 WANGCO PART NUMBERS	10-01	JAN 11,1980	35
4905 WANGCO HARD DISK DRIVE TERMINATOR	10-22	OCT 31,1980	31
4905 WANGCO CALIBRATION (INDEX TO DATA)	9-14	JULY 27,1979	28
4905/4907 ALIGNMENT DISC (119-0896-00) MIXUP	8-05	MAR 3,1978	13
4905/4907/8002/8002A DEF.DISCS 119:1011:00,01 & 119-0848-00,01	10-17	AUG 22,1980	25
4907 DISC DRIVE CALIBRATION	10-09	MAY 2, 1980	32
4907 FILE MANAGER POWER SUPPLY SHORT OUT	8-33	DEC 8,1978	11
4907 FILE MANAGER MAINTENANCE UPDATE	9-14	JULY 27,1979	28
4907 FILE MANAGER	8-19	JUN 9,1978	13

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
4907 FILE MANAGER DRIVE ADDRESSING	8-31	NOV 10,1978	14
4907 FILE MANAGER INTERCONNECT CABLE	8-21	JUN 30,1978	10
4907 FILE MANAGER FIRMWARE CHANGE REVIEW	9-08	MAY 4,1979	38
4907 FIRMWARE CHECKSUMS	10-06	MAR 21,1980	26
4907 GENERAL INFORMATION & CALIBRATION (REF. PULL-OUT)	10-19	SEPT 19,1980	A-1
4907 POWER SUPPLY CABLE PROBLEM	10-05	MAR 7,1980	45
4907 POWER SUPPLY MODIFICATION #40319	10-14	JULY 11,1980	22
4907 POWER SUPPLY CABLE	10-21	OCT 17,1980	27
4907 PRODUCT MAINTENANCE TABLE OF CONTENTS	8-11	APR 14,1978	5
4907 SERVICING THE FILE MANAGEMENT SYSTEM	8-27	SEPT 15,1978	8
4907/4905 FLOPPY DISC MEDIA 119-0848-01, 119-1011-01	10-05	MAR 7,1980	46
4907/4905/8002/8002A DEF.DISCS 119-1011-00,01 & 119-0848-00,01	10-17	AUG 22,1980	25
4923 DIGITAL CARTRIDGE TAPE RECORDER CALIBRATION CLARIFICATION	8-26	SEPT 1,1978	23
4923 OPERATING SPLIT BAUD RATES	7-13	JUNE 24,1977	20
4923 OPT. 1 CUSTOM MOD PROM'S	7-11	MAY 27,1977	13
4923 OPT. 1 HALF DUPLEX	8-05	MAR 3,1978	13
4923 TAPE DRIVE INTERNAL POWER CABLE (198-2641-00)	8-22	JUL 7,1978	9
4923/4081/4924 TAPE DRIVE MOTOR SPEED ERRORS	10-06	MAR 21,1980	21
4924 - U155 PART #156-0778-02 DEFECTIVE DATE CODE	10-11	MAY 30,1980	35
4924 ALTERNATE MODE OPERATION	7-12	JUNE 10,1977	14
4924 BINARY EOF CHARACTER	7-15	JULY 22,1977	12
4924 CARTRIDGE TAPE DRIVE, LEVEL 3 ROM HAS INTERNAL WIRING ERROR	9-02	FEB 2,1979	14
4924 COMPATABILITY WITH 401X OPTION 5	10-06	MAR 21,1980	26
4924 DIGITAL CARTRIDGE TAPE DRIVE FIRMWARE LEVELS	8-13	APR 28,1978	12
4924 DIGITAL CARTRIDGE TAPE DRIVE ROM CHECKSUMS	8-20	JUN 23,1978	12
4924 FIRMWARE CHECKSUMS	10-06	MAR 21,1980	28
4924 FIRMWARE LEVEL 3 CHECKSUMS	7-22	SEPT 23,1977	9
4924 I/O ERROR MODIFICATION #M41584	10-21	OCT 17,1980	27
4924 ROM LOT DATE PROBLEM	7-19	AUG 19,1977	11
4924 TAPE DRIVE, HEAD SKEW AND HEIGHT ADJUSTMENT	8-31	NOV 10,1978	14
4924, 670-4525-04 CONTROL BOARD M35813	10-13	JUNE 27,1980	37
4924/4923/4081 TAPE DRIVE MOTOR SPEED ERRORS	10-06	MAR 21,1980	21
4953 PULSER CABLES	7-07	APR 1,1977	12
4953/4954 LOCKS UP 4010 FAMILY TERMINALS	7-11	MAY 27,1977	9
4953/4954 OPTION 30 OSCILLATOR ON 4081 TABLET CONTROL INTERFACE	9-02	FEB 2,1979	15
4953/4954 PART NUMBER ADDITIONS	8-15	MAY 12,1978	11
4953/4954 PULSER CABLES	7-12	JUNE 10,1977	7
4953/4954/4956 NOISE ELIMINATION	8-27	SEPT 15,1978	16
4953/4954/4956 GRAPHIC TABLETS, TABLET PART NUMBERS	9-09	MAY 18,1979	20
4953/4954/4956 GRAPHICS TABLETS, PREAMP ADJUSTMENT	9-10	JUN 1,1979	25

WIZARDS WORKSHOP INDEX

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
4956 FIRMWARE PART NUMBERS	10-21	OCT 17,1980	28
4956 FRONT PANEL LEDS	8-09	MAR 31,1978	12
4956 GRAPHIC TABLET PREAMP GROUND IMPROVED	7-14	JULY 8,1977	17
4956 INTERMITTENT PROXIMITY LED	7-23	SEPT 30,1977	7
4956 PROMS	8-17	MAY 26,1978	4
4956 REPLACEABLE IC'S	7-08	APR 15,1977	9
4956 REPLACEMENT ASSEMBLIES AND ACCESSORIES	7-07	APR 1,1977	15
602 PHASING ADJUSTMENT	10-20	OCT 3,1980	22
606A 607A 608 624 634 OP AMP CHANGE	10-20	OCT 3,1980	22
608 CRT REPLACEMENT IN EARLY INSTRUMENTS	10-21	OCT 17,1980	24
608 Z-AXIS MODIFICATION 38658	10-24	DEC 12,1980	29
611 MOD AA/JA; CRT CHANGE	9-18	SEPT 21,1979	32
611 U450 LAYOUT MISLEADING	10-21	OCT 17,1980	24
611, 611/2 TRANSISTOR Q520 ON THE STORAGE BOARD	8-30	OCT 27,1978	10
613 +5 VOLT REGULATOR BREAKDOWN (CORRECTION)	10-05	MAR 7,1980	33
613 +5 VOLT REGULATOR BREAKDOWN	9-06	APR 6,1979	16
613 CG, 613-1 CG, 613 JA; MODIFICATION 35391 APPLIES	10-18	SEPT 5,1980	15
613 HIGH VOLTAGE BOARD RESISTOR CHANGES, MOD #35391 (CORRECTION)	10-04	FEB 22,1979	36
613 HIGH VOLTAGE BOARD RESISTOR CHANGES, MOD #M35391	9-03	FEB 16,1979	14
613 MOD JA CM 020-0509-00	10-14	JULY 11,1980	24
613, 619, 4012, RE4012 HIGH VOLTAGE TRANSFORMER MOD 35981	10-04	FEB 22,1979	36
613/613-1 DEFLECTION AMPLIFIER BOARD CAPACITOR CHANGE	8-22	JUL 7,1978	7
613/613-1 HARDCOPY AMPLIFIER MOD #36954	9-11	JUN 15,1979	10
618 CRT	9-09	MAY 18,1979	16
618 DEFLECTION AMPLIFIER, FOCUS CORRECTION AND SLU	9-07	APR 20,1979	14
618 STORAGE BOARD ASSEMBLY, FGA SIGNAL	9-06	APR 6,1979	16
618 TO IBM 3277 INTERCONNECT CABLE	9-10	JUN 1,1979	12
618/619/GMA101A/GMA102A/4014/4015 CRT MODIFICATION	9-07	APR 20,1979	15
618/GMA101A/GMA102A/GMA125A/4016: STORAGE BOARD MODIFICATION	9-22	NOV 16,1979	21
618/GMA101A/GMA102A/GMA125/4016: STORAGE BOARD	9-20	OCT 19,1979	12
619 MANUAL	7-09	APR 29,1977	8
619 MANUAL CORRECTION	7-10	MAY 13,1977	9
619/4081 STORAGE BOARD MODIFICATION #36079	10-04	FEB 22,1979	37
619/4081 STORAGE CIRCUIT BOARD M36079	10-22	OCT 31,1980	27
619/4081 WRITE-THRU INTENSITY	7-09	APR 29,1977	8
619/4081/S1001 SWITCH	8-22	JUL 7,1978	7
634 ARCING CRT DETECTION	10-21	OCT 17,1980	24
634 MODIFICATION #36364	10-18	SEPT 5,1980	15
634 RELIABILITY & NOISE MODIFICATION #37777	10-20	OCT 3,1980	23
634 TORX TOOLS AVAILABLE	10-19	SEPT 19,1980	28
8002/8002A/4905/4907 DEF.DISCS 119-1011-00,01 & 119-0848-00,01	10-17	AUG 22,1980	25

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
832 TEST PROM FOR IDD: ORDERING CORRECT PART NUMBER	10-13	JUNE 27,1980	27
ACCESSORY MOTHER BOARD CABLE CONNECTIONS	7-09	APR 29,1977	9
ADDENDUM TO INSTALLATION OF TTY PORT INTERFACE... WITH M48-024 INTERFACE CARD	7-16	JULY 29,1977	6
ADDENDUM TO RS232 TO 20MA CURRENT LOOP ADAPTER ARTICLE	7-09	APR 29,1977	11
ADDITION TO DECEMBER 22 ARTICLE ON CLEANING KEYBOARDS ON TERMINALS AND SYSTEMS	7-02	JAN 21,1977	8
APPARENT 4956 PROXIMITY LED FAILURE	7-01	JAN 14,1977	10
ASCII & IEEE 488 (GPIB) CODE CHART	9-19	OCT 5,1979	18
BAD FOCUS RESISTOR IN IDG PRODUCTS	7-11	MAY 27,1977	8
CALIBRATION TAPES	8-15	MAY 12,1978	8
CAPACITOR SIZE (C601) INCORRECT ON THE GMA102A LOW VOLTAGE POWER SUPPLY	8-31	NOV 10,1978	7
CIRCUIT BOARD REVISION LEVEL TAGS	10-06	MAR 21,1980	19
CM 020-0336-00 4953 GRAPHICS TABLET...INTERACTIVE BUFFER CM 018-0120-00	8-29	OCT 13,1978	6
COMPUTER DISPLAY HIGH VOLTAGE FAILURES	8-26	SEPT 1,1978	12
COMPUTER VERSUS TERMINAL ANSWERBACK RESPONSE IMPROVEMENT	7-21	SEPT 9,1977	6
CORRECTION TO IDG SERVICE SUPPORT PRODUCT RESPONSIBILITY LIST	8-14	MAY 5,1978	5
DATA CARTRIDGES MISSING STOP HOLES	9-08	MAY 4,1979	31
DATA GENERAL TTY I/F - OPTION 4	7-19	AUG 19,1977	8
DEC DL11W INTERFACE	7-02	JAN 21,1977	7
DEFECTIVE 156-0141-00 & 01 (SN 74156N)	7-05	MAR 4,1977	12
DETERMINING OUTPUT DATA CODING SIZE MESSAGE/READ STATUS FOR RS232 (PULL-OUT REFE	7-14	JULY 8,1977	8
DIGITAL EXERCISER FOR THE GMA101A, GMA102A	8-27	SEPT 15,1978	7
DIODES PRESENTLY SUPPLIED BY VENDOR HAS CHANGED IN PHYSICAL SIZE	8-31	NOV 10,1978	7
DISPLAY BUFFER (CM018-0109-00) WITH MAJOR MOD 4014/15	7-01	JAN 14,1977	9
EPROM REQUIREMENTS	9-16	AUG 24,1979	14
FIRMWARE UPGRADE MOD KIT SUMMARY	7-11	MAY 27,1977	11
FUSEHOLDER MODIFICATION 33774	9-15	AUG 10,1979	31
GMA SERIES OPTION 32 AUDIO TAPE	8-17	MAY 26,1978	4
GMA SERIES OPTION 42/43 FORMAT BOARD CHANGE	8-34	DEC 22,1978	7
GMA SERIES OPTION 42 VECTOR GENERATOR BOARD RESISTOR CHANGES	8-33	DEC 8,1978	7
GMA SERIES OPTION 42/43 FORMAT BOARD MOD #36174	9-08	MAY 4,1979	31
GMA101A AND 102A DEFLECTION AMPLIFIER, FOCUS CORRECTION	9-06	APR 6,1979	9
GMA101A CRT PART NUMBERS	7-19	AUG 19,1977	7
GMA101A FLEXIBLE ECB EXTENDER	7-12	JUNE 10,1977	7
GMA101A HIGH VOLTAGE SUPPLY	8-16	MAY 19,1978	6
GMA101A MANUAL ERROR	7-20	AUG 26,1977	4
GMA101A MANUAL ERROR	7-17	AUG 5,1977	7
GMA101A STORAGE BOARD	8-07	MAR 17,1978	4
GMA101A/GMA102A/618: DEFLECTION AMPLIFIER MODIFICATION-37327	9-17	SEPT 7,1979	17

WIZARDS WORKSHOP INDEX

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
GMA101A/GMA102A MICO INSULATOR REPLACEMENT ON STORAGE BOARD ASSEMBLY	8-29	OCT 13,1978	6
GMA101A/GMA102A/GMA125/618/4016: STORAGE BOARD MODIFICATION #37800	9-20	OCT 19,1979	12
GMA101A/GMA102A REMOTE INTENSITY MODIFICATION	8-19	JUN 9,1978	6
GMA102A DEFLECTION AMPLIFIER MODIFICATIONS #36442 & #37731	10-05	MAR 7,1980	32
GMA102A DEFLECTION AMP CIRCUIT BOARD ASSEMBLY MOD-#36152	9-07	APR 20,1979	13
GMA102A DEFLECTION AMPLIFIER MODIFICATION	9-20	OCT 19,1979	11
GMA102A HARD COPY GAIN ADJUSTMENT POTS ADDED	10-13	JUNE 27,1980	26
GMA102A HIGH VOLTAGE/Z-AXIS, MOD #34690	9-02	FEB 2,1979	7
GMA102A LOW VOLTAGE POWER SUPPLY MODIFICATION 35837	9-18	SEPT 21,1979	21
GMA102A LOW VOLTAGE POWER SUPPLY, +5 VOLT FUSE CHANGE	9-07	APR 20,1979	13
GMA102A MANUAL FOR SERIAL NUMBER B060000 AND UP	10-23	NOV 21,1980	34
GMA102A OPTION 36 RESISTOR CHANGES	9-14	JULY 27,1979	22
GMA102A POWER SUPPLY MODIFICATIONS #37734, #37910 & #37988	10-04	FEB 22,1979	28
GMA102A/GMA125: OPTION 42 AND 43 MODIFICATION #36078	10-04	FEB 22,1980	26
GMA102A/GMA125: OPTION 42 AND 43 MODIFICATION 37335	10-04	FEB 22,1980	26
GMA125 DEFLECTION AMPLIFIER, FOCUS CORRECTION AND HEAT SINK	9-06	APR 6,1979	10
GMA125 LOW VOLTAGE POWER SUPPLY CAPACITOR BOARD	9-06	APR 6,1979	11
GMA125 LOW VOLTAGE POWER SUPPLY, 220V IMPROVEMENT	9-06	APR 6,1979	12
GMA125 LVPS PRIMARY BOARD INVERTER TRANSISTORS	9-06	APR 6,1979	14
GMA125 LVPS PRIMARY BOARD, SWITCHING CIRCUIT	9-06	APR 6,1979	15
GMA125 LVPS SECONDARY BOARD, PARTS LIST ERROR	9-06	APR 6,1979	15
GMA125/4016 DISPLAY: LOW VOLTAGE POWER SUPPLY MOD #37309 (CORRECTION)	10-04	FEB 22,1979	27
GMA125/4016 HIGH EFFICIENCY POWER SUPPLY	10-02	JAN 25,1980	28
GMA125/4016 DISPLAY: LOW VOLTAGE POWER SUPPLY MOD 37309	10-02	JAN 25,1980	24
GMA125/4016: HIGH VOLTAGE AND Z AXIS MODIFICATION 38078	10-05	MAR 7,1980	33
GMA191A/GMA192A/GMA125A/4016/618: STORAGE BOARD MOD NUMBER 37800 CORRECTION	9-22	NOV 16,1979	21
GPIB COMPATIBILITY	8-04	FEB 17,1978	8
GPIB LOADING PROBLEM	7-12	JUNE 10,1977	7
GRAPHIC TABLET REPACKING INFORMATION	7-12	JUNE 10,1977	9
GRAPHIC TABLET MAGNETIC KEEPERS	7-22	SEPT 23,1977	5
H-STS S-3260 ISI CURRENT SUPPLY	8-30	OCT 27,1978	20
HARD COPY PAPER	8-06	MAR 10,1978	8
HCU MOTOR GENERATOR BRUSH REPLACEMENT	8-23	JUL 21,1978	10
IDD MAINTENANCE AGREEMENT PROMOTION SERVICE PLAN 12/14/79	10-22	OCT 31,1980	26
IDD OEM SERVICE GUIDELINES	10-02	JAN 25,1980	25
IDD TEST PROM FOR THE 832,833	10-09	MAY 2,1980	18
IDD TEST PROM FOR THE 832/833 P/N 067-0960-99	10-13	JUNE 27,1980	26
IDENTIFICATION OF IDG CUSTOM MOD BOARDS	8-24	AUG 4,1978	7

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
IDG HAS A NEW FORMAT	8-10	APR 7,1978	4
IDG INTERFACE	8-18	JUN 2,1978	5
IDG KEYBOARDS	7-32	DEC 23,1977	8
IDG PACKAGING CHANGE	7-17	AUG 5,1977	8
IDG SERVICE SUPPORT 24-HOUR TELEPHONE ANSWERING EQUIPMENT	8-07	MAR 17,1978	8
IDG TERMINAL CRT'S	7-32	DEC 23,1977	7
IDP MODIFIED PRODUCTS	7-17	AUG 5,1977	9
INSTALLATION OF TTY PORT INTERFACE...WITH M48-024 INTERFACE BOARD	7-13	JUNE 24,1977	10
INSTALLATION OF OPTION 16 TO DEC PDP-11 WITH DL11-W	7-05	MAR 4,1977	14
INTERACTIVE BUFFER W/TABLET, MODIFICATIONS(MCDOWELL DOUGLAS AUTOMATION SYSTEMS)	7-22	SEPT 23,1977	6
INTERACTIVE BUFFER (018-0120-00) INSTALLATION INSTRUCTION ADDITIONS	7-23	SEPT 30,1977	4
INTERFACING THE 4051 TO ROLM PROCESSORS	7-04	FEB 18,1977	7
INTERMITTENT LOSS OF RECEIVED DATA WITH STANDARD INTERFACE	7-12	JUNE 10,1977	8
INTERMITTENT PROBLEMS ASSOCIATED WITH 4014/15 TC-3	7-05	MAR 4,1977	14
KEY OPERATOR TAGS	8-02	JAN 27,1978	5
KEYBOARDS P/N 119-0482-XX AND 119-0488-XX	10-07	APR 4,1980	11
L1012A HORIZONTAL DEFLECTION COIL DOES NOT HAVE ENOUGH CURRENT SENSING	8-30	OCT 27,1978	10
LABEL CHANGE ON PAPER CANISTERS FOR ALL HARD COPY UNITS	8-23	JUL 21,1978	12
LATEST PRODUCT MODIFICATIONS FOR 4014/4015 COMPUTER TERMINALS	8-27	SEPT 15,1978	7
MAG TAPE UNIT "LOAD POINT" AND "EOT" CURRENTS	8-03	FEB 3,1978	6
MAG TAPE UNIT STATUS BOARD ARTWORK CORRECTION	7-12	JUNE 10,1977	10
MAGNETIC TAPE CARTRIDGE PROBLEMS	7-21	SEPT 9,1977	6
MEG 121/131 AND ASSOCIATED EQUIPMENT MANUALS	9-17	SEPT 7,1979	19
MEG TC-3 CIRCUIT BOARD P/N	10-09	MAY 2,1980	18
MEG121 CHARACTER GENERATOR P/N	9-21	NOV 2,1979	11
NEW MOD COMP TTY PORT INTERFACE THROUGH MODIFIED PRODUCTS	7-20	AUG 26,1977	6
NEW WARRANTY VS. MAINTENANCE AGREEMENTS	10-04	FEB 22,1979	30
OEM SERVICE GUIDELINES, IDD PRODUCTS	10-09	MAY 2,1980	19
OPTION 1 INTERFACE (021-0074-00) MANUAL ERROR	7-03	FEB 4,1977	9
OPTION 10 PRINTER INTERFACE CRC	10-15	JULY 25,1980	15
OPTION 22 - OPTION 40 BOARD IDENTIFICATION CORRECTION	10-02	JAN 25,1980	25
OPTION 22 (P/N 021-0201-00) TEST PROMS (P/N 067-0861-99)	8-31	NOV 10,1978	9
OPTION 22 - OPTION 40 BOARD IDENTIFICATION	9-22	NOV 16,1979	19
OPTION 22, 23, 40 AND 41 TEST FIXTURES USERS MANUAL P/N 067-0861-99	8-13	APR 28,1978	10
ORDERING 021-0135-01 SYNCHRONOUS INTERFACE BOARDS CORRECTION	7-21	SEPT 9,1977	4
PHONE REQUESTS FOR TECHNICAL ASSISTANCE	10-09	MAY22, 1980	21
PLOT 50: STATISTICS VS. 16K 4051 WITH OPTION 1	7-13	JUNE 24,1977	13
POSSIBLE SELF INDUCED AUTO-ERASE	8-24	AUG 4,1978	8
PROCEDURE FOR ORDERING 021-0135-01 SYNCHRONOUS INTERFACE BOARDS	7-19	AUG 19,1977	8

INFORMATION DISPLAY

TITLE	ISSUE	DATE	PAGE
PRODUCT MODIFICATIONS FOR 4014 AND 4015 COMPUTER TERMINALS	8-23	JUL 21,1978	20
QUESTIONS & ANSWERS,REVISION AND CORRECTIONS	10-14	JULY 11,1980	20
QUESTIONS AND ANSWERS	10-10	MAY 16,1980	19
RECOVERING DATA FROM 4907 DISK FILES	8-31	NOV 10,1978	8
RELIABILITY DATA	8-28	SEPT 29,1978	9
REPLACEMENT OF DAMAGED MAG TAPES	7-07	APR 1,1977	11
REVISION OF 3M R MAG TAPE SKEW ADJUST	7-01	JAN 14,1977	7
RS232 TO 20MA CURRENT LOOP ADAPTER	7-08	APR 15,1977	7
S-3200 POWER UP SEQUENCER MOD	8-30	OCT 27,1978	20
S-3260 ON/OFF POWER BULB	8-30	OCT 27,1978	20
S-3260 TYPE D FIXTURING MANUAL CORRECTION	8-30	OCT 27,1978	23
SERVICE UPDATE PROGRAMS STATUS (REFERENCE PULL-OUT)	10-22	OCT 31,1980	B-1
SERVICE UPDATE PROGRAMS	10-06	MAR 21,1980	20
SHIFT KEY CAP PART NUMBER FOR KEYTRONICS KEYBOARDS	7-01	JAN 14,1977	7
STATIC SENSITIVE PARTS HANDLING, PART NUMBER COMPILATION	8-28	SEPT 29,1978	10
TAPE DRIVE MOTOR SPEED ERRORS: 4081/4923/4924	10-06	MAR 21,1980	21
TECHNICAL SUPPORT OF HARD COPIES	7-05	MAR 4,1977	12
TEK 21/TEK 31 CALCULATOR DISPLAY BOARD MODIFICATION	10-04	FEB 22,1979	35
TEK 31 CLOCK HARMONICS	7-11	MAY 27,1977	15
TEK 31 INTERFACE CONNECTOR COVER	7-04	FEB 18,1977	7
TEK 31 LINE FUSE	9-04	MAR 2,1979	8
TEK 31 MAG TAPE CARTRIDGE REPLACABLE PARTS	9-09	MAY 18,1979	15
TEK 31 MAG TAPE SKEW ADJUSTMENT PROCEDURE	7-13	JUNE 24,1977	6
TEK 31 NEW SERVICE MANUAL AVAILABLE	9-18	SEPT 21,1979	21
TEK LOGO ON RAM MOD #35375	9-04	MAR 2,1979	8
TERMINAL INTERFACE FAILURES	7-08	APR 15,1977	4
TM515 TEST FIXTURE	10-02	JAN 25,1980	27
UPCOMING HOLIDAY PERIOD	10-25	DEC 19,1980	5
UPDATING 4051 GRAPHIC SYSTEM FIRMWARE LEVELS	8-10	APR 7,1978	4
VIDEO CASSETTE 4662 INTERACTIVE DIGITAL PLOTTER CALIBRATION	7-09	APR 29,1977	6

WIZARDS WORKSHOP INDEX

DATA COMMUNICATIONS

TITLE	ISSUE	DATE	PAGE
401X OPT 20 CDC SYNCHRONOUS INTERFACE TESTING WITH 832/833	10-21	OCT 17,1980	B-1
NEW DATA COMMUNICATION SECTION	10-21	OCT 17,1980	29

LABORATORY INSTRUMENT DIVISION

MICRO-COMPUTER DEVELOPMENT PRODUCTS

TITLE			
1802 EMULATOR IRREGULARITY	10-06	MAR 21,1980	29
1802 EMULATOR DISASSEMBLY IRREGULARITIES	10-13	JUNE 27,1980	38
1802 J5 NUMBERING CORRECTIONS	10-08	APR 18,1980	28
1802 MICROPROCESSOR ADDRESSING PROBLEM	10-15	JULY 25,1980	17
1802 MICROPROCESSING ADDRESSING PROBLEMS	9-17	SEP 7,1979	21
1802 OUTPUT OPERATION IN MODE 1 (MAPPING PROGRAM MEMORY)	10-02	JAN 25,1980	33
1802 WAIT STATES	10-07	APR 4,1980	23
2650A MICROPROCESSOR BAD CODE DATES	9-09	MAY 18,1979	22
3870/3872 ADDRESS SPACE CONFIGURATOR	9-15	AUG 10,1979	37
3870/3872 EMULATOR PARTS IN EM O	9-15	AUG 10,1979	37
6800/6802 MODIFICATION	10-04	FEB 22,1980	44
6800/6802 ESCAPE FROM A SOFTWARE WAIT	10-02	JAN 25,1980	34
6800/6802 SVC LISTING CORRECTION	10-05	MAR 7,1980	48
6802 CRYSTAL CLOCK SUPPORT	10-09	MAY 2,1980	34
8001 FIRMWARE UPDATE	10-19	SEPT 19,1980	31
8001 TEKOPS V1.7	8-26	SEPT 1,1978	30
8001 VERSION 2.0 FIRMWARE PART NUMBERS	10-05	MAR 7,1980	48
8001 VERSION 2.0 FIRMWARE PART NUMBERS (ARTICLE REPEATED)	10-06	MAR 21,1980	29
8001/8002 FIELD UPDATES	8-26	SEPT 1,1978	31
8001/8002 DATA MANUALS	8-26	SEPT 1,1978	31
8001/8002 Z80 EMULATOR	8-26	SEPT 1,1978	30

WIZARDS WORKSHOP INDEX

MICRO-COMPUTER DEVELOPMENT PRODUCTS

TITLE	ISSUE	DATE	PAGE
8001/8002 MEMORY MAP RAM'S	8-27	SEPT 15,1978	22
8001/8002 EMULATORS MODS AND COMPATIBILITY	8-27	SEPT 15,1978	19
8001/8002 Z80 WAIT STATES	8-28	SEPT 29,1978	22
8001/8002 MANUFACTURING PROBLEM ON THE ACQUISITION INTERFACE B	7-29	NOV 25,1977	4
8001/8002 PART NUMBER CORRECTION	7-27	NOV 11,1977	12
8001/8002/8002A: PROGRAM MEMORY	9-05	MAR 16,1979	14
8001/8002A PROTECTOR PROBE COVER	10-03	FEB 8,1980	30
8001/8002A UNDOCUMENTED SVC'S	10-17	AUG 22,1980	26
8001/8002A/8041 EMULATION RESTRICTIONS	10-22	OCT 31,1980	32
8002 CUSTOMER FAMILIARIZATION COURSE	8-03	FEB 3,1978	10
8002 MANUALS	8-28	SEPT 29,1978	22
8002/8002A/4905/4907 DEF.DISCS 119-1011-00,01 & 119-0848-00,01	10-17	AUG 22,1980	27
8002A DAIB PART NUMBER CHANGE	10-15	JULY 25,1980	18
8002A FLEXIBLE DISC UNIT POWER SUPPLY PART NUMBER	10-20	OCT 3,1980	36
8002A MEMORY BOARD CORRECTION 670-5505-06/07	10-25	DEC 19,1980	15
8002A TEKDOS 8086/8088 ASSEMBLER PATCH	10-24	DEC 12,1980	30
8002A VERSION 3.0 TEK TIP DIAGNOSTICS	10-09	MAY 2,1980	34
8002A, B PHASE MICROLAB RESTRICTION	10-15	JULY 25,1980	18
8002A, MICROLAB 1 & MICROLAB PERSONALITY CARD PART NUMBERS	10-16	AUG 8,1980	16
8002A, TEKDOS DISC FULL ERROR	10-15	JULY 25,1980	18
8048 EMULATOR EXTERNAL CLOCK CONSIDERATIONS	10-12	JUNE 13,1980	15
8048 EMULATOR, OPERATION OF PORT 2	10-15	JULY 25,1980	19
8048 EMULATOR EXTERNAL PROGRAM MEMORY ADDRESSING	10-24	DEC 12,1980	31
8080A NEW EMULATOR SERVICE MANUAL	9-12	JUNE 29,1979	15
8085 EMULATOR APPLICATION FAILURE	10-21	OCT 17,1980	30
8550 QUME DRIVE MOTORS	10-21	OCT 17,1980	31
9900 PROTOTYPE CONTROL PROBE PART NUMBER ERROR	9-06	APR 6,1979	35
9900 VERSION 3.0 TEKDOS - BURNING PROMS	9-09	MAY 18,1979	22
ACTIVITY CODE 18	9-13	JULY 13,1979	31
ADDITION TO Z80 CTC/P10 MOD	9-17	SEPT 7,1979	21
ASSEMBLY LISTING TO CONSOL	8-19	JUNE 9,1978	19
BOARD NUMBER SUFFIX LABELS	9-24	DEC 14,1979	17
CAL COMP FLOPPY DISC VIDEO TAPE AVAILABLE	7-10	MAY 13,1977	5
CALCOMP PART NUMBERS	10-13	JUNE 27,1980	38
CALCOMP TO TEKTRONIX REPLACEABLE PARTS CROSS REFERENCE	9-25	DEC 21,1979	A-1
CT8101 PART NUMBERS	10-20	OCT 3,1980	35
CURRENT MANUAL PART NUMBERS	10-23	NOV 21,1980	38
EMULATOR PROBE TIP ASSEMBLY PART NUMBERS	10-07	APR 4,1980	22
EMULATOR PROBE TIP ASSEMBLY PART NUMBERS	10-25	DEC 19,1980	14
F8/3870 CLOCK FREQUENCY SELECTION	9-09	MAY 18,1979	21
FLEXIBLE DISC PROBLEM	10-02	JAN 25,1980	33

WIZARDS WORKSHOP INDEX

MICRO-COMPUTER DEVELOPMENT PRODUCTS

TITLE	ISSUE	DATE	PAGE
GSA WARRANTY FOR MDL PRODUCTS	9-10	JUNE 1,1979	26
HIGH SPEED RAM/PARITY ERRORS	8-31	NOV 10,1978	18
INCORRECT PART NUMBER IN SERVICE MANUAL	9-09	MAY 18,1979	21
IRREGULARITY ON Z80 CTC/PIO MOD	9-21	NOV 2,1979	16
LP8100 (4641) REPRINTS	9-18	SEPT 21,1979	33
LP8200 DRIVE PULLEY	10-03	FEB 8,1980	30
LP8200 REPLACEABLE PARTS LIST (REFERENCE PULL-OUT)	10-17	AUG 22,1980	A-1
LP8200 RIBBON CABLE ORDERABLE	10-15	JULY 25,1980	17
LP8200 UNEVEN VERTICAL LINE SPACING	10-14	JULY 11,1980	25
MDL MANUALS,CURRENT LIST (REF PULL-OUT)	9-16	AUG 24,1979	A-1
MDL SUPPORT	9-07	APR 20,1979	27
MICROLAB CASSETTE IN/OUT JACKS REVERSED	9-10	JUNE 1,1979	27
MICROPROCESSOR MANUFACTURERS SUPPORTED	9-11	JUNE 15,1979	11
MICROPROCESSOR REFERENCE LIST	10-08	APR 18,1980	24
NEW 8001/8002 SERVICE MANUAL	8-29	OCT 13,1978	10
NEW VERSION 3.0 EDITOR BEING SHIPPED	10-07	APR 4,1980	23
PATCHES FOR TEKDOS VER. 2.1	8-10	APR 7,1978	8
PROBLEM INSTALLING V3.0 EDITOR	10-10	MAY 16,1980	28
RECAP OF Z80 CTC/PIO MOD	10-01	JAN 11,1980	36
REQUEST FROM FACTORY SERVICE	9-22	NOV 16,1979	24
SBP9900 ADAPTER AVAILABLE	10-14	JULY 11,1980	26
SYSTEM UPDATE/INSTALLATION REPORT - REVISED FORMS AVAILABLE	9-06	APR 6,1979	35
TEKDOS ASSEMBLER, ILLEGAL CHARACTER	8-19	JUNE 9,1978	19
TEKDOS EPROM PATCHES FOR 9900	8-12	APR 21,1978	7
TEKDOS V2.1 LOAD WITH BIAS	8-19	JUNE 9,1978	19
UPDATED MANUALS LIST FOR 8001/8002	8-32	NOV 24,1978	10
VERSION 3.X EDITOR RESTRICTION	10-23	NOV 21,1980	41
WORD MEMORY	8-10	APR 7,1978	9

SEMICONDUCTOR TEST SYSTEMS

TITLE	ISSUE	DATE	PAGE
16S-3260 040 KIT FOR POWER	8-28	SEPT 29,1978	16
17S-3260 1140 #2 POWER SUPPLIES	8-28	SEPT 29,1978	17
1803 AC CONTROLLER	9-08	MAY 4,1979	39
1803 CONNECTOR BOARD IMPROVEMENT	9-18	SEP 21,1979	35
1803 TABLE -5.2V SHORTING	7-02	JAN 21,1977	8
1803 TABLE CR112 & CR114 MOUNTING	7-02	JAN 21,1977	9
1803 TEST STATION PART MISSING IN REPLACEABLE PARTS LIST	9-06	APR 6, 1979	34
1804/1805 DESKEWING CABLES	9-21	NOV 2,1979	17
1805 -36V P/N	9-22	NOV 16,1979	24
1805 DC SUBSYSTEM AMPLIFIER	9-08	MAY 4,1979	40
1805 DUT TO D80 WIRE	9-18	SEP 21,1979	36
28S-3200 TEK UNIBUS	9-10	JUN 1,1979	28
S-3200 067-0777-00 DELTA-T RECAL FIXTURE	10-08	APR 18,1980	33
S-3200 070-3477-00, 1330 MANUAL CHANGES	10-10	MAY 16,1980	33
S-3200 1140 CURRENT SUPPLIES MIXED STOCK	10-23	NOV 21,1980	45
S-3200 1140 POWER SUPPLIES NOTE	9-06	APR 6,1979	32
S-3200 1140A POWER SUPPLY MODULES	9-18	SEP 21,1979	35
S-3200 1140A/651F STRAPPING IS DOCUMENTED	9-16	AUG 24,1979	27
S-3200 1803, 4K PRAM LIMITATIONS	10-08	APR 18,1980	32
S-3200 2943/2944 PHASE CARD MODIFICATION M40543	10-24	DEC 12,1980	36
S-3200 2943/2944 MANUAL CORRECTION	9-19	OCT 5,1979	25
S-3200 ANSLEY CONNECTOR DOCUMENTATION	9-05	MAR 16,1979	10
S-3200 BLANK PANELS FOR THE RACK ARE ORDERABLE	10-19	SEPT 19,1980	32
S-3200 BLANK DISK LABELS	9-07	APR 20,1979	25
S-3200 BOOTUP OF MORE THAN 28K OF CORE, MONITOR (II III)	10-03	FEB 8,1980	31
S-3200 BURST ON MODE POTENTIAL PROBLEM	8-34	DEC 22,1978	11
S-3200 CONNECTOR BOARD #1, PATTERN TIMING	10-21	OCT 17,1980	32
S-3200 CUSTOMIZING HANDLR .FNC	9-09	MAY 18, 1979	24
S-3200 CYCLE.EDT, F080 AND THE DELTA-T	9-17	SEP 7,1979	22
S-3200 D70 T.I.M.E. OPTION SKEWS	10-19	SEPT 19,1980	32
S-3200 D70,D80 COMPONENT REPLACEMENT	10-21	OCT 17,1980	36
S-3200 D80 COMPENSATOR WIRES	10-16	AUG 8,1980	18
S-3200 DC SUBSYSTEM MODIFICATION #M40301	10-19	SEPT 19,1980	33
S-3200 DEC MANUALS	9-07	APR 20,1979	25
S-3200 FLUKE OPTION TYPE D FIXTURING RESISTANCE MEASUREMENTS	10-23	NOV 21,1980	42
S-3200 GPIB.FNC	10-06	MAR 21,1980	31
S-3200 IMPEDANCE MISMATCH 1140A651F	10-24	DEC 12,1980	32
S-3200 INITIALIZE PULSE MAY CAUSE FORM FEED TO CP141	10-17	AUG 22,1980	37
S-3200 INTERFACE TESTING	10-16	AUG 8,1980	18
S-3200 INTERMITTENT SQUARE PIN CONNECTORS	9-04	MAR 2,1979	14

SEMICONDUCTOR TEST SYSTEMS

TITLE	ISSUE	DATE	PAGE
S-3200: IP3260 V03.06 CURES HIGH CORE AND BG0 CONFLICT	9-16	AUG 24,1979	20
S-3200 IVORY TOWER PART NUMBER	9-04	MAR 2,1979	15
S-3200 LOGREG - CLARIFICATION OF IT'S USE	9-19	OCT 5,1979	22
S-3200 MISUNDERSTANDINGS WITH KBSTUFF AND FMTNUM	9-16	AUG 24,1979	21
S-3200 MODIFY.RUN	9-17	SEP 7,1979	24
S-3200 NEW FLUKE 8400A DVM CABLE (TEK MADE)	10-16	AUG 8,1980	18
S-3200 PEDIT MANUAL DEFAULTS	10-03	FEB 8,1980	32
S-3200 POWER CABLES, T.I.M.E. OPTION	10-22	OCT 31,1980	33
S-3200 POWER UP SEQUENCE MOD RELAY	10-14	JULY 11,1980	32
S-3200 POWER SUPPLY SUMMARY (REF PULL-OUT)	10-08	APR 18,1980	C1
S-3200 POWER PLUG AND LOAD BOARD HARNESS	9-17	SPE 7,1979	26
S-3200 PRAM EDGE CONNECTOR MAY CAUSE INTERMITTENT CLOCK	10-16	AUG 8,1980	19
S-3200 PROBER PROBLEM SOLVED BY LOOPING THE TEST INTERNALLY	9-16	AUG 24,1979	22
S-3200 R2942.FNC	10-06	MAR 21,1980	31
S-3200 REFCAL.EDT - RANGE SKIPPED IN "DETAIL MODE"	9-19	OCT 5,1979	23
S-3200 RLOADFILE SUBROUTINE DISTURBS INDEX COUNTER	9-15	AIG 10,1979	36
S-3200 S-3270 WITH CFI OSCILLATIONS (VS3)	10-21	OCT 17,1980	38
S-3200 S-3280 SAMPLING RACKS	10-19	SEPT 19,1980	34
S-3200 SECTOR CARD TROUBLE BOOK	10-16	AUG 8,1980	19
S-3200 SECTOR CARD REMOVAL AND INSTALLATION AID-B	9-10	JUN 1,1979	28
S-3200 SERIES CIRCUIT BOARD COMPATIBILITY	10-18	SEPT 5,1980	17
S-3200 SERIES RACK FANS	10-02	JAN 25,1980	35
S-3200 SMI TEST CABLES	10-25	DEC 19,1980	16
S-3200 SOFTWARE CHANGES AND PROBLEMS SOLVED FOR APO11	10-14	JULY 11,1980	32
S-3200 SOFTWARE TEST/EVALUATION	10-05	MAR 7,1980	50
S-3200 SOFTWARE, 3 OPERAND IF STATEMENT, DKARY.FNC	10-07	APR 4,1980	30
S-3200 STATION BUFFER UNIT MANUAL	10-25	DEC 19,1980	16
S-3200 SYS MAY GIVE ERRONEOUS READINGS AT BEGINNING OF RTADJ.EDT:VDT	10-16	AUG 8,1980	19
S-3200 SYSTEM SPARES COMPATIBILITY	10-07	APR 4,1980	31
S-3200 SYSTEMS: CONSOLE TERMINAL HANGS UP	10-07	APR 4,1980	26
S-3200 TEKTEST SOFTWARE NOTE	9-06	APR 6,1979	32
S-3200 TEST STATION POWER SUPPLY SENSING	10-22	OCT 31,1980	35
S-3200 THUMBSCREW 1803, 1804, 1805	10-10	MAY 16,1980	31
S-3200 THUMBSCREWS	9-07	APR 20,1979	25
S-3200 TRAN.RUN - PROBLEM WHEN PATTERN FILES NOT FOUND	9-19	OCT 5,1979	25
S-3200 UTILITY.FNC V02.25 CORRECTS POTENTIAL DATA LOSS PROBLEM	9-16	AUG 24,1979	27
S-3200/S-3280 SYSTEM VERDICT SUMMARY	10-07	APR 4,1980	32

SEMICONDUCTOR TEST SYSTEMS

TITLE	ISSUE	DATE	PAGE
S-3260-CF-1 CURRENT FORCE OPTION CALIBRATION	8-26	SEPT 1,1978	28
S-3260/S-3455 STATION CONTROL BOX (015-0174-05)	8-22	JUL 7,1978	11
S-3260 1140 WRONG PART	9-06	APR 6,1979	33
S-3260, 1803 TABLE MODIFICATION	7-21	SEPT 9,1977	13
S-3260 - 1843 STRAIN RELIEF BRACKETS	9-07	APR 20,1979	26
S-3260-2941, 1340, 1803 CARD NEST PART NUMBERS	7-23	SEPT 30,1977	8
S-3260, DL11A TERMINAL INTERFACE	7-22	SEPT 23,1977	10
S-3260, FRONT CORNER ABERRATIONS OF DATA DRIVER	7-10	MAY 13,1977	16
S-3260, OPTION 20 VERDICT	7-15	JULY 22,1977	18
S-3260, MAINTENANCE LIBRARY	7-17	AUG 5,1977	15
S-3260, POWER SUPPLIES	7-05	MAR 4,1977	27
S-3260, PRAM CARD NEST FUSES	7-25	OCT 21,1977	8
S-3260, PRAM CARD NEST FUSES, CORRECTION ARTICLE	7-30	DEC 9,1977	15
S-3260, PRAM OPTION	7-15	JULY 22,1977	18
S-3260, PRAM OPTION CORRECTION	7-20	AUG 26,1977	3
S-3260, REMEX READER/PUNCH	7-19	AUG 19,1977	12
S-3260, SECTOR CARD NOMENCLATURE	7-26	OCT 28,1977	11
S-3260, SECTOR CARD RELIABILITY	8-19	JUN 9,1978	18
S-3260, SOFTWARE BUGS	7-10	MAY 13,1977	16
S-3260, VERDICT SOFTWARE BUGS	7-08	APR 15,1977	11
S-3260, WRONG PART NUMBER IN 1340 DATA COUPLER MANUAL	8-22	JUL 7,1978	10
S-3260 1140A MISUNDERSTANDING ON THE PROGRAMMABLE RESISTANCE BOARD OPERATION	8-23	JUL 21,1978	23
S-3260 1140A TEST AID	7-06	MAR 18,1977	14
S-3260 1843 REMOTE TEST FIXTURE	8-33	DEC 8,1978	13
S-3260 ACCESSORIES PART NUMBERS	7-14	JULY 8,1977	20
S-3260 CP - 116X	7-06	MAR 18,1977	14
S-3260 DC SUBSYSTEM	10-06	MAR 21,1980	32
S-3260 IS2 CABLE IS NOW AVAILABLE	8-22	JUL 7,1978	10
S-3260 NEW PART NUMBERS	8-34	DEC 22,1978	12
S-3260 NEW SOFTWARE	8-26	SEPT 1,1978	29
S-3260 OPTION 20 RECAL	7-07	APR 1,1977	19
S-3260 OPTION 20 3T6 EXTENDER BOARD	8-34	DEC 22,1978	12
S-3260 PRAM ERROR LOGIC P/N WRONG	8-26	SEPT 1,1978	29
S-3260 R1140A SCHEMATIC ERROR	8-22	JUL 7,1978	10
S-3260 ROLTRON FANS	8-31	NOV 10,1978	17
S-3260 SECTOR BOARDS	10-10	MAY 16,1980	29
S-3260 SOFTWARE	7-05	MAR 4,1977	28
S-3260 TRANSLATING PROBLEM	9-06	APR 6,1979	33
S-3260 VERDICT MANUAL CORRECTION	9-06	APR 6,1979	33
S-3260, 1140A PRECAUTIONS	7-20	AUG 26,1977	7
S-3260, 1803 LOAD BOARD PART NUMBERS	7-20	AUG 26,1977	8
S-3260, 1803 MC-3 VERDICT	7-05	MAR 4,1977	27

SEMICONDUCTOR TEST SYSTEMS

TITLE	ISSUE	DATE	PAGE
S-3260, 1803 SECTOR CARDS	7-05	MAR 4,1977	28
S-3260, 1803 TABLE	7-15	JULY 22,1977	19
S-3260 DC LOAD BOARD PART NUMBER	9-07	APR 20,1979	26
S-3260 LOCKING CONNECTOR PINS AND CONNECTOR HOUSINGS	9-07	APR 20,1979	26
S-3270 S-3280 SECTOR CARD FUSES	10-14	JULY 11,1980	36
S-3270 D70 CARDS BURNING UP	9-16	AUG 24,1979	25
S-3270 VMOD21. EDT: VDT V01.00	9-15	AUG 10,1979	36
S-3280 F090.TST, DELTAT.EDT VERSION CHANGE	9-19	OCT 5,1979	22
S-3455 - 1848 INHIBIT MATRIX CARD (670-5254-02) ONLY	8-23	JUL 21,1978	23
S-3455 1848 TEST HEAD PINS DOWN ERRORS ON NEW CARDS	10-05	MAR 7,1980	51
S-3455 -DUT SOCKET CARD PINS	8-28	SEPT 29,1978	16
S-3455 1848 DATA I/O PIN LEAKAGE	7-30	DEC 9,1977	16
S-3455 AVAILABLE MAINTENANCE PACKAGES	8-02	JAN 27,1978	6
S-3455 BACKPLANE WIRE WRAPPING TOOL	7-30	DEC 9,1977	16
S-3455 DIAGNOSTIC PROGRAM FLOWS	8-21	JUN 30,1978	11
S-3455 FORMAT:REC	10-08	APR 18,1980	31
S-3455 LOWER BLOWER ASSEMBLY CLEANING	10-12	JUNE 13,1980	16
S-3455 MEMORY TESTER, -5.2 VOLT POWER SUPPLY	7-03	FEB 4,1977	19
S-3455 MTLBAK DOES NOT WORK	8-21	JUN 30,1978	13
S-3455 SERVICE TIPS	7-25	OCT 21,1977	8
S-3455 SIGNAL MATRIX ADAPTER	9-06	APR 6,1979	34
S-3455 SPARE KITS	8-12	APR 21,1978	6
S-3455 SYSTEM COOLING	9-03	FEB 16,1979	22
S-3455 SYSTEM SYNOPSIS	9-03	FEB 16,1979	22
S-3455 VERIFY CORRECTIONS	9-17	SEP 7,1979	26
S-3455 VERIFY CHANGES	9-19	OCT 5,1979	25
CORRECTION TO MAINTENANCE AGREEMENT PRICE LIST	10-15	JULY 25,1980	21
CP3200 (PDP11/34) INTERMITTENT LOADING OF PATTERN FILE	10-11	MAY 30,1980	43
DC SUB-SYSTEM SENSITIVITY TO INJECTED NOISE	10-11	MAY 30,1980	44
ENHANCEMENT TO THE SECTOR CARD TEST FIXTURE (067-0745-00)	10-15	JULY 25,1980	21
FET CHECKING ON DRIVER/A	10-10	MAY 16,1980	29
INSTALLATION OF SECOND TERMINAL TO A PDP11/34	10-03	FEB 8,1980	31
MISSING RELAY IN S3260 SCHEMATICS	8-14	MAY 5,1978	8
NEW SUPER BLOWER PRESSURE SWITCH	10-03	FEB 8,1980	31
NEW SUPERBLOWER PRESSURE SWITCH	10-20	OCT 3,1980	36
PROBLEM REPORT PROCEDURE	10-09	MAY 2,1980	36
PROCEDURE FOR CLIP AND SOLDER UPDATE OF DIB SECTOR CHANGE	10-14	JULY 11,1980	27
R1340 IMPROVED INSTRUMENT COOLING	10-05	MAR 7,1980	50
RACK PANELS	9-21	NOV 2,1979	17

SEMICONDUCTOR TEST SYSTEMS

TITLE	ISSUE	DATE	PAGE
SOFTWARE CHANGE AND ADDITION SUMMARY #2	9-20	OCT 19,1979	14
SOFTWARE CHANGES & PROBLEMS SOLVED FOR AP101	10-20	OCT 3,1980	37
SOFTWARE CHANGES AND PROBLEMS SOLVED FOR AP013	10-18	SEPT 5,1980	17
SOFTWARE CHANGES AND PROBLEMS SOLVED FOR AP012	10-17	AUG 22,1980	28
SOFTWARE CHANGES AND PROBLEMS SOLVED FOR AP009 (REF. PULL-OUT)	10-08	APR 18,1980	B1
SOFTWARE CHANGES AND PROBLEMS SOLVED FOR APO10	10-11	MAY 30,1980	36
S-SYSTEMS STATIC INFORMATION	7-06	MAR 18,1977	24
STS INSTALLATION PROBLEM REVIEW	10-13	JUNE 27,1980	39
STS SERVICE RECORDS	9-07	APR 20, 1979	24
STS SYSTEMS MANUAL INFORMATION	7-07	APR 1,1977	19
STUDY GUIDE FOR STS PRETRAINING	7-17	AUG 5,1977	16
SYSTEM UPDATE/INSTALLATION REPORT - REVISED FORMS AVAILABLE	9-06	APR 6,1979	32
SYSTEMS "SYSTEMS DOWN" ORDER PROCEDURES (DOMESTIC ONLY)	8-05	MAR 3,1978	S
TEKTEST SOFTWARE PROBLEM REPORT	9-20	OCT 19,1979	15
TEKTEST SOFTWARE PROBLEM REPORTS	10-14	JULY 11,1980	31
TEMPORARY PRECAUTIONS FOR D.C. SUBSYSTEM OVERSHOOT	9-17	SEP 7,1979	27

SIGNAL PROCESSING SYSTEMS

TITLE	ISSUE	DATE	PAGE
067-0883-99/067-0919-99	10-16	AUG 8,1980	21
067-0919-99 BLANK PROGRAM MODULE	10-20	OCT 3,1980	40
7612D INCORRECT NUMBER OF DATA BYTES, CAUSING CKSUM ERRORS	10-19	SEPT 19,1980	36
7912AD A PLUG-IN INTERFACE EXTENDER CARD	10-08	APR 18,1980	35
7912AD ADDED PROTECTION FOR THE CRT & IMPROVED RELIABILITY	10-19	SEPT 19,1980	39
7912AD CRT FLASH	9-03	FEB 16,1979	21
7912AD FIRMWARE UPDATE	10-11	MAY 30,1980	45
7912AD FIRMWARE UPDATE	10-19	SEPT 19,1980	39
7912AD FIRMWARE UPGRADE CLOSES	10-22	OCT 31,1980	36
7912AD HI VOLT. BRICKS ARE NOT INTERCHANGEABLE ACROSS B05XXXX S/N BREAK	10-06	MAR 21,1980	33
7912AD IMPROVED RELIABILITY FOR THE HI VOLTAGE OSCILLATOR	10-19	SEPT 19,1980	40
7912AD INTERMITTENTLY, INST HANGS UP (CORRECTION)	10-04	FEB 22,1980	45
7912AD INTERMITTENT NOISE IN THE DISPLAY	9-19	OCT 5, 1979	2
7912AD INTERMITTENTLY, INSTRUMENT HANGS UP	9-22	NOV 16,1979	25
7912AD PERFORMANCE MODS	8-34	DEC 22,1978	10
7912AD POWER SUPPLY: INTERMITTENTLY BLOWN LINE FUSES	9-15	AUG 10,1979	39
7912AD POWER SUPPLY RELIABILITY	9-09	MAY 18,1979	27
7912AD READOUT MISSING SYMBOLS AND/OR JITTERY	10-04	FEB 22,1980	49
7912AD RELIABILITY IMPROVEMENT OF THE POWER SUPPLY	10-09	MAY 2,1980	38
7912AD SWITCHING FROM TV TO DIGITAL	9-09	MAY 18,1979	28
7912AD THE LOGIC +5 VDC TO PLUG-INS IS TOO LOW	10-04	FEB 22,1980	49
7912AD, LOW TEMPERATURE POWER UP	9-04	MAR 2,1979	14
7912AD, R7912, R7912R IMPROVED FOCUS CONTROL & RELIABILITY	10-08	APR 18,1980	35
7912AD, SINGLE SWEEP NOISE	9-05	MAR 16,1979	11
7912AD: FLASHING INTENSITY	10-16	AUG 8,1980	27
7A16 PERFORMANCE MOD M34952	9-02	FEB 2,1979	19
7A16P AND 7B90P AN 050 KIT FOR THE 155-0164-00 HYBRID	10-08	APR 18,1980	34
7A16P AND 7B90P IMPROVED RELIABILITY	9-04	MAR 2,1979	13
7A16P GPIB INTERFERENCE WITH TWO 7A16P'S IN 7612D	10-08	APR 18,1980	34
7A16P PERFORMANCE MOD M34952 CLARIFICATION	9-05	MAR 16,1979	10
7A16P READOUT MAY DROP OUT LTRS WITH HORIZTLS, 7B92A, 7B53A AND OTHERS	10-16	AUG 8,1980	23
7A16P SOME 7A16P'S ARE NOT COMPATIBLE WITH THE 7612D	10-09	MAY 2,1980	37
7B90P EXTERNAL TRIGGERS, TROUBLESHOOTING HINTS	9-18	SEP 21,1979	37
7B90P FALSE TRIGGERING WHEN TALKING OVER THE GPIB BUS	10-04	FEB 22,1980	47
7B90P NOISY EXTERNAL TRIGGERS	9-09	MAY 18,1979	26
7B90P PROGRAMMABLE TIME BASE OPERATION ON AN EXTENDER	9-09	MAY 18,1979	26
7B90P READOUT ON OTHER PLUG-INS MAY LOSE OR CHANGE LETTERS IN DDISPLAY	10-16	AUG 8,1980	26
7B90P HIGH FREQUENCY JITTER	9-15	AUG 10,1979	38
7D01 "SOCKET UPDATE PROGRAM"	9-14	JUL 27,1979	30
CP1100 INTERFACE, P/N 021-0115-00, 021-0117-01 AND 021-0131-01	7-16	JULY 29,1977	14

SIGNAL PROCESSING SYSTEMS

TITLE	ISSUE	DATE	PAGE
CP1100/IEEE INFC:CKSUM ERRORS MAY OCCUR WHEN PERF DATA TRANS USING DMA	10-24	DEC 12,1980	38
CP1100/IEEE 488; H0 ERRORS WITH PDP 11/34	9-06	APR 6,1979	28
CP1100/IEEE 488 INTERFACE USED WITH MEMORY MANAGEMENT	9-04	MAR 2,1979	11
CP1100/IEEE-488 HARDWARE ERROR	8-29	OCT 13,1978	9
CP112 FLOPPY DISC DRIVE VIDEO TAPE AVAILABLE	7-14	JULY 8,1977	20
CP112 INSTRUCTION MANUAL	7-12	JUNE 10,1977	19
CP115 SECONDARY WRITE PROTECT METHOD - POSSIBLE PROBLEM	8-33	DEC 8,1978	12
CP4165 CONTROLLER SERVICE MANUAL ERROR	8-29	OCT 13,1978	9
CP4165 IEEE 488 CONNECTOR	8-19	JUN 9,1978	15
CP4165 SERVICE MANUAL SUPPLEMENT	7-30	DEC 9,1977	15
CP4165 STRAPPING OPTIONS	8-31	NOV 10,1978	15
CP4165/GPIB INTERCONNECT CABLES MANUFACTURED WRONG	7-22	SEPT 23,1977	10
CP56002 CHECKOUT SOFTWARE FOR IEEE 488 INTERFACES	8-19	JUN 9,1978	17
DPO'S USED IN SYSTEMS WITH A CP4165 CONTROLLER	7-13	JUNE 24,1977	25
IEEE CHECKOUT SOFTWARE	10-19	SEPT 19,1980	35
IEEE CHECKOUT SOFTWARE	10-21	OCT 17,1980	38
P7001 COMPONENT FAILURES	8-09	MAR 31,1978	13
P7001 SAMPLE AND HOLD	8-13	APR 28,1978	13
P7001/CP4165	8-13	APR 28,1978	14
P7001/R7912/R7912R: COMPONENT CHANGE	9-19	OCT 5,1979	26
R7912 DEFECTIVE HI VOLTAGE MODULES (119-0452-02)	7-16	JULY 29,1977	16
R7912 MEMORY PROBLEM	7-31	DEC 16,1977	12
R7912 OCCASIONAL LONG "HANG-UP" CORRECTION	9-02	FEB 2,1979	17
R7912 OCCASIONAL LONG "HANG-UP"	9-01	JAN 12,1979	10
R7912/R7912R POWER SUPPLY RELIABILITY	8-26	SEPT 1,1978	28
REPORTING FIELD FAILURES FOR WP SYSTEMS	8-05	MAR 3,1978	15
REPORTING P7001 FIELD FAILURES	8-01	JAN 20,1978	12
RUNNING "R7965H" ON PDP11/34	8-01	JAN 20,1978	14
SPS HARDWARE/SOFTWARE PROBLEMS REPORTING	7-20	AUG 26,1977	7
SPS SOFTWARE	10-14	JULY 11,1980	37
SPS SOFTWARE PERFORMANCE REPORT FORMS	7-13	JUNE 24,1977	25
SPS TEK BASIC VO2-02 VO2XM-02 PATCHES	10-20	OCT 3,1980	43
SPS TEK BASIC SOFTWARE PATCH	10-20	OCT 3,1980	42
SYSTEM UPDATE/INSTALLATION REPORT - REVISED FORMS AVAILABLE	9-06	APR 6,1979	31
SYSTEM UPDATE/INSTALLATION REPORTS	8-19	JUN 9,1978	17
THE GPIB-DP2 AS A TROUBLESHOOTING AID FOR THE IEE-388	8-26	SEPT 1,1978	26

WIZARDS WORKSHOP INDEX

COMMUNICATIONS DIVISION (1980)

TITLE	ISSUE	DATE	PAGE
"SCR" PHENOMENA EXHIBITED BY NVM BOARD (ANS.SERVICE BULLETIN #7)	10-17	AUG 22,1980	38
1980 - 1900 COMPATIBILITY (ANSWER SERVICE BULLETIN #10)	10-23	NOV 21,1980	46
ADDITIONAL RECOMMENDED EQUIP FOR 1980 SERV (ANSWER B#2)	10-13	JUNE 27,1980	40
ANSWER SERVICE BULLETIN #1	10-13	JUNE 27,1980	40
FALSE "FPULSE" ERRORS (ANSWER B#4)	10-13	JUNE 27,1980	41
HEAT RELATED CSKIP-F ERROR (ANSWER SERVICE BULLETIN #6)	10-17	AUG 22,1980	38
IMPROPER SETTING OF AIR JUMPER OF NVM BOARD - ANSWER BULLETIN #8	10-21	OCT 17,1980	39
OPTIONAL PATCH ALLOWS GRAPHING VIDEO LINE 263 (ANS.SERV BULLTN#5)	10-16	AUG 8,1980	28
RETURN TO MEASUREMENT ROUTINES AFTER SYSTEM INTERRUPTION(ANSWER B#3)	10-13	JUNE 27,1980	42

