



David J. Johnson
Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

September 24, 2020

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: Advance Notice - Equipment Recall 20S55
Certain 2015-2020 Model Year Left Hand Drive Mustang Vehicles equipped with Automatic Transmission - Brake Pedal Bracket Fracture

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
Mustang	2015-2020	Flat Rock	August 6, 2014 through September 10, 2020

REASON FOR THIS EQUIPMENT RECALL

Some of the affected vehicles may have been repaired using service replacement brake pedal and bracket assemblies (FR3Z-2455-AA/AB) that could fracture at the pedal pivot location during a braking event requiring heavy pressure to the brake pedal. A brake pedal bracket fracturing under heavy pedal force may result in a loss of primary braking capability, increasing the risk of a crash.

SERVICE ACTION

Dealers are to review their part sales records and contact any customers to whom a suspect brake pedal and bracket assembly was sold once the full dealer bulletin is available.

A complete Dealer Bulletin will be provided to dealers in the fourth quarter of 2020 when it is anticipated that parts ordering information and repair instructions will be available to support this equipment recall.

CUSTOMER NOTIFICATION

Owners are to be notified through the dealers using available parts sales records.

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician Society (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

David J. Johnson