



Red Hat Enterprise Linux (RHEL) 6.10 Driver Release Notes

RHEL 6.10

NOTE:

THIS HARDWARE, SOFTWARE OR TEST SUITE PRODUCT □PRODUCT(S)™ AND ITS RELATED DOCUMENTATION ARE PROVIDED BY MELLANOX TECHNOLOGIES AS-IS WITH ALL FAULTS OF ANY KIND AND SOLELY FOR THE PURPOSE OF AIDING THE CUSTOMER IN TESTING APPLICATIONS THAT USE THE PRODUCTS IN DESIGNATED SOLUTIONS. THE CUSTOMER'S MANUFACTURING TEST ENVIRONMENT HAS NOT MET THE STANDARDS SET BY MELLANOX TECHNOLOGIES TO FULLY QUALIFY THE PRODUCT(S) AND/OR THE SYSTEM USING IT. THEREFORE, MELLANOX TECHNOLOGIES CANNOT AND DOES NOT GUARANTEE OR WARRANT THAT THE PRODUCTS WILL OPERATE WITH THE HIGHEST QUALITY. ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT ARE DISCLAIMED. IN NO EVENT SHALL MELLANOX BE LIABLE TO CUSTOMER OR ANY THIRD PARTIES FOR ANY DIRECT, INDIRECT, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES OF ANY KIND (INCLUDING, BUT NOT LIMITED TO, PAYMENT FOR PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY FROM THE USE OF THE PRODUCT(S) AND RELATED DOCUMENTATION EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.



Mellanox Technologies
350 Oakmead Parkway Suite 100
Sunnyvale, CA 94085
U.S.A.
www.mellanox.com
Tel: (408) 9703400
Fax: (408) 9703403

© Copyright 2018. Mellanox Technologies Ltd. All Rights Reserved.

Mellanox®, Mellanox logo, Accelio®, BridgeX®, CloudX logo, CompustorX®, ConnectIB®, ConnectX®, CoolBox®, CORE-Direct®, EZchip®, EZchip logo, EZappliance®, EZdesign®, EZdriver®, EZsystem®, GPUDirect®, InfiniHost®, InfiniBridge®, InfiniScale®, LinkX®, Kotura®, Kotura logo, Mellanox CloudRack®, Mellanox CloudXMellanox®, Mellanox Federal Systems®, Mellanox HostDirect®, Mellanox MuHost®, Mellanox Open Ethernet®, Mellanox OpenCloud®, Mellanox OpenCloud Logo®, Mellanox PeerDirect®, Mellanox ScalableHPC®, Mellanox StorageX®, Mellanox TuneX®, Mellanox Connect Accelerate Outperform logo, Mellanox Virtual Modular Switch®, MetroDX®, MetroX®, MLNX-OS®, NP-1c®, NP-2®, NP-3®, NPS®, Open Ethernet logo, PhyX®, PlatformX®, PSIPHY®, SiPhy®, StoreX®, SwitchX®, Tiler®, Tiler logo, TestX®, TuneX®, The Generation of Open Ethernet logo, UFM®, Unbreakable Link®, Virtual Protocol Interconnect®, Voltaire® and Voltaire logo are registered trademarks of Mellanox Technologies, Ltd.

All other trademarks are property of their respective owners.

For the most updated list of Mellanox trademarks, visit <http://www.mellanox.com/page/trademarks>

Table of Contents

Table of Contents	3
List Of Tables	4
Chapter 1 Overview	5
1.1 Supported HCAs Firmware Versions	5
1.2 SR-IOV Support	6
1.3 RoCE Support	6
1.4 VXLAN Support	6
Chapter 2 Changes and New Features	7
Chapter 3 Known Issues	8

List Of Tables

Table 1:	Supported Uplinks to Servers	5
Table 2:	Supported HCAs Firmware Versions	5
Table 3:	SR-IOV Support.	6
Table 4:	RoCE Support	6
Table 5:	VXLAN Support.	6
Table 6:	Changes and New Features.	7
Table 7:	Known Issues	8

1 Overview

These are the release notes of Red Hat Enterprise Linux (RHEL) 6.10 Driver. This document provides instructions on drivers for Mellanox Technologies ConnectX® based adapter cards with Red Hat Enterprise Linux (RHEL) 6.10 Driver environment.

This version supports the following uplinks to servers:

Table 1 - Supported Uplinks to Servers

Uplink/HCAs	Uplink Speed	Supported Driver
ConnectX®-4	<ul style="list-style-type: none"> InfiniBand: SDR, QDR, FDR10, FDR, EDR Ethernet: 1GigE, 10GigE, 25GigE, 40GigE, 50GigE, 56GigE^a, and 100GigE 	mlx5_core (includes the ETH functionality as well), mlx5_ib
ConnectX®-4 Lx	<ul style="list-style-type: none"> Ethernet: 1GigE, 10GigE, 25GigE, 40GigE, and 50GigE 	mlx5_core (includes the ETH functionality as well)
Connect-IB®	<ul style="list-style-type: none"> InfiniBand: SDR, QDR, FDR10, FDR 	mlx5_core, mlx5_ib
ConnectX®-3/ ConnectX®-3 Pro	<ul style="list-style-type: none"> InfiniBand: SDR, QDR, FDR10, FDR Ethernet: 10GigE, 40GigE and 56GigE^a 	mlx4_core, mlx4_en, mlx4_ib
ConnectX®-2	<ul style="list-style-type: none"> InfiniBand: SDR, DDR Ethernet: 10GigE, 20GigE 	mlx4_core, mlx4_en, mlx4_ib

a. 56GbE is a Mellanox propriety link speed and can be achieved while connecting a Mellanox adapter cards to Mellanox SX10XX switch series or connecting a Mellanox adapter card to another Mellanox adapter card.

1.1 Supported HCAs Firmware Versions

Red Hat Enterprise Linux (RHEL) 6.10 Driver supports the following Mellanox network adapter cards firmware versions:

Table 2 - Supported HCAs Firmware Versions

HCA	Recommended Firmware Rev.
Connect-IB®	10.16.1020
ConnectX®-4 Lx	14.22.1002
ConnectX®-4	12.22.1002
ConnectX®-3 Pro	2.42.5000
ConnectX®-3	2.42.5000
ConnectX®-2	2.9.1000

1.2 SR-IOV Support

Table 3 - SR-IOV Support

Driver	Support
mlx4_core, mlx4_en, mlx4_ib	Technical Preview ^a
mlx5_core (includes ETH functionality), mlx5_ib	No

a. Technical Preview is not fully supported production feature.

1.3 RoCE Support

Table 4 - RoCE Support

Driver	Support
mlx4 - RoCE v1	Yes
mlx4 - RoCE v2	No
mlx5 - RoCE v1/v2	No

1.4 VXLAN Support

Table 5 - VXLAN Support

Driver	Support
mlx4 - VXLAN offload	Yes
mlx5 - VXLAN offload	No

2 Changes and New Features

Table 6 - Changes and New Features

Feature/Change	Description
General	This is a general bug fixes release. It does not include any Mellanox drivers' specific fixes.

3 Known Issues

The following table describes known issues in this release and possible workarounds..

Table 7 - Known Issues (Sheet 1 of 2)

Internal Ref.	Description
765695	Description: mlx4_en network interfaces could be created as a renameX on RHEL6.8 SR-IOV guest.
	Workaround: N/A
	Keywords: mlx4_en network interfaces
754436	Description: Kdump/kexec is not supported on the mlx5 driver.
	Workaround: N/A
	Keywords: Kdump/kexec
753564	Description: Lower than expected TCP throughput over the ConnectX-4 IPoIB interface.
	Workaround: N/A
	Keywords: TCP throughput
978511	Description: Lower than expected TCP throughput over ConnectX-4 100Gb Ethernet.
	Workaround: N/A
	Keywords: TCP throughput, ConnectX-4 100Gb Ethernet
751780	Description: The error message "mlx4_en 0000:05:00.0: Failed assigning an EQ to p6p1-16, falling back to legacy EQ's" will appear in the log messages after changing the mlx4_en interface number of channels.
	Workaround: N/A
	Keywords: mlx4_en network interfaces
961977	Description: Kdump/kexec is not supported in Infiniband devices.
	Workaround: N/A
	Keywords: Kdump/kexec
944778	Description: Dynamic MTU value must be higher than the static MTU in ConnectX-4 when NC-SI is enabled.
	Workaround: Disable NC-SI in the firmware INI and burn it.
	Keywords: Firmware, NC-SI, MTU
887217	Description: macvtap over mlx4_en cannot receive IPv6 ns packet.
	Workaround: N/A
	Keywords: macvtap, IPv6
880822	Description: rdma_cm UD does not function while SR-IOV is enabled.
	Workaround: Disable SR-IOV in grub and via module parameter.
	Keywords: SR-IOV, UD, rdma_cm

Table 7 - Known Issues (Sheet 2 of 2)

Internal Ref.	Description
1001977	Description: ib_pma_portcounters_cong counters freeze at 32b int max.
	Workaround: N/A.
	Keywords: InfiniBand, counters
962813	Description: Running Virtual ETH (VETH) over OVS may cause ovsbr0: hw csum failure messages in log.
	Workaround: N/A.
	Keywords: VETH, OVS