



SA400 Firmware Release Notes

Firmware Revision SBFKB1C3 – Dec 19, 2018

Firmware Revision SBFK71F1 – July 10, 2019

Firmware Revision SBFKB1H5 – Jan 16, 2020

- *SA400S37/120G, SA400S37/240G, SA400S37/480G, SA400S37/960G*
- *SA400M8/120G, SA400M8/240G*



KINGSTON EXPRESSLY DISCLAIMS ALL SUCH WARRANTIES OF ANY KIND, WHETHER EXPRESS, IMPLIED OR STATUTORY, WITH RESPECT TO THE FIRMWARE AND FIRMWARE UPDATES INCLUDING, WITHOUT LIMITATION, WARRANTIES OR CONDITIONS OF QUALITY, PERFORMANCE, NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR USE FOR A PARTICULAR PURPOSE.

KINGSTON DOES NOT REPRESENT OR WARRANT THAT THE FIRMWARE OR FIRMWARE UPDATES WILL ALWAYS BE AVAILABLE, ACCESSIBLE, UNINTERRUPTED, TIMELY, SECURE, ACCURATE, COMPLETE OR ERROR-FREE, INCLUDING BUT NOT LIMITED TO THE ACCURACY OR COMPLETENESS OF ANY INFORMATION, TEXT, GRAPHICS, LINKS OR OTHER ITEMS CONTAINED WITHIN THE FIRMWARE.



For drives with SBFKB1C2 firmware:

Firmware Rev. SBFKB1C3 (12-19-2018)

- Improved responsiveness and system stability
- Fixed corner case where disk activity may spike during usage

For drives with SBFK71B1 or SBFK71E0 firmware:

Firmware Rev. SBFK71F1 (07-10-2019)

- Fixed corner case causing some drives to become unresponsive

For drives with SBFKB1C2, SBFKB1C3, SBFKB1D2 or SBFKB1E2 firmware:

Firmware Rev. SBFKB1H5 (01-16-2020)

- Improved system responsiveness
- Resolves corner case related to HP Notebook drive self-test
- Improved compatibility related to Legacy mode installation with Windows 7 and Windows 10
- Improved caching behavior
- Resolves errant SMART temperature display