Software history – Philips 2K17 6412/6482/7002/7502/8102/8602/9002 ranges

TPM171E _ 001.002.171.000 – Date: 2017/10/16
- Fix for missing channels in DVBC
- Improvement for stability and no response

TPM171E _ 001.002.167.001 – Date: 2017/10/06
- Supports introduction of 8602 range
- Fix for slow response of the set
- Improvement for auto start-up
- Improvement for YT playback
- Improvements for stability/crashes
- Update for channel logo's
- Update for Remote control SW

TPM171E _ 001.002.161.000 – Date: 2017/09/18
- Supports introduction of 8102 range
- PQ improvement, gamma correction

TPM171E _ 001.002.159.000 – Date: 2017/09/06
- Fix for no reaction on Home button
- Fix for Ambilight in screen demo
- Fix for lost/mixed-up channel list
- Fix for sound loss from ARC (5.1 sound) after start-up
- Fix for HBBTV Denmark (DR) content playback
- Improvements for lipsync optical out
- Improvements for stability/crashes
- Improvements for CEC

TPM171E _ 001.002.089.005 – Date: 2017/06/29
- Improvements for network connection in case of low signal
- Improvements for Netflix recommendation

TPM171E _ 001.002.089.001 – Date: 2017/06/09
- Supports introduction of 9002 range
- Fix for reddish and too bright picture
- Fix for no TV Guide in DVBS
- Fix for lipsync when using sound system
- Fix for pink screen after startup on HDMI
- Fix for Videoland buffering issue
- Improvements for stability/crashes
- Improvements for CEC
- Improvements for startup behaviour (auto startup, no picture)
- Improvements for power consumption

TPM171E _ 001.002.035.013 – Date: 2017/05/11
- Fix for startup issues
    - Green splash at startup
    - No picture/No Ambilight at startup
    - Not able to startup

TPM171E _ 001.002.035.010 – Date: 2017/04/25
- Initial SW for the 2K17 6412/6482/7002/7502 ranges