

Received March 6, 2001 at AmericanTCB:

Bill,

This email is intended to provide clarification on the operation description provided in the AB6NT800MFRM filing. The title page for this exhibit included in the filing was incorrectly labeled 1900 MFRM. It should actually read 800 MFRM in place of the 1900 MFRM. The content of the operational description contains references to both 1900 MFRM and 800 MFRM because this is a common platform, which utilizes both radios. The 1900 version will be submitted for approval in the next couple of weeks.

Please do not hesitate to contact me with any further questions or clarifications required for this filing.

Regards

**Glen Moore**

Manager, UMTS Product Integrity

**Sanmina Design Solutions**

Phone # 403-769-5002

ESN # 758-5002

FAX # 403-769-4813

ESN FAX 758-4813

glen.moore@sanmina.com