

CÓDIGO	MODELO
<b>AIWA</b>	
<b>KFT 3AA 294X</b>	AR 205 (Vide Equivalente CCE-49)
<b>KFT 4AA 271X</b>	AR 295RH
<b>KFT 2AA 293X</b>	AR-145 (Vide Equivalente CCE-53)
<b>BAYSONIC</b>	
<b>@ FCK 14A028</b>	CB -14 A ( Vide Equivalente Semivox - SS-04 )
<b>154 - 165D</b>	CB - 20
<b>FCM 20A016</b> TLF 70162	CB 20 A / SINGER TV 3920
<b>BROKSONIC</b>	
<b>FCC 1415AL</b>	GTV 4545 LSTC / Foco Baixo (duplicidade)
<b>FCC 2015AL</b>	GTV 5454
<b>FCC 2015FL</b> ( Foco ALTO )	CTVG-5454-LST GTV 4545 LSTC / Foco Alto (duplicidade)
<b>3.219.004</b>	GT 5454 LST
<b>3213002</b> 3213003	4545LST 14"
<b>KFS60282</b>	CTVL4545 14"
<b>DCF 2077</b>	4545 LSB
<b>BSC 23-1108</b>	BROKSONIC CTVC - 4545
<b>CCE , BLUE SKY, DAEWOO</b>	
<b>TAT 1401 A</b>	HPS 1415 B, 1415 C HPS 1425 A, 1425 B HPS 1450 B, 1465, 1465 A, 1465 B
<b>TAT 1402 A</b> TAT 1402 B TAT 1402 C	HPS 1465 Z, 1470 B, 1470 K, 1470 Z, 1470 ZJ, <b>1490 C</b> HPS 1485, 1485 B, 1485 G, 1485 ZG HPS 1490, 1490 B, 1490 H
<b>TAT 1403 A</b> TAT 1403 B	HPS 1465 C, 1465 ZC, 1465 ZD, 1465 ZG, 1465 ZH HPS 1470 ZC, 1470 ZD, 1470 ZG, 1470 ZH HPS 1485 D, 1485 ZC, 1485 ZD HPS 1490 D, 1490 ZC, 1490 ZD
<b>TAT 1404 A</b>	HPS 1465 ZE, 1465 ZF, 1465 ZI HPS 1470 ZI, 1470 ZE / ZF HPS 1485 E, 1485 I, 1485 F, 1485 ZE, 1485 ZF, 1485 ZI HPS 1490 CD,1490 E,1490 F,1490 I,1490 ZE,1490 ZF,1490 ZI
<b>TAT 1405 A</b> TAT 1405 B TAT 1405 D	HPS 14B, 14E, 14R, 14RB, 14RC, 14RD HPS 1470 AA, 1470AP, 1470 BB, 1470 CC, 1470 DD, 1470 EE, HPS 1470FF, 1470P, 1470Q, 1470R, 1470S,1470T,1470U HPS 1480, 1480 B, 1480 C, <b>1480 D</b> HPS 1481, 1481 B, 1481 C HPS 1492 C
<b>TAT 1406 A</b>	HPS 1401, 1470 V, 1481 E, <b>1481 Y</b>
<b>TAT 1407 A</b> TAT 1407 B	HPS 1401D, <b>1401</b> HPS 1492

CÓDIGO	MODELO
<b>CCE , BLUE SKY, DAEWOO</b>	
<b>TAT 1409 A</b>	HPS 1401 B, 1401 C, 1401 H, 1402 B, 1402 E, 1402F, 1403

TAT 1409 B TAT 1409 C TAT 1409 D	HPS 1403B, 1403C, 1403D, 1404, 14BLK , 14BLKB, 14BLKC MT14, TVC 141
<b>TAT 1412</b>	HPS 141B, 141C, 141D, 141G, 142B, 1405, 1407F, 1407G, HPS 1407S, 1423 , MT14NEW
<b>TAT 1414 A</b>	HPS 14BPS
<b>TAT 1420 A</b>	CCE 1405 H
<b>154 - 179M</b> FBT 2990 A (TRIPLICIDADE) TAT 2990A	HPS 2980 , 2990 , 2990B ( Vide Equivalente Goldstar - GD-03 / LG - 03 )
<b>DCF 1577</b> DCF 1577 A1	HPS 1491, 1495, GTV 4545 LSTC ( Vide Equivalente Precision - PX-02) - <b>NISATO 1445 NCT</b>
<b>TAT 2001 A</b>	HPS 2010 B, 2025 A, 2025 B, 2050 B, 2065, 2070
<b>TAT 2002 A</b> TAT 2002 B	HPS 2065, 2065 Z, 2065 ZB, 2065 ZC, <b>2065 ZD</b> HPS 2070, 2070 B, 2070 Z, 2070 ZB, 2070 ZC HPS 2085, 2085 B, 2085 C, 2085 ZB, 2085 ZC HPS 2090, 2090 B, 2090 C, 2090 ZB, 2090 ZC
<b>TAT 2003 A</b>	HPS 2065 ZD, 2065 ZE, 2070 ZD, 2070 ZE, 2070 ZF D/E/F, <b>2090FD</b> HPS 2085 D, 2085 E, 2085 F, 2090 B, 2090D, 2090 E, 2090 F, <b>2090AP</b>
<b>TAT 2004 A</b> TAT 2004 TAT 2004B	HPS 2070 P, 2070 Q, 2070 R, 2080 F, 2080 R, 2081 B HPS 2070X, 2070 ZD, 2070 ZE, 2070 ZF HPS 2085 D, 2085 E, 2085 F, 2090 B, 2090 D HPS 2090 E
<b>TAT 2005 A</b>	HPS 2080 C, 2080 E
<b>TAT 2006 A</b> TAT 2006 B TAT 2006 C TAT 2006 D	HPS 2070 S, 2070 V, 2080 B, 2081, 2081 C
<b>TAT 2007 A</b>	HPS 2080 D
<b>TAT 2008 A</b>	HPS 2092, 2092 B, 2092 C, 2092 D
<b>TAT 2009 A</b> TAT 2009 B TAT 2009 C TAT 2009 D TAT 2009 E TLF 032013306	HPS 1402 C, 2001, 2001 B, 2001 C, 2001 D, 2002, 2002 D, 2003, HPS 2004 A/B, 2006 MATSUI / MT-20 BLUE SKY - TV 20 BLK
<b>TAT 2011</b>	HPS 2007C, 2023, MT20NEW
<b>TAT 2012</b>	HPS 2005 , 2005G , 2007, 2007F , 2007H , 2007S , 2008, JC20, <b>HPS 2071</b> , HPS 2044.
<b>TAT 2020</b>	HPS 2005 H
@ <b>FSV 20 B 013</b>	BLUE SKY - TC-2033V (Vide Equivalente Cinerla - CN-04)
<b>FCM 2015 CL</b> TLF 70018A	HPS 2010, 2010A, 14 ( 10 Pinos ) ( Vide Equivalente Samsung - SS-17 )
<b>DCF 2077</b> DDF 9802A KFS 61115	HPS 20 VR, 2091, 2095 ( Vide Eq.Paxan e Precision - PX-03/ Philco - PC-07/ Telefunken - TF-03) <b>NISATO 2045 NCT - BROOKSONIC - 4545 LSB.</b>

CÓDIGO	MODELO
<b>CCE , BLUE SKY, DAEWOO</b>	
<b>TAT 2101 A</b>	HPS 2181 A, <b>2181 B.</b>
<b>TAT 2102 A</b>	HPS 20 EP, 21 EB
@ <b>BSC 23-6910</b> FO 1415 (DNF)	BLUE SKY - 1433 (Vide Equivalente Cinerla - CN - 01)

<b>TAT 2701 A</b>	HPS 2780, 2781B, 2980 (IMPORT.)
<b>TAT 2702 A</b>	HPS 2706, 2706 B
<b>TAT 2704 A</b>	HPS 2706C, 27BLK
<b>TAT 2901 A</b> MSU1FHC506 MSU1FHG506 ( TRIPLICIDADE )	HPS 2980, 2981 HPS 2980 (IMPORT.)
<b>TAT 2902 A</b>	HPS 29E "B"
<b>TAT 2903 A/B</b>	HPS 2902, HPS 2901B, HPS 2901
<b>TAT 2904 A</b> TAT 2904B	HPS 2904E, 2906 B, 2906C, 2906D , 29BLK , 29BLKB, 29BLKC, 29BLKD
<b>TAT 2907 A/B</b>	HPS 2906E, 2906F, 2910 , 2910B, 2910C, 2910E
<b>TAT 2908 A</b>	HPS 2908 C
<b>TAT 2908 B</b> TAT 2908C	HPS 2908
<b>FBT 3380</b> TAT 3380	HPS 3380
<b>TAT 3401 A</b>	HPS 33 R / 33 RB
<b>KFS 60226 / B</b>	HPS 1425, 1450 A, 1450 R, 1450 C, 1495, 1495 B, <b>1450 AB, 1495 BR, 1491</b>
<b>KFS 60266</b> FA 1426	HPS 2025, 2050 A, 2050 C, 2050 R, 2095, HPS 20
<b>NF 7301</b> NF 7302 (Foco BAIXO)	HPS 1415, HPS 14 Polegadas (Foco Baixo)  HPS 1430 R
<b>NF 7401</b> FTB 7401C	HPS 20, 2015, 2030 R
<b>TAT 2906B</b>	HPS 2901
@ <b>KFT 3AA 294X</b>	HPS 2003F, TVAR205 (Vide Equivalente Aiwa - AW-01)
<b>KFT 4AW 332Y</b> KFT 4AA 332X	HPS 2912
@ <b>BSC 28-2101</b> C 1226216C	BLUE SKY - TC-2932 / 2933 (Vide Equivalente Ceneral CN-08)
<b>FSA 25023 S</b>	DAEWOO - DTH 14Q2FS / DVX 14F6N
@ <b>KFT 2AA 293X</b>	HPS 1403G / 2003G - (Vide Equivalente Aiwa - AW-03)
<b>FSA 28014M</b>	DAEWOO - DTH 20QTFS
<b>MC-FBM-001</b>	TVP5C, TVP6/B/C, TV65/AUDAX
<b>MC-FBC-002</b> MF-1799	TVP7, TVP7B
<b>MC-FBM-003</b> BSH12-01	TVP8, TVP12, TVP12B/VS

CÓDIGO	MODELO
<b>CCE , BLUE SKY, DAEWOO</b>	
<b>TAT 2104</b>	HPS 2118, <b>HPS 2171, HPS 2185</b>
<b>KFT 4AW 371Y</b>	HPS 2912B
<b>TAT 14101A</b>	(Vide Equivalente SH-21)
<b>TAT 2982A</b>	HPS 2982 , 2991, TVD 2911VS , TP 2958
<b>TAT 2909 A</b> TAT 2971A/B	HPS 2909 / 2971 TVD 2901 ( <b>DUPLICIDADE</b> )
<b>BSC 27-G0101</b>	BLUE SKY - TC PL 2919 P (Vide Equivalente Ceneral CN-12)
<b>FUH 30A005</b>	

<b>MC-FBM-004</b>	
<b>MC-FBM-018</b> (VM-14AF)	
<b>BSC 29-0192F</b>	CCE - HPS 2991FSC, HPS 2997FS
<b>TAT 3301A</b>	HPS - 3301
<b>BSC 29-0157E</b>	HPS 2985/B/C/D ; TVD2901F ; HPS 2988 (DUPLICIDADE)
<b>CFB2-005 / 43-74-1003</b>	TVP 105
<b>CINERAL, BAKOSONIK, CYBER VISION</b>	
<b>FO 1415 (DNF)</b> BSC 23-6910 BSC 25-2701	CINERAL - TC-1432 / 1433 (Vide Equivalente Blue Sky - CCE-31) 14TF
@ <b>154-164 F</b>	CTVG 5050 ( Vide Equivalente Panasonic - P S-11 )
@ <b>FSV 20 B 012</b>	( Vide Equivalente Samsung - SS-14 )
@ <b>FSV 20 B 013</b> C1226214A C1226215A SN: 11226178	CINERAL - TC-2032 / 2033V (Vide Equivalente Blue Sky - CCE-26)
<b>FSA 27018 M</b> DCF 2077Z	1411 / 1422 / 2011 / 2022 CVT 1485
<b>KFS 61262</b>	CINERAL - PVM 2050 / 2051 BR, CVT 2085 (Vide Equivalente Paxan PX-08)
<b>FCM 20A010</b>	CINERAL - 2070
<b>BSC 28-2101</b> C1226216C	CINERAL - TC-2932 / 2933 (DUPLICIDADE) / 29BD (Vide Equivalente CCE-51)
<b>FFA 94024L</b>	TS 2975
<b>DFE 98014</b>	14" E 20" CINERAL
<b>BSC 28-N2313R</b>	CINERAL/BLUESKY/CYBERVISION - TS2932/2933 (DUPLICIDADE) TC 2933 (DUPLICIDADE)
<b>BSC 27-G0101F</b>	TC PL2919P
<b>MCG-21A26</b> SN: 11226230	
<b>PWL - 15</b> BSC 25-N0522	CINERAL - TS 2977
<b>BSC 28-N2328</b>	BLK 2932
<b>OV2094-1</b> (08301FT----)	CINERAL - 2070
<b>MCJ-29A005</b>	TF 2932
<b>BSC 24-N0102C</b> ( OV 2094 )	CINERAL
<b>BSC 25-N0302</b> ( OV 2094 )	CINERAL
<b>BSC 30-N2570</b> 6174917003A	CINERAL
<b>BSC 29-0157E</b>	CINERAL / CYBER CB 2905
<b>3220004</b>	CINERAL VT 0950 M

CÓDIGO	MODELO
<b>CONTINENTAL, COUGAR, EMERSON</b>	
<b>101-21002-03 A</b> LCE CF-0359	EMERSON
<b>FCK 1415 JL</b>	EMERSON - 2122 C, TECSONIC T14RWC
<b>154 - 189 H</b>	3352 Z GT - 9313 ( CONTINENTAL )
<b>3214014</b>	EMERSON - 1465B
<b>3214015</b>	EMERSON - TC-1465
<b>154 - 138B</b> 11226086	EMERSON - TC-1405A
<b>3.220.030</b>	EMERSON - TC-2066
<b>F 2005 CE (H)</b>	COUGAR - CTV 1413 / 2013

3.220.023	VT 2020
<b>GOLDSTAR</b>	
<b>154 - 164 E</b> FC 1445	GTV 5050, CB 14
<b>154 - 177 J</b>	CP1413, CP14 A 13, 14 A 40, 14 A 80, 14 CB 80, 14 A 82, 20 B 70, 20 CB 80, 20 A 82 (Vide Eq. Gradiente - GT-02/ LG-02/ Philco - PC-04/ Samsung - SS-06)
@ <b>154 - 179 M</b>	CP 29 C 10 ( Vide Equivalente LG-03 e CCE-12 )
<b>154 - 207 A</b>	CANGURU KP 14V30 (Vide equivalente Gradiente - GT-03)
<b>154 - 375 A</b>	( Vide Equivalente Gradiente - GT-04/ LG-04/ Samsung - SS-07 )
<b>154 - 375 C</b>	( Vide Equivalente LG-05/ Samsung - SS-08 )
<b>154 - 168C</b>	GOLDSTAR - CNT 9175

**GRADIENTE, JVC, MONITOR DE SEGURANÇA**

<b>FCV 1410 E 06</b> ( 571 395 001 902 )	GT 1410, GT 1411, 14 C 5170 ( Vide Equivalente Telefunken - TF-01 )
@ <b>154 - 177 J</b> ( 571 476 001 902 )	GT 1420, 1422, 2020, 2022, 2025 (Vide equivalente Goldstar - GD-02 / LG-02 / Philco-PC-04 / Samsung - SS-06)
@ <b>154 - 207 A</b> ( 951 167 001 901 )	GTV142 (TV E VIDEO) ( Vide Equivalente Goldstar - GD-04 )
@ <b>154 - 375 A</b>	( Vide Equivalente Goldstar - GD-05/ LG-04/ Samsung - SS-07 )
<b>FCV 2010 E 02</b> FCV 2011 ( 571 391 001 902 )	GT 1410, GT 1411, GT 2010, GT 2011, GT 2015 20 C 5170 ( Vide Equivalente Telefunken - TF-02 )

CÓDIGO	MODELO
<b>GRADIENTE, JVC, MONITOR DE SEGURANÇA</b>	
<b>FCV 2010 E 09A</b> 230934	( Vide Equivalente RCA-08 / Zenith -ZT-01 )
<b>CJ 27773 / 00AJ1</b> CE 42205-002 G 27327-063F	JVC - C1485BR
<b>CJ 27898</b> ( 571 418 001 902 )	HRM 29 PS / HRM 33PS / <b>HRM 37PS</b> JVC - 31BX4
<b>CJ 28069</b>	AV 2196 SAH, AV-T-2172
<b>CJ 28111</b>	JVC C 1486, CT 1471
<b>CJ 28212</b> ( 571 448 001 902 )	HRM 290 PS / HRM 330 S / HRM 370 PS JVC - AVB 2973 - AVB 3373
<b>CE 41899-00A</b>	GRADIENTE - 335 COM PIP JVC - AV 31BP4 / AV-3150
<b>CE 42211-00B</b>	GT - 2825 / 2925

CE 42031-00C 571 414 001902	
<b>CE 42674-001J1</b> ( 571489001902 D )	HT - M 277S / 299S / 29 Mi / <b>29i</b> JVC- AV-T2977
<b>47105380</b> BSC 26-5620 ( 571 439 001 902 )	HRM 290 S
<b>TCV 50 B 01</b> FCV 1422L01	JVC - 2120 (Vide Equivalente Pekonic - PX-05)
<b>6174V - 8004 A</b> 6174V - 8004 D 6174V - 8005 C ( 570007001902 )	2030 / 2033 / M - 20i / 1430 / 1433 / 14 Mi Monitor de Segurança - SM-14 / CFTVSM-20  ( Vide equivatente LG-18 )
<b>QQH 0025-001</b>	HT-M 344S
<b>CE 42374-00-CKJ1</b>	JVC - AV 35BP4U / GRADIENTE - HRM - 37PS
<b>6174Z - 6012 Q</b>	Monitor de Segurança - 29MI (DUPLICIDADE)
<b>CE 41735-00A</b>	GT 29S / S-28
<b>2436214 (MD14L)</b>	GT 2010
<b>JF 0501-19555</b>	GBT-2010 / 2011 / TV-2021
<b>FUH 30A006</b>	

## GRUNDING

<b>2436912</b> NCO 8L	GT 2012 A GT 1412 / 2012 / 2112
<b>1142.5046</b>	( TV + VIDEO ) TVR 3701 SV , TVR 3710

## KIREY, FIRST LINE

<b>@ FC 1412</b>	FIRST LINE ( Vide Equivalente Semivox - SS-02 )
<b>FC 1426</b>	KTV 1414 / TS 14 CIR
<b>@ FA 2017</b>	FIRST LINE - T 20 AW ( Vide Equivalente Semivox - SS-19 )
<b>FA 2019</b>	KTV 2020 / TS 20 CIR

## CÓDIGO

## MODELO

## LG

<b>154 - 103 D</b> 154 - 103 F	CP 29 C 42 / P
<b>@ 154 - 177 J</b>	CP 14 B 84, CP 20 B 84, CP 20 B 85, CP 20 K 40, CP 14 A 82 (Vide equivalente Gradiente-GT-02/Goldstar-GD-02/Philco-PC-04/Samsung-SS-06)
<b>@ 154 - 179 M</b>	CP 29 C 84 M, CP 29 C 85 M, <b>CP 29 C 85</b> (Vide equivalente CCE - 12 / Goldstar - GD - 03)
<b>@ 154 - 375 A</b>	(Vide equivalente Goldstar - GD-05, Gradiente - GT-04, Samsung - SS-07) CP 20 J 20
<b>@ 154 - 375 C</b>	( Vide equivalente Goldstar - GD-06, Samsung - SS-08 )
<b>6174Z - 6002 C</b>	
<b>6174V - 6002 G</b>	CP 14 K 40, 14 K 42, RP 20 CB 62 (DUPLICIDADE)
<b>6174V - 6002 J</b>	RP 21 CA 85

<b>6174V - 6002 U</b> BSC26-N2121(N)	RP 20 CC 20
<b>6174V - 6003 J</b> BSC28 - N2307	CP 29 K 30
<b>6174Z - 6005 D</b>	CN-29 Q 10P , 29 Q 12P
<b>6174Z - 6012 D</b>	CP 29 C 85
@ <b>6174Z - 6012 F</b> 3210-94714-010	( Vide Equivalente Philco - PC-33 )
<b>6174Z - 6012 N</b>	CP 25 Q 20
<b>6174Z - 6031 A</b>	CP 29 Q 50 , <b>CP 29 Q 20 (DUPLICIDADE)</b>
<b>6174Z - 6032 A</b>	CP 21 Q 22
<b>6174Z - 6040 B</b>	CP 14 J 52
@ <b>6174Z / V- 8004 A</b> 6174V - 8004 D 6174V - 8005 C	CP 14 B 85, CP 20 B 15, CP 20 B 85 CP 20 J 52 , 20 K 40 20 K 70 , 20 B 86 , 24K70 ( Vide equivalente Gradiente - GT-17 )
<b>6174Z - 6040 C</b>	
<b>6174V - 6003 M</b> BSC 30-N2514	CP 25Q22
<b>6174Z - 6051 B</b> JW-3	29"
<b>6174V - 7001 A</b> FSA 39012S	CP - 20B15 / 20K40 / 20B85
<b>6174Z - 6012 U</b>	
<b>4410Z - A001 G</b>	RETRO 42"                      1 ENTRADA / 1 SAÍDA (CAPACITOR)
<b>6174Z - 6012 X</b>	
<b>6174Z - 6512 B</b>	

CÓDIGO	MODELO
<b>LG</b>	
<b>6174V - 5003 B</b> BSC 28-N2324	29CC25, 29CC26, 29CC90
<b>6174V - 5003 G</b> BSC 28-N2331	29K30A
<b>6174Z - 6035 D</b>	WP 3210 P
<b>6174V - 6006H</b> BSC23-N0121	CP 15Q90A, 21FB32 RP 21FD10
<b>6174Z - 6400B</b>	RETROPROJETOR
<b>6174V - 6006C</b> BSC23-N0115	CP 21Q24A
<b>6174Z - 5004A</b>	29" CP 29Q54 (duplicidade)
<b>6174V - 6003X</b>	
<b>6174V - 5003L</b> BSC 28-N2334	
<b>6174V - 5003A</b>	RP 29FA30A
<b>6174Z - 6004F</b>	
<b>6174V - 6006J</b> BSC 26-N2123	
<b>6174V - 5003R</b> BSC 25-N1537	RP 29FF80 , RP 29FA35A
<b>6174V - 6006V</b> BSC 25-N1651	RP 21FE85 - G
<b>6174V - 5013A</b> BSC 28-N2355	CP 29K35A
<b>154-238A</b>	CP 29H90P

<b>4410Z - A001P</b> Divisor 1 entrada e 3 saídas	
<b>6174V - 6017A</b> JF 0501-19975	RP 14CB25 20CD2R
<b>6174V - 6010C</b> 6174Z - 6035W	RI 34FC32P
<b>6174V - 5007B</b> 6174V - 5007A	RETRO 54NA40PA 44"
<b>6174V - 6010F</b> 6174Z - 6035X	RP 29FC40P
<b>6174V - 6010A</b>	RP 32FZI224
<b>6174V - 6010D</b>	<b>ATENÇÃO: LER MANUAL!</b>
<b>6174V - 6006W</b>	

**mitsubishi , EVADIN, AIKO**

<b>334 B 06209</b> 334 B 06208	TC 2001, 2002, 2003, 2020, 2021, 2602
<b>334 B 07409</b>	
<b>334 B 07601</b> 840.000.141.142	VS 403R (40 Polegadas) / TC-3701
<b>334 B 08201</b> (Foco ALTO)	TC 1441, 2030, 2031, 2034, 2040, 2041 ( Foco Alto )
<b>334 P 11501</b>	TC 2602
<b>334 P 13001</b> 334 B 08202 334 P 13002 (Foco BAIXO)	TC 1441, 2030, 2031, 2034, 2040, 2041 ( Foco Baixo )
<b>NF 7404 E</b>	TC 2050, 2051, 2090, 2091, 2094
<b>334 P 18102</b> ( 2 FOCUS )	29 FS
<b>334 P 18504</b>	TC 21 FC , 2121 FC

<b>CÓDIGO</b>	<b>MODELO</b>
<b>mitsubishi , EVADIN, AIKO</b>	
<b>334 P 19501</b>	TC 1492 / 2034
<b>334 P 20001</b>	TC 1492, 1498
<b>334 P 20101</b>	TC 2051, 2054 , 2060
<b>334 P 21202</b>	29" TC - 2999
<b>334 P 229B1/C1</b>	TC 1499, 2097, 2098, 2099, 21 S
<b>334 P 22901</b>	TC - 2198
<b>334 P 24801</b> ( 840-000671-247 )	TC 2909 C
<b>334 P 25901</b> KFT 3AB 126C	TC 1409, 2009
<b>334 P 27201</b> KFT 3AA 226C	TC 2018 , 2018 PS
<b>334 P 27301</b>	TC 1418 , 2018 , 2118
<b>334 P 27401</b>	TC 2918 P S
<b>334 P 23101</b>	33" TC-3398 (DUPLICIDADE), TC-3498 , CS 31303
<b>KF 58383 P</b>	33" 3398 (DUPLICIDADE)
<b>334 P 265A10</b>	TC 3309
<b>334 P 272A10</b> BSC 27-0107A	
<b>BSC 27-0104B</b>	TC-2004ST / 2010
<b>334 P 23105</b>	
<b>BSC 27-0167S</b> 840-00001-247	TC 2910
<b>BSC 27-0177R</b>	

BSC 27-0106R	
6174Z-6007A	TC 2018
334 P 16809	CS-3520
PANASONIC	
OLF 04508-F	TC 27G31V , 33V60, 29V60
TLF 14427 F	PVM 2050 TV + VÍDEO (CANGURU)
TLF 14470 F	29 V 50 , 29 V 60
TLF 14531 FV 9 pinos	TC 209 S, 210 S, 210 US, 215 M, 211 N, 212, TC 212 M, 213, 214 , 215 N
TLF 14532 F	TC 141 N, 142 M, 143 M, 161 M, 162 M
TLF 14533 FV 2 9 pinos	TC 20 C1, TC 20 D1, TC 20 R1, TC 214 M, TC 214 MU, TC 214 S
TLF 14534 F 2 9 pinos	TC 144 M, 145 M, 146 M, 163 M, 164 M, 165 M
TLF 14731 F 9 pinos TLF 14731F-1	TC 14R1 M , 144, 145 M, 146 M, 163, 164 M, 165 M
TLF 14731 F-1A 9 pinos	TC 14 C1, 14 C1U, 14 D1, 16 C1, 16 D1, 16 D1V
TLF 14731 F-3A 10 pinos	14 C2, 14 D2, 14R1M, TC-13C1U, TC-14D1U, TC 20CZ
154 - 164 F KFS 60893	1401MN / 1402 MN , TC 1433 ( Vide Equivalente Bakosonic - CN - 02 )
TLF 15531 FA 10 pinos	TC 20 A2, 20 C2, 20 D2
TLF 15540 F-A 10 pinos	TC 29 AS2, TC 29 AV1

CÓDIGO	MODELO
PANASONIC	
TLF 15541 F 10 pinos	TC 20 AS2,
TLF 15564 10 pinos	TC 20 BS 5, TC 20 C 4, TC 20 C 5, 20 D 4, 20 D 5
TLF 15615 F2	PT - 51 G 40 U ; TVC 21 V 50
TLF 15626 F 10 pinos	TC 14 C 4, TC 14 C 5
TLF 15644 F1 TLF 15644 F	TC 14 B 7, TC 14 C 20, TC 20 A 7 (duplicidade) , TC 20 B 7, TC 20 C 20, TC 20 C 7, TC 20 C 21
TLF 15646 F 9 pinos	TC 20G7
KFT 2AB 095F	14A8
KFT 2AB 281F1	14A9 , 14A10, 14A12 (DUPLICIDADE)
KFT 2AB 287F1	14A10
KFT 3AB 096F	TC 20 A 8, 20 A 12 (TRIPLICIDADE) / TC 20A01
KFT 3AB 119F1	TC - 20G9 (DUPLICIDADE) , P S 20G11
KFT 3AB 280F1 KFT 3AB 281F1	TC 20A9 , 20A10P , 20A12 (TRIPLICIDADE)
KFT 4AB 055F	TC 29 A 8 , TC 29A9 (DUPLICIDADE)
KFT 4AB 143F	TC 21G11 (DUPLICIDADE), 27G23W , TC 29A9 , 29G9L, 29G11, 29G12
TLF 4 G 503 F	TC 14 C 6, TC 14 C 20, TC 20 C 6, TC 14 C 7, TC 14 A 7
TLF 6028 F 9 pinos	TC 182 M, 205 M, 205 S
TLF 6522 FN 9 pinos	TC 182 N, 205 N, 206 A, 206 B, 207, 208 M, 211 M
KFT 3AB 054F	TC 20G9 (DUPLICIDADE)
KFT 2AB 073F	14G7 / PVM 1327 / PVM 1347
KFT 3AB 074F1	CTV31L4 / 21G7 TV+VCR DUETO , PVM 2047
ZTFN 05004A	29"
KFT 2AA 425F	
KFT 2AA 427F	
KFT 3AA 426F	TC 20A12 (TRIPLICIDADE)
KFT 3AA 428F	TC 20A12 (TRIPLICIDADE)
ZTFN 32010A	TC 14A12 (DUPLICIDADE)
ZTFN 33005A	TC 20-KL03 / TC 20-KM03

<b>TLF 14767F</b>	TV + VCR CTV 14L3
<b>KFT 3AB 080F</b>	TC-20A7 (DUPLICIDADE)
<b>KFT 3AB 138F</b>	TV + VCR PV-M2048/2058
<b>KFT 4AA 448F</b>	TC 29KM03 , TC 29KL03
<b>KFT 4AX 242 F2</b>	TC 2922LB
<b>KFT 4AX 242 F3</b>	TC 25P22LB
<b>ZTFN 82007 A</b> ZTFN 82001A	TC 20A04 , TC 21FJ30L
<b>ZTFN 35011A</b> ZTFN 35007A	TC29KL04
<b>KFT 5AA 369F</b>	33"
<b>KFT 5AB 106F</b>	TC 33ZB
<b>KFT 6AB 056F</b>	TC 36G32
<b>KF 4867 C</b>	
<b>PAXAN / PEKONIC / PRECISION / BRASSONIC</b>	
<b>E 1051</b>	PAXAN - 14 AV 49 B
@ <b>DCF 1577</b>	PRECISION - PVM 1451 BR ( Vide Equivalente CCE - 13 )
@ <b>DCF 2077</b> DDF 9802A KFS 61115	PAXAN - 20 D 49, 21 M 4 SD PRECISION - PVM 2051BR (Vide Equivalente CCE-28, Philco - PC - 07, Telefunken - TF - 03)

CÓDIGO	MODELO
<b>PAXAN / PEKONIC / PRECISION / BRASSONIC</b>	
<b>TCG 30 B 02</b> TCG 30 B 13	PEKONIC - CT 1000
@ <b>TCV 50 B 01</b> FCV 1422L01	PEKONIC - CT 1400, 1409 (Vide Equivalente JVC - GT-16)
<b>KFS 61269</b>	PRECISION
<b>DFF 98020A</b>	21M49
@ <b>KFS 61262</b>	PAXAN - 21M49B ( Vide Eq. Cinerall - CN-06 )
<b>JF 0503</b> 122-5020503	PRECISION - PTV 2085 RNC
<b>PHILCO</b>	
<b>BW 00103</b> ( 3210-79093-00-0 )	PCS 2952 ( Obs: EM ALGUNS CASOS SERVE P/ PCS 2700 )
<b>FCM 14 B 007B</b> 3213009	PVT 1400 / 1410 / 1412 / 2014
<b>FCK 14 B 025A</b>	DUETO PVT 1418
<b>154 - 177 J</b>	14C82RC, CPT 2030R, CPT 1430, 2030, 2040, 2130, <b>2040R</b> PAVM 2140 ( ARGENTINO ) ( Vide Eq. Goldstar - GD-02/Gradiente GT-02/LG-02/Samsung SS-06 )
<b>154 - 279 F</b> 154 - 279 S	PCS 2950
<b>FCM 20 B 043</b>	PVT 2014, PTVR 2400 , 2410
@ <b>DCF 2077</b> DDF 9802A KFS 61115	C1411R,C1411T,CL1411,CL1411R,CP1411R,CP1411T,CP2011, CP2011R,CP2011T (Vide Equivalente CCE-28,Paxan e Precision - PX-03,Telefunken - TF-03)
<b>OV 2094 / D1</b>	PCM 1448, 1451, 1456, 2048, 2051, 2056

11 PINOS ( 3210-87879-01 B ) ( 3210-E2237-01-4 ) ( 3210-90815-01-7 )	PCR 1447, 1449, 2047, 2049 PCS 2050, 2060 TP-1452N / 1453S / 1454 / 2053S / 2054 CHASSIS CPH-061 CHASSIS CPH-06M
<b>OV 2094 / D1 - B</b> 11 PINOS 08381FT----	
<b>OV 2094 / D1 - C</b> 11 PINOS 08381FT----	TP-2054
<b>OV 2094 / D1 - F</b> 11 PINOS 08381FT----	PCM 2051
<b>OV 2094 / D1 - H</b> 11 PINOS	
<b>OV 2094 / D1 - I</b> 11 PINOS	

CÓDIGO	MODELO
<b>PHILCO</b>	
<b>OV 2094 / D1 - N</b> 11 PINOS	
<b>2436772 /</b>	PAVM 2920
<b>3210-61313-001</b> OV 2094 / D3	PCK 1444 <b>HI VISION</b>
<b>3210-61315-001</b> OV 2094 / D3	PCM 2043, PCS 2168
<b>3210-61317-00-04</b> ( CHASSIS-CPH-05 )	PCS 2700 (Em alguns casos usar BW00103)
<b>B 32 - 3409</b> B 32 - 3403	CTH - 001 (16 e 20 Polegadas) PC 1401, 1402, 1403, 1601, 1602, 1603, 2001, 2002, 2003
<b>B 32 - 3412 - 002</b> B 32-3431	PC 1405, 1406, 1416, 1421, 1425 U, 1426 U, 1427U, <b>PAVM 2140</b> PC 1428 U, 1603, 1605, 1606, 1613, 1616, PAVM 2140V/ST
<b>B 32 - 3413 - 002</b> B 3210-61297-00-3 (T2) TVC / 23	PC 2004, 2007, 2008, 2013, 2015, 2016 U, 2017 PC 2018, 2025 U, 2026, 2027 U, 2028U, 2040U PAVM 2040 (DUPLICIDADE)
<b>B 32 - 3415 - 004</b>	PB 17 A 2, 20 A 2 (Filamento 6V)
<b>B 32 - 3418</b> B 32 - 3426	PAVM 2054, <b>PAVM 2040 (DUPLICIDADE)</b> , 2050, 2052
<b>B 32 - 3427</b>	PAVM 2400U, 2040 (DUPLICIDADE)
<b>B 32 - 3437 - 001</b>	PC 1435, 1436
<b>B 32 - 3438 - 001</b>	PC 2035, 2036, 20 R 36
<b>B 32 - 3439 - 001</b>	PC 2136, PAVM 2160
<b>B 32 - 3448 - 003</b>	PC 1437, 1438, 1439, 1441, 1442
<b>B 32 - 3449 - 003</b> 154 - 177 W	PC 2037, 2038, 2039, 2041, 2042, 2138, 2142, 20 R, 20 R 37 20 R 38, 20 R 42, PAVM 2141, 2142, 2162, 2164, <b>CPH04, 20R48</b>
<b>B 32 - 3452</b>	& PB 17 A 2 (Filamento 11V) (LER MANUAL)
<b>B 32 - 3453 - 001</b>	CPH05 PC 1443, 1444, PC 1445, PCM 1446
<b>B 32 - 3454 - 001</b> 1.35.52113-00	CPH05 PCM 2043, 2044, 2045, 2046, 2144, 2145, 2146, PCS 2168
<b>6174Z - 6012 F</b> FFA 97017L 3210-94714-010	PCS 2956 P / 3320, PCS 2958 P / 3322 / PCS 2976 ( DUPLICIDADE ) ( Vide equivalente LG-13 )
<b>A 6194 - 010</b> JF 0501-2156	PCS 2976, PC-A6174 (DUPLICIDADE)

3210-A6194-010 ( FFA 99057 M )	
<b>FFA 65025 L (1)</b> <b>OH08A4 J</b> <b>4LXXXX</b> ( 2 FOCUS )	<b>LER MANUAL</b>  PCS 2902, PCS 2802/56 TPF 2901 / V , TPF 2902 / V , TPF 3201 / V , TPF 3211 , 3221 & TPF 3421
FFA 65025 L (1) 0K0102 S	
0K1707 S	
FFA 65025 D	
3210-A4660-01-3 LER MANUAL (CUIDADO)	
FFA 65025 L (1) 0H09B1 J 0H0905J	

CÓDIGO	MODELO
<b>PHILCO</b>	
<b>FFA 65025L (1)</b> <b>OG36A1J</b> <b>OG06A1 J</b>	<b>É DIFERENTE</b>  <b>CUIDADO!!!! NAO DISPONIVEL</b>
<b>FFA 97017 L (1)</b> (DUPLICIDADE) <b>OA20A3J</b>	PCS 2956 N / 2902 N (DUPLICIDADE)
<b>OV 2094 / D1 - L</b> 10 PINOS 08273FT---- 08381FT----	TP 2053
<b>FFA 97035 L</b> 3210.A4941.01-9 3210.A4941.02-7 (DUPLICIDADE)	TPF 2901N / 2902N (DUPLICIDADE) / 2921 / 2922 PCS 2956N / 3320N / 3320V / 3322N / 3322V DVS 340DW
<b>OV 2094 / D1 - D</b> 11 PINOS	
<b>FTE - 09A008</b> 3210009	
<b>2437094</b> 3208.6141.2007.16.97.1	PCS 3300N , 3302N
<b>FFA 97031L</b> 4FXXXX 4GXXXX 4iXXXX 5EXXXX 5HXXXX 5iXXXX	
<b>OV 2094 / D1 - A</b> 11 PINOS	
<b>OV 2094 / D1 - G</b> 11 PINOS	
<b>OV 2094 / D1 - M</b> 11 PINOS	
<b>FFA 65025 L</b> 3210.97177.016	<b>LER MANUAL</b>
<b>OV 2094 / D1</b> 10 PINOS 08273FT----	

08381FT----	
<b>OV 2094 / D1 - A</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - B</b> 10 PINOS 08273FT---- 08381FT----	

CÓDIGO	MODELO
<b>PHILCO</b>	
<b>OV 2094 / D1 - C</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - D</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - F</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - G</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - H</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - I</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - M</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - N</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - L</b> 11 PINOS	
<b>OV 2094 / D1 - O</b> 08272FT---- 08273FT---- 08381FT----	TP - 2051
<b>JF 0501 - 19277</b> 3210-F4118-01-09	PCS 2976 / 2976S / 2978 / 2996S / TPF 2922 / 2121
<b>2437428</b> QH 15L	

<b>FFA 97038L</b>	
<b>JF 0501 - 19192A</b> 3210G0940018	TP 2054
<b>B3210-61306-010</b>	PC 20R43
<b>FEA 737</b>	DSV 340 34" C/ PIP
<b>FSV 20B018</b>	PVT 2018, 2028

CÓDIGO	MODELO
<b>PHILIPS</b>	
<b>BW 00101</b> ( 4806-140-170-42 ) ( 4822-140-10506 ) ( 4822-140-10511 )	29GX 1892 / 1895 / 1898
<b>13620004A</b> ( 4806-140-170-91 )	38" 28PW858
<b>140 - 170 - 77</b> 4806-140-170-77 ( 4936 )	29 PT 752 A
<b>OV 2076</b>	20 GL 1333
<b>OV 2076 ( 20591 )</b>	33 PT 772A
<b>OV 2076 ( 20592 )</b> ( 4806-140-170-78 )	29 PT 652 A 29 PT 662 A, 33 PT 772 A
<b>OV 2076 ( 20593 )</b> ( 4806-140-170-85 )	29 PT 652, 654, 654A, 854, 854A 33 PT 752, 33 PT 772, 33 PT 854
<b>OV 2076 ( 20601 )</b> ( 4806-140-170-72 )	29 PT 552A / 78R
<b>OV 2076 ( 20692 )</b> ( 4806-140-10672 )	33 PT 574
<b>OV 2076 ( 20732 )</b>	
<b>OV 2076 ( 20905 )</b>	
<b>OV 2076 / - A</b> 21411FT----	29 PT 658A / 78R
<b>OV 2076 / - B</b> 21411FT----	
<b>OV 2076 / B2</b> <b>OV 2076 / B2-C</b> 08021FT---- ( 4806-158-870-59 )	PT 554
<b>OV 2076 / B2 - L</b>	
<b>OV 2076 / B2 - O</b>	
<b>OV 2076 / B3</b>	20 PT 656 A , 29 PT 856 A
<b>OV 2076 / B3 - B</b>	
<b>OV 2076 / B3 - D</b>	
<b>OV 2076 / B3 - H</b>	
<b>OV 2076 / B3 - I</b>	
<b>OV 2076 / B3 - M</b>	
<b>OV 2076 / B3 - N</b>	
<b>OV 2076 / B3 - O</b>	
<b>OV 2076 / - C</b> 21362FT----	
<b>OV 2076 / - D</b> 21411FT----	

<b>OV 2076 / - F</b> 21421FT----	33 PT 578
<b>OV 2076 / - G</b> 21421FT----	

CÓDIGO	MODELO
<b>PHILIPS</b>	
<b>OV 2076 / - H</b> 21921FT----	28PW6532
<b>OV 2076 / - I</b> 21362FT----	
<b>OV 2076 / - L</b> 21411FT---- 21421FT----	
<b>OV 2076 / - M</b> 21421FT---- ( 4806-140-170-89 )	29 PT 658 , 33 PT 578
<b>OV 2076 / - N</b> 21421FT----	
<b>OV 2076 / - O</b> 21421FT----	
<b>AT 2077/ SO / 50</b> AT 2077/ 1º VERSÃO ( 4806-140-170-31 ) ( 4806-140-170-47 )	28 GR 7580, 28 GR 7680
AT 2077/ 2º VERSÃO ( 3832-0 ) <b>(4806-140-170-34)</b>	28 GR 7585, 7685 V 9350-BP <b>21 GR 7560</b>
<b>AT 2078 ( 21151 )</b> 4806-140-170-87	29 PT 836 <b>21 PT 836</b>
<b>AT 2078 / - A</b> 21391FT---- 21401FT----	
<b>AT 2078 / - B</b> 21391FT---- 21401FT----	29PT4631 (DUPLICIDADE)
<b>AT 2078 / - B</b> 21321FT----	(DUPLICIDADE)
<b>AT 2078 / B 1</b> ( 4806-140-170-63 )	25 GX 1889, PT 230
<b>AT 2078 / B 2</b> AT 2078 ( 20311 ) ( 4806-140-170-68 ) ( 4822-140-106-37 )	21 PT 230, <b>21 PT 232</b> 21 PT 1663, 21 PT 2682, 21 PT 4404, 21 PT 4424 PT 212 , PT 240
<b>AT 2078 / B4</b> ( 4806-148-870-57 )	PT 534
<b>AT 2078 / B4 - F</b>	
<b>AT 2078 / B4 - N</b>	
<b>AT 2078 / - D</b> 21391FT---- 21401FT----	29 PT 458 / 558 (DUPLICIDADE)

CÓDIGO	MODELO
<b>PHILIPS</b>	
<b>AT 2078 / - F</b> 21391FT---- 21401FT----	
<b>AT 2078 / - G</b> 21391FT---- 21401FT----	
<b>AT 2078 / - I</b> 21391FT---- 21401FT----	21 PT 838A 29 PT 458 (DUPLICIDADE) , 29 PT 558 29 PT 4631 (DUPLICIDADE) , 29 PT 4831 BR
<b>AT 2078 / - M</b> 21391FT---- 21401FT----	
<b>AT 2078 / - N</b> AT 2078 / - C AT 2078 / - H 21391FT---- 21401FT---- ( 4806-140-170-88 )	29 PT 558, PT 838A , PT 848
<b>AT 2078 / - O</b> 21391FT---- 21401FT----	
<b>AT 2078 / S O</b> 3760 - 3 ( 4806-140-170-51 ) ( 4806-140-170-75 ) ( 4806-148-870-21 )	14 GL 1010 , 1310 , 1410 16 GL 1030 , 1330 20 GL 1040 , 1340, 1440 CHASSI GR1 - AL
<b>AT 2079 / B O</b> ( 4806-140-170-32 )	14 GL 1013, 1014, 1313, 1314, 1315 16 GL 1033, 1034 20 GL 1314
<b>AT 2079 / B 1</b> 3895-1 U 9252 UV 9239/49 ( 4806-140-170-33 )	14 GL 1033 , 16 GL 1333 20 GL 1043, 1044, 1343, 1344, 1345
<b>AT 2079 / B 2</b> ( 4806-140-170-35 )	17 BL 2022
<b>AT 2079 / B 4</b> ( 4806-140-170-38 )	14 GX 1610, 1616, 1618
<b>AT 2079 / B 5</b> ( 4806-140-170-37 ) ( 4806-140-170-83 )	20 GX 1650 / 56 / 58 / 60 21 GX 1660, 1665, 1666, 1668
<b>AT 2079 / B 6</b> ( 4806-140-170-45 )	14 GL 1015 14 GL 1316
<b>AT 2079 / B 7</b> ( 4806-140-170-46 )	& 20 GL 1045 20 GL 1346 (LER MANUAL)
<b>AT 2079 / B 8</b> ( 4806-140-170-55 )	

CÓDIGO	MODELO
<b>PHILIPS</b>	
<b>AT 2079 / B 9</b> ( 4806-140-170-59 ) ( 4806-140-170-66 ) ( 4806-140-170-81 )	20 GL 1048 , 21 GL 1369 20 GL 1049 20 GL 1349 21 GL 1639
<b>AT 2079 / B 10</b> ( 4806-140-170-61 )	14 GX 1619
<b>AT 2079 / B 11</b> ( 4806-140-170-62 )	14 GX 1619 20 GX 1659 21 GX 1669
<b>AT 2079 / B 12</b> ( 4806-140-170-58 )	14 GL 1018 14 GL 1019, 1319
<b>AT 2079 / S</b> AT 2079 / SO SR-143-3 SR-149-6 SR-2044 SR-3842-4 SR-3842-3 ( 3265-1 ) ( 3842-4 ) ( 4806-140-170-29 ) ( 4806-140-170-76 )	14 GL 1011, 1012, 1031, 1032, 1311, 1312, 1411, 1420 16 GL 1031, 1032, 1331, 1332 20 GL 1041, 1042, 1341, 1342, 1441 21 GL 1451, 1452
<b>OV 2094 (20662)</b> OV 2094 (20661)	PT 316
<b>OV 2094 / 31-8</b>	
<b>OV 2094 / 41</b> ( 4806-140-170-67 ) ( 4806-140-170-73 )	14 PT 100G/78, 14 PT 110A, 14 PT 111A, 14 PT 112 A, 14 PT 113 A, 14 PT 210 A, 20 PT 120A, 20 PT 121A, 20 PT 122 A, 20 PT 123A, 20 PT 220 A / 230A
<b>OV 2094 / 42</b> ( 4806-140-170-69 ) ( 4806-140-170-74 )	14 PT 212A, 17 PT 1511/1563 , 20 PT 222A, PT 324 20 PT 2682, 21 PT 232A
<b>OV 2094 / -A</b> 10 PINOS 08301FT---- 20662FT---- 21541FT----	20 PT 228 / 78R
<b>OV 2094 / AO - A</b>	
<b>OV 2094 / AO - B</b>	
<b>OV 2094 / AO - C</b>	
<b>OV 2094 / AO - D</b>	
<b>OV 2094 / AO - F</b>	
<b>OV 2094 / AO - G</b>	
<b>OV 2094 / AO - H</b>	
<b>OV 2094 / AO - I</b>	
<b>OV 2094 / AO - M</b>	
<b>OV 2094 / - B</b> 10 PINOS 08301FT---- 20662FT---- 21541FT----	

CÓDIGO	MODELO
<b>PHILIPS</b>	

<b>OV 2094 / B1</b> ( 4806-148-870-56 )	PT 314 / 414, 20 PT 326 A / 78 , 20 PT 424, <b>20 PT 324,</b> <b>14 PT 316 , 20 PT 524</b>
<b>OV 2094 / B1 - 1</b>	
<b>OV 2094 / B1 - 3</b>	
<b>OV 2094 / B1 - F</b> 20661FT---- 20662FT----	
<b>OV 2094 / B1 - I</b> 20661FT---- 20662FT----	
<b>OV 2094 / - C</b> 10 PINOS 08301FT---- 20662FT---- 21541FT---- ( 4806-140-170-90 )	PT 218, 20 PT 428 , <b>14 PT 418</b>
<b>OV 2094 / - D</b> 10 PINOS 08301FT---- 20662FT---- 21541FT----	(DUPLICIDADE)
<b>OV 2094 / - D</b> 11 PINOS 08231FT---- 08292FT---- 08361FT----	(DUPLICIDADE)
<b>OV 2094 / - F</b> 10 PINOS 08301FT---- 20662FT---- 21541FT----	20 PT 228A (DUPLICIDADE)
<b>OV 2094 / - G</b> 10 PINOS 08301FT---- 20662FT---- 21541FT----	20 PT 228A (DUPLICIDADE)
<b>OV 2094 / - H</b> 10 PINOS 08301FT---- 20662FT---- 21541FT---- (4806-140-170-99)	14 PT 418 A / 20 PT 5290
<b>OV 2094 / - I</b> 10 PINOS 08301FT---- 20662FT---- 21541FT----	

CODIGO	MODELO
<b>PHILIPS</b>	
<b>OV 2094 / - L</b> 10 PINOS 08301FT---- 20662FT---- 21541FT----	

<b>OV 2094 / - N</b> 10 PINOS (DUPLICIDADE) 08301FT---- 20662FT---- 21541FT----	20 PT 428 20 PT 529A / 78R
<b>OV 2094 / - N</b> 11 PINOS (DUPLICIDADE) 08231FT---- 08292FT---- 08361FT----	
<b>OV 2094 / - O</b> 10 PINOS 08301FT---- 20662FT---- 21541FT----	
<b>2437202</b> ( 4806-140-170-52)	25 GX 1888 , 29 GX 1888
<b>(4806-140-170-64)</b> 3121-218-30121 EIA 232	29 GX 1899, 1999
<b>4822-140-10609</b> ( 4822-140-10567 ) AT 2079/B13 OV 2094/50	14 PV 162, 14 PV 163, 14PV 172 PV 461 / 471 20PV471/78 CANGURU
<b>531-022-82</b> 531-022-79	29 PT 762 A
<b>CTO - L / CTO - C</b> ( 4806-140-170-22 ) ( 4806-140-170-25 ) ( 4806-140-170-56 )	& (LER MANUAL) 21 CT 7675, 21 CT 7678, 28 CT 7690, 28 CT 7692 28 CT 7693, 28 CT 7694 21 CT 7470 CHASSIS CTO - C
<b>CTO - 9 ( PINOS )</b> ( 4806-140-170-23 )	& (LER MANUAL) 14 CT 6401 , 16 CT 6010 , <b>20 CT 6035</b> CHASSIS CTO - 9
<b>NCF - 10 ( PINOS )</b> ( 4806-140-170-23 )	16 CN 4435 , <b>16 CN 4416 , 16 CN 4066</b> CHASSIS NCF - 10
<b>OV 2094 / B1 - D</b> 20661FT---- 20662FT----	20 PT 324A / 78R
<b>OV 2076 (21311)</b> 3128.138.20593 ( 2 FOCUS )	34" 34PT8419
<b>JF0501-19255</b>	14 PT 3131 , 20 PT 3331
<b>JF0501-19196</b>	PT 639 / 739 / 21PT 5431
<b>4806-140-17028</b> 3832-2/SR137	21 GR 7560
<b>JF 0501-1215</b>	

CÓDIGO	MODELO
<b>PHILIPS</b>	
<b>OV 2094 / A1-D</b>	
<b>OV 2094 / B1-8</b>	
<b>OV 2094/-H</b> (11 PINOS) 08231FT---- 08292FT---- 08361FT----	DUPLICIDADE
<b>AT 2078 / B4-2</b>	

<b>OV 2094/-O</b> (11PINOS) 08231FT---- 08292FT---- 08361FT----	DUPLICIDADE
<b>1142.5020</b> 4822.140.10525	14 GX 3516 , 14 GX 8510 , 20 GX 8550
<b>OV 2094 / B1-A</b> 20661FT---- 20662FT----	
<b>OV 2094 / B1-B</b> 20661FT---- 20662FT----	20 PT 324
<b>OV 2094 / B1-C</b> 20661FT---- 20662FT---- (4806-148-870-56)	20 PT 324
<b>OV 2094 / B1-G</b> 20661FT---- 20662FT----	
<b>OV 2094 / B1-H</b> 20661FT---- 20662FT----	20 PT 424A/78
<b>OV 2094 / B1-N</b> 20661FT---- 20662FT----	
<b>OV 2094 / B1-O</b> 20661FT---- 20662FT----	
<b>OV 2076 / - C</b> 21921FT----	
<b>OV 2076 / - H</b> 21362FT----	
<b>OV 2076 / - H</b> 21411FT---- 21421FT----	
<b>OV 2076 / - I</b> 21921FT----	
<b>OV 2094 / - A</b> 11 PINOS 08231FT---- 08292FT---- 08361FT----	

CÓDIGO	MODELO
<b>PHILIPS</b>	
<b>OV 2094 / - B</b> 11 PINOS 08231FT---- 08292FT---- 08361FT----	
<b>OV 2094 / - C</b> 11 PINOS 08231FT---- 08292FT---- 08361FT----	
<b>OV 2094 / - F</b>	

11 PINOS 08231FT---- 08292FT---- 08361FT----	
<b>OV 2094 / - G</b> 11 PINOS 08231FT---- 08292FT---- 08361FT----	
<b>OV 2094 / - I</b> 11 PINOS 08231FT---- 08292FT---- 08361FT----	
<b>OV 2094 / - L</b> 11 PINOS 08231FT---- 08292FT---- 08361FT----	
<b>OV 2094 / A1 - A</b>	
<b>OV 2094 / A1 - C</b>	
<b>OV 2094 (08292)</b>	
<b>JF 0501-2135</b>	21PT5431/5432, 25 PT 5531, 29 PT 4631 (DUPLICIDADE) , 29PT 4640 , 21HT5432 , 29HT4631
<b>OV 2076 / B2-F</b> 21411FT---- 21421FT----	
<b>OV 2076 / B3-A</b>	
<b>OV 2076 / B3-C</b>	
<b>OV 2094 / B1-L</b> 20661FT---- 20662FT----	
<b>OV 2094/-M</b> 10 PINOS 08301FT---- 20662FT---- 21541FT----	

CÓDIGO	MODELO
<b>PHILIPS</b>	
<b>OV 2094 / - M</b> 11 PINOS 08231FT---- 08292FT---- 08361FT----	
OV 2094 (08301) <b>OV 2094 / - A (10PINOS)</b> OV2094-1 (08301FT) 20662FT----	
<b>OV 2094 / A1</b>	
<b>AT 2078 / - A</b> 21321FT----	
<b>AT 2078 / - N</b> AT 2078 / - C AT 2078 / - H	

21321FT----	
<b>AT 2078 / - D</b> 21321FT----	
<b>AT 2078 / - F</b> 21321FT----	
<b>AT 2078 / - G</b> 21321FT----	
<b>AT 2078 / - I</b> 21321FT----	
<b>AT 2078 / - M</b> 21321FT----	
<b>AT 2078 / - O</b> 21321FT----	
<b>OV 2094 / AO - O</b>	
<b>OV 2094 / AO - L</b>	
<b>OV 2094 / A1 - B</b>	
<b>OV 2094 / A1 - F</b>	
<b>OV 2094 / A1 - G</b>	
<b>OV 2094 / A1 - H</b>	
<b>OV 2094 / A1 - I</b>	
<b>OV 2094 / A1 - L</b>	
<b>OV 2094 / A1 - M</b>	
<b>OV 2094 / A1 - N</b>	
<b>OV 2094 / A1 - O</b>	
<b>AT 2078 / B4 - D</b> <b>AT 2078 / B4 - M</b> <b>AT 2078 / B4 - O</b> <b>3128.138.20671</b> <b>20671FT----</b>	21 PT 534 / 78R
<b>JF 0501 - 19555</b>	
<b>JF 0501 - 19563</b>	

<b>CÓDIGO</b>	<b>MODELO</b>
<b>PHILIPS</b>	
<b>AT 2078 / - H</b> <b>AT 2078 / - D</b> 21341FT----	
<b>AT 2078 / - O</b> 21341FT----	
<b>AT 2078 / - D</b> <b>AT 2078 / - A</b> <b>AT 2078 / - B</b> <b>AT 2078 / - C</b> <b>AT 2078 / - H</b> <b>AT 2078 / - M</b> 21342FT---- 3.128.138.213.42	28PW6421 / 6431
<b>OV 2076 / AO</b>	
<b>JF 0501-21835</b>	34 PT 8419 / 78 (DUPLICIDADE)
<b>JF 0501-19272</b>	21PT5433

2422.531.026.13	
<b>JF 0501-21133</b>	29 PT 5642 (DUPLICIDADE)
<b>JF 0501-2136</b>	29 PT 5632 , 29 PT 5642 (DUPLICIDADE)
<b>AT 2078 / - C</b> 21341FT----	
<b>OV 2076 / - A</b> 21362FT----	
<b>OV 2076 / - A</b> 21921FT----	
<b>OV 2076 / - B</b> 21362FT----	
<b>OV 2076 / - B</b> 21921FT----	
<b>OV 2076 / - C</b> 21411FT----	
<b>OV 2076 / - C</b> 21421FT----	
<b>OV 2076 / - D</b> 21362FT----	
<b>OV 2076 / - D</b> 21921FT----	
<b>OV 2076 / - F</b> 21362FT----	
<b>OV 2076 / - F</b> 21921FT----	
<b>OV 2076 / - G</b> 21362FT----	
<b>OV 2076 / - G</b> 21921FT----	

CÓDIGO	MODELO
<b>PHILIPS</b>	
<b>OV 2076 / - L</b> 21362FT----	
<b>OV 2076 / - L</b> 21921FT----	
<b>OV 2076 / - M</b> 21362FT----	
<b>OV 2076 / - M</b> 21921FT----	
<b>OV 2094 / - A</b> 08351FT----	
<b>OV 2094 / - B</b> 08351FT----	
<b>OV 2094 / - C</b> 08351FT----	
<b>OV 2094 / - D</b> 08351FT----	
<b>OV 2094 / - F</b> 08351FT----	
<b>OV 2094 / - G</b> 08351FT----	
<b>OV 2094 / - H</b>	

08351FT----	
<b>OV 2094 / - I</b> 08351FT----	
<b>OV 2094 / - L</b> 08351FT----	
<b>OV 2094 / - M</b> 08351FT----	
<b>OV 2094 / - N</b> 08351FT----	
<b>OV 2094 / - O</b> 08351FT----	
<b>OV 2094 / B1- J</b> 20661FT---- 20662FT----	
<b>OV 2094 / B1 - M</b> 20661FT---- 20662FT----	
<b>PWL13 - B</b> 08411FT----	20PT 3331 / 20PT 4331
<b>PWL 13 - C</b> 08412FT----	
<b>PWL 13 - D</b> 08412FT----	
<b>PWL 13 - G</b> 08411FT----	PT 3496
<b>PWL 13 - H</b> 08412FT----	

CÓDIGO	MODELO
<b>PHILIPS</b>	
<b>PWL 13 - I</b> 08411FT----	
<b>PWL 13 - M</b> 08412FT----	
<b>PWL 13 - N</b> 08411FT----	
<b>PWL 13 - O</b> 08411FT----	
<b>OV 2076 / B2 - I</b>	29 PT 554A / 78
<b>KF 58383P</b> 4822.140.10469	29 SX 8674 / 29 SX 8878/79 29 PT 758 / 78
<b>AT2078 / 21391FT</b>	29 PT 338
<b>1142.5093D</b> 2422.531.02323	14 PT 519 20 PT 529
<b>JF 0501-8604</b> 2422.531.00047	29PT4635 / 29PT 4643
<b>JF 0501-19321</b>	
<b>JF 0501-19323</b>	TPF 2130
<b>PWL - 15</b> 34111	
<b>OV 2076 / - I</b> 21421FT----	
<b>OV 2076 / - O</b> 21921FT----	

<b>3104 308 20831</b> 13929004G	36PW8521 36PW9818
<b>8228.001.3476.1</b>	
<b>OV 2076</b> 21041 21041FT----	37PT 786/78
<b>JF 0501-19865</b> 2422.531.00114	14PT3336 20PT3336
<b>OV 2076 / B2-I</b> 21411FT----	
<b>OV 2094 / AO - N</b> 08231FT----	
<b>JF 0101 - 85038</b> 2422.531.00067	TELA PLANA 32PW8422
<b>JF 0101 - 85040</b> 2422.531.00069	29PT8422, 34PT8422
<b>AT 2078 / - L</b> 21321FT----	
<b>AT 2078 / - L</b> 21391FT----	
<b>OV 2076 / B3 - F</b>	
<b>PWL 13 - A</b> 08411FT----	

CODIGO	MODELO
<b>PHILIPS</b>	
<b>13620004C</b> 2422.531.98025	28PW6521, 28PW6816 , 32PW878A
<b>OV 2076 / - N</b> 21921FT----	
<b>JF 0501-21139</b> TFB 4210AJ	
<b>4086.440.170.91</b> 00.368.026-0001	33PT670
<b>JF 0101-85021</b>	32 PW6542 / 28 PW6542
<b>R C A, GE, ROADSTAR</b>	
<b>154-387 B</b>	RBA 2020
<b>FCV 2010E10</b>	TVC - 20
<b>2 G 25026</b> (316 / B1G / B2F)	RCA - CTC 186 A, F 20637N, F 20638N, F 29632N GE - 25G542
<b>2 G 25028</b> ( B1B ) T 4401 - 1HVT PROSCAN	RBA 33691 , RBA 33693 <b>RBA 29551</b>
<b>JF 0501-1901</b> DCF 980702-BC	ROADSTAR - K 9780
<b>PN 2G 25027</b> 2G25027-A3D	RCA - RBA 29551
<b>JF 0208 - 0208C</b>	ROADSTAR - K-9730
<b>@ FCV 2010E09A</b> 230934	RCA - RBA 1420
<b>SAMSUNG , SEMIVOX</b>	
<b>FCM 1411 L 01</b> FCM 1415 AL TLF 70018F	CB 336F CN 3313 Z, 3315, 3315 Z, 3316, 3329 Z, 3352Z, 3355 Z, 3357 3361, 3552 Z, 5029 Z, CB 336F

<b>FC 1412</b>	TS - 14C1R ( Vide Equivalente First Line - KY-01 )
<b>FCK 14 A 022</b>	SEMIVOX
<b>FCK 14 A 028</b>	SEMIVOX ( Vide Equivalente Baysonic - BY - 01 )
<b>FCK 14 A 033</b>	TV SAMSUNG CN 3338V / 3339 VB - CINERAL
<b>@ 154-177 J</b>	MAT 5352 E (Vide Eq.Gradientes - GT-02/ Goldstar - GD-02 / LG-02 / Philco-PC-04)
<b>@ 154-375 A</b>	( Vide equivalente Goldstar - GD-05, Gradiente - GT-04, LG-04 )
<b>@ 154-375C</b>	( Vide equivalente Goldstar - GD-06, LG-05 )
<b>FSV 20 A 001</b> AA 26-30004H FSV 14 A 001	CN 331, 501, CN 3348, 5038, 5039, 5048, 5066
<b>X FSV 20 A 001 / 27</b>	TXB 2535 / 2735

CODIGO	MODELO
<b>SAMSUNG , SEMIVOX</b>	
<b>FCG 2045 AL</b>	20 CB 534 V / 563Z , CN 5322 CN 5029, 5029 V, 5029 W
<b>FCM 20 A 015</b>	CN 5062, 5062 V, 5062 W CN 5083, 5083 V, 5083 W CN 5314, 5314 V, 5314 W
<b>FCM 20 A 023</b>	CN 5055 Z
<b>FSV 20 B 012</b>	( Vide Equivalente Cinerall - CN-03 )
<b>FCM 20 B 057</b>	SEMIVOX - TS 14C2R , TS 20C2R
<b>FCM 2014 FL</b>	CN 3329 V, 3338 V, 3362 V, 3383V , <b>HPS 14 (CCE)</b>
<b>@ FCM 2015 CL</b> TLF 70018A	( Vide Equivalente CCE-27)
<b>FCM 2015 ML</b> FA 2040 KFS 60769	CN 5013 Z
<b>FA 2017</b>	TS - 20C1R ( Vide Equivalente First Line - KY-03 )
<b>FTH 29 A 001</b>	CN 7202 WB, CN 7207, CN 723
<b>FTR 29 A 003</b> AA26-30002B	CN 7266
<b>FCZ 29 A 006 A</b>	29" CN 721
<b>o FTH 29 A 013 S / P</b> <b>X FTK 14 R 005 C</b>	SAMSUNG - 14" e 20"
<b>oo FTH 29 A 013 S / G</b> <b>X</b>	29 CN 765
<b>FCR 29 A 014 R</b>	CN 7226 W, CN 7230
<b>FTK 20A007P</b>	TV + VCR CANGURU MVR-4190M
<b>FCR 25A006R</b>	SAMSUNG - TXB 2525 / TXC 2516 / CN 2516
<b>FD 2139</b>	SEMIVOX - (JKR) TS-25C15
<b>FUH 29M002</b>	SAMSUNG - CL34V6PQ , CN34V6PQ , CL34Z6PQ
<b>FFA 61012K</b> FFA 61012L	SAMSUNG
<b>FUH 29A001F</b>	SAMSUNG
<b>FSV 20B001</b>	SAMSUNG
<b>FUH 29A001G</b>	SAMSUNG
<b>FOK 14B001</b>	SAMSUNG - CL21M21

<b>FUH 29V003</b>	SAMSUNG
<b>FCA 173 / AA26-00201A</b>	SAMSUNG - CL21M6MQ
<b>FQH 21A001</b>	SAMSUNG
<b>FUH 29A001V</b>	SAMSUNG
<b>FCK 1415EL</b>	SAMSUNG - DX 1332
<b>FSV 20B018</b> 3220045	SAMSUNG
<b>FUH 29V006</b>	SAMSUNG
<b>FUH 29V001</b>	SAMSUNG
<b>FUH 29V007B</b>	SAMSUNG - RETRO
<b>FCK 1415AL</b>	SAMSUNG - M3105
<b>FCM 20A025</b>	SAMSUNG - CXB 1922
<b>FCR 25A001</b>	SAMSUNG - 25 CN 6229W
<b>FOK 14A001</b> AA26-00231A	SAMSUNG
<b>FSV - 14A004 H(S)</b>	SAMSUNG

<b>CÓDIGO</b>	<b>MODELO</b>
<b>SANYO</b>	
<b>FDA 006 N</b>	CTP 3765, 3766
<b>FDA 007 N</b>	CTP 6765 V, 6766 V
<b>FD 0059</b> AC 30050	CTP 3750, 3751, 3752, 3755, 4751
<b>FD 0060</b> AC 30051	CTP 6750, 6751, 6752, 6753, 6755, 6755V-D4KM
<b>FD 0108</b> AC 30052	CTP 3756-V-00
<b>FD 0109</b> AC 30053	CTP 6756-V-01
<b>FD 0181</b>	CLP 2128, CLP 2127
<b>F 1175 - 76</b>	CTP 3720, 3721, 3722, 6720, 6721, 6722
<b>FD 125</b>	CTP 3770, 3771, 3780, 3781 CLP 1451
<b>FD 187</b> L 40 B 03900	CTP 6050, 6051, 6770, 6771, 6780, 6781 CLP 2151
<b>L 40 A 00100</b>	CTP 3790, 3791
<b>L 40 A 00700</b> L 40 A 00710 L 40 A 00711	C 29 LH 43 B , 2997 C 33 LJ 43 B 00 C 3396
<b>L 40 B 00300</b>	
<b>L 40 B 02510</b>	
<b>L 40 B 05500</b>	CTP 6790, 6791, 6792 (20polegadas), 6796
<b>L 40 B 05700</b>	C 2796, 2996, C 29F5 AD
<b>L 40 B 00400</b> 1LBL40B00400	
<b>SEMP (VIDE TOSHIBA)</b>	
<b>SHARP</b>	
<b>F 005ME</b>	29" C 2999
<b>F 0017</b> F0017 MESA / MQBD	C 29 ST 54 ( COM BOBINA NO FERRITE ) <b>FRST LINE 29FL10</b>
<b>F 1232</b> ( Z 4034 ) 14 "	C 1402, 1404, 1417 A, 1425, 1460, 1480, 1484
<b>F 1250</b>	C 1604, 1615, 1616, 1625, 1660, 1665, 1686, 1690

( Z 4035 ) 16 "	
<b>F 1251</b> ( Z 4036 ) 21 "	C 2011, 2015, 2016, 2018, 2025, 2028, 2029, 2060 C 2086, 2090, 2181, 2186
<b>F 1562</b> ( Z 4086 )	C 1425 B, 1426 B, 1430 A, 1465 B, 1487 B, 1490 A C 1425 A
<b>F 1563</b> ( Z 4085 )	TVC 1625, 1626, 1630 A, 1665, 1687, 1690
<b>F 1564</b>	C 2025, 2026, 2030, 2090 "A", <b>2030 A</b>
<b>F 1693 (Z 4183)</b>	C 1492 H, 1626, 1630, 1631, 1665, 1690, 1694
<b>F 1694</b>	C 1426, 1427, 1430, 1431, 1491 B, <b>1410, 1410 B, 1450 B</b>
<b>F 1802</b>	C 2877 B, 2899 A
<b>F 1833</b> ( CE- 00066 )	C 3399

CÓDIGO	MODELO
<b>SHARP</b>	
<b>F 1881</b> F 1890 F 1952	C 1413, 1453, 2013, 2017, 2018H, 2053
<b>F 1894</b>	C 1482, C 1485, <b>1482 B, 1485 B</b>
<b>F 1901 ( C )</b> FOCO Z 4175 154-207R / S	C 2040, 2041, 2082, 2188, 20 R 11, 20 R 12, 20 S 01 C 20 S 02, 20 T 51, 2052, 2053, <b>2092 B</b>
<b>F 1923</b>	C 1413, 1440, 1440B, 1452B, 1453, 1467B, 1482B, 1485B, C 14R12, 14RS02, 14RS03, 14T51, <b>14S02</b>
<b>F 1998 CE ( G )</b>	C 1453 / 1457 / 14 ST 57 / 1417 DUPLICIDADE
<b>F 2005 CE ( H )</b>	C 1438, 2038, 2057, 20 ST 57, 20 ST 58
<b>F 2023 ( E )</b> 6174Z-6279X	C 29 ST 58 / 29 ST 98
<b>F 2092</b>	C 1470 B, 1626, 1630 H, 2010, 2027, 2030 H, 2035, C 2050, 2070, 2090, 2092, 2092 H, 2097, 2199, <b>1412B</b>
<b>TAT 14101A</b> TATS 14101A	(Vide Equivalente CCE - 60)
<b>SONY</b>	
<b>1-439-311-32</b>	KV 1449 AV
<b>1-439-416-21</b>	KV 29 XTR 300 / TR 3
<b>1-439-416-41</b>	KV 29 XTR 20 / 30, KV 2553 BM / MT
<b>1-439-416-61</b>	KV 2114 S, KV 2127 R, KV 2137 RS, KV 2161 S, KV 2110 GM
<b>1-439-418-31</b> 1-439-429-11	KV 2940 BM KV 2945
<b>1-439-421-11</b>	KV 1483
<b>1-439-421-41</b>	KV 1440 B, KV 1441 B, KV 2163S
<b>1-439-421-51</b>	16" e 20" KV 2160 B
<b>1-439-423-11</b>	KV 2102, KV 2500, 2114, 2123, 2133, 2134, 2153
<b>1-439-423-21</b>	KV 20EX10, KV 29TR20, KV 2553BM
<b>1-439-423-31</b>	KV 29*TR30
<b>1-439-423-32</b>	KV 27 EXR 20, KV 29XTR30
<b>1-439-423-41</b>	KV 20TS27
<b>1-439-423-51</b>	KV 2161
<b>1-439-454-11</b>	KV 27ASR10 / iS
<b>1-439-455-11</b>	KV 27XBR15 / BR65
<b>1-439-498-71</b>	KV 2955, KV 2959, KV 3459, KV 27V15, 29 V 15 STR, KV 29 V 55, KV 32 TS 35, 32XBR45, 32S10, 34 V 55

1-439-498-12 1-439-498-21	Modelos importados até o ano de 1994 c/ potenciômetro de foco, "32" 32V15
<b>1-439-520-11</b> 1-453-126-11	KV 32 XBR96S , <b>KV 32 S 26</b> KV 35 V 35 , KV 35 V 36
<b>1-453-141-21</b>	
<b>1-453-142-11</b>	KV 2163S
<b>1-453-142-21</b>	KV 2160 , <b>KY 14MTR1</b>
<b>1-453-146-11</b> 1-453-146-21	KV 27 S 10, 27 S 15, 2959T, 29 RS 10, 2970, 32S16, 32 TS 36

CÓDIGO	MODELO
<b>SONY</b>	
<b>1-453-207-11</b>	& KV 2970 T, KV 32S22 , 3470, KV 3470 T, KV 32S45 NX 2609 (LER MANUAL)
<b>154 - A 51 J</b>	KV 2DVM - 3P ( TV + VCR )
<b>AT 2078 / UO - 1</b> AT 2078 / UO - 2 ( 1-453-208-11 )	KV 1450 B ( Cinesc. Samsung ), KV 2158, 2172 S KV 2170 B, KV 2173 S, KV 21 B 80 , KV 21 VH5BR <b>KV 2159 , KV 21S85</b>
<b>AT 2079 / UO</b>	& KV 1450 (Obs: Sem potenciômetro de Focus Screen)(LER MANUAL)
<b>AT 2079 / U1</b> ( 1-453-209-11 )	KV 1450 B (SOMENTE P/ CINESCÓPIO SONY) KV 14B80 / KV 14VM5BR OBS: CASO SEJA CINESCOPIO SAMSUNG NAO SERVE
<b>AT 2079 / U2</b> ( 1-453-216-11 ) ( 1-453-217-11 )	KV 140 MG KV 200 MG KV 205 MP
<b>8-598-834-20</b> 8-598-834-10	KV 29FS12, KV29FV15B, KV29V15, KV29V15B, KV29FV16B, KV 29V16B, KV29FV100,KV29FS100,KV29FA21,KV29FS12B ( <b>DUPLICIDADE</b> )
<b>8-598-838-40</b> 1.453.316.11 8.598.838.41	KV 21 FE 12 B
<b>8-598-850-00</b>	KV 25 FV 10 B
<b>8-598-922-00</b> ( 1-453-188-11 )	KV 21 XTRI, KV 2152, KV 2158, KV 2159, KV 2162 , KV 2163
<b>8-598-928-01</b>	KP 41 PT 15 B ( TELÃO ), KP 53XBR45
<b>8-598-969-00</b>	NX 2609, KV 2970 T, KV 3470, KV 3470 T , HV 2090 T
<b>8-598-976-00</b>	KV 29 VX 2, KTV - 33T80, KV 34T80
<b>8-598-998-00</b> 8-598-998-03	KV 29 T 75, KV 29 T 76 , 29T80 (NX 4005) KV 27V66 (IMPORT.)
<b>8-598-828-00 / 20</b>	KP 53XBR200/BR300 / KP 57XBR600 / KP 57WV600 / KP 61XBR200
<b>1-453-310-11</b>	KV 29FV16B / KV 29FV30 / KV32FV30 ( <b>DUPLICIDADE</b> )
<b>1-453-338-31</b> 1-453-338-21	KV 29FS100 / KV 32FV30 ( <b>DUPLICIDADE</b> )
<b>1-439-452-11</b> 1-439-533-11	
<b>AT 2078 / UO - 4</b> 08111FT----	
<b>8-598-824-10</b>	KV 34 FV 15 B / KV 38 FV 15 B
<b>8-598-994-00</b>	TELÃO - KP 61V85
<b>1.439.502-11</b> 1.439.498-31 1.439.502-31	KV 27TS27 KV 32TS53
<b>1.453.524-11</b>	
<b>1.453.147-21</b> 1.453.149-21	
<b>1.453.336-11</b>	

1.453.189-11	
8.598.939-00	
1.453.267-11	
1.439.456-11	KV 32XBR15

CÓDIGO	MODELO
<b>TALENT</b>	
<b>154-279C / JF0101</b>	29" TVP 9229
<b>TELEFUNKEN</b>	
<b>@ FCV 1410 E 06</b> ( 571 395 001 902 ) FCV 1411	14 C 5170 ( Vide equivalente Gradiente - GT-01 )
<b>@ FCV 2010 E 02</b> ( 571 391 001 902 ) FCV 2011	20 C 5170 ( Vide equivalente Gradiente - GT-05 )
<b>@ DCF 2077</b> DDF 9802A KFS 61115	AV 135 (Vide Equivalente CCE-28, Paxan e Precision - PX - 03, Philco - PC - 07 )
<b>AT 90 / 7 pinos</b>	Chassi: CH 801, 802, 802A
<b>AT 90 / 11 pinos</b>	Chassi: CH 841
<b>TOSHIBA</b>	
<b>AT 2079 / AO</b> AT 2079 / A2 AT 2079 / A3 (TFB 4067) (TFB 4125 DD) (TFB 4125 DS)	TV 147, 204, 207, 209, 14 A 76 MU, 14 A 82 EAV, 147 CR TV 20 A 76 UM, 20 A 77SU, 20 A 82, 1022 EAV, 1455, 1458 S TV 1474 AMU, 1483 AAV, 2055, 2058 S, 2066 SU, 2078 AMU TV 2079 ASU, 2083 AAV, 2175 CSU, 2987 CSU, 2998CSU TVM 1466 MU, 1467 SU, 2066 U, 2067 MU, 2067 SU, 2082 BAU TVS 1456 M, 1457 M, 1457 S, 1458 S, 1459 ST, 1466 MU TVS 1466 SAP, 1468 U, 1482 EAV, 2056 M, 2057 M, 1480/1484GAV TVS 2057 S, 2058 S, 2066 MU, 2068 U, 2082 M, 2083 BAW / 2084 TVS 2175 SU, 2175U. TS 149CR, 209CR, 2070, 2070E
<b>AT 2079 / A1</b>	& TVC 102 (Modelo novo, não é compatível c/102 TR (antigo)/ 1021 / 1022 ( Vide NF 7305 ) (LER MANUAL)
<b>OV 2094 / AO</b> OV 2094 / AO 08231 FT ----	TV 1484, 1491, 2084HAV
<b>B 32 - 3416</b>	TVC 10 ILX (DUPLICIDADE)
<b>B 32 - 3423</b>	TVC 100
<b>TFB 4029 AD</b>	CF 2051 A
<b>TFB 4030 AD</b>	3466 P / 3486 P
<b>TFB 4034</b>	TS 140, 141, 142, 161, 201, 202, 204, <b>207VS CR / TVC 165</b> <b>TVC 145 - CR / TVC 160 / TVC 164 / TVC-208VS</b>
<b>TFB 4048 BD</b> TFB 4065	TS 147, 147VS-CR, 167, 167 CSCR, 207, VS / 2, TS 168 VC-145VS-A TVC 205, 206 VS
<b>TFB 4059 AD</b>	TVC 206 VS - SÉRIE F, TVC 3064 / 3485P
<b>TFB 4062</b>	TS 287
<b>TFB 4069 AD</b>	210R6B, 215R8F, 259D9B
<b>TFB 4086</b> TFB 4087	TS 2889F, TS 285 ST / PIP TS 289 ST
<b>TFB 4100 AD</b>	2985 S / 2996-S (DUPLICIDADE)
<b>TFB 4121 BD</b>	TV 2986 S, 2996 S (DUPLICIDADE)
<b>TFB 4126 BR</b> TFB 4126 AE TFB 4126 CS	TV 1484, 2078 FM, 2079 FMS, TV 2083 FAV E 14", 2084HAV TV 2089H / 2090 i TV 2096ST / GMS / HMS / TV 2088 I / LUMINA NOVA

TFB 4203 AJ FUY 202011 JF 0501-2417	
<b>TFB 4127 RE</b>	TV 10R22EA, 1022BAV, U8, U9
<b>TFB 4129 AD</b>	2966 S

CÓDIGO	MODELO
<b>TOSHIBA</b>	
<b>TFB 4130 AD</b>	3466P, 3486P , <b>CE 36G18</b>
<b>TFB 4131 DD</b>	2987 SU, 2997 SU, 2997 P
<b>TFB 4132 DH</b> TFB 4132 CD TFB 4132 DD TFB 4132 ED	TV 2987SU, 2997P, 2997SU 29A87, 29A97SU, 34A88P, 34A88SU TV 3488P, 3888P
<b>TFB 4134 AE</b> TFB 4134 AB	TV 1478 FM, 1483 FAV , TV 2080 E, 1488 FMU11
<b>TFB 4151 AD</b> TFB 4151 BE TFB 4151 BH	2987 CS, 2987 CSU, 2987 DS, 2998 CS, 2998 CSU
<b>NF 7304 ST</b>	& TVC 100 (DUPLICIDADE) (LER MANUAL)
<b>NF 7305</b>	TVC 10, TVC 100CR , 102 TR (Modelo Antigo)
<b>KF 7414</b>	& TVC 10 i L (LER MANUAL)
<b>TFB 4118 ZD</b>	29 BC 55 , 29 S 55 ST , CN 35 D 90
<b>TFB 4099 AD</b>	TVC 3064 , TVC 3485 , TVC 3485P
<b>TFB 3058B</b>	6"
<b>TFB 4156AD</b>	2955 DFP / 2956 DFP / 3455 DFP
<b>TFB 4210AH</b> TFB 4198AH BW 03041	TV 2987 IMS / 2981 JAVS CHASSIS 5 e 6 TV 2999 CHASSIS LEN4-LEN5
<b>TFB 4182 AH</b> BW02702	TV 2957 FOCO DUPLO
<b>TFB 4192 AS</b> FMX 32A001	TV 2958 / TV 3489

**ZENITH / GE**

<b>@ FCV 2010 E 09A</b> 230934	RDA 1420 ( Vide Equivalente Gradiente - GT-06 ) <b>14 GE 00</b>
<b>9504372</b>	CHASSIS: SAR, SAY e SAM - 2053 C222BT - 20 Polegadas, SAM 21494 , 2153 BT - 21 Polegadas / 2953 BT - 29 Polegadas/ 3453 BT - 34 Polegadas
<b>95-4134-15</b>	PUY 5263DT , PVR 5263 - 4660 , PVR 6069 , PVY 6069
<b>95-4134-01</b>	FR 3547DT / SY 3581DT / (FR-3587BT : NÃO É UTILIZADO FOCUS SCREEN)
<b>95-4134-07</b>	38"
<b>95-4134-11</b> EIA 343	& SR-3547 DT (LER MANUAL) PZR 5263DT
<b>95.4438</b> FEC 22	
<b>A 17196 - 12</b> DIVISOR DE FOCUS	RETROPROJETOR 60" (LER MANUAL) (COLOCAR VENTUINHA)

**FLIPERAMA / ESPECIAIS**

<b>154 - 168 G</b>	FLIPERAMA / VIDEO GAME / VIDEO BINGO
<b>KFS 60291</b>	FLIPERAMA / MÁQUINA FOTOGRÁFICA NEOPRINT
<b>3121.218.30121</b>	FLIPERAMA / VIDEO GAME / VIDEO BINGO

**DIVERSOS**

<b>43-73-1001B</b>	
<b>FCK 14 A 032</b>	
<b>MSU1FVG213</b>	CCE
<b>154-279R</b>	CCE
<b>CF-33661</b>	

**FOCUS SCREEN**
**MAGNETRON**

<b>2M319K / WBL13H</b>	MAGNETRON PARA MICROONDAS - SAMSUNG 2M219K / 2M319K / 2M210-M1 / OM75P(31) / OM75S(31)
<b>2M219H / WBL13E</b>	MAGNETRON PARA MICROONDAS 2M167B M-16 / 2M167B M-147 / 2M240H / 2M210 M-62
<b>2M219J</b>	MAGNETRON PARA MICROONDAS 2M2169J
<b>2M319J / (2M213)</b>	MAGNETRON PARA MICROONDAS OM75D(10) / 2M172A / 2M213 / 2M214 / 2M218J / 2M246 / 2M319J

**TV / MONITOR DE SEGURANÇA PEQUENO**

<b>6174V - 8004 A</b> 6174V - 8004 D 6174V - 8005 C 570007001908	GRADIENTE - MONITOR DE SEGURANÇA SM-14 / CFTV / CFTV SM-20
<b>BSH-7</b>	
<b>BSH-12N05D</b>	
<b>BSH-13</b>	
<b>BSH-14N304L</b>	
<b>6174Z-6012Q</b>	GRADIENTE 29" MI