

Mentor II Size 1
Plastics and Accessories

Replacement Parts
CTPL# 022



(1)
Mentor II Keypad
PN: 3617-0002-01
Replacement Instructions
CTRI215


(2)
Top Cover
PN: 3582-0201-00

(3)
Access Cover
PN: 3582-0202-00

(4)
Base
PN: 3810-0016




(5)
Fans
PN: 3251-2408
Replacement Instructions
CTRI225



Mentor II Size 1

Mounting Brackets



(6)

Small Mounting Bracket

PN: 6431-0376

2 per kit bag

(7)

Medium Mounting Bracket

PN: 9500-5035

(8)



Large Mounting Bracket

PN: 9500-5035B

Drive	Quantity
M25 or M25R	2 (Small)
M45 or M45R	2 (Small)
M75 or M75R	2 (Small)
M105 or M105R	1 (Medium), 1 (Large)
M155 or M155R	1 (Medium), 1 (Large)
M210 or M210R	1 (Medium), 1 (Large)

TOP SECTION

(9)
MDA1 CPU
PN: 9200-0784




(10)
Ribbon Cable
3471-0207-06


(1)
MII Keypad
PN: 3617-0002-01
CTRI 247



(2)
Top Cover
3582-0201-00
CTRI 247



(11)
MDA2B*
9200-0782



* There are variations to this board that might need to be discussed with a technician (examples MDA 2, and MDA2B).

(12)
MD29**
Repair Only
9200-0896



No Availability


** There are variations to this board that might need to be discussed with a technician (examples MD29AN, and custom program variations-see paper label on large IC)

(3)
Access Cover
3582-0202-00




POWER BOARD SECTION

(13)
MDA75R Power Board
 P/N 9200-0620




Mentor II
M25R
M45R
M75R


(14)
Supply Fuses
 3707-601000




(15)
MDA75 Power Board
 P/N 9200-0624



Mentor II
M25
M45
M75



(16)
MDA210R Power Board
 P/N 9204-0555




Mentor II
M105R
M155R
M210R

(17)
Spike Absorber
 MOV




(18)
MDA210 Power Board
 P/N 9200-0619



Mentor II
M105
M155
M210


BOTTOM SECTION



(19)
Current Transformer
P/N 3225-2030-08



(20)
Thermistor
P/N 1310-2269-06
CTRI 246



* **Mounting
Brackets**



(4)
Base
P/N 3810-0016



(21)
**MDA3 Field
Regulator**
Repair Only
P/N 9290-0059




(5)
Fans
P/N 3251-2408
CTRI 225



**** SCR**

Item Number	Drive	Part Number
22	M25 {R}	2435-2716-01
23	M45 {R}	2435-4216-01
24	M75 {R}	2435-9216-01
25	M105 {R}	2435-3132
25	M155 {R}	2435-3132
25	M210 {R}	2435-3132



**** SCR's**

See the next page to place a quote order.

Request for Quote Order Form

Mentor II Size 1

Item number *	Part Number	Part Description	Quantity
1	3617-0002-01	Mentor II Keypad	
2	3582-0201-00	Top Cover	
3	3582-0202-00	Access Cover	
4	3810-0016	Base	
5	3251-2408	Fans	
6	6431-0376	Small Mounting Bracket	
7	9500-5035	Medium Mounting Bracket	
8	9500-5035B	Large Mounting Bracket	
9	9200-0784	MDA1 CPU	
10	3471-0207-06	Ribbon Cable	
11	9200-0782	MDA2B*	
12	9200-0896	MDA29** No Availability - Repair Only	
13	9200-0620	MDA75R Power Board	
14	3707-601000	Power Supply Fuses	
15	9200-0624	MDA75 Power Board	
16	9204-0555	MDA210R Power Board	
17	2482-2951	Spike Absorber MOV	
18	9200-0619	MDA210 Power Board	
19	3225-2030-08	Current Transformer	
20	1310-2269-06	Thermistor	
21	9290-0059	MDA3 Field Regulator No Availability - Repair Only	
22	2435-2716-01	M25 and M25R SCR	
23	2435-4216-01	M45 and M45R SCR	
24	2435-9216-01	M75 and M75R SCR	
25	2435-3132	M105 - M210 SCR	
25	2435-3132	M105R - M210R SCR	

*Refer to photograph

Please print your information below

Name	
Company	
Street address	
City	
State/Province	
Zip/postal code	
Phone number	
Fax Number	
E-mail address	

Call us Toll Free **1-800-367-8067** and ask for Replacement Parts

or **FAX** using the form above to **716-774-8327**