

Welding Positions


FLAT

HORIZONTAL


VERTICAL

OVERHEAD

Fillet Weld



1F



2F




3F




4F


Groove Weld




1G



2G



3G



4G

LINCOLN[®]
ELECTRIC