


Even the best machine needs a tune-up once in a while to keep producing at top capacity!



Fine-tune your Whitney punch/plasma with the least amount of downtime...and the smallest amount of shop floor interruption.

Schedule an MPA (Machine Performance Audit). A trained Whitney technician inspects your machine and provides a roadmap to increasing and maintaining your accuracy and productivity.

Services performed:

- Verification of full punching tonnage, punch and die alignment and hydraulic system set-up.
- Inspection of punching cylinder and bolster assemblies.
- Inspection of all axes components including ballscrews, ways, bearings blocks and workclamps.
- Checks for proper functioning of all plasma system components.
- Test and verification of all axes overtravels.
- Testing of all safety systems.
- Review of preventive maintenance procedures, machine problem log and maintenance and operator skill levels.
- Review of spare parts inventory.
- Includes (8) hours at facility with (2) hours dedicated to answering Operator, Maintenance and Programmer questions (2 hours of machine down-time required).

You receive a written report detailing maintenance or repair recommendations, required parts and an estimate of hours to complete the work.

Additional savings:

- **10% discount** on replacement or repair parts.
- **20% discount** from current service rates on additional days labor.
- **NO CHARGE** for travel time to and from your facility – or the (8) hours on site!

Contact Whitney today to find out how a small investment pays off with big results for your company.

Whitney Technical Support

7 a.m. - 5 p.m. Central Standard Time: 815-490-0473

After Hours Support Line*: 815-490-0455

Whitney Parts & Tooling Sales: 800-435-2823

Email: service@wawhitney.com

* Charges may apply

 **Megafab™**
PIRANHA · WHITNEY · BERTSCH

650 Race St. • P.O. Box 1206 • Rockford, IL 61105, U.S.A. Proud

Tel: 1-800-338-5471 • E-mail: sales@megafab.com

www.megafab.com

