


Owner's Manual & Safety Instructions

Save This Manual Keep this manual for the safety warnings and precautions, assembly, operating, inspection, maintenance and cleaning procedures. Write the product's serial number in the back of the manual (or month and year of purchase if product has no number). Keep this manual and the receipt in a safe and dry place for future reference.

CENTTECH®

ITEM 60332

1000 GRAM DIGITAL SCALE



Visit our website at: <http://www.harborfreight.com>
Email our technical support at: tech@harborfreight.com

When unpacking, make sure that the product is intact and undamaged. If any parts are missing or broken, please call 1-800-444-3353 as soon as possible.

Copyright© 2012 by Harbor Freight Tools®. All rights reserved.
No portion of this manual or any artwork contained herein may be reproduced in any shape or form without the express written consent of Harbor Freight Tools. Diagrams within this manual may not be drawn proportionally. Due to continuing improvements, actual product may differ slightly from the product described herein. Tools required for assembly and service may not be included.

⚠WARNING

**Read this material before using this product.
Failure to do so can result in serious injury.
SAVE THIS MANUAL.**

Specifications

Max. Capacity	1000 grams
Measurement Units	grams, ounces, grains, pennyweights, troy ounces, and carats
Accuracy	±0.1 gram
Automatic Shut-off	60 seconds
Power Source	2 “AAA” Batteries (included)

Important Safety Information

1. Position batteries in proper polarity and do not install batteries of different types, charge levels, or capacities together.
2. This Scale is not a toy. Do not allow children to play with or near this item.
3. Weight readings are for household use only. Do not use for commerce or trade.
4. Inspect before every use; do not use if parts are loose or damaged.
5. Place Scale on flat, stable, level surface.
6. Sensitive instrument. Do not drop, bump, or shake Scale.
7. Do not exceed Scale's capacity.

Display



Figure A: Startup Screen

hold - Indicates that the reading is stable.

tare - Indicates that tare weight is factored out. Press **TARE** with empty container on Scale to set the Scale to ignore container weight and display content weight only.

zero - Indicates that the Scale has nothing on its platform, and is at its neutral position.

pcs - Indicates that scale is in piece count (custom weight unit) mode.

See *PCS mode* for explanation.

g/oz/ct/ozt/gn/dwt - Indicates weight unit. Press **MODE** to cycle through weight units.

Operation

NOTE: Do not use Scale for commerce or trade.

1. Place the Scale on a flat, hard surface.
2. Remove the cover.
3. Press the ON/OFF button once. The Scale will display everything while starting up - see **Figure A: Startup Screen**. When the Scale shows **zero 0.0g** it is ready for use.



Figure B: Scale ready

Note: If battery is low, Lo (Low Battery) will be shown. See Figure C.



Figure C: Low Battery

To Replace Batteries:

- a. Open battery cover, remove old batteries and dispose of them properly.
 - b. Install 2 new "AAA" batteries according to proper polarity and close cover. Do not install batteries of different types, charge levels, or capacities together.
4. Press **MODE** to cycle through weight units. Current weight unit is displayed on the right of the display.

5. **TARE mode:**

To set the Scale to ignore the weight of a container and weigh only contents, place empty container on Scale and press **TARE**.

tare will be displayed and the Scale will ignore the container's weight. Remove container and press **TARE** again to cancel **tare** mode.

6. **PCS mode:**

This mode is used to count small objects. To get an accurate count, it is essential that the objects all weigh the same. To set up PCS mode:

- a. Place 25, 50, 75, or 100 quantity of the objects on the scale.
 - b. Press and hold **PCS** for 3 seconds.
 - c. Press **MODE** to match the quantity of objects on the scale. Available numbers are 25, 50, 75, and 100.
 - d. Press **PCS** to confirm the quantity. **pcs** will be displayed.
7. Gently place item to be weighed on the center of the platform. The weight (or quantity of objects for **pcs** mode) will appear on the display.

Note: If too much weight is placed on the platform, the display will read O,Ld (Overload) as shown below.



Figure D: Overload

8. To turn off Scale, press the ON/OFF button.

Note: The Scale will automatically turn off 60 seconds after item is weighed.

Calibration

CAUTION: An exact 200g weight is needed for calibration (not included). Improper calibration will make the Scale inaccurate.

1. Make sure nothing is on the platform and it is clean and dry. Place the Scale on a level, flat, hard, stable surface. Turn on Scale.
2. Press and hold **MODE** for longer than 3 seconds, until **CAL** is displayed. Press **MODE** again to calibrate 0.0 reading.
3. The display will flash 200.0g. Place an exact 200g weight on the center of the platform. If calibration is complete, the Scale will show **PASS** and it can be used normally. If not, have the Scale serviced by a qualified technician.



Limited 90 Day Warranty

Harbor Freight Tools Co. makes every effort to assure that its products meet high quality and durability standards, and warrants to the original purchaser that this product is free from defects in materials and workmanship for the period of 90 days from the date of purchase. This warranty does not apply to damage due directly or indirectly, to misuse, abuse, negligence or accidents, repairs or alterations outside our facilities, criminal activity, improper installation, normal wear and tear, or to lack of maintenance. We shall in no event be liable for death, injuries to persons or property, or for incidental, contingent, special or consequential damages arising from the use of our product. Some states do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation of exclusion may not apply to you. THIS WARRANTY IS EXPRESSLY IN LIEU OF ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, INCLUDING THE WARRANTIES OF MERCHANTABILITY AND FITNESS.

To take advantage of this warranty, the product or part must be returned to us with transportation charges prepaid. Proof of purchase date and an explanation of the complaint must accompany the merchandise. If our inspection verifies the defect, we will either repair or replace the product at our election or we may elect to refund the purchase price if we cannot readily and quickly provide you with a replacement. We will return repaired products at our expense, but if we determine there is no defect, or that the defect resulted from causes not within the scope of our warranty, then you must bear the cost of returning the product.

This warranty gives you specific legal rights and you may also have other rights which vary from state to state.

Record Serial Number Here: _____

Note: If product has no serial number, record month and year of purchase instead.

CENTTECH

3491 Mission Oaks Blvd. • PO Box 6009 • Camarillo, CA 93011 • (800) 444-3353