CEN-TECH™

DIGITAL INSTANT-READ THERMOMETER

SPECIFICATIONS

ITEM 95382

Range	-40° to 392° F (-40° to 200° C)
Accuracy	±1.8° F (32 to 212° F) ±1° C (0 to 100° C) ±3.6° F/+2° C (other)
Resolutions	0.1° F/0.1° C
Dimensions	6" L x .02" W (probe end)
Weight	18 grams
Battery	(1) 1.55V SR44 (included)

AWARNING

To prevent serious injury or property damage:

- 1. Do not use to measure temperature higher than 392° F (200° C).
- 2. Do not immerse Thermometer head in liquid.
- Do not let Thermometer head come into contact with liquids/objects with a temperature over 158° F (70° C.).
- Keep out of reach of children.

INSTRUCTIONS

- Wash with warm water and a mild detergent. Dry with a soft cloth.
- 2. Press the ON/OFF button to activate.
- 3. Press the $^{\circ}\text{C}/^{\circ}\text{F}$ button to select the desired temperature setting.
- Hold the head of the Thermometer and insert the probe end into the center part of the object to be checked.

CAUTION! When measuring the temperature of hot water, oil or other hot liquids and objects, insert the probe through

the plastic sheath clamp and hold other end of the sheath.

- When finished, clean the probe with warm water and a mild detergent and place the probe inside the sheath for storage.
- 6. Press ON/OFF button to deactivate.

Power will turn off automatically if ON/OFF button is not pressed within 3 minutes or if the temperature is lower than 104° in 3 mintues.

06k Made in China.