

Harman Becker
Automotive Systems GmbH
Söflinger Str. 100
89077 Ulm, Germany
Phone: +49 (0) 731-3994-325
Fax: +49 (0) 731-3994-250
Email: Werner.Bollinger@harman.com

Harman Becker Automotive Systems GmbH | Söflinger Str. 100 | 89077 Ulm

PHOENIX TEST-LAB GmbH
Product Certification
Königswinkel 10

D 32825 Blomberg

Ulm, 2009-09-21

FCC ID: T8G-BEB019

To Whom It May Concern:

The FCC statements (§15.19 Labelling Requirements)

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation"

and (§15.21 Information to the User)

under relevant title **"CAUTION TO USERS"** or **"FCC WARNING"** or **"NOTE"**

"Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment "

will both be placed in a prominent location in the users manual for the North American Market.

The FCC statement §15.19 Labelling Requirements is also placed in the user manual due to the following reason:

- This equipment is fixed assembled ex-factory. After this equipment is assembled, the user is not easily able to see the FCC text, as this device is generally installed "out of sight" (hidden from user) in vehicles.
- The user manual is the only end-user visible "part".

If you have any questions, please feel free to contact me at the address shown below.

Thank you for your attention to this matter.

Signatory

Werner Bollinger Senior Manager

HARMAN / BECKER

Automotive Systems GmbH

Söflinger Straße 100, 89077 Ulm



Management Board: Dr. Klaus Blickle (Chairman), Dr. Udo Hüls, Michael Mauser, Regis Baudot
Chairman of the Supervisory Board: Ansgar Rempp | Domicile: Karlsbad | Local Court Mannheim: Register No. 361395