



American Certification Body, Inc.
6731 Whittier Ave.
Suite C110
McLean, VA 22101

Statements in the User Manual for the following Cert Numbers:

FCC ID: OYGTSSRE3UC / FCC ID: OYGTSSRE3UB
FCC ID: OYGTSSRE4UB / FCC ID: OYGTSSRE4UC
IC: 3702A-TSSRE3UB / IC: 3702A-TSSRE4UB

We hereby assure that the following caution statement as per CFR 47, §15.21 is included in a prominent location of the owner's manual of the cars:

The title **"CAUTION TO USERS"** or **"FCC WARNING"**: **"NOTE"** or relevant title and

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

In addition, we also assure that the following statement will appear in English and French in a prominent location in the final published manual as per CFR 47, §15.19(a)(3) and RSS-GEN 7.1.3 and we will inform the customer that it must be added before they ship to Canada.

This device complies with Part 15 of the FCC Rules and with Industry Canada license-exempt RSS standard(s). Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes: (1) l'appareil ne doit pas produire de brouillage, et (2) l'utilisateur de l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

Thomas Ring
Teamleader Global Market Access

CSA Group Bayern GmbH
Ohmstrasse 1-4
94342 Strasskirchen, Germany

CSA Group Bayern GmbH
Ohmstrasse 1 - 4
94342 Strasskirchen