



## Microscan Service Price List

Repair or replace list prices. Representative part numbers shown. Accessory discounts apply.

### Auto ID Barcode Readers

Part Number	Description	List Price
FIS-0002-XXXX	MS-2 Repair	€ 275
FIS-0003-XXXX	MS-3 Repair	€ 450
FIS-0710-XXXX	MS-710 Repair	€ 500
FIS-0911-XXXX	MS-9 Repair	€ 630
FIS-0820-XXXX	MS-820 Repair	€ 545
FIS-0830-XXXX	QX-830 Repair	€ 630
FIS-0870-XXXX	QX 870 Repair	€ 815
FIS-0890-XXXX	MS-890 Repair	€ 905
FIS-0210-XXXX	MS-Connect 210 Repair	€ 540

### Auto ID 2D Readers and Verifiers

Part Number	Description	List Price
FIS-0004-XXXX	MS-4, MS-4X, MS-4Xi Repair	€ 540
FIS-6300-XXXX	MINI Hawk Repair	€ 630
FIS-6800 or 6801-XXXX	QX Hawk Repair	€ 905
FIS-UD10-XXXX	UID DPM Verifier Repair	€ 1,725
FIS-UD20-XXXX	UID LDP Verifier Repair	€ 1,635
721X-XXXX-XXXX	MicroHAWK ID-20 Repair	€ 450
731X-XXXX-XXXX	MicroHAWK ID-30 Repair	€ 630
741X-XXXX-XXXX	MicroHAWK ID-40 Repair	€ 815

### Auto ID Handhelds

Part Number	Description	List Price
FIS-HS41X-XXXX	HS-41X Repair	€ 540
FIS-HS51X-XXXX	HS-51 and HS-51X Repair	€ 745
FIS-6170-XXXX	Mobile Hawk Repair	€ 630

### Machine Vision

Part Number	Description	List Price
GMV-6300-XXXX	Vision MINI and Vision MINI Xi Smart Camera Repair	€ 630
GMV-6800-XXXX	Vision HAWK Smart Camera Repair	€ 905
731X-XXXX-XXXX	MicroHAWK MV-30 Repair	€ 725
741X-XXXX-XXXX	MicroHAWK MV-40 Repair	€ 905

### LVS Verifiers and Print Quality Inspection Systems

All LVS products have a minimum service charge of €225 for initial evaluation.  
A repair quote will be provided prior to repair and the service fee will be billed on a time and materials basis.