



GE Appliances

General Electric Company
Appliance Park, Louisville, KY 40225

Service Bulletin

**REFRIGERATORS
ARCTICA SIDE-BY-SIDE
CUSTOMCOOL MODELS
TROUBLESHOOTING FLOW CHART**


REF 34-02

SEPTEMBER 2002

The troubleshooting flow chart included in this bulletin was developed in order to successfully troubleshoot and diagnose malfunctions in the electronic control system of the GE Profile Arctica™ Side-by-Side refrigerators with CustomCool™ technology.

This troubleshooting flow chart will help technicians:

- Quickly determine the exact problem
- Use standard tools
- Determine what parts, if any, to be replaced
- Avoid repeat service calls
- Avoid unnecessary replacement of parts



GE Profile Arctica Side-By-Side Refrigerator
with CustomCool Technology

Arctica Refrigerator Main Board Troubleshooting Flow Chart

