

Technical Bulletin



Date: February 28, 2002

No: TDR-0002-B
Page 1 of 3

| | |
|------------------|--|
| Type | Policy Letter √ Service Information |
| Attention | Service Managers √ Service and Parts Managers |
| Models | ALL 1998 APD to Feb 2002 SxS Dispenser Model Refrigerators |
| Issue | Ice Maker Fill tube Freezing Up No Ice to ice maker fill tube freezing up. |
| Warranty | Covered under terms of warranty issued with the product. |
| Action | Check the following before replacing the fill tube. <ul style="list-style-type: none">▪ Low water pressure (under 20 psi)▪ Leaking water valves▪ Kinked water lines▪ Little or no flow through the saddle valve |

Brand
Maytag

Product
Refrigerator

After checking the above, replace the icemaker fill tube grommet with the icemaker fully vented fill tube kit listed below.

12001935 All Dispenser APD SxS Except CD Models
12001936 APD Dispenser CD (Counter Depth) Models

See attached instruction sheets 16021546