


SIR-GM1 Applications		Recommended Cables				
		If Factory XM, or XM pre-wiring, is Present- Use the following Harness	Connects At	Factory XM tuner location	If Vehicle is not pre-wired for XM use the following Harness	Connects At
Compatible Vehicles						
Buick						
2005-06	Allure	Factory SDAR Interface Cable	XM Tuner Location	Left Rear Quarter Panel	N/A	
2004-05	LeSabre	Factory SDAR Interface Cable	XM Tuner Location	Left Rear Quarter Panel	N/A	
2004-06	Rainier	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-06	Rendezvous	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2005-06	LaCrosse	Factory SDAR Interface Cable	XM Tuner Location	Left Rear Quarter Panel	T-Harness	Radio
2005-06	Terazza	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio
Cadillac						
2004-06	CTS**	Factory SDAR Interface Cable	XM Tuner Location	On rear deck left side	N/A	
2003-06	Escalade/EXT/ESV	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-05	DeVille	Factory SDAR Interface Cable	XM Tuner Location	Behind Rear seat	N/A	
2004-06	SRX	Factory SDAR Interface Cable	XM Tuner Location	Right rear quarter panel	N/A	
2005-06	XLR	Factory SDAR Interface Cable	XM Tuner Location	Between seats	N/A	
Chevrolet						
2003-06	Avalanche	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2004-05	Blazer				T-Harness	Radio
2003-05	Cavalier	Factory SDAR Interface Cable	XM Tuner Location	On rear deck in center	T-Harness	Radio
2005-06	Colorado	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2005-06	Corvette	Factory SDAR Interface Cable	XM Tuner Location	Driver side rear panel (above wheel well)	T-Harness	Radio
2005-06	Equinox	Factory SDAR Interface Cable	XM Tuner Location	Left Rear Quarter Panel	T-Harness	Radio
2003-05	Express Van				T-Harness	Radio
2003-05	Impala	Factory SDAR Interface Cable	XM Tuner Location	Right rear quarter panel	T-Harness	Radio
2003-05	Monte Carlo	Factory SDAR Interface Cable	XM Tuner Location	Right rear quarter panel	T-Harness	Radio
2004	S-10				T-Harness	Radio
2003-06	Silverado/HD	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2004-06	SSR				T-Harness	Radio
2003-06	Suburban	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-06	Tahoe	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-06	Trailblazer	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2005-06	Uplander	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio
2003-05	Venture	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio
GMC						
2005-06	Canyon	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-06	Denali/Denali XL	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-06	Envoy	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2004	Jimmy				T-Harness	Radio
2004	S-15/Sonoma				T-Harness	Radio
2003-05	Savana Van				T-Harness	Radio
2003-06	Sierra/Sierra Denali	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-06	Yukon/Yukon XL	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio

**Note: The Cadillac CTS requires a modification to the Factory SDAR Interface Cable. Pin 3 (White) and Pin 10 (Black) must be switched. See the Cadillac CTS Installation Modification sheet included with the SIR-GM1 for more details.


SIR-GM1 Applications		Recommended Cables				
		If Factory XM, or XM pre-wiring, is Present- Use the following Harness	Connects At	Factory XM tuner location	If Vehicle is not pre-wired for XM use the following Harness	Connects At
Compatible Vehicles						
Hummer						
2004-06	H1	Factory SDAR Interface Cable	XM Tuner Location	Unavailable	T-Harness	Radio
2003-06	H2	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2006	H3	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox (Remove Radio to access)	T-Harness	Radio
Isuzu						
2003-06	Ascender	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
Oldsmobile						
2003-04	Alero	Factory SDAR Interface Cable	XM Tuner Location	RF of passenger compartment	T-Harness	Radio
2003-04	Bravada	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-04	Silhouette	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio
Pontiac						
2003-05	Aztek	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-05	Bonneville	Factory SDAR Interface Cable	XM Tuner Location	Left Rear Quarter Panel	N/A	
2003-05	Grand Am	Factory SDAR Interface Cable	XM Tuner Location	Left Rear Quarter Panel	T-Harness	Radio
2004-06	Grand Prix	Factory SDAR Interface Cable	XM Tuner Location	RF of passenger compartment	T-Harness	Radio
2003-05	Montana	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio
2005-06	Montana SV6	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio
2003-05	Sunfire	Factory SDAR Interface Cable	XM Tuner Location	On rear deck in center	T-Harness	Radio
2004-06	Vibe	Factory SDAR Interface Cable	XM Tuner Location	Right rear quarter panel	T-Harness	Radio
Saab						
2005-06	9-7X	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
Saturn						
2005-06	Relay	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio

Factory SDAR Interface Cable



Used to replace the factory XM tuner module

T-Harness Interface Cable



Used when the vehicle is not pre-wired for satellite radio

Vehicles must be GM Class-2 Bus compliant and the headunits must have a BAND button or Direct XM selection to be compatible. Some of the 2006 vehicles listed may have transitioned to the GM -LAN bus mid year - which are not compatible with the SIR-GM1.

The factory XM antenna is not compatible with the SIR-GM1. Please use the Sirius antenna supplied with the product