

FEDERAL COMMUNICATIONS COMMISSION
Laboratory Division
7435 Oakland Mills Road
Columbia, MD 21046

June 09, 2004

Compliance Certification Services
561F Monterey Road
Morgan Hill, CA 95037

Attention: Mike Kuo

Re: Application Received: 7/8/2003
Equipment Class: PCE-PCS Licensed Transmitter held to ear
Applicant Name: Hyundai Curitel Inc.
FCC ID: PP4TX-95C
TCB Name: Compliance Certification Services
731 Confirmation Number: TC437939

Gentlemen:

The application for the above equipment is hereby DISMISSED pursuant to Section 2.917(a) of the Rules for the following reasons.

Request by TCB in 7 May 2004 in correspondence 11432.

If you elect to refile for equipment authorization you must submit a currently dated and originally signed Form 731, accompanied by all data required by the Rule sections applicable to the equipment. The deficiencies listed above must be corrected before refiling. Do not refile the application with the same deficiencies or we may DENY the application pursuant to 2.919. You cannot reuse the FCC ID number on denied applications as you can with dismissed applications.

You are cautioned that marketing and importation of equipment in the United States bearing the referenced FCC Identifier is prohibited by Section 2.803 of the Rules. Violation of this regulation may subject you to the penalties provided in Sections 501 and 502 of the Communications Act of 1934, as amended.

Sincerely,

Martin Perrine
Electronics Engineer

FEDERAL COMMUNICATIONS COMMISSION
Laboratory Division
7435 Oakland Mills Road
Columbia, MD 21046

June 09, 2004

Hyundai Curitel Inc.
San 136-1, Ami-Ri,
Bubal-Eub, Ichon-Si,
Kyoungki-Do 467-701
South Korea

Attention: Hong-Ki Kim

Re: Application Received: 7/8/2003
Equipment Class: PCE-PCS Licensed Transmitter held to ear
Applicant Name: Hyundai Curitel Inc.
FCC ID: PP4TX-95C
TCB Name: Compliance Certification Services
731 Confirmation Number: TC437939

Gentlemen:

The application for the above equipment is hereby DISMISSED pursuant to Section 2.917(a) of the Rules for the following reasons.

Request by TCB in 7 May 2004 in correspondence 11432.

If you elect to refile for equipment authorization you must submit a currently dated and originally signed Form 731, accompanied by all data required by the Rule sections applicable to the equipment. The deficiencies listed above must be corrected before refileing. Do not refile the application with the same deficiencies or we may DENY the application pursuant to 2.919. You cannot reuse the FCC ID number on denied applications as you can with dismissed applications.

You are cautioned that marketing and importation of equipment in the United States bearing the referenced FCC Identifier is prohibited by Section 2.803 of the Rules. Violation of this regulation may subject you to the penalties provided in Sections 501 and 502 of the Communications Act of 1934, as amended.

Sincerely,

Martin Perrine
Electronics Engineer