

SCHEIDT & BACHMANN™



Cash & Card Fare Vending (CCFVM) Repair & Maintenance Manual

Printing Date: 1-Jul, 2006 Release Version: 1.01 - FINAL
Article/Document Number: 86-38786

Today's Fare Collection Solutions for Tomorrow...



Confidential - Not for public release.

Volume 1 of 7



FCC Labels	Federal Communications Commission (FCC) labels that identify the license for the transponder identification system. These labels are located near each transponder, such as on the Additional Coin Magazine connection board, in the Coin Magazine Drawer and beside the Coin Vault.
Feed/Cut Unit	Feed/Cut Units perform two functions. They feed tickets from ticket stock rolls into the printer and cut the tickets to a precise, pre-defined length.
File Transfer Protocol (FTP)	The Internet's file transfer protocol. FTP, which has been used for more than two decades, is a standard protocol for accessing files on servers all over the world.
Filter	A Filter selects data under special criterion.
Firmware	Computer programs and data loaded into read-only memory that cannot be modified by the computer during normal operation and that is not erased by loss of power.
Flash Card	The Flash Card is a memory storage module (PCMCIA) used for AFC machine initialization and backup storage.
FMV	See "Fare Media Validator".
Freetext Record	The application process receives input data from the customer or agent/service technician as tariff data or operational data. With this data the application process or service process generates a freetext record.
Front Door Lock	See "Door Lock".
Front Panel	Typically, there are three front panels bolted to the outside of the outside of an AFC machine Door — the Customer Service Map Front Panel, Touch Screen Front Panel or Screen Reference Buttons, and the Currency Front Panel. The panels provide information to the customer via raised graphics and Braille symbols.
FTP	See "File Transfer Protocol".
FVM	See "Fare Vending Machine".

CCFVM Repair and Maintenance Manual
16 VOLUME 3 – Chapter 1
Introduction, Glossary, and Safety – Money System

NOTE : THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY RADIO OR
TV INTERFERENCE CAUSED BY UNAUTHORIZED MODIFICATIONS TO
THIS EQUIPMENT. SUCH MODIFICATIONS COULD VOID THE USER'S
AUTHORITY TO OPERATE THE EQUIPMENT.