

SONY

Model: KDL-55HX800

Description: LCD TV


Dimensions: 50 $\frac{3}{8}$ " 31 $\frac{1}{2}$ " 13 $\frac{3}{4}$ "

(WHD): 50 $\frac{3}{8}$ " 30 $\frac{1}{8}$ " 2 $\frac{7}{8}$ " w/o stand

Weight: TBD

Carton Dimensions: tbd
(WHD):

Power requirements: 120V AC
60HZ



NOTE:

WHERE THERE ARE CLOSE TOLERANCES INVOLVED IN CABINET BUILDING OR APPLICATIONS WHICH REQUIRE A GREAT DEGREE OF PRECISION, WE RECOMMEND THAT THE PRODUCT ITSELF BE USED TO MAKE THE ACTUAL MEASUREMENTS. SONY WILL NOT BE HELD RESPONSIBLE FOR INACCURACIES IN THE DESIGN OR MANUFACTURE OF ENCLOSURES.

Consumer Integrated Systems - Park Ridge, New Jersey 07656 - Fax (201)930-7891 - www.sony.com/dn

Features and specifications subject to change without notice. Non-Metric weights and measurements are approximate.

SONY

Model: KDL-55HX800

Description: LCD TV


Dimensions: 50 $\frac{3}{8}$ " 31 $\frac{1}{2}$ " 13 $\frac{3}{4}$ "

(WHD): 50 $\frac{3}{8}$ " 30 $\frac{1}{8}$ " 2 $\frac{7}{8}$ " w/o stand

Weight: TBD

Carton Dimensions: tbd
(WHD):

Power 120V AC
requirements: 60HZ



NOTE:

WHERE THERE ARE CLOSE TOLERANCES INVOLVED IN CABINET BUILDING OR APPLICATIONS WHICH REQUIRE A GREAT DEGREE OF PRECISION, WE RECOMMEND THAT THE PRODUCT ITSELF BE USED TO MAKE THE ACTUAL MEASUREMENTS. SONY WILL NOT BE HELD RESPONSIBLE FOR INACCURACIES IN THE DESIGN OR MANUFACTURE OF ENCLOSURES.

Consumer Integrated Systems - Park Ridge, New Jersey 07656 - Fax (201)930-7891 - www.sony.com/dn

Features and specifications subject to change without notice. Non-Metric weights and measurements are approximate.

SONY

Model: KDL-55HX800

Description: LCD TV



Dimensions: 50 $\frac{3}{8}$ " 31 $\frac{1}{2}$ " 13 $\frac{3}{4}$ "

(WHD): 50 $\frac{3}{8}$ " 30 $\frac{1}{8}$ " 2 $\frac{7}{8}$ " w/o stand

Weight: TBD

Carton Dimensions: tbd
(WHD):

Power 120V AC
requirements: 60HZ



NOTE:

WHERE THERE ARE CLOSE TOLERANCES INVOLVED IN CABINET BUILDING OR APPLICATIONS WHICH REQUIRE A GREAT DEGREE OF PRECISION, WE RECOMMEND THAT THE PRODUCT ITSELF BE USED TO MAKE THE ACTUAL MEASUREMENTS. SONY WILL NOT BE HELD RESPONSIBLE FOR INACCURACIES IN THE DESIGN OR MANUFACTURE OF ENCLOSURES.

Consumer Integrated Systems - Park Ridge, New Jersey 07656 - Fax (201)930-7891 - www.sony.com/dn

Features and specifications subject to change without notice. Non-Metric weights and measurements are approximate.

SONY

Model: KDL-55HX800

Description: LCD TV


Dimensions: 50 $\frac{3}{8}$ " 31 $\frac{1}{2}$ " 13 $\frac{3}{4}$ "

(WHD): 50 $\frac{3}{8}$ " 30 $\frac{1}{8}$ " 2 $\frac{7}{8}$ " w/o stand


Weight: TBD

Carton Dimensions: tbd
(WHD):


Power 120V AC
requirements: 60HZ




20°




15°



10°



5°



0°

NOTE:

WHERE THERE ARE CLOSE TOLERANCES INVOLVED IN CABINET BUILDING OR APPLICATIONS WHICH REQUIRE A GREAT DEGREE OF PRECISION, WE RECOMMEND THAT THE PRODUCT ITSELF BE USED TO MAKE THE ACTUAL MEASUREMENTS. SONY WILL NOT BE HELD RESPONSIBLE FOR INACCURACIES IN THE DESIGN OR MANUFACTURE OF ENCLOSURES.

Consumer Integrated Systems - Park Ridge, New Jersey 07656 - Fax (201)930-7891 - www.sony.com/dn

Features and specifications subject to change without notice. Non-Metric weights and measurements are approximate.

SONY

Model: KDL-55HX800

Description: LCD TV





Dimensions: 50 $\frac{3}{8}$ " 31 $\frac{1}{2}$ " 13 $\frac{3}{4}$ "

(WHD): 50 $\frac{3}{8}$ " 30 $\frac{1}{8}$ " 2 $\frac{7}{8}$ " w/o stand

Weight: TBD

Carton Dimensions: tbd
(WHD):

Power 120V AC
requirements: 60HZ



NOTE:

WHERE THERE ARE CLOSE TOLERANCES INVOLVED IN CABINET BUILDING OR APPLICATIONS WHICH REQUIRE A GREAT DEGREE OF PRECISION, WE RECOMMEND THAT THE PRODUCT ITSELF BE USED TO MAKE THE ACTUAL MEASUREMENTS. SONY WILL NOT BE HELD RESPONSIBLE FOR INACCURACIES IN THE DESIGN OR MANUFACTURE OF ENCLOSURES.

Consumer Integrated Systems - Park Ridge, New Jersey 07656 - Fax (201)930-7891 - www.sony.com/dn

Features and specifications subject to change without notice. Non-Metric weights and measurements are approximate.