ATTACHMENT L - USER MANUAL


USER MANUAL

FCC ID #: LZX32710

Prepared for Unical Enterprises, Inc.

Prepared by EMC Compliance Management Group

Model 32710 25 Channel Cordless Telephone with Caller ID on Handset



Caller ID Features:

- 35 Mutiple Data Memory
 70 Single Data Memory
- 3-Line Alphanumeric LCD Display
- New Call Indication
- Repeat Calls Indication
- Review UP/DOWN Button
- Selective Erase/Erase All
- Call Back
- Long Distance Call Indication
- Call Waiting with Master & Slave Selections

Telephone Features:

- 25 Channel Auto Scan
- 10 Number Memory

- Manual Channel Scan
- Base to Handset Page
- 65,536 Combination Security
- Auto Answer/Auto Standby
- Any Key Press (Handset) to Answer an Incoming Call
- Out-of-Range Indication
- Flash
- Pause
- Last Number Redial
- Battery Low Indication
- Receiver Hi/Low Switch
- Desk/Wall Use
- Hearing Aid Compatible
- 1 Year Limited Warranty

Ordering Information:

Order Number: 32710-4

Color: Black

Display Box:

Weight:

Dimensions: 7.5 x 2.75 x 11.38

Cube: 14

Shipping Carton:

Units per Carton: 4

Weight:

Dimensions: 12 x 11.81 x 8.5

Cube: .70

Bar Code Information:

UPC: 0 88064 32714 1 SCS: 100 88064 32714 8

Specifications Subject to Change Without Notice.

€ Copyright 1998 Rev. 03/03/98



Distributed Exclusively Worldwide by: UNICAL ENTERPRISES, INC. 16960 Gale Avenue

16960 Gale Avenue City of Industry, CA 91745 (626) 965-5588 Fax: (626) 965-0970 This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. Privacy of communications may not be insured when using this phone.

Changes or modifications not expressly approved in writing by Northwestern Bell Phones may void the user's authority to operate this equipment.

Some cordless phones operate at frequencies that may cause interference to nearby TVs and VCRs; to minimize or prevent such interference, the base of the cordless phone should not be placed near or on top of a TV or VCR; and, if interference is experienced, moving the cordless telephone farther away from the TV or VCR will often reduce or eliminate the interference