## **TÜV Rheinland Product Safety GmbH**

# **Appendix 5**



Am Grauen Stein

D - 51105 Köln

14003929 001

Seite 1 von 4 Page 1 of 4



Test Report No.



# **6.0V FULL FUNCTION RADIO CONTROL**

PLEASE ENSURE TO REMOVE ALL ACCESSORIES ANDCOMPONENTS FROM THE PACKAGING

#9374 : TOYOTA - SUPRA #9375 : MITSUBISHI - LANCER EVOLUTION VII

MITSUBISHI AND LANCER EVOLUTION VII ARE TRADEMARKS OF MITSUBISHI MOTORS COPORATION, AND USED WITH PERMISSION. Toyota and supra are trademarks of Toyota Motor Coporation, and used with permission.

BATTERY REQUIREMENT: Vehicle: 4 x 1,5V (AA) size batteries
Transmitter: 1 x 9V (006P, 6F22) size Batteries

BATTERY INSTALLATION

LOCK BATTERY COMPARTMENT: DROP THE BATTERY COMPARTMENT INTO POSITION, LOCK IT, YOU ARE SET TO RUN!










OPERATION un switch to on positic witch off vehicle and tra


### INSTALLATION OF VEHICLE ANTENNA


A. Insert antenna wire through hollow tube.

B. Insert tube into hole of vehicle. AVOID PULLING WIRE TOO TIGHT.

C. Tie a knot on top of wire to secure.







NOTE:

Non-rechargeable batteries are not to be recharged.

Rechargeable batteries are not recommended to be used with this product.

Officent types of batteries or new and used batteries are not to be mixed.

Only batteries of the same or equivalent type as recommended are to be used.

Batteries are to be inverted with the correct polarity.

Enhausted batteries are to be removed from the toy.

The supply terminals are not to be short circuited.

The supply terminals are not to be short circuited.

TROUBLE SHOOTING:

PROBLEM: VEHICLE DOES NOT MOVE

Josephen and "croatets correctly matched in storoutister and car?

Are the metal contact correctly matched in storoutister.

Are the metal contact with soudding may or dirty in transmitter?

As the metal contact tably soudding may or dirty in transmitter?

As the power switch on whick and transmitter sturned on?

Sis the battery yower pack week or out of power?

PROBLEM: VEHICLE RUNS SLOWLY

Are he has haveful in the vehicle and transmitter worn out?

And wave interference may affect behaviour of the venture.

Special care for your vehicle is mentioned below.

DO NOT ABUSE YOUR VEHICLE.

Lawrid heart, water, sand and high impact collisions. Olf road vehicles run easily on grassy surfaces.

A wood heet, water, sand and high impact collisions. Off road vehicles run easily on grassy surfaces.

A wood water, water, sand and high impact collisions. Off road vehicles run easily on grassy surfaces.

A wood using vehicle on west surfaces or in rain.

A wood using vehicle for long persion under direct surlight.

Sunlight or excessive host may damage senditive / electronic instruments.

Some vehicle rained places away from heeters or warm areas.

Collision with hard surface may damage vehicle.

Ye whice will not perform on thick capte or dusty floors.

A wood unning two vehicles of the same frequency (Purchase two vehicles, with different frequencies instead.)

A ways brush your which after use to remove dust, keep vehicle deam.

10. Always brush your which after use to remove dust, keep vehicle deam.

BATTERY LIFE Extend battery life by switching off when not in use.

INTERFERENCE Advisable not to use vehicle close to high tension wires or CB radios

## WARNING:

WARNING:

Changes or modifications to this unit not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment

NOTE. This equipment has been tested and found to comply with the limits for a Class B digital device, parsuant to Part 15 of FCC Rules and RRTTE Directive 1999/57/C. There limits are designed to growde reasonable protection against harmony energy and, if not installed and used in accordance with the installation. There are not generates, the production of the productio

THIS PRODUCT IS FOR THE USE IN U.K., SPAIN, GERMANY, FRANCE, BELGIUM, ITALY, SWITZERLAND, THE NETHERLANDS, DENMARK, U.S., CANADA AND PORTUGAL

C€0197**①** 

printed in China

