

TISSUES Implementation Conformance Statement

for the IEC 61850 Interface

COMPLIANCE SHEET

4.02.0400.23002 1.1 en-US ENGLISH



Important User Information

Disclaimer

The information in this document is for informational purposes only. Please inform HMS Industrial Networks of any inaccuracies or omissions found in this document. HMS Industrial Networks disclaims any responsibility or liability for any errors that may appear in this document.

HMS Industrial Networks reserves the right to modify its products in line with its policy of continuous product development. The information in this document shall therefore not be construed as a commitment on the part of HMS Industrial Networks and is subject to change without notice. HMS Industrial Networks makes no commitment to update or keep current the information in this document.

The data, examples and illustrations found in this document are included for illustrative purposes and are only intended to help improve understanding of the functionality and handling of the product. In view of the wide range of possible applications of the product, and because of the many variables and requirements associated with any particular implementation, HMS Industrial Networks cannot assume responsibility or liability for actual use based on the data, examples or illustrations included in this document nor for any damages incurred during installation of the product. Those responsible for the use of the product must acquire sufficient knowledge in order to ensure that the product is used correctly in their specific application and that the application meets all performance and safety requirements including any applicable laws, regulations, codes and standards. Further, HMS Industrial Networks will under no circumstances assume liability or responsibility for any problems that may arise as a result from the use of undocumented features or functional side effects found outside the documented scope of the product. The effects caused by any direct or indirect use of such aspects of the product are undefined and may include e.g. compatibility issues and stability issues.

1 Description

This document provides the Tissues conformance statement for the IEC 61850 Edition 2 interface in WEB-PLC Version V19.3.32 with IEC 61850 Stack PIS10 Version 2.8.23. According to the UCA Internal User Group QAP the Tissue conformance statement is required to perform a conformance test and is referenced on the certificate.

This document is applicable for WEB-PLC with firmware version V19.3.32.

2 Mandatory Edition 2 Tissues

The tables show an overview of the applicable mandatory Tissues.

Y Implemented by server: the server has implemented the respective tissue.

Supported by client: the client supports servers that have implemented the respective tissue.

ni No impact on testing

N/A Not applicable if the server/client does not support the corresponding ACSI services

Part 6 Tissue	Description	Implemented by server	Supported by client
658	Tracking related features	N/A	N/A
663	FCDA element cannot be a functionally constrained logical node	Y	Y
668	Autotransformer modeling	N/A	N/A
719	ConfDataSet: maxAttributes definition is confusing	N/A	N/A
721	Log element name	N/A	N/A
768	bType VisString65 is missing	N/A	N/A
779	Object references	Υ	Υ
788	SICS S56 from optional to mandatory	N/A	N/A
789	ConfLdName as services applies to both server and client (supportsLdname)	N/A	N/A
804	valKind and IED versus System configuration (valimport)	N/A	N/A
806	Max length of log name inconsistent between -6 and -7-2	N/A	N/A
807	Need a way to indicate if Owner is present in RCB	N/A	N/A
822	Extension of IED capabilities	N/A	N/A
823	ValKind for structured data attributes	Y	Υ
824	Short addresses on structured data attributes	N/A	N/A
825	Floating point value	Y	Υ
845	SGCB ResvTms	N/A	N/A
853	SBO and ProtNs	N/A	N/A
855	Recursive SubFunction	N/A	N/A
856	VoltageLevel frequency and phases	N/A	N/A
857	Function/SubFunction for ConductingEquipment	N/A	N/A
886	Missing 8-1-types	N/A	N/A
901	tServices as AP or as IED element	N/A	N/A
936	SupSubscription parameter usage is difficult	N/A	N/A
1175	IPv6 address lowercase only	N/A	N/A

Part 6 Tissue

Part 7-1 Tissue

Fait /-1 lissue			
Part 7-1 Tissue	Description	Implemented by server	Supported by client
828	Data model namespace revision IEC 61850-7-4:2007 [A]	N/A	N/A
1151	Simulated GOOSE disappears after first appearance when LPHD.Sim = TRUE	N/A	N/A
1196	Extensions to standardized LN classes made by third parties	N/A	N/A

Part 7-2 Tissue			
Part 7-2 Tissue	Description	Implemented by server	Supported by client
778	AdCause values - add value not supported	Y	Y
780	What are unsupported trigger options at a control block?	Y	Y
783	TimOper Resp-; add Authorization check	N/A	N/A
786	AddCause values 26 and 27 are switched	Υ	Y
820	Mandatory ACSI services (use for PICS template)	N/A	N/A
858	Typo in enumeration ServiceType	N/A	N/A
861	dchg of ConfRev attribute	N/A	N/A
876	GenLogicINodeClass and SGCB, GoCB, MsvCB, UsvCB	N/A	N/A
1038	Loss of info detection after resynch	N/A	N/A
1062	Entrytime not used CDC	N/A	N/A
1071	Length of DO name	Y	Υ
1091	Sentence "The initial value of EditSG shall be 0", has to be stated in part 7.2 not in 8.1.	Y	Y
1127	Missing owner attribute in BTS and UTS	N/A	N/A
1163	Old report in URCB	Υ	Υ
1202	GI not optional	Y	Υ

Part 7-3 Tissue

Part 7-3 Tissue	Description	Implemented by server	Supported by client
697	Persistent command/PulseConfig	N/A	N/A
698	Wrong case is BAC.dB attribute	N/A	N/A
722	Units for h and min are not in UnitKind enumeration	Y	Υ
919	Presence condition for sVC	N/A	N/A
925	Presence of i or f attribute, problem with writing	N/A	N/A
926	Presence Conditions within RangeConfig	N/A	N/A

Part 7-4 Tissue

Part 7-4 Tissue	Description	Implemented by server	Supported by client
671	Mistake in definition of Mod & Beh	N/A	N/A
674	CDC of ZRRC.LocSta is wrong	N/A	N/A
675	SIML LN	N/A	N/A
676	Same data object name used with different CDC	N/A	N/A
677	MotStr is used with different CDC in PMMS and SOPM LN classes	N/A	N/A
679	Remove CycTrMod Enum	N/A	N/A
680	SI unit for MHYD.Cndct	N/A	N/A
681	Enum PIDAlg	N/A	N/A
682	ANCR.ParColMod	N/A	N/A
683	Enum QVVR.IntrDetMth	N/A	N/A
685	Enum ParTraMod	N/A	N/A
686	New annex H - enums types in XML	N/A	N/A
694	Data object CmdBlk	N/A	N/A
696	LSVS.St (status of subscription)	N/A	N/A
712	Interpretation of quality operatorBlocked	N/A	N/A
713	DO naming of time constants in FFIL	N/A	N/A
724	ANCR.Auto	N/A	N/A

Part 7-4 Tissue	Description	Implemented by server	Supported by client
725	Loc in LN A-group	N/A	N/A
734	LLN0.OpTmh vs. LPHD.OpTmh	N/A	N/A
735	ISAF.Alm and ISAF.AlmReset	N/A	N/A
736	PFSign	N/A	N/A
742	GAPC.Str, GAPC.Op and GAPC.StrVal	N/A	N/A
743	CCGR.PmpCtl and CCGR.FanCtl	N/A	N/A
744	LN STMP, EEHealth and EEName	N/A	N/A
772	LPHD.PwrUp/PwrDn shall be transient	N/A	N/A
773	Loc, LocKey and LocSta YPSH and YLTC	N/A	N/A
774	ITCI.LocKey	N/A	N/A
775	KVLV.ClsLim and OpnLim	N/A	N/A
776	LPHD.OutOv/InOv and LCCH.OutOv/InOv	N/A	N/A
800	Misspelling in CSYN	N/A	N/A
802	CCGR and harmonized control authority	N/A	N/A
808	Presence condition of ZMOT.DExt and new DOs	N/A	N/A
831	Setting of ConfRevNum in LGOS	N/A	N/A
838	Testing in Beh=Blocked	N/A	N/A
844	MFLK.PhPiMax, MFLK.PhPiLoFil, MFLK.PhPiRoot DEL ->WYE	N/A	N/A
849	Presence conditions re-assessing in case of derived statistical calculation	N/A	N/A
877	QVUB settings should be optional	N/A	N/A
909	Remove ANCR.ColOpR and ColOpL	N/A	N/A
912	Clarification of PwrRtg/VARtg	N/A	N/A
920	Resetable counter is not resetable	N/A	N/A
932	Rename AVCO.SptVol to AVCO.VolSpt	N/A	N/A
939	Change CDC for ANCR.FixCol	N/A	N/A
991	LGOS: GoCBRef (as well as LSVS.SvCBRef) should be mandatory	N/A	N/A
1007	PTRC as fault indicator - Update of description requried	N/A	N/A
1044	TapChg in AVCO	N/A	N/A
1077	Rename DOnames within LTIM	N/A	N/A

Part 7-4	Tissue	(continued)

 (\mathbf{i}) Tissues 675, 735, 772, 775, 776, 878 are not relevant for conformance testing.

Part 8-1 Tissue			
Part 8-1 Tissue	Description	Implemented by server	Supported by client
784	Tracking of control (CTS)	N/A	N/A
817	Fixed-length GOOSE float encoding	Y	Υ
834	File dir name length 64	N/A	N/A
951	Encoding of Owner attribute	N/A	N/A
1040	More associate error codes	Υ	Υ
1178	Select Response+ is non-null value	Y	Y

Compare the TISSUE database for more details on https://iec61850.tissue-db.com

This page intentionally left blank