



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138  
Phone #: (408) 284-8200

## PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: N-12-22R1

Last Buy Deadline for Submission of Order: 28-Nov-2013

Issue Date: 1-Mar-2013

Last Eligible Ship Date: 28-Feb-2014

Contact: IDT Clock Marketing Team

E-mail: [clocks@idt.com](mailto:clocks@idt.com)

### PRODUCT(S) AFFECTED:

### ATTACHMENT

☒ Yes ☐ No

(List Replacement Part #(s), if any)

**Revision 1:** This revised PDN notice is to amend the replacement part#s for selective discontinued part#s.

Please refer to attachments for details.

Attachment I - Discontinued part list with revised replacement part#s

Attachment II - Summary of a list of discontinued part#s with changes made to replacement part#.

Last buy deadline for submission of order and last eligible ship date remain unchanged.

### REASON FOR DISCONTINUANCE:

☐ Replace slower speed with faster speed offerings

☐ Other: \_\_\_\_\_

☐ Obsolete Fab Technology / Process

☒ Obsolete Assembly Technology / Process

The non RoHS compliant lead finish is not available.

☐ Obsolete Package / Material

☐ Declined Market

### CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

Last time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance by IDT at its sole discretion unless otherwise agreed by IDT in writing.

***If you have any questions, please feel free to contact your local IDT distributor or sales representative.***

Customer: \_\_\_\_\_

E-Mail Address: \_\_\_\_\_

Name/Date: \_\_\_\_\_

Phone#: \_\_\_\_\_

Title: \_\_\_\_\_

Fax# : \_\_\_\_\_

### CUSTOMER COMMENTS:

### IDT ACKNOWLEDGEMENT:

Received By: \_\_\_\_\_

Date: \_\_\_\_\_



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138  
Phone #: (408) 284-8200

## PRODUCT DISCONTINUANCE NOTICE (PDN)

### ATTACHMENT I - PDN #: N-12-22R1

#### Affected Part Numbers

| Discontinued Part# | Replacement Part# | Discontinued Part# | Replacement Part#    |
|--------------------|-------------------|--------------------|----------------------|
| 5991A-5JI          | 5991A-5JGI        | 5V991A-2J          | 5V991A-2JG           |
| 5991A-5JI8         | 5991A-5JGI8       | 5V991A-2J8         | 5V991A-2JG8          |
| 5992A-5JI          | None              | 5V991A-5JI         | 5V991A-5JGI          |
| 5992A-5JI8         | None              | 5V991A-5JI8        | 5V991A-5JGI8         |
| 5T2010BBI          | 5T2010BBGI*       | 5V991A-5JI8/N      | None                 |
| 5T2010BBI8         | 5T2010BBGI8*      | 5V991A-7JI         | 5V991A-7JGI          |
| 5T9050PGI          | 5T9050PGGI        | 5V991A-7JI8        | 5V991A-7JGI8         |
| 5T9050PGI8         | 5T9050PGGI8       | 5V991A-7JI8/N      | None                 |
| 5T905PGI           | 5T905PGGI         | 5V993A-2Q          | 5V993A-2QG           |
| 5T905PGI8          | 5T905PGGI8        | 5V993A-2Q8         | 5V993A-2QG8          |
| 5T9110BBI          | 5T9110BBGI        | 5V993A-5QI         | 5V993A-5QGI          |
| 5T9110BBI8         | 5T9110BBGI8       | 5V993A-5QI8        | 5V993A-5QGI8         |
| 5T915PAI           | 5T915PAGI         | 5V993A-7QI         | 5V993A-7QGI          |
| 5T915PAI8          | 5T915PAGI8        | 5V993A-7QI8        | 5V993A-7QGI8         |
| 5T929-30NLI        | 5T929-30NLGI      | 5V994PFI           | 5V994PFGI            |
| 5T929-30NLI8       | 5T929-30NLGI8     | 5V994PFI8          | 5V994PFGI8           |
| 5T9306NLI          | 5T9306NLGI        | 5V995PFI           | 5V995PFGI            |
| 5T9306NLI8         | 5T9306NLGI8       | 5V995PFI8          | 5V995PFGI8           |
| 5T9310NLI          | 5T9310NLGI        | 5V995PFI           | 5V995PFGI            |
| 5T9310NLI8         | 5T9310NLGI8       | 5V995PFI8          | 5V995PFGI8           |
| 5T9316NLI          | 5T9316NLGI        | 74FCT388915T100J   | 74FCT388915T100JG*   |
| 5T9316NLI8         | 5T9316NLGI8       | 74FCT388915T100J8  | 74FCT388915T100JG8*  |
| 5T93GL101PFI       | 5T93GL101PFGI     | 74FCT388915T100PY  | 74FCT388915T100PYG*  |
| 5T93GL101PFI8      | 5T93GL101PFGI8    | 74FCT388915T100PY8 | 74FCT388915T100PYG8* |
| 5T940-30NLI        | 5T940-30NLGI      | 74FCT388915T133J   | 74FCT388915T133JG*   |
| 5T940-30NLI8       | 5T940-30NLGI8     | 74FCT388915T133J8  | 74FCT388915T133JG8*  |
| 5T9950APFI         | 5T9950APFGI       | 74FCT388915T133PY  | 74FCT388915T133PYG*  |
| 5T9950APFI8        | 5T9950APFGI8      | 74FCT388915T133PY8 | 74FCT388915T133PYG8* |
| 5T9950PFI          | 5T9950PFGI        | 74FCT388915T150J   | 74FCT388915T150JG*   |
| 5T9950PFI8         | 5T9950PFGI8       | 74FCT388915T150J8  | 74FCT388915T150JG8*  |
| 5V2528APGI         | 5V2528APGGI       | 74FCT388915T150PY  | 74FCT388915T150PYG*  |
| 5V2528APGI8        | 5V2528APGGI8      | 74FCT388915T150PY8 | 74FCT388915T150PYG8* |
| 5V2528PGI          | 5V2528PGGI        | 74FCT388915T70PY   | 74FCT388915T70PYG*   |
| 5V2528PGI8         | 5V2528PGGI8       | 74FCT388915T70PY8  | 74FCT388915T70PYG8*  |
| 5V927PGI           | 5V927PGGI         | 74FCT88915TT100J   | None                 |
| 5V927PGI8          | 5V927PGGI8        | 74FCT88915TT100J8  | None                 |
| 5V928PGI           | 5V928PGGI         | 74FCT88915TT100PY  | None                 |
| 5V928PGI8          | 5V928PGGI8        | 74FCT88915TT100PY8 | None                 |
| 5V9351PFI          | 5V9351PFGI        | 74FCT88915TT133PY  | None                 |
| 5V9351PFI8         | 5V9351PFGI8       | 74FCT88915TT133PY8 | None                 |
| 5V9910A-2SO        | 5V9910A-2SOG      | 74FCT88915TT55J    | None                 |
| 5V9910A-2SO8       | 5V9910A-2SOG8     | 74FCT88915TT55J8   | None                 |
| 5V9910A-5SOI       | 5V9910A-5SOGI     | 74FCT88915TT55PY   | None                 |
| 5V9910A-5SOI8      | 5V9910A-5SOGI8    | 74FCT88915TT55PY8  | None                 |

Note: For part marked with \*, please contact IDT for further information



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138  
Phone #: (408) 284-8200

## PRODUCT DISCONTINUANCE NOTICE (PDN)

### ATTACHMENT I - PDN #: N-12-22R1

#### Affected Part Numbers

| Discontinued Part# | Replacement Part# | Discontinued Part# | Replacement Part# |
|--------------------|-------------------|--------------------|-------------------|
| 74FCT88915TT70J    | None              | 83940LYIT          | 83940LYILFT       |
| 74FCT88915TT70J8   | None              | 83948AYI           | 83948AYILF        |
| 74FCT88915TT70PY   | None              | 83948AYI-147       | 83948AYI-147LF    |
| 74FCT88915TT70PY8  | None              | 83948AYI-147T      | 83948AYI-147LFT   |
| 83021AMI           | 83021AMILF        | 83948AYIT          | 83948AYILFT       |
| 83021AMIT          | 83021AMILFT       | 840S05AYI          | 840S05AYILF       |
| 83023AMI           | 83023AMILF        | 840S05AYIT         | 840S05AYILFT      |
| 83023AMIT          | 83023AMILFT       | 841608AKI          | 841608AKILF       |
| 83026BGI-01        | 83026BGI-01LF     | 841608AKIT         | 841608AKILFT      |
| 83026BGI-01T       | 83026BGI-01LFT    | 841S04BGI          | 841S04BGILF*      |
| 8302AM             | 8302AMLF          | 841S04BGIT         | 841S04BGILFT      |
| 8302AMI            | 8302AMILF         | 841S04BGIT-09      | 841S04BGI-09LF    |
| 8302AMI-01         | 8302AMI-01LF      | 843001AGI-22       | 843001AGI-22LF    |
| 8302AMI-01T        | 8302AMI-01LFT     | 843001AGI-22T      | 843001AGI-22LFT   |
| 8302AMIT           | 8302AMILFT        | 843002AGI          | 843002AGILF       |
| 8302AMT            | 8302AMLFT         | 843002AGIT         | 843002AGILFT      |
| 8304AM             | 8304AMLF          | 843002AKI-40       | 843002AKI-40LF    |
| 8304AMI            | 8304AMILF         | 843002AKI-40T      | 843002AKI-40LFT   |
| 8304AMIT           | 8304AMILFT        | 843004AGI-01       | 843004AGI-01LF    |
| 8304AMT            | 8304AMLFT         | 843004AGI-01T      | 843004AGI-01LFT   |
| 8304AMT-IB0        | None              | 843023AGI          | 843023AGILF       |
| 83052AGI           | 83052AGILF        | 843023AGIT         | 843023AGILFT      |
| 83052AGI-01        | 83052AGI-01LF     | 8430AY-61          | 8430AY-61LF       |
| 83052AGI-01T       | 83052AGI-01LFT    | 8430AY-61T         | 8430AY-61LFT      |
| 83052AGIT          | 83052AGILFT       | 8430AYI-71         | 8430AYI-71LF      |
| 83054AGI-01        | 83054AGI-01LF     | 8430AYI-71T        | 8430AYI-71LFT     |
| 83054AGI-01T       | 83054AGI-01LFT    | 84314AY            | 84314AYLF         |
| 83056AGI-01        | 83056AGI-01LF     | 84314AYT           | 84314AYLFT        |
| 83056AGI-01T       | 83056AGI-01LFT    | 843252AG           | 843252AGLF        |
| 8305AGI            | 8305AGILF         | 843252AGT          | 843252AGLFT       |
| 8305AGIT           | 8305AGILFT        | 8432BY-51          | 8432BY-51LF       |
| 8308AGI            | 8308AGILF         | 8432BY-51T         | 8432BY-51LFT      |
| 8308AGIT           | 8308AGILFT        | 8432BYI-51         | 8432BYI-51LF      |
| 8312AY             | 8312AYLF          | 8432BYI-51T        | 8432BYI-51LFT     |
| 8312AYT            | 8312AYLFT         | 8432CY-11          | 8432CY-11LF       |
| 8343AYI-01         | 8343AYI-01LF      | 8432CY-111         | 8432CY-111LF      |
| 8343AYI-01T        | 8343AYI-01LFT     | 8432CY-111T        | 8432CY-111LFT     |
| 83904AGI-02        | 83904AGI-02LF     | 8432CY-11T         | 8432CY-11LFT      |
| 83904AGI-02T       | 83904AGI-02LFT    | 8432DY-101         | 8432DY-101LF      |
| 83905AG            | 83905AGLF         | 8432DY-101T        | 8432DY-101LFT     |
| 83905AGT           | 83905AGLFT        | 84330CYI           | 84330CYILF        |
| 83908AG-02         | 83908AG-02LF      | 84330CYIT          | 84330CYILFT       |
| 83908AG-02T        | 83908AG-02LFT     | 8442AY             | 8442AYLF          |
| 83940LYI           | 83940LYILF        | 8442AYT            | 8442AYLFT         |

Note: For part marked with \*, please contact IDT for further information



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138  
Phone #: (408) 284-8200

## PRODUCT DISCONTINUANCE NOTICE (PDN)

### ATTACHMENT I - PDN #: N-12-22R1

#### Affected Part Numbers

| Discontinued Part# | Replacement Part# | Discontinued Part# | Replacement Part# |
|--------------------|-------------------|--------------------|-------------------|
| 844S2416CKI        | 844S2416CKILF     | 85411AMT           | 85411AMLFT        |
| 844S2416CKIT       | 844S2416CKILFT    | 8543BG             | 8543BGLF          |
| 85104AGI           | 85104AGILF        | 8543BGI            | 8543BGILF         |
| 85104AGIT          | 85104AGILFT       | 8543BGIT           | 8543BGILFT        |
| 85105AGI           | 85105AGILF        | 8543BGT            | 8543BGLFT         |
| 85105AGIT          | 85105AGILFT       | 8545AG-02          | 8545AG-02LF       |
| 8516FYI            | 8516FYILF         | 8545AG-02T         | 8545AG-02LFT      |
| 8516FYIT           | 8516FYILFT        | 8545BG             | 8545BGLF          |
| 85210AY-31         | 85210AY-31LF      | 8545BGI            | 8545BGILF         |
| 85210AY-31T        | 85210AY-31LFT     | 8545BGIT           | 8545BGILFT        |
| 85214AG            | 85214AGLF         | 8545BGT            | 8545BGLFT         |
| 85214AGI           | 85214AGILF        | 854S006AGI         | 854S006AGILF      |
| 85214AGIT          | 85214AGILFT       | 854S006AGIT        | 854S006AGILFT     |
| 85214AGT           | 85214AGLFT        | 86004BG-01         | 86004BG-01LF      |
| 8523BGI            | 8523BGILF         | 86004BG-01T        | 86004BG-01LFT     |
| 8523BGIT           | 8523BGILFT        | 86953BYI-147       | 86953BYI-147LF    |
| 8523BGIT-IB0       | None              | 86953BYI-147T      | 86953BYI-147LFT   |
| 85301AG            | 85301AGLF         | 87004AG            | 87004AGLF         |
| 85301AGT           | 85301AGLFT        | 87004AGI           | 87004AGILF        |
| 8530DY-01          | 8530DY-01LF       | 87004AGIT          | 87004AGILFT       |
| 8530DY-01T         | 8530DY-01LFT      | 87004AGT           | 87004AGLFT        |
| 85310AYI-21        | 85310AYI-21LN     | 87008AGI           | 87008AGILF        |
| 85310AYI-21T       | 85310AYI-21LNT    | 87008AGIT          | 87008AGILFT       |
| 8531AY-01          | 8531AY-01LF       | 87016AYI           | 87016AYILF        |
| 8531AY-01T         | 8531AY-01LFT      | 87016AYIT          | 87016AYILFT       |
| 8531AY-01T-IB0     | None              | 8701CYI            | 8701CYILF         |
| 8533AG-01          | 8533AG-01LF       | 8701CYIT           | 8701CYILFT        |
| 8533AG-01T         | 8533AG-01LFT      | 87021AMI           | 87021AMILF        |
| 85357AG-01         | 85357AG-01LF      | 87021AMIT          | 87021AMILFT       |
| 85357AG-01T        | 85357AG-01LFT     | 8705BY             | 8705BYLF          |
| 8535AG-01          | 8535AG-01LF       | 8705BYT            | 8705BYLFT         |
| 8535AG-01T         | 8535AG-01LFT      | 8705BYT-IN0        | None              |
| 8535AG-31          | 8535AG-31LF       | 870919BRI-01       | 870919BRI-01LF    |
| 8535AG-31T         | 8535AG-31LFT      | 870919BRI-01T      | 870919BRI-01LFT   |
| 8535AG-31T-ACT     | 8535AG-31LFT-ACT  | 870931ARI-01       | 870931ARI-01LF    |
| 8535AGI-01         | 8535AGI-01LF      | 870931ARI-01T      | 870931ARI-01LFT   |
| 8535AGI-01T        | 8535AGI-01LFT     | 8725BY-01          | 8725BY-01LF       |
| 8535AGI-31         | 8535AGI-31LF      | 8725BY-01T         | 8725BY-01LFT      |
| 8535AGI-31T        | 8535AGI-31LFT     | 8732AY-01          | 8732AY-01LF       |
| 8535AGT            | 8535AGLFT         | 8732AY-01T         | 8732AY-01LFT      |
| 8535AGT-ACT        | 8535AGLFT-ACT     | 8732AYI-01         | 8732AYI-01LF      |
| 85411AM            | 85411AMLF         | 8732AYI-01T        | 8732AYI-01LFT     |
| 85411AMI           | 85411AMILF        | 87339AGI-11        | 87339AGI-11LF     |
| 85411AMIT          | 85411AMILFT       | 87339AGI-11T       | 87339AGI-11LFT    |

Note: For part marked with \*, please contact IDT for further information



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138  
Phone #: (408) 284-8200

## PRODUCT DISCONTINUANCE NOTICE (PDN)

### ATTACHMENT I - PDN #: N-12-22R1

#### Affected Part Numbers

| Discontinued Part# | Replacement Part# | Discontinued Part# | Replacement Part# |
|--------------------|-------------------|--------------------|-------------------|
| 874003AG-02        | 874003AG-02LF     | MC100ES6254FAR2    | None              |
| 874003AG-02T       | 874003AG-02LFT    | MC12430FN          | 84330BVLFF        |
| 874003AGI-02       | 874003AGI-02LF    | MC12430FNR2        | 84330BVLFT        |
| 874003AGI-02T      | 874003AGI-02LFT   | MC68160AFB         | None              |
| 8741004BGI         | 8741004BGILF      | MC68160AFBR2       | None              |
| 8741004BGIT        | 8741004BGILFT     | MC68160BFB         | None              |
| 8745BY             | 8745BYLF          | MC68160BFBR2       | None              |
| 8745BYI            | 8745BYILF         | MPC905D            | MPC905EF          |
| 8745BYIT           | 8745BYILFT        | MPC905DR2          | MPC905EF          |
| 8745BYT            | 8745BYLFT         | MPC9109FA          | MPC9109AC         |
| 874S02BMI          | 874S02BMILF       | MPC9109FAR2        | MPC9109AC         |
| 874S02BMIT         | 874S02BMILFT      | MPC9229FA          | MPC9229AC         |
| 87608AYI           | 87608AYILF        | MPC9229FAR2        | MPC9229AC         |
| 87608AYIT          | 87608AYILFT       | MPC9229FNR2        | MPC9229AC         |
| 8761CYI            | 8761CYILF         | MPC9230FA          | MPC9230AC         |
| 8761CYIT           | 8761CYILFT        | MPC9230FAR2        | MPC9230ACR2       |
| 8761CYIT-IB0       | None              | MPC9230FN          | MPC9230AC         |
| 87931AYI-147       | 87931AYI-147LF    | MPC9230FNR2        | MPC9230ACR2       |
| 87931AYI-147T      | 87931AYI-147LFT   | MPC9315FA          | None              |
| 87946AYI-147       | 87946AYI-147LF    | MPC9315FAR2        | None              |
| 87946AYI-147T      | 87946AYI-147LFT   | MPC9330FA          | None              |
| 87949AYI           | 87949AYILF        | MPC9330FAR2        | None              |
| 87949AYIT          | 87949AYILFT       | MPC9350FA          | None              |
| 87972DYI           | 87972DYILF        | MPC9350FA/W        | None              |
| 87972DYIT          | 87972DYILFT       | MPC9350FAR2        | None              |
| 87973DYI-147       | 87973DYI-147LF    | MPC9350FAR2/W      | None              |
| 87973DYI-147T      | 87973DYI-147LFT   | MPC9351FA          | None              |
| 87974CYI           | 87974CYILF        | MPC9351FAR2        | None              |
| 87974CYIT          | 87974CYILFT       | MPC9352FA          | None              |
| 889832AK           | 889832AKLF        | MPC9352FAR2        | None              |
| 889832AKT          | 889832AKLFT       | MPC940LFA          | 83940DYILF        |
| FCT388915T100PY8/C | None              | MPC940LFA/W        | None              |
| MC100ES6014DTR2    | 853S014AGILFT     | MPC940LFAR2        | 83940DYILFT       |
| MC100ES60T22D      | 85322AMILF        | MPC940LFAR2/W      | None              |
| MC100ES60T22DR2    | 85322AMILFT       | MPC941FA           | None              |
| MC100ES60T23D      | 83023AMILF        | MPC941FAR2         | None              |
| MC100ES60T23DR2    | 83023AMILFT       | MPC942CFA          | None              |
| MC100ES6111FA      | MC100ES6111AC     | MPC942CFAR2        | None              |
| MC100ES6111FAR2    | MC100ES6111AC     | MPC9443FA          | None              |
| MC100ES6210FA      | MC100ES6210AC     | MPC9443FAR2        | None              |
| MC100ES6210FAR2    | MC100ES6210ACR2   | MPC9446FA          | 87946AYI-147LF    |
| MC100ES6222TB      | 8T33FS6222        | MPC9446FAR2        | 87946AYI-147LFT   |
| MC100ES6222TBR2    | 8T33FS6222        | MPC9447FA          | 83947AYI-147LF    |
| MC100ES6254FA      | None              | MPC9447FAR2        | 83947AYI-147LFT   |

Note: For part marked with \*, please contact IDT for further information



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138  
Phone #: (408) 284-8200

## PRODUCT DISCONTINUANCE NOTICE (PDN)

### ATTACHMENT I - PDN #: N-12-22R1

#### Affected Part Numbers

| Discontinued Part# | Replacement Part# | Discontinued Part# | Replacement Part# |
|--------------------|-------------------|--------------------|-------------------|
| MPC9448FA          | 83948AYI-147LF    | MPC97H74FA         | 87974CYILF        |
| MPC9448FAR2        | 83948AYI-147LFT   | MPC97H74FAR2       | 87974CYILFT       |
| MPC9449FA          | None              | MPC9817SD          | None              |
| MPC9449FAR2        | None              | MPC9817SDR2        | None              |
| MPC94551D          | 551MILF           | MPC9850VF          | MPC9850VM         |
| MPC94551DR2        | 551MILFT          | MPC9850VFR2        | MPC9850VMR2       |
| MPC9456FA          | None              | MPC9855VFR2        | MPC9855VMR2       |
| MPC9456FAR2        | None              | MPC9865VF          | MPC9865VM         |
| MPC9600FA          | None              | MPC9865VFR2        | MPC9865VMR2       |
| MPC9600FAR2        | None              | MPC9893FA          | MPC9893AE         |
| MPC961CFA          | None              | MPC9893FAR2        | MPC9893AER2       |
| MPC961CFAR2        | None              | MPC9992FA          | None              |
| MPC962305DT-1H     | 2305-1HDCGI       | MPC9992FAR2        | None              |
| MPC962305DT-1HR2   | 2305-1HDCGI8      | MPC99J93FA         | 87993AYILF        |
| MPC9772FA          | 87972DYI-147LF    | MPC99J93FAR2       | 87993AYILFT       |
| MPC9772FA/W        | None              | QS5917T-100TQ      | QS5917T-100TJG    |
| MPC9772FAR2        | 87972DYI-147LFT   | QS5917T-100TQ8     | QS5917T-100TJG8   |
| MPC9772FAR2/W      | None              | QS5917T-132TJ      | QS5917T-132TJG    |
| MPC9773FA          | 87973DYI-147LF    | QS5917T-132TJ8     | QS5917T-132TJG8   |
| MPC9773FAR2        | 87973DYI-147LFT   | SC97H73XFA         | None              |
| MPC9774FA          | 87974CYILF        | SC97H73XFAR2       | None              |
| MPC9774FAR2        | 87974CYILFT       |                    |                   |

Note: For part marked with \*, please contact IDT for further information



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138  
Phone #: (408) 284-8200

## PRODUCT DISCONTINUANCE NOTICE (PDN)

### ATTACHMENT II - PDN #: N-12-22R1

#### Summary of Changes on Replacement Part#

| Discontinued Part# | Replacement Part# |                 |
|--------------------|-------------------|-----------------|
|                    | Changed From      | Changed To      |
| 8732AYI-01         | 8732AY-01LF       | 8732AYI-01LF    |
| 8732AYI-01T        | 8732AY-01LFT      | 8732AYI-01LFT   |
| MC100ES6014DTR2    | MC100ES6014EJR2   | 853S014AGILFT   |
| MC100ES60T22D      | MC100ES60T22EF    | 85322AMILF      |
| MC100ES60T22DR2    | MC100ES60T22EFR2  | 85322AMILFT     |
| MC100ES60T23D      | MC100ES60T23EF    | 83023AMILF      |
| MC100ES60T23DR2    | MC100ES60T23EFR2  | 83023AMILFT     |
| MC100ES6222TB      | MC100ES6222AE     | 8T33FS6222      |
| MC100ES6222TBR2    | MC100ES6222AER2   | 8T33FS6222      |
| MC100ES6254FA      | MC100ES6254AC     | None            |
| MC100ES6254FAR2    | MC100ES6254ACR2   | None            |
| MC12430FN          | MPC9230EI         | 84330BVLFF      |
| MC12430FNR2        | MPC9230EIR2       | 84330BVLFT      |
| MPC9315FA          | MPC9315AC         | None            |
| MPC9315FAR2        | MPC9315ACR2       | None            |
| MPC9330FA          | MPC9330AC         | None            |
| MPC9330FAR2        | MPC9330ACR2       | None            |
| MPC9350FA          | MPC9350AC         | None            |
| MPC9350FAR2        | MPC9350ACR2       | None            |
| MPC9350FAR2/W      | None              | None            |
| MPC9351FA          | MPC9351AC         | None            |
| MPC9351FAR2        | MPC9351ACR2       | None            |
| MPC9352FA          | MPC9352AC         | None            |
| MPC9352FAR2        | MPC9352ACR2       | None            |
| MPC940LFA          | MPC940LAC         | 83940DYILF      |
| MPC940LFA/W        | None              | None            |
| MPC940LFAR2        | MPC940LAC         | 83940DYILFT     |
| MPC940LFAR2/W      | MPC940LACR2       | None            |
| MPC941FA           | MPC941AE          | None            |
| MPC941FAR2         | MPC941AER2        | None            |
| MPC942CFA          | MPC942CAC         | None            |
| MPC942CFAR2        | MPC942CACR2       | None            |
| MPC9443FA          | MPC9443AE         | None            |
| MPC9443FAR2        | MPC9443AER2       | None            |
| MPC9446FA          | MPC9446AC         | 87946AYI-147LF  |
| MPC9446FAR2        | MPC9446ACR2       | 87946AYI-147LFT |
| MPC9447FA          | MPC9447AC         | 83947AYI-147LF  |
| MPC9447FAR2        | MPC9447ACR2       | 83947AYI-147LFT |
| MPC9448FA          | MPC9448AC         | 83948AYI-147LF  |
| MPC9448FAR2        | MPC9448ACR2       | 83948AYI-147LFT |
| MPC9449FA          | MPC9449AE         | None            |
| MPC9449FAR2        | MPC9449AER2       | None            |
| MPC94551D          | MPC94551EF        | 551MILF         |



Integrated Device Technology, Inc.  
6024 Silver Creek Valley Road, San Jose, CA 95138  
Phone #: (408) 284-8200

## PRODUCT DISCONTINUANCE NOTICE (PDN)

### ATTACHMENT II - PDN #: N-12-22R1

#### Summary of Changes on Replacement Part#

| Discontinued Part# | Replacement Part# |                 |
|--------------------|-------------------|-----------------|
|                    | Changed From      | Changed To      |
| MPC94551DR2        | MPC94551EFR2      | 551MILFT        |
| MPC9456FA          | MPC9456AC         | None            |
| MPC9456FAR2        | MPC9456ACR2       | None            |
| MPC9600FA          | MPC9600AE         | None            |
| MPC9600FAR2        | MPC9600AER2       | None            |
| MPC961CFA          | MPC961CAC         | None            |
| MPC961CFAR2        | MPC961CAC         | None            |
| MPC962305DT-1H     | MPC962305EF-1     | 2305-1HDCGI     |
| MPC962305DT-1HR2   | MPC962305EJ-1HR2  | 2305-1HDCGI8    |
| MPC9772FA          | MPC9772AE         | 87972DYI-147LF  |
| MPC9772FAR2        | MPC9772AER2       | 87972DYI-147LFT |
| MPC9773FA          | MPC9773AE         | 87973DYI-147LF  |
| MPC9773FAR2        | MPC9773AER2       | 87973DYI-147LFT |
| MPC9774FA          | MPC9774AE         | 87974CYILF      |
| MPC9774FAR2        | MPC9774AER2       | 87974CYILFT     |
| MPC97H74FA         | MPC97H74AE        | 87974CYILF      |
| MPC97H74FAR2       | MPC97H74AER2      | 87974CYILFT     |
| MPC9817SD          | MPC9817EN         | None            |
| MPC9817SDR2        | MPC9817ENR2       | None            |
| MPC9992FA          | MPC9992AC         | None            |
| MPC9992FAR2        | MPC9992ACR2       | None            |
| MPC99J93FA         | MPC99J93AC        | 87993AYILF      |
| MPC99J93FAR2       | MPC99J93ACR2      | 87993AYILFT     |
| SC97H73XFA         | SC97H73XAE        | None            |
| SC97H73XFAR2       | SC97H73XAER2      | None            |