



SAMSUNG LFD Firmware Release Notes

Year: 2017

Region: Worldwide

WMH (55)



Revision History

Version	Date	Description
1240.5	2018/06/09	WMH 6th RC Release [Regular RC and market issue fix]
1231.5	2018/11/29	WMH 5th RC Release
1220.6	2018/08/03	WMH 4th RC Release
1211.4	2018/07/06	WMH 3rd RC Release
1201.3	2018/04/09	WMH 2nd RC Release
1101.2	2018/02/06	WMH TSEC SRA Release
1100.8	2018/01/15	WMH 1 st RC Release
1002.3	2017/11/23	WMH SRA Release
1001.0	2017/11/09	WMH PRA Release

Preface

This Release note provides a brief summary of the feature additions and issues resolved in SAMSUNG LFD firmware release starting with release 1001.0. The sections in this document are organized according to release date, with the most recent releases listed first.

Compatible Models

Region	Model Codes
Worldwide	< WMH> - LH55WMHPTWC/**

Release 1240.5

1. Compatibility Notes

1.1 Version compatibility

Project	Kant-M Version	Sub-Micom Version	
WMH(55)	T-KTMEBPWWC-1240.5	Internal	T-KTMINDWWS-1001
		External	T-KTMEBWWS-1011

2. Main Firmware

2.1 Feature Additions

2.1.1 RM MagicInfo extended feature support for Flip

2.1.2 Annotation On

2.1.3 Reboot on after change Capture value

2.2 Important Bug Fixes

2.2.1 [F][00165727] Improve export file security

2.2.2 [F][00158421] Fix Capture issue for Apple device

2.2.3 [F][00162199] Fix screen mirroring from Knox Enabled mobile to Flip

2.2.4 [F][00168394] Flip losing touch after some time in case of particular scenario.

2.2.5 Virtual Keyboards [IME] was not properly displayed after rotation.

2.2.6 [F][00163411][00164226] Attached PDF File was not shown

3. Internal Sub-Micom Firmware

3.1 Feature Additions

3.1.1 N/A

3.2 Important Bug Fixes

3.2.1 N/A

4. External Sub-Micom Firmware

4.1 Feature Additions

4.1.1 N/A

4.2 Important Bug Fixes

4.2.1 N/A

Release 1231.5

5. Compatibility Notes

1.2 Version compatibility

Project	Kant-M Version	Sub-Micom Version	
WMH(55)	T-KTMEBPWWC-1231.5	Internal	T-KTMINDWWS-1001
		External	T-KTMEBWWS-1009

6. Main Firmware

6.1 Feature Additions

- 6.1.1 Add Capture On/Off
- 6.1.2 Add Touch Firmware auto update
- 6.1.3 Add PIP Screen size function(Full/pip)
- 6.1.4 improve HWR
- 6.1.5 Add Network Reset
- 6.1.6 Add 6 Pin digit (Factory Support)
- 6.1.7 Use of device name for Hostname
- 6.1.8 Image, screen mirroring, pip minimum size small resize
- 6.1.9 Add diagnosis (Email, LDAP, Printer)
- 6.1.10 Add RM(MagicInfo) support (Factory Support)
- 6.1.11 Add "Send To Only Me" function (Factory Support)
- 6.1.12 Auto Power OFF for US/KR region in OSD Menu

6.2 Important Bug Fixes

- 6.2.1 Improve export file security
- 6.2.2 Manual IP setting in 802.1x
- 6.2.3 Support screen share to Stick-CT37CC185066 dongle

7. Internal Sub-Micom Firmware

7.1 Feature Additions

- 7.1.1 N/A

7.2 Important Bug Fixes

- 7.2.1 N/A



SAMSUNG LFD Firmware Release Notes

8. External Sub-Micom Firmware

8.1 Feature Additions

8.1.1 N/A

8.2 Important Bug Fixes

8.2.1 N/A

Release 1220.6

9. Compatibility Notes

1.3 Version compatibility

Project	Kant-M Version	Sub-Micom Version	
WMH(55)	T-KTMEBPWWC-1220.6	Internal	T-KTMINDWWS-1001
		External	T-KTMEBWWS-1006

10. Main Firmware

10.1 Feature Additions

10.1.1 add Doc Viewer Function(ppt,word,pdf)

10.1.2 add Screen Lock Function

10.1.3 increase quality for annotation on image

10.2 Important Bug Fixes

10.2.1 Add Network Support for 802.1x

10.2.2 [F][802.1x] After Success full connection with 802.1x certificates delete permanently from product.

10.2.3 [F][802.1x] Blank field of Anonymous ID should be connected in FLIP as it connected in Mobile.

10.2.4 Remove SNMP Function

10.2.5 wrong ID/PW have crash when Sender Authentication is personal account

11. Internal Sub-Micom Firmware

11.1 Feature Additions

11.1.1 N/A

11.2 Important Bug Fixes

11.2.1 N/A

12. External Sub-Micom Firmware

12.1 Feature Additions

12.1.1 N/A



SAMSUNG LFD Firmware Release Notes

12.2 Important Bug Fixes

12.2.1 N/A

Release 1211.4

13. Compatibility Notes

1.4 Version compatibility

Project	Kant-M Version	Sub-Micom Version	
WMH(55)	T-KTMEBPWWC-1211.4	Internal	T-KTMINDWWS-1001
		External	T-KTMEBWWS-1005

14. Main Firmware

14.1 Feature Additions

14.1.1 Support Enterprise-WPA2 (TLS, TTLS, PEAP)

14.1.2 add Screen Sharing Function

14.1.3 OTN Support Ready

14.1.4 Showing P2P MAC (In Contact Samsung)

14.1.5 Support IPv6

14.1.6 add Help Guide in screen saver

14.1.7 Support Local Address Book

14.1.8 Add an option to switch off Guide when import source full screen Pop-up.

14.1.9 support import source Full Screen Capture

14.1.10 Minor UI Update

14.1.11 support no authentication SMTP

14.1.12 add LDAP auth(Kerberos)

14.1.13 Wifi On/OFF (In Factory)

14.2 Important Bug Fixes

14.2.1 Wifi connection lost after Reset All operation

14.2.2 Compatibility maintenance for old IWB files

14.2.3 HDMI sound plays in background of Flip app.

14.2.4 Gmail not working with SSL ON

14.2.5 support attachment pdf at iOS

15. Internal Sub-Micom Firmware

15.1 Feature Additions

15.1.1 N/A



SAMSUNG LFD Firmware Release Notes

15.2 Important Bug Fixes

15.2.1 N/A

16. External Sub-Micom Firmware

16.1 Feature Additions

16.1.1 N/A

16.2 Important Bug Fixes

16.2.1 N/A

Release 1201.3

17. Compatibility Notes

1.5 Version compatibility

Project	Kant-M Version	Sub-Micom Version	
WMH(55)	T-KTMEBPWWC-1201.3	Internal	T-KTMINDWWS-1001
		External	T-KTMEBWWS-1004

18. Main Firmware

18.1 Feature Additions

18.1.1 change format for e-mail attached file(TIFF->PDF)

18.1.2 add Clone Function

18.1.3 support multi language for IME/HWR

18.1.4 add custom screen saver function

18.1.5 modify subtitle for e-mail

18.1.6 support HID UIBC

18.1.7 Support LDAP Protocol

18.1.8 support RTL Language(Arabic/Hebrew)

18.1.9 spec modify for Access Notification - Always On

18.1.10 Supporting computer name at samba

18.1.11 minor UI update

18.2 Important Bug Fixes

18.2.1 First Roll is saved with date : 2017-01-01 after restart the Flip and ignore the current date.

18.2.2 add dhcp hostname ("Samsung")

18.2.3 HDMI/Screen mirroring audio is audible even after screen saver is on screen

18.2.4 black board roll showed like white board at open menu after sensor off and on

18.2.5 blank page saved after sensor off and on

18.2.6 black screen for windows 8.1 mirroring resize

18.2.7 showing lock file contents

18.2.8 image line shifting when 1366x768 Screen Mirroring Capture

19. Internal Sub-Micom Firmware

19.1 Feature Additions

19.1.1 N/A



SAMSUNG LFD Firmware Release Notes

19.2 Important Bug Fixes

19.2.1 N/A

20. External Sub-Micom Firmware

20.1 Feature Additions

20.1.1 N/A

20.2 Important Bug Fixes

20.2.1 N/A



Release 1101.2

21. Compatibility Notes

1.6 Version compatibility

Project	Kant-M Version	Sub-Micom Version	
WMH(55)	T-KTMEBPWWC-1101.2	Internal	T-KTMINDWWS-1001
		External	T-KTMEBWWS-1003

22. Main Firmware

22.1 Feature Additions

22.2 Important Bug Fixes

22.2.1 Import/export icon fix in simple Chinese

22.2.2 Fix PIN bug

23. Internal Sub-Micom Firmware

23.1 Feature Additions

23.1.1 N/A

23.2 Important Bug Fixes

23.2.1 N/A

24. External Sub-Micom Firmware

24.1 Feature Additions

24.1.1 N/A

24.2 Important Bug Fixes

24.2.1 N/A

Release 1100.8

25. Compatibility Notes

1.7 Version compatibility

Project	Kant-M Version	Sub-Micom Version	
WMH(55)	T-KTMEBPWWC-1100.8	Internal	T-KTMINDWWS-1001
		External	T-KTMEBWWS-1003

26. Main Firmware

26.1 Feature Additions

- 26.1.1 edit file name in Open
- 26.1.2 add sorting in Open
- 26.1.3 add panel type for 55A6AUYKM
- 26.1.4 add Reset Interval Menu
- 26.1.5 csv file import (hidden function)
- 26.1.6 Setting Menu modify

26.2 Important Bug Fixes

- 26.2.1 Auto Save Bug Fix
- 26.2.2 Screen Mirroring Bug Fix
- 26.2.3 fix Crash when sending Email

27. Internal Sub-Micom Firmware

27.1 Feature Additions

- 27.1.1 N/A

27.2 Important Bug Fixes

- 27.2.1 N/A

28. External Sub-Micom Firmware

28.1 Feature Additions

- 28.1.1 N/A

28.2 Important Bug Fixes

- 28.2.1 N/A



Release 1001.2

29. Compatibility Notes

1.8 Version compatibility

Project	Kant-M Version	Sub-Micom Version	
WMH(55)	T-KTMEBPWWC-1001.2	Internal	T-KTMINDWWS-1001
		External	T-KTMEBWWS-1001

30. Main Firmware

30.1 Feature Additions

30.1.1 SRA Release

30.2 Important Bug Fixes

30.2.1 N/A

31. Internal Sub-Micom Firmware

31.1 Feature Additions

31.1.1 SRA Release

31.2 Important Bug Fixes

31.2.1 N/A

32. External Sub-Micom Firmware

32.1 Feature Additions

32.1.1 SRA Release

32.2 Important Bug Fixes

32.2.1 N/A



Release 1000.9

1. Compatibility Notes

1.9 Version compatibility

Project	Kant-M Version	Sub-Micom Version	
WMH(55)	T-KTMEBPWWC-1000.9	Internal	T-KTMINDWWS-1001
		External	T-KTMEBWWS-1000

2. Main Firmware

2.1 Feature Additions

2.1.1 PRA Release

2.2 Important Bug Fixes

2.2.1 N/A

3. Internal Sub-Micom Firmware

3.1 Feature Additions

3.1.1 PRA Release

3.2 Important Bug Fixes

3.2.1 N/A

4. External Sub-Micom Firmware

4.1 Feature Additions

4.1.1 PRA Release

4.2 Important Bug Fixes

4.2.1 N/A