

Firmware Release Notes

CloudMesh Satellite (NS-01)



Copyright

Copyright© 2020 NetComm Wireless Limited. All rights reserved.

NetComm Wireless Limited was acquired by Casa Systems, Inc. a Delaware company on 1 July 2019. The information contained herein is proprietary to Casa Systems, Inc. No part of this document may be translated, transcribed, reproduced, in any form, or by any means without prior written consent of Casa Systems, Inc.

Trademarks and registered trademarks are the property of NetComm Wireless Limited or their respective owners. Specifications are subject to change without notice. Images shown may vary slightly from the actual product.



Note – This document is subject to change without notice.

Document history

This document covers the following product:

CloudMesh Satellite

VER.	DOCUMENT DESCRIPTION	DATE
v1.0	Initial document release	3 July 2020
v1.1	Updated for v2.1.42	3 August 2020

Table i. - Document revision history

Contents

Firmware details	4
Version history	4
v2.1.42.....	4
Enhancements.....	4
v2.1.38.....	4
Enhancements.....	4
v2.1.26.....	4

Firmware details

ITEM	DESCRIPTION
Model	NS-01
Product Name	CloudMesh Satellite
Date	3 August 2020
Firmware Version	2.1.42
Official / Beta Firmware	Official
File Name	ns01_squashfs_sysupgrade_02.01.42-0801.bin
File Size	15.9 MB
MD5 Checksum	47A6AB6BBE3BBAA93DE4412EFF308F11

Version history

v2.1.42

Enhancements

- Improved performance of video conferencing over WiFi

v2.1.38

Enhancements

- Improved mesh stability when the AP changes its WiFi SSID or the WiFi password (TT 40514)
- Fixed the NS-01 LED behaviour when daisy chained (TT 40729)
- Fixed the random issue where NS-01 will sometimes reboot during Mesh reconnection process (TT 40509)
- Fixed a memory issue (TT 40508)
- Updated NS-01 Agent firmware version to match with the firmware name (TT 40322)

v2.1.26

- Initial firmware release