

Section 14. High-Speed PWM

HIGHLIGHTS

This section of the manual contains the following major topics:

14.1 Introduction	
14.2 Features	14-2
14.3 Control Registers	
14.4 Architecture Overview	
14.5 Module Description	
14.6 PWM Operating Modes	
14.7 PWM Generator	
14.8 PWM Trigger	
14.9 PWM Interrupts	
14.10 PWM Fault Pins	
14.11 Special Features	
14.12 PWM Output Pin Control	14-111
14.13 Immediate Update of PWM Duty Cycle	
14.14 Power-Saving Modes	
14.15 External Control of Individual Time Base(s)	
14.16 Application Information	
14.17 Register Map	
14.18 Related Application Notes	
14.19 Revision History	

Note: This family reference manual section is meant to serve as a complement to device data sheets. Depending on the device variant, this manual section may not apply to all dsPIC33E/PIC24E devices.

Please consult the note at the beginning of the "**High-Speed PWM**" chapter in the current device data sheet to check whether this document supports the device you are using.

Device data sheets and family reference manual sections are available for download from the Microchip Worldwide Web site at: http://www.microchip.com

14.1 INTRODUCTION

This section describes the High-Speed Pulse-Width Modulator (PWM) module and its associated operational modes. The High-Speed PWM module in the dsPIC33E/PIC24E device family supports a wide variety of PWM modes and is ideal for power conversion/motor control applications. Some of the common applications include:

- AC-to-DC converters
- DC-to-DC converters
- AC and DC motors: BLDC, PMSM, ACIM, SRM, etc.
- Inverters
- Battery chargers
- Digital lighting
- Uninterrupted Power Supply (UPS)
- Power Factor Correction (PFC) (e.g., Interleaved PFC and Bridgeless PFC)

14.2 FEATURES

The High-Speed PWM module consists of the following major features:

- Up to seven PWM generators, each with an individual time base
- Two PWM outputs per PWM generator
- · Individual period and duty cycle for each PWM output
- Duty cycle, dead time, phase shift and frequency resolution equal to the system clock source (Tosc)
- · Independent fault and current-limit inputs for up to 14 PWM outputs
- Redundant Output mode
- Independent Output mode (this feature is not available on all devices)
- · Push-Pull Output mode
- · Complementary Output mode
- · Center-Aligned PWM mode
- · Output override control
- Special Event Trigger
- · PWM capture feature
- Prescaler for input clock
- ADC triggering with PWM
- Independent PWM frequency, duty cycle and phase shift changes
- Leading-Edge Blanking (LEB) functionality
- Dead time compensation
- Output clock chopping

14.3 CONTROL REGISTERS

Note: Not all registers are available on all devices. Refer to the "**High-Speed PWM**" chapter in the specific device data sheet for availability.

The following registers control the operation of the High-Speed PWM module:

PTCON: PWM Time Base Control Register

- Enables or disables the High-Speed PWM module
- Sets the Special Event Trigger for the ADC
- Enables or disables immediate period updates
- Selects the synchronizing source for the master time base
- Specifies synchronization settings
- PTCON2: PWM Clock Divider Select Register 2
 - Provides the clock prescaler to the PWM master time base

• PTPER: Primary Master Time Base Period Register

Provides the PWM time period value

- STCON: PWM Secondary Master Time Base Control Registe ⁽¹⁾
 - Enables or disables immediate period updates based on the secondary master time base
 - Selects the synchronization source for the secondary master time base
 - Specifies the synchronization setting for secondary master time base control
- STCON2: PWM Secondary Clock Divider Select Register 2(1) Provides the clock prescaler to the PWM secondary master time base

 STPER: Secondary Master Time Base Period Register(1) Provides the secondary master time base period value

MDC: PWM Master Duty Cycle Register

Provides the PWM master duty cycle value

SEVTCMP: PWM Special Event Compare Register

Provides the compare value that is used to trigger the ADC module

• SSEVTCMP: PWM Secondary Special Event Compare Register(1)

Provides the compare value that is used to trigger the ADC module based on the secondary master time base

- CHOP: PWM Chop Clock Generator Register
 - Provides the chop clock frequency
 - Enables or disables the chop clock generator
- PWMKEY: PWM Unlock Register(1)
 - Writes the unlock sequence to allow writes to the IOCONx and FCLCONx registers
- PWMCONx: PWM Control Register
 - Enables or disables fault interrupt, current-limit interrupt and primary trigger interrupt
 - Provides the interrupt status for fault interrupt, current-limit interrupt and primary trigger interrupt
 - Selects the type of time base (master time base or independent time base)
 - Selects the type of duty cycle (master duty cycle or independent duty cycle)
 - Controls Dead Time mode
 - Enables or disables Center-Aligned mode
 - Controls the external PWM Reset operation
 - Enables or disables immediate updates of the duty cycle, phase offset, independent time base period
- IOCONx: PWM I/O Control Register
 - Enables or disables PWM pin control feature (PWM control or GPIO)
 - Controls fault/current limit override values
 - Enables PWMxH and PWMxL pin swapping
 - Controls the PWMxH and PWMxL output polarity
 - Controls the PWMxH and PWMxL output if any of the following modes is selected:
 - Complementary mode
 - Push-Pull mode
 - True Independent mode

• FCLCONx: PWM Fault Current-Limit Control Register

- Selects the current-limit control signal source
- Selects the current-limit polarity
- Enables or disables Current-Limit mode
- Selects the fault control signal source
- Configures the fault polarity
- Enables or disables Fault mode
- PDCx: PWM Generator Duty Cycle Register⁽¹⁾
 - Provides the duty cycle value for the PWMxH and PWMxL outputs, if master time base is selected
 - Provides the duty cycle value for the PWMxH output, if independent time base is selected
- PHASEx: PWM Primary Phase Shift Register
 - Provides the phase shift value for the PWMxH and PWMxL output, if master time base is selected
 - Provides the independent time base period for the PWMxH output, if independent time base is selected
- SDCx: PWM Secondary Duty Cycle Register^(1,2)
 - Provides the duty cycle value for the PWMxL output, if independent time base is selected
- SPHASEx: PWM Secondary Phase Shift Register^(1,2,3)
 - Provides the phase shift for the PWMxL output, if the master time base is selected
 - Provides the independent time base period value for the PWMxL output, if the independent time base is selected
- DTRx: PWM Dead Time Register
 - Provides the dead time value for the PWMxH output, if positive dead time is selected
 - Provides the dead time value for the PWMxL output, if negative dead time is selected
- ALTDTRx: PWM Alternate Dead Time Register
 - Provides the dead time value for the PWMxL output, if positive dead time is selected
 - Provides the dead time value for the PWMxH output, if negative dead time is selected
- TRIGx: PWM Primary Trigger Compare Value Register

Provides the compare value to generate the primary PWM trigger

- TRGCONx: PWM Trigger Control Register
 - Enables the PWMx trigger postscaler start event
 - Specifies the number of PWM cycles to skip before generating the first trigger
- LEBCONx: Leading-Edge Blanking Control Register
 - Selects the rising or falling edge of the PWM output for LEB
 - Enables or disables LEB for fault and current-limit inputs
- LEBDLYx: Leading-Edge Blanking Delay Register

Provides leading-edge blanking delay for the fault and current-limit inputs

• PWMCAPx: Primary PWM Time Base Capture Register

Provides the captured independent time base value when a leading edge is detected on the current-limit input, and when LEB processing on the current-limit input signal is completed

- AUXCONx: PWM Auxiliary Control Register
 - Selects PWM state blank and chop clock sources
 - Selects PWMxH and PWMxL output chopping functionality

•			•				
R/W-0	U-0	R/W-0	HS/HC-0	R/W-0	R/W-0	R/W-0	R/W-0
PTEN	—	PTSIDL	SESTAT	SEIEN	EIPU ⁽¹⁾	SYNCPOL ⁽¹⁾	SYNCOEN ⁽¹⁾
bit 15							bit 8
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
SYNCEN ⁽¹⁾	S	/NCSRC<2:0>	,(1)		SEVTF	S<3:0> ⁽¹⁾	
bit 7				ļ			bit 0
l egend:		HC = Clearer	1 in Hardware	HS = Set in I	Hardware		
R = Readable	bit	W = Writable	bit	U = Unimple	mented bit rea	ad as '0'	
-n = Value at F	POR	'1' = Bit is se	t	'0' = Bit is cle	eared	x = Bit is unkn	own
			-				
bit 15	PTEN: PWM	Module Enabl	e bit				
	1 = PWM mo	dule is enable dule is disable	d				
bit 14	Unimplemen	ted: Read as	"O'				
bit 13	PTSIDL: PWI	M Time Base S	Stop in Idle Mo	de bit			
	1 = PWM time	e base halts in	CPU Idle mod	de			
	0 = PWM time	e base runs in	CPU Idle mod	le			
bit 12	SESTAT: Spe	cial Event Inte	errupt Status bi	t			
	0 = Special E	vent Interrupt	is penaing is not pendina				
bit 11	SEIEN: Speci	ial Event Interi	upt Enable bit				
	1 = Special E	vent Interrupt	is enabled				
	0 = Special E	vent Interrupt	is disabled				
bit 10	EIPU: Enable	Immediate Pe	eriod Updates	bit ⁽¹⁾			
	1 = Active Pe 0 = Active Pe	riod register is riod register u	pdated immo	ediately on PWM cycle	boundaries		
bit 9	SYNCPOL: S	Synchronize In	put and Outpu	t Polarity bit ⁽¹⁾			
	1 = SYNCIx/S	SYNCO polarit	y is inverted (a	active-low)			
	0 = SYNCIx/S	SYNCO is activ	/e-high	(1)			
bit 8	SYNCOEN: F	Primary Time E	ase Sync Ena	ible bit(")			
	0 = SYNCO c	output is disabl	ed				
bit 7	SYNCEN: Ex	ternal Time Ba	ase Synchroniz	zation Enable	bit ⁽¹⁾		
	1 = External s	synchronizatio	n of primary tir	ne base is ena	abled		
	0 = External s	synchronizatio	n of primary tir	ne base is dis	abled		
bit 6-4	SYNCSRC<2	:: 0>: Synchror	IOUS SOURCE S	election bits(")		ce Defer to the	"High_Spood
	PWM" chapte	er in the specif	ic device data	sheet for avai	lability.		Ingn-Speed
bit 3-0	SEVTPS<3:0	PWM Spec	ial Event Trigg	er Output Pos	tscaler Select I	oits ⁽¹⁾	
	1111 = 1:16	postscaler gen	erates Special	Event trigger	at every 16th o	compare match	event
	•						
	•	()		-	1		
	0001 = 1:2 pc 0000 = 1:1 pc	ostscaler gene ostscaler gene	rates Special I rates Special I	Event trigger a Event trigger a	at every second at every compa	re match event	h event
Note 1: The	ese bits should l	be changed or	ly when PTEN	l = 0. In additio	on, when using	the SYNCIx fea	ature, the user

Register 14-1: PTCON: PWM Time Base Control Register

Note 1: These bits should be changed only when PTEN = 0. In addition, when using the SYNCIx feature, the user application must program the period register with a value that is slightly larger than the expected period of the external synchronization input signal.

U-0	U-0	U-0	U-0	U-0	U-0	U-0	U-0
—	—	—	—	—	—	_	—
bit 15							bit 8
U-0	U-0	U-0	U-0	U-0	R/W-0	R/W-0	R/W-0
—	—	—	—	—	P	CLKDIV<2:0>(1)
bit 7							bit 0
Legend:							
R = Readable	bit	W = Writable	bit	U = Unimpler	mented bit, read	1 as '0'	
-n = Value at F	e at POR '1' = Bit is set '0' = Bit is cleared x = Bit is unknown			nown			

Register 14-2: PTCON2: PWM Clock Divider Select Register 2

bit 15-3 Unimplemented: Read as '0'

bit 2-0 PCLKDIV<2:0>: PWM Input Clock Prescaler (Divider) Select bits⁽¹⁾

- 111 = Reserved 110 = Divide by 64 101 = Divide by 32 100 = Divide by 16 011 = Divide by 8 010 = Divide by 4 001 = Divide by 2 000 = Divide by 1, maximum PWM timing resolution (power-on default)
- **Note 1:** These bits should be changed only when PTEN = 0. Changing the clock selection during operation will yield unpredictable results.

Register 14-3: PTPER: Primary Master Time Base Period Register

R/W-1	R/W-1	R/W-1	R/W-1	R/W-1	R/W-1	R/W-1	R/W-1
			PTPEF	R<15:8> ⁽¹⁾			
bit 15							bit 8
R/W-1	R/W-1	R/W-1	R/W-1	R/W-1	R/W-0	R/W-0	R/W-0
			PTPE	R<7:0> ⁽¹⁾			
bit 7							bit 0
Legend:							
R = Readable	bit	W = Writable I	bit	U = Unimpler	mented bit, rea	d as '0'	
-n = Value at P	POR	'1' = Bit is set		'0' = Bit is cle	ared	x = Bit is unkr	nown

bit 15-0 **PTPER<15:0>:** Primary Master Time Base (PMTMR) Period Value bits⁽¹⁾

Note 1: 1 LSb = 1 Tosc. For example, 7.14 ns for 70 MIPS operation.

U-0	U-0	U-0	HS/HC-0	R/W-0	R/W-0	R/W-0	R/W-0
	_	—	SESTAT	SEIEN	EIPU ⁽²⁾	SYNCPOL	SYNCOEN
bit 15							bit 8
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
SYNCEN		SYNCSRC<2:0)>		SEVT	PS<3:0>	10110
bit 7							bit (
Logond:		HC - Cleare	d in Hardware	HS - Sot in H	lardware		
R = Readable	hit	W = Writable	hit	II = I Inimpler	nented hit rea	d as '0'	
-n = Value at P	POR	'1' = Bit is se	t	'0' = Bit is cle	ared	x = Bit is unkr	nown
bit 15-13	Unimpleme	nted: Read as	ʻ0 '				
bit 12	SESTAT: Sp	ecial Event Inte	errupt Status bi	t			
	1 = Seconda	ary Special Eve	nt Interrupt is p	bending			
bit 11	SEIEN Sner	ny Special Even	runt Enable bit	iot perioling			
bit II	1 = Seconda	ary Special Eve	nt Interrunt is e	nabled			
	0 = Seconda	ary Special Eve	nt Interrupt is c	lisabled			
bit 10	EIPU: Enable Immediate Period Updates bit ⁽²⁾						
	1 = Active S 0 = Active S	econdary Perio econdary Perio	d register is up d register upda	odated immedia ates occur on F	ately YWM cycle bou	undaries	
bit 9	SYNCPOL:	Synchronize In	put and Outpu	t Polarity bit			
	1 = SYNCO2 0 = SYNCO2	2 output is activ 2 output is activ	re-low re-high				
bit 8	SYNCOEN:	Secondary Ma	ster Time Base	e Sync Enable I	bit		
	1 = SYNCO2 0 = SYNCO2	2 output is enat 2 output is disa	bled bled				
bit 7	SYNCEN: E	xternal Second	ary Master Tim	ne Base Synch	ronization Ena	ble bit	
	1 = External 0 = External	synchronizatio synchronizatio	n of secondary n of secondary	v time base is e v time base is d	enabled lisabled		
bit 6-4	SYNCSRC<	2:0>: Seconda	ry Time Base S	Sync Source Se	election bits		
	These bits se PWM " chapt	elect the SYNC ter in the specif	Ix or PTGOx ir ic device data	put as the synd sheet for availa	chronous sour ability.	ce. Refer to the	"High-Speed
bit 3-0	SEVTPS<3:	0>: PWM Seco	ndary Special	Event Trigger (Output Postsca	aler Select bits	
	1111 = 1:16	Postscale					
	•						
	•						
	•						
	0001 = 1:2 F	Postscale					

(1)

Note 1: This register is not available on all devices. Refer to the "High-Speed PWM" chapter of the specific device data sheet for availability.

2: This bit only applies to the secondary master time base period.

U-0	U-0	U-0	U-0	U-0	U-0	U-0	U-0
_	—	—	—	—	—	—	_
bit 15							bit 8
U-0	U-0	U-0	U-0	U-0	R/W-0	R/W-0	R/W-0
_	_	—	—	—	P	CLKDIV<2:0> ⁽²	2)
bit 7							bit 0
Legend:							
R = Readable	bit	W = Writable	bit	U = Unimpler	mented bit, read	as '0'	
-n = Value at P	POR	'1' = Bit is set		'0' = Bit is cle	ared	x = Bit is unkr	nown

Register 14-5: STCON2: PWM Secondary Clock Divider Select Register 2⁽¹⁾

bit 15-3 Unimplemented: Read as '0'

bit 2-0 PCLKDIV<2:0>: PWM Input Clock Prescaler (Divider) Select bits⁽²⁾
111 = Reserved
110 = Divide by 64
101 = Divide by 32
100 = Divide by 16
011 = Divide by 8

- 010 = Divide by 4
- 001 = Divide by 2

000 = Divide by 1, maximum PWM timing resolution (power-on default)

- Note 1: This register is not available on all devices. Refer to the "High-Speed PWM" chapter of the specific device data sheet for availability.
 - **2:** These bits should be changed only when PTEN = 0. Changing the clock selection during operation will yield unpredictable results.

Register 14-6:	STPER: Secondar	y Master Time Base Period Register ⁽¹⁾
----------------	-----------------	---

bit 15							bit 8
			STPER	<15:8>			
R/W-1	R/W-1	R/W-1	R/W-1	R/W-1	R/W-1	R/W-1	R/W-1

R/W-1	R/W-1	R/W-1	R/W-1	R/W-1	R/W-1	R/W-1	R/W-1
			STPE	R<7:0>			
bit 7							bit 0

Legend:			
R = Readable bit	W = Writable bit	U = Unimplemented bit, read	l as '0'
-n = Value at POR	'1' = Bit is set	'0' = Bit is cleared	x = Bit is unknown

bit 15-0 STPER<15:0>: Secondary Master Time Base Period Value bits

Note 1: This register is not available on all devices. Refer to the "High-Speed PWM" chapter of the specific device data sheet for availability.

Register 14-7: MDC: PWM Master Duty Cycle Register

R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
	-		MDC<	<15:8>			-
bit 15							bit 8
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			MDC	<7:0>			
bit 7							bit 0

Legend:			
R = Readable bit	W = Writable bit	U = Unimplemented bit, read	as '0'
-n = Value at POR	'1' = Bit is set	'0' = Bit is cleared	x = Bit is unknown

bit 15-0 MDC<15:0>: Master PWM Duty Cycle Value bits

Register 14-8: SEVTCMP: PWM Special Event Compare Register

R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0		
	1011 0	1011 0	1011 0	1011 0	1011 0	1011 0	1411 0		
			SEVTCM	1P<15:8>					
			021101						
bit 15							bit 8		
R/W-0	R/W-0	R/\\/_0	R/\\/_0	R/W-0	R/W-0	R/W-0	R/\\/_0		
10,00-0		10.00-0	10,00-0	10,44=0	10,44-0	10.00-0	10/00-0		
	SEVTCMP<7.0>								
bit 7							bit 0		

Legend:			
R = Readable bit	W = Writable bit	U = Unimplemented bit, read	1 as '0'
-n = Value at POR	'1' = Bit is set	'0' = Bit is cleared	x = Bit is unknown

bit 15-0 SEVTCMP<15:0>: Special Event Compare Count Value bits

.

R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			SSEVTO	CMP<15:8>			
bit 15							bit 8
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			SSEVT	CMP<7:0>			
bit 7							bit 0
Legend:							
R = Readable	R = Readable bit W = Writable bit U = Unimplemented bit, read as '0'			d as '0'			
-n = Value at P	POR	'1' = Bit is set '0' = Bit is cleared x = Bit is unknow			nown		

Register 14-9: SSEVTCMP: PWM Secondary Special Event Compare Register⁽¹⁾

bit 15-0 SSEVTCMP<15:0>: Secondary Special Event Compare Count Value bits The optional SSEVTCMP register and the optional secondary master time base provide an additional Special Event Trigger. The secondary special event trigger also has its own postscaler controlled by the SEVTPS<3:0> bits in the STCON register.

Register 14-10: CHOP: PWM Chop Clock Generator Register

R/W-0	U-0	U-0	U-0	U-0	U-0	R/W-0	R/W-0
CHPCLKEN	—	—	—	—		CHOPC	LK<9:8>
bit 15						•	bit 8
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			CHOPC	CLK<7:0>			
bit 7							bit 0
Legend:							
R = Readable bit W = Writable bit			bit	U = Unimpler	mented bit, read	l as '0'	
-n = Value at POR '1' = Bit is set '0'			'0' = Bit is cle	ared	x = Bit is unkr	nown	
bit 15	CHPCLKEN:	Enable Chop C	lock Generat	tor bit			
	1 = Chop cloo	ck generator is e	enabled				
	0 = Chop cloo	ck generator is o	disabled				
bit 14-10	Unimplemen	ted: Read as '0)'				
bit 9-0	CHOPCLK<9	:0>: Chop Cloc	k Divider bits	;			
	Chop Freque	ncy = (Fp/PLKD	IV) / (CHOP	CLK<9:0> + 1)			
	As an examp	le, for devices i	running at 60	MIPS, a value	e of all zeros wi	Il yield a 60 MI	Hz chop clock
	(period = 16.7)	ns) with the PV	VIM clock pres	scaler configure	ed for fastest clo	ock. A value of '	00000000001'
	for fastest clo	ck.	vili ylelu a 50				
Note: The	chop clock ger	nerator operates	s with the Pr	rimary PWM C	lock Prescaler	bits (PCLKDI)	/<2:0>) in the
PTC	ON2 register.			2		`	,

Note 1: This register is not available on all devices. Refer to the "High-Speed PWM" chapter of the specific device data sheet for availability.

R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			PWMK	EY<15:8>			
bit 15							bit 8
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			PWMK	EY<7:0>			
bit 7							bit 0
Legend:							
R = Readable bit W = Writable bit			bit	U = Unimplemented bit, read as '0'			
-n = Value at POR (1' = Bit is set (0' = Bit is cleared x = Bit is u			x = Bit is unkr	nown			

Register 14-11: PWMKEY: PWM Unlock Register⁽¹⁾

bit 15-0 **PWMKEY<15:0>:** PWM Unlock bits

If the PWMLOCK Configuration bit is asserted (PWMLOCK = 1), the IOCONx and FCLCONx registers are writable only after the proper sequence is written to the PWMKEY register. If the PWMLOCK Configuration bit is deasserted (PWMLOCK = 0), the IOCONx and FCLCONx registers are writable at all times. Refer to 14.5.3 "Write Protection" for further details of the unlock sequence.

Note 1: This register is implemented only in devices where the PWMLOCK Configuration bit is present in the FOSCSEL Configuration register.

HS/HC-0) HS/HC-0	HS/HC-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
FLTSTAT ⁽	¹⁾ CLSTAT ⁽¹⁾	TRGSTAT	FLTIEN	CLIEN	TRGIEN	ITB ⁽³⁾	MDCS ⁽³⁾
bit 15	•				•		bit 8
R/W-0	R/W-0	R/W-0	U-0	R/W-0	R/W-0	R/W-0	R/W-0
D	TC<1:0>	DTCP ⁽⁵⁾	—	MTBS	CAM ^(2,3)	XPRES ⁽⁴⁾	IUE ⁽³⁾
bit 7							bit 0
Legend:		HC = Cleared	in Hardware	HS = Set in H	lardware		
R = Readal	ble bit	W = Writable	bit	U = Unimpler	mented bit, read	l as '0'	
-n = Value a	at POR	'1' = Bit is set		'0' = Bit is cle	ared	x = Bit is unkn	own
bit 15	FLTSTAT: Fat 1 = Fault inter	ult Interrupt Sta rupt is pending	itus bit ⁽¹⁾				
	0 = No fault in This bit is clea	nterrupt is pend ared by setting	ing FLTIEN = 0.				
bit 14	CLSTAT: Curr	rent-Limit Interi	upt Status bit	(1)			
	1 = Current-lir	mit interrupt is	pending				
	0 = No curren	t-limit interrupt					
hit 13	TRGSTAT: Tri	inder Interrunt	Status hit				
bit to	1 = Trigger int	terrupt is pendi	na				
	0 = No trigger This bit is clea	interrupt is pe ared by setting	nding TRGIEN = 0.				
bit 12	FLTIEN: Fault	t Interrupt Enal	ole bit				
	1 = Fault inter 0 = Fault inter	rupt is enabled	l d and the FLT:	STAT bit is cle	ared		
bit 11	CLIEN: Curre	nt-Limit Interru	pt Enable bit				
	1 = Current-lir 0 = Current-lir	mit interrupt en mit interrupt dis	abled abled and the	CLSTAT bit is	scleared		
bit 10	TRGIEN: Trig	ger Interrupt E	nable bit				
	1 = A trigger e 0 = Trigger ev	event generate vent interrupts a	s an interrupt are disabled a	request nd the TRGST	AT bit is cleared	t	
bit 9	ITB: Independ	dent Time Base	e Mode bit ⁽³⁾				
	1 = PHASEx/3 0 = PTPER re	SPHASEx regised services services services services services and services services services services services s	sters provide t timing for this	ime base perio s PWM genera	od for this PWM ator	generator	
bit 8	MDCS: Maste	er Duty Cycle F	legister Select	t bit ⁽³⁾			
	1 = MDC regis 0 = PDCx and	ster provides d d SDCx registe	uty cycle infor rs provide duty	mation for this y cycle informa	PWM generato ation for this PW	r /M generator	
Note 1: 2:	Software must clea The Independent T CAM bit is ignored.	ar the interrupt īme Base mod	status here, a e (ITB = 1) mu	nd in the corre ust be enabled	esponding IFS b I to use Center-/	it in the Interrup Aligned mode. I	ot Controller. f ITB = 0, the

Register 14-12: PWMCONx: PWM Control Register

- **3**: These bits should not be changed after the PWM is enabled (PTEN = 1).
- **4:** To operate in External Period Reset mode, the ITB bit must be set to '1' and the CLMOD bit in the FCLCONx register must be set to '0'.
- **5:** For DTCP to be effective, DTC<1:0> must be set to '11'; otherwise, DTCP is ignored.
- 6: Negative dead time is only implemented for Edge-Aligned mode (CAM = 0).

Regis	ter 14	-12: PWMCONx: PWM Control Register (Continued)
bit 7-6	3	DTC<1:0>: Dead Time Control bits 11 = Dead Time Compensation mode enabled 10 = Dead time function is disabled 01 = Negative dead time actively applied for Complementary Output mode ⁽⁶⁾ 00 = Positive dead time actively applied for all output modes
bit 5		 DTCP: Dead Time Compensation Polarity bit⁽⁵⁾ 1 = If DTCMPx pin = 0, PWMxL is shortened, and PWMxH is lengthened If DTCMPx pin = 1, PWMxH is shortened, and PWMxL is lengthened 0 = If DTCMPx pin = 0, PWMxH is shortened, and PWMxL is lengthened If DTCMPx pin = 1, PWMxL is shortened, and PWMxL is lengthened
bit 4		Unimplemented: Read as '0'
bit 3		 MTBS: Master Time Base Select bit 1 = PWM generator uses the secondary master time base for synchronization and the clock source for the PWM generation logic (if secondary time base is available) 0 = PWM generator uses the primary master time base for synchronization and the clock source for the PWM generation logic
bit 2		CAM: Center-Aligned Mode Enable bit ^(2,3) 1 = Center-Aligned mode is enabled 0 = Edge-Aligned mode is enabled
bit 1		 XPRES: External PWM Reset Control bit⁽⁴⁾ 1 = Current-limit source resets primary local time base for this PWM generator if it is in Independent Time Base mode 0 = External pins do not affect PWM time base
bit 0		 IUE: Immediate Update Enable bit⁽³⁾ 1 = Updates to the active MDC/PDCx/SDCx/DTRx/ALTDTRx/PHASEx/SPHASEx registers are immediate 0 = Updates to the active MDC/PDCx/SDCx/DTRx/ALTDTRx/PHASEx/SPHASEx registers are synchronized to the PWM time base
Note	1: 3 2: 7 (3: 7	Software must clear the interrupt status here, and in the corresponding IFS bit in the Interrupt Controller. The Independent Time Base mode (ITB = 1) must be enabled to use Center-Aligned mode. If ITB = 0, the CAM bit is ignored. These bits should not be changed after the PWM is enabled (PTFN = 1).
	4	The analysis in External Deviat Deviat mode, the ITD bit must be act to (1) and the CLMOD bit in the

- 4: To operate in External Period Reset mode, the ITB bit must be set to '1' and the CLMOD bit in the FCLCONx register must be set to '0'.
- **5**: For DTCP to be effective, DTC<1:0> must be set to '11'; otherwise, DTCP is ignored.
- **6:** Negative dead time is only implemented for Edge-Aligned mode (CAM = 0).

R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
PENH	PENL	POLH	POLL	PMO	D<1:0>	OVRENH	OVRENL
bit 15						•	bit 8
D 444 A	5444.0	D 444 0	D # 4 / 0	D 444 0	D 444 0	5444.0	D 444 A
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
bit 7	AT<1:0>	FLIDAI	\$1:0>(*,=/	CLDA	1<1:0>	SWAP UST	
							bit 0
Legend:							
R = Readable	e bit	W = Writable	bit	U = Unimpler	nented bit, read	d as '0'	
-n = Value at	POR	'1' = Bit is set		'0' = Bit is cle	ared	x = Bit is unkr	iown
bit 15	PENH: PWM: 1 = PWM mod 0 = GPIO mod	xH Output Pin (dule controls P dule controls P	Ownership bi WMxH pin WMxH pin	t			
bit 14	PENL: PWM> 1 = PWM mod 0 = GPIO mod	L Output Pin C dule controls P dule controls P	Ownership bit WMxL pin WMxL pin				
bit 13	POLH: PWMx 1 = PWMxH p 0 = PWMxH p	xH Output Pin I bin is active-low bin is active-hig	Polarity bit / h				
bit 12	POLL: PWM> 1 = PWMxL p 0 = PWMxL p	kL Output Pin F in is active-low in is active-hig	Polarity bit h				
bit 11-10	PMOD<1:0>: 11 = PWM I/C 10 = PWM I/C 01 = PWM I/C 00 = PWM I/C	PWM # I/O Pir D pin pair is in ⁻ D pin pair is in F D pin pair is in F D pin pair is in 6	n Mode bits Frue Indepen Push-Pull Ou Redundant O Complementa	dent PWM Outp tput mode utput mode ary Output mode	out mode ⁽³⁾ e		
bit 9	OVRENH: Ov 1 = OVRDAT 0 = PWM gen	verride Enable f <1> provides d herator provides	for PWMxH F ata for output s data for PW	Pin bit t on PWMxH pir /MxH pin	ı		
bit 8	OVRENL: Ov 1 = OVRDAT· 0 = PWM gen	erride Enable f <0> provides d herator provides	for PWMxL Pi ata for output s data for PW	in bit t on PWMxL pin /MxL pin	I		
bit 7-6	OVRDAT<1:0 If OVERENH If OVERENL	<pre>>: State⁽²⁾ for I = 1, OVRDAT< = 1, OVRDAT</pre>	PWMxH, PW <1> provides 0> provides (MxL Pins if Ove data for PWMxI data for PWMxL	erride is Enable H -	d bits	

Register 14-13: IOCONx: PWM I/O Control Register

Note 1: These bits must not be changed after the PWM module is enabled (PTEN = 1).

2: State represents Active/Inactive state of the PWM, depending on the POLH and POLL bits. For example, if FLTDAT<1> is set to '1' and POLH is set to '1', the PWMxH pin will be at logic level 0 (active level) when a fault occurs.

3: This feature is not available on all devices. Refer to the **"High-Speed PWM"** chapter of the specific device data sheet for availability.

Register 14-13: IOCONx: PWM I/O Control Register (Continued)

- FLTDAT<1:0>: State⁽²⁾ for PWMxH and PWMxL Pins if FLTMOD is Enabled bits⁽¹⁾ bit 5-4 IFLTMOD (FCLCONx<15>) = 0: Normal Fault mode: If fault is active, FLTDAT<1> provides the state for PWMxH. If fault is active, FLTDAT<0> provides the state for PWMxL. IFLTMOD (FCLCONx<15>) = 1: Independent Fault mode: If current-limit is active, FLTDAT<1> provides the state for PWMxH. If fault is active, FLTDAT<0> provides the state for PWMxL. CLDAT<1:0>: State⁽²⁾ for PWMxH and PWMxL Pins if CLMOD is Enabled bits bit 3-2 IFLTMOD (FCLCONx<15>) = 0: Normal Fault mode: If current-limit is active, CLDAT<1> provides the state for PWMxH. If current-limit is active, CLDAT<0> provides the state for PWMxL. IFLTMOD (FCLCONx<15>) = 1: Independent Fault mode: The CLDAT<1:0> bits are ignored. bit 1 SWAP: SWAP PWMxH and PWMxL Pins bit 1 = PWMxH output signal is connected to PWMxL pin; PWMxL output signal is connected to PWMxH pin 0 = PWMxH and PWMxL output signals pins are mapped to their respective pins bit 0 **OSYNC:** Output Override Synchronization bit 1 = Output overrides via the OVRDAT<1:0> bits are synchronized to the PWM time base 0 = Output overrides via the OVRDAT<1:0> bits occur on next CPU clock boundary Note 1: These bits must not be changed after the PWM module is enabled (PTEN = 1).
 - 2: State represents Active/Inactive state of the PWM, depending on the POLH and POLL bits. For example, if FLTDAT<1> is set to '1' and POLH is set to '1', the PWMxH pin will be at logic level 0 (active level) when a fault occurs.
 - **3:** This feature is not available on all devices. Refer to the **"High-Speed PWM"** chapter of the specific device data sheet for availability.

- J	_			J			
R/W-0) R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
IFLTMO	D ⁽⁴⁾	(CLSRC<4:0>(2	2,3)		CLPOL ⁽¹⁾	CLMOD
bit 15							bit 8
R/W-0	D R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
	FL	.TSRC<4:0> ^{(2,3}		FLTPOL ⁽¹⁾	FLTMO)<1:0> ⁽⁴⁾	
bit 7							bit 0
· · ·							
Legend:							
R = Read	able bit	W = Writable	bit		mented bit, read		
-n = Value	e at POR	1' = Bit is set		0' = Bit is cle	eared	x = Bit is unkr	nown
64.4 5			it Maala Easte	L. L.:+(4)			
DIC 15	1 - Independ	dependent Fal	IIt Mode Enab	t input more E			and fault input
	maps FLT	DAT<0> to PV	VMxL output.	The CLDAT<1	:0> bits are not i	used for overric	de functions.
	0 = Normal Fa	ault mode: Cur	rent-limit and f	fault inputs ma	p CLDAT<1:0> a	and FLTDAT<1	:0> to PWMxH
	and PWM	IxL outputs.				(0.1	•
bit 14-10	CLSRC<4:0>	Current-Limit	t Control Signa	al Source Sele	ect bits for PWM	Generator # ^{(2,}	.
	I nese bits specific de	ecity the currer	nt-limit control et for available	signal source.	Refer to the "H	gn-Speed Pw	M" chapter of
bit 9	CI POI : Curr	ent-l imit Polar	ity bit for PWN	/ Generator #	(1)		
Sit 0	1 = The select	cted current-lim	nit source is ac	tive-low			
	0 = The selec	cted current-lim	it source is ac	ctive-high			
bit 8	CLMOD: Cur	rent-Limit Mod	e Enable bit fo	or PWM Gener	rator #		
	1 = Current-L 0 = Current-L	imit mode is ei imit mode is di	nabled sabled				
bit 7-3	FLTSRC<4:0	>: Fault Contro	ol Signal Sour	ce Select bits f	for PWM Genera	ator # ^(2,3)	
	These bits sp device data s	ecify the Fault heet for availal	control source ble selections.	e. Refer to the	"High-Speed P	WM" chapter of	of the specific
bit 2	FLTPOL: Fau	ult Polarity bit fo	or PWM Gene	erator # ⁽¹⁾			
	1 = The selec	cted fault sourc	e is active-low	V			
	0 = The selec	cted fault sourc	e is active-hig	lh	\		
bit 1-0	FLTMOD<1:0	D>: Fault Mode	bits for PWM	Generator #(4)		
	11 = Fault inp 10 = Reserve	out is disabled					
	01 = The sele	ected fault sour	rce forces PW	MxH, PWMxL	pins to FLTDAT	values (cycle)	
	00 = The sele	ected fault sour	rce forces PW	MxH, PWMxL	pins to FLTDAT	values (latche	d condition)
Note 1:	These bits should yield unpredictable	be changed or e results.	ly when PTE	N = 0. Changir	ng the polarity se	election during	operation will
2:	When Independen (FLTSRC<4:0> = k unused current-lim PWMxL outputs.	t Fault mode is 00000), the Cu hit source to pro	s enabled (IFL Irrent-Limit Co event the curre	TMOD = 1) an introl Source S ent-limit source	nd Fault 1 is used select bits (CLSF e from disabling	d for Fault mod RC<4:0>) shoul both the PWM	le d be set to an xH and
3:	When Independen (CLSRC<4:0> = b fault source to pre-	t Fault mode is 0000), the Fau vent Fault 1 fro	s enabled (IFL Ilt Control Sou om disabling b	TMOD = 1), an irce Select bits oth the PWMx	nd Fault 1 is use (FLTSRC<4:0> L and PWMxH c	ed for Current-L) should be set outputs.	imit mode to an unused
4:	This feature is not a data sheet for avai	available on al ilability.	l devices. Refe	er to the " High	-Speed PWM" of	chapter of the s	pecific device

Register 14-14: FCLCONx: PWM Fault Current-Limit Control Register

Register 14-15:	PDCx: PWM Generator Duty Cycle Register ⁽¹⁾
	i box. I will belief all buly by the Register

R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0		
PDCx<15:8>									
bit 15							bit 8		
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0		

		PDCx<7:0>		
bit 7				bit 0
Legend:				
R = Readable bit	W = Writable bit	U = Unimplemented bit,	read as '0'	
-n = Value at POR	'1' = Bit is set	'0' = Bit is cleared	x = Bit is unknown	

bit 15-0 PDCx<15:0>: PWM Generator # Duty Cycle Value bits

Note 1: In Independent PWM mode, PMOD<1:0> (IOCONx<11:10>) = 11, the PDCx register controls the PWMxH duty cycle only. In Complementary, Redundant and Push-Pull PWM modes (PMOD<1:0> (IOCONx<11:0>) = 00, 01, or 10), the PDCx register controls the duty cycle of both the PWMxH and PWMxL.

Register 14-16: PHASEx: PWM Primary Phase Shift Register

R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	
PHASEx<15:8>								
bit 15							bit 8	

R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			PHAS	Ex<7:0>			
bit 7							bit 0
Legend:							
D - Doodable bi	+	M = M/ritable bit		II – Unimplor	nonted hit read	0'	

R = Readable bit	W = Writable bit	U = Unimplemented bit,	read as '0'
-n = Value at POR	'1' = Bit is set	'0' = Bit is cleared	x = Bit is unknown

bit 15-0 PHASEx<15:0>: PWM Phase Shift Value or Independent Time Base Period bits for the PWM Generator

Note 1: If the ITB bit = 0 (PWMCONx<9>), the following applies based on the mode of operation:
 Complementary, Redundant and Push-Pull Output mode (PMOD<1:0> (IOCONx<11:10>) = 00, 01, or 10) PHASEx<15:0> = Phase shift value for PWMxH and PWMxL outputs
 True Independent Output mode (PMOD<1:0> (IOCONx<11:10>) = 11) PHASEx<15:0> = Phase shift value for PWMxH only
2: If the ITB bit = 1(PWMCONx<9>), the following applies based on the mode of operation:
 Complementary, Redundant, and Push-Pull Output mode (PMOD<1:0> (IOCONx<11:10>) = 00, 01, or 10) PHASEx<15:0> = Independent time base period value for PWMxH and PWMxL
 True Independent Output mode (PMOD<1:0> (IOCONx<11:10>) = 11) PHASEx<15:0> = Independent time base period for PWMxH only

Register 14-17:	SDCx: PWM Secondary Duty Cycle Register ^(1,2)	
-----------------	--	--

	B 444 A	D 444 A		B 844 6			-
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			SDC	x<15:8>			
bit 15							bit 8
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			SDC	Cx<7:0>			
bit 7							bit 0
Legend:							
R = Readable bit W = Writable bit		bit	U = Unimplemented bit, read as '0'				
-n = Value at POR		'1' = Bit is set		'0' = Bit is cleared		x = Bit is unknown	

bit 15-0 SDCx<15:0>: Secondary Duty Cycle bits for PWMxL output pin

Note 1: The SDCx register is used in Independent PWM mode only (PMOD<1:0> (IOCONx<11:10>) = 11. When used in Independent PWM mode, the SDCx register controls the PWMxL duty cycle.
 2: This register is not available on all devices. Refer to the "High-Speed PWM" chapter of the specific

Register 14-18: SPHASEx: PWM Secondary Phase Shift Register^(1,2,3)

R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			SPHASE	Ex<15:8>			
bit 15							bit 8
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			SPHAS	Ex<7:0>			
bit 7							bit 0
Legend:							
	1.11	14/ 14/ to b.t.	1. 11			1 (0)	

-n = Value at POR '1' = E	Bit is set '0' = Bit is c	leared x = Bit is unknown

bit 15-0 SPHASEx<15:0>: Secondary Phase Offset bits for PWMxL Output Pin

Note 1: If the ITB bit = 0 (PWMCONx<9>), the following applies based on the mode of operation:
 Complementary, Redundant and Push-Pull Output mode (PMOD<1:0> (IOCONx<11:10>) = 00, 01, or 10) SPHASEx<15:0> = Not used
 True Independent Output mode (PMOD<1:0> (IOCONx<11:10>) = 11) SPHASEx<15:0> = Phase shift value for PWMxL only
2: If the ITB bit = 1 (PWMCONx<9>), the following applies based on the mode of operation:
 Complementary, Redundant and Push-Pull Output mode (PMOD<1:0> (IOCONx<11:10>) = 00, 01, or 10) SPHASEx<15:0> = Not used
 True Independent Output mode (PMOD<1:0> (IOCONx<11:10>) = 11) SPHASEx<15:0> = Independent time base period value for PWMxL only

3: This register is not available on all devices. Refer to the "High-Speed PWM" chapter of the specific device data sheet for availability.

device data sheet for availability.

U-0	U-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0		
	—		DTRx<13:8>						
bit 15							bit 8		
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0		
			DTF	Rx<7:0>					
bit 7							bit 0		
Legend:									
R = Readable bit W = Writable bit			it	U = Unimplemented bit, read as '0'					
-n = Value at POR '1' = Bit is set			'0' = Bit is cleared x = Bit is unknowr			nown			
bit 15-14	Unimpleme	nted: Read as '0	,						

Register 14-19: DTRx: PWM Dead Time Register

bit 13-0 DTRx<13:0>: Unsigned 14-bit Dead Time Value bits for PWMx Dead Time Unit

Register 14-20: ALTDTRx: PWM Alternate Dead Time Register

U-0	U-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0		
—	—		ALTDTRx<13:8>						
bit 15							bit 8		

R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0		
ALTDTRx<7:0>									
bit 7							bit 0		

Legend:			
R = Readable bit	W = Writable bit	U = Unimplemented bit, read	as '0'
-n = Value at POR	'1' = Bit is set	'0' = Bit is cleared	x = Bit is unknown

bit 15-14 Unimplemented: Read as '0'

bit 13-0 ALTDTRx<13:0>: Unsigned 14-bit Dead Time Value bits for PWMx Dead Time Unit

Register 14-21: TRIGx: PWM Primary Trigger Compare Value Register

R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			TRGCM	P<15:8>			
bit 15							bit 8
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			TRGCM	1P<7:0>			
bit 7							bit 0
Legend:							

=ogona.			
R = Readable bit	W = Writable bit	U = Unimplemented bit, read	l as '0'
-n = Value at POR	'1' = Bit is set	'0' = Bit is cleared	x = Bit is unknown

bit 15-0

TRGCMP<15:0>: Trigger Control Value bits

When the primary PWM functions in local time base, this register contains the compare values that can trigger the ADC module.

R/W-0	R/W-0	R/W-0	R/W-0	U-0	U-0	U-0	U-0
	TRGD	IV<3:0>		_			_
bit 15							bit 8
U-0	U-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
	_			TRGS	TRT<5:0>		
bit 7							bit C
Legend:							
R = Readabl	e bit	W = Writable	bit	U = Unimplei	mented bit, rea	ıd as '0'	
-n = Value at	t POR	'1' = Bit is set		'0' = Bit is cle	ared	x = Bit is unkr	nown
		ger output for ev	ery 3rd trigger	event			
	0000 = Trig	ger output for ev	ery trigger eve	ent			
bit 11-6	Unimpleme	nted: Read as '	0'				
bit 5-0	TRGSTRT<	5:0>: Trigger Po	stscaler Start	Enable Select	bits		
	111111 = V	Vait 63 PWM cyc	les before ger	nerating the fir	st trigger even	t after the modul	e is enabled
	•						
	•						
	• 000010 = V 000001 = V 000000 = V	Vait 2 PWM cycle Vait 1 PWM cycle Vait 0 PWM cycle	es before gene es before gene es before gene	erating the first erating the first erating the first	t trigger event t trigger event t trigger event	after the module after the module after the module	is enabled is enabled is enabled

Register 14-22: TRGCONx: PWM Trigger Control Register

.							
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	U-0	U-0
PHR	PHF	PLR	PLF	FLTLEBEN	CLLEBEN		
bit 15							bit 8
U-0	U-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
	_	BCH ⁽¹⁾	BCL ⁽¹⁾	BPHH	BPHL	BPLH	BPLL
bit 7			-		<u></u>		bit 0
Legend:							
R = Readable	bit	W = Writable I	oit	U = Unimpler	mented bit, read	l as '0'	
-n = Value at P	OR	'1' = Bit is set		'0' = Bit is cle	ared	x = Bit is unkn	own
bit 15		J Dising Edge 7	Frigger Engbl	o hit			
DIL 15	1 = Rising ed	ne of PWMxH v	vill trigger Le	e bit ading-Edge Bla	anking counter		
	0 = Leading-E	Edge Blanking i	anores risina	edae of PWM	kH		
bit 14	PHF: PWMxH	I Falling Edge	rigger Enabl	e bit			
	1 = Falling ed	ge of PWMxH	will trigger Le	ading-Edge Bla	anking counter		
	0 = Leading-E	Edge Blanking i	gnores falling	g edge of PWM	хH		
bit 13	PLR: PWMxL	Rising Edge T	rigger Enable	e bit			
	1 = Rising edg	ge of PWMxL w	/ill trigger Lea	ading-Edge Bla	nking counter		
hit 12		Ealling Edge T	rigger Enabl	bit	KL.		
DIC 12	1 = Falling ed		vill trigger Lindbig	ading-Edge Bla	anking counter		
	0 = Leading-E	Edge Blanking i	gnores falling	g edge of PWM	xL		
bit 11	FLTLEBEN: F	ault Input Lead	ding-Edge Bl	anking Enable	bit		
	1 = Leading-E	dge Blanking i	s applied to s	selected fault in	iput ilt input		
bit 10	CLLEBEN: C	urrent-Limit Le	adina-Edae F	Blanking Enable	e bit		
2.1.10	1 = Leading-E	Edge Blanking i	s applied to s	selected curren	t-limit input		
	0 = Leading-E	Edge Blanking i	s not applied	to selected cur	rrent-limit input		
bit 9-6	Unimplement	ted: Read as ')'				
bit 5	BCH: Blanking	g in Selected B	lanking Sign	al High Enable	bit ⁽¹⁾		
	1 = State blan	king (of curren	t-limit and/or	fault input sign	als) when selec	ted blanking sig	anal is high
bit 4		ng when select	ed blanking s	signal is nign	h;;+(1)		
DIL 4	1 = State blan	y in Selected B	Limit and/or	fault input sign	als) when selec	ted blanking sig	wol si low
	0 = No blankir	ng when select	ed blanking s	signal is low		ieu biariking się	
bit 3	BPHH: Blanki	ing in PWMxH	High Enable	bit			
	1 = State blan 0 = No blankir	iking (of curren ng when PWM)	t-limit and/or ‹H output is ł	fault input sign nigh	als) when PWM	IxH output is hig	Jh
bit 2	BPHL: Blanki	ng in PWMxH I	∟ow Enable b	pit			
	1 = State blan 0 = No blankir	king (of curren	t-limit and/or	fault input sign	als) when PWM	IxH output is lov	N
bit 1	BPLH: Blanki	ng in PWMxL H	ligh Enable b	pit			
	1 = State blan	king (of curren	t-limit and/or	fault input sign	als) when PWM	lxL output is hig	ιh
bit 0	BPI I · Rlanki	ng in PWMyl I	ow Enable b	it			
5.00	1 = State blan	iking (of curren	t-limit and/or	fault input sign	als) when PWM	xL output is lov	v
	0 = No blankir	ng when PWM	L output is lo)W			

Register 14-23:	LEBCONx:	Leading-Edge	Blanking	Control	Register
-----------------	----------	--------------	----------	---------	----------

Note 1: The blanking signal is selected via the BLANKSEL<3:0> bits (AUXCONx<11:8>).

U-0	U-0	U-0	U-0	R/W-0	R/W-0	R/W-0	R/W-0
—	—	—	—		LEB<	<11:8>	
bit 15							bit 8
R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			LEB	<7:0>			
bit 7							bit 0
Legend:							
R = Readable	bit	W = Writable	bit	U = Unimplemented bit, read as '0'			
-n = Value at P	POR	'1' = Bit is set		'0' = Bit is cleared x = Bit is unknown			nown

Register 14-24: LEBDLYx: Leading-Edge Blanking Delay Register

bit 15-12 Unimplemented: Read as '0'

bit 11-0 LEB<11:0>: Leading-Edge Blanking Delay bits for Current-Limit and Fault Inputs

Register 14-25: PWMCAPx: Primary PWM Time Base Capture Register

R-0	R-0	R-0	R-0	R-0	R-0	R-0	R-0
			PWMCAF	^{>} <15:8> ^(1,2)			
bit 15							bit 8
R-0	R-0	R-0	R-0	R-0	R-0	R-0	R-0
			PWMCA	P<7:0> ^(1,2)			
bit 7							bit 0
Legend:							
R = Readable	bit	W = Writable b	oit	U = Unimpleme	ented bit, rea	ıd as '0'	
-n = Value at P	' OR	'1' = Bit is set		'0' = Bit is clear	red	x = Bit is unkr	nown

bit 15-0 **PWMCAP<15:0>:** Captured PWM Time Base Value bits^(1,2) The value in this register represents the captured PWM time base value when a leading edge is detected on the current-limit input.

Note 1: The capture feature is only available on the primary output (PWMxH).

2: The feature is only active after LEB processing on the current-limit input signal is complete.

Register 14-	26: AUXCONx:	PWM Auxiliar	y Control R	egister			
U-0	U-0	U-0	U-0	R/W-0	R/W-0	R/W-0	R/W-0
—	—		—		BLANKS	EL<3:0> ⁽¹⁾	
bit 15							bit 8
U-0	U-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
			CHOPS	SEL<3:0>(1)		CHOPHEN	CHOPLEN
bit 7							bit 0
l egend:							
R = Readabl	le bit	W = Writable	bit	U = Unimplei	mented bit_rea	d as '0'	
-n = Value at	POR	'1' = Bit is set		0' = Bit is cle	ared	x = Bit is unkr	nown
				0 21110 010			
bit 15-12	Unimplemen	ted: Read as '	0'				
bit 11-8	BLANKSEL<	3:0>: PWM Sta	ate Blank Sou	urce Select bits	(1)		
	The selected state blank signal blocks the current-limit and/or fault input signals (if enabled via the BCH and BCL bits in the LEBCONx register). 1111 = PWMxH selected as state blank source						
	•						
	•						
	0001 = PWM 0000 = No st	lxH selected as ate blanking	state blank s	source			
bit 7-6	Unimplemen	ted: Read as '	0'				
bit 5-2	CHOPSEL<3	3:0>: PWM Cho	p Clock Sou	rce Select bits ⁽¹)		
	The selected	signal will enal IxH selected as	ole and disab CHOP clock	le (CHOP) the s source	selected PWM	outputs.	
	•						
	•						
	•						
	0001 = PWM 0000 = Chop	IxH selected as clock generate	CHOP clock	source CHOP clock s	ource		
bit 1	CHOPHEN: F	PWMxH Output	t Chopping E	nable bit			
	1 = PWMxH (chopping functi	on is enabled	1			
	0 = PWMxH d	chopping functi	on is disable	d 			
bit 0	CHOPLEN: F	PWMxL Output	Chopping Er	able bit			
	1 = PWMXL c 0 = PW/WyL c	chopping function	on is enabled	4			
				a			

Note 1: These bit selections are device dependent. Refer to the "High-Speed PWM" chapter of the specific device data sheet for availability.

14

High-Speed PWM

14.4 ARCHITECTURE OVERVIEW

Figure 14-1 illustrates the architectural overview of the High-Speed PWM module and its interconnection with the CPU and other peripherals.





The High-Speed PWM module contains multiple PWM generators. Each PWM generator provides two PWM outputs: PWMxH and PWMxL. A master time base generator provides a synchronous signal as a common time base to synchronize the various PWM outputs. Each generator can operate independently or in sync with the master time base. The individual PWM outputs are available on the output pins of the device. The input fault signals and current-limit signals, when enabled, monitor and protect the system by placing the PWM outputs into a known "safe" state.

Each PWM generator can create a trigger to the ADC module to sample the analog signal at a specific instance during the PWM period. In addition, the High-Speed PWM module also generates a Special Event Trigger to the ADC module based on the master time base.

The High-Speed PWM module can synchronize itself with an external signal or can act as a synchronizing source to any external device. The SYNCIx is the input pin, which can synchronize the High-Speed PWM module with an external signal. The SYNCOx pin is an output pin that provides a synchronous signal to an external device.

The High-Speed PWM module can be used for a wide variety of power conversion/motor control applications that require:

- · High operating frequencies with good resolution
- · Ability to dynamically control PWM parameters such as duty cycle, period and dead time
- · Ability to independently control each PWM
- · Ability to synchronously control all PWMs
- · Independent resource allocation for each PWM generator
- Fault handling capability
- · CPU load staggering to execute multiple control loops

Each function of the High-Speed PWM module is described in detail in subsequent sections. Figure 14-2 illustrates the interconnections between various registers in the High-Speed PWM module.





14.5 MODULE DESCRIPTION

14.5.1 PWM Clock Selection

The system clock is used to generate the clock for the High-Speed PWM module internally. The maximum time resolution for this module is TOSC.

14.5.2 Time Base

Each PWM output in a PWM generator can use the master time base or an independent time base. The input clock of the High-Speed PWM module has prescaler (divider) options of 1:1 to 1:64, which can be selected using the PWM Input Clock Prescaler (Divider) Select bits (PCLKDIV<2:0>) in the PWM Clock Divider Select register (PTCON2<2:0>). The prescaled value will also reflect the PWM resolution, which helps to reduce the power consumption of the High-Speed PWM module. The prescaled clock is the input to the PWM clock control logic block. The maximum clock rate provides a duty cycle and period resolution of Tosc.

For example:

- If a prescaler option of 1:2 is selected, the PWM duty cycle and period resolution can be set at Tosc * 2. Thereby, the power consumption of the High-Speed PWM module would be reduced by approximately 50 percent of the maximum speed operation.
- If a prescaler option of 1:4 is selected, the PWM duty cycle and period resolution can be set at Tosc * 4. Thereby, the power consumption of the High-Speed PWM module would be reduced by approximately 75 percent of the maximum speed operation.

The High-Speed PWM module can operate in the standard edge-aligned or center-aligned time base.

14.5.3 Write Protection

Certain devices incorporate a write protection feature for the IOCONx and FCLCONx registers, which prevents any inadvertent writes to these registers. This feature can be controlled by the PWMLOCK Configuration bit (FOSCSEL<6>). The default state of the write protection feature is enabled (PWMLOCK = 1). Refer to the **"Special Features"** chapter of the specific device data sheet for more information of the Flash Configuration bytes.

To gain write access to the locked registers, the user application must write two consecutive values of 0xABCD and 0x4321 to the PWMKEY register. The write access to the IOCONx or FCLCONx registers must be the next SFR access following the unlock sequence; there can be no other SFR accesses during the unlock process and subsequent write access. To write to both the IOCONx and FCLCONx registers requires two unlock operations.

The correct unlocking sequence is described in Example 14-1.

```
Example 14-1: PWM Write-Protected Register Unlock Sequence
```

; FLT32 pin must be pu ; Writing to FCLCON1 r	lled high externally to clear and disable the fault egister requires unlock sequence
mov #0xabcd,w10	;Load first unlock key to w10 register
mov #0x4321,w11	;Load second unlock key to w11 register
mov #0x0000,w0	;Load desired value of FCLCON1 register in w0
mov w10, PWMKEY	;Write first unlock key to PWMKEY register
mov w11, PWMKEY	;Write second unlock key to PWMKEY register
mov w0,FCLCON1	;Write desired value to FCLCON1 register
; Set PWM ownership an	d polarity using the IOCON1 register
; Writing to IOCON1 re	gister requires unlock sequence
mov #0xabcd,w10	;Load first unlock key to w10 register
mov #0x4321,w11	;Load second unlock key to w11 register
mov #0xF000,w0	;Load desired value of IOCON1 register in w0
mov w10, PWMKEY	;Write first unlock key to PWMKEY register
mov w11, PWMKEY	;Write second unlock key to PWMKEY register
mov w0,IOCON1	;Write desired value to IOCON1 register

14.5.4 Standard Edge-Aligned PWM

The standard edge-aligned PWM waveforms are illustrated in Figure 14-3. To create the edge-aligned PWM, a timer or counter circuit counts upward from zero to a specified maximum value, called Period. Another register contains the duty cycle value, which is constantly compared with the timer value. When the timer or counter value is less than or equal to the duty cycle value, the PWM output signal is asserted. When the timer value is greater than or equal to the period value, the timer resets itself and the process repeats.

Figure 14-3: Standard Edge-Aligned PWM Mode



14.5.5 Center-Aligned PWM

The center-aligned PWM waveforms illustrated in Figure 14-4, align the PWM signals with respect to a reference point so that half of the PWM signal occurs before the reference point and the remaining half of the signal occurs after the reference point. The Center-Aligned mode is enabled when the CAM bit (PWMCONx<2>) is set.

When operating in Center-Aligned mode, the effective PWM period is twice the value specified in the PHASEx registers, because the independent time base counter in the PWM generator is counting up and then counting down during the cycle. The up/down count sequence doubles the effective PWM cycle period. This mode is used in many motor control applications.

Note: The Independent Time Base mode (ITB = 1) must be enabled to use the Center-Aligned mode. If ITB = 0, the CAM bit is ignored.



Figure 14-4: Center-Aligned PWM Mode



/* Select Edge-Aligned PWM Time Base */					
<pre>PWMCON1bits.CAM = 0; / ?</pre>	* For Edge-Aligned mode */				
/* Select Center-Aligned PWM	1 Time Base */				
<pre>PWMCON1bits.CAM = 1; /* PWMCON1bits.ITB = 1; /*</pre>	* For Center-Aligned mode */ * Must be set for Center-Aligned mode */				

14.5.6 Master Time Base/Synchronous Time Base

Figure 14-5 illustrates the PWM functionality in the master time base.





Some of the common tasks of the master time base are as follows:

- · Generates time reference for all the PWM generators
- · Generates special event ADC trigger and interrupt
- Supports synchronization with the external SYNC signal (SYNCIx)
- · Supports synchronization with external devices using SYNCOx signal

The master time base for a PWM generator is set by loading a 16-bit value into the Primary Master Time Base Period register (PTPER). In Master Time Base mode, the value in the PHASEx and SPHASEx registers provides phase shift between the PWM outputs. The clock for the PWM timer (PMTMR) is derived from the system clock.

14.5.7 Time Base Synchronization

The master time base can be synchronized with the external synchronization signal via the master time base synchronization signal (SYNCIx). The synchronization source (SYNCIx) can be selected using the SYNCSRC<1:0> bits (PTCON<5:4>). The SYNCPOL bit (PTCON<9>) selects the rising or falling edge of the synchronization pulse, which resets the timer (PMTMR). The external synchronization feature can be enabled or disabled with the SYNCEN bit (PTCON<7>). The pulse-width of the external synchronization signal (SYNCIx) must be more than the period of the post-scaled input clock to ensure reliable detection by the master time base.

An external device can also be synchronized with the master time base using the Synchronization Output (SYNCOx) signal. The SYNCOx signal is generated when the PTPER register resets the PMTMR register. The SYNCOx signal pulse is 12 * TcY to ensure other devices reliably sense the signals. The polarity of the SYNCOx signal is determined by the SYNCPOL bit (PTCON<9>). The SYNCOx signal can be enabled or disabled by selecting the SYNCOEN bit (PTCON<8>).

Note 1: The SYNCIx pulse should be greater than the PWM period value.

- 2: The SYNCIx pulse should be continuous with a minimum pulse-width of 200 ns.
- 3: The PWM cycles are expected to be distorted for the first two SYNCIx pulses.
- **4:** The period value should be a multiple of 8 (Least Significant 3 bits set to '0') for the external synchronization to work in the Push-Pull mode.
- 5: There is a delay from the input of a SYNC signal until the internal time base counter is Reset. This will be approximately 2.5 * prescale clock period.
- 6: The External Time Base Synchronization must not be used with phase shifted PWM as the synchronization signal may not maintain the phase relationships between the multiple PWM channels.
- 7: The External Time Base Synchronization cannot be used in Independent Time Base mode.

The advantage of synchronization is that it ensures the beat frequencies are not generated when multiple power controllers are in use.

Example 14-3: Synchronizing Master Time Base with External Signal

```
/* Synchronizing Master Time Base with External Signal */
PTCONbits.SYNCSRC = 0;  /* Select SYNC1 input as synchronizing source */
PTCONbits.SYNCPOL = 0;  /* Rising edge of SYNC1 resets the PWM Timer */
PTCONbits.SYNCEN = 1;  /* Enable external synchronization */
```

Example 14-4: Synchronizing External Device with Master Time Base

```
/* Synchronizing External Device with Master Time Base */
PTCONbits.SYNCPOL = 0; /* SYNCO output is active-high */
PTCONbits.SYNCOEN = 1; /* Enable SYNCO output */
```

14.5.8 Special Event Trigger

The High-Speed PWM module has a master Special Event Trigger that can be used for synchronization of analog-to-digital conversions with the PWM time base. The analog-to-digital sampling and conversion time can be programmed to occur within the PWM period. The Special Event Trigger allows the user-assigned application to minimize the delay between the time the conversion results are acquired and the time the duty cycle value is updated. The Special Event Trigger is based on the master time base.

The master Special Event Trigger value is loaded into the PWM Special Event Compare register (SEVTCMP). In addition, the SEVTPS<3:0> bits (PTCON<3:0>), control the Special Event Trigger operation. To generate a trigger to the ADC module, the value in the PTPER register is compared with the value in the SEVTCMP register. The master Special Event Trigger has a postscaler that allows a 1:1 to 1:16 postscaler ratio. The postscaler is configured by writing to the SEVTPS<3:0> bits (PTCON<3:0>).

The Special Event Trigger pulses are always generated during the following instances:

- On a match condition regardless of the status of the Special Event Interrupt Enable bit (SEIEN)
- If the compare value in the SEVTCMP register is a value from zero to a maximum value of the PTPER register

High-Speed PWM

The Special Event Trigger output postscaler is cleared on these events:

- Any device Reset
- When PTEN = 0

Example 14-5: ADC Special Event Trigger Configuration

/* ADC Special Event Trigger	Configuration */
SEVTCMP = 1248; /*	Special Event Trigger value set at 25% of the period value (4999)*/ $\!\!\!\!$
PTCONbits.SEVTPS = 0; /*	Special Event Trigger output postscaler set to 1:1 selection */
PTCONbits.SEIEN = 1; /*	Special event interrupt is enabled */
while (PTCONbits.SESTAT == 1); /* Wait for special event interrupt status change */

14.5.9 Independent PWM Time Base

Figure 14-6 illustrates the PWM functionality in the independent time base for devices that support this feature.





Each PWM generator can operate on:

· A shared time base for both the primary (PWMxH) and secondary (PWMxL) outputs

The independent time base periods for both PWM outputs (PWMxH and PWMxL) are provided by the value in PWM Primary Phase Shift register (PHASEx).

• A dedicated time base for each of the primary (PWMxH) and secondary (PWMxL) outputs

The independent time base period for PWMxH output is provided by the value in the PWM Primary Phase Shift register (PHASEx). The independent time base period for PWMxL output is provided by the value in the PWM Secondary Phase Shift (SPHASEx) register.

The PHASEx and SPHASEx registers provide the time period value for the PWMx outputs (PWMxH and PWMxL) in Independent Time Base mode.

Note: The PTMRx and STMRx values are not readable to the user-assigned application.

14.6 PWM OPERATING MODES

The High-Speed PWM module supports the following operation modes:

- · Push-Pull Output mode
- Complementary Output mode
- Redundant Output mode
- · Independent Output mode (this feature is not available on all devices)

These operating modes can be selected using the PMOD<1:0> bits (IOCONx<11:10>).

In the following sections, figures and examples are provided, which show the PWM outputs in multiple operating modes. Table 14-1 provides a list of the available modes and settings, with references to the figures by number.

 Table 14-1:
 Mode and Code Cross-reference Table

PWM Mode	Mode Settings	Related Figure
Push-Pull	Independent Duty Cycle and Phase, Fixed Primary Period, Edge-Aligned	14-7
	Independent Duty Cycle and Phase, Fixed Secondary Period, Edge-Aligned	14-8
	Master Duty Cycle and Independent Phase, Fixed Primary Period, Edge-Aligned	14-9
	Master Duty Cycle and Independent Phase, Fixed Secondary Period, Edge-Aligned	14-10
	Independent Duty Cycles and Periods, No Phase-Shifting, Edge-Aligned	14-11
	Master Duty Cycles and Independent Periods, No Phase-Shifting, Edge-Aligned	14-12
	Independent Duty Cycles and Periods, No Phase-Shifting, Center-Aligned Mode	14-13
	Master Duty Cycles and Independent Periods, No Phase-Shifting, Center-Aligned Mode	14-14
Complementary	Independent Duty Cycle and Phase, Fixed Primary Period, Edge-Aligned	14-15
	Independent Duty Cycle and Phase, Fixed Secondary Period, Edge-Aligned	14-16
	Master Duty Cycle and Independent Phase, Fixed Primary Period, Edge-Aligned	14-17
	Master Duty Cycle and Independent Phase, Fixed Secondary Period, Edge-Aligned	14-18
	Independent Duty Cycles and Periods, No Phase-Shifting, Edge-Aligned	14-19
	Master Duty Cycles and Independent Periods, No Phase-Shifting, Edge-Aligned	14-20
	Independent Duty Cycles and Periods, No Phase-Shifting, Center-Aligned	14-21
	Master Duty Cycles and Independent Periods, No Phase-Shifting, Center-Aligned	14-22
Redundant	Independent Duty Cycle and Phase, Fixed Primary Period, Edge-Aligned	14-23
	Independent Duty Cycle and Phase, Fixed Secondary Period, Edge-Aligned	14-24
	Master Duty Cycle and Variable Phase, Fixed Primary Period, Edge-Aligned	14-25
	Master Duty Cycle and Variable Phase, Fixed Secondary Period, Edge-Aligned	14-26
	Independent Duty Cycles and Periods, No Phase-Shifting, Edge-Aligned	14-27
	Master Duty Cycles and Independent Periods, No Phase-Shifting, Edge-Aligned	14-28
	Independent Duty Cycles and Periods, No Phase-Shifting, Center-Aligned	14-29
	Master Duty Cycles and Independent Periods, No Phase-Shifting, Center-Aligned	14-30
Independent	Independent Duty Cycle and Phase, Fixed Primary Period, Edge-Aligned	14-31
	Independent Duty Cycle and Phase, Fixed Secondary Period, Edge-Aligned	14-32
	Master Duty Cycle, Variable Phase, Fixed Primary Period, Edge-Aligned	14-33
	Master Duty Cycle, Variable Phase, Fixed Secondary Period, Edge-Aligned	14-34
	Independent Duty Cycles and Periods, No Phase-Shifting, Edge-Aligned	14-35
	Master Duty Cycles, Independent Periods, No Phase-Shifting, Edge-Aligned	14-36
	Independent Duty Cycles and Periods, No Phase-Shifting, Center-Aligned	14-37
	Master Duty Cycles, Independent Periods, No Phase-Shifting, Center-Aligned	14-38

14.6.1 Push-Pull PWM Mode

Note: Not all of the features and registers listed in the Figures and Code Examples in this section are available on all devices. Refer to the "High-Speed PWM" chapter of the specific device data sheet for availability.

In Push-Pull mode, the PWM outputs are alternately available on the PWMxH and PWMxL pins. Some typical applications of Push-Pull mode are provided in **14.16** "Application Information".

Figure 14-7 through Figure 14-14 and Example 14-6 through Example 14-13 show the PWM outputs for Push-Pull PWM mode in multiple operating modes.





Example 14-6: Push-Pull PWM Mode – Independent Duty Cycle and Phase, Fixed Primary Period, Edge-Aligned

```
/* Set PWM Period on Primary Time Base */
PTPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
PHASE2 = 100;
PHASE3 = 200;
/* Set Duty Cycles */
PDC1 = 150;
PDC2 = 200;
PDC3 = 400;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Push-Pull */
IOCON1 = IOCON2 = IOCON3 = 0xC800;
/* Set Primary Time Base, Edge-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0000;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-8: Push-Pull PWM Mode – Independent Duty Cycle and Phase, Fixed Secondary Period,



Example 14-7: Push-Pull PWM Mode – Independent Duty Cycle and Phase, Fixed Secondary Period, Edge-Aligned

```
/* Set PWM Period on Secondary Time Base */
STPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
PHASE2 = 100;
PHASE3 = 200;
/* Set Duty Cycles */
PDC1 = 150;
PDC2 = 200;
PDC3 = 400;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Push-Pull */
IOCON1 = IOCON2 = IOCON3 = 0xC800;
/* Set Secondary Time Base, Edge-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0008;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-9: Push-Pull PWM Mode – Master Duty Cycle and Independent Phase, Fixed Primary Period, Edge-Aligned


Example 14-8: Push-Pull PWM Mode – Master Duty Cycle and Independent Phase, Fixed Primary Period, Edge-Aligned

```
/* Set PWM Period on Primary Time Base*/
PTPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
PHASE2 = 100;
PHASE3 = 200;
/* Set Duty Cycles */
MDC = 200;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Push-Pull */
IOCON1 = IOCON2 = IOCON3 = 0xC800;
/* Set Primary Time Base, Edge-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0100;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0x8000;
```





Example 14-9: Push-Pull PWM Mode – Master Duty Cycle and Independent Phase, Fixed Secondary Period, Edge-Aligned

```
/* Set PWM Period on Secondary Time Base*/
STPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
PHASE2 = 100;
PHASE3 = 200;
/* Set Duty Cycles */
MDC = 200;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Push-Pull */
IOCON1 = IOCON2 = IOCON3 = 0xC800;
/* Set Secondary Time Base, Edge-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0108;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0x8000;
```

Figure 14-11: Push-Pull PWM Mode – Independent Duty Cycles and Independent Periods, No Phase-Shifting, Edge-Aligned



Example 14-10: Push-Pull PWM Mode – Independent Duty Cycles and Independent Periods, No Phase-Shifting, Edge-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 1000;
PHASE2 = 900;
PHASE3 = 800;
/* Set Duty Cycles */
PDC1 = 200;
PDC2 = 300;
PDC3 = 400;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Push-Pull */
IOCON1 = IOCON2 = IOCON3 = 0xC800;
/* Set Independent Time Bases, Edge-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0200;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-12: Push-Pull PWM Mode – Master Duty Cycles and Independent Periods, No Phase-Shifting, Edge-Aligned



14

Example 14-11: Push-Pull PWM Mode – Master Duty Cycles and Independent Periods, No Phase-Shifting, Edge-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 1000;
PHASE2 = 900;
PHASE3 = 800;
/* Set Duty Cycles */
MDC = 200;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Push-Pull */
IOCON1 = IOCON2 = IOCON3 = 0xC800;
/* Set Independent Time Bases, Edge-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0300;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-13: Push-Pull PWM Mode – Independent Duty Cycles and Independent Periods, No Phase-Shifting, Center-Aligned Mode



Example 14-12: Push-Pull PWM Mode – Independent Duty Cycles and Independent Periods, No Phase-Shifting, Center-Aligned Mode

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 1000;
PHASE2 = 900;
PHASE3 = 800;
/* Set Duty Cycles */
PDC1 = 200;
PDC2 = 300;
PDC3 = 400;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Push-Pull */
IOCON1 = IOCON2 = IOCON3 = 0xC800;
/* Set Independent Time Bases, Center-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0204;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-14: Push-Pull PWM Mode – Master Duty Cycles and Independent Periods, No Phase-Shifting, Center-Aligned Mode



High-Speed PWN

Example 14-13: Push-Pull PWM Mode – Master Duty Cycles and Independent Periods, No Phase-Shifting, Center-Aligned Mode

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 1000;
PHASE2 = 900;
PHASE3 = 800;
/* Set Duty Cycles */
MDC = 200;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Push-Pull */
IOCON1 = IOCON2 = IOCON3 = 0xC800;
/* Set Independent Time Bases, Center-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0304;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

14.6.2 Complementary PWM Mode

Note: Not all of the features and registers listed in the Figures and Code Examples in this section are available on all devices. Refer to the "**High-Speed PWM**" chapter of the specific device data sheet for availability.

In Complementary PWM mode, the PWM output PWMxH is the complement of the PWMxL output. Some typical applications of Complementary PWM mode are provided in **14.16 "Application Information"**.

Figure 14-15 through Figure 14-22 and Example 14-14 through Example 14-21 show the PWM outputs in multiple operating modes when the module operates in Complementary PWM mode.

Figure 14-15: Complementary PWM Mode – Independent Duty Cycle and Phase, Fixed Primary Period, Edge-Aligned



High-Speed PWN

Example 14-14: Complementary PWM Mode – Independent Duty Cycle and Phase, Fixed Primary Period, Edge-Aligned

```
/* Set PWM Period on Primary Time Base */
PTPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
PHASE2 = 100;
PHASE3 = 200;
/* Set Duty Cycles */
PDC1 = 150;
PDC2 = 200;
PDC3 = 400;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Complementary */
IOCON1 = IOCON2 = IOCON3 = 0xC000;
/* Set Primary Time Base, Edge-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0000;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-16: Complementary PWM Mode – Independent Duty Cycle and Phase, Fixed Secondary Period, Edge-Aligned



Example 14-15: Complementary PWM Mode – Independent Duty Cycle and Phase, Fixed Secondary Period, Edge-Aligned

```
/* Set PWM Period on Secondary Time Base */
STPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
PHASE2 = 100;
PHASE3 = 200;
/* Set Duty Cycles */
PDC1 = 150;
PDC2 = 200;
PDC3 = 400;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Complementary */
IOCON1 = IOCON2 = IOCON3 = 0xC000;
/* Set Secondary Time Base, Edge-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0008;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-17: Complementary PWM Mode – Master Duty Cycle and Independent Phase, Fixed Primary Period, Edge-Aligned



Example 14-16: Complementary PWM Mode – Master Duty Cycle and Independent Phase, Fixed Primary Period, Edge-Aligned

```
/* Set PWM Period on Primary Time Base*/
PTPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
PHASE2 = 100;
PHASE3 = 200;
/* Set Duty Cycles */
MDC = 200;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Complementary */
IOCON1 = IOCON2 = IOCON3 = 0xC000;
/* Set Primary Time Base, Edge-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0100;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0x8000;
```



Figure 14-18: Complementary PWM Mode – Master Duty Cycle and Independent Phase, Fixed Secondary Period, Edge-Aligned

Example 14-17: Complementary PWM Mode – Master Duty Cycle and Independent Phase, Fixed Secondary Period, Edge-Aligned

```
/* Set PWM Period on Secondary Time Base*/
STPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
PHASE2 = 100;
PHASE3 = 200;
/* Set Duty Cycles */
MDC = 200;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Complementary */
IOCON1 = IOCON2 = IOCON3 = 0xC000;
/* Set Secondary Time Base, Edge-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0108;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0 \times 0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```





Example 14-18: Complementary PWM Mode – Independent Duty Cycles and Independent Periods, No Phase-Shifting, Edge-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 800;
PHASE2 = 900;
PHASE3 = 1000;
/* Set Duty Cycles */
PDC1 = 200;
PDC2 = 300;
PDC3 = 400;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Complementary */
IOCON1 = IOCON2 = IOCON3 = 0 \times C000;
/* Set Independent Time Bases, Edge-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0200;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-20: Complementary PWM Mode – Master Duty Cycles and Independent Periods, No Phase-Shifting, Edge-Aligned



Example 14-19: Complementary PWM Mode – Master Duty Cycles and Independent Periods, No Phase-Shifting, Edge-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 800;
PHASE2 = 900;
PHASE3 = 1000;
/* Set Duty Cycles */
MDC = 200;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 25;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Complementary */
IOCON1 = IOCON2 = IOCON3 = 0xC000;
/* Set Independent Time Bases, Edge-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0300;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0 \times 0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-21: Complementary PWM Mode – Independent Duty Cycles and Independent Periods, No Phase-Shifting, Center-Aligned



Example 14-20: Complementary PWM Mode – Independent Duty Cycles and Independent Periods, No Phase-Shifting, Center-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 1000;
PHASE2 = 900;
PHASE3 = 800;
/* Set Duty Cycles */
PDC1 = 400;
PDC2 = 300;
PDC3 = 200;
/* Set Dead Time Values */
/* DTRx Registers are ignored in this mode */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Complementary */
IOCON1 = IOCON2 = IOCON3 = 0xC000;
/* Set Independent Time Bases, Center-Aligned mode and
  Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0204;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0x8000;
```

Figure 14-22: Complementary PWM Mode – Master Duty Cycles and Independent Periods, No Phase-Shifting, Center-Aligned



Example 14-21: Complementary PWM Mode – Master Duty Cycles and Independent Periods, No Phase-Shifting, Center-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 1000;
PHASE2 = 900;
PHASE3 = 800;
/* Set Duty Cycles */
MDC = 400;
/* Set Dead Time Values */
/* DTRx Registers are ignored in this mode */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 25;
/* Set PWM Mode to Complementary */
IOCON1 = IOCON2 = IOCON3 = 0xC000;
/\,\star\, Set Independent Time Bases, Center-Aligned mode and
  Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0304;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0x0000;
/* Enable PWM Module */
PTCON = 0x8000;
```

14.6.3 Redundant PWM Output Mode

Note: Not all of the features and registers listed in the Figures and Code Examples in this section are available on all devices. Refer to the "**High-Speed PWM**" chapter of the specific device data sheet for availability.

In Redundant PWM Output mode, the High-Speed PWM module has the ability to provide two copies of a single-ended PWM output signal per PWM pin pair (PWMxH, PWMxL). This mode uses the PDCx register to specify the duty cycle. In this output mode, the two PWM output pins will provide the same PWM signal unless the user-assigned application specifies an override value. The following eight figures and examples show the Redundant PWM Output mode in multiple operating modes.

Figure 14-23: Redundant PWM Mode – Independent Duty Cycle and Phase, Fixed Primary Period, Edge-Aligned



Example 14-22: Redundant PWM Mode – Independent Duty Cycle and Phase, Fixed Primary Period, Edge-Aligned

```
/* Set PWM Period on Primary Time Base */
PTPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
PHASE2 = 100;
PHASE3 = 200;
/* Set Duty Cycles */
PDC1 = 150;
PDC2 = 200;
PDC3 = 400;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Redundant */
IOCON1 = IOCON2 = IOCON3 = 0xC400;
/* Set Primary Time Base, Edge-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0000;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```





High-Speed PWN

Example 14-23: Redundant PWM Mode – Independent Duty Cycle and Phase, Fixed Secondary Period, Edge-Aligned

```
/* Set PWM Period on Secondary Time Base */
STPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
PHASE2 = 100;
PHASE3 = 200;
/* Set Duty Cycles */
PDC1 = 150;
PDC2 = 200;
PDC3 = 400;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Redundant */
IOCON1 = IOCON2 = IOCON3 = 0xC400;
/* Set Secondary Time Base, Edge-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0008;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-25: Redundant PWM Mode – Master Duty Cycle and Variable Phase, Fixed Primary Period, Edge-Aligned



Example 14-24: Redundant PWM Mode – Master Duty Cycle and Variable Phase, Fixed Primary Period, Edge-Aligned

```
/* Set PWM Period on Primary Time Base */
PTPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
PHASE2 = 100;
PHASE3 = 200;
/* Set Duty Cycles */
MDC = 400;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Redundant */
IOCON1 = IOCON2 = IOCON3 = 0xC400;
/* Set Primary Time Base, Edge-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0100;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0x8000;
```





High-Speed PWN

Example 14-25: Redundant PWM Mode – Master Duty Cycle and Variable Phase, Fixed Secondary Period, Edge-Aligned

```
/* Set PWM Period on Secondary Time Base */
STPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
PHASE2 = 100;
PHASE3 = 200;
/* Set Duty Cycles */
MDC = 400;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Redundant */
IOCON1 = IOCON2 = IOCON3 = 0xC400;
/* Set Secondary Time Base, Edge-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0108;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0x8000;
```

Figure 14-27: Redundant PWM Mode – Independent Duty Cycles and Independent Periods, No Phase-Shifting, Edge-Aligned



Example 14-26: Redundant PWM Mode – Independent Duty Cycles and Independent Periods, No Phase-Shifting, Edge-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 800;
PHASE2 = 900;
PHASE3 = 1000;
/* Set Duty Cycles */
PDC1 = 200;
PDC2 = 300;
PDC3 = 400;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Redundant */
IOCON1 = IOCON2 = IOCON3 = 0xC400;
/* Set Independent Time Bases, Edge-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0200;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0x0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-28: Redundant PWM Mode – Master Duty Cycles and Independent Periods, No Phase-Shifting,



High-Speed PWN

14

Example 14-27: Redundant PWM Mode – Master Duty Cycles and Independent Periods, No Phase-Shifting, Edge-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 800;
PHASE2 = 900;
PHASE3 = 1000;
/* Set Duty Cycles */
MDC = 200;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Redundant */
IOCON1 = IOCON2 = IOCON3 = 0xC400;
/* Set Independent Time Bases, Edge-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0300;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-29: Redundant PWM Mode – Independent Duty Cycles and Independent Periods, No Phase-Shifting, Center-Aligned



Example 14-28: Redundant PWM Mode – Independent Duty Cycles and Independent Periods, No Phase-Shifting, Center-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 1000;
PHASE2 = 900;
PHASE3 = 800;
/* Set Duty Cycles */
PDC1 = 400;
PDC2 = 300;
PDC3 = 200;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Redundant */
IOCON1 = IOCON2 = IOCON3 = 0xC400;
/* Set Independent Time Bases, Center-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0204;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0x0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-30: Redundant PWM Mode – Master Duty Cycles and Independent Periods, No Phase-Shifting,



Example 14-29: Redundant PWM Mode – Master Duty Cycles and Independent Periods, No Phase-shifting, Center-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 1000;
PHASE2 = 900;
PHASE3 = 800;
/* Set Duty Cycles */
MDC = 200;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Redundant */
IOCON1 = IOCON2 = IOCON3 = 0xC400;
/* Set Independent Time Bases, Center-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0304;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0x8000;
```

Table 14-2 provides PWM register functionality for the PWM modes.

Function	Config	uration in PWI	Pins		
	MDCS	ITB	MTBS	PWMxH	PWMxL
PWM Duty Cycle	0	х	x	PDCx	PDCx
	1	х	х	MDC	MDC
PWM Phase Shift	х	0	x	PHASEx	PHASEx
PWM Period	х	x	0	PTPER	PTPER
	х	х	1	STPER	STPER
	x	1	x	PHASEx	PHASEx

Legend: x = don't care

14.6.4 True Independent PWM Output Mode

Note: Not all of the features and registers listed in the Figures and Code Examples in this section are available on all devices. Refer to the "**High-Speed PWM**" chapter of the specific device data sheet for availability.

In True Independent PWM Output mode (PMOD = 11), the PWM outputs (PWMxH and PWMxL) can have different duty cycles. The PDCx register specifies the duty cycle for the PWMxH output, whereas the SDCx register specifies the duty cycle for the PWMxL output. In addition, the PWMxH and PWMxL outputs can either have different periods or they can be phase-shifted relative to each other.

- When ITB = 1, the PHASEx register specifies the PWM period for the PWMxH output and the SPHASEx register specifies the PWM period for the PWMxL output
- When ITB = 0, the PHASEx register specifies the phase shift for the PWMxH output and the SPHASEx register specifies the phase shift for the PWMxL output

Note: In Independent Time Base mode (ITB = 1), there may not be a deterministic phase relationship between the PWMxH and PWMxL outputs.

Figure 14-31: Independent PWM Mode – Independent Duty Cycle and Phase, Fixed Primary Period, Edge-Aligned



High-Speed PWN

Example 14-30: Independent PWM Mode – Independent Duty Cycle and Phase, Fixed Primary Period, Edge-Aligned

```
/* Set PWM Period on Primary Time Base */
PTPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
SPHASE1 = 100;
PHASE2 = 200;
SPHASE2 = 300;
PHASE3 = 400;
SPHASE3 = 500;
/* Set Duty Cycles */
PDC1 = 100;
SDC1 = 200;
PDC2 = 300;
SDC2 = 400;
PDC3 = 500;
SDC3 = 600;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Independent */
IOCON1 = IOCON2 = IOCON3 = 0xCC00;
/* Set Primary Time Base, Edge-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0000;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0x8000;
```

Figure 14-32: Independent PWM Mode – Independent Duty Cycle and Phase, Fixed Secondary Period, Edge-Aligned



Example 14-31: Independent PWM Mode – Independent Duty Cycle and Phase, Fixed Secondary Period, Edge-Aligned

```
/* Set PWM Period on Secondary Time Base */
STPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
SPHASE1 = 100;
PHASE2 = 200;
SPHASE2 = 300;
PHASE3 = 400;
SPHASE3 = 500;
/* Set Duty Cycles */
PDC1 = 100;
SDC1 = 200;
PDC2 = 300;
SDC2 = 400;
PDC3 = 500;
SDC3 = 600;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Independent */
IOCON1 = IOCON2 = IOCON3 = 0xCC00;
/* Set Secondary Time Base, Edge-Aligned Mode and Independent Duty Cycles ^{*/}
PWMCON1 = PWMCON2 = PWMCON3 = 0x0008;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```

Figure 14-33: Independent PWM Mode – Master Duty Cycle, Variable Phase, Fixed Primary Period,



Example 14-32: Independent PWM Mode – Master Duty Cycle, Variable Phase, Fixed Primary Period, Edge-Aligned

```
/* Set PWM Period on Primary Time Base */
PTPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
SPHASE1 = 100;
PHASE2 = 200;
SPHASE2 = 300;
PHASE3 = 400;
SPHASE3 = 500;
/* Set Duty Cycles */
MDC = 300;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Independent */
IOCON1 = IOCON2 = IOCON3 = 0xCC00;
/* Set Primary Time Base, Edge-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0100;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0x0000;
/* Enable PWM Module */
PTCON = 0x8000;
```





Example 14-33: Independent PWM Mode – Master Duty Cycle, Variable Phase, Fixed Secondary Period, Edge-Aligned

```
/* Set PWM Period on Secondary Time Base */
STPER = 1000;
/* Set Phase Shift */
PHASE1 = 0;
SPHASE1 = 100;
PHASE2 = 200;
SPHASE2 = 300;
PHASE3 = 400;
SPHASE3 = 500;
/* Set Duty Cycles */
MDC = 300;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Independent */
IOCON1 = IOCON2 = IOCON3 = 0xCC00;
/* Set Secondary Time Base, Edge-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0108;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0x0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```



Figure 14-35: Independent PWM Mode – Independent Duty Cycles and Periods, No Phase-Shifting, Edge-Aligned

Example 14-34: Independent PWM Mode – Independent Duty Cycles and Periods, No Phase-Shifting, Edge-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 800;
SPHASE1 = 900;
PHASE2 = 1000;
SPHASE2 = 1100;
PHASE3 = 1200;
SPHASE3 = 1300;
/* Set Duty Cycles */
PDC1 = 200;
SDC1 = 300;
PDC2 = 400;
SDC2 = 500;
PDC3 = 600;
SDC3 = 700;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Independent */
IOCON1 = IOCON2 = IOCON3 = 0xCC00;
/* Set Independent Time Bases, Edge-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0200;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0x0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```



Figure 14-36: Independent PWM Mode – Master Duty Cycles, Independent Periods, No Phase-Shifting, Edge-Aligned

Example 14-35: Independent PWM Mode – Master Duty Cycles, Independent Periods, No Phase-Shifting, Edge-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 800;
SPHASE1 = 900;
PHASE2 = 1000;
SPHASE2 = 1100;
PHASE3 = 1200;
SPHASE3 = 1300;
/* Set Duty Cycles */
MDC = 200;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Independent */
IOCON1 = IOCON2 = IOCON3 = 0xCC00;
/* Set Independent Time Bases, Edge-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0300;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0 \times 8000;
```



Figure 14-37: Independent PWM Mode – Independent Duty Cycles and Periods, No Phase-Shifting, Center-Aligned

Example 14-36: Independent PWM Mode – Independent Duty Cycles and Periods, No Phase-Shifting, Center-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 1300;
SPHASE1 = 1200;
PHASE2 = 1100;
SPHASE2 = 1000;
PHASE3 = 900;
SPHASE3 = 800;
/* Set Duty Cycles */
PDC1 = 700;
SDC1 = 600;
PDC2 = 500;
SDC2 = 400;
PDC3 = 300;
SDC3 = 200;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Independent */
IOCON1 = IOCON2 = IOCON3 = 0xCC00;
/* Set Independent Time Bases, Center-Aligned Mode and Independent Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0204;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0x8000;
```



Figure 14-38: Independent PWM Mode – Master Duty Cycles, Independent Periods, No Phase-Shifting, Center-Aligned

Example 14-37: Independent PWM Mode – Master Duty Cycles, Independent Periods, No Phase-Shifting, Center-Aligned

```
/* Set PWM Periods on PHASEx Registers */
PHASE1 = 1300;
SPHASE1 = 1200;
PHASE2 = 1100;
SPHASE2 = 1000;
PHASE3 = 900;
SPHASE3 = 800;
/* Set Duty Cycles */
MDC = 700;
/* Set Dead Time Values */
DTR1 = DTR2 = DTR3 = 0;
ALTDTR1 = ALTDTR2 = ALTDTR3 = 0;
/* Set PWM Mode to Independent */
IOCON1 = IOCON2 = IOCON3 = 0xCC00;
/* Set Independent Time Bases, Center-Aligned Mode and Master Duty Cycles */
PWMCON1 = PWMCON2 = PWMCON3 = 0x0304;
/* Configure Faults */
FCLCON1 = FCLCON2 = FCLCON3 = 0x0003;
/* 1:1 Prescaler */
PTCON2 = 0 \times 0000;
/* Enable PWM Module */
PTCON = 0x8000;
```

Function	Config	uration in PW	Pins		
Function	MDCS	ITB	MTBS	PWMxH	PWMxL
PWM Duty Cycle	0	Х	х	PDCx	SDCx
	1	Х	х	MDC	MDC
PWM Phase Shift	x	0	Х	PHASEx	SPHASEx
PWM Period	х	х	0	PTPER	PTPER
	X	X	1	STPER	STPER
	Х	1	х	PHASEx	SPHASEx

Table 14-3: Independent Output Mode Register Functionality

Table 14-3 lists the PWM register functionality for Independent Output mode.

Legend: x = Don't care

14.7 PWM GENERATOR

Note: Not all registers and features listed in this section are available on all devices. Refer to the "**High-Speed PWM**" chapter in the specific device data sheet for availability.

This section describes the functionality of the PWM generator.

14.7.1 PWM Period

The PWM period value defines the switching frequency of the PWM pulses. The PWM period value can be controlled by the Primary Master Time Base Period register (PTPER), or by the Independent Time Period PHASEx and SPHASEx registers for the respective primary and secondary PWM outputs, if available.

The PWM period value can be controlled in two ways when the High-Speed PWM module operates in Independent Time Base mode:

- In some modes, the PHASEx register controls the PWM period value of the PWM output signals (PWMxH and PWMxL)
- In True Independent Output mode, the PHASEx register controls the PWM period value of the PWMxH output signal, and the SPHASEx register controls the PWM period value of the PWMxL output signal

Refer to **14.6** "**PWM Operating Modes**", for detailed information about various PWM modes and their features.

When the High-Speed PWM module operates in Master Time Base mode, the PTPER register holds the 16-bit value, which specifies the counting period for the PMTMR timer. When the High-Speed PWM module operates in Independent Time Base mode, the PHASEx and SPHASEx registers hold the 16-bit value that specifies the counting period for the PTMRx and STMRx timer, respectively. The timer period can be updated at any time by the user-assigned application. The PWM time period (PTPER) in Edge-Aligned PWM mode (CAM bit (PWMCONx<2>) is set to '0') can be determined by using the Equation 14-1.

Equation 14-1: PERIOD, PHASEx and SPHASEx Register Value Calculation for Edge-Aligned Mode

Fosc

FPWM * PWM Input Clock Prescaler

Where:

FPWM = Desired PWM frequency

Fosc = Oscillator output (120 MHz for 60 MIPS)

PTPER. PHASEx. SPHASEx =

PWM Input Clock Prescaler = Value defined in the PCLKDIV<2:0> bits (PTCON2<2:0)

Based on Equation 14-1, while operating in the master time base (PTPER register) or the independent time base (PHASEx and SPHASEx registers), the register value to be loaded is shown in Example 14-38.

Example 14-38: PWM Time Period Calculation for Edge-Aligned Mode

$$PTPER = \frac{120MHz}{20kHz \times 1} = 6000$$

Where: Desired PWM Switching Frequency = 20 kHz PWM Input Clock Prescaler = 1:1 System Oscillator Frequency (Fosc) = 120 MHz The PWM time period (PHASEx or SPHASEx) in Center-Aligned mode (CAM = 1 and ITB = 1), can be determined using Equation 14-2. The PTPER register does not represent the period in Center-Aligned mode, since this mode requires independent time bases, which are enabled by setting ITB = 1.

Equation 14-2: PHASEx or SPHASEx Register Value Calculation in Center-Aligned Mode

 $PHASEx, SPHASEx = \frac{FOSC}{FPWM \cdot PWM Input Clock Prescaler \cdot 2}$

Based on Equation 14-2, when operating in independent time bases (PHASEx and SPHASEx registers), the register value to be loaded is shown in Example 14-39.

Example 14-39	DWM Time	Pariad C	alculation	Evamplo in	Contor-Ali	anod Modo
Example 14-35.	F VVIVI TITTE	Feriou C	alculation	Example in	Center-An	gneu woue

 $PHASEx, SPHASEx = \frac{120 MHz}{20 kHz \cdot 1 \cdot 2} = 3000$

Where: PWM Frequency (FPWM) = 20 kHz PWM Input Clock Prescaler = 1:1 System Oscillator Frequency (Fosc) = 120 MHz

The maximum available PWM period resolution is Tosc for Edge-Aligned mode and Tosc * 2 in Center-Aligned mode. The PCLKDIV<2:0> bits (PTCON2<2:0>), determine the type of PWM clock. The timer/counter is enabled or disabled by setting or clearing the PTEN bit (PTCON<15>). The PMTMR timer can also be cleared using the PTEN bit.

If the EIPU bit (PTCON<10>) is set, the active master period register (an internal shadow register) is updated immediately instead of waiting for the PWM cycle to end. The EIPU bit affects the PMTMR master time base.

Example 14-40: Clock Prescaler Selection

```
/* Select PWM time base input clock prescaler */
/* Choose divide ratio of 1:2 */
```

PTCON2bits.PCLKDIV = 1;

Example 14-41: PWM Time Period Selection

```
/* Select Time Base Period Control */
/* Choose one of these options */
PWMCON1bits.ITB = 0; /* PTPER provides the PWM time period value */
PWMCON1bits.ITB = 1; /* PHASEx/SPHASEx provides the PWM time period value */
```

Example 14-42: PWM Time Period Initialization

```
/* Choose PWM time period based on FRC input clock */
/* PWM frequency is 100 kHz */
/* Choose one of the following options */
PTPER = 4808;
PHASEx = 4808;
SPHASEx = 4808;
```
14.7.2 PWM Duty Cycle Control

The duty cycle determines the period of time the PWM output should remain in the active state. Each duty cycle register allows a 16-bit duty cycle value to be specified. The duty cycle values can be updated at any time by setting the IUE bit (PWMCONx<0>). If the IUE bit is '0', the active register updates at the start of the next PWM cycle.

The Master Duty Cycle register (MDC) enables multiple PWM generators to share a common duty cycle register. The MDC register has an important role in Master Time Base mode.

In addition, each PWM generator has a Primary Duty Cycle register (PDCx) and on certain devices, a Secondary Duty Cycle register (SDCx) that provides separate duty cycles to each PWM.

14.7.2.1 MASTER DUTY CYCLE (MDC)

The master time base generator controls the master duty cycle. The MDCS bit (PWMCONx<8>), determines whether the duty cycle of each of the PWMxH and PWMxL outputs are controlled by the PWM Master Duty Cycle register (MDC) or the PWM Primary Duty Cycle (PDCx) and PWM Secondary Duty Cycle (SDCx) registers.

The MDC register enables sharing of the common duty cycle register among multiple PWM generators and saves the CPU overhead required in updating multiple duty cycle registers.

14.7.2.2 PRIMARY DUTY CYCLE (PDCx)

The independent time base controls the primary duty cycle when the ITB bit (PWMCONx<9>) is set to '1'. The PDCx register is an input register that provides the duty cycle value for the primary PWM output signal (PWMxH).



Figure 14-39: Primary Duty Cycle Comparison

14.7.2.3 SECONDARY DUTY CYCLE (SDCx)

Note: The SDCx register is not available on all devices. Refer to the "**High-Speed PWM**" chapter of the specific device data sheet for availability.

The independent time base in the PWMCONx register controls the Secondary Duty Cycle register (SDCx) when the ITB bit is set to '1'. The SDCx register is an input register that provides the duty cycle value for the secondary PWM output signal (PWMxL).

Figure 14-40: Secondary Duty Cycle Comparison



The duty cycle can be determined by using Equation 14-3.

Equation 14-3: MDC, PDCx and SDCx Calculation

 $MDC, PDCx, and SDCx = \frac{FOSC}{FPWM \cdot PWM Input Clock Prescaler} \cdot Desired Duty Cycle$ Where: FPWM = PWM FrequencyFOSC = System Oscillator OutputPWM Input Clock Prescaler = Value defined in the PCLKDIV<2:0> bits (PTCON<2:0>)Desired Duty Cycle = Value between 0 and 1 for desired duty cycleNote 1: If a duty cycle value is greater than or equal to the period value, a signal will have a duty cycle of 100 percent.

- 2: When dead time compensation is disabled if PDCx does not adhere to (PDCx > ((ALTDTRx/2) -1)) the PWMxH will be constantly high.
- 3: If PDCx > (ALTDTRx + DTRx 1) condition is not satisfied it could result in one or both of the below:

a) Loss of dead time.

b) PWMxH will be constantly high.

Based on Equation 14-3, when the master, independent primary, or independent secondary duty cycle is used, the register value is loaded in the MDC, PDCx, or SDCx register, respectively.

14.7.2.4 DUTY CYCLE RESOLUTION

The PWM duty cycle bit resolution for Edge-Aligned mode can be determined using Equation 14-4, and the PWM duty cycle bit resolution for Center-Aligned mode can be determined using Equation 14-5.

Equation 14-4: Bit Resolution Calculation for Edge-Aligned Mode

$$Bit Resolution = \log 2 \left[\frac{FOSC}{FPWM \cdot PWM Input Clock Prescaler} \right]$$

Equation 14-5: Bit Resolution Calculation for Center-Aligned Mode

$$Bit Resolution = \log 2 \left[\frac{FOSC}{FPWM \cdot PWM Input Clock Prescaler \cdot 2} \right]$$

Example 14-43: PWM Duty Cycle Selection

PWMCON1bits.MDCS = 0;	/*	PDCx/SDCx	pro	ovides	duty	cycle	value	*/
PWMCON1bits.MDCS = 1;	/*	MDC provi	des	duty	cycle	value	*/	

Example 14-44: PWM Duty Cycle Initialization

/* Initialize	PWM Duty Cycle Value */
PDC1 = 2404;	/* Independent Primary Duty Cycle is 50% of the period */
SDC1 = 2404;	/* Independent Secondary Duty Cycle is 50% of the period */
MDC = 2404;	/* Master Duty Cycle is 50% of the period */

14.7.3 Dead Time Generation

The dead time refers to a programmable period of time (specified by the PWM Dead Time register (DTRx) or the PWM Alternate Dead Time register (ALTDTRx)), which prevents a PWM output from being asserted until its complementary PWM signal has been deasserted for the specified time.

The High-Speed PWM module has four dead time control units. Each dead time control unit has its own dead time value.

Dead time generation can be provided when any of the PWM I/O pin pairs are operating in Complementary Output mode. Many power converter circuits require dead time because power transistors cannot switch instantaneously. To prevent current shoot-through, some amount of time must be provided between the turn-off event of one PWM output and the turn-on event of the other PWM output in a complementary pair or the turn-on event of the other transistor.

The High-Speed PWM module provides positive as well as negative dead time. The positive dead time prevents overlapping of PWM outputs. Positive dead time generation is available for all output modes. Positive dead time circuitry works by blanking (gating) the leading edge of the PWM signal. Negative dead time is the forced overlap of the PWMxH and PWMxL signals. Negative dead time works when the extended time period of the currently active PWM output overlaps the PWM output that is just asserted. Certain converter techniques require a limited amount of current shoot-through.

Negative dead time is specified only for complementary PWM signals. Negative dead time does not apply to user or current-limit, or fault overrides. This mode can be implemented by using phase shift values in the PHASEx registers that shifts the PWM outputs so that the outputs overlap another PWM signal from a different PWM output channel. Negative dead time is only implemented for Edge-Aligned mode (CAM = 0).

The dead time logic acts as a gate and allows an asserted PWM signal or an override value to propagate to the output. The dead time logic never asserts a PWM output on its own initiative.



Figure 14-41: Dual Dead Time Waveforms for Edge-Aligned Mode



Figure 14-42: Dual Dead Time Waveforms for Center-Aligned Mode

The dead time feature can be disabled for each PWM generator. The dead time functionality is controlled by the DTC<1:0> bits (PWMCONx<7:6>).

14.7.4 Dead Time Generators

Each complementary output pair for the High-Speed PWM module has a 12-bit down counter to produce the dead time insertion. Each dead time unit has a rising and falling edge detector connected to the duty cycle comparison output. Depending on whether the edge is rising or falling, one of the transitions on the complementary outputs is delayed until the associated dead time timer generates the specific delay period.

The dead time logic monitors the rising and falling edges of the PWM signals. The dead time counters reset when the associated PWM signal is inactive, and start counting when the PWM signal is active. Any selected signal source that provides the PWM output signal is processed by the dead time logic.

The dead time can be determined using the formula shown in Equation 14-6.

Equation in South Into Calculation	Equation 14	4-6: Dead	Time Calcula	tion
------------------------------------	-------------	-----------	--------------	------

ALTDTRx, $DTRx = FOSC * \frac{Desired Dead Time}{PWM Input Clock Prescaler}$

Three Dead Time Control modes are available, which are described in the following sections.

14.7.4.1 POSITIVE DEAD TIME

The Positive Dead Time mode describes a period of time when both PWMxH and PWMxL outputs are not asserted. This mode is useful when the application designer needs to allocate time to disable some power transistors prior to enabling other transistors. This is similar to a "Break before Make" switch. When Positive Dead Time mode is specified in Edge-Aligned PWM mode (CAM = 0), the DTRx register specifies the dead time for the PWMxH output, and the ALTDTRx register specifies the dead time for the PWMxH output, and the enabled (CAM = 1), the ALTDTR register specifies the dead time, while the DTRx register is ignored. These two modes are shown in Figure 14-43 and Figure 14-44.

Figure 14-43: Positive Dead Time in Edge-Aligned Mode and Complementary Mode







14.7.4.2 NEGATIVE DEAD TIME

The Negative Dead Time mode describes a period of time when both PWMxH and PWMxL outputs are asserted. This mode is useful in current fed topologies that need to provide a path for current to flow when the power transistors are switching. This is similar to a "Make before Break" switch. When Negative Dead Time mode is specified in Edge-Aligned mode, the DTRx register specifies the negative dead time for the PWMxL output, and the ALTDTRx register specifies the negative dead time for the PWMxH output. When Center-Aligned mode is enabled (CAM = 1), negative dead time is not supported, and the ALTDTRx and DTRx registers are ignored. This mode is shown in Figure 14-45.

Figure 14-45: Negative Dead Time in Edge-Aligned Mode and Complementary Mode



14.7.4.3 DEAD TIME COMPENSATION

When dead time is applied to the PWM signals in AC motor control applications, the transistors are disabled. During dead time, motor current continues to flow through the free-wheeling diodes, but the applied voltage is zero. The zero applied voltage during dead time causes a distortion of the desired voltage waveform and subsequently a motor current distortion. This distortion causes torque variations that can affect the stability of the control system, and the performance of the motor.

Dead Time Compensation mode enables an external signal (DTCMPx) to modify the duty cycle to overcome motor current distortion caused by the dead time.

When Dead Time Compensation mode is selected via the DTC<1:0> bits (PWMCONx<7:6>), an external input signal (DTCMPx) will cause the value in the DTRx register to be added to, or subtracted from, the duty cycle specified by the PDCx or MDC registers. The ALTDTRx register will specify the dead time for both the PWMxH and PWMxL output signals.

Dead time compensation is available only for Complementary PWM output mode with Positive Dead Time mode. Negative dead times or any other PWM output mode are not supported by Dead Time Compensation mode.







Figure 14-47: Dead Time Compensation in Edge-Aligned Mode (DTCMPx Pin = 1 and DTCP = 0 or DTCMPx Pin = 0 and DTCP = 1)



– ALTDTRx/2

T

← ALTDTRx/2

I

I

Dead Time Compensation in Center-Aligned Mode (DTCMPx Pin = 0 and DTCP = 0 or DTCMPx Figure 14-48:

PWMxH

PWMxL

ALTDTRx/2

ALTDTRx/2-►

DTRx ≠ 0 ALTDTRx $\neq 0$





The dead time compensation external input control signal, DTCMPx, is sampled at the beginning of each dead time period. This sampling process ensures that the control signal does not change midway through the dead time generation process. The DTCMPx signal determines whether the duty cycle will be increased or decreased by the amount specified in the DTRx register.

14.7.4.4 DEAD TIME DISABLED

The dead time logic can be disabled per PWM generator. The dead time functionality is controlled by the DTC<2:0> bits (PWMCONx<7:6>).

14.7.5 Dead Time Ranges

The dead time duration provided by each dead time unit is set by specifying an unsigned value in the DTRx and ALTDTRx registers. At maximum operating clock frequency with a Tosc duty cycle resolution, the dead time resolution is Tosc (7.14 ns at 140 MHz of Fosc). The maximum dead time value is $(2^{14} - 1)$ Tosc = 116.9 µs when operating at 140 MHz Fosc.

14.7.6 Dead Time Distortion

For duty cycle values near 0% or 100%, the PWM signal becomes nonlinear if dead time is active. For any duty cycle value less than the dead time, the PWM output is zero. For duty cycle values greater than "100% – dead time", the PWM output is the same as if the duty cycle is "100% – dead time".

14.7.7 Dead Time Insertion in Center-Aligned Mode

While using Center-Aligned mode and complementary PWM, only the ALTDTRx register should be used for dead time insertion. The dead time is inserted in the PWM waveform as shown in Figure 14-50.

Figure 14-50: Positive Dead Time Insertion in Center-Aligned Mode



14.7.8 Phase Shift

Phase shift is the relative offset between PWMxH or PWMxL with respect to the master time base. In Independent Output mode, the PHASEx register determines the relative phase shift between PWMxH and the master time base. The SPHASEx register determines the relative phase shift between PWMxL and the master time base. The contents of the PHASEx register are used as an initialization value for the PTMRx register, and the SPHASEx register contents are used as an initialization value for the STMRx register.

Note: The SPHASEx register is not available on all devices. Refer to the **"High-Speed PWM**" chapter in the specific device data sheet for availability.

Figure 14-51 and Figure 14-52 provide example waveforms for phase shifting in Complementary mode and Independent Output mode, respectively.

Figure 14-51: Phase Shifting (Complementary Mode)







In addition, there are two shadow registers for the PHASEx and SPHASEx registers that are updated whenever new values are written by the user-assigned application. These values are transferred from the shadow registers to the PHASEx and SPHASEx registers on an independent time base Reset. The actual application of these phase offsets on the PWM output will occur on a master time base Reset.

Figure 14-53 shows the timing diagram that illustrates how these events are generated.

The phase offset value can be any value between zero and the value in the PTPER register. Any PHASEx or SPHASEx value greater than the PERIOD value will be treated as a value equal to the Period. It is not possible to create phase shifts greater than the Period.





High-Speed PWN

Example 14-45: PWM Phase Shift Initialization

<pre>/* Initialize phas /* Phase shifts ar</pre>	e shift value for the PWM output */ e initialized when operating in Master Time Base */
PHASEx = $100;$	/* Primary phase shift value */
SPHASEx = 100;	/* Secondary phase shift value */

The bit resolution of PWM duty cycle, phase, and dead time with respect to different input clock prescaler selections are shown in Table 14-5.

PWM Clock	Bit Resolution							
Prescaler	64 * Tosc	32 * Tosc	16 * Tosc	8 * Tosc	4 * Tosc	2 * Tosc	Tosc	
1:1	bit 6	bit 5	bit 4	bit 3	bit 2	bit 1	bit 0	
1:2	bit 5	bit 4	bit 3	bit 2	bit 1	bit 0	—	
1:4	bit 4	bit 3	bit 2	bit 1	bit 0	—	—	
1:8	bit 3	bit 2	bit 1	bit 0	—	—	—	
1:16	bit 2	bit 1	bit 0	—	—	—	—	
1:32	bit 1	bit 0	—	—	—	—	—	
1:64	bit 0		_	_	_	_	_	

 Table 14-4:
 Duty Cycle, Phase, Dead Time Bit Resolution vs. Prescaler Selection

14.8 **PWM TRIGGER**

For the ADC module, the TRIGx register specifies the triggering point for the PWMxH and PWMxL outputs, respectively. An ADC trigger signal will be generated when the independent time base counter (PTMRx) register value matches with the specified TRIGx register value.

The TRGDIV<3:0> bits in the TRGCONx register act as a postscaler for the TRIGx register to generate ADC triggers. This allows the trigger signal to the ADC to be generated once for every 1, 2, 3.... and 16 trigger events. These bits specify how frequently the ADC trigger is generated.

Each PWM generator has TRGSTRT<5:0> bits (TRGCONx<5:0>) that specify how many PWM cycles to wait before generating the first ADC trigger.

Figure 14-54 shows the logic for ADC triggering by the High-Speed PWM module.

Figure 14-54: PWM Trigger for Analog-to-Digital Conversion



Depending on the settings of the TRGDIV<3:0> and TRGSTRT<5:0> bits, triggers are generated at different PWM intervals, as shown in Figure 14-55 through Figure 14-62.

Note: A trigger can only be generated on the first PWM interval when the TRGDIV<3:0> bits are set to '0'.

Figure 14-55: PWM Trigger Signal in Relation to the PWM Output in Edge-Aligned Mode (TRGDIV = 0, TRGSTRT = 0)



dsPIC33E/PIC24E Family Reference Manual



Figure 14-56: PWM Trigger Signal in Relation to the PWM Output in Edge-Aligned Mode (TRGDIV = 0, TRGSTRT = 1)





Figure 14-58: PWM Trigger Signal in Relation to the PWM Output in Edge-Aligned Mode (TRGDIV = 1, TRGSTRT = 0)







High-Speed PWM

14

dsPIC33E/PIC24E Family Reference Manual











Figure 14-63: Trigger Signal in Relation to PWM Output in Center-Aligned Mode (TRGDIV = 0, TRGSTRT = 0)



Figure 14-64: Trigger Signal in Relation to PWM Output in Center-Aligned Mode (TRGDIV = 0, TRGSTRT = 1)



High-Speed PWN



Figure 14-66: Trigger Signal in Relation to PWM Output in Center-Aligned Mode (TRGDIV = 1, TRGSTRT = 0)







The trigger divider allows the user-assigned application to tailor the ADC sample rates to the requirements of the control loop.

If ADC triggers are generated at a rate faster than the rate that the ADC can process, the operation may result in loss of some samples. However, the user-assigned application can ensure that the time it provides is enough to complete an ADC operation within a single PWM cycle.

The trigger pulse is generated regardless of the state of the TRGIEN bit (PWMCONx<10>). If the TRGIEN bit (PWMCONx<10>) is set to '1', an interrupt request is generated.

Example 14-46: Independent PWM ADC Triggering

/* Independent PWM ADC Triggering */						
TRIG1 = 1248;	<pre>/* Point at which the ADC module is to be triggered by primary PWM */</pre>					
TRGCON1bits.TRGDIV = 0;	/* Trigger output divider set to trigger ADC on every trigger match event */					
TRGCON1bits.TRGSTRT = 4; /	/* First ADC trigger event occurs after four trigger match events */					
<pre>PWMCON1bits.TRGIEN = 1; // while (PWMCON1bits.TRGSTAT</pre>	<pre>/* Trigger event generates an interrupt request */ = = 1); /* Wait for ADC interrupt status change */</pre>					

Note 1: The TRGSTAT bit is only cleared by clearing the TRGIEN bit. It is not cleared automatically.

2: Dynamic triggering can show some advantages where multiple PWM channels are used in applications, such as IPFC and multi-phase buck regulators. The TRIGx values can be changed based on the PWM period, duty, load current, etc. This is to ensure that the trigger points are separated from the rise and fall instances of the PWM channel.



Figure 14-68: Effect of Phase Shift on PWM Triggers

When phase shifting the PWM signal, the PWM timer value is updated to reflect the new phase value. There is a possibility of missing trigger events when changing the phase from a smaller value to a larger value. The user-assigned application must ensure that this does not affect any control loop execution.

Timing diagrams that show triggers based on multiple PWM time base configurations are provided in Figure 14-63 through Figure 14-67.





















Table 14-6 provides a summary of the registers used as period and compare values for ADC triggers at different PWM configurations.

Table 14-5: ADC Triggers

ADxCC	ADxCON1 ⁽¹⁾		CONx	Function		
SSRCG	SSRC	ITB	MTBS	ADC Trigger Period	ADC Trigger Event	
0	011	х	х	PTPER	SEVTCMP	
0	101	Х	Х	STPER	SSEVTCMP	
1	000	0	0	PTPER	TRIG1	
1	000	0	1	STPER	TRIG1	
1	000	1	Х	PHASE1	TRIG1	
1	001	0	0	PTPER	TRIG2	
1	001	0	1	STPER	TRIG2	
1	001	1	Х	PHASE2	TRIG2	
1	010	0	0	PTPER	TRIG3	
1	010	0	1	STPER	TRIG3	
1	010	1	Х	PHASE3	TRIG3	
1	011	0	0	PTPER	TRIG4	
1	011	0	1	STPER	TRIG4	
1	011	1	Х	PHASE4	TRIG4	
1	100	0	0	PTPER	TRIG5	
1	100	0	1	STPER	TRIG5	
1	100	1	Х	PHASE5	TRIG5	
1	101	0	0	PTPER	TRIG6	
1	101	0	1	STPER	TRIG6	
1	101	1	Х	PHASE6	TRIG6	
1	110	0	0	PTPER	TRIG7	
1	110	0	1	STPER	TRIG7	
1	110	1	Х	PHASE7	TRIG7	
Logond	- don't o	aro		•		

Legend: x = don't care



14.9 **PWM INTERRUPTS**

Note: To enable PWM interrupts, use the initialization procedure defined in Section 6. "Interrupts" (DS70600) of the "dsPIC33E/PIC24E Family Reference Manual", which is available from the Microchip Web site (www.microchip.com).

The High-Speed PWM module can generate interrupts based on internal timing signals or external signals through the current-limit and fault inputs. The primary time base module can generate an interrupt request when a specified event occurs. Each PWM generator module provides its own interrupt request signal to the interrupt controller. The interrupt for each PWM generator is a Boolean OR of the trigger event interrupt request, the current-limit input event, or the fault input event for that module.

Besides one interrupt request signal per PWM generator, the interrupt controller receives an interrupt request signal from the primary time base on special events.

The interrupt requests coming from each PWM generator are called Individual PWM Interrupts. The Interrupt Request (IRQ) for each one of these individual interrupts can come from the PWM individual trigger, PWM fault logic, or PWM current-limit logic. Each PWM generator has the PWM interrupt flag in an IFSx register. When an interrupt request is generated by any of the above sources, the PWM interrupt flag associated with the selected PWM generator is set.

If more than one IRQ source is enabled, the interrupt source is determined using the user-assigned application by checking the TRGSTAT, FLTSTAT and CLSTAT bits in the PWMCONx register.

To configure interrupts, the application software should first clear the interrupt flags, enable the interrupts (see the PTCON (Register 14-1), STCON (Register 14-4), and PWMCONx (Register 14-12) registers), and finally, enable the PWM module.

14.9.1 PWM Time Base Interrupts

In each PWM generator, the High-Speed PWM module can generate interrupts based on the master time base and/or the individual time base. The PWM Special Event Compare register (SEVTCMP) specifies timer based interrupts for the primary time base, and the TRIGx registers specify timer based interrupts for the individual time bases.

The primary time base special event interrupt is enabled via the SEIEN bit (PTCON<11>). In each PWM generator, the individual time base interrupts generated by the trigger logic are controlled by the TRGIEN bit (PWMCON<10>).

Note: When an appropriate match condition occurs, the Special Event Trigger signal and the individual PWM trigger pulses to the ADC are always generated regardless of the setting of their respective interrupt enable bits.

14.10 PWM FAULT PINS

The key functions of the PWM fault input pins are as follows:

- Each PWM generator can select its own fault input source from a selection of up to eight fault and current-limit pins
- Each PWM generator has FLTSRC<4:0> bits (FCLCONx<7:3>). These bits specify the source for its fault input signal.
- Each PWM generator has the FLTIEN bit (PWMCONx<12>). This bit enables the generation of fault interrupt requests.
- Each PWM generator has the FLTPOL bit (FCLCONx<2>). This bit selects the active state of the selected fault input.
- Upon occurrence of a Fault condition, the PWMxH and PWMxL outputs can be forced to one of the following states:
 - If the IFLTMOD bit is enabled, the FLTDAT<1:0> (High/Low) bits (IOCONx<5:4>) provides data values to be assigned to the PWMxH and PWMxL outputs
 - In Fault mode, the FLTDAT<1:0> (High/Low) bits provide the data values to be assigned to the PWMxH and PWMxL outputs

The following list describes major functions of the fault input pin:

- A fault can override the PWM outputs. The FLTDAT<1:0> bits (IOCONx<5:4>) can have a value of either '0' or '1'. If FLTDAT is set to '0', it is processed asynchronously to enable the immediate shutdown of the associated power transistors in the application circuit. If FLTDAT is set to '1', it is processed by the dead time logic and then applied to the PWM outputs.
- The fault signals can generate interrupts. The FLTIEN bit (PWMCONx<12>) controls the fault interrupt signal generation. The user-assigned application can specify interrupt signal generation even if the FLTMOD bits disable the fault override function. This allows the fault input signal to be used as a general purpose external interrupt request signal.
- The fault input signal that can be used as a trigger signal to the ADC, which initiates an ADC conversion process. The ADC trigger signals are always active regardless of the state of the High-Speed PWM module, the FLTMOD bits, or the FLTIEN bit.

The FLTx pins are normally active-high. The FLTPOL bit (FCLCONx<2>), when set to '1', inverts the selected fault input signal; therefore, these pins are set as active-low.

The fault pins are also readable through the port I/O logic when the High-Speed PWM module is enabled. This allows the user-assigned application to poll the state of the fault pins in software.

14.10.1 Class B Fault

Certain devices incorporate a fault that has been implemented with Class B safety features, which is known as the Class B Fault. This fault operates in a similar manner as other faults, with the exception that on any type of reset, the PWM module maintains ownership of that pin. Refer to the **"High-Speed PWM"** chapter in the specific device data sheet for the fault that incorporates this feature.

At reset, this fault is enabled in Latched mode to guarantee the fail-safe power-up of the application. The application software must clear this fault before the PWM module can be enabled. To clear the Fault condition, this fault pin must first be pulled high externally, or the internal pull-up resistor in the CNPUx register can be enabled. Once the Fault condition is cleared, the PWM module can be enabled, and if desired, the fault can be disabled.

Note: If present on the device, the Class B Fault is enabled on any type of reset. The user application must clear this fault before the PWM module can be enabled.



Figure 14-74: PWM Fault Control Module Block Diagram

14.10.2 PWM Fault Generated by the Analog Comparator

The dsPIC33E/PIC24E devices support virtual (internal) connections to the output of the comparator modules CxOUT (see Figure 26-1 in **Section 26.0 "Comparator Module"** (DS70357).

Virtual connections provide a simple way of inter-peripheral connection without utilizing a physical pin. For example, by setting the FLT1R<6:0> bits of the RPINR12 register to the value of 'b0000001, the output of the Analog Comparator, C1OUT, will be connected to the PWM Fault 1 input, which allows the Analog Comparator to trigger PWM faults without the use of an actual physical pin on the device.

Example 14-47 shows the configuration of the Analog Comparator 1 as one of the fault sources to the PWM that is connected to the fault input pin 1.

Example 14-47: Configuring Analog Comparator 1 as a Fault Source to the HS PWM Module

```
__builtin_write_OSCCONL(OSCCON & (~(1<<6))); // Unlock Register
RPINR12bits.FLT1R = 1;// Assign FLT1 to Pin C10UT
__builtin_write_OSCCONL(OSCCON | (1<<6));// Lock Registers
```

14.10.3 Fault Interrupts

The FLTIENx bit (PWMCONx<12>) determine whether an interrupt will be generated when the FLTx input is asserted high. The FLTDAT<1:0> (High/Low) bits supply the data values to be assigned to the PWMxH and PWMxL pins in case of a fault.

The PWM Fault states are available on the FLTSTAT bit (PWMCONx<15>). The FLTSTAT bit displays the fault IRQ latch. If fault interrupts are not enabled, the FLTSTAT bit displays the status of the selected FLTx input in positive logic format. When the fault input pins are not used in association with a PWM generator, these pins can be used as general purpose I/O or interrupt input pins.

In addition to its operation as the PWM logic, the fault pin logic can also operate as an external interrupt pin. If the faults are not allowed to affect the PWM generators in the FCLCONx register, the fault pin can be used as a general purpose interrupt pin.

14.10.3.1 FAULT INPUT PIN MODES

The fault input pin has two modes of operation:

- Latched mode: In Latched mode, the PWM outputs follow the states defined in the FLTDAT bits in the IOCONx registers when the fault pin is asserted. The PWM outputs remain in this state until the fault pin is deasserted and the corresponding interrupt flag has been cleared in software. When both of these actions have occurred, the PWM outputs return to normal operation at the beginning of the next PWM cycle boundary. If the FLTSTAT bit (PWMCONx<15>) is cleared before the Fault condition ends, the High-Speed PWM module waits until the fault pin is no longer asserted. Software can clear the FLTSTAT bit by writing '0' to the FLTIEN bit in the PWMCONx register.
- **Cycle-by-Cycle mode**: In Cycle-by-Cycle mode, the PWM outputs remain in the deasserted PWM state as long as the fault input pin remains asserted. In Complementary PWM Output mode, PWMxH is low (deasserted) and PWMxL is high (asserted). After the fault pin is driven high, the PWM outputs return to normal operation at the beginning of the following PWM cycle.

The operating mode for each fault input pin is selected by using the FLTMOD bits (FCLCONx<1:0>).

14.10.4 Fault Entry

With respect to the device clock signals, the PWM pins always provide asynchronous response to the fault input pins. Therefore, if '0' is deasserted, the FLTDAT bit will immediately deassert the associated PWM output, and if the specified FLTDAT bits are asserted (set to '1'), the FLTDAT bits are processed by the dead time logic prior to being output as a PWM signal.

Refer to **14.12.4** "Fault/Current-Limit Override and Dead Time Logic", for more information on data sensitivity and behavior in response to current-limit or fault events.

14.10.5 Fault Exit

After a Fault condition has ended, the PWM signals must be restored at a PWM cycle boundary to ensure proper synchronization of PWM signal edges and manual signal overrides. The next PWM cycle begins when the PTMR value is zero.

If Cycle-by-Cycle Fault mode is selected, the fault is automatically reset on every PWM cycle. No additional coding is needed to exit the Fault condition.

For the Latched Fault mode, however, the following sequence must be followed to exit the Fault condition:

- 1. Poll the PWM fault source to determine, if the fault signal has been deasserted.
- 2. If the PWM fault interrupt is not enabled, skip the following sub-steps and proceed to step 3. If the PWM fault interrupt is enabled, perform the following sub-steps, and then proceed to step 4.
 - a) Complete the PWM fault Interrupt Service Routine.
 - b) Disable the PWM fault interrupt by clearing the FLTIEN bit (PWMCONx <12>).
 - c) Enable the PWM fault interrupt by setting FLTMOD<1:0> (FCLCONx <1:0>) = 0b00.
- 3. Disable PWM faults by setting FLTMOD<1:0> (FCLCONx <1:0>) = 0b11.
- 4. Enable the latched PWM Fault mode by setting FLTMOD<1:0> (FCLCONx <1:0>) = 0b00.

14.10.6 Fault Exit with PMTMR Disabled

There is a special case for exiting a Fault condition when the PWM time base is disabled (PTEN = 0). When a fault input is programmed for Cycle-by-Cycle mode, the PWM outputs are immediately restored to normal operation when the fault input pin is deasserted. The PWM outputs should return to their default programmed values (the time base is disabled, so there is no reason to wait for the beginning of the next PWM cycle). When a fault input is programmed for Latched mode, the PWM outputs are restored immediately when the fault input pin is deasserted and the FSTAT bit has been cleared in software.

14.10.7 Fault Pin Software Control

The fault pin can be controlled manually in software. Since the fault input is shared with a GPIO port pin, this pin can be configured as an output by clearing the corresponding TRIS bit. When the port bit for the pin is set, the fault input will be activated.

14.10.8 PWM Current-Limit Pins

The key functions of the PWM current-limit pins are as follows:

- Each PWM generator can select its own current-limit input source with up to eight Fault and current-limit pins. To configure the analog comparator as one of the current-limit sources, refer to 14.10.2 "PWM Fault Generated by the Analog Comparator".
- Each PWM generator has control bits, CLSRC<4:0> (FCLCONx<14:10>). These bits specify the source for its current-limit input signal.
- Each PWM generator has a corresponding CLIEN bit (PWMCONx<11>). This bit enables the generation of current-limit interrupt requests.
- Each PWM generator has an associated CLPOL bit (FCLCONx<9>).
- Upon occurrence of current-limit condition, outputs of the PWMxH and PWMxL generator change to one of the following states:
 - If the Independent Fault Mode enable bit (IFLTMOD) is set, the CLDAT<1:0> bits are not used for override functions
 - If the Independent Fault Mode Enable bit (IFLTMOD) is clear, and the Current-Limit Mode Enable bit (CLMOD) is set, enabling the current-limit function, the CLDAT<1:0> bits (High/Low) supplies the data values to be assigned to the PWMxH and PWMxL outputs when a current-limit is active

The major functions of the current-limit pin are as follows:

- A current-limit can override the PWM outputs. The CLDAT<1:0> bits (IOCONx<3:2>) can
 have a value of either '0' or '1'. If CLDAT is set to '0', it is processed asynchronously to
 enable immediate shutdown of the associated power transistors in the application circuit. If
 CLDAT is set to '1', it is processed by the dead time logic and then applied to the PWM
 outputs.
- The current-limit signals can generate interrupts. The CLIEN bit (PWMCONx<11>) controls the current-limit interrupt signal generation. The user-assigned application can specify interrupt generation even if the CLMOD bit (FCLCONx<8>) disables the current-limit override function. This allows the current-limit input signal to be used as a general purpose external interrupt request signal.
- The current-limit input signal that can be used as a trigger signal to the ADC, which initiates an ADC conversion process. The ADC trigger signals are always active regardless of the state of the High-Speed PWM module, the FLTMOD bits, or the FLTIEN bit.
- A current-limit signal resets the time base for the affected PWM generator when the following occurs:
 - The CLMOD bit (FCLCONx<8>) for the PWM generator is '0'
 - The XPRES bit (PWMCONx<1>) is '1'
 - The PWM generator is in the Independent Time Base mode (ITB = 1)

This behavior is called Current Reset mode, which is used in some Power Factor Correction (PFC) applications.



Figure 14-75: PWM Current-Limit Control Circuit Logic Diagram

14.10.9 Current-Limit Interrupts

The state of the PWM current-limit conditions is available on the CLSTAT bit (PWMCONx<14>). The CLSTAT bits display the current-limit IRQ flag if the CLIEN bit is set. If current-limit interrupts are not enabled, the CLSTAT bits display the status of the selected current-limit inputs in positive logic format. When the current-limit input pin associated with a PWM generator is not used, these pins can be used as general purpose I/O or interrupt input pins.

The current-limit pins are normally active-high. If set to '1', the CLPOL bit (FCLCONx<9>) invert the selected current-limit input signal and drives the signal into active-low state.

The interrupts generated by the selected current-limit signals are combined to create a single interrupt request signal. This signal is sent to the interrupt controller, which has its own interrupt vector, interrupt flag bit, interrupt enable bit, and interrupt priority bits associated with it.

The fault pins are also readable through the port I/O logic when the High-Speed PWM module is enabled. This capability allows the user-assigned application to poll the state of the fault pins in software.

14.10.10 Simultaneous PWM Faults and Current-Limits

The current-limit override function, if enabled and active, forces the PWMxH and PWMxL pins to read the values specified by the CLDAT<1:0> bits (IOCONx<3:2>), unless the fault function is enabled and active. If the selected fault input is active, the PWMxH and PWMxL outputs read the values specified by the FLTDAT<1:0> bits (IOCONx<5:4>).

14.10.11 PWM Fault and Current-Limit Trigger Outputs to ADC

The current-limit and fault source selection bits, CLSRC<4:0> (FCLCONx<14:10>) and FLTSRC<4:0> (FCLCONx<7:3>), control the fault selection to each PWM generator module. The control multiplexers select the desired fault and current-limit signals for their respective modules.

Example 14-48: PWM Fault, Current-Limit and Leading-Edge Blanking Configuration

```
/* PWM Fault, Current-Limit and Leading-Edge Blanking Configuration */
FCLCON1bits.IFLTMOD = 0;
                         /* CLDAT bits control PWMxH and FLTDAT bits control PWMxL */
                          /* Current-limit input source is Analog Comparator 1 */
FCLCON1bits.CLSRC = 8;
FCLCON1bits.FLTSRC = 9; /* Fault input source is Analog Comparator 2 */
FCLCON1bits.CLPOL = 1; /* Current-limit source is active-low */
FCLCON1bits.FLTPOL = 1; /* Fault Input source is active-low */
FCLCON1bits.CLMOD = 1;
                          /* Enable current-limit function */
FCLCON1bits.FLTMOD = 1; /* Enable Cycle-by-Cycle Fault mode */
IOCON1bits.FLTDAT = 0;
                          /* PWMxH and PWMxL are driven inactive on occurrence of fault */
IOCON1bits.CLDAT = 0;
                          /* PWMxH and PWMxL are driven inactive on occurrence of current-limit */
LEBCON1bits.PHR = 1;
                        /* Rising edge of PWMxH will trigger LEB counter */
LEBCON1bits.PHF = 0;
                        /* Falling edge of PWMxH is ignored by LEB counter */
LEBCON1bits.PLR = 1;  /* Rising edge of PWMxL will trigger LEB counter */
LEBCON1bits.PLF = 0;  /* Falling edge of PWMxL is ignored by LEB counter */
LEBCON1bits.FLTLEBEN = 1; /* Enable fault LEB for selected source */
LEBCON1bits.CLLEBEN = 1; /* Enable current-limit LEB for selected source */
                          /* Blank for a period (8 x Tosc) */
LEBDLY1bits.LEB = 8;
PWMCON1bits.XPRES = 0; /* External pins do not affect PWM time base reset */
PWMCON1bits.FLTIEN = 1; /* Enable fault interrupt */
PWMCON1bits.CLIEN = 1;  /* Enable current-limit interrupt */
while (PWMCON1bits.FLTSTAT == 1); /* Wait when fault interrupt is pending */
while (PWMCON1bits.CLSTAT == 1);
                                      /* Wait when current-limit interrupt is pending */
```

14.11 SPECIAL FEATURES

The following special features are available in the High-Speed PWM module:

- Leading-Edge Blanking (LEB)
- State Blanking
- Chop mode
- Individual time base capture
- PWM pin swapping
- · PWM output pin control and override
- PWM immediate update

14.11.1 Leading-Edge Blanking (LEB)

Each PWM generator supports LEB of the current-limit and fault inputs configured using the LEBCONx and LEBDLYx bits in the Leading-Edge Blanking Control registers. The purpose of LEB is to mask the transients that occur on the application printed circuit board when the power transistors are turned ON and OFF.

The LEB bits are edge-sensitive. These bits support the blanking (ignoring) of the current-limit and fault inputs for a period of 0 to (4095 * Tosc) following any specified rising or falling edge of the PWMxH and PWMxL signals.

Equation 14-7: Leading-Edge Blanking Calculation

*LEB Duration at Maximum Clock Rate = (LEBDLYx<11:0>) * Tosc*

In high-speed switching applications, switches (such as MOSFETs and IGBTs) typically generate very large transients. These transients can cause measurement errors. The LEB function enables the user-assigned application to ignore the expected transients caused by the MOSFETs/IGBTs switching that occurs near the edges of the PWM output signals.

The PHR, PHF, PLR and PLF bits of the LEBCONx register select the edge type of the PWMxH and PWMxL signals, which starts the blanking timer. If a new selected edge triggers the LEB timer while the timer is still active from a previously selected PWM edge, the timer reinitializes and continues counting.

The FLTLEBEN and CLLEBEN bits enable the application of the blanking period to the selected fault and current-limit inputs. Figure 14-76 illustrates how an application ignores the fault signal in the specified blanking period.

Figure 14-76: Leading-Edge Blanking



© 2010-2011 Microchip Technology Inc.

14.11.2 State Blanking

Each PWM generator supports state blanking where it is possible to specify conditions where the current-limit and/or Fault signal is entirely ignored. The BCH, BCL, BPHH, BPHL, BPLH, and BPLL bits in the LEBCONx registers select any combination of the PWMxH, PWMxL, and CHOP clock signals as the source of the state blanking function.

The selected Fault or current-limit signal can be ignored when either the PWMxH or PWMxL output is high or low. In addition, the BLANKSEL<3:0> bits (AUXCONx<11:9>) can be used to select another PWM generator as the blanking signal source.





14.11.3 Chop Mode

Many power control applications use transistor configurations that require an isolated transistor gate drive. An example is a three-phase "H-bridge" configuration, where the upper transistors are at an elevated electrical potential.

One method to achieve an isolated gate drive circuit is to use pulse transformers to couple the PWM signals across a galvanic isolation barrier to the transistors. Unfortunately, in applications that use either long duty cycle ratios, or slow PWM frequencies, the transformer's low-frequency response is poor. The pulse transformer cannot pass a long duration PWM signal to the isolated transistor(s). If the PWM signals are "chopped" or gated by a high-frequency clock signal, the high-frequency alternating signal easily passes through the pulse transformer. The chopping frequency is typically hundreds or thousands of times higher in frequency as compared to the PWM frequency. The higher the chopping (carrier) frequency relative to the PWM frequency, the more the PWM duty cycle resolution is preserved.

Figure 14-78 shows an example waveform of high-speed PWM chopping. In this example, a 20 kHz PWM signal is chopped with a 500 kHz carrier generated by the chop clock.



Figure 14-78: High-Frequency PWM Chopping

The chopping function performs a logical AND operation of the PWM outputs. Because of the finite period of the chopping clock, the resultant PWM duty cycle resolution is limited to one half of the chop clock period.

The CHOP register enables the user to specify a chopping clock frequency. The CHOP value specifies a PWM clock divide ratio. The chop clock divider operates at the PWM clock frequency specified by the PWM Clock Divider Select bits, PCLKDIV<2:0> (PTCON2<2:0>). The CHPCLKEN bit (CHOP<15>) enables the chop clock generator.

The CHOPHEN and CHOPLEN bits in the AUXCONx register enable the chop clock to be applied to the PWM outputs. The CHOPSEL<3:0> bits (AUXCONx<5:2>), select the desired source for the chop clock. The default selection is the chop clock generator controlled by the CHOP register. The CHOPSEL<3:0> bits enable the user to select other PWM generators as a chop clock source.

If the CHOPHEN or CHOPLEN bits are set in the AUXCONx register, the chopping function is applied to the PWM output signals after the current-limit and fault functions are applied to the PWM signal. The chop clock signal is available for output from the module for use as an output signal for the device.

Normally, the chopping clock frequency is higher than the PWM cycle frequency, but new applications can use chop clock frequencies that are much lower than the PWM cycle frequency. Figure 14-79 shows a low-frequency PWM chopping waveform. In this figure, another PWM generator operating at a lower frequency chops or "blanks" the PWM signal.

dsPIC33E/PIC24E Family Reference Manual



Figure 14-79: Low-Frequency PWM Chopping

14.11.4 Individual Time Base Capture

Each PWM generator has a PWMCAPx register that automatically captures the independent time base counter value when the rising edge of the current-limit signal is detected. This feature is active only after the application of the LEB function. The user-assigned application should read the register before the next PWM cycle causes the capture register to be updated again.

The Capture register is used in current mode control applications that use the analog comparators or external circuitry to terminate the PWM duty cycle or period. By reading the independent time base value at the current threshold, the user-assigned application can calculate the slope of the current rise in the inductor. The secondary independent time base does not have an associated Capture register.

14.11.5 PWM Pin Swapping

The SWAP bit (IOCONx<1>), if set to '1', enables the user-assigned application to connect the PWMxH signal to the PWMxL pin and the PWMxL signal to the PWMxH pin. If the SWAP bit is set to '0', the PWM signals are connected to their respective pins.

To perform the swapping function on the PWM cycle boundaries, the OSYNC bit (IOCONx<0>) must be set. If the user-assigned application changes the state of the SWAP bit (IOCONx<1>) when the module is operating and the OSYNC bit is clear, the SWAP function will attempt to execute in the middle of a PWM cycle and the operation will yield unpredictable results.

The SWAP function should be executed prior to the application of dead time. Dead time processing is required since execution of switch function may enable the transistors in the user-assigned application that are previously in disable state, possibly causing current shoot-through.

The SWAP feature is useful for the applications that support multiple switching topologies with a single application circuit board. It also enables the user-assigned application to change the transistor modulation scheme in response to changing conditions.

The SWAP function can be implemented by using either of the following methods:

- **Dynamic Swapping:** In the dynamic swapping, the state of the SWAP bit can be changed dynamically based on the system response (e.g., Switch Mode Power Supply (SMPS) Power Control)
- **Static Swapping:** In static swapping, the SWAP bit is set during the start-up configuration and remains unchanged during the program execution or on-the-fly (e.g., Motor Control)
14.11.5.1 EXAMPLE 1: PIN SWAPPING WITH SMPS POWER CONTROL

The SMPS Power Control example describes dynamic swapping. In power conversion/motor control application, the transistor modulation technique can be changed between the full-bridge Zero Voltage Transition (ZVT) and standard full-bridge "on-the-fly" transition to meet different load and efficiency requirements. As shown in Figure 14-80, the generic full-bridge converter can operate in Push-Pull mode. The transistors are configured as follows:

- Q1 = Q4
- Q2 = Q3

The generic full-bridge converter can also operate in a ZVT mode. The transistors are configured as follows:

- Q1 = PWM1H
- Q2 = PWM1L
- Q3 = PWM2H
- Q4 = PWM2L

Figure 14-80: SMPS Power Control



14.11.5.2 EXAMPLE 2: PIN SWAPPING WITH MOTOR CONTROL

The Motor Control example describes static swapping. Consider a generic motor control system, which is capable of driving two different types of motors, such as DC motors and three-phase AC induction motors.

Brushed DC motors typically use a full-bridge transistor configuration, as shown in Figure 14-81. The Q1 and Q4 transistors are driven with similar waveforms, while the Q2 and Q3 transistors are driven with the complementary waveforms. This is also known as "driving the diagonals". Note that the Q5 and Q6 transistors are not used in a brushed DC motor.

The transistors are configured as follows:

- Q1 = PWM1H
- Q2 = PWM1L
- Q3 = PWM2L
- Q4 = PWM2H

Figure 14-81: Motor Control



When compared to the DC motor, an AC induction motor uses all the transistors in the full-bridge configuration. However, the significant difference is that the transistors are now driven as three half-bridges where the upper transistors are driven by the PWMxH outputs and the lower transistors are driven by PWMxL outputs.

The transistors are configured as follows:

- Q1 = PWM1H
- Q2 = PWM1L
- Q3 = PWM2H (note the difference with DC motors)
- Q4 = PWM2L (note the difference with DC motors)
- Q5 = PWM3H
- Q6 = PWM3L

Example 14-49: PWM Pin Swapping

14.12 PWM OUTPUT PIN CONTROL

If the High-Speed PWM module is enabled, the priority of PWMxH/PWMxL pin ownership from lowest to highest priority is as follows:

- PWM generator (lowest priority)
- · Swap function
- · PWM output override logic
- · Current-limit override logic
- Fault override logic
- PTEN (GPIO/PWM) ownership (highest priority)

If the High-Speed PWM module is disabled, the GPIO module controls the PWMx pins.

Example 14-50: PWM Output Pin Assignment

```
/* PWM Output pin control assigned to PWM generator */
IOCON1bits.PENH = 1;
IOCON1bits.PENL = 1;
```

Example 14-51: PWM Output Pins State Selection

```
/* High and Low switches set to active-high state */
IOCON1bits.POLH = 0;
IOCON1bits.POLL = 0;
```

Example 14-52: Enabling the High-Speed PWM Module

```
/* Enable High-Speed PWM module */
```

```
PTCONbits.PTEN = 1;
```

14.12.1 PWM Output Override Logic

The PWM output override feature is used to drive the individual PWM outputs to a desired state based on system requirements. The output can be driven to both the active state as well as the inactive state. The High-Speed PWM module override feature has the priority as assigned in the list above. All control bits associated with the PWM output override function are contained in the IOCONx register. If the bits, PENH (IOCONx<15>) and PENL (IOCONx<14>) are set, the High-Speed PWM module controls the PWMx output pins. The PWM Output Override bits allow the user-assigned application to manually drive the PWM I/O pins to specified logic states, independent of the duty cycle comparison units.

The OVRDAT<1:0> bits (IOCONx<7:6>), determine the state of the PWM I/O pins when a particular output is overridden by the bits, OVRENH (IOCONx<9>) and OVRENL (IOCONx<8>).

The OVRENH and OVRENL bits are active-high control bits. When these bits are set, the corresponding OVRDAT bit overrides the PWM output from the PWM generator.

When the PWM is in Complementary PWM Output mode, the dead time generator is still active with overrides. The output overrides and fault overrides generate control signals used by the dead time unit to set the outputs as requested. Dead time insertion can be performed when the PWM channels are overridden manually.

14.12.2 Override Priority

When the PENH and PENL bits are set, the following priorities apply to the PWM output:

- 1. If a fault is active, the Fault Override Data bits (FLTDAT<1:0>) override all other potential sources and set the PWM outputs.
- If a fault is not active, but a current-limit event is active, the CLDAT<1:0> bits (IOCONx<3:2>) are selected as the source to set the PWM outputs.
- If neither a fault nor a current-limit event is active, and a user Override Enable bit is set to OVRENH, OVRENL, the associated OVRDAT<1:0> (IOCONx<7:6>) register bits set the PWM output.
- 4. If no override conditions are active, the PWM signals generated by the time base and duty cycle comparator logic are the sources that set the PWM outputs.

14.12.3 Override Synchronization

If the OSYNC bit in the PWM I/O Control register (IOCONx<0>) is set, the output overrides performed by the OVRENH (IOCONx<9>), OVRENL (IOCONx<8>) and OVRDAT<1:0> (IOCONx<7:6>) bits are synchronized to the PWM time base. Synchronous output overrides occur when the time base is zero. If PTEN = 0, meaning the PWM timer is not running, writes to IOCONx take effect on the next TCY boundary.

14.12.4 Fault/Current-Limit Override and Dead Time Logic

In the event of a Fault and Current-Limit condition, the data in the FLTDAT<1:0> bits (IOCONx<5:4>) or CLDAT<1:0> bits (IOCONx<3:2>) determine the state of the PWM I/O pins.

If any of the FLTDAT<1:0> bits (IOCONx<5:4>) or CLDAT<1:0> bits (IOCONx<3:2>) are '0', the PWMxH and/or PWMxL outputs are driven inactive immediately, bypassing the dead time logic. This behavior turns off the PWM outputs immediately without any additional delays. This may aid many power conversion/motor control applications that require a fast response to fault shutdown signals to limit circuitry damage and control system accuracy.

If any of the FLTDAT<1:0> bits (IOCONx<5:4>) or CLDAT<1:0> bits (IOCONx<3:2>) are '1', the PWMxH and/or PWMxL outputs are driven active immediately passing through the dead time logic and, therefore, will be delayed by the specified dead time value. In this case, dead time will be inserted even if a Fault or Current-Limit condition occurs.

14.12.5 Asserting Outputs Via Current-Limit

In response to a current-limit event, the CLDAT bits (IOCONx<3:2>) can be used to assert the PWMxH and PWMxL outputs. Such behavior could be used as a current force feature in response to an external current or voltage measurement that indicates a sudden sharp increase in the load on the power-converter output. Forcing the PWM to an ON state can be considered a feed-forward action that allows quick system response to unexpected load increases without waiting for the digital control loop to respond.

Note: In Complementary PWM Output mode, the dead time generator remains active under override condition. The output overrides and fault overrides generate control signals used by the dead time unit to set the outputs as requested, including dead time. Dead time insertion can be performed when the PWM channels are overridden manually.

14.12.6 PENx (GPIO/PWM) Ownership

Most of the PWM output pins are normally multiplexed with other GPIO pins. When the Debugger halts the device, the PWM pins will take the GPIO characteristics that is multiplexed on that pin. For example, if the PWM1L and PWM1H pins are multiplexed with RE0 and RE1, the configuration of GPIO pins will decide the PWM output status when halted by the Debugger.

Example 14-53: Code Example

```
/* PWM output will be pulled to low when the device is halted by the
    debugger */
TRISE = 0x0000; RE0 and RE1 configured for an output
LATE = 0x0000; RE0 and RE1 configured as Low output
/* PWM output will be pulled to high when the device is halted by the
    debugger */
TRISE = 0x0000; RE0 and RE1 configured for an output
LATE = 0x0003; RE0 and RE1 configured as High output
/* PWM output will be in tri-state when the device is halted by the
    debugger */
TRISE = 0x0003; RE0 and RE1 configured for an input
```

14.13 IMMEDIATE UPDATE OF PWM DUTY CYCLE

The high performance PWM control-loop application requires a maximum duty cycle update rate. Setting the Immediate Update Enable bit (IUE) in the PWM Control registers (PWMCONx<0>) enables this feature. In a closed-loop control application, any delay between the sensing of a system state and the subsequent output of PWM control signals that drive the application reduces the loop stability. Setting the IUE bit minimizes the delay between writing the duty cycle registers and the response of the PWM generators to that change.

The IUE bit enables the user-assigned application to update the duty cycle values immediately after writing to the duty cycle registers, rather than waiting until the end of the time base period. If the IUE bit is set, an immediate update of the duty cycle is enabled. If the bit is cleared, immediate update of the duty cycle is disabled. The following three cases are possible when immediate update is enabled:

- **Case 1:** If the PWM output is active at the time the new duty cycle is written and the new duty cycle is greater than the current time base value, the PWM pulse-width is lengthened
- Case 2: If the PWM output is active at the time the new duty cycle value is written and the new duty cycle is less than the current time base value, the PWM pulse-width is shortened
- **Case 3:** If the PWM output is inactive when the new duty cycle value is written and the new duty cycle is greater than the current time base value, the PWM output becomes active immediately and remains active for the newly written duty cycle value. As seen in Figure 14-82, in this case, the dead time will not be incorporated into the first edge of the active PWM period.





Example 14-54: Immediate Update Selection

/* Enable Immediate	Jpdate of PWM */									
PTCONbits.EIPU = 1;	/* Update active period register immediately									
<pre>PWMCON1bits.IUE = 1;</pre>	/* Update active duty cycle, phase offset and									
	independent time period immediately */									

14.14 POWER-SAVING MODES

This section discusses the operation of the High-Speed PWM module in Sleep mode and Idle mode.

14.14.1 High-Speed PWM Operation in Sleep Mode

When the device enters Sleep mode, the system clock is disabled. Since the clock for the PWM time base is derived from the system clock source (Tosc), that clock will also be disabled and all enabled PWM output pins that were in effect prior to entering Sleep mode will be frozen in the output states. If the High-Speed PWM module is used to control a load in a power application, the High-Speed PWM module outputs must be placed into a safe state before executing the PWRSAV instruction. Depending on the application, the load may begin to consume excessive current when the PWM outputs are frozen in a particular output state. In such a case, the override functionality can be used to drive the PWM output pins into the inactive state.

If the fault inputs are configured for the High-Speed PWM module, the fault input pins continue to function normally when the device is in Sleep mode. If one of the fault pins is driven low while the device is in Sleep mode, the PWM outputs are driven to the programmed fault states. The fault input pins can also wake the CPU from Sleep mode. If the fault pin interrupt priority is greater than the current CPU priority, program execution starts at the fault pin interrupt vector location upon wake-up. Otherwise, execution continues from the next instruction following the PWRSAV instruction.

14.14.2 High-Speed PWM Operation in Idle Mode

The PWM module has a PTSIDL control bit in the PTCON register. This bit determines if the PWM module will continue to operate or stop when the device enters Idle mode. If PTSIDL = 0, the module will continue to operate as normal. If PTSIDL = 1, the module will shut down and stop its internal clocks. The system will not be able to access the special function registers in this mode. This will be the minimum power mode for the module. Stopped Idle mode functions like Sleep mode and fault pins will be asynchronously active. The control of the PWM pins will revert back to the GPIO bits associated with the PWM pins if the PWM module enters an Idle state.

It is recommended that the user-assigned application disable the PWM outputs prior to entering Idle mode. If the PWM module is controlling a power conversion/motor control application, the action of putting the device into Idle mode will cause any control loops to be disabled, and most applications will likely experience issues unless they are explicitly designed to operate in an open loop mode.

Note: For more details on power-saving modes, refer to Section 9. "Watchdog Timer (WDT) and Power-Saving Modes" (DS70615).

14.15 EXTERNAL CONTROL OF INDIVIDUAL TIME BASE(S)

External signals can reset the primary dedicated time bases, if the XPRES bit (PWMCONx<1>) is set. This mode of operation is called Current Reset PWM mode. If the user-assigned application sets the ITB bit, a PWM generator operates in Independent Time Base mode. If the user-assigned application sets the XPRES bit and operates the PWM generator in Master Time Base mode, the results may be unpredictable.

The current-limit source signal specified by the CLSRC<4:0> bits (FCLCONx<14:10>) causes the independent time base to reset. The active edge of the selected current-limit signal is specified by the CLPOL bit (FCLCONx<9>).

In Primary Independent Time Base mode, some Power Factor Correction (PFC) applications need to maintain the inductor current value above minimum desired current level. These applications use the external Reset feature. If the inductor current falls below the desired value, the PWM cycle is terminated early so that the PWM output can be asserted to increase the inductor current. The PWM period varies according to the application needs. This type of application is a variable frequency PWM mode.

14.16 APPLICATION INFORMATION

Typical applications that use different PWM operating modes and features are:

- Complementary Output Mode
- Push-Pull Output Mode
- Multi-Phase PWM
- Variable Phase PWM
- Current Reset PWM
- Constant Off-Time PWM
- Current-Limit PWM

Each application is described in the following sections.

14.16.1 Complementary Output Mode

The Complementary PWM mode shown in Figure 14-83 is generated in a manner that is similar to Standard Edge-Aligned mode. This mode provides a second PWM output signal on the PWMxL pin that is the complement of the primary PWM signal (PWMxH).

Figure 14-83: Complementary PWM Output Mode for SMPS





Figure 14-84: Complementary PWM Output Mode for Motor Control

14.16.2 Push-Pull Output Mode

The Push-Pull PWM mode, shown in Figure 14-85, alternately outputs the PWM signal on one of two PWM pins. In this mode, complementary PWM output is not available. This mode is useful in transformer-based power converter circuits that avoid flow of direct current that saturates their cores. The Push-Pull mode ensures that the duty cycle of the two phases is identical, thereby yielding a net DC bias of zero.



Figure 14-85: Push-Pull PWM Output Mode

14

14.16.3 Multi-Phase PWM

The Multi-Phase PWM, shown in Figure 14-86, uses phase shift values in the PHASEx registers to shift the PWM outputs with respect to the primary time base. Because the phase shift values are added to the primary time base, the phase shifted outputs occur earlier than a PWM signal that specifies zero phase shifts. In Multi-Phase mode, the specified phase shift is fixed by the application's design. Phase shift is available in all PWM modes that use the master time base.

Multi-phase PWM is often used in DC-to-DC converters that handle fast load current transients, and need to meet smaller space requirements. A multi-phase converter is essentially a parallel array of buck converters that are operated slightly out of phase with each other. The multiple phases create an effective switching speed equal to the sum of the individual converters.

If a single phase is operating at a PWM frequency of 333 kHz, the effective switching frequency for the circuit, shown in Figure 14-87, is 1 MHz. This high switching frequency greatly reduces input and output capacitor size requirements. It also improves load transient response and ripple figures.



Figure 14-86: Multi-Phase PWM

14.16.3.1 INTERLEAVED POWER FACTOR CORRECTION (IPFC)

The interleaving of multiple boost converters in PFC circuits is becoming popular in the recent applications. Figure 14-87 and Figure 14-88 illustrate the typical interleaved PFC circuit configuration and the interleaved PFC operational waveforms, respectively.

By staggering the channels at uniform intervals, multichannel interleaved PFC can reduce the input current ripple significantly due to the ripple cancellation effect. The smaller input current ripple indicates the low Differential Mode (DM) noise filter. It is generally believed that the reduced Differential mode noise magnitude makes the Differential mode filter smaller. The output capacitor voltage ripples are also reduced significantly as a function of the duty cycle.





Figure 14-88: Interleaved PFC Operational Waveforms













14.16.4 Variable Phase PWM

The Variable Phase PWM shown in Figure 14-91, constantly changes the phase shift among PWM channels to control the flow of power, which is in contrast with most PWM circuits that vary the duty cycle of PWM signal to control power flow. In variable phase applications, the PWM duty cycle is often maintained at 50 percent. The phase shift value is available to all PWM modes that use the master time base.

The variable phase PWM is used in newer power conversion/motor control topologies that are designed to reduce switching losses. In the standard PWM methods, when a transistor switches between the conducting state and the non-conducting state (and vice versa), the transistor is exposed to the full current and voltage condition during the time when the transistor turns ON or OFF and the power loss (V * I * Tsw * FPWM) becomes appreciable at high frequencies.

The Zero Voltage Switching (ZVS) and Zero Current Switching (ZVC) circuit topologies attempt to use quasi-resonant techniques that shift either the voltage or the current waveforms relative to each other to change the value of voltage or the current to zero when the transistor turns ON or OFF. If either the current or the voltage is zero, no switching loss occurs.



Figure 14-91: Variable Phase PWM

14.16.5 Current Reset PWM

The Current Reset PWM shown in Figure 14-92 is a variable frequency mode, where the actual PWM period is less than or equal to the specified period value. The independent time base is reset externally after the PWM signal has been deasserted. The Current Reset PWM mode can be used in Constant PWM On-Time mode. To operate in PWM Current Reset, the PWM generator should be in Independent Time Base. If an external Reset signal is not received, the PWM period uses the PHASEx register value by default.

Note: In Current Reset mode, the local time base resetting is based on the leading edge of the current-limit input signal after completion of the PWMxH/L duty cycle.

In Current Reset mode, the PWM frequency varies with the load current. This is different from most PWM modes because the user-assigned application sets the maximum PWM period and an external circuit measures the inductor current. When the inductor current falls below a specified value, the external current comparator circuit generates a signal that resets the PWM time base counter. The user-assigned application specifies a PWM ON time, and then some time after the PWM signal becomes inactive, the inductor current falls below a specified value and the PWM counter is reset earlier than the programmed PWM period. This is called Constant On-Time Variable Frequency PWM output and is used in Critical Conduction mode PFC applications.

This should not be confused with the cycle-by-cycle current-limiting PWM output, where the PWM output is asserted, an external circuit generates a current fault, and the PWM signal is turned off before its programmed duty cycle would normally turn it off. Here, the PWM frequency is fixed for a given time base period.

The advantages of Current Reset PWM mode in PFC applications are as follows:

- As the PFC boost inductor does not require to store energy at the end of each switching cycle, a smaller inductor can be used. The usage of the smaller inductor leads to reduced cost.
- Commutation of Boost diode from ON to OFF happens at zero current. The slower diodes can be used to reduce the cost.
- · Inner current feedback loop is much faster, as the feedback is received for every cycle

Figure 14-92: Current Reset PWM





14.16.6 Constant Off-Time PWM

Constant Off-Time PWM, shown in Figure 14-93, is a variable-frequency PWM output where the actual PWM period is less than or equal to the specified period value. The PWM time base resets externally after the PWM signal duty cycle value has been reached and the PWM signal has been deasserted. This is implemented by enabling the On-Time PWM output called Current Reset PWM and using the complementary PWM output (PWMxL).

The Constant Off-Time PWM can be enabled only when the PWM generator operates in independent time base. If an external Reset signal is not received, by default, the PWM period uses the value specified in PHASEx register.





14.16.7 Current-Limit PWM

The cycle-by-cycle current-limit shown in Figure 14-94, truncates the asserted PWM signal when the selected external fault signal is asserted. The PWM output values are specified by the CLDAT<1:0> bits (IOCONx<3:2>). The override outputs remain in effect until the beginning of the next PWM cycle. This is sometimes used in the Power Factor Correction (PFC) circuits, where the inductor current controls the PWM On-Time. This is a constant frequency PWM.





14.16.8 Discontinuous or Burst Mode Implementation

In applications where the load current drawn from the converter is much smaller than its nominal current/converter operating at no load, the power drawn from the source can be reduced by forcing the converter to deassert the PWM output by using manual override. Typically, the converter PWM output can be turned off over a period of time based on the output voltage regulation, which can reduce the no load power requirements significantly.

Table 14-7 maps the bit functions for the High-Speed PWM control registers.

Table 14-6: High-Speed PWM Register Map

	-	<u> </u>	-															
File Name	Bit 15	Bit 14	Bit 13	Bit 12	Bit 11	Bit 10	Bit 9	Bit 8	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0	All Resets	
PTCON	PTEN	_	PTSIDL	SESTAT	SEIEN	EIPU	SYNCPOL	SYNCOEN	SYNCEN	S`	SYNCSRC<2:0> SEVTPS<3:0>							
PTCON2	-	—	—		_		—	—	—		—	—	- PCLKDIV<2:0>					
PTPER	PTPER<15:0>															FFF8		
STCON	_	—	—	SESTAT	SEIEN	EIPU	SYNCPOL	SYNCOEN	SYNCEN	EN SYNCSRC<2:0> SEVTPS<3:0>							0000	
STCON2	_	—	—	_	-	_	—	—	_		— — — PCLKDIV<2:0>							
STPER	STPER<15:0>															FFF8		
MDC	MDC<15:0>															0000		
SEVTCMP	SEVTCMP<15:0>														0000			
SSEVTCMP	SSEVTCMP<15:0>														0000			
CHOP	CHPCLKEN	—	_		_						CHOPC	LK<9:0>					0000	
PWMKEY								PWMKEY	/<15:0>								0000	
PWMCONx	FLTSTAT	CLSTAT	TRGSTAT	FLTIEN	CLIEN	TRGIEN	ITB	MDCS	DTC	<1:0>	DTCP	—	MTBS	CAM	XPRES	IUE	0000	
IOCONx	PENH	PENL	POLH	POLL	PMOD	<1:0>	OVRENH	OVRENL	OVRDAT<1:0>		FLTDAT<1:0>		CLDAT<1:0>		SWAP	OSYNC	0000	
FCLCONx	IFLTMOD		CLSRC<4:0> CLPOL CLMOD FLTSRC<4:0> FLTPOL FLTMOD<1:0										D<1:0>	0000				
PDCx	PDCx<15:0>														0000			
PHASEx	PHASEx<15:0>														0000			
SDCx	SDCx<15:0>														0000			
SPHASEx	SPHASEx<15:0>														0000			
DTRx	— — DTRx<13:0>														0000			
ALTDTRx	_	—							ALTDTR	x<13:0>							0000	
TRIGx		TRGCMP<15:0> 0														0000		
TRGCONx		TRGDI	DIV<3:0> TRGSTRT<5:0>										0000					
LEBCONx	PHR	PHF	PLR	PLF	FLTLEBEN	CLLEBEN	_	_	_	_	BCH	BCL	BPHH	BPHL	BPLH	BPLL	0000	
LEBDLYx	_	_	_	_	LEB<11:0> 0										0000			
PWMCAPx					•			PWMCAP	1<15:0>								0000	
AUXCONx	—	—	_	—	BLANKSEL<3:0> — — CHOPSEL<3:0> CHOPHE						CHOPHEN	CHOPLEN	0000					

Legend: x = unknown value on Reset, — = unimplemented, read as '0'. Reset values are shown in hexadecimal.

Note 1: Not all bits are available for all devices. Please refer to the "High-Speed PWM" chapter in the specific data sheet for details.

14.18 RELATED APPLICATION NOTES

This section lists application notes that are related to this section of the manual. These application notes may not be written specifically for the dsPIC33E/PIC24E product family, but the concepts are pertinent and could be used with modification and possible limitations. The current application notes related to the High-Speed PWM module are:

Title

Application Note

N/A

No related application notes are available at this time.

Note: Please visit the Microchip web site (www.microchip.com) for additional Application Notes and code examples for the dsPIC33E/PIC24E family of devices.

14.19 REVISION HISTORY

Revision A (September 2010)

This is the initial released revision of this document.

Revision B (June 2011)

This revision includes the following updates:

- Added the PWMKEY register description to 14.3 "Control Registers"
- Added the PWMKEY: PWM Unlock register (see Register 14-11)
- Added 14.5.3 "Write Protection", which provides information on the write protection feature for the IOCONx and FCLCONx registers
- Added 14.10.1 "Class B Fault", which describes the fault implemented for Class B safety features
- Added the PWMKEY register to the High-Speed PWM register map (see Table 14-7)
- · Changes to formatting and minor text updates have been incorporated throughout the document

Revision C (December 2011)

This revision includes the following updates:

- · Notes have been added throughout the document regarding feature availability
- All occurrences of PCLKSEL<2:0> were changed to: PCLKDIV<2:0>
- All occurrences of SYNCI1 and SYNCI2 were updated to: SYNCIx
- · All occurrences of SYNCO were updated to: SYNCOx
- Updated 14.1 "Introduction" to include the types of AC and DC motors supported
- · Updated frequency resolution in 14.2 "Features"
- Updated the bit value definitions for CLSRC<4:0> and FLTSRC<4:0> in FCLCONx: PWM Fault Current-Limit Control Register (see Register 14-14)
- Updated the bit value definitions for TRGDIV<3:0> in TRGCONx: PWM Trigger Control Register (Register 14-22)
- Updated the bit value definitions for BLANKSEL<3:0> and CHOPSEL<3:0> in AUXCONx: PWM Auxiliary Control Register (see Register 14-26)
- Updated the High-Speed PWM Module Architectural Overview diagram (see Figure 14-1)
- Updated the High-Speed PWM Module Interconnection Diagram (see Figure 14-2)
- Updated the operation specifications in 14.5.1 "PWM Clock Selection"
- Updated Note 1 in 14.5.7 "Time Base Synchronization"
- Added Note 2 in 14.6.4 "True Independent PWM Output Mode"
- Updated the first paragraph in 14.7.2.4 "Duty Cycle Resolution"
- Removed Equation 14-4
- Updated the Maximum PWM Frequency with Fosc = 120 MHz and 1:1 Clock Input values (see Table 14-4)
- Added 14.11.2 "State Blanking"
- · Updated the dead time resolution and values in 14.7.5 "Dead Time Ranges"
- Added a note to 14.9 "PWM Interrupts"
- Updated the PWM Fault Control Module Block Diagram (see Figure 14-74)
- Updated the PWM Current-Limit Control Circuit Logic Diagram (see Figure 14-75)
- Updated the Duty Cycle Update Times When Immediate Updates are Enabled diagram (see Figure 14-82)
- · Minor updates to formatting and text have been incorporated throughout the document

Note the following details of the code protection feature on Microchip devices:

- · Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

QUALITY MANAGEMENT SYSTEM CERTIFIED BY DNV ISO/TS 16949:2009

Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC³² logo, rfPIC and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniscient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICtail, REAL ICE, rfLAB, Select Mode, Total Endurance, TSHARC, UniWinDriver, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2010-2011, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.



ISBN: 978-1-61341-906-9

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and mulfacture of development systems is ISO 9001:2000 certified.



Worldwide Sales and Service

AMERICAS

Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support: http://www.microchip.com/ support

Web Address: www.microchip.com

Atlanta Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455

Boston Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088

Chicago Itasca, IL Tel: 630-285-0071 Fax: 630-285-0075

Cleveland Independence, OH Tel: 216-447-0464 Fax: 216-447-0643

Dallas Addison, TX Tel: 972-818-7423 Fax: 972-818-2924

Detroit Farmington Hills, MI Tel: 248-538-2250 Fax: 248-538-2260

Indianapolis Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453

Los Angeles Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608

Santa Clara Santa Clara, CA Tel: 408-961-6444 Fax: 408-961-6445

Toronto Mississauga, Ontario, Canada Tel: 905-673-0699 Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office Suites 3707-14, 37th Floor Tower 6, The Gateway Harbour City, Kowloon Hong Kong Tel: 852-2401-1200 Fax: 852-2401-3431 Australia - Sydney

Tel: 61-2-9868-6733 Fax: 61-2-9868-6755

China - Beijing Tel: 86-10-8569-7000 Fax: 86-10-8528-2104

China - Chengdu Tel: 86-28-8665-5511 Fax: 86-28-8665-7889

China - Chongqing Tel: 86-23-8980-9588 Fax: 86-23-8980-9500

China - Hangzhou Tel: 86-571-2819-3187 Fax: 86-571-2819-3189

China - Hong Kong SAR Tel: 852-2401-1200 Fax: 852-2401-3431

China - Nanjing Tel: 86-25-8473-2460 Fax: 86-25-8473-2470

China - Qingdao Tel: 86-532-8502-7355 Fax: 86-532-8502-7205

China - Shanghai Tel: 86-21-5407-5533 Fax: 86-21-5407-5066

China - Shenyang Tel: 86-24-2334-2829 Fax: 86-24-2334-2393

China - Shenzhen Tel: 86-755-8203-2660 Fax: 86-755-8203-1760

China - Wuhan Tel: 86-27-5980-5300 Fax: 86-27-5980-5118

China - Xian Tel: 86-29-8833-7252 Fax: 86-29-8833-7256

China - Xiamen Tel: 86-592-2388138 Fax: 86-592-2388130

China - Zhuhai Tel: 86-756-3210040 Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore Tel: 91-80-3090-4444 Fax: 91-80-3090-4123

India - New Delhi Tel: 91-11-4160-8631 Fax: 91-11-4160-8632

India - Pune Tel: 91-20-2566-1512 Fax: 91-20-2566-1513

Japan - Osaka Tel: 81-66-152-7160 Fax: 81-66-152-9310

Japan - Yokohama Tel: 81-45-471- 6166 Fax: 81-45-471-6122

Korea - Daegu Tel: 82-53-744-4301 Fax: 82-53-744-4302

Korea - Seoul Tel: 82-2-554-7200 Fax: 82-2-558-5932 or 82-2-558-5934

Malaysia - Kuala Lumpur Tel: 60-3-6201-9857 Fax: 60-3-6201-9859

Malaysia - Penang Tel: 60-4-227-8870 Fax: 60-4-227-4068

Philippines - Manila Tel: 63-2-634-9065 Fax: 63-2-634-9069

Singapore Tel: 65-6334-8870 Fax: 65-6334-8850

Taiwan - Hsin Chu Tel: 886-3-5778-366 Fax: 886-3-5770-955

Taiwan - Kaohsiung Tel: 886-7-536-4818 Fax: 886-7-330-9305

Taiwan - Taipei Tel: 886-2-2500-6610 Fax: 886-2-2508-0102

Thailand - Bangkok Tel: 66-2-694-1351 Fax: 66-2-694-1350

EUROPE

Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393 Denmark - Copenhagen Tel: 45-4450-2828 Fax: 45-4485-2829

France - Paris Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79

Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44

Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781

Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340

Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91

UK - Wokingham Tel: 44-118-921-5869 Fax: 44-118-921-5820

11/29/11