



Insert demo units as directed in merchandising plan.



Align slot on plug with pin in hole.



Ensure top of plug is flush with surface.

