

## TROUBLESHOOTING

Problem	Causes	Correction
Vehicle doesn't move	<ul style="list-style-type: none"> <li>Power switch is turned OFF.</li> <li>Vehicle is too far away from the transmitter.</li> <li>Check battery installation to ensure proper polarity.</li> </ul>	<ul style="list-style-type: none"> <li>Turn the power switch ON.</li> <li>Bring the vehicle closer to the transmitter.</li> <li>Re-install batteries with correct polarity.</li> </ul>
Loss of Control	<ul style="list-style-type: none"> <li>Another radio control vehicle using the same frequency is operated near your vehicle.</li> </ul>	<ul style="list-style-type: none"> <li>Race against other vehicles using a different frequency or channel.</li> </ul>
Vehicle drives slowly	<ul style="list-style-type: none"> <li>Weak charge in the vehicle.</li> </ul>	<ul style="list-style-type: none"> <li>Recharge the vehicle.</li> </ul>
Poor range control	<ul style="list-style-type: none"> <li>Weak battery in the transmitter.</li> <li>Strong interference in the surrounding area.</li> </ul>	<ul style="list-style-type: none"> <li>Replace with new batteries.</li> <li>Move vehicle away from other electronic devices.</li> </ul>

**WARNING: Modifications not approved by Excaltibur Electronics voids warranty.**

## FCC Compliance

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

**THIS PRODUCT IS FOR THE USE IN U.K., SPAIN, GERMANY, FRANCE, BELGIUM, ITALY, SWITZERLAND, THE NETHERLANDS, DENMARK, U.S., CANADA AND PORTUGAL.**

Made in China



**WARNING!**  
CHOKING HAZARD - Small parts.  
Not suitable for children under 3 years.

## Limited 90-Day Warranty

EXCALIBUR ELECTRONICS, INC., warrants to the original consumer that its products are free from any electrical or mechanical defects for a period of 90 DAYS from the date of purchase. If any such defect is discovered within the warranty period, EXCALIBUR ELECTRONICS, INC., will repair or replace the unit free of charge upon receipt of the unit, shipped postage prepaid and insured to the factory address below. The warranty covers normal consumer use and does not cover damage that occurs in shipment or failure that results from alterations, accident, misuse, abuse, neglect, wear and tear, inadequate maintenance, commercial use, or unreasonable use of the unit. Removal of the top panel voids all warranties. This warranty does not cover cost of repairs made or attempted outside of the factory. Any applicable implied warranties, including warranties of merchantability and fitness, are hereby limited to 90 DAYS from the date of purchase. Consequential or incidental damages resulting from a breach of any applicable express or implied warranties are hereby excluded. Some states do not allow limitations on the duration of implied warranties and do not allow exclusion of incidental or consequential damages, so the above limitations and exclusions in these instances may not apply. The only authorized service center in the United States is:

Excaltibur Electronics, Inc.  
13755 SW 119th Ave.  
Miami, FL 33186 U.S.A.


Ship the unit carefully packed, preferably in the original carton, and send it prepaid, and adequately insured. Include a letter detailing the complaint, along with your daytime telephone number, inside the shipping carton. If your warranty has expired and you want an estimated fee for service, write to the above address, specifying the model and the problem.

**PLEASE DO NOT SEND YOUR UNIT WITHOUT RECEIVING AN ESTIMATE FOR SERVICING. WE CANNOT STORE YOUR UNIT!**



**Excaltibur**  
ELECTRONICS, INC.

Excaltibur Electronics, Inc.  
13755 SW 119th Avenue • Miami, FL 33186  
Tel: 305.477.8980 • Fax: 305.477.3516 • www.ExcaltiburElectronics.com  
MIGRO MONSTERS is a trademark of Excaltibur Electronics, Inc.  
Actual product may differ slightly from photograph.



## INSTRUCTION MANUAL

Please read through this instruction manual carefully before starting to operate.  
Please ensure to remove all accessories and components from packaging.