

**Continental Automotive GmbH,**  
Siemensstraße 12,  
93055 Regensburg, Germany

**FCC ID:** KR5DWMI2017B

**Model:** D-WMI2017B

### **Compliance Statement in User Manual**

To whom it may concern

Our product with the above FCC ID are marketed together with cars, where it's operation is included in the individual owner's manual of the cars.

We hereby assure that the following caution statement as per CFR, §15.21 is included in a prominent location of the owner's manual of the cars:

The title **"CAUTION TO USERS"** or **"FCC WARING"**, **"NOTE"** or relevant title and **"Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment."**

And also

**"A separation distance of at least 10 cm between all persons and the device must be provided at all times. The Device must not be co-located or operating in conjunction with any other antenna or transmitter."**

In addition, we also assure that the following statement is also included in a prominent location in the manual as per CFR 47, §15.19(a)(3):

**This device complies with Part 15 of the FCC Rules.**

**Operation is subject to the following two conditions:**

- (1) This device may not cause harmful interference, and**
- (2) This device must accept any interference received, including interference that may cause undesired operation.**

If you have any questions, please feel free to contact me at the address shown below.

Yours sincerely,



---

By: Dagmar Kolar  
Title: RF Homologation  
Company: Continental Automotive GmbH  
Telephone: +49 941 790-6699  
e-mail: [Dagmar.Kolar@continental-corporation.com](mailto:Dagmar.Kolar@continental-corporation.com)