



Errata Sheet

This Errata Sheet contains corrections or changes made after the publication of this manual.

Product Family:	DL405	Date:	November 18, 2013
Manual Number	D4-HSC-M		
Revision and Date	Revision A, June 1998		

Changes to Chapter 7. Program Applications

Page 7-2. A Quick Checkout of the Module; Wiring Diagram for Example

The wiring diagram shows +24 VDC going to terminal INA-. This is incorrect; it should be -24 VDC.