

HARMAN/BECKER Automotive Systems GmbH · Söflinger Str. 100 · 89077 Ulm

Phone: +49 (0) 731-3994-136
Fax: +49 (0) 731-3994-61136
Email: HKlemm@harmanbecker.com

PHOENIX TEST-LAB GmbH
Product Certification
Königswinkel 10

32825 Blomberg

Ulm, 9 May 2008

FCC ID: T8G667XBT

To Whom It May Concern:

The FCC statements (§15.19 Labelling Requirements)

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation"

and (§15.21 Information to the User)

under relevant title **"CAUTION TO USERS"** or **"FCC WARNING"** or **"NOTE"**

"Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment"

will both be placed in a prominent location in the users manual for the North American Market.

If you have any questions, please feel free to contact me at the address shown below.

Thank you for your attention to this matter.

Yours sincerely,
Harman/Becker Automotive Systems GmbH


Ulm, 7 May 2008, Heinz Klemm


Werner Bollinger