

The list below shows all the service provider settings from **United Kingdom**. Please look for the correct **Service Provider Name**.

You can use these details to fill in the information into your Linksys ADSL Gateway.

**NOTE:** Examples on filling in the details, please click [here](#).

Network Setup (WAN)								
		Internet Connection Type	VC Settings					Optional Settings
Country	Service Provider Name	Encapsulation	Multiplexing (LLC or VC)	Autodetect	Virtual Circuit VPI	Virtual Circuit VCI	DSL Modulation	MTU
<b>EMEA</b>								
<b>United Kingdom</b>	<b>4D Internet</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
	<b>Alto Highway</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
	<b>AOL</b>	RFC 2516 PPPoE	LLC	Disable	0	38	Multimode	1400
	<b>AOL</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	1400
	<b>AAISP</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
	<b>Adept Telecom</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
	<b>ADSL24</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
	<b>Axis</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
	<b>BE</b>	RFC 1483 Bridged	LLC	Disable	0	101	Multimode	Auto
	<b>Boat Blue</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
	<b>Breathe</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
	<b>BT Broadband</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	1400
	<b>BT Click</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
	<b>BT Internet</b>	RFC 2364	VC	Disable	0	38	Multimode	Auto

		PPPoA						
<b>BT Openworld</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Bulldog</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Carphone Warehouse</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Clara.net</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Chess</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Daisy Broadband</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Demon</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>E7even</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Eclipse Internet</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Eircom</b>	RFC 2516 PPPoE	LLC	Disable	8	35	Multimode	Auto	
<b>Euro1net</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Eurotel</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Exa</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Excellent</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Exceltelecom</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>F2S</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Fast</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Fasthosts</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Firefly</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	

<b>Force9</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Fort Network System</b>	DHCP	-	-	-	-	-	-
<b>FreedomToSurf</b>	RFC 2364 PPPoA	VC	Disable	0	35 or 38	Multimode	Auto
<b>Free Online</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Freeola</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Freenet through BT</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Freenetname</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Frostbyte</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Global Network</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Green</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Greenbee</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Griffin</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Hebrides.net</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Home call</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Hostway ISP Broadband</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Hydrogene</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>IC24</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Idnet</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Jersey Telecom</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Karoo</b>	RFC 2364	LLC	Disable	0 or 1	50	Multimode	Auto

		PPPoA						
<b>Kingston</b>	RFC 2516 PPPoE	LLC	Disable	0 or 1	50	Multimode	Auto	
<b>KBnet</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Lixxus</b>	RFC 2364 PPPoA	VC	Disable	0	38	G.dmt	Auto	
<b>Local Dial</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Madasafish</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Mainstream Digital</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Manx Telecom</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Metro Net</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Mildram</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Milifax</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Namesco</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Newnet</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Nildram</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Northwest Electronic Wireless</b>	Static IP	-	-	-	-	-	-	
<b>NTL through BT</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>O2</b>	RFC 1483 Bridged	VC/LLC	Disable	0	100 or 101	Multimode	Auto	
<b>Onebill Telecom</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Onetel</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Opal</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	

<b>Orange</b>	RFC 2364 PPPoA	VC	Disable	0	38	G.dmt	Auto
<b>Pipex</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Phone Coop Broadband</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Plusnet</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Post Office</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Prodigynet</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Pro-Net</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Redstone</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Scotnet</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Sky</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Skymarket</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Supanet</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Sure</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Talktalk</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Telecomplete</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Telecomplus</b>	RFC 2516 PPPoE	VC	Disable	0	38	Multimode	Auto
<b>Tesco</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto
<b>Tiscali</b>	RFC 2364 PPPoA	VC	Disable	0	38	G.dmt	Auto
<b>Tiscali/Baby XL in Netherlands</b>	RFC 1483 Bridged	LLC	Disable	0	34	Multimode	Auto
<b>Toucan Surf</b>	RFC 2364	VC	Disable	0	38	Multimode	Auto

		PPPoA						
<b>UK Online</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>UTV Internet</b>	RFC 2364 PPPoA	VC	Disable	8	35	Multimode	Auto	
<b>Utilitywareh use</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>V21 ISP</b>	RFC 2364 PPPoA	VC	Disable	0	35 or 38	Multimode	Auto	
<b>Virgin ADSL</b>	RFC 2364 PPPoA	VC	Disable	8	35	Multimode	Auto	
<b>Vispa</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Vodafone</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Waitrose</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>XLN</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Yourcalls.net</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Zen</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Zen from BT</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Zetnet</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>ZX3</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	
<b>Default-Other</b>	RFC 2364 PPPoA	VC	Disable	0	38	Multimode	Auto	