

Electromagnetic Compatibility (EMC) Notices

For Europe: CE

This device fulfils the following requirements:

EN 55022:1998 Limit B

(Radiated emission), EN55024:1998 (Immunity of IT-equipment), EN

61000-3-2:95+A1+A2+Corrig.+A14 (Harmonic current emissions), EN

61000-3-3:95+A1 (Limitation of voltage fluctuations and flicker), EN

61000-6-2:1999 (Immunity for industrial environments), EN 300 330-2: v.1.1.1

(06-2001) (Radio - spectrum), EN 301 489-01: v.1.2.1 (07-2000) (Radio - EMC)

and EN 301 489-03 (07-2000) (Radio - EMC).

AM010020 R1A Dec. -01

User instructions Precise Miranda

DRAFT



Dag Hammarskjöldsväg 2, SE-224 64 Lund, Sweden.

Phone +46 46 311 100, Fax +46 46 311 101

info@precisebiometrics.com

www.precisebiometrics.com




1.



Connect the power to Precise Miranda.
Connect the serial cable to Precise Miranda and your computer.

2.



Place the card on top of Precise Miranda for best performance.

DRAFT