

## Function

### LED Indicator Light Instructions

Bluetooth Mode	Blue indicator light start flashes slowly when headset works while it remains solid when headset is off
Standby Mode	Blue indicator light remains light
Message State	Blue indicator light start flashes quickly
Lower Power State	Red indicator light start flashes quickly
Charging State	Power indicator light flashes slowly in charging state,white indicator light remains light when battery is full charged,when four indicator lights remain light when it is full charged



## Function

### Basic Keys Operation

#### Power On

Hold Press the **O/M** 3 seconds ,there will be the automatic voice prompt:Power on,the blue indicator light flashes 2 seconds,Power indicator light runs two times in the form of horse race lamp, display the current electric quantity,then goes out after 10 seconds

#### Power Off

Hold Press the **O/M** 3 seconds,there will be the automatic voice prompt:Power off,the red and blue indicator light flashes 2 seconds at the same time.

#### M Function button

Click once to display the battery power,will flash 10 seconds

#### Volume Control

Short press **W/+** and **W/-** ,change the volume of headset.

#### Play / Pause

Press the **W/↵** one time to play or pause the music.

Next Track : Hold press the **W/+** ,change to the next track.

Previous Track : Hold press the **W/-** ,back to the previous track.

Answering a Call : Short press on the **W/↵**

Ending a Call : Short press on the **W/↵** while in a call.

Rejecting a Call :Hold press the **W/↵** 2 seconds when comes a call.

Redialing the Last Called Number ; Double press the **W/↵**

#### EQ Switch Function

Short press the volume up and down buttonat the same time,change to EQ mode when listen to music.There are two groups of EQ mode,one is bass sound,the other is normal sound.can change from two groups freely,the red and blue light keep on for 2 seconds when change successfully.

#### Factory Data Reset

Hold press volume up and down button 6 seconds when headset is power on not in a call ,if the headset need to be reset when paired by other phone or other issues.

## Function

### Battery Capacity State

When headset paired with IOS devices,current headphone battery charge is displayed in the upper right corner of the phone screen.

When headset is power on,click on-off button,battery indicator light start after 10 seconds.

### Charging State

The new headset can be used for many times with enough battery,when it is in lower power,please charge it by USB cable for 2 hours,the headset will power off automatically when charged, the battery capacity indicator light flashes slowly and keep on light after current battery charged fully, all indicator lights both keep on light after full charged .

### Bluetooth Mode

Hold press on-off button 3 seconds until the headset is in pairing status,the red and blue light flashes alternately, start the mobile phone bluetooth function and search the device : P28s,click the device name to connect it,the blue light keep on light if paired successfully,there will be the automatic voice prompt : Connected.

### Line-in Mode

Plug in the aux cable when the headset is power on,it turns off automatically,no voice prompt,can't power on again.


Plug in the aux cable when the headset is power off,it has nothing respond,can't power on again.Note : Bluetooth mode cannot be used when wired.

### Connect Two Bluetooth Mobile Phones at the Same Time

The headset can be paired with two different bluetooth mobile phones at the same time ,won't interfere with each other,can answer a call from both two cell phones.

- 1.With the headset power off mode,hold press on-off button 3 seconds until the headset is in pairing status,pairing the first mobile phone.
- 2.Turn off the bluetooth function of the first mobile phone,then pair to the second bluetooth mobile phone.
- 3.Open the bluetooth function of the first mobile phone to pair the headset.

## Button Instructions



## Specification & Accessories

Compatible Bluetooth profiles :	A2DP,AVRCP,HFP,HSP
Transmission Distance :	8 ~10 m
Impedance :	32Ω±15℃
Sensitivity :	108±3db
Frequency band :	20-20000Hz

### Packing Accessories

- 1 : Bluetooth Headset
- 2 : User Manual
- 3 : Charging Cable
- 4 : Aux in Cable
- 5 : Warranty Card
- 6 : Certificate of Approval

### Like Warm and Prompt:

- 1.Please use USB power of 5V1A/5V2A for output when charged, it my damage the headset using charging equipment with high voltage.
- 2.When the headset is not in use for more than three months,please use it after full charged.
- 2.When the headset is not in use for more than three months,please use it after full charged.

## Precautions

- Please Don't place headset in high temperature,including strong sun exposure.
- Please Don't place headset near a fire or other hot environment.
- Please Don't place headset in wet or submerged in liquid environment,keep it dry.
- Please use the specified charge cable offered by our company.
- Please don't disassemble ,repair or reform it.
- Please note that excessive drop, impact, abrasion or other acts of affecting headset deformation, if there is any damage, such as depression, puncture, tearing, deformation or corrosion etc., please stop using the device immediately, and contact the seller or contact us by the service information on the warranty card.
- Please stop using the headset immediately If the headset produces abnormal smell, higher than normal temperature, and abnormal changes in color or shape,and contact the seller or contact us by the service information on the warranty card.



### Warning

Using headset at high volume for long periods of time may cause damage to your hearing

**FCC WARNING**

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation.

NOTE 1: Any changes or modifications to this unit not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.