
Control Box Operation Guide FAB-100C

Notice : The changes or modifications not expressly approved by the party responsible for compliance could void the user'sauthority to operate the equipment.

IMPORTANT NOTE:

To comply with the FCC RF exposure compliance requirements, no change to the antenna or the device is permitted. Any change to the antenna or the device could result in the device exceeding the RF exposure requirements and void user's authority to operate the device. This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



DC Power Input

MODEL: FAB-100C INPUT : 29V 2.5A Ser.No. : C001724F00001

C·XXXX-XXXXXX

Rev.No.: 00 FCC ID : TRUCB-AQUARIUS UART port

Household use only / Pour usage domestique seulement Cau t i on : Riak of Fire and Electric Shock Disconnect Plug Before Servicing, AVERT I SSEMENT : RISOUED 'DIVERDIE' DU DE CHOC ELECTRIQUES. Debranchez I alimentation avant toute maintenance. This device complex with, part 5 of the FCC Rules. Operation is subject to the following two concitions: (1) This device may not cause hamful interference. Intal Timay cause undesired operation. CAN ICES-303/WHR-318)

QR CODE Learn Button



Read advisory information in the owner's manual carefully before using this product. The potential for electrical shock exists if electrical components are not installed or operated properly.

FCC INFORMATION

The Federal Communication Commission Radio Frequency Interference Statement includes the following paragraph: The equipment has been tested and found to comply with the limits for a Class B Digital Device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instruction, may cause harmful interference to radio communication. However, there is no grantee that interference will not occur in a particular installation. If this equipment dose cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on , the user is encouraged to try to correct the interference by one or more of the following measures:

--Reorient or relocate the receiving antenna.

--Increase the separation between the equipment and receiver.

--Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.

--Consult the dealer or an experienced radio/TV technician for help.

The user should not modify or change this equipment without written approval from Ruoey Lung Enterprise Corp. Modification could void authority to use this equipment.

Ruoey Lung Enterprise Corp. / No.17, Lu-Kung South 2 Road, Chang-Pin Industrial Park, Lu-Kang, Changhua, Taiwan